

Jon A. Franke
Site Vice President

Susquehanna Nuclear, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.2904 Fax 570.542.1504
Jon.Franke@TalenEnergy.com



JUL 12 2016

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 50.73

**SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388/2016-005-00
UNIT 2 LICENSE NO. NPF-22
PLA-7504**

Docket No. 50-388

Attached is Licensee Event Report (LER) 50-388/2016-005-00. The LER reports an event where Unit 2 High Pressure Coolant Injection (HPCI) was manually overridden immediately prior to a manual scram during a plant transient. This event was determined to be reportable in accordance with 10 CFR 50.73(a)(2)(v) as a condition that could have prevented fulfillment of a safety function.

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new regulatory commitments

A handwritten signature in black ink, appearing to be "J. A. Franke".

J. A. Franke

Attachment: LER 50-388/2016-005-00

Copy: NRC Region I
Mr. J. E. Greives, NRC Sr. Resident Inspector
Ms. T. E. Hood, NRC Project Manager
Mr. M. Shields, PA DEP/BRP

NRC FORM 366 (11-2015)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 10/31/2018	
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block)		Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.			
1. FACILITY NAME Susquehanna Steam Electric Station Unit 2				2. DOCKET NUMBER 05000388		3. PAGE 1 of 3	
4. TITLE Unit 2 HPCI Manually Overridden Prior to a Manual Scram During a Plant Transient							
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY
05	13	2016	2016	- 005	- 00	07	12
						8. OTHER FACILITIES INVOLVED	
						FACILITY NAME DOCKET NUMBER 05000	
						FACILITY NAME DOCKET NUMBER 05000	
9. OPERATING MODE							
11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)							
1		☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.73(a)(2)(ii)(A)	
		☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.73(a)(2)(ii)(B)	
		☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.73(a)(2)(iii)	
		☐ 20.2203(a)(2)(i)		☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(iv)(A)	
		☐ 20.2203(a)(2)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(v)(A)	
		☐ 20.2203(a)(2)(iii)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(v)(B)	
		☐ 20.2203(a)(2)(iv)		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(C)	
		☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(A)		☒ 50.73(a)(2)(v)(D)	
10. POWER LEVEL 069		☐ 20.2203(a)(2)(vi)		☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(vii)	
				☐ 50.73(a)(2)(i)(C)		☐ OTHER Specify in Abstract below or in NRC Form 366A	
12. LICENSEE CONTACT FOR THIS LER							
LICENSEE CONTACT Nicole Pagliaro, Licensing Specialist - Nuclear Regulatory Affairs						TELEPHONE NUMBER (Include Area Code) (570) 542-6578	
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT							
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT
14. SUPPLEMENTAL REPORT EXPECTED ☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)						☒ NO	
						15. EXPECTED SUBMISSION DATE	
						MONTH DAY YEAR	

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On 5/13/2016 at 0055, the Unit 2 Unit Supervisor directed manually overriding High Pressure Coolant Injection HPCI (HPCI) immediately prior to a manual scram during a plant transient.

This event is being reported under 10 CFR 50.73(a)(2)(v)

There were two causes of this event. First, the Unit Supervisor made a decision to prematurely override HPCI to minimize distractions later in the shutdown without procedural guidance to do so. Second, weaknesses in teamwork and oversight prevented the mistake from being corrected by the crew. Immediate corrective actions include removing qualifications from the individuals involved and communicating expectations with the remaining crews. Additional corrective actions being taken include incorporating this event into initial licensed operator training and a Human Performance Improvement Plan will be created to address gap noted in the crew's performance.

NRC FORM 366A
(11-2015)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB: NO. 3150-0104

EXPIRES: 10/31/2018



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Susquehanna Steam Electric Station, Unit 2	05000388	YEAR	SEQUENTIAL NUMBER	REV NO.
		2016	- 005	- 00

NARRATIVE

CONDITIONS PRIOR TO EVENT

Unit 1 – Mode 1, 100 percent Rated Thermal Power

Unit 2 – Mode 1, 069 percent Rated Thermal Power

At 23:55 on 5/12/16, Unit 2 experienced an electrical transient resulting in a loss of 2B246 Reactor Building Engineered Safeguard System (ESS) Division 480 volt Motor Control Center (MCC) (EIS: B) and 2Y246 208/120 Volt Alternate Current (AC) Instrument Panel (EIS: JL). With the loss of the Reactor Building ESS Division 480 volt MCC, several drywell cooling fans were lost leading to an increase in drywell pressure.

EVENT DESCRIPTION

On 5/12/16 at 2355, Unit 2 experienced an electrical transient caused by a loss of 480VAC MCC 2B246 breaker. Operations reduced reactor power by reducing reactor recirculation flow. Drywell pressure and temperature began to rise and it was reported by Maintenance that the 2B246 bus faulted and was not able to be re-energized. Operations determined that a manual scram was required based upon a loss of drywell cooling. On 5/23/2016 at 0055 HPCI (EIS code: BJ) was overridden prior to the manual scram to prevent the trip of all feedwater pumps on reactor pressure vessel high water level alarm (EIS: JB). Technical specification 3.5.1 was entered for HPCI inoperable due to manual override. At 0110, Unit 2 was manually scrammed and HPCI was restored to AUTO at 0122.

The Unit Supervisor directed the override of HPCI without following station procedures which require adequate core cooling to be assured by at least two independent indicators. The Reactor Operator at the HPCI controls did not question the Unit Supervisor's decision.

The Unit 2 scram event will be addressed under LER 388/ 2016-004-00.

CAUSE OF EVENT

There were two causes of this event. First, the Unit Supervisor made a decision to prematurely override HPCI to minimize distractions later in the shutdown without procedural guidance to do so. OP-AD-300, Administration of Operations, provides direction for overriding ECCS systems and clearly defines when such a system may be placed in manual. This procedure was not followed. Second, weaknesses in teamwork and oversight prevented the mistake from being corrected by the crew. A crew update was not conducted to announce the placing of HPCI in manual override, preventing the crew from providing a peer check of the Unit Supervisor's decision.

NRC FORM 366A
(11-2015)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB: NO. 3150-0104

EXPIRES: 10/31/2018



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Susquehanna Steam Electric Station, Unit 2	05000388	YEAR	SEQUENTIAL NUMBER	REV NO.
		2016	- 005	- 00

NARRATIVE

ANALYSIS/SAFETY SIGNIFICANCE

The actual consequences of this event were the inability of an ECCS system to perform its automatic function.

The potential consequence of overriding HPCI is, in the event of a small break loss of coolant accident, that operations would not be able to maintain adequate core cooling.

There were no actual or potential consequences to the health and safety of the public as a result of this event.

CORRECTIVE ACTIONS

Immediate corrective actions include removing qualifications from the individuals involved and communicating expectations with the remaining crews. Additional corrective actions being taken include incorporating this event into initial licensed operator training and a Human Performance Improvement Plan will be created to address gap noted in the crew's performance.

PREVIOUS SIMILAR EVENTS

There were no previous similar events in which an ECCS system was incorrectly overridden.