

Paul Fessler
Senior Vice President and Chief Nuclear Officer

DTE Energy Company
6400 N. Dixie Highway, Newport, MI 48166
Tel: 734.586.4153 Fax: 734.586.1431
Email: paul.fessler@dteenergy.com



10 CFR 50.73

April, 22, 2019
NRC-19-0020

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 2019-002

Pursuant to 10 CFR 50.73(a)(2)(v)(C), DTE Electric Company (DTE) is submitting LER No. 2019-002, Secondary Containment Airlock Doors opened at the same time resulting in a condition prohibited by Technical Specifications.

No new commitments are being made in this LER.

Should you have any questions or require additional information, please contact Mr. Scott A. Maglio, Manager – Nuclear Licensing, at (734) 586-5076.

Sincerely,

A handwritten signature in black ink, appearing to read "P. Fessler".

Paul Fessler
Senior Vice President and CNO

Enclosure: Licensee Event Report No. 2019-007, Secondary Containment Airlock Doors Opened at the Same Time Resulting in a Condition Prohibited by Technical Specifications

USNRC
NRC-19-0020
Page 2

cc: NRC Project Manager
NRC Resident Office
Reactor Projects Chief, Branch 5, Region III
Regional Administrator, Region III
Michigan Public Service Commission
Regulated Energy Division (kindschl@michigan.gov)

**Enclosure to
NRC-19-0020**

**Fermi 2 NRC Docket No. 50-341
Operating License No. NPF-43**

**Licensee Event Report (LER) No. 2019-002
Secondary Containment Airlock Doors Opened at
the Same Time Resulting in a Condition Prohibited
by Technical Specifications**

**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. Facility Name

Fermi 2

2. Docket Number

05000 341

3. Page

1 OF 3

4. Title

Secondary Containment Airlock Doors Opened at the Same Time Resulting in a Condition Prohibited by Technical Specifications

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number
02	19	2019	2019	002	00	04	22	2019	N/A	05000
9. Operating Mode			11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)							
1			☐ 20.2201(b)	☐ 20.2203(a)(3)(i)		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)		
			☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)		☐ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)		
			☐ 20.2203(a)(1)	☐ 20.2203(a)(4)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)		
			☐ 20.2203(a)(2)(i)	☐ 50.36(c)(1)(i)(A)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)		
10. Power Level			☐ 20.2203(a)(2)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(v)(A)		☐ 73.71(a)(4)	
100			☐ 20.2203(a)(2)(iii)	☐ 50.36(c)(2)		☐ 50.73(a)(2)(v)(B)		☐ 73.71(a)(5)		
			☐ 20.2203(a)(2)(iv)	☐ 50.46(a)(3)(ii)		☒ 50.73(a)(2)(v)(C)		☐ 73.77(a)(1)		
			☐ 20.2203(a)(2)(v)	☐ 50.73(a)(2)(i)(A)		☐ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(i)		
			☐ 20.2203(a)(2)(vi)	☐ 50.73(a)(2)(i)(B)		☐ 50.73(a)(2)(vii)		☐ 73.77(a)(2)(ii)		
			☐ 50.73(a)(2)(i)(C)		☐ Other (Specify in Abstract below or in NRC Form 366A)					

12. Licensee Contact for this LER**Licensee Contact**

Fermi 2 / Scott A. Maglio - Manager, Nuclear Licensing

Telephone Number (Include Area Code)

734-586-5076

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to ICES	Cause	System	Component	Manufacturer	Reportable to ICES
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

14. Supplemental Report Expected☐ Yes (If yes, complete 15. Expected Submission Date) ☒ No**15. Expected Submission Date**

Month Day Year

Abstract (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)

On February 19, 2019, at 1307 EST, with the reactor at 100 percent Core Thermal Power and steady state conditions, plant personnel notified the Main Control Room that both doors in the Secondary Containment Airlock on the Reactor Building Fifth Floor were opened and could not close. The Airlock Doors were opened simultaneously for a period of approximately five minutes (i.e., from 1253 to 1258 EST). A technician had opened both air lock doors simultaneously when he egressed through first door and grabbed the handle of the second airlock door and inadvertently pushed the door open before the opposing door had closed. The interlock device for the doors had failed. The interlock is designed to prevent both doors from being opened simultaneously. Technical Specification (TS) Surveillance Requirement (SR) 3.6.4.1.3 was not met. The maximum Secondary Containment (SC) pressure observed during that time remained within TS limits. There were no radiological releases associated with this event. Declaring SC inoperable as a result of not meeting TS SR 3.6.4.1.3 is reportable under 10CFR50.72(b)(3)(v)(C) and this written report is required under 10CFR50.73(a)(2)(v)(C) as an event or condition that could have prevented the fulfillment of a safety function needed to control the release of radioactive material. The doors were closed in approximately 5 minutes and SC was restored.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Fermi 2	05000- 341	YEAR 2019	SEQUENTIAL NUMBER 002	REV NO. 00

NARRATIVE**INITIAL PLANT CONDITIONS**

Mode 1

Reactor Power 100%

DESCRIPTION OF THE EVENT

On February 19, 2019, at 1307 Eastern Standard Time (EST), with the reactor in steady state operations, the main control room was notified that both airlock doors [[DR]] for the Secondary Containment (SC) [[NH]] on the reactor building fifth floor were opened. The airlock doors were opened simultaneously for a period of approximately five minutes (i.e., from 1253 to 1258 EST). A technician had opened both air lock doors simultaneously when he egressed through first door and grabbed the handle of the second airlock door and inadvertently pushed the door open before the opposing door had closed. The airlock door locking pins became stuck once the doors were simultaneously opened preventing either door from being closed. The interlock [[IEL]] device for the doors had failed. The interlock is designed to prevent both doors from being opened simultaneously. Technical Specification (TS) Surveillance Requirement (SR) 3.6.4.1.3 was not met with both doors opened. The locking pins were released and airlock doors were closed after approximately 5 minutes. The airlock and secondary containment were restored. The maximum SC pressure observed during that time remained within TS limits for SC operability.

There were no radiological releases associated with this event. Declaring SC inoperable was a result of not meeting TS SR 3.6.4.1.3. The condition was reported to the NRC Operations Center per event notification number 53888 under 10CFR50.72(b)(3)(v)(C) and this written report is required under 10CFR50.73(a)(2)(v)(C) as an event or condition that could have prevented the fulfillment of a safety function needed to control the release of radioactive material.

SIGNIFICANT SAFETY CONSEQUENCES AND IMPLICATIONS

There were no safety consequences or radiological releases associated with this event. At no time during this event was there a potential for endangering the public health and safety.

The SC reactor and auxiliary building fifth floor airlock maintains one door closed when traversing into or out of the reactor building fifth floor. A negative pressure is maintained in the reactor building and portions of the auxiliary building. Radioactive materials remain in the auxiliary building and reactor building and any release of radioactive material is monitored for radiation before exhausting to the environment during normal operation. When both air lock doors were open for approximately 5 minutes on February 19, negative pressure was maintained in SC and the auxiliary building. The SC vacuum remained within the TS operability limit of greater than or equal to 0.125 inches of vacuum water gauge per TS Surveillance Requirement (SR) 3.6.4.1.1. Therefore, there was no unmonitored release during the event.

CAUSE OF THE EVENT

The technician turned the auxiliary building fifth floor door handle and inadvertently pushed on the auxiliary building door prior to the reactor building door being closed and latched. The technician didn't recognize the risk of turning the handle prior to verifying the opposing door being closed and latched and relied on the interlock to hold the reactor building door closed. The reactor building fifth floor airlock door did not latch and the airlock doors interlock failed, allowing the auxiliary building fifth floor door to open while the reactor building fifth floor door still was open. The interlock device failed.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Fermi 2	05000-	YEAR	SEQUENTIAL NUMBER	REV NO.
	341	2019	002	00

NARRATIVE**CORRECTIVE ACTIONS**

Contacted Security and Operations to reset pins and close door. Performed a walk down of the area. The airlock doors are now posted as "Emergency Exit Only" until the reactor building and auxiliary building door interlock is repaired.

A Human Performance Department Reset was issued as a result of this event. The event briefing sheet was presented to the Radiation Protection department staff. Radiation Protection Management communicated to the staff the importance of ensuring the first door is closed prior to opening the second door, and not challenging the interlock.

The interlocking device is being reviewed. When the appropriate design or adjustment is determined, the interlock will be repaired.

PREVIOUS OCCURRENCES

The negative pressure in SC was maintained by Reactor Building Heating Ventilation and Air Conditioning (RBHVAC) [[VA]] and remained within the TS requirement during this event. There are no previous occurrences that involved the human performance error of simultaneous opening of both air lock doors.