



Earl Berry
Vice President - Farley

Joseph M. Farley Nuclear Plant
7388 North State Hwy 95
Columbia, Alabama 36319
334.661.2100 tel
334.661.2512 fax

EBerry@southernco.com

October 14, 2025

Docket No.: 50-348
50-364

NL-25-0382

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant - Unit 1 & 2
Licensee Event Report 2025-001-00
Emergency Diesel 1C Unable to Achieve 110% of Maximum Load

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(i)(B), Southern Nuclear Company is submitting the enclosed Licensee Event Report for Unit 1 & 2. The enclosed LER describes a condition which was prohibited by Technical Specifications.

This letter contains no NRC commitments. If you have any questions regarding this submittal, please contact Gene Surber, Licensing Manager, at (334) 661-2265.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "E. Berry", written over the printed name "Earl Berry".

Earl Berry

Vice President – Farley

EB/rgs/cbg

Enclosure: Unit 1 & 2 Licensee Event Report 2025-001-00

Cc: Regional Administrator, Region II
NRR Project Manager – Farley Nuclear Plant
Senior Resident Inspector – Farley Nuclear Plant
RTYPE: CFA04.054

**Joseph M. Farley Nuclear Plant - Unit 1 & 2
Licensee Event Report 2025-001-00
Emergency Diesel 1C Unable to Achieve 110% of Maximum Load**

Enclosure

Unit 1 & 2 Licensee Event Report 2025-001-00



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form)

<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

Joseph M. Farley Nuclear Plant, Unit 1

☒ 050☐ 052

2. Docket Number

348

3. Page

1 OF 2

4. Title

Emergency Diesel 1C Unable to Achieve 110% of Maximum Load

5. Event Date

6. LER Number

7. Report Date

8. Other Facilities Involved

Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	☒ 050	Docket Number
08	13	25	2025	- 001 -	00	10	14	2025	Farley Nuclear Plant U2		364
									Facility Name	☐ 052	Docket Number

9. Operating Mode

1

10. Power Level

100

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(I)	☐ 50.36(c)(1)(I)(A)	☐ 50.73(a)(2)(II)(B)	☐ 50.73(a)(2)(vIII)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☒ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Ronnie Gene Surber, Licensina Manager

Phone Number (Include area code)

3346612265

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
D	DC	DG	F010	Y					

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On August 13, 2025, at approximately 2126 CDT with Unit 1 and Unit 2 in Mode 1 at 100% power the 1C Emergency Diesel Generator (EDG) was unable to be loaded to 3100 kilowatts (kW) as required by Surveillance Requirement (SR) 3.8.1.12 (24 hour run). The 1C EDG can be aligned to Farley Nuclear Plant (FNP) Unit 1 or Unit 2.

During the 24 hour run, SR 3.8.1.12 requires operating the 1C EDG at a load greater than or equal to 110% (3100 kW) capacity for a time of greater than two hours of the 24 hour requirement. When operators were adding the additional load to the 1C EDG, the generator was only capable of reaching 2950 kW. Per SR 3.0.1 failure to meet the SR means the Limiting Condition of Operation (LCO) is not met. FNP operators declared the 1C EDG inoperable.

It was determined that during the 1C EDG outage in October of 2024 that the EDG governor linkage was removed and re-installed to the fuel rack. The fuel rack was found limited in movement by the governor linkage preventing further loading. The 1C EDG governor linkage was corrected and the 1C EDG successfully completed post maintenance testing on August 14, 2025, and was declared operable.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	☒ 050 ☐ 052	2. DOCKET NUMBER	3. LER NUMBER		
Joseph M. Farley Nuclear Plant, Unit 1		348	YEAR 2025	SEQUENTIAL NUMBER 001	REV NO. 00

NARRATIVE**Plant Conditions / Event Description:**

On August 13, 2025, at approximately 2126 CDT, with Farley Nuclear Plant (FNP) Unit 1 and Unit 2 in Mode 1 at 100% power, the 1C Emergency Diesel Generator (EDG) [EIIIS: DC / DG] was unable to reach a load of 3100 kilowatts (kW) during the Technical Specification (TS) Surveillance Requirement (SR) 3.8.1.12 (24 hour run). The 1C EDG can be aligned to Farley Nuclear Plant (FNP) Unit 1 or Unit 2 thus both units were affected.

Event Analysis:

During the 24 hour run, SR 3.8.1.12 requires operating the 1C EDG [Manufacturer: Fairbanks Morse] at a load of 2850 kW or higher. The SR also requires that the 1C EDG run loaded greater than or equal to 3100 kW for a time of greater than two hours of this 24 hour requirement. When operators were adding the additional load to the 1C EDG the diesel generator was only capable of reaching 2950 kW. FNP operators declared the 1C EDG inoperable due to failure to meet the SR.

Reportability and Safety Assessment:

Per SR 3.0.1, failure to meet the SR means the Limiting Condition of Operation (LCO) is not met. Since the LCO for Technical Specification 3.8.1 was not met, FNP had been in a condition prohibited by TS since October 25, 2024. The event was within the analysis of UFSAR Chapter 15 and is reportable per 10 CFR 50.73(a)(2)(i)(B) for the 1C EDG being inoperable for longer than allowed by TS 3.8.1. The Safety Function was met as the 1C EDG provides loads for Loss of Offsite Power (LOSP) which was met by meeting 100% load demand of 2850 kW.

Cause(s):

It was determined that during the 1C EDG outage in October of 2024 that the EDG governor linkage was removed and re-installed to the fuel rack. Following the August 13, 2025, run of the 1C EDG, the investigation found that the fuel rack was limited in movement by the governor linkage preventing further loading. It was determined that the FNP PMT guidance did not require a PMT of 110% (3100 kW) capacity upon the replacement of the fuel injector pump. Additionally, maintenance procedures did not require a 110% loaded run upon the adjustment or replacement of equipment that could adversely impact EDG performance criteria.

Corrective Actions Planned / Completed:

The 1C EDG governor linkage was corrected and the 1C EDG successfully completed PMT on August 14, 2025, and was declared operable.

Fleet and site procedures are being revised to ensure 110% load PMT occurs when work is performed on systems that affect combustion engine performance. Revisions are being tracked in the site's Corrective Action Program.

An extent of condition was performed on all 4 remaining diesel generators which determined the same condition did not exist.

Previous Similar Events:

No known previous events.