

RBG-48380

10 CFR 50.73

October 20, 2025

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Subject: Licensee Event Report 50-458 / 2025-005-00, Containment Unit Coolers
Inoperable Due to Compensatory Measures

River Bend Station – Unit 1
NRC Docket Nos. 50-458
Renewed Facility Operating License No. NPF-47

In accordance with 10 CFR 50.73, enclosed is the subject Licensee Event Report.

This document contains no commitments.

Should you have any questions, please contact Mr. Jack McCoy, Regulatory and Emergency Planning Manager, at 225-378-3310.

Respectfully,

**Jack
McCoy** 
Digitally signed by Jack McCoy
DN: cn=Jack McCoy, o=Manager
Regulatory and Emergency Preparedness,
ou=Entergy/ River Bend,
email=jmccoy1@entergy.com
Date: 2025.10.20 13:35:51 -05'00'

JM/jdb

Enclosure: LER 50-458 / 2025-005-00, Containment Unit Coolers Inoperable
Due to Compensatory Measures

cc: NRC Region IV Regional Administrator - Region IV
NRC Senior Resident Inspector - River Bend Station
NRC Office of Nuclear Security and Incident Response

Enclosure

RBG-48380

Licensee Event Report
50-458/2025-005-00

NRC FORM 366 (04-02-2024)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104 Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.						
		LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)									
1. Facility Name River Bend Station, Unit 1					☒ 050 ☐ 052		2. Docket Number 00458		3. Page 1 of 3		
4. Title Containment Unit Coolers Inoperable Due to Compensatory Measures											
5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number	
08	20	2025	2025	005	00	10	20	2025	N/A	☐ 050	
									Facility Name	Docket Number	
									N/A	☐ 052	
9. Operating Mode 1						10. Power Level 100					
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)											
10 CFR Part 20		☐ 20.2203(a)(2)(vi)		10 CFR Part 50		☐ 50.73(a)(2)(ii)(A)		☐ 50.73(a)(2)(viii)(A)		☐ 73.1200(a)	
☐ 20.2201(b)		☐ 20.2203(a)(3)(i)		☐ 50.36(c)(1)(i)(A)		☒ 50.73(a)(2)(ii)(B)		☐ 50.73(a)(2)(viii)(B)		☐ 73.1200(b)	
☐ 20.2201(d)		☐ 20.2203(a)(3)(ii)		☐ 50.36(c)(1)(ii)(A)		☐ 50.73(a)(2)(iii)		☐ 50.73(a)(2)(ix)(A)		☐ 73.1200(c)	
☐ 20.2203(a)(1)		☐ 20.2203(a)(4)		☐ 50.36(c)(2)		☐ 50.73(a)(2)(iv)(A)		☐ 50.73(a)(2)(x)		☐ 73.1200(d)	
☐ 20.2203(a)(2)(i)		10 CFR Part 21		☐ 50.46(a)(3)(ii)		☐ 50.73(a)(2)(v)(A)		10 CFR Part 73		☐ 73.1200(e)	
☐ 20.2203(a)(2)(ii)		☐ 21.2(c)		☐ 50.69(g)		☐ 50.73(a)(2)(v)(B)		☐ 73.77(a)(1)(i)		☐ 73.1200(f)	
☐ 20.2203(a)(2)(iii)				☐ 50.73(a)(2)(i)(A)		☒ 50.73(a)(2)(v)(C)		☐ 73.77(a)(2)(i)		☐ 73.1200(g)	
☐ 20.2203(a)(2)(iv)				☒ 50.73(a)(2)(i)(B)		☒ 50.73(a)(2)(v)(D)		☐ 73.77(a)(2)(ii)		☐ 73.1200(h)	
☐ 20.2203(a)(2)(v)				☐ 50.73(a)(2)(i)(C)		☐ 50.73(a)(2)(vii)					
☐ Other (Specify here, in abstract, or in NRC 366A).											
12. Licensee Contact for this LER											
Licensee Contact Jack McCoy, Regulatory and Emergency Planning Manager									Phone Number (Include Area Code) (225) 378-3310		
13. Complete One Line for each Component Failure Described in this Report											
Cause	System	Component	Manufacturer	Reportable To IRIS	Cause	System	Component	Manufacturer	Reportable To IRIS		
14. Supplemental Report Expected						15. Expected Submission Date			Month	Day	Year
☒ No		☐ Yes (If yes, complete 15. Expected Submission Date)									
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)											
On August 20, 2025, at 1020 CDT, River Bend Station, Unit 1 (RBS) was operating at 100% power, when it was discovered that previously implemented compensatory measures were determined to have rendered Containment Unit Cooler 'A' (HVR-UC1A) and Containment Unit Cooler 'B' (HVR-UC1B) inoperable. On August 14, 2025, RBS placed HVR-UC1A and HVR-UC1B in lockout as a compensatory measure to ensure operability following a Part 21 notification from General Electric. On August 20, 2025, it was discovered that the lockout function would delay the start of a time-delay relay needed for load sequencing in the event of an accident. The cause of this event was due to inadequate compensatory measures that were established by plant personnel. These compensatory measures would have prevented the containment unit coolers from performing their safety function. This event is being reported under 10 CFR 50.73 (a)(2)(ii)(B) as any event or condition that results in the nuclear power plant being in an unanalyzed condition that significantly degrades plant safety, 10 CFR 50.73(a)(2)(v)(C) and 10 CFR 50.73(a)(2)(v)(D) as an event or condition that could have prevented fulfillment of a safety function that is needed to control the release of radioactive material and mitigate the consequences of an accident, and 10 CFR 50.73(a)(2)(i)(B) as an Operation or Condition Prohibited by Technical Specifications.											

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
River Bend Station, Unit 1	☒ 050	00458	YEAR	SEQUENTIAL NUMBER	REV NO.
	☐ 052		2025	005	00

NARRATIVE**Event Description**

On August 14, 2025, River Bend Station, Unit 1 (RBS) placed Containment Unit Cooler 'A' (HVR-UC1A) [VA:CLR] and Containment Unit Cooler 'B' (HVR-UC1B) [VA:CLR] in lockout as a compensatory measure to ensure operability following a Part 21 notification from General Electric.

On August 20, 2025, it was discovered that the lockout function would delay the start of a time-delay relay [RLY] needed for load sequencing in the event of an accident. This condition would prevent the unit coolers from starting within their required sequence following a Loss of Offsite Power.

The compensatory measures included actions to place HVR-UC1A and HVR-UC1B in a continuously running state during normal plant operation. In the event of a Loss of Offsite Power, a dedicated operator would be required to reset the lockout pushbuttons for each unit cooler to meet the safety function time requirement associated with the load sequence. Following a review of the compensatory actions on August 20, 2025, it was determined that the compensatory actions were inappropriately applied. The compensatory actions that were implemented would have caused HVR-UC1A and HVR-UC1B to start up to 10 minutes after the dedicated operator reset the lockout pushbuttons, instead of 10 minutes following a Loss of Offsite Power.

During the time that HVR-UC1A and HVR-UC1B were in lockout, Technical Specifications (TS) Limiting Condition for Operation 3.6.1.7, Primary Containment Unit Cooler, Condition B was applicable. On August 20, 2025, at 1219 CDT, these compensatory measures were removed.

This event was reported under 10 CFR 50.72(b)(3)(ii)(B) as any event or condition that results in the nuclear power plant being in an unanalyzed condition that significantly degrades plant safety, as well as, 10 CFR 50.72(b)(3)(v)(C) and 10 CFR 50.72(b)(3)(v)(D) as an event or condition that could have prevented fulfillment of a safety function that is needed to control the release of radioactive material and mitigate the consequences of an accident and 10 CFR 50.73(a)(2)(i)(B) as an Operation or Condition Prohibited by TS.

Event Cause

The cause of the event was due to multiple ineffective reviews of electrical drawings resulting in Engineering personnel failing to recognize the impact of the compensatory measures on the loading sequence of the containment unit coolers. During review and validation prior to implementation, Operations personnel did not recognize the impact of the compensatory measures. As a result, compensatory measures were implemented which would have prevented the containment unit coolers from performing their safety function.

Safety Assessment

The actual consequences of this event were minimal. A loss of offsite power did not occur during the duration that HVR-UC1A and HVR-UC1B were inoperable. There were also no radiological impacts. Therefore, there was no actual impact on the health and safety of the public.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
River Bend Station, Unit 1	☒ 050	00458	YEAR	SEQUENTIAL NUMBER	REV NO.
	☐ 052		2025	005	00

Corrective Actions

Planned:

- Perform a standards reset with respect to the expectations of independent reviews.
- Perform a standards reset with personnel to ensure compliance with procedures that govern pre-job briefs and human performance tools.
- Perform management observations during development of operability determinations.
- Incorporate operational experience and lessons learned from this event into continual training.

Previous Occurrences

None

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX]. River Bend equipment codes are identified as (XX).