



10 CFR 50.73

CCN: 25-89

November 13, 2025

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Peach Bottom Atomic Power Station (PBAPS) Units 2 and 3
Subsequent Renewed Facility Operating License No. DPR-44, DPR-56
NRC Docket No. 50-277, 50-278

Subject: Licensee Event Report (LER) 2025-003-00 Invalid Actuation Due to
Transformer Breaker Trip

The subject report is being submitted in accordance with 50.73(a)(2)(iv)(A) for an invalid actuation of general containment isolation signals affecting containment isolation valves in more than one system.

There are no commitments contained in this letter. If you have any questions, please contact the Peach Bottom Regulatory Assurance Manager, Mr. Brian Woodard at (257) 533-7430.

Respectfully,

Stiltner, Ryan Digitally signed by Stiltner,
Ryan C
C Date: 2025.11.13 12:23:32
-05'00'

Ryan C. Stiltner
Plant Manager
Peach Bottom Atomic Power Station

Enclosure

cc: USNRC, Administrator, Region I
USNRC, Senior Resident Inspector
W. DeHaas, Commonwealth of Pennsylvania
S. Seaman, State of Maryland
B. Watkins, PSE&G, Financial Controls and Co-Owner Affairs

**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

Peach Bottom Atomic Power Station (PBAPS), Unit 2

☒ **050**
☐ **052****2. Docket Number**

00277

3. Page**1 OF 2****4. Title**

Invalid Actuation Due to Transformer Trip

5. Event Date

Month	Day	Year
09	19	2025

6. LER Number

Year	Sequential Number	Revision No.
2025	- 003 -	00

7. Report Date

Month	Day	Year
11	13	2025

8. Other Facilities Involved

Facility Name	☒ 050	Docket Number
PBAPS, Unit 3		00278
Facility Name	☐ 052	Docket Number

9. Operating Mode

1

10. Power Level

100

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

10 CFR Part 20	☐ 20.2203(a)(2)(vi)	10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ **OTHER** (Specify here, in abstract, or NRC 366A).**12. Licensee Contact for this LER****Licensee Contact**

Brian Woodard, Regulatory Assurance Manager

Phone Number (Include area code)

(267) 533-7430

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
E	EA	DISC	I005	Y					

14. Supplemental Report Expected☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)**15. Expected Submission Date**

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On September 19th, 2025, the 13 kV non-safety related AS4 feeder breaker, which powers the B Cooling Tower Lift Pump (EIIS:NN) tripped as a result of an electrical fault downstream of the breaker. The electrical fault resulted in a momentary voltage dip on the offsite power source (3SU). This condition led to a partial invalid Primary Containment Isolation System (PCIS) (EIIS: JM) isolation including isolation of the Reactor Water Cleanup System (RWCU) (EIIS: CE) on both units. The cause of the breaker trip was a faulted disconnect switch, likely due to component aging.

This condition is reportable under 50.73(a)(2)(iv)(A) as an invalid actuation of general containment isolation signals affecting containment isolation valves in more than one system. The isolation was caused by degraded voltage. The actuation was invalid because the conditions for which isolation is required were not present.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME

Peach Bottom Atomic Power Station (PBAPS),
Unit 2

☒ **050**☐ **052****2. DOCKET NUMBER**

00277

3. LER NUMBER

YEAR	SEQUENTIAL NUMBER	REV NO.
2025	- 003	- 00

NARRATIVE**Plant Operating Conditions Before the Event**

Prior to the event, Peach Bottom Atomic Power Station, Unit 2 was operating at approximately 100% power in MODE 1. Unit 3 was operating at approximately 91% power in MODE 1 in end-of-cycle coast down. There were no structures, systems or components (SSC) that were inoperable at the start of the event that contributed to the event.

Event Description

On September 19th, 2025, at approximately 9:34am, operators received alarms indicating that the 480V motor control center that supplies support power to the B Cooling Tower (EIS: NN) lift pump tripped and caused various isolations on both units. On Unit 2, the voltage reduction caused a partial invalid Primary Containment Isolation System (PCIS) (EIS: JM) isolation of Group II and Group III inboard valves including isolation of the Reactor Water Cleanup System (RWCU) (EIS: CE), isolation of nitrogen compressors (EIS: LK), failure of the B vent stack radiation monitor (EIS: IL), and loss of flow to containment hydrogen and oxygen analyzers (EIS: IK). On Unit 3, this condition resulted in actuations of PCIS Group II and III outboard valves, isolation of RWCU, isolation of nitrogen compressors and a trip of a service water booster pump (EIS: DA). The A train of flow indication to the Main Stack sampler (EIS: IL) was also lost.

The cause of the breaker trip was a faulted disconnect switch, likely due to component aging and general corrosion. The failed switch is located outdoors and was replaced in 2007 after a similar failure. Preventive maintenance had not been performed since the 2007 failure.

This condition is reportable under 50.73(a)(2)(iv)(A) as an invalid actuation of general containment isolation signals affecting containment isolation valves in more than one system. The isolation was caused by degraded voltage. The actuation was invalid because the conditions for which isolation is required were not present.

Safety Consequences

There were no challenges to plant safety as a result of this event. Both units responded as designed to the electrical transient, and PCIS isolations were reset without error within approximately one hour of the trip.

Corrective Actions

Corrective actions for this condition include replacement of the components that were damaged by the fault, including radiation monitors, transformer disconnect switch and cabling. The maintenance strategy for this equipment will be reviewed.

Previous Similar Events

Peach Bottom experienced the following similar events:

- Invalid actuations due to a trip of the AS4 feeder breaker in 2007, ref. EN# 43910
- Invalid actuations due to an emergency bus breaker relay failure in 2019, ref. LER 2019-001-00.
- Invalid actuations due to a bus failure on August 20, 2025, rev. LER 2025-001-00.