



Constellation

Clinton Power Station
8401 Power Road
Clinton, IL 61727

U- 604861

10 CFR 50.73

January 13, 2026

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Clinton Power Station, Unit 1
Facility Operating License No. NPF-62
NRC Docket No. 50-461

Subject: Licensee Event Report 2025-004-00

Enclosed is Licensee Event Report (LER) 2025-004-00: Emergency Diesel Generator Automatic Start due to Emergency Reserve Auxiliary Transformer Trip. This report is being submitted in accordance with the requirements of 10 CFR 50.73.

There are no regulatory commitments contained in this report.

Should you have any questions concerning this report, please contact Mr. Derek Hillinger, Regulatory Assurance Manager, at (217) 937-2800.

Respectfully,

Frank Payne
Site Vice President
Clinton Power Station

Attachment: Licensee Event Report 2025-004-00

cc:

Regional Administrator - Region III
NRC Senior Resident Inspector - Clinton Power Station
Office of Nuclear Facility Safety - Illinois Emergency Management Agency

TE22
NRR



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A101), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

Clinton Power Station

☒ 050
☐ 052

2. Docket Number

00461

3. Page

1 OF 3

4. Title

Emergency Diesel Generator Automatic Start due to Emergency Reserve Auxiliary Transformer Trip

5. Event Date

Month	Day	Year
11	14	25

6. LER Number

Year	Sequential Number	Revision No.
2025	004	00

7. Report Date

Month	Day	Year
01	13	26

8. Other Facilities Involved

Facility Name	☐ 050	Docket Number
N/A		
Facility Name	☐ 052	Docket Number
N/A		

9. Operating Mode

Mode 1

10. Power Level

99%

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

10 CFR Part 20	☐ 20.2203(a)(2)(vi)	10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

Derek Hillinger, Regulatory Assurance Manager

Phone Number (Include area code)

(217) 937-2800

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
	EA	XFMR	B455	Y					

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

At 1351 on 11/14/25, with the unit in Mode 1 at 99% power, an actuation of the Division 1, 2, and 3 Emergency Diesel Generators (EDGs) occurred when a fault occurred on the Emergency Reserve Auxiliary Transformer (ERAT). The Reserve Auxiliary Transformer (RAT) B was previously de-energized and isolated for maintenance. The cause of the Division 1, 2, and 3 EDGs auto-start was an actuation of the Loss of Voltage Function undervoltage relays for each respective bus. The Division 1, 2, and 3 EDGs automatically started as designed when the applicable Loss of Voltage signals were received.

This event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) for "Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section." The specific system listed in that paragraph that actuated was the "Emergency ac electrical power systems, including: emergency diesel generators (EDGs);...and BWR dedicated Division 3 EDGs."

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Clinton Power Station	☒ 050	2. DOCKET NUMBER 00461	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 004	REV NO. - 00

NARRATIVE**CONDITION PRIOR TO THE EVENT**

Unit: 1 Event Date: November 14, 2025, Event Time: 13:51 CST
Mode: 1 Mode Name: Power Operation Reactor Power: 99%

EVENT DESCRIPTION

At 1351 CST on November 14, 2025, Clinton Power Station Unit 1 experienced a trip of the ERAT (138 kV offsite power source). The trip was a result of a phase-to-phase differential overcurrent. RAT B (345 kV offsite power source) had been previously taken out of service and made both inoperable and unavailable to support maintenance at 2000 CST on November 9, 2025. At the time of the event, the station was in LCO 3.8.1 condition A, completing required actions A.1 as needed and utilizing a 30-day Risk Informed Completion Time for required action A.2. When the ERAT tripped, the TS 3.3.8.1 Loss of Voltage Function undervoltage relays for each Class 1E 4160V AC bus actuated as designed, providing a valid automatic start signal to the Division 1, 2, and 3 EDGs. All three EDGs started and operated properly, carrying their respective buses until both offsite sources were restored to their normal lineup on November 16, 2025.

CAUSE OF THE EVENT

Actuation of the Division 1, 2, and 3 loss of voltage undervoltage relays due to a trip of the ERAT

SAFETY CONSEQUENCES

The ERAT transforms the electrical power from the 138kV offsite source to 4160V auxiliary bus voltage to each onsite class 1E bus. In the event of loss of both normal offsite sources of power (reserve and emergency reserve transformers) to the Class 1E AC power system, each EDG set is automatically started and loaded by controls and circuitry which are independent of that used to start and load the redundant buses. The instrumentation and controls for each Class 1E AC bus, as well as the EDGs themselves, responded appropriately to the transient. There were no safety consequences impacting plant or public safety as a result of this event, and there was no radioactive release associated with this event. This event was bounded by the analysis of UFSAR Chapter 15.

CORRECTIVE ACTIONS

Immediate Corrective Actions: The section of ERAT bus affected by the fault was isolated and quarantined. Power was then restored to the ERAT. RAT B was returned to service from planned maintenance. Each Class 1E 4160V AC bus was transferred to an offsite source supplying the load with its EDG secured and placed in a standby lineup.

PREVIOUS OCCURRENCES

A review of Licensee Event Reports for the past five years identified no previous similar occurrences at Clinton Power Station.