



Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450

10 CFR 50.73

January 15, 2026

SVPLTR 26-0001

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Dresden Nuclear Power Station, Units 2
Renewed Facility Operating License Nos. DPR-19
NRC Docket Nos. 50-237

Subject: Licensee Event Report 237/2025-003-00, High Pressure Coolant Injection Inoperable
Due to Failed Indicating Light and Blown Fuse

Enclosed is Licensee Event Report 237/2025-003-00, High Pressure Coolant Injection Inoperable Due to Failed Indicating Light and Blown Fuse. This report describes an event being reported in accordance with 10 CFR 50.73(a)(2)(v)(D) for an event or condition that could have prevented the fulfillment of a safety function needed to mitigate the consequences of an accident.

There are no regulatory commitments contained in this submittal.

Should you have any questions concerning this letter, please contact Tara Noah, acting Regulatory Assurance Manager, at (779) 231-7447.

Respectfully,

A handwritten signature in blue ink that reads "Hardik Patel".

Hardik Patel
Site Vice President
Dresden Nuclear Power Station

Enclosure: Licensee Event Report 237/2025-003-00

IE 22
NRR



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name	☒ 050 ☐ 052	2. Docket Number	3. Page
Dresden Nuclear Power Station, Unit 2		00237	1 OF 3

4. Title
High Pressure Coolant Injection Inoperable Due to Failed Indicating Light and Blown Fuse

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	☐ 050	Docket Number
11	17	2025	2025	- 003 -	00	01	15	2026	Facility Name	☐ 052	Docket Number

9. Operating Mode	10. Power Level
2, Startup	002

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☒ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact	Phone Number (Include area code)
Tara Noah, Acting Manager Site Regulatory Assurance	779-231-7447

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
TBD	BJ	TBD	TBD	Y	TBD	BJ	TBD	TBD	Y

14. Supplemental Report Expected				15. Expected Submission Date		
☐ No	☒ Yes (If yes, complete 15. Expected Submission Date)			Month	Day	Year
				03	13	2026

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

At 1613 CST on 11/17/25, with Unit 2 in Mode 2, Startup, at 2 percent power, it was discovered that the single train of high pressure coolant injection (HPCI) was inoperable. The cause of the HPCI inoperability was a damaged stop valve closed indicating light socket and an opened negative 125 VDC fuse that occurred when the Unit 2 HPCI Turbine Turning Gear engaged. The turning gear motor turned off without operator action. The stop valve closed indicating circuit was isolated and the fuse was replaced in accordance with station procedures and HPCI operability was restored at 2253 CST. An evaluation of the event is in progress and a supplemental report will be submitted with the conclusions of the evaluation.

This report is being submitted in accordance with 10 CFR 50.73(a)(2)(v)(D) for an event or condition that could have prevented the fulfillment of a safety function needed to mitigate the consequences of an accident.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Dresden Nuclear Power Station, Unit 2	☒ 050	2. DOCKET NUMBER 00237	3. LER NUMBER		
	☐ 052		YEAR 2025	SEQUENTIAL NUMBER - 003	REV NO. - 00

NARRATIVE**PLANT AND SYSTEM IDENTIFICATION - UNIT 2**

General Electric - Boiling Water Reactor, 2957 megawatts thermal rated core power

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX]

A. CONDITIONS PRIOR TO EVENT

Unit: 2	Event Date: November 17, 2025	Event Time: 1613 CST
Reactor Mode: 2	Mode Name: Startup	Power Level: 2%
Pressure level: 185 psig	Temperature: 376 °F	

No systems, structures, or components that were inoperable at the start of the event contributed to the event.

B. DESCRIPTION OF EVENT

At 1613 CST on 11/17/25, with Unit 2 in Mode 2, Startup, at 2 percent power, it was discovered that the single train of high pressure coolant injection (HPCI) [BJ] was inoperable. The cause of the HPCI inoperability was a failed stop valve indicating light [IL] circuit and a blown negative 125 VDC fuse [FU] that occurred when the Unit 2 HPCI Turbine [TRB] Turning Gear [TGR] engaged. The turning gear motor [MO] turned off without operator action. The indicating light circuit was isolated and the negative 125 VDC fuse was replaced in accordance with station procedures and HPCI operability was restored at 2253 CST on 11/17/25.

Event Notification System (ENS) report number 58043 was transmitted to the NRC at 2328 CST on 11/17/25.

This event is being reported in accordance with 10 CFR 50.73(a)(2)(v)(D).

C. CAUSE OF EVENT

The cause of the event was a damaged indicating light socket and a blown negative 125 VDC fuse when the HPCI Turbine Turning Gear was engaged. The negative 125 VDC fuse in question is required for the initiation of the steam turbine. An evaluation of the event is currently in progress. A supplemental report will be submitted with the conclusions of this evaluation.

D. SAFETY ANALYSIS**System Design**

The HPCI system is designed to ensure that adequate core cooling takes place for all break sizes less than those for which Low Pressure Coolant Injection (LPCI) [BO] or Core Spray [BM] systems can adequately protect the core without assistance from other engineered safety features. The negative 125 VDC fuse in

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME

Dresden Nuclear Power Station, Unit 2

☒ 050☐ 052**2. DOCKET NUMBER**

00237

3. LER NUMBER

YEAR	SEQUENTIAL NUMBER	REV NO.
2025	- 003	- 00

NARRATIVE

question is required for the initiation of the steam turbine. Without this turbine driving the HPCI pumps [P], the system is not capable of injection.

Safety Impact

The safety significance of this event is minimal. At the time of the event, Unit 2 was at two percent power in a normal electric plant lineup with all other means of Reactor Coolant Injection available. The Unit 2 Isolation Condenser (IC) [BL] system and the Unit 2 Automatic Depressurization System (ADS) remained Operable throughout the event. There was no impact on the health and safety of the public or plant personnel. This event was within the analysis of Updated Final Safety Analysis Report (UFSAR) Chapter 15, Accident and Transient Analysis.

There was no radioactive release associated with this event.

E. CORRECTIVE ACTIONS

At 2253 CST on 11/17/2025, HPCI operability was restored following the isolation of the indicating light circuit and replacing the blown negative 125 VDC fuse. Additional corrective actions will be determined by the evaluation currently in progress.

F. PREVIOUS OCCURENCES

A 5-year internal corrective action program and Licensee Event Report (LER) database review was performed for Dresden Nuclear Power Station (DNPS). No previous occurrences of HPCI inoperability were found at DNPS within the 5-year review timeline due to indicator light socket damage or blown negative 125 VDC fuse. Other events identified during the evaluation in progress will be discussed in the supplemental report.

G. COMPONENT FAILURE DATA

Causal investigation is ongoing, component failure data will be updated in supplemental LER.