

Ventilation Unit VU-400 — Annual Service Report

Facility North-2 · Service window 12–14 March · Reference SR-2311-084

The unit was inspected under normal operating load. Filter differential pressure remained within the manufacturer's envelope for the entire observation period, and no bearing noise was detected on either fan assembly. The heat-recovery core was cleaned in place; recovery efficiency measured after cleaning is reported in the table below.

Measured parameters

Parameter	Unit	Before service	After service	Limit
Supply airflow	m ³ /h	352	398	≥ 380
Extract airflow	m ³ /h	341	402	≥ 380
Filter pressure drop	Pa	184	92	≤ 150
Heat recovery efficiency	%	61	78	≥ 70
Motor current, supply fan	A	1.9	1.6	≤ 2.2

Both airflow readings recovered above the design threshold after the filter set was replaced. The pressure-drop reading of 92 Pa corresponds to a fresh F7 filter and should be re-checked at the six-month mark. Recovery efficiency improved from 61% to 78%, which is consistent with the amount of dust removed from the core.

Recommendations

Replace the filter set again no later than September. Order one spare belt for the extract fan; the installed belt shows early glazing but does not require immediate replacement. No other corrective actions are required before the next scheduled service.