
ROCO222: Intro to sensors and actuators

Lecture 9


3-phase induction motors

Principle of induction motor operation




- The lines of flux cutting the conductor will induce a voltage, and consequent current flow, in the conductive disk
- This current flow creates an electromagnet whose polarity opposes the motion of the permanent magnet
- The polarity of the electromagnet is such that it pulls against the permanent magnet

Typical induction motor



- The induction motor is the most commonly used type of AC motor
- They are simple, low cost and rugged in construction
- They do not require commutation do there are no brushes to wear out
- Indeed life generally limited by life of the bearings
- The induction motor derives its name from the fact that ac voltages are induced in the rotor circuit by the rotating magnetic field of the stator
- An induction motor is a constant speed device


Typical induction motor



- Stator carries the motor primary windings, which are coils of wire, which are connected to the power source
- Current is induced in the rotor windings (conductors) by transformer action
- Torque is produced by the reaction between the induced rotor currents and the air-gap flux created by the stator currents
- Drive shaft attached to and driven by rotor and supported by ball bearings each end
- Cooling fan causes air to circulate and reduce temperature of windings and rotor
- Frame needed to support stator and bearings and provide attachment point
- Terminal block provides power connection point


3-phase drive to stator coils

 AC 3-phase supply driving 3 sets of coil (2 poles per phase) positioned 120 degrees around the circumference of the stator circle results in a rotating magnetic field



3-phase drive results in rotating fields

- If there are 2 poles per phase then field rotates at supply frequency
 If there are 4 poles per phase then field rotates at half supply frequency



Squirrel cage induction motor


A squirrel cage rotor is a simple, low cost, robust,


 Its rotor winding is composed of copper or aluminum bars embedded in the rotor slots and shorted at both end by end rings

 Often the conductors are skewed to reduce cogging, improve starting and make rotation smoother


A ferromagnetic core is used to ensure magnetic flux density B is high

The core is usually laminated ferromagnetic material to reduce eddy current






Squirrel cage rotor



Wound rotor induction motor

- Rotor winding is wound by wires.
- The winding terminals can be connected to external circuits through slip rings and brushes.
- Purpose is to allow resistance to be placed in series with the rotor windings while starting - to reduce current
- Resistance is shorted out once the motor is started

Easy to control speed, more expensive




Induced current animation

Field rotates synchronously with supply frequency **Rotor rotates** more slowly so current induced into it Squirrel-cage induction motor

2-pole stator

Rotating fields causes rotor to rotate



4-pole stator

Induction motor rotational speed

- Primary factors that affect running speed of an induction motor are the supply frequency and its number of pole
- Also the loading will affect running speed
- In no-load conditions it will approach synchronous speed
- At full rated load there will be some slip which will be specified in the motor specifications

$$n_s = \frac{120 \times f}{poles}$$


Slip
$$S=rac{n_{_S}-n_{_r}}{n_{_S}}$$

Where n_r is actual rotational speed in RPM

Induction motor synchronous speed (RPM)


Poles	50 Hz	60 Hz
2	3000	3600
4	1500	1800
6	1000	1200
8	750	900
10	600	720
12	500	600

Compare with a transformer




Secondary winding current
$$I_s = I_s \left(\frac{N_p}{N_s} \right)$$

Transformer equivalent circuit




- Primary winding resistance R_P
- Primary leakage reactance X_P
- Secondary winding resistance R_s
- Secondary leakage reactance X_S
- Equivalent core loss resistance $R_{\rm C}$ and core loss current $I_{\rm C}$
- Magnetising reactance X_M and magnetising current I_M
- No-load current I₀
- Primary and secondary EMF E_P and E_S, developed over an ideal transformer
- Primary and secondary terminal voltages and currents V_P, I_P, V_S and I_S




In the equivalent circuit

• R₁ represents, the resistance of the stator winding




In the equivalent circuit

- R₁ represents, the resistance of the stator winding
- X₁ the stator leakage reactance (flux that does not link with the air gap and rotor)




In the equivalent circuit

- R₁ represents, the resistance of the stator winding
- X₁ the stator leakage reactance (flux that does not link with the air gap and rotor)
- Magnetizing reactance required to cross the air gap is represented by X_m




In the equivalent circuit

- R₁ represents, the resistance of the stator winding
- X₁ the stator leakage reactance (flux that does not link with the air gap and rotor)
- Magnetizing reactance required to cross the air gap is represented by X_m
- Core losses (hysteresis and eddy current) by R_c




- An ideal transformer of N₁ and N₂ turns respectively represents the air gap
- For the rotor side, the induced EMF is affected by the slip
- As the rotor gains speed, slip reduces and less EMF is induced
- The rotor resistance and reactance are represented by R₂ and X₂;
 with X₂ being dependent on the frequency of the inductor rotor EMF

- Circuit can be drawn without transformer as shown below
- How can we determine parameters?




DC resistance measurement

With DC measurements:



DC resistance measurement


So DC circuit simplified to



Can directly measure the stator DC resistance R₁


Blocked rotor condition

- Clamp rotor to prevent rotation
- Mechanical speed ω_m is then zero so slip is unity.
- Rotor impedance Z₂ now much smaller than magnetizing impedance Z_m.
- Magnetizing impedance can be neglected




Blocked rotor condition

• So blocked rotor circuit simplified to:




No load condition


- Motor is operating at rated voltage without a load
- Mechanical speed is close to synchronous and the slip goes towards zero
- Rotor impedance goes towards infinity



No load condition

So no load rotor circuit simplified to:






 The torque characteristic of induction motor is quite complex compared to that of DC motor

Plot shows:

- Percent of synchronous speed on the x-axis
- Percent of full load torque on the y-axis
- We now consider some important points on the characteristic curve


Asynchronous motor characteristic



Asynchronous motor characteristic

A. Locked Rotor or Starting Torque


- The torque the electrical motor develop when its starts at rest or zero speed.
- A high Starting Torque is more important for application or machines that are hard to start
- E.g. good for positive displacement pumps, cranes etc.
- A lower Starting Torque can be accepted in applications as centrifugal fans or pumps where the start load is low or close to zero



Asynchronous motor characteristic

B. Pull-up torque


- The minimum torque developed by the electrical motor when it runs from zero to full-load speed (before it reaches the breakdown torque point)
- When the motor starts and begins to accelerate the torque in general decrease until it reach a low point at a certain speed - the pull-up torque - before the torque increases again
- The pull-up torque may be critical for applications that needs power to go through some temporary barriers achieving the working conditions



Asynchronous motor characteristic

C. Break-down torque


 Highest torque available as the torque decreases when the machine continues to accelerate to the working conditions.



D. Full-load (Rated) Torque or Braking Torque

 The Full-load Torque is the torque required to produce the rated power of the electrical motor at full-load speed.

Asynchronous motor characteristic



Asynchronous motor characteristic


E. No-load speed


- Speed reached when no load is present
- Essentially reaches synchronous speed

Starting 3 phase induction motors

Induction motor staring currents can be very high. Solution is to:

- Start the motor in star connection
- When the motor has gained sufficient speed the change connections to delta connection!







- Start connection leads to full supply voltage across two coils
- to full supply voltage across each coil

Starter devices are commercially available

Choosing an induction motor


0.33

- Decide on
- 1 or 3 phase
- Power output
- Rotational speed (2 or 4 pole)
- Continuous or intermittent
- Physical motor size
- Etc.



Dimensions (mm) - 1 and 3 Phase





Part No. 6330210

Specification - 3 Phase

Specification - 1 Phase						
	kW	Pole (speed)	Frame	Volts	Wt (kg)	Part No.
}	0.25	2 (3000)	63	230	4.6	6310203
,	0.55	2 (3000)	71	230	7.2	6310208
)	1.10	2 (3000)	80	230	10.3	6310214
)	1.50	2 (3000)	80	110	11.9	6310226
)	2.20	2 (3000)	90	110	16.8	6320228
			4	_	_	
-	tar De	Ita			1000	
			(3)	-1	-	
		Line			-	
		bined		(a)	_	
	ressu				Sec.	
		arters				-
- /	lvailal	ole	E	THE	ALC: U	
Se	e Pag	e 22	Direct (n-Line	Pres	sure

ROCO222: Intro to sensors and actuators

Lecture 9

Single phase induction motors


Single phase induction motors

- Single-phase motors are used mostly to operate home appliances
- E.g air conditioners, refrigerators, pumps, and fans
- Designed to operate on 120 V or 240 V
- They range in capacity from fractional horsepower to several horsepower depending on the application






Single phase induction motor magnetic field




- A single phase field does not rotate
- However the field still changes sinusoidally with time
- Such a field can be considered as two counter rotating magnetic field phasors
- It turns out if rotor rotates, one rotating phasor will exert more torque on the rotor than the other
- Therefore if rotor already moving it will develop torque can be driven by the stator field
- Therefore motor will run if we can think of a way to get it started

Split phase induction motors

- To get an induction motor started need to setup a rotating field!
- A rotating magnetic field can be produced with a two-phase system
- Split phase induction motors split the current flow through two separate windings to simulate a two-phase power system
- Two phases can be produced by splitting a single phase
- There are two main types of split-phase motors depending on the means of starting




Inductance: Current lags applied voltage




Capacitance: Current leads applied voltage

The capacitor-start induction motor




- The stator consists of the main winding and a starting winding
- The starting winding is connected in parallel with the main winding and is placed at right angles to it
- A 90-degree electrical phase difference between the two windings is obtained by connecting the auxiliary winding in series with a capacitor and a starting switch
- When the motor is energized, the starting switch is closed
- This places the capacitor in series with the auxiliary winding

The capacitor-start induction motor



- This gives an RC circuit (starting winding and the capacitor) and an RL circuit (main winding)
- The currents in each winding are therefore 90° out of phase, so are the magnetic fields that are generated
- When nearly full speed is obtained, a centrifugal device (the switch) can be used to cut-out the starting winding
- The motor then runs as a single-phase induction motor


The resistance-start induction motor



The out-of-phase condition between start and run winding current is caused by the start winding having more resistance than the run winding. Specifically:

- The main winding has a high inductance and a low resistance.
- The current lags the voltage by a large angle
- The starting winding have a low inductance and a high resistance
- The current lags the voltage by a smaller angle

The resistance-start induction motor





The amount of starting torque produced is determined by:

- The strength of the magnetic field of the stator
- The strength of the magnetic field of the rotor
- The phase angle difference between current in the start winding and current in the run winding (maximum torque is achieved when these two currents are 90° out of phase with each other)

Shaded pole induction motor

- Stator is made from a magnetically soft laminated core with a coil wound around it
- Rotor is generally made up of a squirrel cage rotors
- This has a magnetically soft laminated core with pure aluminum wires among its length that are shored at the ends






Shaded pole induction motor operation


- Induction motors need a rotating field to get them to start rotating
- AC single phase supply to coil generates a magnetic field that does not rotate but field changes sinusoidally and changes direction once per period
- Short circuit around end of pole sections (ht e shaded pole) cause a delay in build up of magnetic field at that point

 When combined with main flux path this gives rise to a weak rotating magnetic field at the poles that enables the motor to start



Shaded pole induction motor

- Motor is stable and reliable, low noise level and without electro magnetic interference
- Exhibits low starting torque due to weak field rotation
- Has low efficiency since short-circuit wastes power
- Widely used in low load starting home appliances, e.g fans, washing machine pump motors






ROCO222: Intro to sensors and actuators

Lecture 9


Other types of AC motors

Synchronous AC motors

- Similar to the induction motor in that it is a poly-phase machine in which the stator produces a rotating field
- A synchronous motor is also similar to an brushless DC motor, but the latter is commutated to ensure synchronous operation
- However the rotor is constructed from either
- Electromagnets energized by direct current supplied through slip ring
- Permanent magnets
- Fixed speed applications such as clocks and timers




Reluctance motor





- Magnetic flux seeks the path of least reluctance
- This is an AC motor that operates much like a reluctance stepper motor

Linear induction motor

Like an AC induction motor that has been opened out and laid flat







SMOOTH THE ROTOR INTO SEPARATE SHEETS