

Date	Category	Type	Reporter	Device	Location	Issue	Reason	Solution	Link to documents	Ver
05.01.25	Sensors	Bug	Jonathan	MPS24	Bar-Ilan1	Error with EC sensor. 16.12.24 the EC sensor ENV-40-EC-K1. 0 began to gradually reduce the readings. At the time of replacement the sensor showed values of about 5	The reason is unknown. Recalibration did not give results. The data from the sensor is unstable, the values jump. Cleaning with special E.C. Probe Cleaner also did not help.	Replacing the sensor		
04.02.25	Wires	Bug	Jonathan	MPS28	Holon-4	The power button doesn't light up green	Incorrect wiring connection	Replacing wire set		
27.02.25	Wires	Bug	Jonathan	MPS29	Modi'in-2	27.02.25 MiniPC stopped starting. At the same time, the modem in the device continued to work	The Qijie connector connected to the input of Qijie splitter 1-2 burned out due to poor contact	Replacing connector		
31.01.25	Electronics	Bug	Jonathan	MPS33	Azor-2	The device is offline from 31.01.25	The contact between the Modem power wires in the power splitter has been lost.	Recheck all connections		
01.02.25	ML	Event	Jonathan	MPS31	Holon-1	Most of the time the device detects Iron-Y in water	There is a suggestion that the model in this device is faulty TBD	A decision was made to replace the device with another one. 05.03.2025 the MPS31 was replaced with MPS38. TBD	Iron-Y in water.png	
17.03.25	Sensors	Event	Jonathan	MPS36	Modi'in-3	The sensor pH is faulty	By mistake, controllers with s/n:009 were installed instead of s/n:006, sensors were with s/n:006	Replacing sensors set with s/n:023	The sensor pH is faulty.png	
20.03.25	Electronics	Update	Jonathan	22, 24, 25	all	TP-Link modems sometimes lose internet connection. To restore it you need to physically reboot the modem.	Common network equipment error	To avoid potential problems in the future, a schedule was set to automatically reboot Tp-link modems every Saturday at 00:00	TP-Link Reboot Schedule.png	
27.02.25	Electronics	Event	Jonathan	MPS34	Lab	MiniPC stopped starting.	The CMOS battery inside the MiniPC is low	CMOS Battery Replacement		
20.04.25	Electronics	Bug	Jonathan	MPS37	SmartCities1	The ventilation system is not working	The Relay module for fans is faulty	20.04.2025 the relay was replaced		
09.04.25	Optic	Bug	Jonathan	MPS38	Holon-1	The light intensity dropped to minimum values	The light bulb burned out	21.04.25 the device was returned to the lab for replacement of the light source and recalibration.	The light bulb burned out.png	
10.04.25	Electronics	Bug	Jonathan	MPS28	Holon-4	The device and the Modem are offline	DC IN Qijie connector burned out	21.04. 25 DC IN wires updated with version v. 3.1.1 instead v.2.1.7		
21.04.25	Sensors	Bug	Jonathan	MPS28	Holon-4	The device returns an error when reading data from sensors	The wires are loosely clamped in the PCB Plug (J2). At the same time, the ESP32 controller continued to work. But when trying to read data from the PCB, the program returned an error	Strengthened wire fastening in the PCB Plug (J2)		
28.04.2025	Electronics	Bug	Jonathan	MPS15	Lab	The PCB sn:009 that was installed in the MPS15 doesn't read data from the sensor EC.	A possible reason could be that the last time we calibrated the sensors on this device, we left the calibration mode for the sensor for a long time. In this mode, it reads data from the sensor every second.	Replacing the PCB		
07.05.25	Electronics	Event	Jonathan	MPS26	Lab	MiniPC stopped starting.	The CMOS battery inside the MiniPC is low	CMOS Battery Replacement		
01.06.25	Mechanical	Event	Jonathan	MPS26	Lab	StepIM Motor stopped working	TBD	TBD		
30.07.25	Electronics	Bug	Jonathan							