Inspection report (sample data)

Site: Skyline Residency Clubhouse **Unit:** M-121, Daikin VRV IV RXYQ10 (rooftop outdoor unit)

Reported: unit not cooling, display shows E3 (high-pressure / compressor protection trip) three times in one week.

Findings

- Supply voltage measured at 189 V under load, below the 200 V the unit expects.
- Compressor contactor coil scorched; contacts pitted.
- Refrigerant pressures normal. Compressor draws normal current when it runs.

Actions

1. Replaced the compressor relay board. The unit tripped again the same afternoon.
2. Replaced the compressor contactor (DK-CTR-24V). The unit ran for the whole test period without a trip.

Recommendation: raise the supply voltage issue with the building electrician. Do not replace the relay board on this model for an E3 trip.