# BOILER B-301 ANNUAL INSPECTION REPORT

Inspection date: 2026-08-12

Inspector: Inspection Department

Scope: shell, tubes, burner, pressure relief valve and flue gas thermocouple.

Findings:

1. Tube fouling and scale deposits were found on the fire-side tubes of Boiler B-301, reducing heat transfer efficiency.
2. Minor corrosion was observed on the economiser tubes near the lower header.
3. The pressure relief valve lifted at 10.2 bar against a set pressure of 10.0 bar, which is within tolerance.
4. The flue gas thermocouple showed reading drift of 6 C.

# RECOMMENDATIONS - BOILER B-301

- Clean the fouled tubes by chemical flushing during the next shutdown.
- Calibrate or replace the flue gas thermocouple.
- Re-inspect the corroded economiser area within 90 days.

Compliance: this inspection was performed in accordance with IKI-REG-12.
Next boiler safety inspection due: 2027-02-08.
Prepared by the Inspection Department.