

REPORT DATE 07 September 2026	WORKER ID OIL-W-104
SITE / FACILITY Duliajan Oilfield — Well Pad 12, Assam	SHIFT Day Shift (08:00–16:00)
LOCATION ON SITE Wellhead maintenance area, near pipeline manifold	INCIDENT TYPE NEAR MISS

SIF RISK STATUS: PENDING SIFRA AI ANALYSIS — submit to ML + RAG pipeline for classification

INCIDENT DESCRIPTION

While performing routine maintenance on the wellhead manifold, a contract worker was tightening a flange bolt on a pressurized line when the pressure gauge suddenly spiked beyond the expected range. The work permit indicated the line had been isolated and depressurized, but a secondary valve downstream was later found to be only partially closed. As the worker leaned in with a wrench, a small hissing sound was heard from the flange joint and a brief release of gas/vapor occurred at low pressure before the crew immediately stopped work, retreated to a safe distance, and alerted the site HSE supervisor. No injury occurred and no fire/ignition source was present at the time. The line was fully isolated, verified with a lockout–tagout tag, and re-tested before work resumed two hours later.

IMMEDIATE ACTIONS TAKEN

- Work stopped immediately by the crew lead.
- Area cordoned off and gas detector readings taken (within safe limits).
- Site HSE Officer notified within 10 minutes.
- Isolation verified with a second competent person before resuming work.

CONTRIBUTING FACTORS (WORKER-OBSERVED)

- Energy isolation / LOTO verification was not independently double-checked before work start.
- Work permit sign-off may have been completed before the secondary valve confirmation.
- No qualitative pressure test was performed at the point of work before hands-on activity began.

WORKER'S OWN ASSESSMENT

Classification: Near miss — no injury, but could have resulted in exposure to pressurized hydrocarbon release if the worker had been in direct line of fire of the flange gap at higher pressure.

LIKELY RELEVANT IOGP LIFE-SAVING RULES

Rule	Relevance
Energy Isolation	Secondary valve not fully closed despite permit sign-off.
Line of Fire	Worker positioned directly at flange joint during pressure spike.
Work Authorization	Permit approved isolation status not independently re-verified on site.

This document is a structured incident intake record prepared for submission to the SIFRA AI ML Fatality Risk Model (XGBoost V2) and Hybrid RAG engine. Final SIF risk classification, violated barriers, root-cause analysis, and IOGP citations will be generated upon pipeline processing and issued as a separate Trust Report.