

Page 1 of 4

Doc. No.: WI-MTC-07

Rev. No.: 00

Date: 15/10/2022

Purpose: To know the steps of camera calibration in mono parc wafer.

Scope: This procedure covers the all steps of in cell camera adjusment /

calibration in mono parc wafer.

Responsibility: HOD Maintenance


Procedure:

• Place the cell in 1st transport and let it came to 3rd transport.

- Place the cell in inner table . Put the machine in mannual . Click the single step button, rise the table to the upper waiting position and place the wafer on the center of table.
- Position of the wafer in table as per the below pic:



- Log in with proper authorization.
- Click the vision on the main page. Open the DP camera page.



Prepared by Approved by




Page 2 of 4

Doc. No.: WI-MTC-07

Rev. No.: 00

Date: 15/10/2022

- Click the Grab button. Four pattern will occure and four template will visible.
- Select PrintPattern Click Grab Frame the 4 make points in the figure Click Register Mark and save Exit the interface after saving.



• Similar process complete in Calibpattern (Screen Mark).



Prepared by Approved by




Page 3 of 4

Doc. No.: WI-MTC-07


Rev. No.: 00

Date: 15/10/2022

- Make sure in both cases mode should be "On image" as shown in green circle in above picture.
- Next step will be screen fiducial calibration which should be perform after every screen change.
- Click the change screen button on the main page.



• Select Change Screen Calib Choose Pattern Select DP Camera Image



Prepared by

Approved by



Page 4 of 4

Doc. No.: WI-MTC-07

Rev. No.: 00

Date: 15/10/2022

• Prepare two silicon wafers and place them on the transport rail Click Inner, after the printing of the machine is completed, check whether the 4 make points have been captured. If the graphics are not captured, please match them manually Click Outer, After the machine is printed, check whether the 4 make points have been captured. If the graphics are not captured, please match them manually Click Calc Rotate Center, after the calibration of the inner and outer countertops is completed. After the calculation results come out, will be saved and exited.



Now all steps are completed.

Prepared by	
-------------	--