

UltraVision Touch 3.8R11

Limitations and Remaining Anomalies



Table of Content

Table of Content	2
IMPORTANT MESSAGE.....	3
Fixed Anomalies	4
NDT Paintbrush	4
Pump button does not work.....	4
TOPAZ16 – NDT PaintBrush – Pitch and Catch GE probes cannot be configured using Calculator	Erreur ! Signet non défini.
WELD Crawler	4
Ruler fork is at wrong position on wedge	4
Setup and Inspection	4
Autocrossing Gates (disabled in version 3.8R7).....	4
TCG Split Sector Calibration	5
TOPAZ Instruments	Erreur ! Signet non défini.
TOPAZ16 – A Pitch and Catch channel does not show a warning message for probe overlap	5
Message for FPGA update when instrument is booted with a Hypertronics splitter connected.....	7
Limitations and Remaining Anomalies.....	6
Setup	6
TOPAZ16 – Protection mode can cause installation to rollback	6
TOPAZ16 – F1 and F2 buttons can't be configured	6
TOPAZ16 - Impossible to create TCG point with gain lower than channel gain.....	6
TOFD Calibration	6
Split Sector Calibration - Nothing is showing you which sector you're calibrating	7
Reset Scan button for Clicker Indexer.....	7
Analysis and reporting	7
Uncorrected Sectorial Scan is not available.....	7
C-Scan Stitching using Difference Gate.....	8
Custom Info fields are reset when clicked a second time	8

IMPORTANT MESSAGE

UltraVision Touch 3.8R11 is the latest UltraVision release in UltraVision software. This new version incorporates TOPAZ16 support and a series of new features and improvements as described in the Product Bulletin document.

Zetec is committed to the highest levels of product quality. Some limitations and remaining anomalies were detected during the validation campaign and are listed in this document.

If using UltraVision Touch 3.8R11 you detect any other limitations or remaining anomalies not included in this document, please contact us at the address: Support-UTProducts@zetec.com. Detailed information about the problem will help our software team to expedite the correction process.

FEDERICO ZOTTIG

UT Product Manager

Zetec

418.263.3678 (office)

fzottig@zetec.com

Fixed Anomalies

NDT Paintbrush

Pump button does not work

Status:	Anomaly	B1723
Description:	Remote pump control button on scanner does not work.	
Correction:	Water pump button function on NDT PaintBrush has now been reactivated.	

WELD Crawler

Ruler fork is at wrong position on wedge

Status:	Anomaly	B1742
Description:	Creating a setup with the Proposed Setup tool does not give the same position as manually creating the same setup.	
Correction:	Fork offset references are unified when a setup is manually created or using the Propose setup tool.	

Setup and Inspection

Scan plan Presentation for Circumferential Weld Inspection

Status:	Limitation	B2027
Description:	Because of the perspective in the Calculator views, when a scan offset is added on a welded pipe, the view is correctly displayed.	
Correction:	View is correctly to display the correct offsets.	

Autocrossing Gates (disabled in version 3.8R7)

Status:	Limitation	B1797
Description:	When Gates are set to <i>Autocrossing</i> mode (detection threshold is changed according to the maximum signal amplitude detected) some unwanted side effects	

have been detected on this feature. Autocrossing mode is temporarily disabled for improving its performance.

Correction: Autocrossing gates computing is improved and gate Crossing (-6dB) is now reactivated.
Autocrossing Crossing (-12dB) not yet available.

TCG Split Sector Calibration

Status: Anomaly | B2056

Description: It is possible to calibrate a single TCG point for each sector, but trying to calibrate another point disables the Compute button.

Correction: Each sector must be confirmed for the first point, then each sector can be confirmed for the second point.

TOPAZ¹⁶ – A Pitch and Catch channel does not show a warning message for probe overlap

Status: Anomaly | B2058

Description: When Transmitter / Receiver probes overlap, the calculator doesn't generate an error message.

Correction: A warning message is shown when Transmitter / Receiver probes overlap.

No warning for low SSD space

Status: Anomaly | B1904

Description: No warning when booting an instrument with low SSD space available.
No warning when trying to save a file without enough SSD space. Data files could be corrupted at saving if no enough disk space available.

Correction: After a unit is booted, a warning is displayed if available disk space is below 25%.
After a Data File is saved, a check for remaining disk space is performed. If there is less than 10% free disk space remaining, a warning will be displayed.

Limitations and Remaining Anomalies

Setup

TOPAZ¹⁶ – Protection mode can cause installation to rollback

Status:	Anomaly B2072
Description:	When installing a new software version, it may cause the installation process to rollback. This may also happen when booting TOPAZ ¹⁶ , switching to remote mode and coming back to Touch interface. In this case, the views will show no data, and the sectorial scan will be completely grey.
Bypass:	If the installation rolls-back, it is necessary to re-install the software.

TOPAZ¹⁶ – F1 and F2 buttons can't be configured

Status:	Anomaly B2060
Description:	F1 and F2 buttons on the right side of the TOPAZ16 are not functional.
Bypass:	None. To be implemented in next release.

TOPAZ¹⁶ - Impossible to create TCG point with gain lower than channel gain

Status:	Limitation B2036
Description:	When creating a TCG point, the gain can't be lower than the Channel gain.
Bypass:	None.

TOFD Calibration

Status:	Limitation B1208
Description:	When changing the crossover parameter in a TOFD calibration, no warning message is displayed to avoid losing all existing TOFD calibration parameters.
Bypass:	None.

Split Sector Calibration - Nothing is showing you which sector you're calibrating

Status:	Limitation B1148
Description:	Split sector calibration doesn't clearly display the sector separation.
Bypass:	None.

Reset Scan button for Clicker Indexer

Status:	Anomaly B1982
Description:	The Reset Scan button of the clicker indexer does not do when set to Yes.
Bypass:	None.

Message for FPGA update when instrument is booted with a Hypertronics splitter connected

Status:	Anomaly B1833
Description:	When the TOPAZ is booted with a splitter connected, a window pops up asking for a FPGA update. If the FPGA update is accepted, it won't be possible to connect TOPAZ to UltraVision and there won't be any data throughput. Then it is needed to re-install UltraVision to fix.
Correction:	When booting a TOPAZ, do not connect a splitter to the instrument until boot process is finished. If a TOPAZ is booted with a splitter connected and the Update Firmware popup window appears, Do not click on YES for the FPGA update. Connect the splitter after booting is finished.

Analysis and reporting

Uncorrected Sectorial Scan is not available

Status:	Limitation B1979
Description:	There is no uncorrected sectorial scan in UVTouch
Bypass:	None.

C-Scan Stitching using Difference Gate

Status:	Anomaly	B1854
Description:	When selecting a Difference Gate before executing a C-Scan Stitching, only the stitched C-Scan for that Difference Gate is created and other gates are not included.	
Bypass:	Select another gate than the Difference Gate before clicking on the Merge button.	

Custom Info fields are reset when clicked a second time

Status:	Limitation	B1729
Description:	For both the Application Info fields and for the Indication Table Info Fields, when a "Custom" set of fields is defined, clicking on custom a second time wipes the content of the "Custom" set.	
Bypass:	None.	

Quality

All work is done in accordance with ZETEC Quality standards program, which complies with 10CFR50 Appendix B, ISO 9001:2008 and ISO/IEC 17025:2005.



Toll free: 800.643.1771 (USA)

info@zetec.com

www.ZETEC.com