

GLOBAL RISK SERVICES

# WORKERS' COMPENSATION RISK ASSESSMENT REPORT

|                  |                                 |                   |                   |
|------------------|---------------------------------|-------------------|-------------------|
| Account Name:    | Precision Castings & Components | Survey Date:      | 2026-03-04        |
| Policy Number:   | WC-84223-2026                   | Surveyor Name:    | Marcus Vance, CSP |
| Insured Address: |                                 | Industry Segment: |                   |

## EXECUTIVE SUMMARY

Precision Castings & Components operates a mid-sized machining and die-casting facility. The general safety culture is functional but inconsistent. Operational controls exist for primary hazard areas, but there are critical gaps in routine safety administration. Specifically, overhead crane inspection logs are outdated, and coolant mist condensation on shop walkways presents an active slip hazard. Management needs to standardize safety guidelines to prevent recurring minor laceration claims at grinding stations.

## DETAILED FIELD OBSERVATIONS & RISK EVALUATION

### 1. Lifting (Industrial Ergonomics) — ADEQUATE

**Hazard Context:** Industrial ergonomics and lifting hazards related to handling heavy sheet metal raw stocks and dies.

**Field Observations:** Pneumatic manipulator arms are available for loading core molds onto die machines. However, heavy hand-grinding parts (averaging 45 lbs) are still manually lifted from pallets to grinding tables. Ergonomic floor mats are present but worn.

**Risk Control Recommendation:** Provide adjustable-height scissor lifts at all manual grinding tables to minimize lower-back bending and repetitive heavy lifting. CNA RISK CONTROL SERVICES WORKERS' COMPENSATION FIELD REPORT

## 2. Lacerations / Cut Safety — LIMITED/INCONSISTENT

**Hazard Context:** Control of puncture and cut injuries stemming from raw sheet metal handling and grinding operations.

**Field Observations:** While the company has a standard cut-resistant glove policy, compliance was observed to be inconsistent. In the secondary grinding and de-burring area, two out of five workers were operating without cut-resistant gloves, claiming the gloves limit precision. This inconsistent PPE usage correlates with three minor laceration claims filed in Q4 2025.

**Risk Control Recommendation:** Implement a mandatory glove policy compliance check by supervisors at the start of every shift. Procure higher-dexterity cut-resistant gloves to address employee precision concerns.

## 3. Material Loading / Unloading & Securement — ADEQUATE

**Hazard Context:** Forklift and heavy machinery operations involving loading flatbeds and storage yard logistics.

**Field Observations:** Forklift drivers are fully certified, and safety walkways are painted. Flatbed loading is performed in a designated rear bay. Load-strapping is completed using manual steel banding tools, which are stored in proper racks when not in use.

**Risk Control Recommendation:** Provide workers on the loading docks with hand-protection guards on the steel band tensioning tools to prevent pinch injuries.

## 4. Overhead Lifting Equipment — LIMITED/INCONSISTENT

**Hazard Context:** Use and structural integrity of overhead cranes, hoists, rigging slings, and crane hooks.

**Field Observations:** The surveyor reviewed the inspection logs for the two bridge cranes in the heavy machining bay. The annual third-party check was completed (May 2025), but the mandatory daily and monthly maintenance records were blank for January and February 2026. Two nylon slings in active use showed minor fraying near the eyelets.

**Risk Control Recommendation:** Enforce daily pre-use inspections of bridge cranes and immediately document them. Destroy and discard the frayed nylon rigging slings to prevent heavy load drops. CNA RISK CONTROL SERVICES WORKERS' COMPENSATION FIELD REPORT

## 5. Machine Guarding & Electrical Safety — ADEQUATE

**Hazard Context:** Physical point-of-operation machinery guards and electrical Lockout/Tagout procedures.

**Field Observations:** Guards are present on primary lathe spindles and machining centers. However, a manual drill press in the maintenance department was operating with its spindle guard swung to the side. Lockout/Tagout kits are present, but the written machine-specific LOTO logs were missing for three out of five CNC routers.

**Risk Control Recommendation:** Re-install and interlock the drill press guard. Draft and post laminated, step-by-step LOTO instructions on the CNC routers immediately.

## 6. Occupational Disease & Illness — ADEQUATE

**Hazard Context:** Control of employee exposure to noise, toxic fumes from welding, and hexavalent chromium.

**Field Observations:** Industrial air extraction hoods are located in the primary welding bays. Hearing protection signs are posted in grinding areas, and earplugs are provided. The local air filter units appeared to have dark dust accumulation, suggesting they are close to capacity.

**Risk Control Recommendation:** Schedule immediate replacement of welder extraction hood HEPA filters. Conduct noise mapping of the grinding bay to verify compliance.

---

## 7. Walking / Working Surfaces — LIMITED/INCONSISTENT

**Hazard Context:** Housekeeping, fluid leaks, slip-and-fall hazards, and floor maintenance.

**Field Observations:** Oil and coolant mist condensation was noted on the floor of CNC machining aisles #3 and #4, creating slick surfaces. Spill cleanup stations are located near the bay entrance, but maintenance response times are slow. Safety cones were not deployed around the slick surfaces.

**Risk Control Recommendation:** Install overhead mist collector units above the CNC machines to capture airborne coolants before they settle on concrete floors. Deploy safety cones immediately around any detected leak.

---

## 8. Elevated Work Surfaces — ADEQUATE

**Hazard Context:** Stairs, platforms, fall arrest harnesses, and elevated mezzanine structures.

**Field Observations:** The maintenance supply mezzanine is equipped with a compliant top and mid-rail guardrail system and a standard 4-inch toe-board. The access stairs are slip-resistant and in good repair.

**Risk Control Recommendation:** Maintain regular inspections of the self-closing safety gate at the top of the mezzanine stairs.

---