



LINE MOLEING/PIPE CLEANING

CHECKLIST (Manual)



- ☐ All team members must understand and practice hand signals for “Turn on Water”, “Pressure Up/OK to begin blasting”, and “Cut Pressure”
- ☐ Understand pipe size and layout

Safety Devices

- ☐ Select appropriate backout preventer
- ☐ Utilize stinger, if necessary – total rigid length of tool assembly should be at least 1.5 diameter of pipe
- ☐ Test the safety device before pressuring up – pull on the hose to ensure that the tool catches on the backout preventer

Pressurizing the System

- ☐ Mark the hose conspicuously at 2', 4', and 6' from the tool
- ☐ Insert the tool at least 24" into the tube before activating the dump
- ☐ Use **clear hand signals** and maintain line of sight with the pump operator
- ☐ Signal to the pump operator to pressurize the system, activate the dump until the required pressure is achieved
- ☐ Test the dump valve before starting to clean



LINE MOLEING/PIPE CLEANING

CHECKLIST (Manual) - CONT.



Pipe Cleaning – Oscillating Technique (Loop and Feed)

- ☐ Use proper hand position – hands 24” apart, knuckles facing up, the hand closest to the pipe has a loose grip, allowing the hose to rotate
- ☐ The hand further from the pipe turns 180 degrees towards the front hand, into a “palm up” position – achieve oscillation of the hose
- ☐ Feed the hose in 12-18” sections, making sure to back flush frequently to avoid blockage or hydraulicing

System Pressure Down

- ☐ Release foot pedal to dump pressure
- ☐ Signal pump operator to shut down pump, maintaining line of sight with pump operator
- ☐ Maintain control of the hose – do not leave unattended until the pump is completely shut down