
**PART NUMBER 56219-02K** 

## Center Support/Direct Drum Sleeve

## 56219-02K

1 Sleeve

Note: Fits '96 & earlier bushing style center supports only.



## **Instructions:**

1. Remove OEM sleeve from the center support.

Note: This may be done by cutting the sleeve with a die grinder and splitting with a chisel. Extreme caution must be used to avoid cutting the center support (especially in the sealing ring area) and to avoid gouging the aluminum with the chisel.

- 2. Apply Loctite® 609 to the inside of the replacement sleeve.
- 3. Press the sleeve onto the support.
- 4. Remove any residual Loctite®.
- 5. Air check the forward clutch circuit.
- 6. If the fit of the direct drum bushing is tight, hone the direct drum bushing as necessary.

