Troubleshooting Guide - Robot Dispensing Cell D2

Document no.	TS-ROB-004	**Revision**	B
Document type	Troubleshooting Guide	**Status**	Current
Effective date	2026-03-02	**Owner**	Maintenance
Classification	Internal		

1 Scope

This guide helps maintenance technicians to find the cause of the most common alarms of the sealant dispensing cell D2 on line L2. Before entering the cell, apply LOTO according to MP-LOTO-002.

2 Alarm codes

Code	Meaning	Likely cause	Action
E-101	Sealant pressure low	Cartridge empty or air in the line	Change cartridge, vent the dosing pump
E-102	Sealant pressure high	Nozzle blocked	Replace nozzle 1.2 mm, do not clean with wire
E-205	Vision: bead interrupted	Air bubble, nozzle too far from the part	Check nozzle height 1.5 mm, vent the system
E-207	Vision: bead too wide	Robot speed too low, nozzle worn	Check speed 120 mm/s, replace nozzle
E-310	Robot collision detected	Part not seated in fixture	Check fixture pins, reference the robot
E-412	Safety door open	Door switch faulty or door not closed	Check door switch, never bridge it

3 Venting the dosing pump

1 Put the cell in manual mode.

2 Hold the purge container under the nozzle.

3 Press PURGE on the HMI for at least 20 s until the sealant flows without bubbles.

4 Wipe the nozzle and run one test bead on a test plate.

4 Escalation

If the same alarm occurs more than 3 times in one shift, open a maintenance ticket and inform the process engineer. Repeated E-205 alarms were one of the causes in 8D-2026-017.

5 Revision history

Rev	Date	Change
A	2025-05-19	First issue
B	2026-03-02	E-205 / E-207 vision alarms added