

Deviation Report DEV-2602-001

Deviation Number: DEV-2602-001. Related Batch: MP-PCM-2602. Date Raised: 2026-02-14. Raised By: Priya Nair. Category: In-process quality check failure - tablet weight out of specification.

Description: During routine in-process weight verification, tablets produced on Machine TCM-04 were found to average 612mg, exceeding the upper specification limit of 600mg. Operator Priya Nair immediately halted the compression run and notified Shift Supervisor Rajesh Kumar.

Root Cause Investigation: Maintenance Engineer Anita Desai inspected Machine TCM-04 on 2026-02-15 and identified a worn punch tip in station 6 of the upper punch set, along with visible degraded punch tooling causing inconsistent fill depth. Wear and tear on the punch assembly beyond acceptable tolerance was confirmed as the direct root cause.

Underlying Cause: Cross-reference with the Machine TCM-04 maintenance history showed that the scheduled preventive maintenance checkup mandated by SOP ENG-007 (due 2026-01-30) had been missed. The maintenance team, led by Suresh Iyer, had not performed the punch inspection and replacement cycle required at the 90-day interval.

Corrective and Preventive Action (CAPA): Replace worn punch tooling on TCM-04. Reinforce scheduling compliance for SOP ENG-007 across all compression machines. Batch MP-PCM-2602 was rejected and will not be released.