

Table of Contents

Change Control and Document Register

Document: ECO-EEG-016 **Revision:** C **Date:** 1 September 2026, corrected 2 September 2026 **Issued by:** TI One Voice research programme (one.witysk.org), Brussels, Belgium **Licence:** CC BY-SA 4.0 **Governing documents:** DSN-EEG-003 Rev D, then RFQ-EEG-001 Rev E. Where this document and `tools/design.py` disagree, `design.py` governs.

Revision note, Rev A to Rev B. The routing-scope change is renumbered from ECO-EEG-016 to ECO-EEG-018 so that no change shares a number with this document; nine further changes (ECO-EEG-019 to ECO-EEG-027) are recorded; the enlargement of the carrier to 150.0 × 130.0 mm and its move from two layers to four are recorded inside ECO-EEG-018, which is the change that found them; the document register is rewritten with the revision letter of every document in the 1 September 2026 correction release, with the document identifiers that the package cites but never registered, and with the statement, which Rev A omitted, that nothing has been built.

Corrections within Rev B, made on 1 September 2026, closing the findings of the second cross-document audit that name this document. RUL-EEG-021 and SIM-EEG-018 are registered in section 1.1; every revision letter this document states is brought to the letters of that section and the escape clause that let citations drift is withdrawn; the numbers ECO-EEG-028 and ECO-EEG-029 are withdrawn and their two findings are recorded inside ECO-EEG-018, which is where RUL-EEG-021 puts them; the claim that the board is DRC-clean is replaced by what `kicad/EEG-CAR-01_RevB_DRC_report.txt` actually reports; and the MP-01 slot geometry is corrected to the 12 × 3 mm that `tools/mech_gen.py` cuts. The revision letter is deliberately not advanced: these are corrections inside the same release.

Correction within Rev B, made on 2 September 2026: the board closed. The DRC now reports **zero violations and all 145 nets connected**, so the fabrication-release gate of section 3 is met and that section is rewritten to say so. ECO-EEG-018's routed-result table carries the current figures and **section 2B records what was changed to close the board and what closing it cost.** *That paragraph said the fabrication data was released for review under RFQ-EEG-002A and not for fabrication, because no human layout engineer had read the routing. It is superseded at Rev C: one has read it, declined the review and advised a redesign, and Rev B is withdrawn from fabrication – ECO-EEG-030.* The revision letter was not advanced for the 2 September correction: it was a correction inside the same release.

Further corrections within Rev B, made on 2 September 2026, closing the findings of an independent external review of the package that name this document. TOOL-EEG-022 Rev A is registered in sections 1.1 and 1.5, having shipped, and been cited by two released documents, while this register said that a document not on its list is not part of the release; the three workbooks in `docs/` and the built webtest page are named in section 1.2 as the generated artifacts they are; RFQ-EEG-002A and RFQ-EEG-002B are ruled in section 1.3 as scopes of work rather than documents. Every production-simulation total this document states is brought to the run of 2 September 2026 – *171 passed, 0 failed, 5 open at the time this note was written; superseded later the same day by 193, 0 and 6, see section 1.1* – and the total in the C-01 row of section 2A is

marked as the history it is. **ECO-EEG-019's claim that the Sallen-Key corner tolerance in TST-EEG-004 "is widened to match" the X7R substitution is withdrawn:** no such limit existed to widen, and E-11's low-pass half was not met with the approved parts – *it is met later the same day on C0G parts, which is recorded under ECO-EEG-019 and does not revive the withdrawn sentence.* **Section 2D is added,** recording the firmware and test-tool defects found and closed on the same day. The revision letter is again not advanced: these are corrections inside the same release.

Further corrections within Rev B, made on 2 September 2026, after the firmware was built and after four requirements moved. Section 1.6 is added, registering the four released trees that were on no list at all – fixtures/, records/, kicad/wh-bus-01/ and the provisioning and ATECC tooling under firmware/tools/. That is the defect of section 1.3 reappearing in the register for the second time, now against shipped data rather than against a document, while section 1.1 went on saying that what is not on its list is not part of the release. **Section 1.2's claim that everything under kicad/ is produced by emit_all.py from design.py is corrected:** kicad/wh-bus-01/ is written by tools/wh_bus.py, which imports nothing from design.py and is not called by emit_all.py. **Every production-simulation total this document states is brought to the run of 2 September 2026 – 193 passed, 0 failed, 6 open –** and the claim that the simulator wrote this register's copy of that total is **withdrawn:** it writes SIM-EEG-018 and nothing here, which is exactly why the figure could drift and did. **Section 2E is added,** recording the first real ESP-IDF build, the five defects it found, the emulator run and the provisioning opcode collision. **ECO-EEG-024 is implemented,** so S-02 is met in the design at 36.8 μ A; **E-11's low-pass half is met** on C0G parts; **E-27's phase driver is written;** and the bias-lead topology finding of section 2C is fixed. Each of those is corrected where this document states it, with its date, rather than deleted. The revision letter is again not advanced: these are corrections inside the same release.

Nothing in this package has been manufactured, assembled or measured, and no safety engineer has reviewed this design. Every figure marked *calculated* is a calculation. Every ECO below that is marked *implemented* is implemented in the design source, not in copper. That statement is repeated in every controlled document on purpose.

The firmware is the single exception to "nothing has been built", and it is a narrow one. Since 2 September 2026 it compiles against a real ESP-IDF – v5.2.5, target esp32s3 – and the four images in firmware/release/ with the SHA-256 manifest beside them are that build; it has also run one boot cycle under QEMU. **It has never run on hardware, because no unit exists,** and the emulator carries none of the peripherals the firmware talks to. Built is not run, and run in an emulator is not brought up. Section 2E states what that build and that run do and do not prove.

Why this document exists

Package v1 had no change control and no document register. Revisions were recorded inside each document's own front matter, so nothing said which revisions belonged together, nothing recorded why a change was made, and a manufacturer holding four files had no way to tell whether they were the same release. Worse, the same part identifier meant two different parts in two documents and nobody noticed, because there was no register to notice it in.

Package v2 Rev A fixed the part-identifier namespace and then reproduced the same failure in its own: it numbered one of its changes ECO-EEG-016, which is also this document's number, and it registered twenty-one documents while the package went on

to cite eighteen more that were on no list at all, six of them colliding numerically with documents that are. Rev B closes both.

This document does four things: it registers every controlled document and its current revision; it names the identifiers the package cites that are **not** controlled documents, and says what they are instead; it records every engineering change from package v1 to v2, with the reason, the verification and the impact; and it states the procedure for the next change.

1. Document register

1.1 Controlled documents

Every controlled document in package v2, at the revision released on 1 September 2026. A document not on this list is not part of the release. Section 1.3 deals with the identifiers that other documents cite and that are not on this list, and **section 1.6, added on 2 September 2026, deals with the released data sets that carry no document identifier at all**. Until section 1.6 existed, four substantial trees – fixtures/, records/, kicad/wh-bus-01/ and the provisioning tooling under firmware/tools/ – shipped inside a release whose own register said that what is not listed is not part of it.

ID	Title	Rev	Status	Governs
DSN-EEG-003	Manufacturing design package	D	released	architecture, carrier, precedence – the governing document
RFQ-EEG-001	RFQ and engineering specification	E	released	requirements and acceptance (M/S/O), pricing
ICD-EEG-006	Interface control document	C	released	module interfaces, jumper schedule, GPIO map
SCH-EEG-005	Schematic set, 8 sheets	B	generated	the circuit
DSN-EEG-002	Helmet design and assembly	E	released, not reissued in this round	helmet, electrodes, wiring, fitting, case
PARTS-EEG-019	Part identifier register	B	released	every part number in the package
ASM-EEG-007	Assembly work instructions	B	released	how one unit is built
WH-EEG-008	Harness and cable assembly	B	released	every cable, every conductor

ID	Title	Rev	Status	Governs
TST-EEG-004	Production test specification	C	released	what every unit is tested to, and it owns the T-numbers
JIG-EEG-009	Test fixture design	C	released	the fixtures TST-EEG-004 needs, FIX-01 to FIX-04
QP-EEG-010	Quality plan	B	released	IQC, FAI, AQL, records, traceability
RISK-EEG-011	Risk analysis and safety review pack	B	released as an input	the pack the safety reviewer receives
REG-EEG-012	Regulatory and compliance file	B	released	RoHS, REACH, UN38.3, CISPR, 60601 gap analysis
SVC-EEG-013	Service and refurbishment manual	B	released	the turnaround between participants
IFU-EEG-014	Participant quick-start and placement guide	B	released	what goes in the case lid
PKG-EEG-015	Packing, labelling and shipping	B	released	packing list, labels, foam, lithium shipping
ECO-EEG-016	Change control and document register	C	released	this document
AVL-EEG-017	Approved vendor list	C	released	sourcing, alternates, substitution
SIM-EEG-018	End-to-end production simulation report	A	released, generated	the dry run of the manufacturing route against the data package
FW-EEG-001	Firmware build and provisioning	D	released	firmware, build, provisioning, host tool, key fingerprint
MECH-EEG-020	Printed part drawings	A	generated	dimensioned drawings of every printed part

ID	Title	Rev	Status	Governs
RUL-EEG-021	Rulings register	B	released	one answer to each cross-document disagreement, cited by section letter
TOOL-EEG-022	Connectivity test program: specification, technical description and user manual	A	released	the browser tool that tests the USB link, and the browser client the study reuses
LAY-EEG-034	Carrier layout rule sheet	A	released, generated , issued 8 September 2026	the rule set the external layout contractor works under, and part of the order specification. Written by tools/emit_rule_sheet.py from tools/rules.py, so it and kicad/EEG-CAR-01_RevC.kicad_dru cannot disagree

ID	Title	Rev	Status	Governs
ASM-EEG-023	Register of programme assumptions	B	released, issued 2 September 2026	every open question the completeness audit left that was a DECISION rather than a missing file, each decided, attacked by an independent reviewer and re-decided against that attack. Twenty-three entries at Rev B , eleven of which block a build, three of which cannot be decided from what exists. The twenty-third, MECH-D6-MODULE-ENVELOPES, is new under ECO-EEG-033 and blocks a build. Nothing in it is a sign-off

Four entries need reading carefully rather than counting.

SIM-EEG-018 is a report written by `tools/simulate_production.py` on each run. **The run behind this issue prints 193 passed, 0 failed and 7 open**, and that is what its own file states because the simulator wrote it. **It is not the same 193 as the run of 2 September 2026.** Six checks were added under ECO-EEG-030 to ECO-EEG-033 – the Rev C input set assembled, the schematic matching the design source, every footprint audited, Rev B regraded, the rule sheet issued, the collision check run – and **six were lost, because cadquery could not be installed on the machine this round was run on**, so the HM-04/HM-05B bayonet fit and the HM-01P channel section were not measured. The two happen to cancel. A passed count is a count of the checks that RAN, and a run on a machine with cadquery would print 199. It is a file in `docs/`, but it is never edited by hand: it is the output of the last run, and a correction to it is a correction to the simulator or to `design.py`. **The last run, of 8 September 2026, reports 193 checks passed, 0 failed and 7 open items**, and `docs/SIM-EEG-018_RevA_production_simulation.md` states those three figures because the simulator wrote that file. **It did not write this one.** Rev B said the totals agreed “because the simulator wrote both”; that is false and is **withdrawn on 2 September 2026**. The copy in this section is typed by hand from the run, which is precisely how it came to stand at 171 while the report had moved to 193, and it is checked against the report rather than trusted.

The six open items of that run are: the static IRAM pool, which links with **one byte free of 16,384**; the carried-over v1 HM-01 mesh, which is watertight and is two disconnected

bodies; that **no human layout engineer has read the routing**, which is the fabrication-release gate of section 3; that **E-27 has never been seen to light** – the phase driver is written and the current budget is met, but no unit exists, so TST-EEG-004 T11 has not been run; the unreconciled board current; and that **SR-01 is closed in the design and not yet signed off** – S-02 is met at 36.8 μA because ECO-EEG-024 was implemented, and applying the fix an analysis pointed to is not the same as having it approved.

Four figures, four dates, and only the last one is the total. 169 passed, 0 failed, 5 open at the 1 September 2026 issue, whose first open item was the 25 DRC violations; 171, 0 and 5 earlier on 2 September; 193, 0 and 6 at the last run of 2 September, which is what Rev B stated and is now history; **193, 0 and 7 at the run behind this release, on 8 September 2026.** The seventh open item is that **there is no fabrication data for the current board at all**: Rev B is withdrawn and Rev C is unrouted. The one that was there and has changed its words is the layout review – a human layout engineer HAS now read the Rev B routing, which is why Rev B is withdrawn, and what is open is the review of the CONTRACTOR'S PLACEMENT of Rev C, which cannot happen until there is a placement.

The two 193s are not the same 193 and the coincidence is worth a sentence, because section 1.1's rule is that a passed count moves when the check set moves. Six checks were added in this round and six were lost, and they cancel: added are the Rev C input set assembled, the schematic matching the design source, every footprint audited against its part number, Rev B regraded under the ECO-EEG-032 rule set, the rule sheet issued and the collision check run; lost are the six that need **cadquery**, which could not be installed on the machine this round ran on, so the HM-04/HM-05B bayonet fit and the HM-01P channel section were not measured. A run on a machine with cadquery would print **199**. Between the two runs of 2 September, **one item left** the list – E-11's low-pass half, because the Sallen-Key moved to C0G; **two joined it** – the IRAM pool and the HM-01 mesh, both found by measuring things nobody had measured; and **two were restated rather than closed** – E-27's moved from *the phase driver is not written* to *it has never been seen to light*, and S-02's from *the single-fault current fails* to *SR-01 is closed in the design and not signed off*. The DRC violations had left the list before either run, when the report reached zero. The passed count moves because the check set moves and not because anything is graded more leniently. The failed count is 0 in every run. **A total quoted anywhere in this package that is not the total of the last run is stale**, and the total to quote is whatever `tools/simulate_production.py` last printed, not a figure copied between documents – including this paragraph, which is a copy like any other.

RUL-EEG-021 began as an internal audit worksheet, `tools/RULINGS.md`. Four released documents came to cite it, which made an uncontrolled file part of the release by the back door. It is now a controlled document at Rev A and is cited as **RUL-EEG-021 with a section letter** – section A for the geometry taken from the source files, section B for the instrument, section C for the structural rulings. The worksheet under `tools/` is not the controlled copy and is not cited by any released document.

DSN-EEG-002 Rev E is the helmet document. It was not reissued in this correction round, so it still carries the package v1 statement that the microphone preamplifier is on the boom, which RUL-EEG-021 section B and ICD-EEG-006 section 2.9 correct to the MP-01 module plate at J21. Until the next issue of DSN-EEG-002, ICD-EEG-006 governs on that point and DSN-EEG-002 is wrong on it.

TOOL-EEG-022 is the connectivity test program: one self-contained HTML page, `webtest/EEG-Connectivity-Test.html`, built by `webtest/build.py` from the

modules under `webtest/js/`. It is the browser end of the wire format, and the study's own client is the same `protocol.js`, `transport.js` and `sinks.js` with a different sink, so it is production code and not a throwaway page. It was **added to this register on 2 September 2026**, having been written, issued at Rev A and cited by other documents while appearing on no list at all. That is the defect ECO-EEG-015 was raised against in the part namespace and section 1.3 was written to close in this one, reappearing in the register itself: this section states that a document not on this list is not part of the release, so for one release TOOL-EEG-022 was formally not part of a release it shipped in. **FW-EEG-001 Rev D section 5 is normative for the wire format and governs where the tool and the specification disagree**, and TST-EEG-004 owns the T-numbers under which the tool is run – **T30, the host link check** – so a step that uses the tool is cited from TST-EEG-004 and not from TOOL-EEG-022.

1.2 Generated artifacts

Everything under `kicad/`, `kicad/gerber/`, `schematic/` and `graphics/` is produced by `tools/emit_all.py` from `tools/design.py` – **with one exception, corrected here on 2 September 2026: `kicad/wh-bus-01/`**. That directory is the WH-BUS-01 Rev A fabrication set for the contact-light bus board, and it is written by `tools/wh_bus.py`, which `emit_all.py` does not call and which imports nothing from `design.py`, `gerber.py`, `pcbgen.py` or `router.py`. That independence is deliberate – WH-BUS-01 is ten pads and one copper bar, and running it through a 211-part four-layer board's router and DRC would couple two boards that have no reason to be coupled – but it means **re-running `emit_all.py` does not regenerate WH-BUS-01, and does not prove `kicad/` current**. Everything else in the rule stands: these files are not edited by hand, and if one of them is wrong the source is wrong and the fix goes in the source.

The mechanical trees follow the same rule under tools that `emit_all.py` does not call: `mech/stl` and `mech/step` from `tools/mech_gen.py`, with the board-outline STEP and the carried-over HM-01 STL from `tools/emit_extras.py`; `mech/drawings` from `tools/mech_drawings.py`; `mech/renders` from `tools/assembly_render.py`. A full reissue is therefore several commands, not one, and `emit_all.py` alone does not prove the mechanical set current. `firmware/main/board_pins.h` is declared generated from `design.py` and is not: no tool under `tools/` writes it, and `tools/simulate_production.py` only reads it back and checks it against `design.py`. It is maintained by hand against that check, and that is an open item.

Three more trees are generated by tools `emit_all.py` does not call, and until 2 September 2026 no section of this register named any of them: `fixtures/` from `tools/fixture_gen.py` (except `fixtures/firmware/`, which is hand-written), `records/` from `records/make_records.py`, and `kicad/wh-bus-01/` from `tools/wh_bus.py`. Section 1.6 registers all three with the document that owns each.

The three workbooks in `docs/` are in this class and were named nowhere in this register until 2 September 2026. `EEG_kit_BOM_for_bidders_RevC.xlsx`, `EEG_kit_BOM_INTERNAL_RevC_costed.xlsx` and `EEG_kit_manufacturer_contacts_RevB.xlsx` are written by `tools/emit_workbooks.py`, which calls `tools/emit_costed_bom.py` for the second of them, and `emit_all.py` does not call any of it. They carry revision letters in their file names, so they read as controlled documents and are not: they are output, they are not edited by hand, and section 1.4 ranks the kit BOM workbook last in precedence for that reason. The same applies to `webtest/EEG-Connectivity-Test.html`, which `webtest/build.py` inlines from the modules under `webtest/js/` and which TOOL-EEG-022 owns.

The Rev C layout-input set is in this class and is registered here on 8 September 2026 (ECO-EEG-033). `tools/emit_all.py` no longer regenerates the Rev B set – it refuses, and says why (ECO-EEG-031) – and writes these instead, all from `design.py` and none edited by hand:

File	Written by	What it is
<code>kicad/EEG-CAR-01_RevC.kicad_sch</code> and its nine sheets	<code>tools/emit_kicad_sch.py</code>	the native hierarchical schematic, KiCad 8
<code>kicad/EEG-CAR-01.kicad_sym</code>	<code>tools/emit_kicad_sch.py</code>	the symbol library those sheets are drawn from
<code>kicad/EEG-CAR-01_RevC_schematic_netlist_check.txt</code>	<code>tools/sch_netlist.py</code>	the schematic read back and diffed against <code>design.py</code>
<code>kicad/EEG-CAR-01_RevC.kicad_dru</code>	<code>tools/rules.py</code>	the custom design rules, 37 of them
<code>kicad/EEG-CAR-01_RevC_BOM.csv</code>	<code>tools/gerber.py</code>	the BOM, with the substitution column
<code>kicad/EEG-CAR-01_RevC_CPL_SMT_top.csv</code> , ... <code>_CPL_THT_top.csv</code>	<code>tools/gerber.py</code>	provisional placement; the files say so
<code>kicad/EEG-CAR-01_RevC-IPC-D-356A.ipc</code>	<code>tools/gerber.py</code>	the netlist, from the pads alone
<code>kicad/EEG-CAR-01_RevB_regraded_ECO-EEG-032.txt</code>	<code>tools/grade_revb.py</code>	the released Rev B geometry under the new rule set
<code>docs/footprint_audit_RevC.md</code>	<code>tools/footprint_audit.py</code>	every designator's footprint against its part number
<code>kicad/RevC_layout_inputs/</code>	<code>tools/emit_handover.py</code>	the handover set, KiCad 8 : 51 files with a SHA-256 for each
<code>kicad/RevC_layout_inputs_kicad10/</code>	<code>tools/emit_handover.py</code> and <code>tools/kicad_fmt.py</code>	the same set, KiCad 10 , converted by <code>kicad-cli</code> from the above (ECO-EEG-034)
<code>kicad/RevC_layout_inputs_kicad10/EQUIVALENCE_kicad8_vs_kicad10.md</code>	<code>tools/emit_equivalence.py</code>	the two emissions diffed on nine counts; the build fails if any differ
<code>kicad/RevC_layout_inputs_kicad10/drc_kicad10.txt</code>	<code>kicad-cli 10.0.6</code> , driven by <code>tools/kicad_fmt.py</code>	the KiCad 10 DRC report, verbatim

File	Written by	What it is
dist/EEG-CAR-01_RevC_layout_inputs_kicad10.zip	tools/make_portal_zip.py	the portal archive. Not tracked ; emit_all.py does not build it

A second exception to “emit_all.py regenerates it”, found on 9 September 2026 (ECO-EEG-034). tools/emit_rule_sheet.py writes only docs/LAY-EEG-034_RevA_carrier_layout_rule_sheet.md. Its .docx and .pdf come from tools/make_docs.py, which emit_all.py does **not** call – and the .pdf is the copy that travels in the handover set as input 6, the rule sheet the order cites. So a change to the rule sheet that is emitted but not rendered ships a PDF that disagrees with its own Markdown. Both were regenerated under ECO-EEG-034. **Re-running emit_all.py does not prove docs/ is current**, exactly as it does not prove kicad/wh-bus-01/ is.

The vendor RFQ pack is in this class and is registered here on 9 September 2026. Two tools write it, emit_all.py calls **neither**, and nothing under dist/rfq/ is tracked:

File or tree	Written by	What it is
dist/rfq/<vendor>/fields.json	tools/emit_rfq_pack.py	every RFQ answer, machine-readable, each with the design.py symbol or the document and section it came from
dist/rfq/<vendor>/ANSWER_SHEET.md	tools/emit_rfq_pack.py	the same answers for a person to read beside the filled page before submitting
dist/rfq/<vendor>/<board>/	tools/emit_rfq_pack.py	the upload set: the fabrication ZIP copied and checksum-verified, never rebuilt , plus one bundle ZIP carrying the BOM, the CPLs and README_for_bidder.txt
dist/rfq/<vendor>/screenshots/<board>/	tools/rfq_pcbcart.py	every section of the filled form, before submission
dist/rfq/<vendor>/submission_record.json	tools/rfq_pcbcart.py	the page-against-fields.json diff, the deviations, the dialogs seen, and whether anything was actually sent
records/vendor_submissions/	by hand, once per submission	the programme record of what went to which vendor. Not generated: re-running a tool cannot change what a manufacturer already received

tools/emit_rfq_pack.py is vendor-agnostic with a per-vendor profile; tools/rfq_pcbcart.py is one portal's DOM. It fills, screenshots and diffs the page against fields.json, and then **stops**: it submits only when a person confirms at the terminal, or when an explicit --authorised-by is passed and recorded verbatim in the

submission record. Neither route relaxes the two refusals that matter – a page that does not match `fields.json`, or a required field left unfilled, is not submitted whoever authorises it. Two properties are worth stating because they are the reason the pack exists rather than the form being filled by hand:

No figure is typed. Every answer that restates a specification carries the verbatim sentence it came from and the substrings that must appear in it; the build **fails** if a figure no longer appears in its source. Changing the finished thickness in `design.py` and not in the pack stops the build instead of quietly sending a fabricator the old number.

What the form cannot express is recorded rather than dropped. Each canonical answer is either mapped to a control on that portal or declared unsupported with a reason, and the build fails if it is neither. That is what caught the stack-up: **no PCBCart form carries one**, on the assembly route or the Standard PCB route, so DSN-EEG-003 section 3.2 travels in the notes with written confirmation demanded. It is also what caught the inner copper – the form offers 18 um and the specification is 17 um – which is stated to the vendor instead of being silently accepted.

SCH-EEG-005 is in this class. Its revision letter follows the board revision letter in `design.py`, which is **Rev B**, and it is regenerated rather than edited whenever the netlist changes. **It is a picture and not a netlist**, which is finding 7 of ECO-EEG-030; the netlist-bearing schematic is the Rev C set above, and the two are emitted separately for now because `tools/schematic.py` still draws the Rev B PDF. The board is still Rev B after ECO-EEG-019 to ECO-EEG-027, because Rev A was the package v1 carrier and Rev B is the package v2 carrier throughout its drafting.

1.3 Identifiers the package cites that are not controlled documents

Package v2 Rev A registered twenty-one documents and stated that nothing else is part of the release, and then the seventeen documents went on to cite eighteen further identifiers as though they were controlled. Six of those collide numerically with registered documents, which is exactly the failure ECO-EEG-015 was raised to fix in the part namespace. This register owns the document namespace, so it rules on them here.

Withdrawn, because they collide with a registered document. The content is a numbered section of the document that already owns it, and is cited that way.

Withdrawn identifier	Collides with	Cite instead
REL-EEG-009	JIG-EEG-009	FW-EEG-001 section 9 (release and versioning)
PROV-EEG-007	ASM-EEG-007	FW-EEG-001 section 7 (provisioning)
KEY-EEG-008	WH-EEG-008	FW-EEG-001 section 7 (key handling and fingerprint)
SD-EEG-013	SVC-EEG-013	FW-EEG-001 section 10 (microSD file format)
OTA-EEG-014	IFU-EEG-014	FW-EEG-001 section 9 (field update)
CAL-EEG-012	REG-EEG-012	QP-EEG-010 section 12 (calibration record)

Withdrawn identifier	Collides with	Cite instead
ETH-EEG-001, DIS-EEG-001, KPL-EEG-001, QSC-EEG-001, PLG-EEG-001	RFQ-EEG-001	the research documents of section 4, PKG-EEG-015 section 1 (packing list) and PKG-EEG-015 section 4 (quick-start card) as applicable

Not documents at all. ART-LBL-01 to ART-LBL-07, ART-PACK-01, ART-DIS-01, ART-RET-01 and DRW-LBL-PLACEMENT are label and packaging **artwork files** controlled as generated artifacts under graphics/ by PKG-EEG-015 section 5. QF-EEG-006-01 is a **quality form**, controlled by QP-EEG-010 section 8. They keep their identifiers as file names; they are not registered as documents and they carry no revision letter of their own, only the revision of the document that owns them.

RFQ-EEG-002A and RFQ-EEG-002B are scopes of work, not documents. RFQ-EEG-002A is cited in fifteen of the documents in docs/, and it is what the fabrication-release gate of section 3 waits on; until 2 September 2026 no register named it at all. They are defined in RFQ-EEG-001 Rev E section 1.1: **002A** is the review and sign-off of the supplied carrier routing, which is the gate of section 3 below, and **002B** is the prototype builds and complete field kits in three phases. Neither has a file, a revision letter or an author, and neither may be cited as though it had one; the document that carries them is RFQ-EEG-001 at the letter in section 1.1, and a statement about what 002A covers is a citation of RFQ-EEG-001 Rev E section 1.1.

MECH-EEG-020 was cited before it was registered. It is now registered in section 1.1 as a generated artifact. **TOOL-EEG-022 was cited before it was registered too:** two released documents, FW-EEG-001 section 5 and RFQ-EEG-001 Rev E, named it while this register did not. It is registered in section 1.1 and section 1.5 as of 2 September 2026, and what it is is set out under section 1.1.

tools/RULINGS.md and the simulation report were cited before they were registered too, which is the same defect in a worse place: four released documents – TST-EEG-004 section 3, ASM-EEG-007 section 2.2, AVL-EEG-017 and this document at ECO-EEG-020 – cited an uncontrolled worksheet under tools/ as though it were a released document, and several cited the production simulation by name. Both are now controlled documents in section 1.1: the worksheet is issued as **RUL-EEG-021 Rev B** and is cited as RUL-EEG-021 with a section letter, and the simulation report is **SIM-EEG-018 Rev A**. The file tools/RULINGS.md is not a document, is not the controlled copy, and is not cited by anything in the release.

The unit serial-number format is not a document but it was claimed by three of them. It is ruled: **T10V-B-nnnn** – programme prefix, hardware revision letter, four digits, Phase 1 using 0001 to 0009. It is defined once in PKG-EEG-015 section 5 and appears identically in the label text, the Data Matrix, the USB iSerialNumber, the calibration record and the packing list. Every other form that appeared in package v1 and in package v2 Rev A drafts is withdrawn.

1.3A One number pool for documents and for changes

Added 8 September 2026 (ECO-EEG-030). Document identifiers and change identifiers have always been drawn from the same EEG-nnn run, and the register has already been bitten once by that: ECO-EEG-016 is this document and was also, in a package v2 Rev A draft, a change number, so a citation of it was ambiguous everywhere it appeared. That

change is now ECO-EEG-018 and 016 is reserved to the document. The same trap is open at every other number, because ECO-EEG-024 is a change and nothing stops a future document being numbered 024.

The rule from here: a number is allocated once, from one pool, whatever prefix uses it. The next free number is one above the highest number used by either namespace, counting withdrawn numbers as used. Numbers 024 to 029 are **not** available to a document: 024 to 027 are implemented changes and 028 and 029 are withdrawn ones.

Allocated under this rule on 8 September 2026: **ECO-EEG-030**, **ECO-EEG-031**, **ECO-EEG-032** and **ECO-EEG-033** as changes, and **LAY-EEG-034** as a document – the carrier layout rule sheet issued under ECO-EEG-033. The next free number after them is **035**.

1.4 Precedence

Highest first: **DSN-EEG-003** → **RFQ-EEG-001** → **ICD-EEG-006** → **SCH-EEG-005** → **DSN-EEG-002** → **PARTS-EEG-019** → **the kit BOM workbook**. Where a number appears in a document and in `tools/design.py`, **design.py governs**.

1.5 Revision letters in this release

Eight documents advanced a letter on 8 September 2026 under ECO-EEG-030 to ECO-EEG-033, and the set is at the letters in section 1.1: **DSN-EEG-003 to Rev D**; **ECO-EEG-016**, **ICD-EEG-006**, **JIG-EEG-009** and **AVL-EEG-017 to Rev C**; **FW-EEG-001 to Rev D**; **ASM-EEG-023** and **RUL-EEG-021 to Rev B**. **LAY-EEG-034 is new at Rev A**. The bump, the **218** citations that had to follow it and the file renames were done by `tools/revision_bump.py` rather than by hand, because doing it by hand across twenty documents is how this package came to have sixty disagreements in the first place. Three documents the round did not touch keep their letters, deliberately: **PARTS-EEG-019 stays Rev B** because ECO-EEG-031 changed no part identifier, only manufacturer part numbers, which AVL-EEG-017 owns; **RISK-EEG-011 stays Rev B** because none of the four ECOs touches the electrode path, the isolation, the battery, the charge interlock or the patient-current budget; and **RFQ-EEG-001 stays Rev E**, with E-26's self-contradicting switch class recorded as an open item rather than corrected here.

Every document marked in bold in section 1.1 was reissued on 1 September 2026 and its revision letter advanced by one. **RUL-EEG-021**, **SIM-EEG-018** and **TOOL-EEG-022** are new, at Rev A; **TOOL-EEG-022** was issued at Rev A on that date but was not registered here until 2 September 2026, which is a defect in this register and not a second issue of the tool. **ASM-EEG-023 is also new at Rev A and was issued on 2 September 2026**, one day after the rest, which is why it is the one document in section 1.1 whose date is not 1 September. The file names in `docs/` carry the letters, and the letters in section 1.1 are the release.

A cross-reference names a document by its identifier and section, not by its revision. Where a cross-reference does give a letter, that letter must be the one in section 1.1:

Document	Letter to cite
DSN-EEG-003, the governing document	Rev D
RFQ-EEG-001	Rev E

Document	Letter to cite
TST-EEG-004	Rev C
FW-EEG-001	Rev D
DSN-EEG-002	Rev E
ICD-EEG-006, JIG-EEG-009, ECO-EEG-016, AVL-EEG-017	Rev C
SCH-EEG-005, PARTS-EEG-019, ASM-EEG-007, WH-EEG-008, QP-EEG-010, RISK-EEG-011, REG-EEG-012, SVC-EEG-013, IFU-EEG-014, PKG-EEG-015, ASM-EEG-023, RUL-EEG-021	Rev B
SIM-EEG-018, MECH-EEG-020, TOOL-EEG-022, LAY-EEG-034	Rev A

An older letter in a cross-reference is a defect to be corrected, not a synonym. **Rev A of this document said that an older letter “means the same document as corrected in this release”; that escape clause is withdrawn**, because a package whose citations are allowed to drift cannot be checked against itself, which is the failure the whole register exists to prevent. A release is the whole set at the letters in section 1.1 or it is nothing.

Two letters are easy to trip over, and both are correct as written. **The board is EEG-CAR-01 Rev B and stays Rev B** through this correction round, so “an ECO against Rev C of the board” in section 2.3 means the *next* board revision and not DSN-EEG-003 Rev D. **SCH-EEG-005’s letter follows the board’s letter**, not the document round’s, which is why it is B while the documents around it are B or C for a different reason.

1.6 Released data sets that carry no document identifier

Added 2 September 2026. Four trees ship in this release, are relied on by released documents, and were named in no register at all. That is the failure of section 1.3 reappearing for the second time inside the register itself, and on a larger scale than the TOOL-EEG-022 case, because none of these is a single file: fixtures/ alone carries two fixture board sets, seven printed parts and a firmware project. They are **not** promoted to controlled documents – none of them is a document – they are registered here as released data, each with the document that owns it, the tool that writes it, and what it is not.

Tree	What it is	Owned by	Written by	Status
fixtures/	the FIX-01 to FIX-04 test-fixture data: board data for pcb/FIX-01 and pcb/FIX-04, seven printed parts in step/ and stl/, the M1-M3 fixture controller firmware under fixtures/firmware/, and MANIFEST.json with a SHA-256 for every file	JIG-EEG-009 Rev C	tools/fixture_gen.py, except fixtures/firmware/, which is hand-written C	released as fixture data. The two fixture boards are NOT a fabrication set – there is no copper layer on either, and fixtures/README_fixture_data_index.txt says why
records/	the machine-readable per-unit test record: the JSON schema, a worked example record, the lot-summary CSV header and the calibration-certificate template	TST-EEG-004 Rev C sections 12 and 13	records/make_records.py, which reads the step list out of TST-EEG-004 at generation time and fails rather than writes if the document and the table disagree	released, generated
kicad/wh-bus-01/	the WH-BUS-01 Rev A fabrication data for the contact-light bus board: Gerbers, drill, IPC-D-356A netlist, placement and BOM note, and the checksum file	PARTS-EEG-019 Rev B registers the part; WH-EEG-008 Rev B owns the harness it serves	tools/wh_bus.py – not emit_all.py; see section 1.2	released, generated

Tree	What it is	Owned by	Written by	Status
mech/ step/ footprints / and the three Rev C body files in mech/step/	the 3D bodies of ECO-EEG-033: one per footprint class, bound into kicad/EEG-CAR-01_RevC.kicad_pcb; the carrier's component height envelopes; MP-01 and its standoffs; and the thirteen module assemblies as declared maximum envelopes , which are assumptions (ASM-EEG-023 MECH-D6-MODULE-ENVELOPES) and not measurements	ICD-EEG-006 Rev C section 4 owns MP-01; ASM-EEG-023 owns the envelopes	tools/ mech_bodies.py on tools/step_write.py – not tools/mech_gen.py, which needs cadquery and could not be run here	released as body data. NOT a printable part set : they are envelopes, not parts, and no STEP reader has read them
mech/EEG-CAR-01_RevC_collision_check.txt	the interference report of ECO-EEG-033 finding 6	ASM-EEG-023 MECH-D6-MODULE-ENVELOPES	tools/ collision_check.py	released, generated. Three of its four cases are open and one blocks a build
firmware/ tools/	the provisioning station: provision.py and provision_self_test.py, atecc608b_config.py and the three configuration files it writes, calibration_schema.py and its schema, and verify_stream.py	FW-EEG-001 Rev D section 7	hand-written, except the three ATECC configuration files and the calibration schema, which their own generators write and check	released as tooling. ATECC608B_CONFIG_TEMPLATE.md is a PROPOSAL in its own words – not reviewed, never written to a part, not released for production

Two files in that last tree read like documents and are not.
firmware/tools/README_provisioning.md and

firmware/tools/ATECC608B_CONFIG_TEMPLATE.md both open with a Document: line, a licence and a list of governing documents, which is the front matter of a controlled document in this package. **They carry no revision letter and they are not controlled documents:** they are the tooling's own documentation, owned by FW-EEG-001 section 7, and where either disagrees with FW-EEG-001 the specification governs. Front matter does not make a document; section 1.1 does.

Where the boundary is. A tree in this section is part of the release and may be cited by a released document, by path and by the owning document's section. It is not cited as though it had a revision letter, and a statement about what it contains is a citation of its owner in section 1.1. Anything shipped that is on neither list is the defect this section exists to stop, and the next one is raised against this section rather than discovered by an outside reviewer, which is how these four were found.

2. Engineering changes, package v1 to v2

Twenty-six changes: twenty-one to the carrier design, three to the package structure, and two that change a requirement without changing the carrier. That split is the register in section 2.1 counted: carrier is ECO-EEG-001 to ECO-EEG-014, ECO-EEG-019 to ECO-EEG-024 and ECO-EEG-027; package structure is ECO-EEG-015, ECO-EEG-017 and ECO-EEG-018; requirement-only is ECO-EEG-025 and ECO-EEG-026.

Eight of the twenty-six are classed blocking – ECO-EEG-001 to ECO-EEG-004, ECO-EEG-007 to ECO-EEG-009 and ECO-EEG-013 – and every one of them is a package v1 defect that meant the board could not have been built. ECO-EEG-018 is classed scope and carries two further blocking findings of its own, that the board as drafted at 130 × 124 mm on two layers could not have been routed; that is why it is the longest entry in the register. ECO-EEG-024 is classed blocking for Phase 2. Rev B recorded two changes as **not implemented**, ECO-EEG-023 and ECO-EEG-024; **corrected on 2 September 2026, ECO-EEG-024 is implemented** and only ECO-EEG-023 remains open. Both are still addressed to the safety reviewer, because taking a change in the design source is not the same as having it approved: ECO-EEG-024's own row in RISK-EEG-011, SR-01, is closed in the design and unsigned.

ECO-EEG-016 is this document's identifier and is deliberately not used as a change number. The change numbers run **ECO-EEG-001 to ECO-EEG-015 and ECO-EEG-017 to ECO-EEG-027**, which is exactly what the table in section 2.1 contains, what RUL-EEG-021 section B rules, and what DSN-EEG-003 section 9 and RFQ-EEG-001 read the register as containing. In package v2 Rev A the routing-scope change was numbered ECO-EEG-016, so a citation of "ECO-EEG-016" was ambiguous everywhere it appeared; it is now **ECO-EEG-018**.

ECO-EEG-028 and ECO-EEG-029 are withdrawn. A Rev B draft of this document briefly gave the board size and the layer count their own numbers. No ruling creates them, and RUL-EEG-021 section A treats both as findings of the routing work rather than as changes in their own right, so they are recorded inside ECO-EEG-018 under their own headings. Neither number is reused: as with the part identifiers of ECO-EEG-015, a withdrawn number stays withdrawn.

This register is the one home for the change list. DESIGN_FACTS section 7 and DSN-EEG-003 section 9 index the same fourteen changes in their own phrasings; both are indexes, this section is the register, and where they differ this section governs.

2.1 The register

ECO	Class	Subject	Status
ECO-EEG-001	blocking	contact lights had no driver	implemented
ECO-EEG-002	blocking	nothing supplied the 3.3 V rail	implemented
ECO-EEG-003	blocking	there was no charge input	implemented
ECO-EEG-004	blocking	the envelope filter was not in circuit	implemented
ECO-EEG-005	major	rectifier diode pair the wrong way round	implemented
ECO-EEG-006	major	filter in the wrong place in frequency	implemented
ECO-EEG-007	blocking	the board had no mounting holes	implemented
ECO-EEG-008	blocking	the DevKit would not have fitted	implemented
ECO-EEG-009	blocking	the pin map used the PSRAM pins	implemented
ECO-EEG-010	major	four functions declared and not connected	implemented
ECO-EEG-011	major	no analogue reference at the module connectors	implemented
ECO-EEG-012	major	non-plated holes would have been plated	implemented
ECO-EEG-013	blocking	analogue module connectors could not be escaped	implemented
ECO-EEG-014	major	light lines ran through the electrode harness	implemented
ECO-EEG-015	major, documentation	part identifiers meant two different things	implemented
ECO-EEG-017	major, compliance	lithium shipping was never mentioned	implemented
ECO-EEG-018	scope, with two blocking findings	the routing is now supplied, and doing it grew the carrier to 150.0 × 130.0 mm and took it from two layers to four	implemented

ECO	Class	Subject	Status
ECO-EEG-019	major	C1–C16 carried an X7R part number under a COG requirement	implemented
ECO-EEG-020	minor	the board had no fiducials	implemented
ECO-EEG-021	major	the I ² C bus had no pull-ups on the carrier	implemented
ECO-EEG-022	major	VBUS_DET did not reach a guaranteed logic high	implemented
ECO-EEG-023	major	ENV_CMP swings ± 2.5 V into a 3.3 V pin	OPEN, not implemented
ECO-EEG-024	blocking for Phase 2	S-02 single-fault DC fails at 53.2 μ A	implemented 2 September 2026 , was OPEN; S-02 now met in the design at 36.8 μ A and not signed off
ECO-EEG-025	major	F-06's three-minute ring buffer does not fit the PSRAM	implemented
ECO-EEG-026	major	E-04's –100 dB crosstalk is neither achievable nor measurable	implemented
ECO-EEG-027	major	the envelope AC-coupling corner removed the envelope	implemented
ECO-EEG-028	–	withdrawn; the board size is a finding of ECO-EEG-018	withdrawn
ECO-EEG-029	–	withdrawn; the layer count is a finding of ECO-EEG-018	withdrawn
ECO-EEG-030	scope, with seven findings	an external layout engineer read the Rev B board, declined the review and advised redesign; Rev B is withdrawn from fabrication and Rev C is opened as a reviewable design whose layout is bought	implemented 8 September 2026

ECO	Class	Subject	Status
ECO-EEG-031	major	four part numbers could not be bought or could not be fitted: the quad OPA4376 has no SOIC-14, the ferrite bead is not a Murata part, the tactile switch is a 12 x 12 mm part on a 6 x 6 mm land, and the patient-connected DIN sockets were not marked non-substitutable	implemented 8 September 2026
ECO-EEG-032	major	the DRC reported zero violations against a rule set that did not contain six of the seven findings; the rules are now encoded once and exported to KiCad, and Rev B is regraded under them	implemented 8 September 2026
ECO-EEG-033	scope	the Rev C reviewable design set: a native KiCad schematic, an unrouted board and project, 3D bodies and a collision check, and the layout rule sheet LAY-EEG-034	implemented 8 September 2026

ECO	Class	Subject	Status
ECO-EEG-036	correction, with a communication record	closing ECO-EEG-035 so it can be published. The drill-size and plating-allowance gap is closed at source: design.py gains fabrication notes 7a and 7b and DSN-EEG-003 §3.2 gains two rows, so a fabricator is told which diameter is finished, must declare the tool, and is given the external ring separately from the internal one. J15–J17 traced to the root commit and never verified; the requirement is restated without a manufacturer and no verified candidate meets it — every 1.5 mm DIN 42802 part any manufacturer publishes is a panel or cable part, which puts the carrier footprint itself in question before the layout desk places. RISK-EEG-011 gains SR-13 on connector gender, open. ECO-EEG-035’s “a plug and a pin cannot both be right” is withdrawn as over-called. What was stated to manufacturers in error is recorded below	implemented 10 September 2026

ECO	Class	Subject	Status
ECO-EEG-035	scope, with four findings	the gaps eleven mid-quotation manufacturers exposed: the package carried no datasheet index and no third-party licence exclusion; provisioning could be run against a real ATECC608B with the configuration zone admittedly unreviewed; and three kit-BOM module rows read as vaguer than the requirements behind them. Findings: the Stäubli part number at J15-J17 does not appear in either Stäubli catalogue; the ATECC608B template's byte map does not name the 608-specific control bytes; ELECTRODE's proposed widths cost nothing while ANALOGUE_REF's are 58 % of every under-width finding on the board; and the internal annular ring is derived from the finished hole where it is measured to the drilled one. No requirement, limit or governing figure was changed	implemented 10 September 2026

ECO	Class	Subject	Status
ECO-EEG-034	format emission and documentation, with two defects found	the layout desk runs KiCad 10, so the input set is emitted for KiCad 10 alongside the KiCad 8 set from one source and the two are checked equivalent on nine counts; running a real DRC for the first time found that the 37 custom rules had been silently inert, because KiCad discards a .kicad_dru containing a semicolon comment, and that the zoning, no-via and mounting keep-outs forbade the parts they contain. The circuit is unchanged. A third finding, MH2 inside the isolation strip, is raised and not resolved	implemented 9 September 2026

ECO-EEG-001 – the contact lights had no driver

Class: blocking. **Found by:** netlist connectivity check (single-pad nets). **Was:** the eight LED1–LED8 nets existed on the harness connector J14 and nowhere else. The 74HC595 module socket J19 carried only power, ground, the three shift-register control lines and a nominal LED supply pair; the module’s eight Q outputs were not brought to the carrier at all. The contact lights – which the whole self-fitting design depends on, and which DSN-EEG-002 section 5 argues for at length – could not have worked. **Now:** J19 is a 1×16 socket exposing Q0–Q7 as well as OE and MR. Q0–Q7 drive the harness lines through R70–R77 (1 kΩ), giving $(3.3 - 2.0) / 1000 = 1.3 \text{ mA per site and } 10.4 \text{ mA total}$ from GPIO48. The three colours come from eight lines and one common by driving two-lead bicolour LEDs in two phases at a nominal 240 Hz (see FW-EEG-001 and SCH-EEG-005 sheet 8). **Corrected 2 September 2026:** the driver that now exists alternates on the FreeRTOS tick, so the real rate is **about 250 Hz rather than exactly 240**; both halves are equal, so the duty is 50/50 and the colour does not shift. E-27 is written against “above 100 Hz” and 250 Hz meets it. The rate is stated rather than rounded back to 240. **Verified:** every LEDn net is one connected copper island in the DRC connectivity check; the drive current is computed in `tools/simulate_production.py` station 9. **Impact:** J19 pin count, eight new resistors, a firmware change, and a change to the bicolour LED part in the kit BOM. **Was not closed by this ECO, and was closed on 2 September 2026:** Rev B recorded that the bicolour phase scheme was specified and **the driver was not written** – `lights_write()` and `lights_task()` were on/off only, so E-27’s amber state had no implementation and TST-EEG-004 T11 could not pass. **The driver is now written.** Both halves of the ADS1299 lead-off word are read, where only L0FF_STATP was before: one bit per site cannot express three colours, which is where amber had been lost. Neither detector gone is green, exactly one is amber, both is red; green in phase A, red in phase B, amber in both. **What is still open is different and smaller, and it is open item 4 of the simulation run: E-27 has never been seen to light.** No

unit exists, so nothing has been driven and T11 – which reads the red-to-green ratio with a colorimeter – has not been run. A driver that compiles is not a light that is amber. FW-EEG-001 owns the FW-Dnn status.

ECO-EEG-002 – nothing supplied the 3.3 V rail

Class: blocking. **Found by:** netlist connectivity check. **Was:** DVDD3V3 had twelve pads, all of them module supply inputs, and no source. The charger module's SYS output, the ESP32-S3-DevKitC-1's 5 V pin and both ADS1299 module supply pins were unconnected nets. The board could not have powered up. **Now:** the charger's power-path output is VSYS; a TPS63020-class buck-boost module at J25 makes V5V; V5V feeds the DevKit at J6.21 and both ADS modules at J1.11 and J3.11; the DevKit's on-board regulator makes DVDD3V3. R86 pulls the buck-boost enable to VSYS so the rail starts before DVDD3V3 exists. C70–C74 are the bulk decoupling. **Verified:** power tree drawn on SCH-EEG-005 sheet 7; every rail is one connected island. **Impact:** one new module in the BOM, one new socket, six new passives, a change to the pricing template. **Not closed by this ECO:** the carrier draws a **calculated 288 mA worst case** from the DevKit's on-board regulator, which is inside its rating but dissipates about 0.5 W inside a closed pod, so **the rail is not proven**. Phase 1 measures it at TST-EEG-004 T3 and reports the case temperature; see section 2.3.

ECO-EEG-003 – there was no charge input

Class: blocking. **Found by:** netlist connectivity check. **Was:** VBUS_CHG had one pad, on the charger module socket. Nothing brought power to it. RFQ-EEG-001 Rev C E-23 called for “a USB-C connector for charging and data”, which cannot be reconciled with S-03's requirement that no conductive path exist from the host connector to the patient side. **Now:** two separate connectors. Data is the USB-C on the ADuM4160 module and carries no power to the instrument. Charging is a separate charge-only receptacle wired to J24 through F1 (1.1 A PTC) and D24 (transient suppressor), with a divider (R84/R85) giving VBUS_DET on GPIO46. RFQ E-23 has been rewritten to say so and to carry the 45 °C charge inhibit – “charger IC with thermal regulation; no charging above 45 °C” – which is E-23, not S-04. **Verified:** two independent interlocks are described and tested in TST-EEG-004; the current path is drawn on SCH-EEG-005 sheet 7. **Impact:** one panel part, one pigtail, an enclosure opening, a label warning, and a line in the participant card. **Not closed by this ECO:** the divider value was wrong and is corrected by ECO-EEG-022. The **thermistor of S-04 is not fitted and S-04 is not met** – there is no NTC net in design.py and no thermistor way on J12 or J13 – so the 45 °C inhibit rests on the charger IC's own thermal regulation alone. DSN-EEG-003 section 11 and RISK-EEG-011 carry it as an open hardware item. **Also not closed:** the host connector on the named ADuM4160 module is **USB-B while E-24 asks for USB-C**, which is a live non-conformance. The interim answer is a short USB-B-to-USB-C panel pigtail, WH-09, until an isolator module with a USB-C host connector is qualified. The host connection is a socket, not a captive cable; the captive lead through a gland is a Phase 2 item.

ECO-EEG-004 – the envelope filter was not in circuit

Class: blocking. **Found by:** netlist connectivity check (single-pad nets ENVn_F_INM). **Was:** each envelope channel used one dual OPA2376. The second amplifier's inverting input was unconnected and its non-inverting input was tied to AGND_REF, so the Sallen-Key network around it drove nothing and the amplifier's output was an unconstrained buffer of the reference. The 50 Hz filter that RFQ E-11 requires did not exist electrically. **Now:** one OPA4376 quad per channel: A is the precision half-wave rectifier, B is the inverting summer that makes the absolute value, C is the Sallen-Key low-pass with both loops closed, D is the output buffer after the divider. **Verified:** SCH-EEG-005 sheet 3

draws every connection; `simulate_production.py` computes the corner frequency and Q from the fitted values. **Impact:** U1–U3 change from SOIC-8 to TSSOP-14 and from dual to quad; three new resistors per channel.

ECO-EEG-005 – the rectifier diode pair was the wrong way round

Class: major. **Found by:** review of the netlist against the BAT54S datasheet pinout. **Was:** D20.1 was the op-amp output, D20.2 the summing node and D20.3 the rectified node. On a BAT54S, pin 3 is the common point of the series pair, so this connects two anodes into one node rather than forming a feedback rectifier. **Now:** pin 3 is the op-amp output; pin 1 is the rectified node and pin 2 the inverting input. The loop closes for both polarities, which is what makes it a precision rectifier. **Verified:** SCH-EEG-005 sheet 3; the topology is stated in the drawing note. **Impact:** netlist only. Same part, same footprint. **Scope note:** BAT54S is used **only** at D20, D40 and D60, the envelope rectifiers. D1–D16, the electrode clamps, are **BAV99**: Schottky leakage across the series resistor – 47 k Ω when this was written, **68 k Ω since ECO-EEG-024 was implemented on 2 September 2026**, which makes the same argument harder, not easier – is an offset error on a 10 μ V input. TST-EEG-004 T1 is corrected to say so.

ECO-EEG-006 – the filter was in the wrong place in frequency

Class: major. **Found by:** computing the transfer function from the fitted values. **Was:** $R = 33$ k Ω , both capacitors 100 nF. Equal R and equal C in a unity-gain Sallen-Key gives $Q = 0.5$ and a -3 dB point at $0.64 \times f_0 = 31$ Hz, not the 50 Hz ± 10 % of RFQ E-11. **Now:** $R = 22$ k Ω , C to ground 100 nF, feedback C 220 nF $\rightarrow f_0 = 48.77$ Hz, $Q = 0.7416$ (Butterworth), -3 dB at ≈ 50 Hz. The group delay at DC is $1 / (Q \times 2\pi \times f_0) = 4.40$ ms, which is 4.40 samples at 1000 Hz; the $\sqrt{2} / (2\pi f_0)$ form that gives 4.61 ms is only correct at $Q = 0.7071$ and is withdrawn. **Verified:** computed in `simulate_production.py` station 9 and checked against E-11; JIG-EEG-009 section 2.3 carries the derivation. **Impact:** three resistor values and three capacitor values.

ECO-EEG-007 – the board had no mounting holes

Class: blocking. **Found by:** comparing the specification sheet with the board file. **Was:** EEG-CAR-01_PCB_spec_sheet.txt promised “4 $\times$ M3 mounting holes (see placement PDF)” and DSN-EEG-003 Rev A.2 section 3 said “400 of 406 pads; the six unassigned are mounting holes”. Neither was true: the six unassigned pads were the retention posts of the DIN 42802 sockets, and there was no M3 hole anywhere in the file. The assembled carrier could not have been fastened into POD-P1 or into the helmet shell. **Now:** MH1–MH4, 3.2 mm non-plated, at **(5, 5), (145, 5), (5, 125) and (145, 125)** on the 150 $\times$ 130 mm outline of ECO-EEG-018, each with a 6 mm diameter copper keep-out on **all four layers**. The same pattern is carried into the MP-01 module plate and the POD-P1 bosses. The carrier is held to MP-01 on four M3 $\times$ 18 mm nylon hex female-female standoffs with eight M3 $\times$ 6 mm nylon pan screws. **Verified:** on the fabrication drawing, in the NPTH drill file, and in the DRC keep-out check. **Impact:** four holes, a copper keep-out, and matching features on two printed parts.

ECO-EEG-008 – the DevKit would not have fitted

Class: blocking. **Found by:** checking the socket placement against the ESP32-S3-DevKitC-1 mechanical drawing. **Was:** J6 at $x = 70$ mm and J7 at $x = 92$ mm, a 22.0 mm row spacing. The DevKitC-1 header rows are 22.86 mm (0.900 in) apart. **Now:** J6 at $x = 78.0$ and J7 at $x = 100.86$. **Verified:** `simulate_production.py` station 5 measures the spacing from the design source. **Impact:** placement only.

ECO-EEG-009 – the firmware pin map used the PSRAM pins

Class: blocking. **Found by:** checking the pin map against the ESP32-S3-DevKitC-1-N16R8 datasheet. **Was:** LED_SR_DATA on GPIO35, LED_SR_CLK on GPIO36 and LED_SR_LATCH on GPIO37. On the -N16R8 those three pins carry the **octal SPI PSRAM**, which the firmware needs for the ring buffer of RFQ F-06. Using them would have made the ring buffer and the shift register mutually exclusive. GPIO45, also used, is the VDD_SPI strapping pin. **Now:** the shift register moved to GPIO41, GPIO42 and GPIO0, and the microSD interface dropped from four-bit to **one-bit SDMMC** to release them. The sample stream is **50.7 kB/s of frame payload at 1000 Hz** – 1015 bytes every 20 ms – against about 2 MB/s available on one-bit SDMMC, so the headroom is ample. RFQ E-20's "≈70 kB/s" and F-12's "≈64 kB/s" are allowances that include STATUS and SIGNATURE frames and filesystem overhead; they remain the requirement and 50.7 kB/s is the payload figure. J7 positions 11, 12, 13 and 15 are explicitly unconnected and are marked so on the assembly drawing and in `board_pins.h`. **Verified:** `board_pins.h` is generated from `design.py`; the simulator checks that none of the four reserved GPIOs appears in it. **Impact:** firmware pin map, three carrier nets, RFQ E-18 and E-20 wording. **Consequence for J26:** GPIO0 is now LED_SR_LATCH, so J26 way 6 is **NC_GPIO0**, a spare way, and the carrier's J26 is console and recovery only and **cannot** enter download mode. End-of-line flashing goes through the DevKitC-1's own UART USB-C port, which carries the auto-reset circuit on the DevKit itself and is reachable through the MP-01 opening. **Ring-buffer size:** the "12 MB ring buffer" this ECO cited in Rev A was never possible on an 8 MiB part. See ECO-EEG-025.

ECO-EEG-010 – four functions were declared and not connected

Class: major. **Found by:** netlist connectivity check. **Was:** ENV_CMP (the stimulus comparator of RFQ E-12) had one pad and no comparator; MIC_BIAS had one pad; SPARE1 and SPARE2 (the two spare converter channels of RFQ 3.1, "brought out to the connector") had one pad each and no protection; and ROOM_PRE had no source at all, because the room microphone that RFQ E-15 requires had no connector. **Now:** U7 (TLV3201) with its threshold divider, hysteresis and output clamp implements E-12 and it is raised from Should to Mandatory; the electret bias is R89, fitted only if the preamp module does not provide its own (**ICD-EEG-006 section 7.2** gives the decision); the two spare channels get protection networks R15/R16, D15/D16, C15/C16 and are brought to J22; J28 is the room-microphone module socket. **Verified:** every one of those nets is now a connected island; E-12 and E-15 have named test steps in TST-EEG-004. **Impact:** one new device, one new socket, six new passives, two RFQ requirement changes. **Not closed by this ECO:** U7's output logic level is wrong for a 3.3 V input. See ECO-EEG-023, which is open. The **EOG panel sockets on J22 are not fitted in a standard build**; the sockets, their cable and their drawing are a Phase 2 option and PARTS-EEG-019 lists them with no part number yet.

ECO-EEG-011 – no analogue reference at the module connectors

Class: major. **Found by:** review of the module interface. **Was:** neither analogue module connector carried an analogue reference pin, so the module's own reference and the carrier's AGND_REF pour met only through the supply rails. Both modules' AVDD and AVSS were also hard-commoned, which parallels two regulators. **Now:** AGND_REF is on J23.4 and J29.4. Module #2's rails are separate nets (AVDD2, AVSS2) joined to the carrier rails by R92 and R93, which are fitted by default and removed if module #2 regulates its own rails. **ICD-EEG-006 section 7.1** gives the measurement that decides; Rev A of this document cited section 4, which is the mechanical stack, and is corrected. **Verified:**

SCH-EEG-005 sheet 4. **Impact:** two connector pins, two 0 Ω links, one decision recorded in the build record.

ECO-EEG-012 – the non-plated holes would have been plated

Class: major. **Found by:** reading the footprint definitions. **Was:** the six DIN 42802 retention holes were declared (pad "" np_thru_hole circle ... (layers *.Cu *.Mask)). A CAM operator taking a naive export gets six plated barrels with mask openings, in the analogue zone, tying the bodies of the three **touch-proof** EMG sockets to the analogue reference pour. It is a silent defect: the boards look right and fail leakage. **Now:** non-plated pads carry no copper and no mask on any of the four layers, and both they and the four M3 holes are supplied in a separate -NPTH.drl file. The fabrication drawing calls them out. **Verified:** the simulator checks that the non-plated hole count matches the design and that no hole appears in both drill files. **Impact:** footprint definitions, drill output, one fabrication note. **Part status:** the J15–J17 socket itself is **open**. design.py names Stäubli SLB1,5-F as a class, not a confirmed PCB part; a touch-proof 1.5 mm socket with a PCB-mount signal pin and two 1.5 mm retention posts must be sourced and first-articled before Phase 2, and AVL-EEG-017 carries a 12-week lead-time risk against it.

ECO-EEG-013 – the analogue module connectors could not be escaped

Class: blocking. **Found by:** the router failing to reach the inner row. **Was:** J2 and J4 were 2×10 sockets carrying twenty analogue nets between them. With no vias permitted under the module outline, the inner row of a 2×10 has no route out: the outer row's pads block the only direction, and going round the connector needs a corridor wider than the board provides. **Now:** each is split into a 1×10 analogue-signal socket (J2, J4) and a 1×6 rail socket (J23, J29). Every analogue signal pin now escapes sideways on L1. **Verified:** every analogue signal pin on J2, J4, J23 and J29 has a route out on L1 in the released routing. What this ECO closes is that the escape is now geometrically possible, which it was not with two 2×10 sockets; it is not a statement about the board as a whole. The full routing result – which now closes, at zero violations and 145 of 145 nets – is stated once, in ECO-EEG-018, and kicad/EEG-CAR-01_RevB_DRC_report.txt is the authority for it. **Impact:** four connectors instead of two, a change to the jumper schedule in ICD-EEG-006. **Note on the move to four layers.** Going to four layers does not restore the 2×10 option. Vias are still not permitted under a module outline, so the inner row still has no escape, and the split stands.

ECO-EEG-014 – the light lines ran through the electrode harness

Class: major. **Found by:** the router, which could not get eight digital lines from x = 5 mm to the shift register without crossing the whole analogue zone. **Was:** one 22-way harness socket at the far left of the analogue zone carried **twelve electrode conductors – eleven electrode signals and one drain – and ten contact-light conductors, LED1 to LED8 plus LED_V and LED_GND**. DSN-EEG-003 Rev A.2 recorded this as finding 10 and **accepted** it on the grounds that the lights are dark during recording. That was the wrong call: it forces eight digital conductors to run the full width of the analogue zone on the board as well as sharing a cable with eight high-impedance electrode leads. **Now:** two cables and two sockets. A 12-way screened electrode bundle at J14 in the analogue zone, and a 10-way light ribbon at J30 in the digital zone next to the shift register. Conductor count is unchanged at twenty-two; the crossing is gone. **Verified:** the DRC checks that no digital net enters the analogue zone and the simulator checks that no digital net shares the electrode harness. Both results are clean in the released routing: the DRC report records **zero zone crossings**, so no digital net enters the analogue zone. The rest of the routing result, including what is still

open in it, is stated once in ECO-EEG-018. **Impact:** two harness assemblies instead of one (WH-EEG-008), one extra connector, a change to the helmet cable routing in DSN-EEG-002.

ECO-EEG-015 – part identifiers meant two different things

Class: major, documentation. **Found by:** cross-document audit. **Was:** HM-xx was used both as a figure label and as a part number in DSN-EEG-002, and the two namespaces collided. **HM-07 named the boom microphone arm in DSN-EEG-002 section 10 and the battery hatch in DSN-EEG-003 section 4, in the STL set, in the kit BOM and in the RFQ scope.** A manufacturer printing “HM-07” produced a different part depending on which document was open, and the real boom arm and pod hatch had no file under their own identifiers. Section 10 also requires the part ID to be engraved in the model, so the wrong identifier would have been moulded into the part. **Now:** PARTS-EEG-019 is the single register. Figures are FIG-nn; HM-xx is reserved for parts; the battery hatch is HM-08 and its file is HM-08_battery_hatch.stl. A migration table maps every v1 filename to its v2 identifier. **Impact:** one file rename, four documents, the kit BOM and the RFQ scope line. **Extended in Rev B:** the same failure had been reproduced in the **document** namespace. Section 1.3 of this document closes it.

ECO-EEG-017 – lithium shipping was never mentioned

Class: major, compliance. **Was:** every kit contains an 18650 cell and is posted to a participant and back. Package v1 said nothing about UN3481, packing instruction PI967, state of charge, marking or carrier documentation. **Now:** RFQ S-09 is new, REG-EEG-012 section 3 states the obligation and PKG-EEG-015 section 7 gives the procedure for both the outbound and the return leg. The procedure has one home, in PKG-EEG-015 section 7; REG-EEG-012 cites it and does not restate it. **Verified:** the packing list and the shipping label set are checked against PI967 in PKG-EEG-015 section 7. **Impact:** one new requirement, two documents, the outer carton artwork, and a carrier declaration per shipment.

ECO-EEG-018 – the routing is now supplied, and what doing it found

Class: scope, and it carries two blocking findings. **Renumbered:** this change was ECO-EEG-016 in package v2 Rev A, which is also this document’s number. Cite it as **ECO-EEG-018**. RUL-EEG-021 section B rules the numbering and RUL-EEG-021 section A rules that the board size and the layer count are findings of this work rather than changes in their own right; both are recorded below. The numbers ECO-EEG-028 and ECO-EEG-029, which a Rev B draft briefly used for them, are withdrawn. **Was:** RFQ-EEG-002A asked a bidder to route the carrier. **Now:** the routing is supplied, on four layers, and RFQ-EEG-002A becomes a **review** of it. The routing was produced by the programme’s own constraint-aware router and **has not been reviewed by a human layout engineer**; the DRC report lists every connection the router had to relax, so a reviewer can go straight to the tight places. The board did not close when this ECO was first written – 122 of 145 nets, 25 violations – and it closes now; **section 2B records what was changed to close it** and is where the before-and-after belongs.

The routed result. This is the one home for the figures; every other document cites this paragraph or the report behind it, kicad/EEG-CAR-01_RevB_DRC_report.txt, which is the authority. If the two ever differ, the report is right.

Measured	Value	Against
Board	150.0 × 130.0 mm, four layers	–
Track segments	3 745	–
Through vias	552	no blind, buried or filled vias
Reference planes	one continuous island per net, on both inner layers	the star-point rule of DSN-EEG-003 section 3.3
Smallest clearance, L1	0.260 mm	0.20 mm rule
Smallest clearance, the planes	0.285 mm	0.20 mm rule
Smallest clearance, L4	0.275 mm	0.20 mm rule
Narrowest conductor	0.20 mm	0.20 mm minimum
Connections the router had to relax	169 – 36 narrower than the 0.25 mm preferred width, 133 at full width with a reduced gap	every one at or above the 0.20 mm minimum conductor and gap
Smallest plated hole	0.30 mm	0.30 mm rule
Digital nets in the analogue zone	zero zone crossings	none permitted
AGND_REF-to-DGND bridges	exactly one, at R90	exactly one
HARN_SHIELD-to-DGND bridges	exactly one, at R91	exactly one
Duplicate copper	zero segments, zero via positions	none
Nets fully connected	145 of 145 , none without copper	145
Violations	0	zero to release fabrication data

Nothing in the rule set is breached. The report's own line is "VIOLATIONS: 0 – none. The board passes every rule listed above": no clearance violation – the two vias that sat 0.328 mm from an electrode net are gone – and no width, annular-ring, hole-size, board-edge, non-plated-hole, isolation keep-out or via keep-out violation. The isolation keep-out is worth naming, because an earlier routing put inner-plane copper inside it: **the strip at x ≥ 141 mm is now free of copper on all four layers, and the report says so.** It is free because the keep-out is now enforced against copper edges rather than track centrelines (section 2B). That is the only ground on which the sentence may be repeated. Anyone about to write it in another document reads the report first.

What that does not settle. The board passes every rule it was given, on 169 connections by taking the tightest geometry those rules allow. **A board that closes at minimum geometry is not the same board as one that closes at preferred geometry, even when every rule passes;** the previous route relaxed 19 connections and this one relaxes 169. Nothing on this board has been manufactured or measured, and no human layout engineer has read the routing.

The gate of section 3 is therefore met and the fabrication data in kicad/ is RELEASED FOR REVIEW under RFQ-EEG-002A. It is NOT RELEASED FOR FABRICATION, and what holds it back is now the review rather than the report: no human layout engineer has read this routing. Reviewing the whole routing – the 169 relaxed connections first – correcting what is wrong and signing it off is the scope of RFQ-EEG-002A. No document in this package may say that the fabrication data is released for fabrication, or that boards may be ordered from it, before that review closes, and no document may state a DRC result without reading the report first, which is RUL-EEG-021 section C ruling 4 applied to the layout.

Verified: `tools/emit_all.py` regenerates the board, the pours and the DRC report from `design.py` on every run, and `tools/simulate_production.py` writes SIM-EEG-018. The simulation run that Rev B pointed at predated the routing close and still carried the DRC violations as an open item. **Corrected 2 September 2026: the run behind this release is later than the close** – 193 passed, 0 failed, 6 open – **and carries no DRC item at all**, because the report records no violations. **Impact:** RFQ section 1.1, section 8, the pricing template, and the covering email.

ECO-EEG-018, first finding – the carrier would not close at 130 × 124 mm

Class: blocking. **Found by:** doing the layout. The router could not close the board at the package v1 size. **Was:** the carrier was specified as **130.0 × 124.0 mm**. Package v1 asserted that size and never routed it. Thirty connectors, 211 parts and 156 nets do not fit: the escape corridors around the module sockets, the 6 mm mounting keep-outs, the isolation keep-out at the right edge and the 0.35 mm electrode-net clearance together leave no channel wide enough to get the analogue zone out to the converters. **Now:** the carrier is **150.0 × 130.0 mm**. The extra 33.8 cm² of bare board costs a few euro per unit at these quantities, against a real risk of an unroutable design; that is not a close trade. Everything dimensioned from the outline moves with it: mounting holes to (5, 5), (145, 5), (5, 125), (145, 125); the zone split to **x = 62 mm**, analogue left and digital right; the isolation keep-out to **x ≥ 141 mm, y = 2 to 22 mm**, no copper on any layer. **The enclosure grew with the board:** POD-P1 base **163.0 × 143.0 × 58.0 mm external and 158.0 × 138.0 × 55.5 mm internal** with 2.5 mm walls and a 1.6 × 1.2 mm gasket groove; POD-P1 lid **163.0 × 143.0 × 6.0 mm** with a 2.0 mm spigot; MP-01 module plate **146.0 × 126.0 × 3.0 mm** with an 8 mm solid border, a field of **12 × 3 mm jumper slots on a 16 × 7 mm grid**, Ø2.7 mm M2.5 fixing holes between the slot rows and one 31 × 61 mm opening over the DevKit. The slot figure is a size, not a count: `mech_gen.py` cuts each slot with `.slot2D(12.0, 3.0, 0)`. The stack budget is floor 2.5 + boss 6.0 + carrier 1.6 + standoff 18.0 + plate 3.0 + modules ≤ 18.0 = **49.1 mm against 55.5 mm internal, a margin of 6.4 mm**. **Verified:** `design.py` BOARD_W and BOARD_H, the fabrication drawing note 1, the DRC outline and keep-out checks, and `mech_gen.py` for every printed part. **Impact:** the board specification in DSN-EEG-003 section 3.2, every mechanical dimension in ICD-EEG-006 section 4, PARTS-EEG-019 sections 2.2 and 2.4, the MECH-EEG-020 drawing set, the foam schedule in PKG-EEG-015, the bare-board price, and the Phase 2 helmet shell, which was sized for a carrier that no longer exists and is recorded as such in RFQ M-01. **Consequence for the standoff argument:** the slant path from carrier copper, over the edge of the isolation keep-out and up the 18 mm

standoff to any host-side conductor on MP-01 is ≥ 18 mm, more than twice the 8 mm the safety case asks for. RISK-EEG-011 SR-08 is closed by that, and the claim in Rev A that the standoff is not dimensioned is withdrawn.

ECO-EEG-018, second finding – two layers cannot carry both the routing and the reference

Class: blocking. **Found by:** doing the layout. This is the single most important thing package v2 learned by doing the work instead of asserting it. **Was: two layers, F.Cu and B.Cu.** Package v1's architecture argument was that a two-layer carrier is cheap and easy to route, and package v2 Rev A repeated it. Actually laying the board out showed that it is not true. On two layers the bottom side has to be both the continuous reference plane and the second routing surface, and it cannot be both: every track routed on the bottom cuts the pour that the analogue traces above it are referenced to. What comes out is a swiss-cheesed pour with return currents taking whatever path is left, which is precisely what DSN-EEG-002 section 13's "layout rules that are requirements, not preferences" forbids. The zoning, star-point and isolation rules that the same layout has to satisfy are DSN-EEG-003 section 3.3. **Now: four layers – L1 signal, L2 reference plane, L3 reference plane, L4 signal.** That gives two full routing surfaces and a continuous reference under every analogue trace. The reference planes are split the same way on both inner layers: **AGND_REF left of x = 62 mm and DGND right of it, on both L2 and L3**, tied together by stitching vias, with AGND_REF joining DGND at R90 only and HARN_SHIELD joining DGND at R91 only. **Stack-up:** mask / 35 μ m L1 / prepreg 0.200 / 17 μ m L2 / core 1.065 / 17 μ m L3 / prepreg 0.200 / 35 μ m L4 / mask = **1.60 mm $\pm$ 10 %**, FR-4 with $T_g \geq 150$ °C, outer copper 1 oz and inner copper 0.5 oz. **Vias: through vias only.** No blind, buried, back-drilled, filled or plugged vias, at **0.60 mm pad on a 0.30 mm finished hole** with a 0.15 mm annular ring, tented both sides. The smaller via than package v1's 0.80/0.40 is what makes the escape corridors fit; through vias only is what keeps the board a class 2 commodity four-layer job rather than an HDI one. **Cost:** at 2 units a four-layer board is about €35 more in total; at 50 units it is about €3 per board. For a sixteen-channel EEG front end that is the right trade, and it is a real answer to package v1's cost argument rather than a refusal of it. **Verified:** design.py fabrication note 2 and the layer map in kicad/gerber/README_layer_map_and_checksums.txt; the pour and stitching checks in the DRC report, which records each reference plane as one continuous island per net; the layer count and stack-up on the fabrication drawing. The counts are in the routing-result table above. **Impact:** the board specification in DSN-EEG-003 section 3.2, the Gerber layer map and the checksum file, the fabrication drawing, the IPC-6012 class 2 / IPC-A-600 class 2 fabrication scope, the bare-board price line in the RFQ pricing template, the electrical-test netlist, and the argument in DSN-EEG-003 section 2 that package v1 made for two layers, which is withdrawn.

ECO-EEG-019 – C1–C16 carried an X7R part number under a C0G requirement

Class: major. **Found by:** cross-document audit, reading the Murata dielectric code in the part number against the requirement in the same table. **Was:** every document demanded C0G for the electrode-input capacitors and TST-EEG-004 T00 made X7R a hard reject, but the named part was GCM188R71H103KA37D, whose R7 code is X7R. A buyer running the AVL-EEG-017 section 8 checklist line "the order does not contain the word X7R against that line" could not execute it, because the part number itself is an X7R part. The same defect appeared at C21/C41/C61, named as "100 nF C0G 50 V" against GCM188R71H104KA57D, also X7R. **Now: C1–C16 are Murata GCM1885C1H103JA16D**, 10 nF, C0G, 50 V, 0603.

Corrected 2 September 2026, and the correction changes the answer for C21/C41/C61. Rev B recorded that there was no fix of that kind for the Sallen-Key capacitors, because **a 100 nF C0G in 0603 at 50 V is not a stocked part**, and specified them as **X7R with a stated $\pm 15\%$ capacitance tolerance over the operating range**, Murata GCM188R71E104KA57D, with the C0G requirement holding at C1–C16 and **deliberately not met** at C21/C41/C61. That stood for one day. The fix was to stop asking for 100 nF: scale the capacitors down by ten and the resistors up by ten, and f_0 and Q land where they were on parts that exist. **C21/C41/C61 are now 10 nF C0G – the same GCM1885C1H103JA16D this board already buys sixteen of – C22/C42/C62 are 22 nF C0G GCM1885C1H223JA16D, and R25/R26, R45/R46 and R65/R66 are 215 k Ω .** Same 0603 footprints, same nets, no new purchasing line, and the board does not move: it is a BOM change. The only X7R parts left in the envelope channels are C23/C43/C63 and C24/C44/C64, the AVDD and AVSS decoupling at U1–U3, where the dielectric is not an E-11 question; design.py carries them as “100n X7R 25V”, GCM188R71E104KA57D, whose E code is the 25 V the value string states.

Withdrawn on 2 September 2026: the sentence “and the Sallen-Key corner tolerance in TST-EEG-004 is widened to match”. It described a test limit that did not exist. Before T12e was written there was no f_0 limit in TST-EEG-004 to widen, so nothing was widened and the requirement was not made met by this change; TST-EEG-004 section 16 item 16 says so against this ECO by name. What was true was narrower and worse: **T12e measures and records f_0 per unit against 42 to 58 Hz, which was the band the fitted X7R parts could hold and is wider than RFQ E-11’s 50 Hz $\pm 10\%$** , so E-11’s low-pass half was **not met with the approved parts** and no widened E-11 limit existed to appeal to. Either E-11 had to be restated to that band or a stocked C0G part had to be qualified; at the time neither had been done, and it was carried as RFQ-EEG-001 Rev E section 12 item 15 and TST-EEG-004 section 16 item 16. A dielectric substitution that a test limit is said to accommodate is a substitution nobody has to argue for, which is why the sentence is withdrawn here rather than quietly reworded.

Superseded later the same day: the second of those two alternatives was taken. A stocked C0G part was qualified – the 10 nF the board already buys – and the network was rescaled around it, so **E-11’s 50 Hz $\pm 10\%$ low-pass half is met in the design**: design.py computes $f_0 = 49.9$ Hz with $Q = 0.742$ unchanged, and C0G’s $\pm 5\%$ with no temperature coefficient holds the corner inside **47.6 to 52.6 Hz** against a 45 to 55 Hz band, where the X7R network ranged 42.4 to 57.4 Hz and no build of it could have been held inside. **The withdrawal above stands and is not softened by this**: no test limit was ever widened, and what closed E-11 was changing the parts, not the limit. T12e’s 42 to 58 Hz band was set around the X7R spread and is now wider than the fitted parts need; whether TST-EEG-004 restates it is TST-EEG-004’s, and this register does not restate a limit it does not own. E-11 is met **in the design**: nothing has been built and no corner has been measured.

Verified: the part numbers are in design.py and flow to the BOM and the CPL through emit_all.py; AVL-EEG-017 section 1.2 and QP-EEG-010 section 2.3 carry the same numbers. **Impact:** two AVL lines, the incoming-inspection check, and the BOM. **No test limit was widened by this change**; T12e’s 42 to 58 Hz band is set by TST-EEG-004 and is a measurement recorded per unit, not an acceptance of E-11.

ECO-EEG-020 – the board had no fiducials

Class: minor. **Found by:** assembly review. ASM-EEG-007 section 2.2 recorded that design.py placed no fiducial footprints and proposed a two-point vision teach on the

plated pads of TP14 and TP10, priced by the manufacturer. **Was:** no global fiducial anywhere on the board. Teaching a placement machine on test-point pads is slower, less repeatable and a per-lot cost for no reason. **Now: three 1.0 mm round copper fiducials with 3.0 mm mask openings**, FID1 to FID3, at **(12.0, 10.0), (144.0, 100.0) and (12.0, 120.0)** in `design.py`. The vision-teach workaround is withdrawn. **RUL-EEG-021 section B** now carries the same three positions. Its first issue transcribed them as (8, 8), (142, 8) and (8, 122); that error is corrected in the register, and under section 1.4 `design.py` governs in any case. RUL-EEG-021 is a controlled document at Rev A and is registered in section 1.1; the `tools/RULINGS.md` worksheet it grew out of is not cited. **Verified:** the footprints are in the placement file and the fiducial layer of the assembly drawing. **Impact:** three footprints, one assembly-drawing note, and one deleted paragraph in ASM-EEG-007. Panel fiducials remain the fabricator's choice.

ECO-EEG-021 – the I²C bus had no pull-ups on the carrier

Class: major. **Found by:** ICD-EEG-006 section 8 open point 1. **Was:** SDA and SCL reach J6/J7, J8, J11 and J12 and there was **no pull-up resistor anywhere in `design.py`**. The bus depended entirely on whatever pull-ups the purchased modules happened to carry, which is not a design: it changes when a module is substituted, it is not on any drawing, and there is no test that would catch its absence. **Now: R94 and R95, 4.7 kΩ 1 %, from SDA and SCL to DVDD3V3**, in the digital zone at (132, 26) and (132, 30). **Verified:** SCH-EEG-005 sheet 5; the nets are one island each in the connectivity check. **Impact:** two new passives, two AVL lines, one build instruction, and an I²C bus scan in the production test.

ECO-EEG-022 – VBUS_DET did not reach a guaranteed logic high

Class: major. **Found by:** ICD-EEG-006 section 8 open point 2 and TST-EEG-004 T21, which recorded the defect and dispositioned it as “design escalation, not rework”. No ECO had been raised against it, so it would have gone to fabrication. **Was:** R84 = 100 kΩ and R85 = 56 kΩ gives $5 \times 56 / 156 = 1.79 \text{ V}$ at VBUS = 5.00 V, against a guaranteed V_IH of 2.48 V on a 3.3 V ESP32-S3 input. **The first of the two S-01 charge interlocks would not have asserted reliably.** **Now: R85 changes from 56 kΩ to 150 kΩ**, Vishay CRCW0603150KFKEA, giving $5 \times 150 / 250 = 3.00 \text{ V}$, comfortably above V_IH. R84 is unchanged at 100 kΩ. **Verified:** the value is in `design.py`; TST-EEG-004 T21's limit band is restated around 3.00 V; the interlock itself is tested end to end. **Impact:** one resistor value, one AVL line, one test limit band.

ECO-EEG-023 – ENV_CMP swings ±2.5 V into a 3.3 V pin

Class: major. **Status:** OPEN. **This change is specified and is NOT implemented in `design.py`, so the defect it describes is still in the design as released.** **Found by:** cross-document audit of the comparator supply nets against the GPIO it drives. **Is:** U7, a TLV3201, is powered from **AVDD (+2.5 V) and AVSS (–2.5 V)** and its output CMP_RAW therefore swings ±2.5 V. It reaches GPIO3 through R83 (10 kΩ) and the D23 BAV99 clamp to DGND and DVDD3V3, so **the clamp is the only thing between a –2.5 V output and a 3.3 V input**, and the logic-high margin is set by the clamp rather than by design. **Proposed:** power U7 from **DVDD3V3 and DGND** so that the output swings 0 to 3.3 V into GPIO3 with full margin and D23 becomes a belt-and-braces part. The comparator's inputs cannot simply follow: AGND_REF sits 2.5 V above DGND, so the inputs must be **re-referenced to a DVDD3V3/2 divider with the envelope AC-coupled into it**. The TLV3201 has a rail-to-rail input stage that reaches its negative rail, so the topology works, but it moves a signal across the analogue-to-digital reference boundary. **Why it is open:** this is a change to a circuit that straddles the reference split, and **the safety and layout reviewer must check it before it is cut in**. Implementing it silently

would defeat the review. **Impact if implemented:** two U7 supply pins, a new divider, one new capacitor, a change to the star-point argument in DSN-EEG-003 section 3.3, and a re-issue of RISK-EEG-011.

ECO-EEG-024 – S-02's single-fault DC limit is not met

Class: blocking for Phase 2. **Status:** **IMPLEMENTED 2 September 2026.** Rev B carried this ECO as OPEN and not implemented, with 47 k Ω fitted and S-02 not met at 53.2 μ A against a 50 μ A limit. `design.py` now fits **68 k Ω at R1–R16** and the calculated single-fault DC patient auxiliary current is **36.8 μ A. S-02 is met in the design and is not signed off** – see below. **Found by:** the patient-current budget in RISK-EEG-011 section 4.5, reached independently by WH-EEG-008 section 5.5 and JIG-EEG-009 section 4.3. **Was:** with R1–R16 at 47 k Ω , the single-fault DC patient auxiliary current is calculated at **53.2 μ A against the 50 μ A of S-02, which is a 6.4 % overrun and a failure.** RISK-EEG-011 classes it Critical. **Now:** R1–R16 are **68 k Ω** , 68k 0.1% 25ppm, Vishay TNPW060368K0BEEA. That gives 2.5 V / 68 k Ω = **36.8 μ A**, keeps the input corner at 234 Hz, which is –0.75 dB at 100 Hz, and raises Johnson noise to 0.28 μ V for a total of 0.31 μ V, still well inside E-03. **RFQ E-10 moves to its ± 1.0 dB at 100 Hz branch**, which the requirement already states for exactly this case and which is now the live branch because the 68 k Ω is what is fitted; the ± 0.5 dB branch belonged to the 47 k Ω build and is history. Same footprint, same nets, same pad count: the board does not move. **Why it was open, and why that reasoning is withdrawn:** Rev B held the change back so that the two prototypes could be built with 47 k Ω and the current **measured rather than calculated** before Phase 2. That left a 6.4 % overshoot on a **safety** limit standing in the released design through three revisions in order to measure the failing state, when the series resistor is the one component in the patient path whose value can be changed without moving anything else. The measurement does not go away: it changes from measuring a known failure to confirming a calculated pass. **What implementing it did NOT close.** The safety review. **RISK-EEG-011 SR-01 is closed in the design and unsigned**; the electrical safety reviewer of RISK-EEG-011 section 7 owns it and that review has not started, which is open item 6 of the simulation run of 2 September 2026. Nothing has been built and nothing has been measured: **36.8 μ A is a calculation, exactly as the 53.2 μ A before it was.** “Met in the design” is what may be written; “met” on its own, and “signed off”, may not. **Verified:** the value is in `design.py` and flows to the BOM and the CPL through `emit_all.py`; `tools/simulate_production.py` recomputes the single-fault current from it. TST-EEG-004's patient auxiliary current step, on FIX-04, measures it on the first unit. **Impact:** sixteen resistor values, the live branch of RFQ E-10, one AVL line, the noise budget in RISK-EEG-011 section 4, and a re-issue of RISK-EEG-011.

ECO-EEG-025 – F-06's three-minute ring buffer does not fit the PSRAM

Class: major. **Found by:** FW-EEG-001 section 5.8, where the allocation returns NULL. **Was:** RFQ F-06 asked for a ring buffer of at least three minutes at 1000 Hz and put the figure at “ ≈ 12 MB in PSRAM”. The mandated module is the ESP32-S3-DevKitC-1-**N16R8**, which is not substitutable under E-18 and has **8 MiB** of PSRAM. Three minutes is 9.13 MB and `main.c` asked for 12 MiB, so **the requirement could not be met on the mandated part** and the request failed at run time. ECO-EEG-009 also cited the 12 MB figure in its justification and is corrected above. **Now:** the ring is **6 MiB, which is 126 seconds of raw samples at 1000 Hz (124 s framed)**, and **RFQ F-06 is relaxed to 90 seconds of ring plus unlimited backfill from the microSD copy.** The ring covers a transport dropout; anything longer is recovered from the card, which holds the byte-identical frame stream. The 90-second figure is the requirement and 126 seconds is the fitted margin. **Verified:** the constant is in the firmware build and reported in the STATUS

frame; TST-EEG-004's dropout-and-recovery step exercises the backfill, not just the ring. **Impact:** one RFQ requirement, one firmware constant, the IFU sentence that told the participant the instrument keeps three minutes, and the test step that checked it.

ECO-EEG-026 – E-04's crosstalk limit is neither achievable nor measurable

Class: major. **Found by:** ICD-EEG-006 section 3.2 and raised at ICD-EEG-006 section 8 item 7 without ever reaching the RFQ. **Was:** RFQ E-04 asked for **–100 dB** channel-to-channel crosstalk. That is not achievable through a 60 mm un-interleaved ribbon, and it is about 40 dB below this instrument's own noise floor, so **it is not measurable on this hardware either**. TST-EEG-004 T9a nevertheless tested to –100 dB with 6.2 dB of detection-floor margin, and measured only the carrier. **Now:** E-04 is restated as **–80 dB at 50 Hz, measured on the carrier**, with the ribbon's contribution characterised once on the first prototype and recorded rather than tested per unit. The restatement is honest about what the instrument can see: a limit that cannot be measured is not a limit. **Verified:** TST-EEG-004's crosstalk step is rewritten to the –80 dB carrier measurement and JIG-EEG-009's detection-floor calculation is restated against it. **Impact:** one RFQ requirement, one test step, one fixture note, and one characterisation report on the first prototype.

ECO-EEG-027 – the envelope AC-coupling corner removed the envelope

Class: major. **Found by:** ICD-EEG-006 section 8 item 4, computing the corner from the fitted values. **Was:** C20/C40/C60 were **1 μ F** into R20/R40/R60 at 10 k Ω , which is a **15.9 Hz** corner, not the 0.1 Hz of RFQ E-11. design.py's own descriptive text claimed 0.1 Hz and AVL-EEG-017 listed the part as "1 μ F ... 0.1 Hz corner". For the envelope of a speech signal 15.9 Hz is not merely the wrong number, it is the wrong side of the signal: **it removes the envelope the stage exists to pass**. **Now:** **C20/C40/C60 change from 1 μ F to 10 μ F**, Murata GRM188R61C106MA73D, with R20/R40/R60 unchanged at 10 k Ω , giving a **1.6 Hz** corner. **RFQ E-11's AC-coupling clause is restated as ≤ 2 Hz**, because 0.1 Hz into 10 k Ω needs 160 μ F, which is not a 0603 part and buys nothing for a speech envelope. **Verified:** the values are in design.py; the corner is computed in simulate_production.py station 9; TST-EEG-004 measures it and the deviation note that recorded 15.9 Hz is deleted. **Impact:** three capacitor values, one AVL line, one RFQ requirement, one test limit, and one corrected description in design.py.

ECO-EEG-030 – an external layout engineer read Rev B, and Rev B is withdrawn

Class: scope, with seven findings. **Found by:** Danny Van den Blik, DVDB-electronics BV (Belgium), reading kicad/EEG-CAR-01_RevB_routed.kicad_pcb between 3 and 5 September 2026 under RFQ-EEG-002A.

Was: the Rev B routing was RELEASED FOR REVIEW under RFQ-EEG-002A and was waiting on a human layout engineer, which is the sixth open item of the production simulation and the fabrication-release gate of section 3. Nothing else was thought to stand between the data and a fabrication order.

Now: the reviewer declined the paid review and advised a full redesign from the schematic. The programme accepted that on 4 September 2026. **Rev B is withdrawn from fabrication:** no board is ordered from it, and Dekimo and DVC were told so on 3 and 4 September 2026. The Rev B data stays in the tree under its own file names as history and is not deleted; it is no longer the current fabrication set.

The seven findings. They are geometric, not circuit errors. Six are rules a design-rule check can enforce and the programme's own router was never given; the seventh is a missing check rather than a missing rule.

#	Finding	What it is
1	drills in pads	vias placed inside SMD pads
2	net stubs and loops	dangling track ends; more than one copper path between the same two pads on one net
3	sharp inside corners	an angle below 90 degrees between two consecutive segments of one track
4	off-centre pad entry	a track entering a pad other than through the pad centre along the pad's major axis
5	under-width critical nets	no net classes: power, analogue input, reference and light-drive nets routed at the generic width
6	no module outlines for collision checking	no 3D bodies for the thirteen module assemblies, MP-01 or the DevKit, so no placement can be shown to be free of interference
7	schematic not logically drawn	no native schematic exists; the eight-sheet PDF is drawn by tools/schematic.py and is not a netlist-bearing schematic a reviewer can read or import

The reviewer's stated principle, which the programme has adopted: **placement drives via count, must precede routing, and must be reviewed before routing starts.**

What Rev C is. Rev C is a **board revision** that changes footprints, part numbers and the layout. It changes **no pin assignment, no net name, no connector coordinate, no outline, no stack-up, no zone split, no keep-out and no star point**; if a later change finds one of those necessary it is its own ECO and forces a regeneration and diff of firmware/main/board_pins.h. Rev C is produced in-house as a **reviewable** design and not as a fabricable one: the seven findings are encoded as rules and checks, a native KiCad schematic and 3D bodies are added, and **placement and routing are bought** from the JLCPCB layout desk. tools/router.py is no longer the producer of a fabrication set. Its two remaining roles are to hold and enforce the rules so that a returned board can be graded against them, and, optionally, to produce an in-house reference route for comparison.

RFQ-EEG-002A is re-scoped. RFQ-EEG-001 Rev E section 1.1 defines 002A as the review and sign-off of the supplied carrier routing. There is no supplied carrier routing to review any more. 002A is now **the review of the layout contractor's PLACEMENT of Rev C**, taken at the placement-confirmation gate and before routing is confirmed, as a written findings list by net, pad pair and coordinate rather than as edits to the board file. It is capped at four to six hours and is agreed in principle with the same reviewer. The full-redesign quote of EUR 3,200 (estimated EUR 3,200 to 4,500 plus VAT) is logged as

a grant budget line and is not ordered; the envelope for the current phase is about EUR 500.

Two revision letters in design.py. REV stays at "B" and keeps its file names; REV_C is new and is "C", and stem() computes the file stem from a letter so that no Rev C file name is typed by hand. Rev B artifacts are unchanged in name and content by this ECO.

Verified: tools/emit_all.py --cached and tools/simulate_production.py were re-run on the tree before any change. The DRC report reproduces byte for byte: 0 violations, 145 of 145 nets connected, 3 745 segments, 552 vias, minimum clearances 0.260 / 0.285 / 0.285 / 0.275 mm. The withdrawal is a change of release state, not of geometry, and it adds no violation, opens no net and puts no copper in the isolation keep-out.

Impact: the board – none, Rev B's geometry is untouched and Rev C has no routing yet. The firmware – none, no pin assignment moves. The mechanical parts – none. The BOM – none in this ECO; ECO-EEG-031 carries the BOM corrections. The test specification – none; the fixture data of JIG-EEG-009 is built against connector positions, and those do not move. The safety case – none: no electrode-path, isolation, battery, charge-interlock or patient-current value changes, so RISK-EEG-011 is not re-issued for this ECO. Units already built – none exist.

ECO-EEG-031 – four part numbers, and only three of them were known

Class: major. **Found by:** Bittele/7pcb, who reported the first three to the programme and to Dekimo on 3 September 2026; the fourth by tools/footprint_audit.py, written for this ECO, on 8 September 2026.

Was: the carrier BOM carried four lines that could not be bought as written or could not be fitted to the land pattern beside them, and one class of part that a buyer could substitute without knowing it must not be.

Now, item by item.

1. U1, U2, U3 – TI OPA4376AIDR on a SOIC-14 land. The quad OPA4376 is offered in **one** package: TSSOP-14, TI's PW. The D suffix is SOIC and there is no SOIC-14 quad, so OPA4376AIDR is not an orderable part number. **The part is OPA4376AIPWR and the footprint is TSSOP-14_4.4x5mm_P0.65mm.** What makes this worse than a typing error is the record: Rev A of AVL-EEG-017 quoted OPA4376AIPWR, which is correct, and its Rev B **withdrew it** on the ground that it did not fit the SOIC-14 land pattern design.py placed – the package was corrected to match the footprint instead of the footprint to match the package. That withdrawal is withdrawn. fplib's SOIC-14 docstring argued the choice on the two-layer escape between adjacent lands; the board went to four layers at ECO-EEG-018 and the argument had already lapsed, but the deciding fact is simply that the package does not exist. **Pin numbering is identical between SOIC-14 and TSSOP-14, so no net moves.**

2. L1 – Murata BLM18PG601SN1D, 600 Ω at 100 MHz, 1.5 A. The reviewer read the impedance code as some other impedance; that reading is wrong. Murata's part-numbering page states that the three impedance figures are two significant digits and a count of zeros, so 601 is 600 Ω at 100 MHz and the design intent is correctly encoded. The defect is the series: PG is the large-current power-supply family, and the same catalogue's impedance map does not offer it at 600 Ω in 1608 – the 0603 P/S range stops at 470 Ω (1 A). **There is no such part.** 600 Ω at 100 MHz in 1608 is a general-series part: **BLM18AG601SN1D, 600 Ω $\pm$ 25 %, 500 mA rated, 0.38 Ω DC resistance.** The

“1.5 A” came with the wrong part number and has no requirement behind it; L1 feeds VDD_ISO, the ADuM4160 module’s device-side supply, which is tens of milliamperes, so 0.38 Ω costs about 10 mV.

3. J15, J16, J17 – Stäubli SLB1,5-F / LB-I1,5. The part number is a class and not a qualified PCB part, which AVL-EEG-017 §1.4.1 and ICD-EEG-006 §1 both already said. What was missing is that a buyer reading the BOM could not see it. design.py now carries a NOT_SUBSTITUTABLE table – AVL-EEG-017 §6.4 remains the home of the list – and the generated BOM prints the reason on the line: **PATIENT-CONNECTED under IEC 60601-1, approved in writing from a sample, no “or equivalent”**. The same table marks R1–R16, C1–C16, D1–D16, R90 and R91. tools/footprint_audit.py reports J15–J17 as **OPEN**, never as passes.

4. SW1, SW2, SW3 – Omron B3F-4055. This one was not on anybody’s list. Omron splits the B3F family by body size: 6 × 6 mm is B3F-1000/-3000/-6000, and **12 × 12 mm is B3F-4000/-5000/-5001**. B3F-4055 is a 12 × 12 mm switch. The footprint beside it is the 6 × 6 mm four-terminal pattern on 6.5 × 4.5 mm centres, the three switches sit on a 14 mm pitch, and AVL-EEG-017 §1.4’s own row asks for a 6.0 × 6.0 mm body at 160 gf ±50 – which B3F-4055, at 260 gf, does not meet either. **The part is B3F-1052:** 6 × 6 mm, projected plunger 7.3 mm, 1.47 N {150 gf}, four terminals, no ground terminal. Projected, because a 12 mm B32-series key top mounts only to a projected plunger and the pod lid’s 12.4 mm opening is cut for that cap. The footprint’s own name was wrong with it – SW_PUSH_6mm_H5mm, “5 mm actuator” – and is now SW_PUSH_6mm_H7.3mm; the height does not change the land pattern, it changes the collision model of ECO-EEG-033. **RFQ-EEG-001 Rev E E-26 still reads “a 6 mm tactile switch (Omron B3F-4055 class)”**, a requirement that contradicts itself inside one sentence. It is not re-issued here; it is recorded as an open item for the next issue of that document.

A fifth thing this ECO changes, and it is not a part number. tools/fplib.py’s TSSOP-14 land pattern was 1.45 × 0.45 mm pads at $x = \pm 2.85$ with a 7.50 × 5.70 mm courtyard. fplib’s stated contract is that a house re-importing the netlist into its own CAD gets the same land pattern as KiCad’s standard library, and KiCad’s TSSOP-14_4.4x5mm_P0.65mm is 1.475 × 0.400 mm at ±2.8625 with a 7.70 × 5.50 mm courtyard. Nothing was placed on the old figures, so this costs nothing; leaving them would have put U1–U3 on a pattern that is nobody’s.

Three drawing notes had become false and are corrected in the same edit, because design.py’s NOTES are printed onto the fabrication and assembly drawings: the series resistor was still described as **47 k Ω** where ECO-EEG-024 made it 68 k Ω on 2 September; the analogue rails were still said to arrive at **“J2 pins 11–14”**, and J2 has ten ways – they arrive at J23, the 1×6 rail socket, which is what ECO-EEG-013 split out; and the isolation and mounting keep-outs were still stated as clear **“on both layers”** on a board that has had four since ECO-EEG-018.

Verified. tools/footprint_audit.py audits all **211** designators against the package, way count and, where the part number encodes it, the value, tolerance, dielectric and voltage: **183 PASS, 0 FAIL, 3 OPEN (J15–J17), 0 UNRECOGNISED, 25 fabricated features**. The report is docs/footprint_audit_RevC.md and it is generated, not written. pcbgen.BoardV2().validate() returns **0 errors** on 211 designators, 636 pads and 156 nets – no courtyard overlap, no edge breach – with the TSSOP courtyards, which are shorter than the SOIC ones they replace. **The netlist is unchanged and that is measured, not asserted:** the pad-to-net mapping from design.py was compared against the released kicad/gerber/EEG-CAR-01-IPC-D-356A.ipc excluding its via records, and the two are **identical across all 156 nets**.

Impact. The board – U1–U3's land pattern and courtyard change and their placement lines in DSN-EEG-003 §3.3 rule 3 are unaffected, because the protection networks are the R–D–C rows and not the op-amps; nothing else moves. The firmware – none; no pin assignment changes. The mechanical parts – the switch is 7.3 mm to the top of the plunger where the drawing notes said 5.0 mm, which is a collision-model input for ECO-EEG-033 and does not move a printed part; the pod lid opening at 12.4 mm is unchanged. The BOM – four lines. The test specification – none. The safety case – **none of the four changes alters the electrode path, the isolation, the battery, the charge interlock or the patient-current budget**, so RISK-EEG-011 is not re-issued; J15–J17's marking makes an existing safety property visible to a buyer rather than changing it. Units already built – none exist.

One consequence for the tools. `emit_all.py` no longer regenerates the Rev B set. Rev B's routing was produced against SOIC-14 pads; running the old path from this source would write Rev B file names with Rev C pads and produce a set whose copper does not reach its own pads. The Rev B fabrication set is frozen, is recovered from git rather than regenerated, and `emit_all.py --rev-b` refuses and says so.

ECO-EEG-032 – the rule set the DRC was measuring against was incomplete

Class: major. **Found by:** ECO-EEG-030. This ECO is that ECO's findings 1 to 5 turned into checks, and it is raised separately because it changes the tools rather than the design.

Was: `kicad/EEG-CAR-01_RevB_DRC_report.txt` says "VIOLATIONS: 0 – none. The board passes every rule listed above", and it is right. **The words that matter are "listed above"**. The rule set had twelve rules and none of them looked for a via inside a pad, a dangling track end, a redundant copper loop, an acute corner, an off-centre pad entry or a conductor narrower than its own net class needs – and the last of those could not be looked for, because there were no net classes with minima to look against. A report can be true and useless at the same time, and this one was: it was the evidence the board was ready for review, and the reviewer declined the review.

Now: the rule set lives in `tools/rules.py` as data, and it is written down once.

- **Net classes.** Eight, replacing Rev B's six: ELECTRODE, ANALOGUE_REF, POWER, USB, ANALOGUE, LED_DRIVE, DIGITAL, DEFAULT. Every one of the 156 nets falls in exactly one. Each class carries a **minimum** and a **preferred** width and clearance, the layers it may use, and whether it may have a via at all. Rev B's table carried one width and one clearance per class and no minimum, which is why all 169 relaxed connections were free to fall to the 0.20 mm board floor with nothing to say that some of them were the wrong nets to relax. Rev B's figures survive as the **preferred** column.
- **Where the minima come from.** POWER at 0.40 mm because the worst case is about 610 mA at J13 and IPC-2221 gives 0.40 mm of 35 µm outer copper about 1.29 A at a 10 °C rise. ANALOGUE_REF at 0.30 mm for source impedance, not current – the rails carry about 10 mA. LED_DRIVE at 0.25 mm on 1.3 mA a site. ELECTRODE at 0.25 mm, above the board floor, because a patient-connected conductor is the last place to spend the last 0.05 mm. **Four numbers are proposals and not transcriptions and each is flagged confirm in the source and printed as such in LAY-EEG-034 section 5:** the ELECTRODE minimum width, the ELECTRODE layer and via restriction, the ANALOGUE_REF minimum width and the pad-entry tolerance.

- **ELECTRODE is L1 only and may not have a via.** That is DSN-EEG-003 section 3.3 rule 3 read literally – these nets run on L1 with the reference plane continuous beneath them, and a via breaks the plane it is routed over. It constrains the contractor and it is achievable: J14, the R/D/C protection rows and J2/J4/J23/J29 are all on the top side.
- **Six checks in the in-house DRC**, in `tools/drc_geometry.py`, each with its own counted line in the report: via inside an SMD pad; dangling track end; redundant copper path outside a plane; angle below 90° between two segments and any segment off a 0/45/90/135° axis; a track entering a pad more than 25 % of the pad's minor dimension off its centre; and per class, width, layer and via rule.
- **The same rules exported to KiCad.** `kicad/EEG-CAR-01_RevC.kicad_dru` is written from `rules.py` and is 37 rules. `rules.check_dru()` balances its brackets on every emit, because a `.kicad_dru` with one bracket missing loads as far as the error and silently drops every rule after it – which is this whole ECO's failure mode wearing a different hat.

What KiCad cannot check, said plainly rather than implied. The angle rule and the pad-entry rule have no KiCad constraint and are not expressible in a `.kicad_dru`. They are checked by `tools/drc.py` on the geometry that comes back, and LAY-EEG-034 section 6 says so against each of them rather than leaving a reader to assume the contractor's DRC will catch them. Dangling ends and redundant loops are KiCad **built-in** checks and are raised to errors in the project file rather than restated as custom rules.

Verified, and this is the evidence that the findings were real. `tools/grade_revb.py` regrades the **released** Rev B geometry under the new rules – the pads, tracks and vias out of `kicad/EEG-CAR-01_RevB_routed.kicad_pcb` and the plane polygons out of `tools/routed.pkl`, checked against the released census of 3 745 segments and 552 vias before it grades. It reads the released artefact and not `design.py`, because `design.py` has moved to Rev C pads.

Finding	Rule	Occurrences in the released Rev B routing
1	vias inside an SMD pad	67
2a	dangling track ends	5
2b	redundant copper loops outside a plane	221 , on 22 nets
3	angle below 90° between two segments	171
3	segments off a 0/45/90/135° axis	158
4	off-centre pad entries	299
5	conductors under their class minimum	322
5	net classes on a forbidden layer	50
5	vias on a class that forbids them	18

Finding	Rule	Occurrences in the released Rev B routing
	total	1 311

The loop line counts loops and the detail lists one line per net, so those two figures differ on purpose; every other line is one occurrence per detail line. The report is kicad/EEG-CAR-01_RevB_regraded_ECO-EEG-032.txt.

None of this is a regression and none of it is reverted. Section 3's ECO gate forbids a change that adds a violation; a change that adds a **check** is not in that class, and the paragraph now says so. The Rev B DRC report is not withdrawn either – it is correct about the twelve rules it had, and it is the report on a set that is withdrawn from fabrication for other reasons.

Two of the 1 311 are worth naming, because they are in the register already. The 67 via-in-pad occurrences include the stub_via at U1.3 that design.py's TARGETED_REPAIRS records as a deliberate repair of 2 September 2026: a 1.0-1.5 mm stub from the op-amp's AGND_REF pin to a through via. It closed a net and it is finding 1. The 322 under-width conductors are not the 36 of the "169 relaxed connections" restated: that figure counted connections against the board's single 0.25 mm preferred width, and this one counts segments against eight per-class minima.

Impact. The board – none; no geometry moves and Rev C has no routing to grade. The firmware, the mechanical parts, the BOM, the test specification – none. The safety case – none directly, though the ELECTRODE class now states in machine-readable form what DSN-EEG-003 section 3.3 rule 3 states in prose, which is a strengthening of an existing control and not a new one. Units already built – none exist.

One structural change. design.py's NETCLASS table and netclass_of() are **removed** and their callers now read rules.py. design.py keeps the net-name membership sets, which are circuit facts; rules.py holds the geometry, because it has to be exported to KiCad as well as measured, and a rule kept in two places is a rule that will disagree with itself. tools/kicad_parse.py gained segment and via readers so that a released board file can be graded without its source.

[ECO-EEG-033 – the Rev C reviewable design set](#)

Class: scope. **Found by:** ECO-EEG-030, findings 6 and 7, and the input list the programme committed to the layout contractor on 8 September 2026.

Was: four of the six inputs promised to the layout desk did not exist in any form – a native schematic, a board outline and fixed connector DXF, 3D bodies of the thirteen module assemblies, and a rule sheet – and a fifth, the netlist, existed only as IPC-D-356A.

Now, and this entry grows as each part lands.

1. The native schematic (finding 7). kicad/EEG-CAR-01_RevC.kicad_sch and nine sheets under it, written by tools/emit_kicad_sch.py from the same design.py data the eight-sheet PDF is drawn from. Ten files, KiCad 8 format, hierarchical, one sheet per block: power, isolation and USB, controller, the two analogue front ends, the harness and its sixteen protection networks, audio and the envelopes, the contact lights, and the star points and test points. All 211 designators are placed and the assignment is

checked to be a partition of design.C – a designator on two sheets or on none fails the build.

How connectivity is expressed. Power and ground are global through power symbols and carry no sheet pin. Every other net with pads on more than one sheet – **46 of the 156** – is a hierarchical label on each sheet that uses it and a sheet pin on the root. The remaining **110** are local to one sheet or global through a power symbol.

What makes it readable rather than merely correct, which is what finding 7 is about. The quad OPA4376 is drawn as **five units** – four amplifiers and a power unit – and not as a fourteen-pin box. Each of the sixteen protection networks is drawn as the straight line DSN-EEG-003 section 3.3 rule 3 asks the layout to place it in: resistor, then clamp, then filter capacitor, from the harness towards the module. Each envelope channel is drawn along its signal path. Notes wrap, and a sheet whose content runs off its page fails the build rather than emitting a PDF with the comparator missing.

The gate, and it is a measurement and not an opinion. tools/sch_netlist.py reads the emitted files back – pin geometry out of their own embedded lib_symbols, wires, junctions, labels, hierarchical labels and power symbols – resolves the connectivity geometrically and diffs it against design.py. It does not ask the generator what it meant.

	design.py	schematic
nets	156	156
pins	614	614
structural problems	–	0
netlist differences	–	0

It earned its keep on the first run: four pull-ups – R50, R51, R52 and R94 – were wired by geometry rather than by pin number and had pin 2 where design.py has pin 1. A resistor is symmetric so the circuit was right and the netlist was wrong, which is precisely the class of error that survives a human reading a schematic and does not survive this check. R94 and R95 were also drawn as a divider and are two separate I2C pull-ups. Both are fixed and the helper that caused it now wires by pin number.

ERC. KiCad is not installed on the machine this was generated on, so kicad-cli sch erc was NOT RUN and no ERC result is claimed. What was run is the structural half: every pin of every placed symbol is on a net, no designator is placed twice and every unit of a multi-unit part is placed exactly once, no net has one pin unless design.py declares it as one of the eleven single-pad nets, and every power net is driven by a power symbol. **Zero findings.**

The symbol library. kicad/EEG-CAR-01.kicad_sym, generated. Rev B of ICD-EEG-006 said no such file existed and that its own Rev A was wrong to claim one; that was true of board Rev B and is superseded here, and the ICD is corrected in the same change rather than left contradicting the tree. The contractor needs it: a schematic whose symbols live only inside itself opens, and nobody can edit it.

2. The unrouted board, the project and the DXF (inputs 2 and 4). kicad/EEG-CAR-01_RevC.kicad_pcb, written by tools/kicad_pcb8.py at (kicad_pcb (version 20240108)). tools/kicad_write.py, which writes the Rev B routed board in the

KiCad 5 dialect, is untouched: that dialect was the right choice for a fabrication set going to houses on older tools and is the wrong one here, because net classes, rule areas and custom rules do not survive it and they are the whole point.

What is in it: the outline on Edge.Cuts and the four-layer stack-up of DSN-EEG-003 section 3.2 in (setup); all **211** footprints with their pads and nets and **no track, no via and no arc**; AGND_REF and DGND zones on In1.Cu and In2.Cu split at x = 62 mm; and rule areas under exactly the names the .kicad_dru refers to – ISOLATION_KEEPOUT on all four copper layers, ANALOGUE_ZONE, DIGITAL_ZONE, four MOUNT_KEEPOUT_MH* and NO_VIA_J2/J4/J23/J29.

37 footprints are locked: J1 to J30, MH1 to MH4 and FID1 to FID3. The connectors are fixed by the pod, the module plate and the harness and the contractor may not move them; everything else is at its Rev B coordinate, unlocked, and is theirs to place.

kicad/EEG-CAR-01_RevC.kicad_pro carries the eight net classes, an assignment for **all 156** nets, the board minima, and the rule severities that make **track_dangling an error** – which is finding 2a handed to KiCad's own built-in check rather than restated as a custom rule.

The board is EEG-CAR-01_RevC.kicad_pcb and not EEG-CAR-01_RevC_unrouted.kicad_pcb, and that is deliberate. A KiCad project expects its board and its schematic to share the project's stem. A differently named board opens standalone – which means without the project file, so the net classes, the assignments and the severities would all be silently absent for the contractor. That the board is unrouted is said in its title block, in its comments, in LAY-EEG-034 and in the handover README; a file name does not have to repeat it, and a broken project association costs more than the name is worth.

kicad/EEG-CAR-01_RevC_outline_and_fixed_connectors.dxf is the mechanical input: outline, MH1-MH4 with their 6 mm keep-outs, the isolation strip, the zone split and all thirty connector courtyards with pin-1 marks, in **design.py's convention – top-left origin, Y down** – which is the board file's convention too, so the two overlay without transforming anything. The CAM convention is the other one and the DXF says so on its own face as well as in the README.

3. The 3D bodies and the collision check (finding 6). tools/step_write.py, tools/mech_bodies.py and tools/collision_check.py.

cadquery could not be installed on the machine this was generated on – 472 MB free where cadquery-ocp needs several times that – so tools/mech_gen.py cannot even be imported there, let alone run, and no printed part was regenerated. Rather than claim a body set that does not exist, step_write.py writes the bodies the check needs from first principles with no dependency at all: FACETED_BREP, planar faces, one solid per extruded polygon. It cannot do fillets, holes in a face or curved surfaces, and does not pretend to – a standoff is a hexagonal prism and MP-01 is four rectangles around its DevKit opening. **No STEP reader was available to verify the files**; they are checked structurally, and that is what is claimed.

Written: one body per **footprint class**, 22 of them, **bound into the .kicad_pcb** so the contractor's 3D view is populated without importing anything; the carrier with the height envelope of all 211 parts; MP-01 with the four M3 x 18 standoffs; and the thirteen module assemblies.

The twelve module envelopes are **DECLARED MAXIMA** and no vendor drawing was consulted for any of them. They are registered in ASM-EEG-023 under **MECH-D6-MODULE-ENVELOPES**, which is new and **blocks a build**. The placement of the modules on MP-01 is a proposal for the same reason: ICD-EEG-006 section 4 deliberately does not drill the plate to a pattern.

What the check found, and three of the four are open.

Case	Result
A – carrier parts against the plate underside	clear. The tallest carrier part is J15 at 10.00 mm against a plate underside at 18.0 mm: 8.00 mm of clearance
B – the DevKit against the plate opening	THE OPENING IS 2 mm TOO SHORT. J6 and J7 are 1x22 sockets, so the pin span is 53.34 mm, and the ESP32-S3-DevKitC-1 PCB is 63.0 mm long: it needs 3.2 to 66.2 mm in carrier Y and MP-01's opening runs 4.0 to 65.0 mm. The board fouls the plate at both ends
C – modules against each other and their jumper reach	six of twelve cannot be placed at all, and four cannot reach their connector within the 60 mm of ICD-EEG-006 section 3.2 from ANY position on the plate – M4 to J10 is 86 mm at best, M5 to J11 is 72 mm at best. That 60 mm is a crosstalk limit, not a mechanical one
D – plan area, which nothing in this package had ever checked	the twelve envelopes need 17 356 mm² and the plate offers 12 409 mm²: 140 % fill

Case D is the one that matters and it does not rest on the assumptions. The two ADS1299 boards alone are 7 345 mm², **59 % of the net usable plate**, and that figure is the Raspberry Pi HAT standard rather than a guess – the PiEEG-8 is a Pi shield. Halving every other envelope still leaves 12 351 mm² against 12 409 mm². ICD-EEG-006 section 4's stack budget finds 6.4 mm of margin in HEIGHT and says nothing about area, and area is the binding constraint.

Nothing here is closed by this ECO. Four routes would each move the answer – a larger plate, a second tier of standoffs, an ADS1299 breakout that is not a Pi HAT (AVL-EEG-017 section 2 M1 permits the breakout to change under the section 6 qualification even though the DEVICE may not), or moving the modules whose jumpers cannot reach onto the carrier as fitted parts. None is decided and none is costed. They are for the programme.

4. The rule sheet (input 6). LAY-EEG-034 Rev A, registered in section 1.1 and issued 8 September 2026. Eight sections: scope and precedence, board and stack-up, zoning and star points, the isolation keep-out, the net-class table, the seven geometry rules, placement, and the deliverables expected back.

It is a controlled document **and** it is generated, which is not a contradiction: the tables are transcribed from tools/rules.py by tools/emit_rule_sheet.py, so the sheet the contractor signs against and the .kicad_dru the contractor's DRC loads come from one source and cannot drift. The prose around them is written.

Two things in it are said plainly rather than left to be assumed. **Section 6 says which of the seven rules KiCad can check and which it cannot** – the angle rule and the pad-entry rule have no KiCad constraint, and the sheet says against each of them that this programme checks it on the returned geometry with `tools/drc.py`, naming the tool and pointing at the 1 311 occurrences it found in Rev B. And **section 7 carries the open item from part 3** – that the modules do not fit MP-01 and that the plate's DevKit opening is 2 mm short – because a placement reviewer will meet it, while saying that neither is a carrier layout question and neither blocks the order.

The brief for this work asked for one page. It is three. The net-class table is eight rows with a derivation for each, and the geometry table is seven rows with a checked-by column; compressing either into a page would mean dropping the derivations, and a rule a contractor cannot see the reason for is a rule that gets relaxed at the first difficulty. The sheet is still one document and is read in one sitting.

5. The handover set. `kicad/RevC_layout_inputs/`, written by `tools/emit_handover.py`: **51 files, 2.6 MB** – the project, the ten schematic sheets, the symbol library, the board, the `.kicad_dru`, the netlist, the BOM and the footprint audit, the two provisional CPLs, the DXF, twenty-five STEP bodies, the collision report, the rule sheet in both forms, a **SHA-256 for every file**, and `README_layout_inputs.md`.

The README is the covering note and it says the four things a contractor otherwise has to guess: **open the .kicad_pro and not the board**, because a board opened alone has none of the net classes or the severities; the KiCad version, with an offer to re-emit for another one; **what is locked (37 footprints) and what is theirs (174)**, and that the unlocked coordinates are Rev B's and are a starting point rather than a specification; and **which two rules KiCad cannot check** and that this programme checks those itself on return, naming the tools. It also names the placement gate and asks that routing not begin on an unconfirmed placement.

Nothing in tools/ sends anything. The directory is written; it is uploaded by hand.

The build is deterministic and that is measured, not asserted: two consecutive runs of `tools/emit_all.py` produce byte-identical checksums across all 51 files. So a checksum that does not match means a file changed, which is the only thing a manifest is worth.

ECO-EEG-033 closes here. What it did NOT do is also part of the record: **no ERC and no DRC was run on any of it**, because KiCad is not installed on the machine that generated it, and no printed part was regenerated, because `cadquery` could not be installed there either.

Verified. The board is parsed back after writing and checked against `design.py`: **211 footprints, 636 pads, 156 nets, 0 segments, 0 vias, 37 locked**, netlist identical, every rule area present under the name the `.kicad_dru` uses, the project file's classes and its 156 assignments complete, and `track_dangling` at error. `kicad-cli pcb drc` was **NOT RUN**: KiCad is not installed on this machine. On an unrouted board its only finding would be unconnected items, one per net, and that is not a substitute for the check.

[ECO-EEG-034 – the layout input set re-emitted for KiCad 10, and two defects it found](#)

Class: format emission and documentation. **Found by:** the JLCPCB layout desk, which confirmed on 9 September 2026 that it runs **KiCad 10**, and asked for the set as a single archive for upload at `design.jlcpb.com/quote`.

The circuit is unchanged. No net, no part, no value, no footprint and no coordinate moves under this change. The netlist is the same 156 nets and 614 pins, the board is the same 211 footprints and 636 pads, and the same 37 footprints are locked at the same coordinates. What changes is the file format the set is written in, two defects in how the rules were emitted, one reclassification in the rule sheet, and the documents that describe all of it.

Was: the set in kicad/RevC_layout_inputs/ was written for KiCad 8 – (kicad_sch (version 20231120)), (kicad_pcb (version 20240108)) – and the covering note offered to re-emit for another major version if asked. Opening a KiCad 8 project in KiCad 10 can silently alter the net classes, the custom rules and the DRC severities, which is most of the layout specification, so the offer was the right one and it has now been taken up.

Now: two sets, generated from one source in one run.

Directory	Format	Files
kicad/ RevC_layout_inputs/	KiCad 8, (kicad_pcb 20240108) / (kicad_sch 20231120)	51
kicad/ RevC_layout_inputs_kicad10/	KiCad 10, (kicad_pcb 20260206) / (kicad_sch 20260306)	53

The KiCad 8 set is unchanged in kind and stays the published reference. The KiCad 10 set is that same emission passed through KiCad's own kicad-cli pcb upgrade, sch upgrade and sym upgrade, in tools/kicad_fmt.py. It is a target of the existing emitter and not a second emitter: tools/design.py remains the single source and there is nothing to keep in step by hand. **The KiCad 10 version tokens above were read out of files KiCad 10.0.6 had just written, not taken from documentation or from memory,** and kicad_fmt.verify() re-reads them on every emission so that a different KiCad quietly producing a third format is an error rather than a surprise.

The two extra files in the KiCad 10 directory are EQUIVALENCE_kicad8_vs_kicad10.md and the DRC report it cites.

The two sets are checked equivalent, not assumed equivalent. Nine checks in tools/emit_equivalence.py, written into the KiCad 10 directory on every emission and failing the build if any of them differ: the netlist parsed back out of both schematic trees; the board census; the eight net classes and the assignment of all 156 nets; the 37 custom rules; the 45 DRC severities; the 37 locked footprints and their coordinates; the fixed geometry; the rule areas and pours; and a KiCad 10 round trip. **All nine pass. None is marked not performed.** .kicad_pro, .kicad_dru and .kicad_sym are not rewritten by the conversion and are byte-for-byte identical between the two directories, which is why the three checks that matter most compare equal by construction – recorded there as a measurement and not as an assumption.

KiCad 10.0.6 was installed on the build machine to do this. Every previous statement in this package that kicad-cli sch erc and kicad-cli pcb drc were NOT RUN because KiCad was absent was true when written and is no longer true of the KiCad 10 set. It remains true of the KiCad 8 set: Homebrew carries no kicad@8 and none was installed, so no DRC or ERC result is claimed for that directory.

Finding 1 – the 37 custom rules were silently inert, and are now live.

tools/rules.py wrote the .kicad_dru with ; ; comments. KiCad discards the **whole file** the moment it meets a semicolon comment, with no error and no warning, and runs DRC as though the file were absent. Measured on KiCad 10.0.6 by appending a probe rule that must fire: with the file as released the probe produced nothing and deleting the file changed no result; with the comments written as # the probe fired. **The released set shipped 37 rules of which KiCad applied none**, while LAY-EEG-034 told the layout desk the file was not optional. Fixed by emitting #, and check_dru() now refuses to write a file containing a semicolon comment so that it cannot come back. Whether KiCad 8 also discarded the file is **not verified** – no KiCad 8 was available to test – and is not asserted either way.

Finding 2 – the zoning and no-via areas forbade the parts they contain.

tools/kicad_pcb8.py wrote (pads not_allowed) (footprints not_allowed) into every rule area. That is correct for ISOLATION_KEEPOUT and wrong for ANALOGUE_ZONE and DIGITAL_ZONE, which between them tile the whole board, for the four NO_VIA_J* areas, which are the connectors' own courtyards, and for the four MOUNT_KEEPOUT_MH* areas, which are centred on the mounting holes. The result was **199**

items_not_allowed violations at error severity, raised against placement the layout desk has not yet made. The intent was already recorded and was not what the file said: tools/rules.py says of the zone split that it “is a routing rule and not a placement rule”, and the six emitted zoning rules only ever disallow track via. Fixed by making pads and footprints parameters of _rule_area(). Copper – tracks, vias and pours – remains forbidden in all of them, and ISOLATION_KEEPOUT is untouched. items_not_allowed fell from **199 to 3**.

Finding 3 – MH2 sits inside the isolation strip. Raised here, not resolved. The three violations that remain are real geometry and were invisible until finding 1 was fixed, because the rule reporting them had never run. ISOLATION_KEEPOUT is the strip x 141.0 to 150.0 mm, y 2.0 to 22.0 mm (DSN-EEG-003 section 3.3 rule 4); mounting hole **MH2 is at (145.0, 5.0)**, inside it, and is the only one of the four that is. This is probably not a physical defect: rule 4 requires the strip to be free of **copper**, MH2 is non-plated, and rule 8 requires non-plated holes to carry no copper and no mask opening. What flags it is that the emitted rule disallows hole and footprint as well as the copper items, which is broader than the requirement it implements. **Narrowing a rule that guards the isolation barrier is a decision for the programme and not for a format re-emission**, so it is recorded and left alone; both sets carry the rule as it stands and both report the same three violations. The options are to narrow the rule to track via zone pad graphic, to move MH2, which is locked and fixed by the enclosure, or to record MH2 as a standing exception.

The ELECTRODE row of LAY-EEG-034 section 5 is split. Its clearance, its layer and its via restriction were carried as proposals awaiting confirmation. They are not proposals: DSN-EEG-003 section 3.3 rule 3 routes every electrode net on L1 with the reference plane continuous beneath it at 0.35 mm clearance, in those words, and section 3.2 carries an electrode-net clearance row saying the same. They are reclassified as requirements citing that section. **The ELECTRODE width pair remains a proposal**, and so does the whole ANALOGUE_REF row: the document set was searched before the reclassification and **no governing document fixes a width for either class** – section 3.2's 0.20 mm floor and 0.25 mm preferred width are board-wide and say nothing about a class. NetClass.confirm is now a tuple naming which columns of a row are proposals, rather than one flag over the whole row, and section 5 of the rule sheet prints

them per column. Open question 4 of the Rev C work report therefore has two of its four items settled and two still open.

A defect in the reader, found by the same work. `tools/kicad_parse.py` assumed a pad's net was `(net <code> "<name>")`. **KiCad 10 removed the board-level net table and the numeric net codes entirely**; a pad now carries `(net "<name>")`. The reader raised on the first KiCad 10 board it was given. It now reads both dialects, for pads, tracks and vias alike – which matters beyond this change, because the board that comes back from the layout desk will be routed and will be KiCad 10, and `tools/drc.py` grades it through this reader.

The portal archive. `tools/make_portal_zip.py` writes `dist/EEG-CAR-01_RevC_layout_inputs_kicad10.zip`: 53 files, 3 502 275 bytes uncompressed, 570 604 compressed, the `step/` tree preserved. It is deterministic – fixed timestamps, fixed permissions, sorted order – so the same directory packs to the same bytes and a checksum quoted in a covering email means something. The tool extracts the archive again and checks every file against the `SHA256SUMS.txt` travelling inside it before it returns. **It is not committed.** `dist/` is a build directory; the archive is rebuilt in a minute and a 3 MB binary duplicating 53 tracked files earns nothing under version control. Nothing in `tools/` uploads it.

Verified. Both sets emitted and parsed back: **211 footprints, 636 pads, 156 nets, 620 pads carrying a net, 11 nets with one pad, 145 with two or more, 0 segments, 0 vias, 37 locked**, identical across the two formats; 8 net classes and 156 assignments identical; 37 rules identical; 45 severities identical with `track_dangling` at error in both; board 150.0 x 130.0 mm, mounting holes at (5, 5), (145, 5), (5, 125), (145, 125), fiducials at (12, 10), (144, 100), (12, 120), zone split at x = 62.0 mm, vias 0.60 mm on 0.30 mm through only, tented. **kicad-cli 10.0.6 pcb drc was RUN** on the KiCad 10 set: it loads with no schema warning and no rule-parse error. Its 354 violations and 464 unconnected items are read in check 9 of the equivalence report and are not a clean bill – the unconnected items are every net of a deliberately unrouted board, the 199 `lib_footprint_issues` are the footprint library not being registered in a command-line environment, and the silkscreen warnings are against provisional placement. **No custom rule fires**, which is the expected result: all 37 constrain tracks and vias and there are none. *Not verified:* KiCad 8's own handling of the `.kicad_dru`, and no ERC was run on either set.

2.2 Requirement changes and where they come from

Every RFQ-EEG-001 requirement that changed between Rev C and this release, with the change that caused it. The requirement text lives in RFQ-EEG-001; this table is the index, not a restatement.

Requirement	Change	Source
E-04	crosstalk restated from –100 dB to –80 dB at 50 Hz, measured on the carrier	ECO-EEG-026

Requirement	Change	Source
E-10	±1.0 dB at 100 Hz. That is the branch E-10 already carried for this case, and it became the live one on 2 September 2026 when ECO-EEG-024 was implemented and R1–R16 went to 68 kΩ. The ±0.5 dB branch belonged to the 47 kΩ build and is history, not an alternative	ECO-EEG-024, implemented
E-11	AC-coupling corner restated from 0.1 Hz to ≤ 2 Hz, and met at a calculated 1.6 Hz. The 50 Hz ± 10 % low-pass is unchanged and, since 2 September 2026, met in the design: the Sallen-Key moved X7R → C0G at 10 nF / 22 nF with 215 kΩ, giving $f_0 = 49.9$ Hz and a corner inside 47.6 to 52.6 Hz against the 45 to 55 Hz band. It was not met with the X7R parts, which ranged 42.4 to 57.4 Hz. Unchanged here still means not restated	ECO-EEG-027 for the AC coupling; the low-pass closed under ECO-EEG-019, 2 September 2026
E-12	raised from Should to Mandatory, because the comparator is now fitted	ECO-EEG-010
E-18, E-20	pin map and throughput wording; 50.7 kB/s of payload stated against the ≈70 kB/s allowance	ECO-EEG-009
E-23	rewritten as a separate charge-only receptacle, and the 45 °C charge inhibit restored to E-23 rather than cited from S-04	ECO-EEG-003
E-24	live non-conformance: the named isolator module presents USB-B against a USB-C requirement; interim answer is the WH-09 panel pigtail	no ECO; open
E-26	restated as a 6 mm tactile switch with a 12 mm coloured cap on an extender; panel openings 13.0 mm on a 14 mm pitch	correction, no ECO
E-27	unchanged, and met in the design since 2 September 2026: the bicolour phase driver is written, alternating on the FreeRTOS tick at about 250 Hz against E-27's "above 100 Hz". No unit exists, so no light has ever been driven and T11 has not been run	ECO-EEG-001

Requirement	Change	Source
E-28	restated as TP1–TP18 plus a 1×6 UART debug header at J26; the 2×5 1.27 mm JTAG/SWD header is withdrawn and every “E-28 deviation” note is deleted	correction, no ECO
E-29	new: headphone output not to exceed 100 dB SPL at any commanded level on an artificial ear, with the codec volume register clamped at the calibrated value. Calculated full-scale output is about 110 dB SPL, which is why the requirement is needed. Added as a type test and to RISK-EEG-011	new requirement, no ECO
F-06	ring relaxed from three minutes to 90 seconds plus unlimited microSD backfill	ECO-EEG-025
S-02	unchanged, and met in the design since 2 September 2026 at a calculated 36.8 μ A against 50 μ A, R1–R16 having gone to 68 k Ω . Not signed off: RISK-EEG-011 SR-01 is closed in the design and the safety review has not started	ECO-EEG-024, implemented
S-04	unchanged, and not met: no NTC net and no thermistor way exists	no ECO; open hardware item
S-09	new: lithium shipping under UN3481 and PI967	ECO-EEG-017
A-03	headband withdrawn as a kit item and rewritten to cover the HM-06 chin strap and the HM-03 occipital yoke, both on the frame	correction, no ECO
M-01	POD-P1 enlarged to 163 × 143 × 58 mm external; the Phase 2 helmet-shell figures are sized for a carrier that no longer exists	ECO-EEG-018, first finding
M-02	LED opening withdrawn: all eight lights are in the helmet and the pod carries no indicator	correction, no ECO

2.3 Foreseen and not raised

Two things are known, are not defects today, and would become ECOs if a measurement goes the wrong way. They are listed here so that they are not discovered as surprises.

1. **The DevKit 3V3 rail.** The carrier draws a calculated 288 mA worst case from the DevKit’s on-board regulator, which dissipates about 0.5 W in a small package inside a closed pod. Phase 1 measures it at TST-EEG-004 T3 and reports the

regulator case temperature. **If it exceeds 85 °C, a 3.3 V regulator on the carrier fed from V5V is an ECO against Rev C of the board.** It is not solved today; it is measured.

2. **Conformal coating.** The board is **not coated for Phases 1 and 2**, and that is a decision rather than a deferral: the board lives inside a gasketed enclosure, and coating a board with thirty connectors and a socketed DevKit costs more in masking than it buys. It is revisited before Phase 3 if a unit returns with corrosion.
-

2A. Corrections made by the third cross-document audit

A third pass, run after the second audit's corrections were applied, looked for one thing only: a number, a citation or a claim in one document that a different document contradicts. It found thirteen. **None of them is a design change** – no schematic, netlist, layout, firmware or mechanical part moves – so none takes an ECO number. They are corrections, and they are listed here so that anyone holding a printed copy can see what changed and why.

#	What was wrong	Where	Now
C-01	SIM-EEG-018 graded the DRC as a pass while its own evidence column read “25 violations”, and the headline said “1 known open item”	tools/ simulate_production.py	the check now asserts only that the violations are of the two known kinds, and the 25 are raised as an open item. History, and true when this row was written: the headline was 169 passed, 0 failed, 5 open. Superseded on 2 September 2026: the DRC reports zero violations, so the exception has nothing left to except and that open item is gone. The headline stood at 171 passed, 0 failed, 5 open when that sentence was written and is 193 passed, 0 failed, 6 open at the run behind this release – section 1.1 states it and names the six, and this row is not the place to read it from, which is the second time this row has had to be corrected for exactly the reason it warns about. A total written into a table as prose is a total that stops moving when the run does not; that is the second thing this row now guards. The first stands: a check that graded a DRC as a pass while its own evidence column read 25 violations is what it was raised against
C-02	Two different byte rates were both called “the stream”: 50.0 kB/s in SIM, 50.7 kB/s everywhere else	SIM-EEG-018	both are reported, named: 50.0 kB/s of raw sample payload, 50.7 kB/s framed (1014 bytes of frame, 1015 after COBS, every 20 ms)

#	What was wrong	Where	Now
C-03	The ring buffer was 118 s in seven documents, 126 s in two	RUL-EEG-021, RFQ-EEG-001, TST-EEG-004, DSN-EEG-003, AVL-EEG-017, ECO-EEG-016, IFU-EEG-014	126 s. The 118 s divided 6 MB <i>decimal</i> by the <i>framed</i> rate; the ring is 6 MiB = 6,291,456 bytes and it holds raw samples. 124 s if counted framed. RING_BYTES and the 90 s of F-06 are unchanged, so this is arithmetic recorded under ECO-EEG-025, not a new ECO
C-04	Ten documents said “no clearance violation” while the same page reported two of them. The Rev B closure named six and corrected three	corrected at Rev B: PARTS-EEG-019, the PCB spec sheet, README_package_index.txt. Named at Rev B but left unqualified until now: TST-EEG-004, ASM-EEG-007, RFQ-EEG-001. Never in the Rev B scope and also unqualified: ICD-EEG-006, QP-EEG-010, REG-EEG-012, FW-EEG-001	each of the ten was made to say <i>beyond those two electrode-net via clearances</i> , which is what the DRC report supported at the time. Withdrawn on 2 September 2026: those two vias are gone and the report records no clearance violation at all, so the qualifier is now itself wrong and the plain sentence is correct. What survives is the rule, not the wording – no document states a DRC result it has not read in the report. The Rev B row was written as closed before three of the six it named had been edited; the scope is restated here rather than closed a second time. No automatic check guards the wording yet, so review holds it until one is added to tools/simulate_production.py; a copy of the sentence found without the qualifier is a reintroduction and is to be raised against this row

#	What was wrong	Where	Now
C-05	SIM reported 156 surface-mount placements against 153 everywhere else	SIM-EEG-018	153 placed parts, of which R89 is do-not-populate; the CPL has 156 rows because it also carries the three fiducials , which take copper and mask apertures but no paste
C-06	The PCB spec sheet said TST-EEG-004 has 30 steps; TST-EEG-004 says thirty-one	kicad/EEG-CAR-01_RevB_PCB_spec_sheet.txt	31 steps (T00, T0, T1 to T29)
C-07	RUL-EEG-021 printed the fiducials at (8, 8), (142, 8) and (8, 122), and three documents called that a transcription error while the register still carried it	RUL-EEG-021, DSN-EEG-003, ASM-EEG-007, QP-EEG-010	the register carries (12, 10), (144, 100) and (12, 120) , matching design.py and the CPL, and the withdrawal is stated in the register itself
C-08	RUL-EEG-021 listed the ECOs as 001–015, 017 and 018, omitting the nine issued since	RUL-EEG-021	001–015, 017, 018 and 019–027, with 028 and 029 withdrawn
C-09	RUL-EEG-021 said the isolation keep-out is clear on “either layer”	RUL-EEG-021	all four layers
C-10	SIM graded E-27 a pass on the light current alone, while ECO-EEG-016 and TST-EEG-004 T11 both record E-27 as not met	SIM-EEG-018	the current check is retitled <i>current only</i> , and E-27’s missing bicolour phase driver is an open item. Superseded 2 September 2026: the driver is written, so the open item is no longer the missing driver but <i>E-27 has never been seen to light</i> – no unit exists and T11 has not been run. The split between a current check and a colour check is what this row bought, and it stands

#	What was wrong	Where	Now
C-11	SIM graded E-22 on a 150 mA board current that ICD-EEG-006 disputes at about 440 mA	SIM-EEG-018	E-22 is checked at both figures – 20.0 h and 6.8 h, so it is met either way – and the unreconciled current is an open item, as RFQ-EEG-001 Rev E open item 14
C-12	The DRC report's "CONDUCTORS BELOW THE 0.25 mm PREFERRED WIDTH: 19" contained entries at 0.28 and 0.56 mm, and disagreed with the "200" under MEASURED	tools/drc.py	the section is CONNECTIONS THE ROUTER HAD TO RELAX , split into <i>narrower than 0.25 mm and full width with a reduced gap</i> , and it states that it counts connections while MEASURED counts segments. The counts move with the route: 169 as the board now stands, 36 and 133 , against 19 when this row was written
C-13	Four citations pointed at things that do not exist: firmware/pinmap_EEG-CAR-01.h (twice), "DSN-EEG-003, Rev B as it then stood, section 5", "ASM-EEG-007 stage 2" for the reflow profile, and "FW-EEG-001 section 8" for F-08	ICD-EEG-006, SIM-EEG-018	firmware/main/board_pins.h, Rev C section 5, ASM-EEG-007 section 2.5 , FW-EEG-001 section 5.6 . The reflow figures now match ASM-EEG-007 section 2.5 exactly: 45–90 s above liquidus, 235–245 °C at the U1 body, 245 °C maximum anywhere

2A.1 What package v1 had and package v2 had dropped

A fourth pass compared every file in package/ against package_v2.4/ by CONTENT, not by name – twenty-eight artefacts, including the four workbooks and the zip that sit beside the package folder. Twenty-three were covered outright. Five were not, and all five were cases of package v2 carrying a file forward in name while losing what was inside it. None was noticed by any of the three earlier audits, because all three read package v2 against itself and never opened package v1.

#	What v1 had that v2 had lost	Severity	Now
C-14	The entire internal cost model. EEG_kit_BOM_INTERNAL_costed.xlsx held an Assumptions sheet, 436 price cells across four quantity breaks, and a subsystem roll-up. EEG_kit_BOM_INTERNAL_RevB_costed.xlsx was a copy of the <i>bidders'</i> workbook with two renamed columns and zero numeric price cells – it even carried the bidders' footer, "no prices are given in this file by design"	major	Rebuilt as EEG_kit_BOM_INTERNAL_RevC_costed.xlsx from tools/emit_costed_bom.py, on v2's 47-line part list, with the Assumptions sheet, per-line prices at 2/10/25/50, a per-line price basis column, the subsystem roll-up, the programme build-up with spares and NRE, and a v1-versus-v2 comparison. The empty Rev B file is deleted
C-15	The mirrored solder-side view. v1 shipped EEG-CAR-01_placement_bottom.pdf. v2's assembly drawing had a "bottom side" sheet, but it used the <i>same</i> transform as the top sheet, so it was the top view with a different title and every left-right instruction on it was wrong	major	tools/drawings.py gained a mirror transform. ASM 2 of 2 is now drawn as seen from underneath and says so on its face. This matters because ASM-EEG-007 §2.7 solders 217 socket-strip, 4 JST, 12 switch and 3 DIN joints from the bottom, and QP-EEG-010 IQC-B10 inspects against the sheet
C-16	The nine manufacturers' replies, and with them the only commercial evidence either package holds: Makerfabs' blank-sheet ODM quotation of US\$20-30k for Phase 1 design plus two samples	minor	Restored as DSN-EEG-003 §8.1, with the arithmetic that makes it matter: a blank-sheet engagement is four to seven times the whole of Phase 1 at the two-unit break, which is <i>why</i> the instrument is module-on-carrier

#	What v1 had that v2 had lost	Severity	Now
C-17	The RFQ cover email , RFQ-EEG-001 Rev C Annex A – the only text in the package written for a reader who has opened nothing yet	minor	Restored as RFQ-EEG-001 Rev E Annex A , updated: four layers not two, and routing supplied not requested. It stated the twenty-five open items in the letter rather than leaving them to be discovered after quoting; since 2 September 2026 what it must state instead is that the data is released for review and not for fabrication, and that the routing is unreviewed. The reference-document list moves to Annex B
C-18	Every foam corner radius . v1 specified sheet R14, HELMET R40, HEADPHONES/ELECTRODES R10 and the small pockets R8. Both v2 DXFs drew every profile square, and no document stated a radius	minor	tools/mech_gen.py draws true arcs at v1's radii. PKG-EEG-015 §2.3 orders a steel-rule die for Phase 3, and steel rule cannot be folded to a true 90 degree inside corner – a square profile either tears the foam or silently becomes whatever radius the die maker picks

Three findings raised by the same pass were **refuted** on re-check and are recorded here so they are not raised a fourth time: the netlist report's two USB route rules (the geometry survives in v2 rule 6 and the stub prohibition in RFQ F-12), the Ø104 mm circle in v1's foam top layer (a helmet dome relief made unnecessary by the two-layer split), and the three cover-email variants of v1's Annex A (carried by DSN-EEG-003 Annex B's conditional wording).

The lesson is the one C-01 to C-13 already taught, applied to a different axis.

Those thirteen were package v2 contradicting itself. These five are package v2 contradicting package v1 – a file kept by name and emptied of content. A name-by-name diff finds none of them; only opening both files does.

Two further corrections were made at the same time and are not numbered above because they close a finding rather than resolve a contradiction: **FW-D15** is marked closed, because the header it complained about now reads RFQ-EEG-001 Rev E; and SIM-EEG-018's manual-handling note now states the two-to-three-minute fitting time as IFU-EEG-014 does – *once the participant has done it once*, with five minutes allowed for a first-timer.

2B. How the board was closed, 2 September 2026

Class: not a change to the instrument. No schematic, netlist, BOM, mechanical part or firmware line moves in this section: parts moved on the board and three faults in the programme's own tools were corrected. **It takes no ECO number.** The placement comments in `tools/design.py` label these changes ECO-EEG-028, which is a number this register withdrew under section 2 and does not reuse; the record is here, and the next free ECO number is still **ECO-EEG-030**.

Was: the route ECO-EEG-018 was first written against – **122 of 145 nets connected, 23 unclosed, 7 of those with no copper at all, 25 DRC violations.** **Now: 145 of 145 connected, 0 unclosed, 0 without copper, 0 violations.** Four things did it, and the order matters, because each one exposed the next.

1. **Placement, before routing. J4 moved 14 mm south**, from $y = 36$ to $y = 50$, so that its analogue pins face the protection rows that feed them instead of fanning diagonally through one window and sealing each other in. **R92 and R93**, the separable AVDD2/AVSS2 rail links, moved off $x = 54$ – where the rail trunk ran between them and J29, which is why AVSS2 shipped with no copper at all – to the mid-latitude of the pins they serve, so no rail net runs the length of the socket. **J22** moved from the bottom edge to directly under the protection ladder, which shortened two electrode runs from about 50 mm to under 9 mm and freed the ladder's own escape lane. Smaller moves went with them: C80/C81, J9, J26, R94/R95, TP10/TP11, and one millimetre of extra pitch between the clamp and capacitor columns for a rail lane.
2. **The isolation keep-out was being measured from centrelines.** The router blanked the cells of the strip but ignored the width of the copper it was carrying, so a 0.56 mm track whose *centreline* stayed outside the keep-out could still overhang it. The blank is now inflated per layer by the carried copper radius, so **copper edges** stay out of the strip. This is the mechanism behind the inner-plane copper that earlier revisions found inside it.
3. **The pre-placed reference vias were stamped on two layers of four.** `_place_ground_via` stamped each one on the top layer and the first inner layer only, while `Router.rebuild()` stamps all four, so **69 vias were invisible to the bottom-layer router**: it routed over them, and at AGND_REF pad U1.3 it ran a track through one and disconnected it. Stamping every reference via on all four layers is a one-line fix and it closed most of what was left open.
4. **Two targeted repairs.** An **AGND_REF stub outward from U1.3 with a through-via** onto the planes, which reports itself skipped if the pad is already joined; and the **SPARE2 corridor**, R16.2 to D16.3, freed by ripping AVDD, AVSS, AGND_REF, EMGIN3 and EOGIN1 where they crossed it, routing SPARE2 first at its full electrode class and then **re-joining all five ripped nets at their own full class**. Rotating R16 was measured and rejected: pad 2 already faces D16, and turning it would move the pad away and push EOGIN2 across the lane SPARE2 needs.

What it cost, and it is not nothing. Connections the router had to relax rose from **19 to 169** – 36 with a conductor narrower than the 0.25 mm preferred width, 133 at full width with a reduced gap, every one at or above the 0.20 mm minimum conductor and gap, so none of them is a violation. Track segments went from 3 370 to **3 745** and through vias from 498 to **552**. **A board that closes at minimum geometry is not the same board as one that closes at preferred geometry, even when every rule passes.** The 169

are listed in the DRC report by net and by pad pair, and they are the first thing RFQ-EEG-002A's reviewer is asked to read.

Verified: kicad/EEG-CAR-01_RevB_DRC_report.txt – violations 0, 145 of 145 nets fully connected with none left without copper, minimum clearance 0.260 mm on F.Cu, 0.275 mm on B.Cu and 0.285 mm on the planes against a 0.200 mm rule, narrowest track 0.200 mm, smallest plated hole 0.300 mm, zero zone crossings, exactly one AGND_REF-to-DGND bridge and one HARN_SHIELD-to-DGND bridge, no duplicate segments and no duplicate via positions, and one continuous plane island per net on both inner layers.

2C Two findings of 2 September 2026, after the gate was met

Both came out of auditing the package against a question it had not been asked – whether anything attaches to the wrist – and neither is a routing defect.

The pad model. tools/fplib.py:171 gives every through-hole header pin but pin 1 the shape oval, which at equal sides is a circle; that is the KiCad convention and what kicad_write.py emitted. pours.py modelled every non-circular pad as a box and gerber.py apertured it R,1.6X1.6, so the connectivity check, the clearance check and the copper that would have been fabricated all carried a 1.6 mm square where the design has a 1.6 mm round pad. The corners are 27 % of the pad area and the router used them: 145 of 145 nets closed on the square, 62 of 145 on the round pad. **Fixed** – gerber.py now emits C,w for a square oval and pours.py models a circle, so the fabricated copper, the KiCad file and the check agree. 184 stranded track ends were given entry stubs to the pad centre by the new tools/pad_snap.py, added rather than substituted because moving an end rotates its segment and the first attempt put MISO 0.158 mm from a via of START. Re-checked: **145 of 145, VIOLATIONS: 0** on the round pads. Segments 3 560 -> 3 744, vias unchanged. That 3 744 is the figure at that repair and **not the census of the released board**, which is **3 745 segments and 552 vias** – the bias-lead fix below added one of each. The routing-result table in ECO-EEG-018 and kicad/EEG-CAR-01_RevB_DRC_report.txt carry the current figures.

The bias-lead protection topology. As found: design.py wired all sixteen protection networks as src(patient) -[Rn]- dst(module) with Dn.3 and Cn.1 on dst, and then overrode channel 11 to put D11.3 and C11.1 on BIAS_EL, the patient side. A shorted D11 half therefore reached the Fpz electrode **with no series resistor in the path at all** (183.6 uA on this programme's bound B, against S-02's 50 uA), and a shorted C11 bonded that electrode to AGND_REF – the earth connection IFU-EEG-014 tells the participant does not exist. Rev B recorded it as **not fixed, and not fixable by layout** – RISK-EEG-011 **SF-1a**, **SF-6a** and **SR-12** – with the sheet-2 schematic note that claimed every conductor reaching a person passes through one resistor and one clamp corrected against it.

Fixed on 2 September 2026, and it is a netlist change, not a layout one. The channel-11 exception in design.py is deleted: the row is generated by the same loop as the other fifteen, so **D11.3 and C11.1 sit on BIASOUT, behind the series resistor**, and the Fpz electrode is no longer reachable through a shorted clamp half with nothing in the path. **SF-1a collapses into the ordinary SF-1**, and no part is added and no value changes: an exception is removed. ECO-EEG-024 alone would not have closed this – D11 had no resistor in its fault path at all, so a larger resistor elsewhere changed nothing, which is why the two had to be taken together. Getting four re-labelled pads back into a closed board took a repair rather than a re-route: tools/repair_nets.py runs a full DRC afterwards and refuses to write unless the board comes out at least as

good as it went in, and it refused twice. The board is **145 of 145 nets, 0 violations, 3 745 segments and 552 vias** – one segment and one via more than before the fix. **It is still for the electrical safety review that has not happened:** RISK-EEG-011 owns SF-1, SF-6 and SR-12, and a fault path removed in the netlist is not a fault path reviewed.

Impact: the fabrication-release gate of section 3 is met, and the data in kicad/ is **released for review under RFQ-EEG-002A**; the routing-result table in ECO-EEG-018 above and section 3.4 of DSN-EEG-003 are restated from the report. Nothing else moves. **Nothing here has been manufactured or measured, and no human layout engineer has reviewed the routing.**

*This is the record of 2 September 2026 and it stands as a record. **Both of its last two statements are superseded by ECO-EEG-030 of 4 September 2026:** a human layout engineer has read the routing, and the data in kicad/ for Rev B is withdrawn from fabrication rather than released for review. Section 3 is the current gate. Rev B closed this section by naming two requirements that were not met and were untouched by the routing work: S-02 at a calculated 53.2 μ A, and S-04's charge thermistor. **Corrected 2 September 2026: S-02 is met in the design at 36.8 μ A under ECO-EEG-024, and unsigned. S-04 is unchanged and still not met** – there is no NTC net in design.py and no thermistor way on J12 or J13, so it does not exist and cannot be tested.*

2D The firmware and the test tool, 2 September 2026

Class: not a change to the instrument, and **it takes no ECO number.** No requirement, schematic, netlist, BOM, mechanical part or pin assignment moves in this section. What moved is firmware source that did not do what FW-EEG-001 Rev D already required of it, and browser source that did not either. FW-EEG-001 owns the firmware defect register and the FW-Dnn numbers; this section records what happened so that the register is not the only place it is written down. The next free ECO number is unchanged at **ECO-EEG-030.**

The firmware could not have been built. firmware/main/drivers.h did not exist. main.c called seven functions that drivers.c defines – sd_free_mb, unit_serial_into, atecc_serial_into, battery_percent, envelope_onset_after, codec_play_tone_at and the drv_* group – with no declaration in scope. In C99 and later an implicit declaration is an error rather than a warning, and ESP-IDF compiles with -Werror=implicit-function-declaration, so the build stops. Where a toolchain does accept it, the failure is quieter and worse: an undeclared function is assumed to return int, so sd_free_mb()'s uint32_t and the pointer returns are truncated or misread at run time with no diagnostic. **Now:** drivers.h declares the API and is included by both main.c and drivers.c, so the compiler checks the definitions against the prototypes the callers use. main.c also now includes board_pins.h and esp_attr.h, which it had been using without including.

FW-D14: every command the browser sent started a recording session. A host command is a full frame – the ten-byte header of FW-EEG-001 section 5.1, then the opcode, then the opcode's own payload. rx_task() handed handle_command() the frame from byte 0, so what the firmware read as the opcode was header byte 0, the protocol version. PROTO_VERSION is 1 and CMD_START_SESSION is 0x01, so **IDENTIFY, LOOPBACK, CLOCK_XCHG and the rest all dispatched as START_SESSION**, and the one command that appeared to work did so by that coincidence and not because anything was right. **Now:** rx_poll() strips the ten-byte header and validates the

version and the frame type before dispatch, and the body of `rx_task()` is factored into `rx_poll()` so a host harness can drive the real decode path rather than a copy of it. FW-D14's status in the defect register belongs to FW-EEG-001.

The acknowledgement did not have the shape the specification gives it. FW-EEG-001 section 6.2 fixes the `CMD_ACK` payload as opcode echoed, one reserved zero byte, status, result length, then the result. Every ack went out as two bytes with the status at offset 1 and no length, and `IDENTIFY`, `LOOPBACK` and `CLOCK_XCHG` skipped the shape altogether and returned their result at offset 0. That is not tidiness: with no opcode echoed on three replies, a host cannot tell which command an acknowledgement answers, and a queue that resolves the next pending command with whatever arrives will mis-attribute a reply under any load at all. **Now:** the firmware emits the section 6.2 shape, with defined statuses for ok, unknown opcode, the VBUS charge interlock of S-01 and not-implemented; and the browser tool's `transport.js` and its simulated device were corrected to read and write the same shape.

Two capability bits said something they did not mean. `CMD_IDENTIFY` never set `CAP_CODEC` under any condition, although TOOL-EEG-022 section 2.3 defines bit 3 as *codec initialised* and the tool displays it, so a working codec always read as absent. `CAP_ATECC` was set only when the ATECC608B's configuration zone was locked, conflating *the chip is fitted* with *the unit is provisioned* – different questions, asked at different stations, and the second is what T6 turns on. **Now:** `CAP_CODEC` is set when the codec is ready, `CAP_ATECC` when the chip answers, and `CAP_PROVISIONED` when the configuration zone is locked.

Why none of this was caught, which is the part worth keeping. The browser tool's own test suites passed throughout, and they still pass. They could not have failed. The host and the simulated device it is tested against are **both JavaScript, written together from the same reading of the specification, and they shared the same misunderstanding:** the JS device answered an acknowledgement of { opcode, 0xFF }, the JS host expected exactly that, they agreed with each other on every run, and they agreed with neither FW-EEG-001 section 6.2 nor `main.c`. There were three acknowledgement shapes in the package – the specification's, the firmware's and the JavaScript pair's – and the only pair ever compared was the one that could not disagree. The header defect was invisible for the same reason: the JS device read the header the JS host wrote, so nothing in that suite ever asked where the opcode was. It is not a weak test; it is a test of the wrong thing, and no quantity of it would have found FW-D14.

Now: `webtest/tests/interop/` removes the shared author. It compiles the shipped firmware/`main/main.c` against small ESP-IDF stubs – on a copy, with one `_Static_assert` on a TinyUSB descriptor length neutralised because the stubs cannot expand that macro, and the shipped source is not modified – wires its USB endpoints to a pipe, and drives it with the browser tool's own `protocol.js` and `transport.js` under Node. The C firmware and the JavaScript host are therefore checked against each other rather than each against its own reflection. It runs **57 checks, all of which pass and none of which fail** – 32 when this section was written, and the count moved as checks were added, most recently for the provisioning opcodes of section 2E – and is invoked as `sh webtest/tests/interop/run.sh`. It needs a C compiler and Node, and neither ESP-IDF nor hardware. That total is the interop harness's own; the production-simulation total is the one in section 1.1, and the two are not to be quoted for each other.

Impact: firmware source, the browser tool's `transport` and simulated device, and one new test directory. **Nothing here has been run on hardware** – no unit exists, the interop harness runs the firmware's dispatch path on a host compiler against stubs, and

what it proves is that the two implementations agree with the specification and with each other, not that either works on the instrument. *Rev B wrote “nothing here has been built or run on hardware”; the “built” half became false later the same day and is corrected in section 2E, which records the first real ESP-IDF build. The “run on hardware” half stands. Three documents carry the consequences and not this one:* FW-EEG-001 owns the FW-Dnn register, the section 5 wire format and the section 6.3 opcode table that places CMD_IDENTIFY and CMD_LOOPBACK; TOOL-EEG-022 owns the tool's own file list and its account of what the tool is tested against; TST-EEG-004 owns the T-numbers, and **the interop harness has none and is not a production test step** – TST-EEG-004 requires it re-run for every firmware image as a control on the tool, which is a different thing from a step a unit passes.

2E The firmware was built, and then it was run, 2 September 2026

Class: not a change to the instrument, and **it takes no ECO number**. No requirement, schematic, netlist, BOM, mechanical part or pin assignment moves here. What moved is the firmware project's own build configuration and one host script. FW-EEG-001 owns the firmware, the FW-Dnn numbers and the opcode table; this section records what happened, because until 2 September 2026 no document in this package could say that the firmware had ever been through a compiler, and several said the opposite as a matter of record. The next free ECO number is unchanged at **ECO-EEG-030**.

The build

ESP-IDF v5.2.5, target esp32s3. firmware/release/ holds the four images ASM-EEG-007 section 6.1 and FW-EEG-001 section 9 tell the operator to flash – bootloader.bin at 0x0, partition-table.bin at 0x8000, ota_data_initial.bin at 0xF000 and eeg_field_kit.bin at 0x20000 – with **manifest.json recording the SHA-256 of each**, and the production simulation verifies every digest on every run. The application image is **405,360 bytes** as flashed, and esp_idf_size reports **405,245 bytes** of linked image in firmware/release/size.json. The build is the Phase 1 configuration, sdkconfig.defaults + sdkconfig.phase1: secure boot, flash encryption and anti-rollback off, so a prototype burns no eFuses and stays re-flashable (RUL-EEG-021 section B).

That closes a hole the package had carried since v1: the shop had a flashing procedure and nothing to run it on, while the same documents forbid the shop building the firmware itself.

The five defects the build found, none of which any check in this package could have found

The interop harness of section 2D compiles main.c against stubs, and **a stub agrees with anything**. A real toolchain does not.

1. **esp_driver_i2c does not exist at ESP-IDF 5.2.** The I²C driver was split into its own component at 5.3 and main/idf_component.yml permits 5.2, so the project required a component by name at a version where it is absent, and configuration stopped dead. The driver component provides I²C at both versions.
2. **sdkconfig.phase1 set CONFIG_BOOTLOADER_APP_ANTI_ROLLBACK twice** – =n, with a comment explaining why a Phase 1 prototype has none, and =y eleven lines later in a block added to close FW-D11. **The later duplicate silently wins**, so the Phase 1 intent was being undone by a line that read as an addition. It also

fails the build outright: ESP-IDF refuses anti-rollback on a partition table carrying a factory partition, and `partitions.csv` has one. That is how it was found – the first real build stopped there.

3. **CONFIG_TINYUSB_VENDOR_ENABLED does not exist.** `esp_tinyusb 1.4.x` calls it `TINYUSB_VENDOR_COUNT`, and **ESP-IDF warns on an unrecognised key rather than failing**, so the setting looked present while `CFG_TUD_VENDOR` stayed 0, `tusb.h` declared none of the `tud_vendor_*` functions, and **the WebUSB interface this whole instrument is built around would not have existed.** It surfaced as an implicit declaration of `tud_vendor_mounted` the first time the firmware met a real compiler.
4. **Three descriptor callbacks were defined twice.** `main.c` defined `tud_descriptor_device_cb`, `_configuration_cb` and `_string_cb` and passed the same descriptors through `tinyusb_config_t`; `esp_tinyusb` defines those three itself, so the link failed with three multiple-definition errors. With `CONFIG_TINYUSB_DESC_CUSTOM` the descriptors are data and the component owns the callbacks. `tud_descriptor_bos_cb` stays, because the component defines no BOS callback and without BOS there is no WebUSB.
5. **firmware/main/drivers.h did not exist**, so `main.c` called seven functions with no declaration in scope. That one was found earlier the same day and is recorded in section 2D above; it is counted here because it is the same class of defect and the same compiler would have caught it.

One more thing the build measured rather than fixed. Static IRAM links with **one byte free of 16,384**. That is a cliff, not a pass: the next function anyone marks `IRAM_ATTR` fails the link with an error naming a section rather than a cause, and this design has more interrupt work coming. Two ISRs this firmware does not use – there is no SPI slave in the design and nothing uses `gptimer` – were taken out of IRAM and **the figure did not move by a single byte**, so that is not the cause and is not to be recorded as the fix. It is open item 1 of the simulation run, and settling it means reading the linker map against hardware.

The QEMU run, and what it does not prove

`firmware/release/qemu_boot.log` is one full boot cycle from `qemu-system-xtensa 9.0.0, -M esp32s3`, against this build with an emulation overlay – `sdkconfig.qemu`, which sets `CONFIG_SPIRAM_IGNORE_NOTFOUND` because QEMU's `esp32s3` has no octal PSRAM, and which is an emulation overlay and not a build configuration for any unit. What executed, none of which ever had: the second-stage bootloader read **this** partition table, all nine entries, and loaded the app from the factory slot at `0x20000`; `app_main()` reached its own banner; the microSD mount failed, as it must with no card, and the firmware continued with the warning it was written to give; the ES8388 failed and degraded the same way; and the 6 MiB ring would not allocate, where **FW-D13's NULL guard caught it and named the cause**, `CONFIG_SPIRAM_MODE_OCT` and the `-N16R8` part. Three bring-up paths exercised, three behaved as designed.

It has never run on hardware, and QEMU carries none of the peripherals this firmware talks to – no octal PSRAM, no microSD, no ES8388, no ADS1299. No register value, no daisy-chain order and no SPI timing has met silicon. The run proves the part that needs none of them. About the instrument it proves nothing.

And it found a failure mode, which is what running things is for. Two subsystems degrade and one aborts: a missing card and a missing codec are warnings, a missing ring calls `abort()`, and the unit reboots into the same abort for ever. On a bench that is right – without the ring there is no recording. In a participant's home it is the worst

available behaviour: **a boot loop is indistinguishable from a flat battery or a broken cable**, the device never enumerates, and the browser tool that exists precisely to answer “what is wrong with this unit” can never reach it. It is raised against F-06 and TOOL-EEG-022 and it is not closed here.

The provisioning opcode collision, and the guard that was missing

firmware/tools/provision.py and main.c both allocated **0x4A** on 2 September 2026 – the host for the ATECC configuration-zone write, the firmware for `CMD_READ_CALIBRATION` – because each picked the next free opcode without the other. Moving the host’s config write to 0x4B then landed on an opcode **the same file was already using**, so for a short time both `CMD_ATECC_WRITE_CONFIG` and `CMD_READ_CALIBRATION` stood at 0x4B: a second collision, made while fixing the first, and this one inside a single file. Provisioning step 7b’s read-back would have sent a three-byte request that the firmware parses as a 65-byte configuration write and answers bad-length, so **TST-EEG-004 T6’s acceptance read-back would have failed on every unit**.

Both collisions are closed, and main.c is the authority: 0x4A reads calibration, 0x4B writes the configuration zone, which is what the firmware implements and what provision.py now sends. The guard matters more than the fix. **provision_selftest.py now asserts that every CMD_ constant in that file is unique and matches main.c** – the check whose absence let one opcode be allocated twice in a single day – and two of the interop harness’s 57 checks pin the meanings from the other end, refusing a short config write with bad-length and confirming that 0x4A still answers as the calibration reader. An opcode table belongs in one place; until it is in one place, a test has to hold it.

Impact: the firmware project’s component list and build configuration, one host script and its self-test, and four release images with a manifest. **Nothing here changes the instrument, and nothing here is a bring-up. Three documents carry the consequences and not this one:** FW-EEG-001 owns the FW-Dnn register, the section 6.3 opcode table and the ESP-IDF version it pins; TOOL-EEG-022 owns what the tool is tested against; TST-EEG-004 owns T6 and the T-numbers. **Any document still saying that the firmware has never been compiled is wrong as of 2 September 2026**, and each of those documents corrects that for itself – this register records the fact, it does not amend other documents from here.

ECO-EEG-035 — the gaps eleven quotations exposed

Raised 10 September 2026. Eleven manufacturers are mid-quotation and their questions found things that were invisible until somebody tried to price or build from the package. Six work packages were opened. **Two of them were decisions and produced no change to any document**, which is recorded here as an outcome and not as an omission.

What changed.

Change	Where
A datasheet index, link-only, with a per-row verified / resolved / blocked mark	docs/datasheets/README_datasheets.md (new)

Change	Where
The third-party licence exclusion, stated in three places	README.md, README_package_index.txt, docs/datasheets/third_party/LICENCE_NOTE.md (new)
A review gate on the ATECC608B configuration zone, and the per-byte review behind it	firmware/tools/atecc608b_config.py, firmware/tools/provision.py, FW-EEG-001 section 7.6 (new), template checklist item 9 (new)
Three kit-BOM module rows restated to say what is open and what is not	tools/emit_workbooks.py; the two BOM workbooks regenerated
Three papers: two decisions and one investigation	reports/DECISION_electrode_analogue_ref_widths.md, reports/DECISION_internal_annular_ring.md, reports/INVESTIGATION_fixture_pcb_copper.md (all new)

What did NOT change, deliberately. No requirement, no limit, no netclass width, no governing figure, and no part number. tools/design.py, tools/rules.py, DSN-EEG-003, QP-EEG-010 and RFQ-EEG-001 are untouched. The ATECC608B configuration is **not** marked approved.

The licence position, which was worse than “incomplete”. The repository has **no LICENCE file at all**. It carried two blanket statements — README.md and README_package_index.txt — asserting CC BY-SA 4.0 over “hardware and documents” with **no third-party carve-out anywhere**. Placing a manufacturer’s datasheet inside that tree would have purported to license a work this programme does not own. The exclusion is now stated in all three places rather than only in the subfolder, because a reader who never opens docs/datasheets/ still has to meet it. **No datasheet PDF is stored**; the index links to manufacturers’ own URLs.

Finding 1 — the Stäubli part number does not resolve, and it is the patient-connected one. design.py gives J15, J16 and J17 Stäubli SLB1,5-F / LB-I1,5. **Neither designation appears in Stäubli’s medical catalogue (doc. 11014109) or its Test & Measurement catalogue (doc. 11014124)**, both of which were fetched and searched. In the SLB series the numeral is the contact diameter — SLB2-*, SLB4-* — and there is no 1.5 mm member. What Stäubli publishes at Ø 1.5 mm to DIN 42802 is MEB1,5-R, MLB1,5-R, LS1,5-B, MS1,5-S and MLK1,5-B. This is very likely why three manufacturers asked for the datasheet and nobody could supply it. **design.py is unchanged**: correcting a non-substitutable patient-connected part is a person’s decision, and it also raises a question this register does not settle — the two panel-mount parts Stäubli publishes present a **pin**, the carrier footprint is named . . . _Socket, and kit BOM row 36 buys leads with a **plug**. Which end carries the male contact belongs to RISK-EEG-011 and the safety reviewer. ECO-EEG-031 already marked these sockets non-substitutable; it did not check that the part exists.

Finding 2 — provisioning could be run against a real part. provision.py printed “PROPOSAL, not reviewed” and then carried on. It now **refuses and exits 2** on any run that is not --dry-run, and there is **no --force, no environment variable and no file**

that enables it: the flag is set by a person editing `atecc608b_config.py`. `--dry-run` is unaffected and `provision_selftest.py` passes unchanged. The consequence, stated plainly for assemblers, is that **provisioning cannot be quoted as a production operation today** — it is blocked at the tool, by design.

The review itself is FW-EEG-001 section 7.6. It corrects the common framing: the template **specifies four bytes and deliberately does not write the other 124**, so the outstanding question for those 124 is not “what value” but “is inheriting the factory default acceptable on a part that will be permanently locked”. Choosing 124 values would be the worse outcome. Section 7.6 also finds that the template’s byte map does not name the **608-specific** control bytes — `UseLock`, `VolatileKeyPermission`, `SecureBoot`, the KDF IV controls and `ChipOptions` — which the published 608 map places at offsets **68–74 and 90–91**. That is **new checklist item 9**, and the offset attribution is asserted from the published map, not read out of the datasheet.

Finding 3 — the width proposals cost the opposite of what was assumed.

Measured from the released Rev B geometry, segment by segment, reproducing the regrade tool’s 322 under-width findings exactly: **ELECTRODE has zero**, at a narrowest 0.300 mm against a 0.25 mm minimum and 0.30 mm preferred — it already meets the *preferred* figure everywhere, so promoting it costs nothing. **ANALOGUE_REF has 186, 58 % of every under-width finding on the board**, and all 186 are on AVDD and AVSS while AGND_REF has none — meaning the 0.30 mm minimum binds hardest on the two nets its own justification, written about the mid-rail, does not describe. The paper also corrects the brief that raised it: both rows are `confirm=( "width" , )`, not a whole-row flag. **No width was chosen.**

Finding 4 — the annular ring is derived from the wrong diameter. The 0.15 mm nominal ring and the 0.125 mm misregistration budget check out arithmetically against DSN-EEG-003 §3.2. But every statement of them in this package derives the ring from the **0.30 mm finished hole**, where the internal annular ring is measured to the **drilled** hole, which is larger by the plating allowance. At a routine 25 µm per wall the real budget is **0.100 mm, 20 % tighter than the plan states**. Related and independent: **nothing in this package states a drill size or a plating allowance anywhere** — the fabricator is given a finished dimension and asked to meet a ring figure computed as though no plating existed. That gap should be closed whatever is decided about IQC-B11. This point is **asserted from standard IPC practice and has not been verified against a copy of IPC-6012**. QP-EEG-010 is unchanged.

An investigation that concluded the work should not start. `fixtures/pcb/` holding only FIX-01 and FIX-04 is **correct and complete**: FIX-03 is a printed nest plus bought items and is not an electronic assembly at all, and FIX-02 has a circuit but no board and never had one specified — §6.1 prices a PCB line for FIX-01 and FIX-04 only. Copper was omitted by decision, is priced at **85 hours / EUR 4 675** one-off in §6.1 and scheduled at **15 working days** in §6.3, and turns on one number the package does not carry: **the Omron G6K-2F-Y land pattern**, against a FIX-01 area budget with a **1.0 % margin**. Routing before that number is known would spend EUR 2 530 against an outline that may not close. `tools/fixture_gen.py` cannot emit copper and should not learn to — machine routing on the carrier is exactly what the external reviewer rejected. **No fixture file was changed.**

A pre-existing break found in passing, not fixed. `tools/emit_workbooks.py` resolves `V1 = os.path.dirname(PKG)` and reads `EEG_kit_manufacturer_contacts.xlsx` from **beside the repository**, where it does not exist, so `main()` cannot complete. The kit BOM and the costed BOM were

regenerated by calling their builders directly;
EEG_kit_manufacturer_contacts_RevB.xlsx was **not** regenerated and is unchanged. emit_workbooks.py also needs openpyxl, which is not in any pinned requirement file in this repository. Raised, not solved.

Impact: two new documents under docs/datasheets/, three papers under reports/, one new section in FW-EEG-001, one new checklist item, a refusal in one host tool, three restated BOM rows and the licence exclusion in two top-level files. **Nothing here changes the instrument, and nothing here closes a decision that belongs to a person.**

ECO-EEG-036 — closing ECO-EEG-035 so it can be published

Raised 10 September 2026. ECO-EEG-035 did what it was asked and stopped where it was told to. Two of its findings **contradict statements already made to manufacturers**, and nothing could be published to them until those were resolved. This change resolves them.

What changed

Change	Where
Hole sizes declared as finished diameters; the fabricator must declare the tool size and plating allowance per lot	tools/design.py fabrication notes 7a and 7b ; DSN-EEG-003 §3.2, two new rows
The via row now says 0.15 mm EXTERNAL annular ring, with the internal ring stated separately as (0.60 – drilled) / 2	DSN-EEG-003 §3.2
J15–J17 provenance, requirement and candidate search	reports/ INVESTIGATION_din42802_sockets_ J15_J17.md (new)
Connector gender opened as a finding, with the analysis attached	RISK-EEG-011 SR-13 and new §10.1
Three blocked lookups, one page	docs/datasheets/OPEN_LOOKUPS.md (new)
ECO-EEG-035's plug/pin claim withdrawn	docs/datasheets/ README_datasheets.md §1
Recompute, verification status and the superseded-figure list	reports/ DECISION_internal_annular_ring. md §3.4–3.6

No requirement or limit was changed. QP-EEG-010 is untouched — that decision is open and vendor answers are still arriving. **design.py's part number for J15–J17 is untouched.**

The J15–J17 part number: traced, and it was never verified

SLB1,5-F / LB-I1,5 entered at **b18782a**, the **root commit of the repository**, byte-identical to today, and eight subsequent commits touched the string without changing it.

The package never claimed it was verified. AVL-EEG-017 §1.4.1 has said throughout that it is “a class of part, not a confirmed PCB part”, that “no catalogue part has been confirmed to fit it”, and that the line has **no qualified vendor** and a **12-week first-article lead time**; footprint_audit.py reports J15–J17 as **OPEN**, never as a pass. **ECO-EEG-031 is the near miss**: it audited four unbuyable part numbers, corrected three outright, and for this one added a NOT_SUBSTITUTABLE flag instead — nobody checked that the designation exists.

One refinement to AVL-EEG-017 §1.4.1, which is **not amended here**: it describes the two strings as “cable and panel parts”. On the fetched catalogues they are **not Stäubli designations of any kind**. Its conclusion — no qualified vendor, sample required — stands.

The finding that is urgent because of timing, not severity

No verified candidate meets the requirement, and the reason is structural. Stäubli’s medical catalogue, searched in full as fetched text, contains **no occurrence of “PCB”, “printed circuit”, “solder pin”, “through-hole” or “board mount” anywhere**. Every 1.5 mm DIN 42802 part any manufacturer was found to publish is a **panel** part or a **cable** part. The carrier footprint DIN42802_1p5mm_Socket is a **PCB** part, and fplib.py’s own docstring calls it a “panel socket, **PCB-mount version**”.

AVL-EEG-017 §3 already names the fallback: “a panel-mount socket on a flying lead into a 1×3 header, **which moves the part off the carrier footprint entirely**”.

That is a placement change, and the Rev C layout desk has not started. Three 9.8 × 7.8 mm bodies and nine holes sit in the analogue zone under the tightest clearance rule on the board. Taken now it is an edit to design.py and a re-emission. Taken after placement, the 15-day layout leg is paid twice. **The recommendation — stated as a recommendation — is to settle whether these are board- or panel-mounted before the layout desk is released to place, even if the part itself is not chosen by then.**

A claim withdrawn

ECO-EEG-035 recorded that “a plug and a pin cannot both be right”. **That was over-called and is withdrawn.** In DIN 42802 trade usage the lead-end part is a *touch-proof plug* and is **electrically female**; the instrument end is an *input socket* carrying a **recessed male pin**. Two independent manufacturers state it, and Stäubli’s product shapes agree. The package’s naming is therefore consistent, not contradictory.

What is genuinely open is **SR-13**: the convention is read from vendor documentation, not from DIN 42802 or IEC 60601-1, neither of which this programme holds; and WH-EEG-008 §3.1.2.1 calls the lead-end parts “**male** plugs” where those manufacturers call the same part female. Under one reading that is a wording correction; under the other it is a patient-safety concern. **It is not corrected here, because correcting it presumes the answer.**

The IPC reading stays asserted, deliberately

A copy of IPC-6012 is **not available** — paywalled, and held nowhere in this repository. The reading that the internal annular ring is measured to the **drilled** hole therefore **stays marked asserted** and has **not** been upgraded by finding a secondary source that agrees.

WP-F — what was stated to manufacturers, and what supersedes it

Recorded here so that a vendor receiving a correction can see it logged in the same register that governs everything else they have been given.

Stated	To whom	When	Evidence	Superseded by
<i>“J15, J16 and J17 are Staubli SLB1,5-F / LB-11,5 DIN 42802 1.5 mm touchproof sockets”, with an offer to supply them on consignment if they could not be sourced</i>	PCBCart , ticket BSY-598327, quotations 20260909185 (EEG-CAR-01) and 20260909781 (WH-BUS-01)	9 September 2026	dist/rfq/pcbcart/EEG-CAR-01/README_for_bidder.txt note 5; records/vendor_submissions/PCBCART_BSY-598327.md	This entry. The part cannot be identified, so the consignment offer cannot be honoured as written . “Non-substitutable” stands and is correct
The Stäubli part described as genuine and non-substitutable	three manufacturers , per the brief that raised this change	not evidenced in this repository	—	This entry. The identity of the three and the dates are not recorded here because they are not held here ; they are in the correspondence and should be added by whoever holds it
Internal annular ring budget 0.125 mm	three manufacturers , per the brief	not evidenced in this repository	—	reports/DECISION_internal_annular_ring.md §3.2 and §3.6: the figure is derived from the finished hole and is optimistic ; at a 0.10 mm allowance the budget is 0.100 mm

What was NOT sent, checked rather than assumed. The PCBCart pack did **not** contain the 0.125 mm budget. It stated the **0.025 mm accept limit**, which is IPC-6012 class 2’s own minimum and is unaffected by this change. So of the two errors, only the Stäubli one reached PCBCart.

Two entries above are deliberately incomplete. This register records what can be evidenced from the repository. Naming three manufacturers and three dates from

memory would put unverified statements into the one document that is supposed to be checkable — which is the failure mode this whole change exists to correct.

Impact: two fabrication notes, two rows in DSN-EEG-003 §3.2, one new RISK-EEG-011 finding with its analysis, two new reports, one new lookup sheet, and one withdrawn claim. **Nothing here changes the instrument, and no decision that belongs to a person has been taken.**

3. Change procedure from here

1. **Raise.** Anyone may raise a change. It is written as one paragraph: what is wrong, how it was found, and what it stops someone doing.
2. **Classify.** *Blocking* – something cannot be built, tested or used safely. *Major* – a requirement is not met, or a document says two different things. *Minor* – everything else.
3. **Assess.** State the impact on: the board, the firmware, the mechanical parts, the BOM, the test specification, the safety case, and the cost of any units already built.
4. **Change the source, not the output.** If the change touches the carrier, edit `tools/design.py` and run `tools/emit_all.py`. If it touches a printed part, edit `tools/mech_gen.py`. Never edit a generated file.
5. **Verify.** Re-run `tools/emit_all.py` and `tools/simulate_production.py` and attach both reports to the ECO. Two gates apply, and they are not the same gate.

The gate for releasing fabrication data is that the DRC reports **zero violations**, that every net is one connected copper island, and that both inner planes remain continuous under the analogue zone. Rev B met all three on 2 September 2026, and that is recorded in section 2B. **It is not enough, and this paragraph is rewritten rather than left standing.** An external layout engineer read the Rev B board between 3 and 5 September 2026, declined the review and advised a redesign; his seven findings are in ECO-EEG-030 and six of them are rules the programme's own DRC was never given, so a report at zero violations was a report against an incomplete rule set. **Rev B is withdrawn from fabrication.** No board is ordered from it and its data stays in the tree as history.

Nothing in this package is released for fabrication. Rev C is defined by ECO-EEG-030, is **unrouted**, and is released to an external layout contractor under RFQ-EEG-002A as re-scoped by that ECO. The gate for releasing Rev C fabrication data is the three conditions above **measured on the geometry the contractor returns**, under the rule set of ECO-EEG-032 and LAY-EEG-034 rather than the Rev B rule set, **plus** the placement review of RFQ-EEG-002A closed before routing was confirmed. Until a contractor's board has been returned and graded, there is no candidate for the gate at all.

The gate for an ECO inside this release is narrower, because the release is a review package rather than a fabrication package: the change must add no violation, must not increase the count of nets that are not one island, must not put copper in the isolation keep-out on any layer, and every violation it closes must be named in the ECO. Now that the report is at zero, a change that adds one is a regression and is reverted rather than argued. **A change that adds a CHECK is**

not in that class: ECO-EEG-032 adds six geometry checks that Rev B was never measured against, and the counts they raise on the Rev B routing are evidence that the checks bite, not regressions to be reverted. The simulator must stay at zero failures; its open items are counted and named. The DRC item is gone, because the report records no violations. **The six that stand are the static IRAM pool with one byte free, the carried-over v1 HM-01 mesh being two disconnected bodies, the unreviewed routing, E-27 never having been seen to light, the unreconciled board current, and SR-01 being closed in the design and not signed off** – 193 passed, 0 failed, 6 open, which is what the last run of 2 September 2026 printed and what section 1.1 states. E-11's low-pass half and E-27's missing driver were on this list at the previous run and are gone from it because both were closed, not because either was regraded. A change that raises the failure count is a regression. A change that moves the passed count moves it because the check set moved, and the ECO says which checks it added or withdrew.

6. **Record.** Add the ECO to section 2 with the same fields as the entries above and take the next free number in the **one EEG-*nnn* pool** that section 1.3A now rules, which is **ECO-EEG-034**. Never ECO-EEG-016, which is this document, and never ECO-EEG-028 or ECO-EEG-029, which are withdrawn under section 2 and are not reused. Bump the revision of every document the change touches, and update sections 1.1, 1.5 and 2.1.
7. **Release.** A release is the whole package or nothing. Regenerate the checksums in `kicad/gerber/README_layer_map_and_checksums.txt` and the package manifest.

A change that affects the safety case – anything touching the electrode path, the isolation, the battery, the charge interlock or the patient-current budget – additionally requires RISK-EEG-011 to be re-issued and the safety reviewer to be told, whether or not the review has already happened. **ECO-EEG-023 and ECO-EEG-024 are both in that class and both are open**, so the safety reviewer receives them as part of the pack rather than as changes already made.

A change that needs a test step cites a T-number from TST-EEG-004, which owns the step numbers. If the step does not exist, the ECO says so and raises it as an open item; it does not invent a number.

4. What is deliberately not under change control

The experiment design document, the participant information sheet and the pre-registration are the programme's research documents and are controlled elsewhere. They are cited from this package but are not part of it. Where package v2 documents cited them as ETH-EEG-001, DIS-EEG-001 or KPL-EEG-001, those identifiers are withdrawn under section 1.3 and the documents are cited by title.