

FID-10: No Connection to Unit 🖱️

The recovery steps depend on the **module affected**. Here are the details:

🖱️ ABIL (FSP Subunit Lost / No Connection to Unit)

Applicable SW: 25R3, 26R1, 26R2

1. Wait for **automatic recovery resets (3 times)**
 2. If ABIL not recovered after auto recovery:
 - Perform **BBMOD power off/power on** (with 1-hour waiting period)
 - Perform **Web-EM site power reset**
-

🖱️ AEHC (No Connection to Unit)

Applicable SW: 25R3, 26R1, 26R2 | **Waiting Period:** 120 Minutes

1. Collect **Pre and Post Snapshot**
 2. **Engage R&D ASAP** (No recovery before engaging R&D)
 3. Wait up to **2 hours** for self-recovery (No TSH required within waiting period)
 4. Check if RU unit is **reachable/pinging**, then collect RU logs
-

🖱️ AHLOB / AHFII (No Connection to Unit)

Applicable SW: 25R3, 26R1, 26R2 | **Waiting Period:** 45 Minutes

1. Collect **Pre and Post Snapshot**
 2. Check **Rx power at BB** from the unit
 3. Try **SFP procedure** and wait minimum **20 minutes**
 4. The unit should **recover on its own** in most cases
-

🖱️ AHFII, AHLOA, AHLOB, AHFIG (FID-10 at NR End)

- LTE module is **Up and Running**
-  Perform **pssreboot HW from LTE end using SSH**

 AHFII, AHLOA, AHLOB, AHFIG (FID-10 at LTE End)

- NR module is **Up and Running**
-  Perform **Web-EM RMOD reset from NR**

 **NOTE:** During troubleshooting, if FID-10 turns into **FID-1850 / FID-23 / FID-2934 / FID-2935 / FID-2942**, it means connectivity to RU is established. Collect **RU logs and snapshot** at this point for R&D investigation.