

Pratt & Whitney Canada Corp.
1000 Marie-Victorin
Longueuil, Quebec, Canada J4G 1A1
(450) 647-9411



Pratt & Whitney Canada
Une société de United Technologies / A United Technologies Company

DAA2017-448-PW210S-BM0117
CRM: PWC-81790-X7Y4

07 June 2017

Thai Aviation Services Ltd.
601 Moo 1 Tumbon Pakpoon
Nakhon Si Thammarat District
Nakhon Si Thammarat Province, 80000, Thailand

Attention: Daryl Dixon - Maintenance Manager

Subject: Deviation Letter, PW210S S/N BM0117 (TTSN: 873.1 hrs)
Air Inlet Screen rubber gasket crack.

Pratt & Whitney Canada (P&WC) understands that the subject engine was found with a single crack on its air inlet screen rubber gasket during scheduled inspection. Per Engine Maintenance Manual, the part had to be rejected from service.

An engineering evaluation had determined that the engine, in this regard, continues to comply with its certification basis and is in a serviceable condition for continued operation up to TTSN: 973.1 hrs subject to the following maintenance action:

1. Visual inspection of affected area at intervals not to exceed 25 flight hours for evidence of crack growth.
2. If existing crack length propagates to twice the original length recorded at TSN: 873.1 hours, or if additional cracks develop, replace the air inlet screen.

Please retain a copy of this letter in the engine logbook.

Should you require further clarification on this subject, do not hesitate to contact your local Field Service Representative or the undersigned.

Thank you,

PRATT & WHITNEY CANADA Corp

Kenneth.Carroll
Turboshaft Customer Engineer
Email: kenneth.carroll@pwc.ca

Gerry Whitty
Deputy Chief Engineer
Customer Support
DAA #81, DAO-93-Q-01

This Deviation Letter constitutes Transport Canada approved data. P&WC acknowledges the final authority of the local regulatory agency in the application of this data. Applicable engine Airworthiness Limitations and Airworthiness Directives shall take precedence.

Export Control Classification:

This document contains no technical data controlled by the Canadian Export Control List or controlled more restrictively than ECCN 9E991 by the United States Department of Commerce.

CC: daryl_d@tasl.co.th, grant_r@tasl.co.th, Cfirst@pwc.ca, David.Yakin@pwc.ca, COPS and TRAC