

# Safety Alert SA-2026-05

## Unexpected energised parts during inverter replacement

Hannah Weber · 15 June 2026 · SA-2026-05

Safety alert SA-2026-05 – please share at your next toolbox talk and confirm to HSE.

### What happened

During the replacement of central inverter INV-07 at Uckermark Solarpark on 9 June 2026, a technician found the DC input terminals still live after the AC side had been isolated. The string combiner switches had not been opened because the isolation certificate listed only the AC breaker. Nobody was hurt.

### Why it matters

PV arrays produce voltage whenever there is daylight. DC arcs up to 1,500 V do not extinguish by themselves and can cause severe burns.

### What you must do

- List every energy source – AC and DC – on the isolation certificate (form HSE-FRM-0103).
- Open and lock the string combiner switches before touching DC terminals.
- Test for absence of voltage on both sides, every time.
- Wear arc-rated PPE when testing.

Issued by Hannah Weber, HSE Manager, on 2026-06-15.