SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 1 /28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Job No	Description	Line Amount
1100	BERTH PREPARATION, DOCKING AND UNDOCKING:-	24,000.00
	Berth prepared, vessel docked and undocked. QRs 16,000.00	
	Vessel undocked 2nd time. QRs 8,000.00	
	As per our quotation EM 15702 Rev , item 1.01.1	
1101	DOCK HIRE, WHARFAGE CHARGES AND SERVICES:-	154,530.00
	Dock hired /alongside for during repairs from 21.03.2021 to 10.05.2021.	
	Berthing crews provided. Fire line provided and connection/disconnection x 1 time. Fire and safety watch provided Galley garbage skip provided. Electrical shore power line 1 no including connection and disconnection. 1 no. sea water cooling line and 1 no. overboard line including connection and disconnection	
	QRs 3030 per day x 51 days = QRs 154,530.00	
	As per our quotation EM 15702 Rev , item 1.01.2	
1150	WHARFAGE AND SERVICE CHARGES:-	39,092.00
	From 01.06.2021 to 19.06.2021	
	Wharfage charges- QRs 1,238 per day x 19 days = QRs 23,522.00	

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

: 4771687 Fax



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 2 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No	Description	Line Amount
	Fire and safety watch - QRs 330 per day x 19 days = QRs 6,270.00 Fire line 1 no provided + connection/disconnection = QRs 200 per day x 19 days + ORs 275 = ORs 4075.00	

Galley garbage skip provided x 19 days = QRs 275 x 19 days = QRs

5,225.00

1151 COMPRESSED AIR SUPPLY:-

N.A

1152 780.00 CRANE ASSISTANCE:-

Dock crane 2 hours dated 31.03.2021 for shifting of food - QRs

620.00

Rigger: 2 hours - QRs 160.00

GAS FREE CERTIFICATE:-1153

N.A

1154 HIRE OF EQUIPMENTS:- 6,200.00

HP Jet washing machine 1 no and Wildon pump no provided to client for 20 days- QRs 250 per day x 20 days = 5000.00Provided fresh water line for 20 days - QRs 60 per day x 20 days = QRs 1,200.00

Consider minimum 1 ton each day x 20 days.

1155 BALLAST TANKS:-

Not done.

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 3 /28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Job No	Description	Line Amount
1156	SEWAGE:-	
	Not done.	
1157	DISPOSAL OF BILGE OILY WATER:-	15,400.00
	Collected and disposed bilge oily water - 26.98 m3	,
	QRs 2200 per time (min 4 ton per time) x 7 times = QRs $15,400.00$	
1158	STAGING:-	
	N.A	
1159	EMERGENCY GENERATOR REPLACEMENT OF EXHAUST INSULATION &CLADING:-	12,285.56
	Scaffolding an approx. 1500mm height x 2000mm long arranged for access and later removed on completion of insulation works. Insulation and clading work carried out by specialist subcontractor.	
	Subcontractor charges = 9508.8 Qrs + 20% yard markup = QRs 11,410.56 Scaffolding = 875 Qrs (amount reduced)	
	Total = QRs 12,285.56	
1160	TANK SOUNDING SYSTEM:-	
	N.A	

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 4 /28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021 W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Nam	me/Description: M.V. "HALUL-83"	
Job No	Description	Line Amount
1161	ER BLOWER SPACE INSULATION:-	8,906.00
	Insulation/cladding to be renewed in ER blower space by yard arranged subcontractor.	
	As per our quotation EM 15702 C, item no 2	
1162	EMEG GENERATOR EXHAUST PIPE LINE:-	
	Incl in Job no 1159	
1163	N.A	
1164	N.A	
1200	TOP SIDE AREA TREATMENT AND PAINTING:-	24,643.00
	Top side area an approx of 852 square metres treated and painted as per paint manufacturer's representative's recommendation and your representative's instruction.	
	H.P. jet washing using fresh water- QRs 8,840.00 Spot Grit sweeping to SA 1, 5% area - QRs 2,150.00 Spot GritBlasting to SA 2.5, 5% area - QRs 2,795.00 Hosing down with fresh water - QRs 1,768.00 Applied one touch coat primer (Hempadur 17634 beige) - QRs 3094.00	
	Applied one full top coat (Hempathane 55210 orange) - QRs 3,536.00	
	Protection covering all tyre fenders and accommodation with blue canvas and tape - QRs 1,500.00	
	Disposal of used grit/garnet/waste water which mixed with	
	ferros, paint, oil and chemical, collection, transportation and safe disposal as per Qatar safety envionment regulation in	

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687 Fax



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 5 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

> DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description Line Amount

Mesaieed - 4 ton - QRs 240 x 4 = QRs 960.00 Notes: All paint composition, thinners and tool cleaners supplied by client.

Based on our quotation EM 15702 Revised, item 4.01.1

1201 UNDER WATER AREA TREATMENT AND PAINTING:- 189,566.00

Underwater area an approx. 2078 square meters treated and painted as per paint manufacturer's representative's

recommendation and your representative's instruction. Hand scraped to remove marine growth. QRs 8,312.00

H.P. jet washing using fresh water. QRs 13,650.00 Spot Grit sweeping to SA 1, 50% area . QRs 51,950.00 Spot GritBlasting to SA 2.5. 50% area. QRs 67,535.00

Hosing down with fresh water. QRs 4,156.00

Applied one full coat primer (Hempadur 17634 red and beige) QRs 7,273.00

Applied one full coat sealer (Hempadur 47182)-QRs 8,312.00 Applied two coats antifouling on vertical side (Hempel oceanic

73652 Red and brown - QRs 6,832.00

Applied one coats antifouling on flat bottom (Hempel oceanic 73652 Red and brown) - QRs 4,896.00

Protection covering all zinc andoes with masking tape.

Protection covering echo sounder and speed log. Protection covering with blue canvas on accommodation.

QRs 2,250.00

Disposal of used grit/garnet/waste water which mixed with ferros, paint, oil and chemical, collection, transportation and safe disposal as per Qatar safety envionment regulation in Mesaieed - 60 Ton

QRs 14,400.00

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 6 /28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

vessei Nai	me/Description: M.V. "HALUL-83"	
Job No	Description	Line Amount
	Notes:All paint composition, thinners and tool cleaners supplied by client.	
1202	SHIP'S MARKS:-	3,800.00
	Painting existing name, home port, draught marks and load lines marks with two coats gloss.	
	As per our quotation EM 15702 Revised, item 4.05	
1350	PORT AND STBD. CHAINS:-	7,500.00
	Lowering anchors and anchor chains to the dock bottom using ship's windlass, ranging out for examination and later restoring. Both Port & Stbd anchors & chains to lowered & be run out until bitter end, chains flaked out on dock bottom and later restored. Port and stbd anchor chains HP washed. Port and stbd chains shots marked. As per our quotation EM 5702 A, 16.1	
1400	SEA CHESTS AND GRIDS:-	9,350.00
	8 in nos. seachests grating removed. Sea chests and grids , HP washed, cleaned & painted as per flatbottom area treatment and painting specification. Later grids refitted on completion. QRs 4,400.00	
	Erected and removed staging. QRs 3,200.00	
	5 nos grit blasted. QRs 1,750.00	

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 7 /28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

Based our quotation EM 15702 Revised item 2.03

1401 BT 1 REPLACEMENT OF INPUT DRIVE SEALS:-

6,760.00

Motor electrical connections are disconnected and removed. Motor foundation bolts and coupling bolts are removed. Motor lifted and secured by chain blocks at one side. Driven shaft coupling was removed by hydraulic jacks. Top seal locking plate removed. Seal stuffing box/seal collar and seals are removed. Client supplied new seal collar is not matching with old/existing seal collar. Height of new seal collar was 2mm more than the old collar. Yard machined the new seal collar to match with the old one.

Seal area thoroughly cleaned. Seal collar and input drive seals are installed in position. Inspected and witnessed by client. Driven shaft coupling installed on position by heating. Inspected by Client. Motor foundation and motor couplings are cleaned. Motor shifted back to the location and installed on position. Coupling bolts installed back and tightened. Electric connections are reinstalled back. Inspected and witnessed by client

Based on our quotation EM 15702 revised, item 9.14

1402 BT 2 REPLACEMENT OF INPUT DRIVE SEALS:-

6,760.00

Motor electrical connections are disconnected and removed. Motor foundation bolts and coupling bolts are removed. Motor lifted and secured by chain blocks at one side. Driven shaft coupling was removed by hydraulic jacks. Top seal locking plate removed. Seal stuffing box/seal collar and seals are removed. Client supplied new seal collar is not matching with old/existing seal collar. Height of new seal collar was 2mm more than the old collar. Yard machined the new seal collar to match with the old one.

SHIP REPAIR & FABRICATION

Telephones

Office : 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 8 /28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021 W/O Number : 21-011090

W/O Ref : MDO 21067 EXPENSE A/C : 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

Seal area thoroughly cleaned. Seal collar and input drive seals are installed in position. Inspected and witnessed by client. Driven shaft coupling installed on position by heating. Inspected by Client. Motor foundation and motor couplings are cleaned. Motor shifted back to the location and installed on position. Coupling bolts installed back and tightened. Electric connections are reinstalled back. Inspected and witnessed by client.

Based on our quotation EM 15702 revised, item 9.14

1403 GATE VALVES AND BUTTERFLY VALVE RENEW:-

3,370.00

Engine room Over board Globe valve DN40-1no, Gate valve 5K 80-2nos and Gate valve 5K 65-3nos are removed from location. Found in bad condition. As per client instruction owner supplied same size new valves-6nos fitted back on position with yard supplied new gaskets and bolts nuts.

5nos of DN120 Gate valves are removed from location brought to workshop dismantled and cleaning done. Valve condition is found bad. As per Client instruction all the 5nos of Gate valves DN120 replaced by client supplied new DN120 Butterfly valves. Due to the length variation Client modified spool pieces are installed with yard supplied new bolts, nuts and new gaskets. Witnessed by client.

Based on our quotation EM 15702 Rev , item 17.01

1404 REPLACING OF VALVES:-

6,132.00

Following valves removed and client supplied new valves fitted in position.

Auxiliary engine sea water inlet 5K 80A Gate valve-2no removed

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 9 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

from location and brought to workshop. Valve condition was bad. Client rejected. Yard supplied new 5K 80 gate valve -2nos are shifted to vessel and fitted back on position with yard supplied new gaskets and bolt nuts. Witnessed by Client.

Z-Peller sea water gate valve 5K 65A -3nos removed from location and brought to workshop. Valves are in bad condition, Client rejected the valves. Yard supplied new 5K 65A gate valve shifted to vessel and fitted back on position with yard supplied new bolts and nuts. Witnessed by Client.

Refer sea water glove valve DN40 -1no removed from location and brought to workshop. Dismantled and chemical cleaning and buffing done. Valves disc and valves seat lapped and cleaned. After Client inspection Valve assembled with yard supplied new gland packing, new gaskets. Gravity test done. No leaks found. Witnessed by client and yard QC. Valve shifted on-board and fitted back on position. Witnessed by client.

As per our quotation EM 15702 A, item 16.04

1405 MGPS SYSTEM MODIFICATION AND INSTALLATION:-

9,710.00

8 Nos. MGPS anodes removed.

2 Nos MGPS anodes renewed. (Client supplied)

6 nos blanked.

Yard fabricated 2 nos flanges and fitted with yard supplied new gaskets, bolts & nut.

1 No. 5" dia. x 1500mm long pipe for fresh water transfer line removed for access and later refitted. Sea chest vent line removed for access and later refitted on completion. 1 No. Bilge suction strainer and sea chest vent pipe removed for

SHIP REPAIR & FABRICATION

Telephones

Office : 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 10 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

access and later refitted.

As per our quotation EM 15702 A, item 21.07

1800 LIFE RAFT SECURING FRAME FABRICATION & RENEWAL:-

2,980.00

6 pcs Liferafts removed from supports and later positioned after completion of retainer repair works. Retaining frame to be removed, each is held in place by loff M12 bolt fitted to each leg [2 in total] 4 off new frames to fabricated using following materials.Material: 32mm OD Carbon Steel Schd 40, Height Overall: 73cm, Width: 54cm outside to Outside2off eyes of 12mm round & 45mm height to be fitted at 20cm from centre lineNew fabricated frames to be refitted to main frames & new bolts used on re-assembly.

As per our quotation EM 15702 rev , item 6.01

1801 FLOOR PLATE MODIFICATION:-

4,464.00

Floor plates are retained by M6 counter sunk screws each plate containing valve assessPlate size $-180\,\mathrm{mm}$ OD x $130\,\mathrm{mm}$ ID x $4\,\mathrm{mm}$ - 18 nos .Fitted and welded.M6 X $20\,\mathrm{mm}$ long stainless steel counter sunk bolt - 30 nos.

1802 MOORING ROPE FRAME:-

1,780.00

2 Nos. mooring rope frame to be fabricated and welded on port and stbd. crash barrier to size each 2"dia., sch 40 ms pipe \times 2800mm long provided with 1 NO. cold bend.

As per our quotation EM 15702 rev , item 21.02 rev

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 11 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

VC55CI Nan	ne/ bescription. M.V. MADON 03	
Job No	Description	Line Amount
1803	BT ROOM GRATING:-	2,150.00
	1 No. Frp grating size $600\mathrm{mm}$ x 600 provided with $40\mathrm{mm}$ X $40\mathrm{mm}$ ms angle bar frame and 2 Set hinges to be fabricated and installed to open inboard position at BT room T'ween deck emergency escape.	
	As per our quotation EM 15702 rev, item 21.03	
1804	RAISED PLATFORM FOR VALVE ACCESS:-	
	Not done.	
1805	FABRICATION OF ANGLE BARS TO FIT AT FRC DECK:-	2,000.00
	2 Nos. 'L shape angle fabricated & fitted to FRC deck to size size each 200 mm x 90 mm x 12 mm thickness ms channel x 1300mm long provided with 2 nos bends Brackets to be fabricated of MS Channel 200 mm x 90 mm x 12 mm -2 nos Triangular brackets size each 250mm x 250mm x 10mm thickness - 4 Nos.	
	As per our quotation EM 15702 A, item 21.05	
1806	HATCH COVER REMOVE/REFIT:-	1,100.00
	Eye pad 4 nos. fitted and welded.	
1807	MGPS ANODE:-	1,110.00
	Flange Slot cutting on the 2 no. flange to fit on existing flange as requested by client.= 16 slot Sleeve type New MS	

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 12 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

vessel Nam	e/Description: M.V. "HALUL-83"	
Job No	Description	Line Amount
	flange of size14mm thick X 220 mm OD x 95mm ID, PCD 180 mm fabricate and supply.= 02 nos.	
	As per our quotation EM 15702 G, item 3	
1808	ZINC ANODE:-	1,200.00
	Installation of zinc anodes -6 nos.	
	As per your email,	
2400	FRESH WATER TANK CLEANING:-	
	Not done.	
2401	MUD TANK CLEANING:-	
	Not done.	
2402	BULK TANK:-	
	Not done.	
2403	DIRTY OIL TANK CLEANING:-	4,305.00
	Gas free of tank 1 no.Pump out remaining fuel and dispose if any.Cleaning bottom and sides by means of wiping with cotton rags.	
2404	BASE OIL TANK (308 M2):-	52,729.00

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 13 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

Remove and refit manhole cover.

Ventilation using electrical blower.

Erected full scaffolding

H.P. jet washing using fresh water.

Pump out mop dry.

Full Grit blasting to SA 2.5

Removing dirts and debris - 1 m3

vacuum cleaning and protection covering

Hand cleaning full internal area .

Applied one full coat (Hempadur 85671 Grey/ Off white)

Applied one full stripe coat

Applied second full coat (Hempadur 85671 Grey/ Off white) Note

: All paints supplied by Client

As per quotation EM 15702 Revised, item no 20.11

2405 BILGE OIL TANK CLEANING:-

4,305.00

Gas free of tank 1 no.Pump out remaining fuel and dispose if any.Cleaning bottom and sides by means of wiping with cotton

rags.

As per our quotation EM 15702 H, item no 2

2500 RESTORING OF STORES CRANE HYDRAULIC TANK:-

4,710.00

 $2 \times \text{tanks}$ covers removed in situ for access securing bolt threads drilled taped and helicoil fitted back as per client instruction 10MM helicoils 12 nos ,8MM helicoil 16 nos

Note:M10X20 Long ms bolt 12 nos with10MM flat washer 12 nos M8X20 Long ms bolt 16 nos with 16 nos 8MM Flat washer handed

over to client

Erected staging before start the job and removed after

completion of the job. (approx size 5 meter)

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code: QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 14 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

vessel Name/Description: M.V. "HALUL-83"			
Job No	Description	Line Amount	
	As per our quotation EM 15702 Rev, 3.02		
2501	FUEL TANK SOUNDING CAP:-	3,760.00	
	4 Port Fuel oil tank's old sounding cap removed by drilling taping and 1 No. new cap manufactured by yard and fitted back in original position size $58\mathrm{mm}$ Od x $30\mathrm{mm}$ long provided with $6\mathrm{mm}$ x $30\mathrm{mm}$ long key slot and M44 thread. Using brass material.		
	7 nos sounding cap New manufactured (58MM Od 30MM long material brass) fitted back original position witnessed by ship crew (S4P4,S5P5,S3P3,S2,P2)		
	Based on our quotation EM 15702 Rev, 17.06.1		
2502	AHU MOTOR ADDITIONAL WORK:-	1,400.00	
	AHU motor NDE cover bearing worn out bearing area premachined, sleeve manufactured, inserted with interference fit, secured with 02 nos M5 grub screw and final machined according bearing OD 120.00.		
	As per quotation EM 5702 B, item 1		
2503	FABRICATION OF PLUGS FOR MUD TANK MANHOLES:-	720.00	
	Carried out freeing of old plugs.		
2504	RESLEEVING OF END COVER - STBD SHAFT GENERATOR:-	3,450.00	
	Resleeving of stbd DG end cover . OD 240 CI material used.		
	As per Qtn EM 15702 I		

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code: QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 15 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Job No	Description	Line Amount
2800	TYRE FENDER RENEWAL:-	3,510.00
	13 nos pad eyes cutting and grinding. 02 nos tyre removed and fitted back. 01 Tyre position on ship. Provided crane support	
5050	MAIN ENGINE CHARGE AIR COOLERS:-	12,400.00
	Both port and stbd coolers removed from vessel, brought to workshop, mechanically and chemically cleaned, pressure tested and return to vessel and fitted back in position.	
	As per our quotation EM 15702 F, item 1.3	
5051	PORT AND STBD. MAIN ENGINE TURBOCHARGERS:-	940.00
	Provided riggers and dock crane assistance for the removal and refitting of turbocharger.	
	Dock crane: QRs 310 per hour \times 2 hours = QRs 620.00 Riggers : QRs 80 per hour \times 4 hours = QRs 320.00	
5052	MAIN ENGINE PLATE COOLERS:-	
	Not done.	
5053	N.A	
5600	MAIN ENGINE FRESH WATER COOLING PUMPS:-	940.00
	Both Port & Starboard engine driven fresh water cooling pumps	

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 16 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description Line Amount removed from engines & sent to workshop for overhaul.

Tomovou IIom onginos a sono co moinonop Ioi ovoinuai

Based our quotation EM 15702 rev, item no 10.15

5601 MAIN ENGINE SEA WATER COOLING PUMPS:-

940.00

Both Port & Starboard engine driven sea water cooling pumps removed from engines & sent to workshop for overhaul.

Based on our quotation EM 15702 rev, item no 10.15

5602 1 & 2 BOW THRUSTER L.O. COOLERS:-

5,800.00

Bow thruster Lube Oil coolers (Port and Stbd)-2nos removed from location by removing inlet and outlet pipes and foundation bolts. Coolers lifted and shifted to yard workshop. Coolers end covers removed and chemical cleaning and buffing done. Cover plugs -4nos found damaged. Yard fabricated -4nos of end cover plugs, Material Brass. Tube are cleaned by steel rods and chemicals. After washing cleaning inspected by chief engineer.

End covers are assembled back with yard supplied new O-rings. Pressure test 4Bar was carried out. No leaks found. Witnessed by Yard QC and Client. After client inspection coolers are shifted to vessel and fitted back on position with yard supplied new gaskets. Inlet and outlet pipe line are fitted back with yard supplied new gaskets. Inspected and witnessed by chief engineer

As per our quotation EM 15702 rev, item no 12.03

5603 Z-PELLER_PUMPS:-

6,375.00

Port and stbd sea water pump disconnected from inlet and outlet

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 17 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

pipes.

Brought to workshop and dismantled.

Casing 2 nos , mechanical seals and bearing renewed.(client

supplied.)

Pumps 1 no assembled back with old impeller and 1 no without

impeller.

Both pumps shifted to vessel and hand over to client.

Based on our quotation EM 15702 rev, item no 14.28

5604 PORT & STARBOARD FIFI GEARBOX L.O. COOLERS:-

3,500.00

Coolers removed and brought to workshop, cleaned chemically and mechanically, pressure tested and fitted back in position. Pressure tested. Assembled with yard supplied O rings and gaskets.

Cleared the blocks using steel rods.

As per our Qtn EM 15702 A, item 12.07

5605 P&S Z-PELLER SW PUMP OVERHAUL:-

Incl n job no 5603

5606 D/G COOLER CLEANING AND TESTING:-

2,550.00

Received 2 nos DG cooler at workshop, dismantled, chemically and mechanically cleaned, pressure tested and re assembled provided shell housing.

18 tubes in one cooler and 40 tubes in another cleaned with steel rods and hand drill machine.

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code: QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 18 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021

W/O Number : 21-011090 W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Nam	e/Description: M.V. "HALUL-83"	
Job No	Description	Line Amount
	Pressure tested at 2 bar and cooler hand over to ship staff.	
5607	ALIGNMENT OF AC COMPRESSOR:-	1,800.00
	Stbd side AC compressor no 2 foundation adjusted with respect to motor by added shims and fixed. Motor foundation bolts loosened, and motor adjusted by using old shims. Lased alignment tool fixed. Alignment done. Inspected by client. Motor foundation bolts and coupling bolts are tightened. Alignment report submitted.	
5800	WINDLASS BRAKE LINING:-	
	Not done.	
5850	STORES CRANE REFITTING OF BOOM EXTENSION RAM:- Job cancelled.	
6000	FABRICATION OF SEAWATER PIPES:-	
	Job cancelled.	
6001	REMOVAL, INSPECTION & CLEANING OF BHS LOADING & DISCHARGE LINES:- Job cancelled.	
6002	MODIFICATION IN BULK MANIFOLD:-	11,200.00
	2 Nos. Port. & Stbd. Bulk pipe lines extended by approx. 750mm	

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 19 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

long, Sch. 80, 5" dia.

Material: Pipe 5" dia. Sch. 80 Seamless Carbon Steel Pipe and

Camlock coupling removed & thread cropped,

Cropped ends & 1 x end of extension pieces prepared for full penetration welds other end of extension piece threaded for to suit camlock coupling. (One new camlock coupling supplied by owner. Other existing camlock coupling cleaned and refitted.) Extension pieces prepared & applied one coat shop primer.M.P.I

done for all pipe weld joints by Q/A Q/C.Female camlock

couplings refitted to extension pieces.

Pipe lines shifted to main deck.

5" dia. temperary blind flange fitted both side for hydro testing.20mm dia. male brass plug made in machine shop and

dfitted with the pipeline. - 02 nos.

Testing pressure - 8 bar.

Testing process inspected by Q/C and certificate issued. After testing refitted the pipe lines it's own position.

As per our quotation EM 15702 Revised, item no 17.03

6003 SEAWATER CONNECTION PIPES:-

3,105.00

Fabricated and fitted 03 nos. blind flange for Prov ref compressor condenser line, ECR air conditioner condenser line and accommodation air compressor condenser lines.Size - O.D. 200mm. P.C.D. 165mm. Hole - 08 nos. Hole dia. 19 mm. - 03 nos.Size: - M.S. Blind Flange,O.D. 115mm, P.C.D. 95mm. Hole - 04 nos. Hole dia - 15mm. - 01 nos.

As per our quotation EM 15702 Revised, item 21.07

6004 SEAWATER CONNECTION PIPES:-

Not done.

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 20 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

6005 INSTALLTION OF CUPRON SYSTEM NOZZLE:-

8,740.00

Port and stbd. cupron system nozzle installed on top of sea chest plate in void space tank.

Details - Port. Side.

1 ½" Dia. Hole penetration provided longitudinal Bulkhead. - 01 nos.1 ½" Dia. Hole penetration provided on sea chest top. - 01 nos. Owner supplied body threaded flange installed on sea chest top and bottom area.1 ½" dia. M.S. pipe, sch 80.,100mm long provided with one 90 deg. -Elbow and 02 nos. flanges.- 01 nos.1 $\,$ ⅓" dia. M.S. pipe, sch 80.,200mm long provided with both side flange -01 nos.01 nos. M.S. pad plate welded on Bhd. Size -O.D.130mm, X .I.D.50mm X 8 mm thick. - 01 nos.After fabrication all spools fixed on sea chest top with owner supplied valve in void tank area. Stainless steel Bot & Nut. M 16 X 50mm long. - 08 nos.G.I. Bolt and nut. M 16 X 60mm long - 08 nos.Details-Stbd. Side.1 ½" Dia. Hole penetration provided longitudinal Bulkhead. - 01 nos.1 ½" Dia. Hole penetration provided on sea chest top. - 01 nos.Owner supplied body threaded flange installed on sea chest top and bottom area.1 ½" dia. M.S. pipe, sch 80.,100mm long provided with one 90 deg. -Elbow and 02 nos. flanges. - 01 nos.1 ½" dia. M.S. pipe, sch 80.,200mm long provided with both side flange -01 nos.01 nos. M.S. pad plate welded on Bhd. Size - O.D.130mm, X .I.D.50mm X 8 mm thick.- 01 nos.After fabrication all spools fixed on sea chest top with owner supplied valve in void tank area. Stainless steel Bot & Nut. M 16 X 50mm long.- 08 nos.G.I. Bolt and nut. M 16 X 60mm long - 08 nos.

MPI Testing process done inspected by Q/C and certificate issued. After testing refitted the pipe lines it's own position.

As per our quotation EM 15 702 D, item no 1

6006 FABRICATION AND SUPPLY OF SEA CHEST FILTERS:-

1,840.00

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 21 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

Main sea chest strainer filter new fabricate from 2mm ss perforated sheet filter size is OD - 550 mm , Hight - 750 mm (Perforated sheet supplied by client) =02 no. Dia 550 mm X 2 mm thickness SS plate for base plate = 02 nos. (Yard supply material)SS round bar dia 12 mm X 550 mm long for filter lifting = 04 nos. Fabricate and supply 2 nos

As per our quotation EM 15702 G, item no 1

7000 PORT AND STBD. ENGINE ROOM FANS:-

15,520.00

Job has been identified with ship ETO and corresponding breakers are isolated by ship ETO. Unbolt blower Hood hatch cover and shift aside. Removed the foundation bolts of blower trunk, protection grid, disconnect the power supply cable. Access cutting done for take out the blower assembly. shifted the Blower assembly away from the hood and brought to workshop. Checked motor insulation tested. Withdraw the blower fan and cleaned trunk assembly with scraper cleaner. Dismantled blower motor to start overhauling. Clean the motors using electrical cleaning solvent, cured inside the temperature control oven and re-varnished the motor windings. All mechanical parts are cleaned by chemical solvent. both motor end cover bearing housing Areas are checked, found OK. Required QAQC report prepared sent to QC for preparing final report for client approval. Re-assembled motor using yard supplied bearings. MEGGER testing of motor carried out found satisfactory. Reassembled blower, bench tested and shifted back to vessel. Refit the blower and protection grid. Gasket 3mm thickness renewed. base bolts, nuts washers are renewed by Yard supplied. Reconnected the power cables as per the marking. Satisfactory running test carried out presence of ETO. found satisfactory. Access angles welding completed. hatch cover Closed properly. Hatch cover gasket also renewed.

As per our quotation EM 15702 Rev, 5.09

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 22 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021 W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

7001 MAIN AC AHU MOTOR TO OVERHAUL (18.5kW 415V/3PH/ 50Hz) - 1 NO.:-

4,625.00

Job identified with ETO and LOTO applied. Electrical connection marked disconnected. motors transferred to electrical workshop. Checked motors winding insulation value noted. Dismantled motor end covers removed existing bearing from rotor shaft. Draw out rotor unit from stator body. Clean the motors winding, other parts by using electrical cleaning solvent, cured inside the temperature control oven. Checked insulation value of stator coil. Found good. Re-varnished the motor windings. Checked bearing clearance of end covers and found all end covers are good. Reading has been submitted to QC. After ETO inspection Re-assembled Motor using Ship Supplied bearings. workshop running test carried out with presence of ship ETO Shifted back to on-board and installed back to original position. Alignment done. Reconnected electrical cable as per marking on-board running test carried out. found satisfactory.

As per our quotation EM 15702 Rev, 5.24

7002 GALLEY EXTRACTION FAN MOTOR (0.55kW 415V/3PH/ 50Hz) - 1 NO:-

1,563.00

Job identified with ETO and LOTO applied. Disconnected the electrical cables. lifted shifted to workshop along with fan trunk. Visual inspection done. Value of motor winding checked value recorded. Dismantled motors end covers removed existing bearing from rotor shaft. Draw out rotor unit from stator body. Cleaned the motors winding by electro solvent, other parts also cleaned using electrical cleaning solvent. Motor kept inside the Oven. Re-varnished the motor windings. Checked insulation value of motor stator winding. Found out value was more than the tolerance insulation value recorded. Checked bearing clearance of each end covers. Each end covers knurling done. Report prepared submitted QAQC to prepare final report for

SHIP REPAIR & FABRICATION

Telephones

Office : 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 23 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

client. After ETO inspection Re-assembled motor using ship supplied bearings 6202 RS - 02 PC's. Fan fixed as per marking. Motor tested in workshop. Shifted back to On-board installed. Prepared new gasket renewed bolts. All power cables reconnected as per original marking. on-board test carried out with presence of ETO. found satisfactory.

As per our quotation EM 15702 Rev, 5.25

7003 AHU FAN BEARING REPLACEMENT (ALLOW 1 AHU):-

1,650.00

Job identified with help of ship ETO. Isolated AHU fan motor breaker by ETO. V-belt has been marked removed. AHU Blower Motor Fan existing bearing removed on both side of the shaft. Properly cleaned bearing seating area on the shaft. installed ship supplied bearing set on both sides. Re-installed V-belt checked belt alignment with respect to motor pulley. Run test carried out with presence of ETO. Found satisfactory.

NOTE: Bearings supplied by the owner.

As per our quotation EM 15702 rev, item no 12.08

7004 MAIN AND EMERGENCY SWITCH BOARD:-

Job cancelled.

7005 Z-PELLER P & S HYDRAULIC MOTORS TO OVERHAUL (EACH 45KW X 2

11,800.00

NOS.):-

Power: 45kW 415V/3PH/ 50HzRPM:

Motors megger tested before removal & after reassembly tests to

witnessed by vessels ETOElectrical cabling disconnected,

SHIP REPAIR & FABRICATION

Telephones

Office : 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 24 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE : 17/05/2021 W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

brought to work shop, dismantled, overhauled, Motors is retained in position by 4off M16 bolts eachMotor is transported to workshop for overhaulMotor is dismantled, cleaned & presented to Vessel ETO for inspectionRe-insulation of motor. Client supplied bearings to be fitted. Motor to be reassembled after completion of ETO's inspection.Returned to vessel and refitted.2 x copies of motor overhaul to be provided 1 x copy to C/E 1 x copy to Vessel Superintendent.

As per our quotation EM 15702 A, item no 5.08

7006 MAIN AC COMPRESSOR NO.2:-

Job cancelled.

7007 PORT & STBD SHAFT GENERATOR:-

58,610.00

(Maker : Leroy SomerWeight 3300 kg, 1250 Kva , Rating: 1000 KW, Qty : 2 nos)

Port side shaft generator:-

Port shaft alternator power cables, control cables and AVR disconnected from alternator terminal box. Shaft Coupling marked disconnected and shifted aside. Alternator drive coupling with drawn from Gear box. Alternator lifted from position and shifted aside. After that megger and airgap checked in front of ETO. Alternator end covers marked dismantled. Alternator existing drive end and non-drive end bearings removed. All electrical mechanical parts cleaned using electrical cleaning solvent (using Eletrokleen-D4). End covers bearing clearance calibrated and found OK. Alternator winding heat up heating lamp. Checked value of winding insulation reading noted. After ETO inspection re-assembled the alternator by using owner supplied new bearings. O ring renewed.

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 25 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number: 21-011090 W/O Ref: MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

Alternator boxed up and coupling fitted back. Foundation area cleaning and buffing done. Alternator shifted back to position, aligned with gear box. Laser alignment carried out with gear box and alternator. Report submitted to client. After alignment chock fasting done. Chock fsat supplied by Yard. Witnessed by client. After 22 hours foundation tightened and all accessories refitted. Taken airgap between stator and rotor. Reading noted and report submitted to QAQC, and Alignment report submitted to QAQC by mechanical team. Chock fast done. Power cables, control cables and monitoring cables AVR re-connected. Close all terminal covers. found satisfactory.

Stbd side shaft generator:-

Stbd shaft alternator power cables, control cables and AVR disconnected from alternator terminal box. Shaft Coupling marked disconnected and shifted aside. Alternator drive coupling with drawn from Gear box. Alternator lifted from position and shifted aside. After that megger and airgap checked in front of ETO. Alternator end covers marked dismantled. Alternator existing drive end and non-drive end bearings removed. All electrical mechanical parts cleaned using electrical cleaning solvent (using Eletrokleen-D4). End covers bearing clearance calibrated and found OK. Alternator winding heat up heating lamp. Found diode stud burned. Renewed new one with the help of machine shop. Checked value of winding insulation reading noted. After ETO inspection re-assembled the alternator by using owner supplied new bearings. O ring renewed. Alternator boxed up and coupling fitted back. Foundation area cleaning and buffing done. Alternator shifted back to position, aligned with gear box. Laser alignment carried out with gear box and alternator. Report submitted to client. After alignment chock fasting done. Chock fsat supplied by Yard. Witnessed by client. After 22 hours foundation tightened and all accessories refitted. airgap between stator and rotor. Reading noted and report

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH

Cable : "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 26 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

submitted to QAQC, and Alignment report submitted to QAQC by mechanical team. Chock fast done. Power cables, control cables and monitoring AVR re-connected. Close all terminal covers. found satisfactory.

NOTE: Bearings supplied the owner.

7500 SUPPLY OF MATERIAL:-

5,194.00

Following matrerial supplied against signed delivery note:-

4" flange 165 PCD 8 HOLE 12 pcs

4" flange 200 PCD 8 HOLE 12 pcs

welding rod 2.5 mm 3 pack

welding rod 3.2 mm 3 pack

cutting nozel wiscol 16 2 pcs

Cutting wheel 1 mm 50 pcs

Cutting wheel 3 mm 50 pc

Grinding wheel 4 1/2" - 50 pcs

MS sockket 1/2" 05 nos

MS plug 1/2" 05 nos

MS SOCKET 1/4" 05 NOS

GI BOLT/NUT 16X50 -60 NOS

GI BOLT/NUT 16X 100 - 60 NOS

2 inch SS ball valve 12 pcs

2 inch socket 4 pc

2" Nipples 12pcs

8000 PORT & STARBOARD AZI BLADES CLEAN & POLISH:-

6,750.00

PORT & STBD side propellers each 2.8 meter, 4 blade of fixed pitch type fitted in Kort Nozzle cleaned and polished with grade 36 sanding disc at site.erected staging before start the

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 27 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

job and removed after completion of the job.

As per our quotation EM 15702 Rev, 9.02

8001 BOW THRUSTER NO:1 FORWARD CLEAN & POLISH:-

4,900.00

FWD Bow thruster No.1 removed grating, propeller size 1750mm in diameter 04 blades cleaned and polished with grade 36 sanding disc at site after completion refit the grating.erected staging before start the job and removed after completion of the job.

As per our quotation EM 15702 Rev, 9.03

8002 THRUSTER 1 AFT CLEAN & POLISH:-

4,900.00

AFT Bow thruster No.1 removed grating, propeller size 1750mm in diameter 04 blades cleaned and polished with grade 36 sanding disc at site after completion refit the grating.erected staging before start the job and removed after completion of the job.

As per our quotation EM 15702 Rev, 9.04

SHIP REPAIR & FABRICATION

<u>Telephones</u>

Office: 4771690 / 4771695

Fax : 4771687



Telex : 4206 DH

Cable: "NAVIGATION" Doha Bank A/c: QNB Main Branch P.O.Box 1000, Doha - Qatar

Swift Code : QNBAQAQA

QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

DRAFT INVOICE

Page: 28 / 28

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard

WS

PO Box 153, Doha - Qatar

INVOICE NO : SFWK-DMY-008063

DATE: 17/05/2021

W/O Number : 21-011090

W/O Ref : MDO 21067

EXPENSE A/C: 85.901.1434006

Vessel Name/Description: M.V. "HALUL-83"

Job No Description

Line Amount

Invoice Amount --> 800,099.56

(QAR - Eight Hundred Thousand Ninety-Nine And 56/100 Only)