

IM-500 — Error Code Addendum (New Codes, Rev 2.5)

Supplement to the IM-500 Error Code Reference Manual. Adds newly introduced diagnostic codes.

Code	Meaning	Likely Cause	Recommended Action	Severity
E-620	Servo drive overheat	Cooling fan failure on servo drive, ambient temperature too high	Stop machine, replace servo drive cooling fan, clean air vents, verify panel AC	High
E-621	Servo position error	Encoder feedback fault; loose encoder cable, inspect motor coupling	Check encoder cable, inspect motor coupling, rehome the axis	Medium

Note

E-620 requires the servo drive to cool below 45°C before restart. If the fault repeats after fan replacement, escalate to the electrical maintenance team.