

Injection Molding Machine IM-500 — Error Code Reference Manual

Model: IM-500 | Line: Plastic Molding, Bay 3 | Rev 2.4

Code	Meaning	Likely Cause	Recommended Action	Severity
E-101	Barrel over-temperature	Heater band controller fault; blocked cooling	Stop production, check heater band & thermocouple, allow barrel to cool to 180°C	Critical
E-102	Hydraulic pressure low	Oil level low; pump seal leak	Check oil reservoir level, inspect pump seals, top up ISO VG46 oil	High
E-205	Mold clamp not aligned	Tie-bar misalignment; worn plate	Pause cycle, run manual clamp alignment, inspect tie-bars for wear	Medium
E-210	Injection screw overload	Material contamination; screw wear	Purge barrel, verify material spec, inspect the flights	Medium
E-303	Cooling water flow low	Clogged filter; pump underperformance	Clean inline filter, verify chiller pump, check flow > 8 L/min	Medium
E-404	Emergency stop triggered	Operator E-stop; safety gate open	Confirm area safe, close safety gate, reset E-stop, restart cycle	Critical
E-512	Ejector jam	Part stuck; ejector pin bent	Stop machine, remove stuck part, inspect and replace ejector pins	Medium

General Notes

Always follow lockout-tagout (LOTO) before opening any guard. Codes with severity Critical or High require supervisor sign-off before restart. Log every fault in the shift maintenance register.