FUJIKURA FIBER OPTICS VIETNAM LTD

OPERATION PROCEDURE OF T-CONNECTOR GUMI PRODUCT		
Document No.: 4-OP-0081	Version: 12	Page: 1/23

I. Purpose

- To instruct operation method which implemented in Fujikura Fiber Optics Vietnam

II. Application



- This guideline is applied for T-Connector Gumi as processes following

No	Product name	Remark
S-GAISHI-71-2186-3	KY-T-Connector S-LG	Use 20dB FBG
S-GAISHI-71-2186-3	KY-T-connector S-LM-R	Use 40dB FBG

- This document concerns to Production function, Production engineering function, Quality Assurance function and Planning function.

III. References



Customer specification

Reference document	Product name	Remark
S-GAISHI-71-2186-3	KY-T-Connector S-LG	Use 20dB FBG
S-GAISHI-71-2186-3	KY-T-connector S-LM-R	Use 40dB FBG

IV. Term and Definition

FOV: Fujikura Fiber Optics Viet Nam

SIC: Section In Charge

T-Connector GUMI: one kind of products which are manufacture in FOV

V. <u>Traceability control:</u>

The requirement of traceability record for each products shall follow the 9-PR-013 Data traceability procedure.

Type of record	Items	Record
Quality control items	Refer to: QC Flow chart 4-QC-0081	
Identification & trace ability record	4M information (if any): - Material Lot# - Machine/Tool-jig control number - Operator code - Manufacturing/ inspecting date	Related Check sheet

	FUJIKURA FIBER C	PTICS VIETNAM LTD.
OPERATION PROCEDURE OF T-CONNECTOR GUMI		
Document No.: 4-OP-0081	Version: 12	Page: 2/24

VI. Content

1. Epotek mixing & injection

1.1 Process specification

Item	Specification
Final mixture	- Enough part
	- Mixing ratio, time
	- Pot time
	- Expire date of each part

1.2 Process condition

Item	Condition
Amount of part A and B	Scale, software
Mixing in 5 minutes	Timer
Remove air bubble	Centrifugal

Step 1: Put the cup on to the scale and fill Epotek part A with amount in Table 1


Step 2: Fill Epotek part B into the cup with amount in Table 1

Phần A (2)	Phần B (01)
2g (1.8g ~ 2.2g)	$0.2g (0.18g \sim 0.22g)$

Step 3: Mix by manual in 5 minutes.



Step 4: Fill into the syringe and put it into centrifugal to remove air bubble at least 10 minutes.



Step 5: Check air bubble inside syringe

FUJIKURA FIBER OPTICS VIETNAM LTD.		
OPERATION PROCEDURE OF T-CONNECTOR GUMI		
Document No.: 4-OP-0081	Version: 12	Page: 3/24

2. GUMI mixing

2.1 Process specification

Item	Specification
Final mixture	- Enough part (FW-L + FW-H+ MEK if any)
	- Mixing ratio (27%,4%), time
	- Pot time (≤15h)
	- Expire date of each part

2.2 Process condition

Item	Condition
Amount of FW-L, MEK, FW-H	Scale
Tolerance	0.01 gram
Remove air bubble	Centrifugal
Mixing adhesive	By mixer

Apply Gumi mixing program:



- Step 1: Measure the weight of FW-H.
- Step 2: Add amount of MEK need input to balance into FW-H.
- Step 3: Measure the weight of FW-L and add FW-H into FW-L (following to instruction of program).

Step 4: Input solvent MEK into FW-L.



Step 5: Shake by manual in about 2 minutes to mix 2 parts



FUJIKURA FIBER OPTICS VIETNAM LTD.			
OPERATION PROCEDURE OF T-CONNECTOR GUMI			
Document No.: 4-OP-0081	Version: 12	Page: 4/24	

Step 6: Mixing by mixer in 10 minutes



Step 7: Fill into the syringe and put it into centrifugal to remove air bubble in 5 minutes.





Step 8: Check air bubble inside syringe

3. GUMI process

3.1 Process specification

Item	Specification
Fiber	- Enough length
	- Correct direction
	- No contamination
	- Blow by ion fan
	- End-face no chip.
Film attached on fiber	- No tail
	- Adhesive attach on surround of fiber less than haft of fiber
Branching fiber	- No broken
Measure GUMI thickness	- Nikon microscope (Sample 3pcs/machine/day)
	- Thickness 25~35um


3.2 Process condition

This process should be carried out in cleanroom and without wind.

Item	Condition
Check the film shape.	Visual
Cleaning adhesive base	After clean no adhesive attach on base, no alcohol remain
Curing	Hotplate at 130°C ±5 at least 60 minutes
Branching fiber	By manual

*** 20dB FBG

Step 1: Set ribbon fiber on the checking length jig.




FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 5/24



Step 3: Separate ribbon fiber into individual fiber and set fibers into jig.



Step 4: Set fiber into UV holder, fiber and UV hoder will be dip in Acetone and dried in front of ion fan about 20s. Clean by dusper with alcohol (if detect contamination on fiber) and flow it by ion fan.








*** 40dB FBG

Step 1: Use CT-30 cut the short side of ribbon fiber.



Step 2: Separate ribbon fiber into individual fiber and set fibers into jig. Set fiber on the checking length jig, use the jig 20.97mm for 40dB FBG





FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI











Step 4: Cut fiber by CT-30.




*** The next steps are the same for 20dB FBG and 40dB FBG


Step 5: Put holder into base of machine. Fiber end above static base. Close the clamp to fix fiber. Press the button "Run"






Step 6: Check film is attached by static electric or not (check voltage change or not when running every first time use index maching film machine)? Check film shape









In case film NG, we can use acetone to clean film. After than blow it by ion fan in 1 min

FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 7/24





Step 7: Take out holder and clean adhesive base.




Step 8: Put fiber with holder into curing jig and cur it in 1 hour and set hotplate 130° C (Temperature specification: 85° C - 115° C)





Step 9: Checking GUMI thickness (sample)



4. Ferrule assembly

4.1 Process specification

Item	Specification
Fiber	No broken.
	Fiber end stay between 4 marks
Film	No damage, contamination
Ferrule	Enough epotek in cone
	No crack, damage

4.2 Process condition

FUJIKURA FIBER OPTICS VIETNAM LTD.			
OPERATION PROCEDURE OF T-CONNECTOR GUMI			
Document No.: 4-OP-0081	Version: 12	Page: 8/24	


Item	Condition
Curing	Hotplate at 130°C ±5 at least 10mins
Check epotek	Visual
Adjust fiber in 4 marks	Pull protrusion fiber from the top of ferrule. Don't touch film

*** 20dB FBG

Step 1: Set ferrule (insert mold) into jig and put the jig into auto suction machine:



Step 2: Adjust suitable program for sucking epotek into ferrule and use auto suction machine to suck epotek. Step 3: Check amount of epotek in cone of ferrule and on the top of ferrule.



Epotek on the top of ferrule

*** 40dB FBG

Step 1: Set ferrule into jig and put the jig into auto suction machine.



Step 2: Adjust suitable program for sucking epotek into ferrule and use auto suction machine to suck epotek. Check amount of epotek in cone of ferrule and on the top of ferrule.



Step 3: Put epotek into groove of ferrule body => assembly to lower body by assembly tool, clean ferrule and check length of ferrule after assembly.










*** The next steps are applied for both 2 kinds of products: 20dB and 40dB.

Step 4: Take out curing jig after curing and set on jig under microscope for checking.

FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 9/24




Step 5: Cut fiber by CT-30 and keep fiber by bare fiber holder.

Step 6: Take out fiber holder and set it in fiber insert tool. Slide fiber holder until we can see fiber protrusion ~2mm at the tip of ferrule. Open the lock and pull back fiber holder.





Step 7: Adjust fiber in 4 marks by <u>pull</u> protrusion fiber on the tip of fiber. (Never push fiber end)



Step 8: Curing body at least 10mins at 130° C ± 5



5. Polishing

5.1 Process specification

Item	Specification
Ferrule length	7.75mm ~7.95mm
Inter	Radius of curvature(mm): 10~25 Apex offset(um): < 50 Fiber height(nm): -100~50
End-face	Follow 4-OP-0397 spec

5.2 Process condition

0.2 110 00 55 00110101011	
Item	Condition
Polishing ferrule	Polisher
Polishing liquid, cleaning	Water, Kim wipe
Inter	Inter machine
End-face	Microscope at lens 400x

Details step please refer to:

FUJIKURA FIBER OPTICS VIETNAM LTD.		
OPERATION PROCEDURE OF T-CONNECTOR GUMI		
Document No.: 4-OP-0081	Version: 12	Page: 10/24

+ 4-OP-528: Polishing condition

Note:

- Apply white tube to protect GUMI from contamination, polishing water
- Sampling Inter 02 Jig/shift.

6. Film inspection (Appearance 3+ appearance 5)

6.1 Process specification


Item	Specification
V-groove area	No contamination
GUMI film	No deform, damage No contamination

6.2 Process condition

Item	Condition
Checking GUMI shape	Microscope ME2503 system
V-groove area	Microscope
Air blow	By air gun

*** Appearance 3:


No dust in V-groove area.





Note: If have contamination, only blow by air. Don't use alcohol to clean contamination.

*** Appearance 5: Check GUMI shape



7. Body cleaning

7.1 Process specification

Item	Specification
Upper body A, B/ Upper body FAS	- Cleaning condition
Lower body	- No burr, stone, crack


7.2 Process condition

Item	Condition
Alcohol for cleaning	Change after cleaning 25,000 pcs


FUJIKURA FIBER OPTICS VIETNAM LTD.			
OPERATION PROCEDURE OF T-CONNECTOR GUMI			
Document No.: 4-OP-0081	Version: 12	Page: 11/24	

Tray to storage lower body	No contamination
PE bag to storage upper body	No contamination inside. Don't damage
Cleaning time, dry body	Timer, auto drying machine

Step 1: Check body appearance. Cleaning 1: use alcohol to clean it by ultrasonic machine in 10 minutes



Step 2: Carry out cleaning 2 by ultrasonic with alcohol in 10 minutes. After that, dry body by auto drying machine. The last, upper body were put into plastic box.





8. Body assembly

8.1 Process specification

Item	Specification
Upper body A,B/ Upper body FAS	-No contamination, dirty stuck on body.
C-sleeve	- Position and direction of key
Appearance	- No contamination, no scratch


8.2 Process condition

Item	Condition
Upper body	- Check contamination by visual.
Body Assembly	 Tool for assembly: Smoothly, no any damaged onto product. Assembly condition: carried out in the clean bench Check appearance by visual

Step 1: Set lower body and upper on body assembly tool. And assembly $\leq 1/2$ C-Sleeve to the pin of body assembly tool.


FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 12/24






Step 2: Put upper B on lower body. And push C-sleeve to cover body.





Step 3: Take out and check C-Sleeve position. Check body appearance.



9. Material preparation

9.1 Process specification


Item	Specification	
Holder	- Correct part	
Wedge	- Enough quantity	
	- No crack, broken.	
Stop-ring/PS	- Correct part	
Slider	- Enough quantity	
Lever	- No crack, broken.	
Assembly part	- Correct direction, parts	


9.2 Process condition

Item	Condition
Appearance	Visual
Assembly	Manual

Step 1: Assembly Wedge into Holder (With products that use 40dB FBG)


- Use 2 kinds of Wedge: Wedge (FG) => Wedge 1 and Wedge (FA) => Wedge 2.





FUJIKURA FIBER OPTICS VIETNAM LTD.			
OPERATION PROCEDURE OF T-CONNECTOR GUMI			
Document No.: 4-OP-0081	Version: 12	Page: 13/24	

- Assembly wedge into tool and then press Holder to insert Wedge into Holder.





Step 2: Check appearance of material and assembly PS, Lever and Slider.



10. Housing

10.1Process specification

Item	Specification
Housing part	- Correct part
	- Enough quantity
Part assembly	- Correct direction
	- Spring can movement smoothly

10.2 Process condition

Item	Condition	
Appearance	Visual	
Clean	By dusper/ bemcot	
Housing Assembly	 Tool for assembly: Smoothly, no any damaged onto product. Assembly condition: carried out in the clean bench Check appearance by visual 	



XOperation step:

Step 1: Use vacuum machine to remove contamination on the body.




FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 14/24


Step 2: Insert body to jig




Step 3: Insert PS for SC-GT to jig





Step 4: Put spring into PS for SC-GT



Step 5: Insert body to PS for SC-GT









4. insert body into PS for $$\text{C-GT}_{\odot}$$

FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 15/24

Step 6: Take out the assembled product




Step 7: Check spring by visual




product。

Step 8: Check body assembly completely in PS for SC-GT



Step 9: Push coupling from the top of plug-frame. Use bemcot for cleaning endface of products.



Step 10: Assembly holder.

* With products that use 40dB FBG:

FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 16/24



*With products that use 20dB FBG:



11. Loss inspection

11.1 Process specification

*** 20dB FBG

- FBG type G:

Items	RL Value	Wavelength	Equipment & Condition	Sampling
In a set in a	< 1.35 dB	1310±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	10pcs/PO
Insertion Loss	< 1.35 dB	1550±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	All
LOSS	≥ 21 dB	1650± 6 nm	SLD+OSA (*)	All
Datas	≥ 35 dB	1310±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	10pcs/PO
Return Loss	≥ 35 dB	1550±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	All
LUSS	< 3.95 dB	1650± 5 nm	SLD+OSA (*)	All

- FBG type H:

Items	RL Value	Wavelength	Equipment & Condition	Sampling
	< 1.35 dB	1310±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	10pcs/PO
Insertion Loss	< 1.35 dB	1550±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	All
LOSS	≥ 22.5 dB	1650± 6 nm	SLD+OSA (*)	All
Return	≥ 35 dB	1310±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	10pcs/PO
Loss	≥ 35 dB	1550±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	All
	< 3.95 dB	1650± 5 nm	SLD+OSA (*)	All

*** 40dB FBG

Items	RL Value	Wavelength	Equipment & Condition	Sampling
Insertion	< 1.35 dB	1310±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	10pcs/PO
Loss	< 1.35 dB	1550±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	All
LOSS	≥41.5 dB	1650± 5 nm	SLD+OSA (*)	All
Datum	≥ 35 dB	1310±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	10pcs/PO
Return Loss	≥35 dB	1550±20 nm	SLD+OSA (Optical Spectrum Analyzer) (*)	All
	< 3.95 dB	1650± 5 nm	SLD+OSA (*)	All

FUJIKURA FIBER OPTICS VIETNAM LTD.		
OPERATION PROCEDURE OF T-CONNECTOR GUMI		
Document No.: 4-OP-0081	Version: 12	Page: 17/24

(*) In case of using TLD, measuring wavelength should be 0.01um step. In case of using SLD, measuring should be continuity

With products that use 40dB FBG: Assembly Holder cover after measuring loss.



11.2 Process condition

Item	Condition
Measuring cable	UV fiber 0.25
Bare fiber checking	Microscope SZ-61


Prepare fiber with parameter as below:


- Strip and cut the fiber with the length: 9.7 => 10.7mm.
- Life time of using: If UV coating becoming peel off of after maximum 6 products measured, the measuring cable should be re-preparing again.
- Time of insertion of measuring fiber into product: 1 product is allowed maximum 2 times.
- Check appearance of measuring fiber after measuring 6 products to ensure appearance of measuring fiber and quality of Gumi.
- Wedge no.1 have to insert and take out before wedge no.2

12. Reflection inspection

12.1Process specification

Item	Kind of FBG	Specification
EDC mosition	20 dB	Distance from the top of ferrule to the end of FBG is 7~9.3 mm
FBG position 40dB	40dB	Distance from the top of ferrule to the end of FBG is 8.7~11 mm





12.2 Process condition

Item	Condition
Reflect inspection	Reflect machine
Judgement	Visual, template

Note: Sampling Reflect 1pcs/shift.

13. Final End-face

Follow spec S-GAISHI-01-2000-5 and FOV general 4-OP-0397 for more detail



14. QC Appearance

14.1 Process specification

Item	Specification	
Attached component	- Enough quantity and right parts.	
Appearance of main product	- Stain of material not > 5mm - Scratch should not be feeling by finger nail	
	No any crack, no any bubble, no any contamination.No any burr.	

14.2 Process condition

Item	Condition
Appearance	Visual
PE bag	

15. QC packing

15.1 Process specification

Item	Specification
Process	Carry out in inside (Step 1, 2, 3) and outside (step 4, 5) cleanroom
	condition

FUJIKURA FIBER OPTICS VIETNAM LTD.		
OPERATION PROCEDURE OF T-CONNECTOR GUMI		
Document No.: 4-OP-0081	Version: 12	Page: 19/24

Packing materials	Correct pack, carton box, labels. Enough quantity
-------------------	---


15.2 Process condition

Item	Condition
Packing	Manual

Step 1: Put 1 product + 1 Clamp M ver.2 into each slot into PE bag B-4 (60x85mm)



- Step 2: Put 10 packaging of product into the PE bag(G-4). Direction is changed one by one. The place of slider M is anywhere OK.
- Put spare of 1 clamp M into a PE bag(B-4) and put into a PE bag(G-4).




Step 3: Paste the label of T-connector packing on PE bag(G-4)


FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI : 4-OP-0081 Version: 12 Page : 20/24



Label information



- (1) Product name: "KY-ガイヒハジTS<SC>-<LG>-<F>" (KY-T-Connector S-LG) "KY-ガイヒハジTS<SC>-<LM-R>-<F>" (KY-T-Connector S-LM-R)
- (2) Barcode: "21360839" (KY-T-Connector S-LG)
 "21360871" (KY-T-Connector S-LM-R) *by cord-39
- (3) Quantity:"10個入"
- (4) Product month:



- (5) SG product code: "1170031" (KY-T-Connector S-LG) "1170032" (KY-T-Connector S-LM-R)
- (6) W/O No (Work Order No.)
- (7) Box No: F******-001


FUJIKURA FIBER OPTICS VIETNAM LTD. OPERATION PROCEDURE OF T-CONNECTOR GUMI Document No.: 4-OP-0081 Version: 12 Page: 21/24

Where:
F*******: PO number
0001: serial

Step 4: Pack 10 PE bag (G-4) into the inner carton [ID] L300mmxW160mmxH150mm. And, put in the pad to the bottom and top.



Check the label outside the box:



Step 5: Packing method with pallet (Container 20FT contain maximum 20 pallets (1150*1150*1130) ~ 216,000 products)

FUJIKURA FIBER OPTICS VIETNAM LTD.		
OPERATION PROCEDURE OF T-CONNECTOR GUMI		
Document No.: 4-OP-0081	Version: 12	Page : 22/24

Item	Dimension (mm)
Inner carton	300*160*150 (OD)
Pallet	1150*1150*1130





16. Shipping

Shipping Q'ty and product name must be confirm correct with P/O from Customer Test report of that shipment will be sent to Customer latest one day after product is ex-factory The content of test report included items that are request in Product spec.

FUJIKURA FIBER OPTICS VIETNAM LTD.				
OPERATION PROCEDURE OF T-CONNECTOR GUMI				
Document No.: 4-OP-0081	Version: 12	Page: 23/24		

REVISION HISTORY

Date	Person	Version		ntent	Reason	Change
	in charge		Old description	New description		Requester
			Specification: S-GAISHI-71-2128-2	- Specification: S-GAISHI-71-2186-3	Update Spec changed	
1-Oct-2024	Thu DTM	12	*** Appearance 3: Check fiber in 4 marks, no dust in V-groove area	*** Appearance 3: No dust in V-groove area	Follow 9-PR-0014- 9-FO-0001-4-RC- 0141	Nguyen Ba Phuoc
			13. Final End-face Follow spec S-GAISHI- 01-2000-4	13. Final End-face Follow spec S-GAISHI-01- 2000-5	Document review	
10-Apr-24	Nguyen Ly Thien Ngan		- Specification: S-GAISHI-71-2128-6	- Specification: S-GAISHI-71-2186-2	-Apply new template 0-PR-001- 0-TEM-0008	Pham Dinh Hieu
		11	- Item 1.2: Step 1: With products that use 20dB FBG, use 1 kind of Wedge: Wedge (FA). Step 2: Check appearance of material and assembly Stopring, Lever and Slider. Item 2.1 & 9.1: Upper body A,B	- Correct numerical order of process compliance to QC flow chart - Item 9.1 (change order): Step 1: Cancel Step 2: Check appearance of material and assembly PS, Lever and Slider.	- New product design from customer	
			-Item 10: Housing by manual -All Checking items in each process -Item 7. Checking items: Sampling Inter 2pcs/shift	Item 7.1 & 8.1(change order): Upper body A,B/ FAS -Item 10: Housing by tool -Item V. Traceability control -Item 5 (change order): Checking items: Sampling Inter 2jig/shift		
04-Sep-18	Nguyen Thi Lan Phuong	10	- Item 8.1: Body: No broken. No contamination. + Item 8.2: Body chip + Item 8.3: Epotek in cone, body chip	- Item 8.1: V-groove area: No broken. No contamination. + Item 8.2: V-groove area + Item 8.3: V-groove area	- Improvement with 4M: 4-Pr-007-4-Fo- 001-4-RC-0512	Deputy Div. Manager Nguyen Trung Kien
23-Jul-18	Duong Xuan Mai	09	- Item 11.2: Measuring cable: Drop-cable - Item 4.1: Mixing ratio, Pot time.	- Item 11.2: Measuring cable: UV fiber 0.25 - Item 4.1: Mixing ratio (27%4%), Pot time (≤15h) Item 15.1: Carry out in	- Improvement with 4M: 4-Pr-007-4-Fo- 001-4-RC-0460 - Correction	Dept. Manager Nguyen Trung Kien
			- Item 15.1: Carry out outside in cleanroom condition Item 5.2: Step 4:	inside (Step 1, 2, 3) and outside (step 4, 5) cleanroom condition Item 5.2: Step 4:	- Correction	

FUJIKURA FIBER OPTICS VIETNAM LTD.				
OPERATION PROCEDURE OF T-CONNECTOR GUMI				
Document No.: 4-OP-0081	Version: 12	Page: 24/24		

			+ Set fiber into UV holder. - Item 5.2: Step 7: Clean adhesive base.	+ Set fiber into UV holder, fiber and UV hoder will be dip in Aceton and dried in front of ion fan about 20 sec Item 5.2: Step 7: revise picture for description more: move around cleaning pad for cleanning adhesive base.	- Correction (decrease defect mode "film no absorb on fiber" of Gumi machine) - Correction (decrease defect mode "film over flow" of Gumi machine)	
01-Sep- 2017	Nguyen Thi Lan Phuong	08	- Use Outer carton for packing method - Clean 1> Dry> Clean 2> Put into plastic. - Mix by manual in 1 minute and after that mix by machine in 4 minutes. - Item 14, 15: QAS. - Mixing Gumi adhesive follow to excel form.	 New packing method. (Don't use Outer carton) Clean 1> Clean 2> Dry> Put into plastic Mix by manual in 5 minutes. Item 14, 15: QAS -> QCS. Mixing Gumi adhesive follow to program. 	- Improvement with 4M: 4-PR-007-4-FO-001-4-RC-0236 - Correction. - Correction - Correction - Correction	Dept. Manager Nguyen Trung Kien
22-Dec-16	Nguyen Thi Lan Phuong	07	- Check appearance of measuring fiber 100%	- Check appearance of measuring fiber 1pc/6 products	- Improvement with 4M: 4-PR-007-4- FO-001-4-RC-0097	Dept. Manager Nguyen Trung Kien