

Rotating Equipment Inspection Report

Pump P-101 | Utilities Cooling Loop A | Inspection date: 18 July 2026

Inspection summary

Field	Value
Equipment	P-101 - Cooling Water Pump
Inspector	A. Mehta, Reliability Engineer
Operating state	Running at 92 percent load
Overall assessment	Action required

Trend readings

Date	Vibration RMS	Drive-end temperature	Observation
02 Jul 2026	4.2 mm/s	72 C	Baseline; no abnormal noise
10 Jul 2026	5.9 mm/s	79 C	Increasing trend
18 Jul 2026	7.8 mm/s	88 C	Metallic noise near drive-end bearing

P-101 now exceeds the OEM alert limits of 7.1 mm/s vibration and 85 C bearing temperature. The concurrent rise and metallic noise indicate a credible drive-end bearing defect rather than a single noisy measurement.

Recommended action

Reduce pump load where operationally possible. Review lubrication work-order status and inspect the drive-end bearing within 24 hours. Record post-maintenance vibration and temperature before full-load return.

Instrument traceability

Vibration meter VM-22, calibration valid through 12 December 2026. Infrared thermometer IR-08, calibration valid through 03 November 2026. Readings were repeated twice within a five-minute interval.