

Applicability and conditions

Slats and flaps

Abnormal procedure — slats jammed

Object code	DMC-A350X-A-27-81-00-00A-130A-A	Issue	002-00 (revised)
Issue date	2026-01-30	Language	en-GB
Responsible partner	AIRBUS S.A.S. (U8025)	Originator	AIRBUS S.A.S. — Flight Operations Support (U8025)
Security	01 — Unclassified	Quality assurance	Second verification (onobject)
Applicability	A350X-900 and A350X-1000, all aircraft		

Applicability and conditions

This drill applies when the ECAM shows F/CTL SLATS JAMMED and the slat surfaces do not follow the lever position. The flaps are not affected and stay available for the approach.

CAUTION

Do not move the flap and slat control lever again before the drill is complete. A second command can lock the wing tip brakes and remove the flap system as well.

Slats jammed — drill

- FLAP LEVER..... **DO NOT MOVE**
- SPEED..... **MAINTAIN BELOW PLACARD**
- SLAT POSITION INDICATION..... **CHECK AND NOTE**

NOTE: The slat position at the time of the jam determines the approach speed increment and the landing distance factor to be applied.

- LANDING DISTANCE..... **APPLY FACTOR 1.35**
- APPROACH SPEED..... **VREF + 15 KT**
- FOR LANDING..... **USE FLAP 3**
- GO-AROUND THRUST..... **CONFIRM AVAILABLE**
- AUTOBRAKE..... **MEDIUM**

After landing

Write the fault in the aircraft technical log with the slat position at the time of the jam and the ECAM messages that were shown. Maintenance action is required before the next flight.