

1. Fault description

Slat control and monitoring system

Fault isolation — SLAT SYS 1 FAULT

Object code	DMC-A350X-A-27-81-00-00A-420A-A	Issue	001-00 (new)
Issue date	2026-02-18	Language	en-GB
Responsible partner	AIRBUS S.A.S. (U8025)	Originator	AIRBUS S.A.S. — Technical Data Toulouse (U8025)
Security	01 — Unclassified	Quality assurance	First verification (tabtop)
Applicability	A350X-900 and A350X-1000, all aircraft		

1. Fault description

The maintenance status page shows the fault message **SLAT SYS 1 FAULT** together with the correlated message **SFCC1 (27CV1)**. The slat system continues to operate on the standby channel at half rate.

Do this procedure after a flight in which the fault message was shown, or after the message is raised during a system test on the ground.

2. Job set-up information

A. Referenced information

TYPE	DESIGNATION	IDENTIFICATION No.
DM	The aircraft electrical power is available.	DMC-A350X-A-24-41-00-00A-861A-A

B. Fixtures, tools, test and support equipment

QTY	DESIGNATION	IDENTIFICATION No.
1	Portable maintenance access terminal	98D45111000000 (CAGE U8025)

C. Consumable materials

No consumable materials required

D. Expendable parts

No expendable parts required

E. Safety conditions

WARNING

Make sure that the slat travel area is clear of persons and equipment before you do a system test. The slats move without a warning when the test is started.

3. Fault isolation procedure

4. Close-up

STEP 1

Do the SFCC 1 built-in test on the maintenance terminal. Is the fault message SFCC1 CHANNEL A shown at the end of the test?

ANSWER	ACTION
YES	The fault is inside the computer or on its power supply. Go to step 2
NO	The fault is in the position feedback or in the wiring. Go to step 3

STEP 2

Examine the circuit breaker 4027GA on panel 121VU. Is the circuit breaker tripped?

ANSWER	ACTION
YES	Corrective action: Reset the circuit breaker and do the slat system operational test. If the circuit breaker trips again, replace the SFCC 1. Go to the end of the procedure
NO	Corrective action: Replace the SFCC 1 and do the slat system operational test. Go to the end of the procedure

STEP 3

Do a continuity check of the harness between connector 2027VC on the PCU and connector 2101VC on the SFCC 1. Is the resistance of each conductor less than 1.5 ohm?

ANSWER	ACTION
YES	Corrective action: Replace the feedback position pick-off unit on the PCU output and do the slat system operational test. Go to the end of the procedure
NO	Corrective action: Repair the harness between the two connectors and do the slat system operational test. Go to the end of the procedure

END OF FAULT ISOLATION PROCEDURE

Make sure that no fault message is shown on the maintenance status page and make an entry in the aircraft technical log.

4. Close-up

Remove the maintenance terminal and close the access panels.