

REPAIR QUOTE

No. VC-169-001

PROPERTY 1811 S Quebec Way #169, Denver, CO 80231	DATE October 5, 2026
PREPARED FOR Seller, 1811 S Quebec Way #169	VALID THROUGH October 21, 2026
BASIS Alpine Building Performance home inspection, 9/30/2026	SCOPE Inspection repairs with full carpet and LVP replacement
ITEMS 34 inspection items (1 priced with another item); sewer scope	

Each item number below opens that item in the inspection report. [View the full inspection report](#)

FULL SCOPE

\$15,999

9 work packages covering every inspection item; open any package for its details

REPORT ITEM	REPAIR	PRICE
▶ Smoke and CO alarms	2 items	\$588
▶ Electrical safety	5 items	\$1,289
▶ Gas, furnace and air	5 items	\$1,771
▶ Sewer line	1 item	\$540
▶ Plumbing	8 items	\$2,751
▶ Fireplace	1 item	\$480
▶ Flooring	2 items	\$5,520
▶ Doors, stairs and windows	6 items	\$1,380
▶ Interior finishes	7 items	\$1,680
Inspection items and sewer scope		\$15,306
Permits, inspections and licensed sign-off		\$693
TOTAL		\$15,999

TERMS

- Each price covers labor and materials to complete the repair described for that report item.
Each item number links to its section of the inspection report.
- Included are the report items priced above, including the west deck stairs. Roof, siding, grading and landscaping maintained by the HOA are not included.
- Each item was priced by contractors to perform the work effectively at the most competitive rates.

- 4. Permit lines cover the City and County of Denver permit fees and inspections, and sign-off on the electrical work by a licensed electrician. The plumbing valve work is performed by a licensed plumber. The heating, cooling and gas prices include that trade's Denver mechanical permit.
- 5. Conditions concealed behind walls, floors or finishes are not included; any change to the work or price is agreed in writing before that work proceeds.
- 6. This quote is valid through October 21, 2026.

Guess Oka	October 5, 2026
Member, Velocity Contracting LLC	Date
Accepted by seller, signature	Date

ITEM DETAIL

REPORT ITEM	REPAIR	PRICE
Smoke and CO alarms		\$588
<u>11.2.1</u>	Bedroom smoke alarms Bedrooms: add a hardwired smoke alarm in each bedroom	\$456
<u>11.3.1</u>	CO alarm near the bedrooms 2nd floor: add a hardwired CO alarm within 15 ft of the bedrooms	\$132
Electrical safety		\$1,289
<u>5.5.1</u>	Loose outlet West bedroom: Loose outlet not secured in the box: re-secure	\$36
<u>5.5.2</u>	Missing cover plates East bedroom, sump pump, attic, one more: Missing or broken cover plates: install	\$83
<u>5.6.1</u>	GFCI outlets Kitchen, laundry: No GFCI protection: install GFCI outlets	\$324
<u>8.7.1</u>	Furnace and AC disconnect Mechanical room: No disconnect within 6 ft of the furnace and AC: install one	\$204
	Electrical permit and licensed sign-off City and County of Denver electrical permit and inspection, with sign-off on the electrical work by a licensed electrician	\$642
Gas, furnace and air		\$1,771
<u>7.7.1</u>	Combustion air Mechanical room: the inspector did not identify a dedicated combustion air source; heating and cooling trade to evaluate and correct to code	\$1,080
<u>7.8.1</u>	Furnace gas valve Furnace: replace the old gas shutoff with a ball valve	\$360
<u>8.1.1</u>	Furnace and AC service Furnace and AC: Clean and service both units; CO and backdraft check	\$300
<u>8.6.1</u>	Combustion air at the water heater Same repair as 7.7.1 (the report lists it under both water heater and furnace); priced once there	With 7.7.1
<u>8.8.1</u>	Furnace filter Furnace: Replace dirty air filter	\$31
Sewer line		\$540
	Sewer descale and rescope Descalc the cast iron section of the sewer line and rescope to confirm the possible hole at the 11 ft mark. Any repair the rescope finds, and the cracked clean-out boot, are quoted separately	\$540
Plumbing		\$2,751
<u>4.9.1</u>	Water pressure regulator Main water line: a licensed plumber removes the existing pressure reducing valve, installs a new one and sets the pressure	\$660
<u>7.2.1</u>	Main water shutoff valve Basement east: a licensed plumber replaces the old main water shutoff with a full-port ball valve	\$780
<u>7.4.1</u>	Slow basement drain Basement bath: Slow drain: clear the line	\$180

REPORT ITEM	REPAIR	PRICE
7.5.1	Loose toilet East bedroom bath: Toilet loose at floor: reset with new wax ring and bolts	\$180
7.5.2	Leaking shower heads 2nd floor baths: Shower heads leak at the connection: rebuild or replace	\$240
7.5.3	Tub and shower diverter West bedroom bath: Tub and shower diverter does not fully engage: repair or replace	\$480
10.8.1	Washer hoses Laundry: Replace rubber washer hoses with braided stainless	\$180
	Plumbing permit City and County of Denver plumbing permit and inspection, for the licensed plumber's valve work	\$51
Fireplace		\$480
8.9.1	Chimney sweep and inspection Fireplace: Wood burning fireplace: chimney sweep and inspection	\$480
Flooring		\$5,520
11.6.1	First floor hard flooring 1st floor: replace the hard flooring with LVP, which also resolves the 5 damaged spots	\$3,120
11.6.2	Carpet Throughout: replace the dirty and stained carpet, including the stairs; the stains and odor are from a previous tenant's cat urine, which cleaning may not fully remove	\$2,400
Doors, stairs and windows		\$1,380
4.5.1	Entry door weatherstripping West and east entries: Replace damaged or missing door weatherstripping	\$180
4.5.2	Deck closet door latch Deck closet: Door knob or latch damaged: repair or replace	\$120
4.5.3	Sliding screen door West entry: Screen door screen damaged: rescreen or replace	\$240
4.7.1	Deck stair risers West deck: Stair risers over 7-3/4 in: rebuild steps to code	\$480
11.4.1	Closet door floor guides 2nd floor: replace the broken or missing sliding closet door floor guides	\$120
11.5.3	Window balance rod Living room: Window balance rod stuck or damaged: repair	\$240
Interior finishes		\$1,680
11.5.1	Window caulking Bedrooms, living room: Touch up interior window caulking	\$120
11.7.1	Touch-up paint Throughout: touch-up paint, caulk and minor repair on walls, ceilings and trim	\$360
11.7.2	Wall and ceiling cracks Living room: patch and paint minor wall and ceiling cracks	\$360
11.7.3	Staircase stain Staircase: seal and repaint the stain the inspector found inactive	\$120
11.9.1	Countertop chip Kitchen: Countertop cracked, chipped or delaminating: repair	\$180

REPORT ITEM	REPAIR	PRICE
11.9.2	Kitchen cabinet finish Kitchen: Cabinet finish worn: refinish	\$360
11.10.1	Shower surround All baths: Shower surround stops below the head: seal and finish the wall above it	\$180