

REPAIR QUOTE

No. VC-169-001

PROPERTY 1811 S Quebec Way #169, Denver, CO 80231	DATE October 4, 2026
PREPARED FOR Seller, 1811 S Quebec Way #169	VALID THROUGH October 21, 2026
BASIS Alpine Building Performance home inspection, 9/30/2026	SCOPE Inspection repairs with full carpet and LVP replacement
ITEMS 34 inspection items (1 priced with another item); sewer scope	

Each item number below opens that item in the inspection report. [View the full inspection report](#)

EXPECTED BEFORE CLOSING

\$779

4 items: the lender's appraisal and Colorado's carbon monoxide alarm law

HEALTH AND SAFETY

\$4,943

12 items, including the ones above and the sewer line

FULL SCOPE

\$16,107

every inspection item priced below

REPORT ITEM	REPAIR	PRICE
11.2.1	ELECTRICAL Safety Recommendation - Install Additional Smoke Alarms EXPECTED BEFORE CLOSINGHEALTH AND SAFETY Bedrooms: add a hardwired smoke alarm in each bedroom	\$492
11.3.1	ELECTRICAL Safety Recommendation - Install Additional CO Detectors EXPECTED BEFORE CLOSINGHEALTH AND SAFETY 2nd floor: add a hardwired CO alarm within 15 ft of the bedrooms	\$168
5.5.2	ELECTRICAL Cover Plates Missing (1 more defect) EXPECTED BEFORE CLOSINGHEALTH AND SAFETY East bedroom, sump pump, attic, one more: Missing or broken cover plates: install	\$83
5.5.1	ELECTRICAL Loose Receptacle EXPECTED BEFORE CLOSINGHEALTH AND SAFETY West bedroom: Loose outlet not secured in the box: re-secure	\$36
7.7.1	HEATING, COOLING AND GAS Combustion Air - Dedicated Source Not Identified APPRAISER MAY REQUIREHEALTH AND SAFETY Mechanical room: the inspector did not identify a dedicated combustion air source; heating and cooling trade to evaluate and correct to code	\$1,080

REPORT ITEM	REPAIR	PRICE
4.9.1	PLUMBING High Water Pressure - Adjust Or Install Water Pressure Regulator HEALTH AND SAFETY Main water line: a licensed plumber removes the existing pressure reducing valve, installs a new one and sets the pressure	\$660
	SEWER LINE SEWER SCOPE Sewer scope finding HEALTH AND SAFETY Descale the cast iron section of the sewer line and rescope to confirm the possible hole at the 11 ft mark. Any repair the rescope finds, and the cracked clean-out boot, are quoted separately	\$540
4.7.1	INTERIOR, DOORS AND SAFETY Risers - Too Tall APPRAISER MAY REQUIRE HEALTH AND SAFETY West deck: Stair risers over 7-3/4 in: rebuild steps to code	\$480
8.9.1	FIREPLACE Wood Burning - Recommend Professional Cleaning And Service HEALTH AND SAFETY Fireplace: Wood burning fireplace: chimney sweep and inspection	\$480
7.8.1	HEATING, COOLING AND GAS Outdated Gas Valve HEALTH AND SAFETY Furnace: replace the old gas shutoff with a ball valve	\$360
5.6.1	ELECTRICAL No GFCI Protection Installed APPRAISER MAY REQUIRE HEALTH AND SAFETY Kitchen, laundry: No GFCI protection: install GFCI outlets	\$324
8.7.1	ELECTRICAL Disconnect - Not Present HEALTH AND SAFETY Mechanical room: No disconnect within 6 ft of the furnace and AC: install one	\$240
11.6.1	FLOORING Flooring - Damaged (General) (4 more defect) 1st floor: replace the hard flooring with LVP, which also resolves the 5 damaged spots	\$3,120
11.6.2	FLOORING Carpet - Dirty/Stained (1 more defect) Throughout: replace the dirty and stained carpet, including the stairs; the stains and odor are from a previous tenant's cat urine, which cleaning may not fully remove	\$2,400
7.2.1	PLUMBING Outdated Valve Basement east: a licensed plumber replaces the old main water shutoff with a full-port ball valve	\$780
	ELECTRICAL PERMIT Permit, inspection and licensed sign-off City and County of Denver electrical permit and inspection, with sign-off on the electrical work by a licensed electrician	\$642
7.5.3	PLUMBING Diverter - Tub Shower Diverter Does Not Fully Engage West bedroom bath: Tub and shower diverter does not fully engage: repair or replace	\$480

REPORT ITEM	REPAIR	PRICE
<u>11.7.1</u>	INTERIOR, DOORS AND SAFETY Touchup Paint (1 more defect) Throughout: touch-up paint, caulk and minor repair on walls, ceilings and trim	\$360
<u>11.7.2</u>	INTERIOR, DOORS AND SAFETY Wall/Ceiling - Minor Cracking Living room: patch and paint minor wall and ceiling cracks	\$360
<u>11.9.2</u>	INTERIOR, DOORS AND SAFETY Cabinet - Refinish Needed Kitchen: Cabinet finish worn: refinish	\$360
<u>8.1.1</u>	HEATING, COOLING AND GAS Maintenance Note: HVAC Equipment Furnace and AC: Clean and service both units; CO and backdraft check	\$300
<u>4.5.3</u>	INTERIOR, DOORS AND SAFETY Screen (Sliding/Storm Door) - Damaged, Old Or Missing West entry: Screen door screen damaged: rescreen or replace	\$240
<u>7.5.2</u>	PLUMBING Shower - Leaking Shower Head APPRAISER MAY REQUIRE 2nd floor baths: Shower heads leak at the connection: rebuild or replace	\$240
<u>11.5.3</u>	INTERIOR, DOORS AND SAFETY Channel Rod - Stuck/Damaged Living room: Window balance rod stuck or damaged: repair	\$240
<u>4.5.1</u>	INTERIOR, DOORS AND SAFETY Weatherstripping - Damaged/Missing/Improperly Installed West and east entries: Replace damaged or missing door weatherstripping	\$180
<u>7.4.1</u>	PLUMBING Slow Draining Drain Basement bath: Slow drain: clear the line	\$180
<u>7.5.1</u>	PLUMBING Toilet - Loose At Floor East bedroom bath: Toilet loose at floor: reset with new wax ring and bolts	\$180
<u>10.8.1</u>	PLUMBING Rubber Hoses Installed Laundry: Replace rubber washer hoses with braided stainless	\$180
<u>11.9.1</u>	INTERIOR, DOORS AND SAFETY Counter - Cracked/Chipped/Delamination Kitchen: Countertop cracked, chipped or delaminating: repair	\$180
<u>11.10.1</u>	INTERIOR, DOORS AND SAFETY Shower Surround Ends Below Shower Head All baths: Shower surround stops below the head: seal and finish the wall above it	\$180
<u>4.5.2</u>	INTERIOR, DOORS AND SAFETY Door Knobs/Locks/Latches - Damaged, Malfunctioning Or Missing APPRAISER MAY REQUIRE Deck closet: Door knob or latch damaged: repair or replace	\$120
<u>11.4.1</u>	INTERIOR, DOORS AND SAFETY Sliding Door - Floor Guides/Bumpers Broken Or Missing 2nd floor: replace the broken or missing sliding closet door floor guides	\$120

REPORT ITEM	REPAIR	PRICE
11.5.1	INTERIOR, DOORS AND SAFETY Perimeter Caulking Bedrooms, living room: Touch up interior window caulking	\$120
11.7.3	INTERIOR, DOORS AND SAFETY Evidence Of Moisture - Staining - Inactive Staircase: seal and repaint the stain the inspector found inactive	\$120
	PLUMBING PERMIT Permit and inspection City and County of Denver plumbing permit and inspection, for the licensed plumber's valve work	\$51
8.8.1	HEATING, COOLING AND GAS Filter Dirty - Replace Furnace: Replace dirty air filter	\$31
8.6.1	HEATING, COOLING AND GAS Combustion Air - Dedicated Source Not Identified Same repair as 7.7.1 (the report lists it under both water heater and furnace); priced once there	<i>With 7.7.1</i>

Inspection items and sewer scope	\$15,414
Permits, inspections and licensed sign-off	\$693
TOTAL	\$16,107

TERMS

- 1. Each price covers labor and materials to complete the repair described for that report item. Each item number links to its section of the inspection report.
- 2. Included are the report items priced above, including the west deck stairs. Roof, siding, grading and landscaping maintained by the HOA are not included.
- 3. The seller pays this quote at closing through the title company. Items marked expected before closing are completed before the lender's appraisal; the remaining work is completed after closing.
- 4. Permit lines cover the City and County of Denver permit fees and inspections, and sign-off on the electrical work by a licensed electrician. The plumbing valve work is performed by a licensed plumber. The heating, cooling and gas prices include that trade's Denver mechanical permit.
- 5. Conditions concealed behind walls, floors or finishes are not included; any change to the work or price is agreed in writing before that work proceeds.
- 6. This quote is valid through October 21, 2026.

Guess Oka Member, Velocity Contracting LLC	October 4, 2026 Date
Accepted by seller, signature	Date