

REPAIR QUOTE

No. VC-169-001

PROPERTY 1811 S Quebec Way #169, Denver, CO 80231	DATE October 4, 2026
PREPARED FOR Seller, 1811 S Quebec Way #169	VALID THROUGH October 7, 2026
BASIS Alpine Building Performance home inspection, 9/30/2026	SCOPE Inspection repairs with full carpet and LVP replacement
ITEMS 34 inspection items (1 priced with another item); sewer scope	

Each item number below opens that item in the inspection report. [View the full inspection report](#)

REPORT ITEM	REPAIR	PRICE
Electrical		\$1,985
5.5.1	Loose Receptacle West bedroom: Loose outlet not secured in the box: re-secure	\$36
5.5.2	Cover Plates Missing (1 more defect) East bedroom, sump pump, attic, one more: Missing or broken cover plates: install	\$83
5.6.1	No GFCI Protection Installed Kitchen, laundry: No GFCI protection: install GFCI outlets	\$324
8.7.1	Disconnect - Not Present Mechanical room: No disconnect within 6 ft of the furnace and AC: install one	\$240
11.2.1	Safety Recommendation - Install Additional Smoke Alarms Bedrooms: add a hardwired smoke alarm in each bedroom	\$492
11.3.1	Safety Recommendation - Install Additional CO Detectors 2nd floor: add a hardwired CO alarm within 15 ft of the bedrooms	\$168
	PERMIT Permit, inspection and licensed sign-off City and County of Denver electrical permit and inspection, with sign-off on the electrical work by a licensed electrician	\$642
Plumbing		\$2,751
4.9.1	High Water Pressure - Adjust Or Install Water Pressure Regulator Main water line: a licensed plumber removes the existing pressure reducing valve, installs a new one and sets the pressure	\$660
7.2.1	Outdated Valve Basement east: a licensed plumber replaces the old main water shutoff with a full-port ball valve	\$780
7.4.1	Slow Draining Drain Basement bath: Slow drain: clear the line	\$180
7.5.1	Toilet - Loose At Floor East bedroom bath: Toilet loose at floor: reset with new wax ring and bolts	\$180
7.5.2	Shower - Leaking Shower Head 2nd floor baths: Shower heads leak at the connection: rebuild or replace	\$240
7.5.3	Diverter - Tub Shower Diverter Does Not Fully Engage West bedroom bath: Tub and shower diverter does not fully engage: repair or replace	\$480

REPORT ITEM	REPAIR	PRICE
<u>10.8.1</u>	Rubber Hoses Installed Laundry: Replace rubber washer hoses with braided stainless	\$180
	PERMIT Permit and inspection City and County of Denver plumbing permit and inspection, for the licensed plumber's valve work	\$51
Heating, cooling and gas		\$1,771
<u>7.7.1</u>	Combustion Air - Dedicated Source Not Identified Mechanical room: the inspector did not identify a dedicated combustion air source; heating and cooling trade to evaluate and correct to code	\$1,080
<u>7.8.1</u>	Outdated Gas Valve Furnace: replace the old gas shutoff with a ball valve	\$360
<u>8.1.1</u>	Maintenance Note: HVAC Equipment Furnace and AC: Clean and service both units; CO and backdraft check	\$300
<u>8.6.1</u>	Combustion Air - Dedicated Source Not Identified Same repair as 7.7.1 (the report lists it under both water heater and furnace); priced once there	<i>With 7.7.1</i>
<u>8.8.1</u>	Filter Dirty - Replace Furnace: Replace dirty air filter	\$31
Interior, doors and safety		\$10,020
<u>4.5.1</u>	Weatherstripping - Damaged/Missing/Improperly Installed West and east entries: Replace damaged or missing door weatherstripping	\$180
<u>4.5.2</u>	Door Knobs/Locks/Latches - Damaged, Malfunctioning Or Missing Deck closet: Door knob or latch damaged: repair or replace	\$120
<u>4.5.3</u>	Screen (Sliding/Storm Door) - Damaged, Old Or Missing West entry: Screen door screen damaged: rescreen or replace	\$240
<u>4.7.1</u>	Risers - Too Tall West deck: Stair risers over 7-3/4 in: rebuild steps to code	\$480
<u>11.4.1</u>	Sliding Door - Floor Guides/Bumpers Broken Or Missing 2nd floor: replace the broken or missing sliding closet door floor guides	\$120
<u>11.5.1</u>	Perimeter Caulking Bedrooms, living room: Touch up interior window caulking	\$120
<u>11.5.3</u>	Channel Rod - Stuck/Damaged Living room: Window balance rod stuck or damaged: repair	\$240
<u>11.6.1</u>	Flooring - Damaged (General) (4 more defect) 1st floor: replace the hard flooring with LVP, which also resolves the 5 damaged spots	\$4,560
<u>11.6.2</u>	Carpet - Dirty/Stained (1 more defect) Throughout: replace the dirty and stained carpet, including the stairs	\$2,400
<u>11.7.1</u>	Touchup Paint (1 more defect) Throughout: touch-up paint, caulk and minor repair on walls, ceilings and trim	\$360
<u>11.7.2</u>	Wall/Ceiling - Minor Cracking Living room: patch and paint minor wall and ceiling cracks	\$360
<u>11.7.3</u>	Evidence Of Moisture - Staining - Inactive Staircase: seal and repaint the stain the inspector found inactive	\$120
<u>11.9.1</u>	Counter - Cracked/Chipped/Delamination Kitchen: Countertop cracked, chipped or delaminating: repair	\$180

REPORT ITEM	REPAIR	PRICE
11.9.2	Cabinet - Refinish Needed Kitchen: Cabinet finish worn: refinish	\$360
11.10.1	Shower Surround Ends Below Shower Head All baths: Shower surround stops below the head: seal and finish the wall above it	\$180
Fireplace		\$960
8.9.1	Wood Burning - Recommend Professional Cleaning And Service Fireplace: Wood burning fireplace: chimney sweep and inspection	\$960
Sewer line (sewer scope, Denver Sewer Pros, 10/3/2026)		\$540
	SEWER SCOPE Sewer scope finding Descale the cast iron section of the sewer line and rescope to confirm the possible hole at the 11 ft mark. Any repair the rescope finds, and the cracked clean-out boot, are quoted separately	\$540
		Inspection items and sewer scope \$17,334 Permits, inspections and licensed sign-off \$693 TOTAL \$18,027

TERMS

- Each price covers labor and materials to complete the repair described for that report item.
Each item number links to its section of the inspection report.
- Included are the report items priced above, including the west deck stairs. Roof, siding, grading and landscaping maintained by the HOA are not included.
- Provided this quote is accepted by October 7, 2026 and permits are issued in the normal course, work will be completed before the October 21, 2026 closing.
- Permit lines cover the City and County of Denver permit fees and inspections, and sign-off on the electrical work by a licensed electrician. The plumbing valve work is performed by a licensed plumber. The heating, cooling and gas prices include that trade's Denver mechanical permit.
- Conditions concealed behind walls, floors or finishes are not included; any change to the work or price is agreed in writing before that work proceeds.
- This quote is valid through October 7, 2026.

Guess Oka Member, Velocity Contracting LLC	October 4, 2026 Date
Accepted by seller, signature	Date