

REPAIR QUOTE

No. VC-169-001A

PROPERTY 1811 S Quebec Way #169, Denver, CO 80231	DATE October 3, 2026
PREPARED FOR Seller, 1811 S Quebec Way #169	VALID THROUGH October 7, 2026
BASIS Alpine Building Performance home inspection, 9/30/2026	OPTION Option A: Full flooring replacement
SCOPE Inspection repairs with full carpet and LVP replacement	
ITEMS 34 inspection items (1 duplicate), 33 priced	

Each item number below opens that item in the inspection report. [View the full inspection report](#)

REPORT ITEM	REPAIR	PRICE
Electrical		\$1,894
5.5.1	Loose Receptacle West bedroom: Loose outlet not secured in the box: re-secure	\$36
5.5.2	Cover Plates Missing (1 more defect) East bedroom, sump pump, attic, one more: Missing or broken cover plates: install	\$83
5.6.1	No GFCI Protection Installed Kitchen, laundry: No GFCI protection: install GFCI outlets	\$324
8.7.1	Disconnect - Not Present Mechanical room: No disconnect within 6 ft of the furnace and AC: install one	\$204
11.2.1	Safety Recommendation - Install Additional Smoke Alarms Bedrooms: add a hardwired smoke alarm in each bedroom	\$456
11.3.1	Safety Recommendation - Install Additional CO Detectors 2nd floor: add a hardwired CO alarm within 15 ft of the bedrooms	\$132
	LICENSED TRADE Licensed electrician EST \$624 Sign-off on the electrical work by a licensed electrician	
	PERMIT Permit City and County of Denver electrical permit, published fee at cost	\$35
Plumbing		\$2,527
4.9.1	High Water Pressure - Adjust Or Install Water Pressure Regulator Main water line: Water pressure is high: install a pressure reducing valve, set 40 to 80 psi	\$480
7.2.1	Outdated Valve Basement east: Main water shutoff is an old gate valve: replace with a ball valve	\$240
7.4.1	Slow Draining Drain Basement bath: Slow drain: clear the line	\$180
7.5.1	Toilet - Loose At Floor East bedroom bath: Toilet loose at floor: reset with new wax ring and bolts	\$180

REPORT ITEM	REPAIR	PRICE
7.5.2	Shower - Leaking Shower Head 2nd floor baths: Shower heads leak at the connection: rebuild or replace	\$240
7.5.3	Diverter - Tub Shower Diverter Does Not Fully Engage West bedroom bath: Tub and shower diverter does not fully engage: repair or replace	\$480
10.8.1	Rubber Hoses Installed Laundry: Replace rubber washer hoses with braided stainless	\$180
	LICENSED TRADE Licensed plumber Sign-off on the plumbing work by a licensed plumber	EST \$504
	PERMIT Permit City and County of Denver plumbing permit, published fee at cost	\$43
Heating, cooling and gas		\$1,446
7.7.1	Combustion Air - Dedicated Source Not Identified Mechanical room: the inspector did not identify a dedicated combustion air source; heating and cooling trade to evaluate and correct to code	\$720
7.8.1	Outdated Gas Valve Furnace: replace the old gas shutoff with a ball valve	\$360
8.1.1	Maintenance Note: HVAC Equipment Furnace and AC: Clean and service both units; CO and backdraft check	\$300
8.6.1	Combustion Air - Dedicated Source Not Identified Same repair as 7.7.1 (the report lists it under both water heater and furnace); priced once there	<i>With 7.7.1</i>
8.8.1	Filter Dirty - Replace Furnace: Replace dirty air filter	\$31
	PERMIT Permit City and County of Denver gas and mechanical permit, published fee at cost	\$35
Interior, doors and safety		\$7,680
4.5.1	Weatherstripping - Damaged/Missing/Improperly Installed West and east entries: Replace damaged or missing door weatherstripping	\$180
4.5.2	Door Knobs/Locks/Latches - Damaged, Malfunctioning Or Missing Deck closet: Door knob or latch damaged: repair or replace	\$120
4.5.3	Screen (Sliding/Storm Door) - Damaged, Old Or Missing West entry: Screen door screen damaged: rescreen or replace	\$240
4.7.1	Risers - Too Tall West deck: Stair risers over 7-3/4 in: rebuild steps to code	\$360
11.4.1	Sliding Door - Floor Guides/Bumpers Broken Or Missing 2nd floor: replace the broken or missing sliding closet door floor guides	\$120
11.5.1	Perimeter Caulking Bedrooms, living room: Touch up interior window caulking	\$120
11.5.3	Channel Rod - Stuck/Damaged Living room: Window balance rod stuck or damaged: repair	\$240
11.6.1	Flooring - Damaged (General) (4 more defect) 1st floor: replace the hard flooring with LVP, which also resolves the 5 damaged spots	EST \$2,880
11.6.2	Carpet - Dirty/Stained (1 more defect) Throughout: replace the dirty and stained carpet, including the stairs	EST \$1,920

REPORT ITEM	REPAIR	PRICE
11.7.1	Touchup Paint (1 more defect) Throughout: touch-up paint, caulk and minor repair on walls, ceilings and trim	\$360
11.7.2	Wall/Ceiling - Minor Cracking Living room: patch and paint minor wall and ceiling cracks	\$360
11.7.3	Evidence Of Moisture - Staining - Inactive Staircase: seal and repaint the stain the inspector found inactive	\$120
11.9.1	Counter - Cracked/Chipped/Delamination Kitchen: Countertop cracked, chipped or delaminating: repair	\$120
11.9.2	Cabinet - Refinish Needed Kitchen: Cabinet finish worn: refinish	\$360
11.10.1	Shower Surround Ends Below Shower Head All baths: Shower surround stops below the head: seal and finish the wall above it	\$180
Fireplace		\$300
8.9.1	Wood Burning - Recommend Professional Cleaning And Service Fireplace: Wood burning fireplace: chimney sweep and inspection	\$300

Inspection items	33 items · \$12,606
Licensed electrician and plumber	\$1,128
Permits	\$113
TOTAL	\$13,847

TERMS

- 1. Each price covers labor and materials to complete the repair described for that report item.
Each item number links to its section of the inspection report.
- 2. Included are the report items priced above, including the west deck stairs. Roof, siding, grading and landscaping maintained by the HOA are not included.
- 3. Provided this quote is accepted by October 7, 2026 and permits are issued in the normal course, work will be completed before the October 21, 2026 closing.
- 4. Lines marked EST are carried at a trade's preliminary price and are confirmed in writing before that work begins.
- 5. Permit lines are the City and County of Denver's published trade permit fees, carried at cost. The licensed trade lines cover a licensed electrician and a licensed plumber performing or signing off on that trade's work, and are included in the total.
- 6. Conditions concealed behind walls, floors or finishes are not included; any change to the work or price is agreed in writing before that work proceeds.
- 7. This quote is valid through October 7, 2026.

Guess Oka Member, Velocity Contracting LLC	October 3, 2026 Date
---	-------------------------

Accepted by seller, signature

Date