

9-080-42-7190 -D00

Juli 26th 2006

9.3 Contour processing makros

9.3.1 Contourfraesen: Routing to a Contour elements

ID-Number: 105

```
E.g.:
<105 \Contourfraesen\
EA="1:1"
MDA="TAN"
RK="WRKL"
EE="1:2"
MDE="TAN_AB"
EM="1"
RI="1"
TNO="101"
SM="0"
S_="100"
F_="20"
AB="0"
ZA="2"
```

Erklärung:

EA : Number of start elements
MDA : Start mode
TAN =0: tangential
SEI =1: from side
SEN =2: vertical
or self defined start mode
RK : Radius correction:
NOWRK =0: Tool runs on programmed line
WRKL =1: Tool runs left of programmed line
WRKR =2: Tool runs right of programmed line
EE : Number of end element
MDE : Start mode
TAN_AB =0: tangential
SEI_AB =1: from side
SEN_AB =2: vertical
or self defined start mode
MD : Self defined mill mode
EM : Insert mode
0: vertical dive
1: inserting in the move
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: not forward, i.e. conter drawing direction of contour element
TNO : T-Number (toolnumber)
SM : Revolution mode
0: revolutions in percent
1: in RPM
S_ : Revolutions in percent
S_A : Revolutions in RPM
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

AB : Distance from programmed contour. If distance is negative ist, material will be milled away.
AF : approach distance
ZA : Start coordinate in Z
?? : condition (default=1)
EN : Enable (default=1)
VLS : Extension at startpoint
VLE : Extension at endpoint
STUFEN : routing by steps (default = 0)
ZSTART : Z-Start routing by steps
ANZZST : stepcount for routing by steps
OSZVS : feed for oscillating routing
OSZI : enable oscillating routing yes/no (default : 0)

9.3.2 Contourverleimen: Edgebanding at Contour Element

ID-number: 106

E.g.:
<106 \Contourverleimen\
EA="1:0"
EE="1:1"
P59="1"
AB="0"
P60="0"
WS="3"
F_="5"
DZ="0"
S_="45"
S_="0"
TL="1"
M15="1"
NM="STANDARD"
KM="PVC-Kante 2mm"
KN="32"
KZ="20"
DK="0"
KA="110"
LA="0"
SV="0"
SE="0"
ABN="20"
RI="1"
ABV="30"
ABA="5"
VA="2"
ABT="60"
FK="2"
TB="30"
SK="2"
RSP="1"
AC="1"
SL="100"
SA="10"
CF="5"
??=" _nonmirror"



PRODUCT INFORMATION

Subject : 4.2.7

Description woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

Explanation

EA	:	Number of start elements
EE	:	Number of end elements
P59	:	Edge (choosing edge channel)
AB	:	Distance from programmed contour. If distance is negative, more pressure will be given to work piece.
Z_	:	Z-value (optional) (default=0)
P60	:	C-angle
WS	:	Maintanance time
F_	:	Feedrate
DZ	:	define revolution speed relative (default: 0, must be defined prior to S_ and S_P)
S_	:	revolution speed (must be „0“ if DZ=1)
S_P	:	revolution speed (must be „0“ if DZ=0)
TL	:	Test run (without edge)
		0: no test run
		1: test run, e.g. without edge material and glue
M15	:	Test run (without M15 i.e. over work piece)
NM	:	Name of gluing parameter file
KM	:	Comment
VM	:	Gluing makro (Art of gluing unit) – up to WoodWOP-Build 556
KN	:	Art of gluing unit – WoodWOP-Build 556 or greater
MD	:	Self defined mode – WoodWOP-Build 556 or greater
TNO	:	T-Number (tool number)
HL	:	Heat power in %
HL2	:	Heat power 2 in %
KZ	:	Edge material adding
KB	:	time for edge supply
AV	:	distance of glueingdevice (lop point)
DK	:	Thickness of edge
LA	:	Slow pull out
SV	:	Bulb pre snip station
SE	:	Bulb gluing station
ABN	:	Distance post press roller on
RI	:	Direction of processing
		1: forward, i.e. in drawing direction of contour element
		0: conter forward i.e. against drawing direction of contour element
ABV	:	Distance edge transport
ABA	:	Distance post press roller off
	:	KA : Snipdistance from end only in conjunction with NC-Generator-Option „edge material grouping“)
VA	:	Waiting time post press roller
ABT	:	Distance , drive way-sensor
FK	:	Feedrate sensoring
TB	:	Sensor area, slow way
SK	:	Joint correction
KS	:	Swing snipping saw
SVK	:	Pre snipping station with bulb
RV	:	Banding around, i.e. Joint at not cosed contour (optional) (default=0)
RSP	:	Turnung of gluing station to start point
		1: clockwise
		0: conter clockwise
		Ist parameter not declarated, the minimum turning of gluing station will be calculatedt.
AC	:	Automatic correction of the C-Offset (collision test)
		1: ON
		0: OFF
SL	:	Splitting length: Length for the splitting of the contour
SA	:	Safety distance for the collision test.



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

CF : C-Korrekturwinkel:
?? : condition (*default=1*)
EN : Enable (*default=1*)
SCA : Specify Glueing section with swivel arm for portal machines

9.3.3 Stegkante: T-molding

ID-number: 136

E.g.:
<106 \Stegkante\
EA="1:0"
EE="1:1"
P59="1"
AB="0"
P60="0"
WS="3"
KA="0"
RK="WRKL"
F_="5"
S_="45"
TL="1"
M15="1"
NM="STANDARD"
KM="PVCKante 2mm"
VM="27"
LA="1"
KZ="20"
ABN="20"
RI="1"
ABV="30"
ABA="5"
VA="2"
ABT="60"
KSE="250"
KSF="3.5"
ARA="200"
ARE="60"
APR="300"
FK="2"
TB="30"
SK="2"
RSP="1"
AC="1"
SL="100"
SA="10"
CF="5"
??=" _nonmirror"

Explanation:

EA : Number of start elements
EE : Number of end elements
P59 : Edge (choosing edge channel)
AB : Distance from programmed contour. If distance is negative, more pressure will be given to work piece.
Z_ : Z-value (optional) (*default=0*)
P60 : C-angle
WS : Maintenance time

9-080-42-7190 -D00

Juli 26th 2006

F_ : Feedrate
S_ : Revolutions
TL : Test run (without edge)
0: no test run
1: test run, e.g. without edge material and glue
M15 : Test run (without M15 i.e. over work piece)
NM : Name of gluing parameter file
KA : With glue apply
LA : Slow pull out
RK : Processing side (WRKL = Left, WRKR = Right)
KM : Comment
VM : Makro (art of units)
TNO : T-Number (tool number)
KZ : Edge material addition
ABN : Distance pre pressure roll on
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward i.e. against drawing direction of contour element
ABV : Distance edge transport
ABA : Distance post press roller off
KA : Snipdistance from end only in conjunction with NC-Generator-Option „edge material grouping“)
VA : Waiting time post press roller
ABT : Distance , drive way-sensor
FK : Feedrate sensing
TB : Sensor area, slow way
SK : Joint correction
KS : Swing snipping saw
KA : With/without glue application
KSE : Distance glue on
KSF : Feedrate while glue application
ARA : Distance pressure roll off
ARE : Distance pressure roll on
APR : Distance post pressing
RV : Banding around, i.e. Joint at not cosed contour (optional) (default=0)
RSP : Turning of gluing station to start point
1: clockwise
0: conter clockwise
Ist parameter not declarated, the minimum turning of gluing station will be calculatedt.
AC : Automatic correction of the C-Offset (collision test)
1: ON
0: OFF
SL : Splitting length: Length for the splitting of the contour
SA : Safety distance for the collision test.
CF : C-Korrekturwinkel:
?? : condition (default=1)
EN : Enable (default=1)
AI : Unit with Interface (default=1)
BP : approach feed position (default=0)

9.3.4 Buendigfraesen: Flush Trimming

ID-number: 107

E.g.:
<107 \Buendigfraesen\
EA="1:1"

9-080-42-7190 -D00

Juli 26th 2006

```
EE="1:5"
AG="110"
RI="1"
AB="2"
P60="12"
F_="STANDARD"
MD="LI"
AC="1"
KU="0"
SL="100"
SA="10"
CF="5"
??="_nonmirror"
```

Explanation:

EA : Number of start elements
 EE : Number of end elements
 AG : Unit
 RI : Direction of processing
 1: forward i.e. in drawing direction of contour element
 0: counter forward, i.e. against drawing direction of contour element
 AB : Distance from programmed contour. If distance is negative, more pressure will be given to work piece.
 P60 : Offset C-axis
 F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
 By STANDARD the Feedrate of the Tooldata will be used (default).
 MD : Mode
 LI =0: Tool runs left
 RE =1: Tool runs right
 MOD : Modus (selfdefined start sub program)
 Z_ : Z-coordinate
 AC : Automatic correction of the C-Offset (collision test)
 1: ON
 0: OFF
 KU : finish by grinding yes(1) / no(0) (default=0)
 SL : Splitting length: Length for the splitting of the contour
 SA : Safety distance for the collision test.
 S_ : Revolutions
 ?? : condition (default=1)
 EN : Enable (default=1)

9.3.5 Kappen: End Trimming

ID-number: 108

E.g.:
 <108 \Kappen\
 EA="1:1"
 EE="1:1"
 P60="0"
 P61="0"
 P62="1"
 RI="1"
 ABV="0"
 ABH="0"
 VH="1"
 VK="1"

9-080-42-7190 -D00

Juli 26th 2006

HK="1"
RK="1"

Explanation

EA : Number of start element (front edge)
 EE : Number of end element (back edge)
 P60 : Offset C-Axis front edge
 (positiv=away from work piece, negativ=to work piece)
 F_ : Feedrate
 S_ : Revolutions
 P61 : Offset C-Axis back edge
 (positiv=away from work piece, negativ=to work piece)
 P62 : Offset C-Axis (free cut angle e.g. 1)
 RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward i.e. against drawing direction of contour element
 ABV : Distance edge transport
 (positiv=away from work piece, negativ=to work piece)
 ABH : Distance from programmed contour point back edge
 (positiv=away from work piece, negativ=to work piece)
 VH : =1 -> front edge before back edge
 =0 -> back edge before front edge
 VK : snipping front edge yes/no (1/0)
 HK : snipping back edge yes/no (1/0)
 MD : Mode
 T_ : Tool (optional)
 RK : Edge side (optional)
 1=Left
 2=Right
 ?? : condition (default=1)
 EN : Enable (default=1)

9.3.6 Klink: Corner notching

ID-number: 127

E.g.:
 <127 \Klink\
 EA="1:1"
 P60="0"
 ABV="0"
 AEV="0"
 MD="MOD0"

Explanation:

EA : Number of start elements
 P60 : Offset C-Axis VK
 P61 : Offset C-Axis HK
 ABV : Distance element VK
 AEV : Distance edge VK
 ABH : Distance element HK
 AEH : Distance edge HK
 MD : nodging mode
 MOD0: double side nodging VK and HK
 MOD1: nodging only VK
 MOD2: nodging only HK



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

MOD : Self defined mode (optional)
RK : Tool radius correction LI=left RE=right
TNO : Unit (optional)
?? : condition (default=1)
EN : Enable (default=1)

9.3.7 Schleifen: Contour Sanding

ID-number: 125

E.g.:
<125 \Schleifen\
EA="1:1"
MDA="TAN"
RK="WRKL"
EE="1:5"
MDE="TAN_AB"
RI="1"
TNO="101"
SM="0"
S_="STANDARD"
F_="STANDARD"
AB="0"
P60="0"
ZA="0"

Explanation:

EA : Number of start elements
MD : Mode
MDA : Start mode
 TAN =0: tangential
 SEI =1: from side
 SEN =2: vertical
 or self defined start mode
RK : radius correction:
 NOWRK =0: Tool runs on programmed line
 WRKL =1: Tool runs left of programmed line
 WRKR =2: Tool runs right of programmed line
EE : Number of end element
MDE : Start mode
 TAN_AB =0: tangential
 SEI_AB =1: from side
 SEN_AB =2: horizontal
 or self defined start mode
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: counter forward i.e. against drawing direction of contour element
TNO : T-Number (Toolnumber)
EM : Insert mode
SM : Revolution mode
 0: revolutions in Prozent
 1: R.P.M.
S_ : Revolutions
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
 By STANDARD the Feedrate of the Tooldata will be used (default).
AB : Distance to programmed contour. If distance is negative material will be sanded away.
P60 : C-Angle

9-080-42-7190 -D00

Juli 26th 2006

ZA : Start coordinate in Z
OSZVS : feed for oscillating routing
OSZI : enable oscillating routing yes/no (default : 0)
?? : condition (default=1)
EN : Enable (default=1)

9.3.8 Drucken: Pressure Zone at a Contour

ID-number: 134

E.g.:
<134 \Drucken\
EA="1:0"
RK="WRKL"
EE="1:1"
RI="1"
F_="5"
AB="30"
AS="0"
AN="30"
TI="10"
HL="10"
HO="0"

Explanation:

EA : Number of start elements
EE : Number of end elements
RK : radius correction:
 NOWRK =0: Tool runs on programmed line
 WRKL =1: Tool runs left of programmed line
 WRKR =2: Tool runs right of programmed line
TNO : T-Number (tool number)
MOD : Self defined mode
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward, i.e. against drawing direction of contour element
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).
AS : Distance from programmed contour.
AN : Start distance
AB : Stop distance
TI : Pre heat time (in seconds)
HO : Hights (Z-coordinate, measured from Z=0)
HL : Heating power
?? : condition (default=1)
EN : Enable (default=1)

9.3.9 Ritzen: Processing of an Edge at Door Rabbit Prozzessing r

ID-number: 138

E.g.:
<138 \Ritzen\
EA="1:0"
RK="WRKL"
EE="1:1"
RI="1"



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

F_="5"
FB="30"
SB="10"
TV="0"
MD="VKANDHKSLOTTING"
MX="0"
MY="0"
MZ="0"

Explanation:

EA : Number of start element
EE : Number of end element
RK : radius correction:
 NOWRK =0: Tool runs on programmed line
 WRKL =1: Tool runs left of programmed line
 WRKR =2: Tool runs right of programmed line
TNO : T-Number (tool number)
MOD : Self defined mode
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward, i.e. against drawing direction of contour element
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).
FB : Distance von of programmierten Contour.
SB : Area
TV : Groove hight
?? : condition (default=1)
EN : Enable (default=1)

9.3.10 Horizontales Fraesen: Contour Element

ID-number: 133

E.g.:
<133 \Contourfraesen\
EA="1:0"
MDA="TAN"
RK="WRKL"
EE="1:1"
MDE="TAN_AB"
EM="0"
RI="1"
TNO="156"
SM="0"
S_="STANDARD"
F_="5"3
AB="0"
ZM="0"

Explanation:

EA : Number of start element
MDA : Start mode

9-080-42-7190 -D00

Juli 26th 2006

TAN =0: tangential
SEI =1: from side
SEN =2: vertical
or self defined start mode

RK : radius correction:
NOWRK =0: Tool runs on programmed line
WRKL =1: Tool runs left of programmed line
WRKR =2: Tool runs right of programmed line

EE : Number of end element
MD : Self defined mill mode
MDE : Start mode
TAN_AB =0: tangential
SEI_AB =1: from side
SEN_AB =2: horizontal
or self defined start mode

EM : Inserting mode
0: vertical diving
1: dive in the move

RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: counter forward, i.e. against drawing direction of contour element

TNO : T-Number (tool number)
SM : Revolution mode
0: revolutions in Prozent
1: R.P.M.

S_ : Revolutions
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD the Feedrate of the Tooldata will be used (*default*).

AB : Distance to programmed contour. If distance is negative material will be sanded away.
ZM : Z-Mass
XY : Side X/Y. If Horizontal milling will be used to a contour element in of XY-Level
C_ : C-value (If Tool not vertical to XY-level of macro coordinate system)
A_ : A-value (If Tool not vertical to XY-level of macro coordinate system)
KO : Coordinate system (normally horizontal coordinate system A0,A1,...D3, see default coordinate system)

AN : Start distance (optional)
ABT : Stop distance (optional)
?? : condition (*default=1*)
EN : Enable (*default=1*)

9.3.11 Vektor Fraesen: 5-Axis Routing

ID-number: 140

E.g.:
<140 \Vektorfraesen\
EA="1:0"
MDA="TAN"
RK="WRKL"
EE="1:1"
MDE="TAN_AB"
EM="0"
RI="1"
TNO="156"
SM="0"
S_="STANDARD"
F_="5"

9-080-42-7190 -D00

Juli 26th 2006

AB="0"
ZM="0"

Explanation:

EA : Number of start element
MDA : Start mode
 TAN =0: tangential
 SEI =1: from side
 SEN =2: vertical
 or self defined start mode
RK : radius correction:
 NOWRK =0: Tool runs on programmed line
 WRKL =1: Tool runs left of programmed line
 WRKR =2: Tool runs right of programmed line
EE : Number of end element
MD : Self defined mill mode
MDE : Start mode
 TAN_AB =0: tangential
 SEI_AB =1: from side
 SEN_AB =2: horizontal
 or self defined start mode
EM : Inserting mode
 0: vertival diving
 1: dive in the move
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward, i.e. against drawing direction of contour element
TNO : T-Number (tool number)

SM : Revolution mode
 0: revolutions in Prozent
 1: R.P.M.

S_ : Revolutions
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (*default*).

AB : Distance to programmed contour. If distance is negative material will be sanded away.
ZM : Z-Mass
XY : Side X/Y. If Horizontal milling will be used to a contour element in of XY-Level
C_ : C-value (If Tool not vertical to XY-level of macro coordinate system)
A_ : A-value (If Tool not vertical to XY-level of macro coordinate system)
KO : Coordinate system (normally horizontal coordinate system A0,A1,...D3, see
default coordinate system)
?? : condition (*default=1*)
EN : Enable (*default=1*)
CR : C-value relative to contour (*default=0*)
KG : smooth contour
MB : maximum track deviation (or maximum track error)
AS : skip record length smaller than [value]
MW : maximum angular deviation
AW : skip angular movements smaller than [value]

9.3.12 Unterflurfräsen : Routing from below

ID-number: 113

E.g.:



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

```
<113 \Unterflur-Fraesen\  
EA="1:1"  
RK="WRKL"  
EE="1:5"  
MDE="TAN_AB"  
RI="1"  
TNO="101"  
SM="0"  
S_="STANDARD"  
F_="STANDARD"  
WI="0"  
AN="30"  
AB="30"  
ZA="3"
```

Explanation:

EA : Number of start element
MDA : Start mode
 TAN =0: tangential
 SEI =1: from side
 SEN =2: vertical
 or self defined start mode
RK : radius correction:
 NOWRK =0: Tool runs on programmed line
 WRKL =1: Tool runs left of programmed line
 WRKR =2: Tool runs right of programmed line
EE : Number of end element
MD : Self defined mill mode
MDE : Start mode
 TAN_AB =0: tangential
 SEI_AB =1: from side
 SEN_AB =2: horizontal
 or self defined start mode
EM : Inserting mode
 0: vertical diving
 1: dive in the move
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: counter forward, i.e. against drawing direction of contour element
TNO : T-Number (tool number)
SM : Revolution mode
 0: revolutions in Prozent
 1: R.P.M.
S_ : Revolutions
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
 By STANDARD the Feedrate of the Tooldata will be used (default).
AB : Distance to programmed contour. If distance is negative material will be sanded away.
ZM : Z-Mass
XY : Side X/Y. If Horizontal milling will be used to a contour element in of XY-Level
C_ : C-value (If Tool not vertical to XY-level of macro coordinate system)
A_ : A-value (If Tool not vertical to XY-level of macro coordinate system)
ABS : Distance from the contour
KO : Coordinate system (normally horizontal coordinate system A0,A1,...D3, see
 default coordinate system)
?? : condition (default=1)

9-080-42-7190 -D00

Juli 26th 2006

EN : Enable (default=1)

9.3.13 Vert Getastet-Fraesen: Vertical Touched Routing

ID-number: 128

E.g.:

```
<128 \Vert Getastet-Fraesen\
EA="1:0"
MDA="TAN"
RK="WRKL"
EE="1:1"
MDE="TAN_AB"
RI="1"
TNO="230"
EM="MOD0"
S_="100"
F_="5"
WI="90"
AB="0"
ZA="19"
TH="2"
TM="0"
_CM="1"
CM="1"
HP="1"
SP="3"
YVE="1000"
MX="1"
MY="0"
MZ="0"
ZUA="0"
ZU="5"
VLS="10"
VLE="10"
```

Explanation:

EA : Number of start element
MDA : Start mode
TAN =0: tangential
SEI =1: from side
SEN =2: vertical
or self defined start mode
RK : radius correction:
NOWRK =0: Tool runs on programmed line
WRKL =1: Tool runs left of programmed line
WRKR =2: Tool runs right of programmed line
EE : Number of end element
MDE : Start mode
TAN_AB =0: tangential
SEI_AB =1: from side
SEN_AB =2: horizontal
or self defined start mode
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element

9-080-42-7190 -D00

Juli 26th 2006

0: conter forward, i.e. against drawing direction of contour element

TNO : T-Number (tool number)

EM : Insert mode

MOD0 =0: groove has at start and end-coordinates full depth

MOD1 =1: groove starts at start and end coordinates

S_ : Revolutions

F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).

WI : C-angle

AB : Distance from programmed contour.

ZA : Z-value touching

ZWZ : Z-value routing or

TH : touch lift

CM : C-value mode

0: as offset

1: absolut

FL : dive in mode

AB : approach distance

_CM : CNew mode

TM : Test Mode, i.e. span touching

MD : Mode

ZUA : Feed adjust Z enable (0/1 default=0)

ZU : Feed adjust Z value (feed)

VLS : Extension at startpoint

VLE : Extension at endpoint

?? : condition (default=1)

EN : Enable (default=1)

9.3.14 Abblasen: Blow Cleaning of Contour

ID-number: 126

E.g.:

```
<126 \Abblasen\
EA="1:1"
RK="WRKL"
EE="1:5"
RI="1"
F_="STANDARD"
AB="0"
P60="0"
ZA="0"
```

Explanation:

EA : Number of start element

RK : radius correction:

NOWRK =0: Tool runs on programmed line

WRKL =1: Tool runs left of programmed line

WRKR =2: Tool runs right of programmed line

EE : Number of end element

RI : Direction of processing

1: forward, i.e. in drawing direction of contour element

0: conter forward, i.e. against drawing direction of contour element

TNO : T-Number (tool number)

F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).

AB : Distance from programmed contour.

9-080-42-7190 -D00

Juli 26th 2006

P60 : C-Angle
ZA : Start coordinate in Z
?? : condition (*default=1*)
EN : Enable (*default=1*)

9.3.15 Laser-Anzeige: Showing Contour by Laser

ID-number: 154

E.g.:
<154 \Laser-Anzeige\
EA="1:1"
RK="WRKL"
EE="1:5"
RI="1"
F_="STANDARD"
ZY="1"
NR="1"

Explanation:

EA : Number of start element
EE : Number of ende elements
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward, i.e. against drawing direction of contour element
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (*default*).
ZY : Number of Zycles (only reticule laser)
NR : Laser Number
?? : condition (*default=1*)
EN : Enable (*default=1*)

9.3.16 NC-New: Discharge Macros (outdated)

For changing of technology values. With a NC-New-Makro there can also be changed several technology values together like feedrate and revolution.

ID-number: 118

E.g.:
<118 \NCNew\
FF=32
EA="1:1"
F_="10"
S_="80"

Explanation:

FF : Funktion sflag (always 32)
EA : Number of refer element
Z_ : New value for Z-axis
F_ : New value for feedrate
M_ : New M-funktion
S_ : New value for evolution
C_ : New value for C-axis
A_ : New value for A-axis
G_ : New G-funktion
NC_ : New NC-sentence
HL : New heat power

9-080-42-7190 -D00

Juli 26th 2006

HL2 : New heat power 2
 ?? : condition (default=1)
 EN : Enable (default=1)
 DS_TYPn (n =1..10): Type of Discharge, see below for details
 DS_WERn (n =1..10): Value of Discharge Type (1 to 10)
 DS_STRn (n =1..10): distance of Discharge Type (1 to10)
 Discharge Type:: Variables DS_TYP1 to DS_TYP10 can be assigned one of eleven possible values, their meanings are::

- 1: New value for feedrate
- 2: New value for C-axis
- 3: New value for evolution
- 4: New value for Z-axis
- 5: New M-function
- 6: New G-function
- 7: New NC-sentence
- 8: New value for A-axis
- 9: New heat power
- 10: New heat power 2
- 11: Edge Sanding Length (%)

9.3.16 Technology Macro: Discharge Macros

Modify Technology Paramters. Several (up to 16) parameters like feed or c-axis can be changed at a time.
 ID-Number: 180

```
Example.:
<180 \Neustr\
FF=32
EA="1:2"
EE="1:3"
DS_TYP1="1"
DS_WER1="12"
DS_OR1="3"
DS_STR1="0"
DS_TYP2="2"
DS_WER2="-45"
DS_OR2="2"
DS_STR2="0"
KM="This is a Comment"
AU="0"
FN=""
```

Explanation:

FF : Function-flag (always 32)
 EA : Number of reference element (start element)
 EE : Number of reference element (end element)
 KM : comment (string)
 AU : macro was generated automatically (value=1) or entered manually (value=0)
 FN : filename (only set if macro was loaded from or saved to a file)
 DS_TYPn: (n =1..16) Type of Discharge, see below for details
 DS_WERn: (n =1..16) Value of Discharge Type
 DS_ORn: (n =1..16) Discharge type valid at start (value=2)- or end (value=3)- point
 DS_STRn: (n =1..16) distance of Discharge Type

Discharge Type: Variables DS_TYP1 to DS_TYP10 can be assigned one of eleven possible values:

1: New value for feedrate



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

- 2: New value for C-axis
- 3: New value for evolution
- 4: New value for Z-axis
- 5: New M-function
- 6: New G-function
- 7: New NC-Set
- 8: New value for A-axis
- 9: New heat power
- 10: New heat power 2
- 11: Edge Sanding Length (relative)

9.3.17 Ablauf: Run Macro (Sequence Macro)

Allows the grouping of several contour processes to one run. Application: Rabbet with several tools, complets edge processing . All processes in the run macro

- Relates to start and end point of run macro
- Will be calculated with the condition of the run macro (AND-link)
- And will be switched off with the run macro (Reminder: Space button puts processing to comment)

Run macros can be saved and loaded. Files withnsaved run macros have the extension **.abl**.

ID-number: 122

E.g.:
<122 \Ablto\
EA="1:1"
EE="1:5"
RI="1"
NM="profil1.abl"
DP="2"

Explanation

EA : Number of Startelements (Vorofkante)
EE : Number of Endelements (Hinterkante)
RI : Direction of Processing
1: vorwärts, i.e. in Zeichnungsdirection of Contour elementses
0: nicht vorwärts, i.e. gegen Zeichnungsdirection of Contour elementses
NM : Name of Abltomakros (Filename falls Ablto of a File geladen wurde)
DP : Dependent, i.e. Number abhängiger Makros im Ablto
?? : condition (default=1)
EN : Enable (default=1)

9.3.18 Contour routing with C-Axis

ID-number: 149

E.g.:
<149 \Contourfraesen mit C-Achse\
EA="1:0"
MDA="TAN"
RK="WRKL"
EE="1:1"
MDE="TAN_AB"
EM="0"
RI="1"
TNO="101"



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

C_="0"
SM="0"
S_="STANDARD"
F_="5"
AB="0"
ZA="-3"
HP="0"
SP="0"
YVE="0"
MX="0"
MY="0"
MZ="0"

Explanation:

EA : Number of Startelements (Vorofkante)
MDA : Start mode
 TAN =0: tangential
 SEI =1: from side
 SEN =2: vertical
 or self defined start mode
RK : radius correction:
 NOWRK =0: Tool runs on programmed line
 WRKL =1: Tool runs left of programmed line
 WRKR =2: Tool runs right of programmed line
EE : Number of end element
MD : Self defined router mode
MDE : Start mode
 TAN_AB =0: tangential
 SEI_AB =1: from side
 SEN_AB =2: horizontal
 or self defined start mode
SM : Revolution mode
 0: revolutions in Prozent
 1: R.P.M.
EM : Insert mode
 0: horizontal dive
 1: dive in move
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward, i.e. against drawing direction of contour element
TNO : T-Number (toolnumber)
C_ : C-value
S_ : Evolutions
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).
AB : Distance from programmed contour.
VLS : Extension at startpoint
VLE : Extension at endpoint
OSZVS : feed for oscillating routing
OSZI : enable oscillating routing yes/no (default : 0)
ZA : Start coordinate in Z
?? : condition (default=1)
EN : Enable (default=1)

9-080-42-7190 -D00

Juli 26th 2006

9.3.19 Routing with a FK-Unit

ID-Number: 161

Bsp.:
<161 \ FK-Fraesen\
EA=""
RK="WRKL"
VK="0"
HK="1"
EE=""
RI="1"
TNO="1"
F_="10"
EL="-20"

EA : Number of Startelements (Vorofkante)
EE : Number of end element
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward, i.e. against drawing direction of contour element
RK : radius correction:
NOWRK =0: Tool runs on programmed line
WRKL =1: Tool runs left of programmed line
WRKR =2: Tool runs right of programmed line
AB : Distance from programmed contour.
TNO : T-Number (toolnumber)
F_ : Feedrate: contains either the concrete value in m/min or the key word STANDARD.
By STANDARD theFeedrate of the Tooldatas will be used (default).
EL : Distance
?? : condition (default=1)
EN : Enable (default=1)

9.3.20 Routing with a CF-Unit

ID-Number: 158

Bsp.:
<158 \CF-Fraesen\
EA="1:0"
EE="1:9"
BK="0"
RI="1"
TNO="101"
AB="0"
FS="10"

EA : Number of Startelements (Vorofkante)
EE : Number of end element
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward, i.e. against drawing direction of contour element
AB : Distance from programmed contour.
TNO : T-Number (toolnumber)
?? : condition (default=1)
EN : Enable (default=1)
FS : Cuting feed



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

9.3.21 Gluing with a CF-Unit

ID-Number: 159

Bsp.:
<159 \CF-Leimen\
NM="STANDARD"
KM="PVC-Kante 2mm REHAU"
EA="1:0"
EE="1:9"
BK="0"
DK="0"
RI="1"
TNO="101"
AB="0"
C_="10"
KZ="10"
KUH="0"
KUV="0"
KTA="10"
STR="10"
AC="0"
WA="0"

EA : Number of Startelements (Vorofkante)
EE : Number of end element
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward, i.e. against drawing direction of contour element
AB : Distance from programmed contour.
TNO : T-Number (toolnumber)
?? : condition (default=1)
EN : Enable (default=1)
BK : Definition edge (0: begin of edge , 1: end of edge)
DK : Thick edge (0: no, 1: Yes)
C_ : C-angle
KZ : Kantenlängezugabe
KUH : Kantenueberstand vorne
KUB : Kantenueberstand hinten
KTA : Kantentransport aus
STR : Strahler
AC : Automatic correction of the C-Offset (collision test)
1: ON
0: OFF
SL : Splitting length: Length for the splitting of the contour
SA : Safety distance for the collision test.

9.3.22 Flush trimming with a CF-Unit

ID-Number: 157

Bsp.:
<157 \CF-Buendigfraesen\
EA=""
EE=""
BK="0"
RI="1"

9-080-42-7190 -D00

Juli 26th 2006

```
TNO="101"
AB="0"
C_="10"
TT="10"
SLQ="10"
AC="0"
TS="0"
```

EA : Number of Startelements (Vorofkante)
 EE : Number of end element
 RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward, i.e. against drawing direction of contour element
 AB : Distance from programmed contour.
 TNO : T-Number (toolnumber)
 BK : Definition edge (0: begin, 1: end)
 C_ : C-angle
 CF : C- correction angle
 TT : touch depth
 SLQ : Splitting length for quality
 TS : With touch(1: Yes, 0: No)
 ?? : condition (default=1)
 EN : Enable (default=1)

9.3.23 Pressure with a CF-Unit

ID-Nummer: 165

```
Bsp.:
<165 \CF-Druck\
EA=""
EE=""
RI="1"
TNO="101"
AB="0"
HO="10"
```

EA : Number of Startelements (Vorofkante)
 EE : Number of end element
 RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: conter forward, i.e. against drawing direction of contour element
 AB : Distance from programmed contour.
 TNO : T-Number (toolnumber)
 ?? : condition (default=1)
 EN : Enable (default=1)
 HO : Height

9.3.24 Cutting with a CF-Unit

ID-Nummer: 166

```
Bsp.:
<166 \CF-Kappen\
EA="1:0"
EE="1:9"
RI="1"
```



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

TNO="101"
AB="0"
C_="0"
HF="1"
VF="1"
HK="1"
VK="1"

EA : Number of Startelements (Vorofkante)
EE : Number of end element
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward, i.e. against drawing direction of contour element
AB : Distance from programmed contour. (Begin)
C_ : Distance from programmed contour. (end)
TNO : T-Number (toolnumber)
HK : end
VK : begin
HF : Hinterkante kappen mit Faseanschlag
VF : Vordererkante kappen mit Faseanschlag
?? : condition (default=1)
EN : Enable (default=1)

9.3.25 Sanding with a CF-Unit

ID-Nummer: 167

Bsp.:
<167 \CF-Schleifen\
EA="1:0"
EE="1:9"
RI="1"
TNO="101"
AB="0"
S_="10"

Erklärung:

EA : Number of Startelements (Vorofkante)
EE : Number of end element
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward, i.e. against drawing direction of contour element
AB : Distance from programmed contour.
TNO : T-Number (toolnumber)
S_ : Rotation
?? : condition (default=1)
EN : Enable (default=1)

9.3.26 Contur operation with a CF-Unit

ID-Nummer: 170

Bsp.:
<170 \CF-KTRStation\
EA="1:0"
EE="1:9"
RI="1"

9-080-42-7190 -D00

Juli 26th 2006

TNO="101"
AB="0"

EA : Number of Startelements (Vorofkante)
EE : Number of end element
RI : Direction of processing
 1: forward, i.e. in drawing direction of contour element
 0: counter forward, i.e. against drawing direction of contour element
AB : Distance from programmed contour.
TNO : T-Number (toolnumber)
?? : condition (default=1)
EN : Enable (default=1)

9.3.27 Operation without contour with a CF-Unit

ID-Number: 169

Bsp.:
<169 \CF-Station\
SNO="101"

EA : Number of Startelements (Vorofkante)
SNO : Station-Number (toolnumber)
?? : condition (default=1)
EN : Enable (default=1)

9.3.28 Foiling (Heissprägen)

ID-Number: 135

E.g.:
<135 \Heisspraegen \
EA="1:0"
EE="1:1"
AB="-0.5"
Z_="1"
P60="0"
SLS="1001"
WSA="1754"
ZPE="0.3"
F_="5"
S_="50"
M15="1"
NM="STANDARD"
KM="Kante"
VM="180"
KN="180"
TNO="STANDARD"
ABN="90"
RI="1"
ABA="90"
ST="1"
AC="0"
SL="50"
SA="2"



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

```
CF="5"  
??="_nonmirror AND _nonymirror "  
MX="0"  
MY="0"  
MZ="0"  
MXF="1"  
MYF="1"  
MZF="1"  
HP="0"  
SP="0"  
YVE="0"  
WW=""  
ASG="2"  
RSEL="0"  
RWID="0"
```

Explanation:

EA : Number of start elements
EE : Number of end element
AB : Distance
Z_ : Z-value (optional) (*default=0*)
P60 : OffsetC
SLS : Heating
WSA : Backw. Dist. Heat lamp off
advice: parameter WSA and ZPE are permuted, this behaviour was never changed due to compatibility reasons
ZPE : Delay Embossing Roll On
F_ : Feed
S_ : Speed
M15 : Test run (without M15 i.e. over work piece)
NM : parameter-file name
KM : comment for parameter-file
VM : macro name
KN : ID
TNO : Tool
ABN : Dist. Swinging bolt on
ABA : Withdrawal Clearing
?? : condition (*default=1*)
EN : Enable (default : 1)
RI : Direction (1=In, 2= Out)
ST : Heating Lamp On
AC : AutoCorrect
SL : Splitting length: Length for the splitting of the contour
CF : CFactor
SA : Safety distance
HL : heating power

9-080-42-7190 -D00

Juli 26th 2006

9.4 Konsolen und Saugermacros: Vacuum Cup Macros

9.4.1 Single-Vacuum-Cup

ID-number: 114

E.g.:
<114 \Sauger\
XA="300"
YA="B-70"
WI="45"
TY="0"

Explanation

XA : X-position of cup center
YA : Y-position of cup center
WI : Turn angle of cups
TY : Typ of cups (0 bis 19)
KO : Coordinate system
?? : condition (default=1)
EN : Enable (default=1)

9.4.2 SaugerK: Vaccum cups (parallel to Y-Axis)

ID-number: 115

E.g.:
<115 \SaugerK\
XA="0"
AN="1"
YA1="0"
YA2="0"
YA3="0"
YA4="0"
YA5="0"
YA6="0"
YA7="0"
YA8="0"
WI1="0"
WI2="0"
WI3="0"
WI4="0"
WI5="0"
WI6="0"
WI7="0"
WI8="0"
TY1="0"
TY2="0"
TY3="0"
TY4="0"
TY5="0"
TY6="0"
TY7="0"
TY8="0"



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

Explanation:

XA : X coordinate of console
AN : Number of cups
YA1 : Y coordinate of 1 cup
YA2 : Y coordinate of 2 cup
YA3 : Y coordinate of 3 cup
YA4 : Y coordinate of 4 cup
YA5 : Y coordinate of 5 cup
YA6 : Y coordinate of 6 cup
YA7 : Y coordinate of 7 cup
YA8 : Y coordinate of 8 cup
Wlx : Angle of cup x
TY1 : Typ of 1 cup
TY2 : Typ of 2 cup
TY3 : Typ of 3 cup
TY4 : Typ of 4 cup
TY5 : Typ of 5 cup
TY6 : Typ of 6 cup
TY7 : Typ of 7 cup
TY8 : Typ of 8 cup
VA1 : Vakuum cup 1: 1=on 0=of
VA2 : Vakuum cup 2: 1=on 0=of
VA3 : Vakuum cup 3: 1=on 0=of
VA4 : Vakuum cup 4: 1=on 0=of
VA5 : Vakuum cup 5: 1=on 0=of
VA6 : Vakuum cup 6: 1=on 0=of
VA7 : Vakuum cup 7: 1=on 0=of
VA8 : Vakuum cup 8: 1=on 0=of
KO : Coordinate system
?? : condition (default=1)
EN : Enable (default=1)

8.4.3 SaugerL: Konsolensauger längs (parallel to X-Axis)

ID-Number: 130

E.g.:

<130 \SaugerL\

YA="0"

AN="1"

XA1="0"

XA2="0"

XA3="0"

XA4="0"

TX1="0"

TX2="0"

TX3="0"

TX4="0"

WI1="0"

WI2="0"

WI3="0"

WI4="0"

WI5="0"

WI6="0"

WI7="0"

WI8="0"



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

VA1="1"
VA2="1"
VA3="1"
VA4="1"

Erklärung:

YA : Y Coordinate of Konsole
AN : Number of Sauger
XA1 : X Coordinate of 1 cups
XA2 : X Coordinate of 2 cups
XA3 : X Coordinate of 3 cups
XA4 : X Coordinate of 4 cups
XA5 : X Coordinate of 5 cups
XA6 : X Coordinate of 6 cups
XA7 : X Coordinate of 7 cups
XA8 : X Coordinate of 8 cups
Wlx : Angle of cup x
TX1 : Typ of 1 cups
TX2 : Typ of 2 cups
TX3 : Typ of 3 cups
TX4 : Typ of 4 cups
TX5 : Typ of 5 cups
TX6 : Typ of 6 cups
TX7 : Typ of 7 cups
TX8 : Typ of 8 cups
VA1 : Vakuum Sauger 1: 1=on 0=off
VA2 : Vakuum Sauger 2: 1=on 0=off
VA3 : Vakuum Sauger 3: 1=on 0=off
VA4 : Vakuum Sauger 4: 1=on 0=off
VA5 : Vakuum Sauger 5: 1=on 0=off
VA6 : Vakuum Sauger 6: 1=on 0=off
VA7 : Vakuum Sauger 7: 1=on 0=off
VA8 : Vakuum Sauger 8: 1=on 0=off
KO : Coordinate system
?? : condition (default=1)
EN : Enable (default=1)

Note: you can save up to 20 parallel-to-x-axis suction cups although for clarity reasons only 8 ones are used in the example above

9.4.4 Transport: Work piece Transport with Vacuum Carpet

ID-number: 148

E.g.:
<148 \OfTransport\
XA="100"
YA1="200"
YA2="200"
T_="16"
KL="241"
KR="241"
XV="1000"
KI="1"
LI="1"

9-080-42-7190 -D00

Juli 26th 2006

RE="1"

Explanation:

XA : Start coordinate in X
YA1 : Start coordinate in Y left vacuum carpet
YA2 : Start coordinate in Y right vacuum carpet
F_ : Feedrate
T_ : Tool
KL : WZ-Descriptor left
KR : WZ-Descriptor right
XV : X-offset
KI : Critical, i.e. not to lift workpiece but sliding/pull out
LI : Left
RE : Right
KO : Coordinate system
?? : condition (default=1)
EN : Enable (default=1)

9.4.5 Transport: Part handling with bridge

ID-Nummer: 184

Bsp.:

```
<184 \Transport\
XA1="2"
YA1="3"
ZA1="4"
T_="92"
XA2="7"
YA2="8"
ZA2="9"
ST="1"
F_="5"
AM="6"
RE="1"
RI="2"
KO="00"
??="999"
```

Erklärung:

XA1 : X-Offset table
YA1 : Y- Offset table
ZA1 : Z- Offset table
XA2 : X- Offset table
YA2 : Y-Versatz Stapel
ZA3 : Z-Versatz Stapel
ST : Stapelnummer
F_ : Feed
RE : Cleaning
RI : Direction (1=In, 2= Out)
UM : restack (0 = inactive, 1 = activ)
AM : Mode
KO : Coordinate system
?? : condition (default=1)
EN : Enable (default=1)
MD : userdefined transport mode.



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

T_ : Tool

9.4.6 Gebietsmakro: Area Macro

ID-number: 182

E.g.:
<182 \Gebiet\
EA="1:0"
WE="1"
SF="0"
RT="0"
RW="1"
PT="1"
HS="1"
VS="1"
XP="0"
XM="0"
YP="0"
YM="0"
ZH="1"
ZV="1"
SX="0"
SY="1"
HV="1"
T_="102"
AS="0"
RX="50"
RY="50"
MB="10"
AZ="20"
ZU="0.5"
ZA="-3"
F_="STANDARD"
SW="300"

Explanation:

EA : Number of start elements
WE : the area macro defines the outer contour of a workpiece if WE equals 1
SF : the area macro defines the outer contour of a blocked area if SE equals 1
RT : Remainder contour when RT=1
RW : Partcontour with cutting remainder when RW=1
PT : Generae automatic parameters when PT=1
HS : Process horizontal cuttings when HS=1 (man. Parameter)
VS : Process vertical cuttings when VS=1 (man. Parameter)
XP : Vertical cuttings in X+ sequence
XM : Vertical cuttings in X- sequence
YP : Horizontal cuttings in Y+ sequence
YM : Horizontal cuttings in Y- sequence
ZH : Zigzag sequence horizontal
ZV : Zigzag sequence vertical
SX : Cutting sequence X+ for vertical cuttings
SY : Cutting sequence Y+ for horizontal cuttings
HV : Horizontal cuttings before vertical cuttings
T_ : Tool number
AS : Additional distance for cutting
RX : Grid size X



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

RY : Grid size Y
MB : Minimal cutting path length
AZ : Start distance in Z-Axis
ZU : Infeed speed for Z-Axis when doing remainder cutting
ZA : Z-Reference value for the depth
F_ : Feed
?? : Condition (*default=1*)
EN : Enable (*default=1*)
SW : Threshold for cross cutting
MD : selfdefined mode
TR : separate cuttings (1=on, 0=off)
NS : NCStop (1=on, 0=off)
OSZVS : feed for oscillating routing
OSZI : enable oscillating routing yes/no (default : 0)

9.4.7. Extrudieren: Extruding Edge along a contour

ID-Number: 187

E.g.:
<187 \Extruder\
MDA="TAN"
MDE="TAN_AB"
EA="1:0"
EE="1:1"
P59="1"
AB="0.0"
AC="0"
SL="50"
SA="2"
CF="5"
P60="0.0"
WS="0.0"
F_="1.8"
DZ="1"
S_="0"
S_P="100"
TL="1"
M15="1"
NM="STANDARD"
KM="Extrudieren"
VM="290"
KN="290"
TNO="STANDARD"
RV="0"
ABN="55.0"
ABA="10"
VA="0.8"
ABT="58.0"
FK="0.5"
TB="28.0"
SK="15.0"
??=" _nonmirror AND _nonymirror "
MX="0"
MY="0"
MZ="0"



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

MXF="1"
MYF="1"
MZF="1"
HP="0"
SP="0"
YVE="0"
WW="290"
ASG="2"
KAT="Extruder"
MNM="Extruder"
RSEL="0"
RWID="0"

Explanation:

MDA : Start mode
TAN =0: tangential
SEI =1: from side
SEN =2: vertical
or self defined start mode

MDE : Start mode
TAN_AB =0: tangential
SEI_AB =1: from side
SEN_AB =2: horizontal
or self defined start mode

EA : Number of start elements
EE : Number of end element
P59 : Edge (choosing edge channel)
AB : Distance from programmed contour. If distance is negative, more pressure will be given to work piece.

Z_ : Z-value (optional) (default=0)
P60 : C-angle
WS : Maintenance time
F_ : Feedrate
S_ : revolution speed (must be „0“ if DZ=1)
TL : Test run (without edge)
0: no test run
1: test run, e.g. without edge material and glue

M15 : Test run (without M15 i.e. over work piece)
NM : Name of gluing parameter file
KM : Comment
VM : Gluing makro (Art of gluing unit) – up to WoodWOP-Build 556
KN : Art of gluing unit – WoodWOP-Build 556 or greater
MD : Self defined mode – WoodWOP-Build 556 or greater
TNO : T-Number (tool number)
HL : Heat power in %
HL2 : Heat power 2 in %
KZ : Edge material adding
DK : Thickness of edge
LA : Slow pull out
SV : Bulb pre snip station
SE : Bulb gluing station
ABN : Distance post press roller on
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: counter forward i.e. against drawing direction of contour element

ABV : Distance edge transport
ABA : Distance post press roller off

9-080-42-7190 -D00

Juli 26th 2006

KA : Snipdistance from end only in conjunction with NC-Generator-Option „edge material grouping“)

VA : Waiting time post press roller

KA : Snipdistance from end only in conjunction with NC-Generator-Option „edge

VA : Waiting time post press roller

ABT : Distance , drive way-sensor

FK : Feedrate sensing

TB : Sensor area, slow way

SK : Joint correction

KS : Swing snipping saw

SVK : Pre snipping station with bulb

RV : Banding around, i.e. Joint at not cosed contour (optional) (default=0)

RSP : Turning of gluing station to start point

1: clockwise

0: conter clockwise

Ist parameter not declarated, the minimum turning of gluing station will be calculatedt.

AC : Automatic correction of the C-Offset (collision test)

1: ON

0: OFF

9.4.8. Easyedge: Edgebanding using Easyedge device along a contour

ID-Number: 188

E.g.:

```
<188 \Easyedge\
MDA="TAN"
MDE="TAN_AB"
EA="1:0"
EE="1:0"
P59="1"
AB="-2"
AC="0"
SL="50"
SA="2"
CF="5"
P60="-55"
WKS="2"
FKA="3"
TL="1"
M15="1"
NM="STANDARD"
KM="PVC-Kante 2mm REHAU"
VM="262"
KN="262"
TNO="STANDARD"
KZ="25"
KB="1"
AV="0"
DK="0"
LA="0"
RV="1"
AAE="55"
RI="0"
OA="10"
AAA="55"
WKE="1"
```



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

ALA="50"
KLA="0"
??=" _nonmirror AND _nonymirror "
MX="0"
MY="0"
MZ="0"
MXF="1"
MYF="1"
MZF="1"
HP="0"
SP="0"
YVE="0"
WW=""
ASG="2"
KAT="Easyedge"
MNM="Easyedge"
RSEL="0"
RWID="0"

Explanation:

MDA : Start mode
TAN =0: tangential
SEI =1: from side
SEN =2: vertical
or self defined start mode

MDE : Start mode
TAN_AB =0: tangential
SEI_AB =1: from side
SEN_AB =2: horizontal
or self defined start mode

EA : Number of start elements
EE : Number of end element
P59 : Edge (choosing edge channel)
AB : Distance from programmed contour. If distance is negative, more pressure will be given to work piece.

Z_ : Z-value (optional) (default=0)
P60 : C-angle
WKS : Maintenance time for fixing the edgebanding material at contour start
FKA : feed at the beginning of the edge
S_ : revolution speed (must be „0“ if DZ=1)
TL : Test run (without edge)
0: no test run
1: test run, e.g. without edge material and glue

M15 : Test run (without M15 i.e. over work piece)
NM : Name of gluing parameter file
KM : Comment
VM : Gluing makro (Art of gluing unit) – up to WoodWOP-Build 556
KN : Art of gluing unit – WoodWOP-Build 556 or greater
MD : Self defined mode – WoodWOP-Build 556 or greater
TNO : T-Number (tool number)
HL : Heat power in %
HL2 : Heat power 2 in %
KZ : Edge material adding
DK : Thickness of edge
LA : Slow pull out
SV : Bulb pre snip station
SE : Bulb gluing station



PRODUCT INFORMATION

Subject : 4.2.7

Description
woodWOP- file

9-080-42-7190 -D00

Juli 26th 2006

AAE : distance pin roller on
RI : Direction of processing
1: forward, i.e. in drawing direction of contour element
0: conter forward i.e. against drawing direction of contour element
OE : Offset pin roller
AAA : distance pin roller off
VA : Waiting time post press roller
KA : Snipdistance from end only in conjunction with NC-Generator-Option „edge
WKE : Maintenance time for fixing the edgebanding material at contour ending
ALA : distance glue application
FK : Feedrate sensing
TB : Sensor area, slow way
KLA : correction for glue application
KS : Kappsappsäge schwenken
SVK : Vorkappstation mit Strahler
KS : Swing snipping saw
SVK : Pre snipping station with bulb
RV : Banding around, i.e. Joint at not cosed contour (optional) (*default=0*)
RSP : Turnung of gluing station to start point
1: clockwise
0: conter clockwise
Ist parameter not declarated, the minimum turning of gluing station will be calculatedt.
AC : Automatic correction of the C-Offset (collision test)
1: ON
0: OFF