N848 T

**TEXTRON** Lycoming

#2

# ENGINE LOG

SSP-1872-1

Serial No.

| Date    |     | me  | REPAIRS - ADJUSTMENTS - SI | EDVICE DEMARKS   | Signature            | License      |
|---------|-----|-----|----------------------------|--|----------------------|--------------|
|         | Hrs | Min | REPAIRS - ADJUSTMENTS - SI | ENVICE - REMARKS   | o ignaturo           | Number       |
| 1-10-08 | 71  | ACH | :3754.5 CHANGEL            | OIL AND FILTER.  | SERVICE              | RAY bulk     |
|         |     |     | w/ /1 Q7                   | S AS /UDW, LK CK   | OK                   | 9.91         |
|         |     |     | /                          | 10/  | Y I I I I I I I      |              |
|         |     |     |                            | JC 4, N  |                      |              |
|         |     |     |                            | 561926478 R  |                      |              |
|         |     |     |                            |  | 01107100             |              |
|         |     |     |                            | Ingular calls  |                      |              |
|         |     |     |                            | THE RELIEF WITHOUT THE PARTY OF |                      | NESTA BIN    |
|         |     |     | S.H n0039                  | MIN.   |                      | AE SITTLE VI |
|         |     |     | HIME!                      | Ishari   |                      | 19           |
|         |     |     | Page Total                 | All Repair Data Must Bear  | the Endorsement of a | J. J. Pin    |
|         |     |     | Brought Forward            | Certificated Mechanic, and   | his Rating and       |              |
|         |     |     | Total to Date              | Certificate Number MUST  | be Shown.            |              |

Turbine Aircraft Services, L.C.

ENGINE LOG ENTRY

S/N: 3213027

MODEL: 10-540-KIGSD

S/N: RL-27438-48A

PAGE: 1 of 1

DATE: 2-26-09

AFTT: 3764.5 HM: 1954.2

MODEL: PA-32R-301 N: 848T

TACH: 3764.5

TSO: 1738.3

- Completed 100 Hr. Inspection In Accordance With Part 43 Appendix (D) Inspection Guide.
- 2. Cleaned Fuel Filters.
- Changed Oil And Filter, Old Filter Inspected, No Contamination Found. Serviced Engine With Aeroshell 80W Filter P/N CH48103-1.
- Compression Check, Cylinders 1) 78/80 2) 72/80 3) 74/80
   4) 71/80 5) 76/80 6) 76/80.
- 5. Cleaned, Gapped And Tested Spark Plugs.
- 6. Cleaned Fuel Nozzles.
- 7. Set Magneto To Engine Timing.
- 8. Installed All New Exhaust Flange Gaskets P/N 77611

- Installed All New Rocker Box Cover Gaskets P/N 67193.
- Installed All New Rocker Box Cover Drain Line Hoses P/N STD-2180
- 11. Installed New Induction Air Filter P/N 3A-BA104.
- 12. Installed New Induction Drain Line Fitting P/N 492-091.
- Complied With A.D. 2009-02-03 Precision Airmotive Fuel Servo Plug Inspection. Installed New Gasket P/N 2577258.
- Washed Engine And Completed Satisfactory Ground Run, No Leaks Noted.
- A.D. 2008-14-07 Effective Date 8/14/08. Lycoming Fuel Injections Lines Inspected In Accordance With MSB342E, No Defects Noted. Reinspection Due In 100 Hours Or AFTT 3864.5

I Certify That This Aircraft Engine Has Been Inspected In Accordance With A 100 Hr. Inspection And Was Determined To Be In Airworthy Condition For Return To Service At This Time, Reference To Work Order 09-5695 Dated 2-26-09

SIGNED:

FOR: Michael Harbison Turbine Aircraft Services, LL.C. A&P # 44470224 IA

5831 Tulakes Ave. Hangar 16, Wiley Post Airport Bethany, OK 73008

Serial No.

### Turbine Aircraft Services, LLC.

MODEL: PA32R-301 N: 848T

S/N: 3213027

ENGINE LOG ENTRY Model: 10-540-A165D S/N: RL-27438-48A PAGE: 1 of 1

DATE: 4-21-09

AFTT: 3814.0

TACH: 3814.0

TSO: 1787.7

 Changed Engine Oil And Filter. Inspected Old Filter, No Metal Found. Serviced Engine With Aeroshell 100W Oil. Washed Engine, Ran Engine, No Leaks Noted. P/N CH48103-1 Oil Filter.

Ref.W/O #09-5757 Dated 4-21-09

SIGNED:

Cody A. Harbison

Turbine Aircraft Services, L.L.C.

5831 Tulakes Ave. Hangar 16, Wiley Post Airport Bethany, OK 73008

Total to Date

CELLINGATE MANIDEL MICO I DE SHOWII.

A&P # 2962302

### ENGINE LOG Serial No.

| MDDEL: PA32R-301<br>NNBR: 848T SN: 3213027   | Turbine Aircraft Services, L.L.C. ENGINE LOG ENTRY                                   | PAGE: 1 of 1   |
|--|--|----------------|
|  | MODEL: 10-540-KIG5D S/N: RL-27438-48A  | DATE: 6-2-2009 |
| AFTT: 3862.3   | TACH: 3862.3   | TSO: 1836.1    |
| Changed Oil And filter, P/N CH48103-1<br>Washed Engine, Ran Engine, No Leaks<br>ef. W/O 09-5789 Dated 6-2-2009 | . Inspected Old Filter, No Contamination Found. Serviced Engine With Aeroshes Noted. | ell 100W Oil.  |
| IGNED: Buffer  | Ryan J. Morphew Turbine Aircraft Services, L.L.C.                                    | A & P# 3109029 |
|  | 5831 Tulakes Ave. Hangar 16, Wiley Post Airport<br>Bethany, OK 73008                 |                |

Carial No

| \$1,400  | ENGINE LOG  | Serial No.  |
|--|---|---|
| Time the menant  | Turbine Aircraft Serv   | víces, L.L.C.                                     |
| MDDEL: PA32R-301 S/N: 3213027<br>NNBR: 848T  | ENGINE LOG ENTRY<br>MODEL: 10-540-KIG5D S/N: RL-27438-  | PAGE: 1 of 1                                      |
| AFTT: 3913.9   | TACH: 3913.9  | TSO: 1887.7                                       |
| <ol> <li>Changed Oil And Filter, Inspected<br/>No Leaks Or Defects Noted. Filter</li> <li>Ref. W/O 09-5841 Dated 8-4-2009</li> </ol> | d Old Filter, No Metal Found. Serviced Engine With Aeroshell<br>r P/N CH48103-1.                                      |   |
| SIGNED: Cody a. Zheh   | FOR: Cody A. Harbison Turbine Aircraft Services, L.L.C. 5831 Tulakes Ave. Hangar 16, Wiley Post Air Bethany, OK 73008 |   |
| Brought For Total to Da  | 0 .: 1  | Mechanic, and his Rating and umber MUST be Shown. |

Serial No.

### Turbine Aircraft Services, L.L.C.

MODEL: PA32R-301 S/N: 3213027

NNBR: 848T

ENGINE LOG ENTRY
MODEL: ID-540-KIG5D S/N: RL-27438-48A

PAGE: 1 of 1 DATE: 9-28-09

AFTT: 3973.1

TACH: 3973.1

 Changed Oil And Filter, Inspected Old Filter, No Metal Found. Serviced Engine With Aeroshell W100 Oil. Washed Engine, Ran Engine, No Leaks Or Defects Noted. Filter P/N CH48103-1.

Ref. W/O 09-5880 Dated 9-28-2009

SIGNED: Jama Dopl

FOR: James C. Morphew
Turbine Aircraft Services, L.L.C.
5831 Tulakes Ave. Hangar 16, Wiley Post Airport
Bethany, OK 73008

ASP # 442589115

TOTAL TO DATE

Date 1-10-10 WO # 9037

AIRCRAFT D&B ENGINES

(405) 495-0457 Fax (405) 495-9021 5508 N. Rockwell Bethany, OK 73008 USA Faa CRS# HX2R888K Eng Type <u>**T0540**k1650</u> S/N <u>3213027</u> Time <u>3995.0</u>

This engine removed from N 848T for major overhaul. Engine disassembled & cleaned. All steel parts magnafluxed. All ferrous parts zygloed. Crankshaft is standard rods and .003 under sized on mains. Connecting rods rebushed and installed with new bearings, bolts and nuts. Counterweight bushings on shaft replaced. Counterweights installed with new pins, plates and circlips. Crankcase reworked and certified by CRS-H1HR096O. Camshaft and lifter bodies reworked and certified by CRS-DD2R764K. Crankcase assembled with new .003 undersized main bearings. Cylinders are standard steel. New guides and exhaust valves. New pistons, rings and piston pin plugs. Cylinders installed torqued. Fuel servo overhauled by CRS-BF2R714K. New fuel pump installed. Prop governor overhauled by CRS-QYIR334Y. Magneto S/N G07GA122R overhauled by CRS-HX2R888K. Engine baffle reworked and installed. New fluid carrying hoses. Engine reinstalled on N848T with new lord mounts. Filled with Page 1 of 2

Aero Shell 40 non-detergent oil and ground run satisfactorily. AD 97-15-11 complied with on piston pin inspection. AD 2000-18-53 complied with on oil filter plate. AD 2008-14-7 complied with on fuel line. Service Instruction 14727B complied with on ground run. Service Bulletin 240 U complied with on 100% parts replacement. MSB 518C complied with on vernatherm - New style installed.

> This engine and/or component was repaired and inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under work order

Signed\_

Date 1-10-10

D & B AIRCRAFT ENGINES

5508 N. ROCKWELL

BETHANY, OKLA. 73008

FAA Certified repair station #HX2R888K

Turbine Aircraft Services, L.C. **ENGINE LOG ENTRY** 

MODEL: PA32R-301

NNBR: 848T SN: 3213027

MODEL: 10-540-K1G5D S/N: RL-27438-48A PAGE: 1 of 1 DATE: 3-12-2010

AFTT: 3999.3

HM: 2191.8

TSO: 4.3

#### **INSPECTION ITEMS**

Completed A 100 Hour Inspection Using Part 43 Appendix (D) Inspection

#### AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS

- Found A.D. 2009-02-03 Precision Airmotive Fuel Servo Plug Gasket Complied With At Overhaul By Martin Induction Systems Inc., Dated 1-6-10 W/O 582 CRS BF2R714K.
- Complied With A.D. 2008-14-07 Effective Date 8/14/08. Lycoming Fuel Injection Lines Using MSB342E. No Defects Noted. Reinspect In 100.0 Hours Or At AFTT 4099.3.

#### MISCELLANEOUS MAINTENANCE AND REPAIRS

- Cleaned Fuel Screens.
- Compression Check 1.) 78/80 2.) 78/80 3.) 77/80 4.) 78/80 5.) 78/80 6.) 76/80.
- Oil And Filter To Be Replaced At 25.0 Hours Or AFTT 4020.0 Hours
- · Washed Engine.
- · Completed Satisfactory Ground Run. No Leaks Noted.

I Certify That This Engine Has Been Inspected In Accordance With A 100 Hour Inspection And Was Determined To Be In Airworthy Condition For Return To Service At This Time, Reference To Work Order 10-5978 Dated 3-12-2010.

Michael Harbison Turbine Aircraft Services, L.L.C. A&P 003398356IA

5831 Tulakes Ave. Hangar 16, Wiley Post Airport Bethany, OK 73008

|     | ENGINE MODEL. 10-540-K165D ENGINE S/N ENGINE S/N ENGINE S/N ENGINE S/N Bethany, Oklahoma 73008   | DATE: 4/23/2010 A/C TSN: 4022.5 ENG TT: TSMOH: 27.5 TACH: 4022.5   |            |
|-----|--|--|------------|
| ate | REG. NO. N848T<br>WORK ORDER: 50008  | en   | nse<br>ber |
| 500 | Engine Entries   |  | -          |
|     | (1) Changed oil and filter, Inspected old filter, no metal found by visual inspengine with 12 quarts Aeroshell 100 Mineral oil. Engine ground normal, no l | ection. Installed new filter P/N CH48103-1 and serviced eaks noted.  |            |
|     | DATE: 4/23/2010 SIGNED C D-1   | Work Order: 50008  |            |
|     | James Morphew, A&P: 442589115  | Printed by EBis 3 (datcomedia.com)   |            |
|     |  |  |            |
|     | V  |  |            |
| 2   |  |  |            |
|     |  |  |            |
|     |  |  |            |
|     |  |  |            |
|     |  |  |            |
|     | Fags Total   | Research to the Bear the Child Control of the Control  |            |
|     | Frount Frount Co.  | Afficiency (An objection and the finding street of the contract of the contrac |            |
|     |  |  |            |
|     | 1 of 1   |  |            |
|     |  |  |            |

| Date | ENGINE MODEL<br>10-540-K165D<br>ENGINE S/N.<br>RL-27438-48A<br>REG. NO. N848T<br>WORK ORDER: 50108 | Turbine Aircraft Services LLC<br>5831 Tulakes Ave, Hangar 18<br>Bethany, Oklahoma 73008  | DATE: 12/14/2010<br>A/C TSN: 4084 9<br>ENG TT<br>TSMOH: 89 9<br>TACH: 4084 9 |
|------|--|--|--|
|      | Engine Entries   |  |  |
|      | (1) Changed oil and filt<br>engine with 12 quarts A  | er, Inspected old filter, no metal found by visual inspection. In<br>Aeroshell 15w50 oil. Engine ground run normal, no leaks noted | nstalled new filter P/N CH48103-1 and serviced d                             |
|      |  | nent(s) items identified above were repaired and inspected in accordance   | e with current Federal Aviation Regulations and was                          |
|      | found Airworthy for return to  |  |  |
|      | DATE: 12/14/2010   | SIGNED: Thankwel N. Halyan   | Work Order: 50108  |
|      |  |  |  |
|      | ET French Mann   | Michael B. Harbison, License 003106668IA   | Printed by EBis 3 (datcomedia.com)   |
|      | 1 Marketon   |  | Printed by EBis 3 (datcomedia.com)   |
|      | I was to the   |  | Printed by EBis 3 (datcomedia.com)   |
|      | A Marketin   | Michael B. Harbison, License. 003106668IA  |  |
|      | 1 mis 12 127   | Michael B. Harbison, License 003106668IA   |  |
|      |  | Michael B. Harbison, License 003106668IA   |  |
|      |  | Michael B. Harbison, License. 0031066681A  |  |

|      | ENGINE MODEL<br>10-540-K1G5D<br>ENGINE S/N:<br>RL-27438-48A  | Turbine Aircraft Services LLC<br>5831 Tulakes Ave, Hangar 16<br>Bethany, Oldahoma 73008   | DATE 5/9/2011<br>A/C TSN: 4127.5<br>ENG TT: 4127.5<br>TSMOH: 132.5<br>HORBS: 2321.4  | =    |
|------|--|---|--|------|
| Date | REG. NO: N848T<br>WORK ORDER: 50147  |   | HODDS 23214  | ense |
|      | Engine Entries   |   |  |      |
|      | (4) Changed oil and filt engine with 12 quarts (5) Checked magneto (6) Inspected and clea (7) Cleaned, gapped a (8) Compression teste (9) Cleaned and inspection (12) Airworthiness Director per para (k) of this A.I. hours or ACTT 4227.6 (34) A.D 2005-12-06. Service Bulletin MSB6 inspection due at AFT | ned air filter.  Ind tested spark plugs. Reinstalled using new gaskets.  d as follows: 1, 76/80. 2, 72/80. 3, 75/80. 4, 77/80. 5,  cted fuel screens.  ective 2008-14-07 Amend: 39-15602 dated Aug. 14, 20  and Lycoming Service Bulletin 342F. No defects note  .  Effective date July 19, 2005. Magneto impulse coupling  45 at this time. Magneto marked with letter "A" Snap re | tion. Installed new filter P/N CH48103-1 and serviced is noted.  , 75/80. 6, 75/80.  008 Lycoming fuel lines. Inspected affected fuel lines ed at this time. Fuel lines due inspection again in 100 g. Found not applicable by Teledyne Continental ring impulse coupling installed. 500 hour wear |      |
|      | The Engine and/or compor found Airworthy for return  | nent(s) items identified above were repaired and inspected in actorservice.   | cordance with current Federal Aviation Regulations and was   |      |
|      | DATE: 5/9/2011   | SIGNED Rouff  | Work Order: 50147  |      |
|      |  | Ryan Morphew, Cense 1003109029IA  | Printed by EBis 3 (datcomedia.com)   |      |
|      | This   |   |  |      |
|      | _  |   |  |      |

ENICINE LOC

Date 9.23.11 WO # 9458

AIRCRAFT D&B ENGINES

(405) 495-0457 Fax (405) 495-9021 5508 N. Rockwell Bethany, OK 73008 USA Faa CRS# HX2R888K Eng Type 540-K1G50 S/N KL-27438-48A Time 4106.6 TACH

This engine removed from N848T for a prop strike inspection. Engine disassembled, cleaned and inspected. All steel parts Magnaflux inspected and all aluminum parts Zyglo inspected. Crankshaft run out is good. All accessory drives checked with no damage found. Engine reassembled with new seals and gaskets. Reinstalled on N848T and filled with Aero Shell 50 ND oil and ground run satisfactorily.

AD 2005-19-11

SB 533A

Complied with on prop strike inspection

Complied with on prop strike

D & B AIRCRAFT ENGINES CRS # HX2R888K

Page 1 of 1

Serial No.

| OMEGA                           |  |  |
|---------------------------------|--|--|
| OMEGA<br>Aircraft Services, LLC |  |  |
|                                 |  |  |

Date: February 16, 2012

Hobbs Time: 2404.4

Tach Time: 4204.5

3000 Logan Road South Hanger Weatherford, OK 73096 580-774-5393

Registration: N848T Serial Number: 3213027

Removed oil filter and replaced with CH48103-1, drained oil, took oil sample and sent to Aviation Lab, serviced with 11 qts of Phillips XC 20W 50 oil, performed ground run with no leaks noted at this time. Aircraft approved for return to service for the work performed. Dennis K. Falasco A&P 3174880.

License Number

of a

ıd ın ls

Serial No.

S/N RL-27438-48A **Engine Log** Tach & Eng. Total 4222.0 T.S.M.O.H. 227.0 05-21-2012

100 Hour inspection completed I/A/W FAR 43 Appendix D, Performed pre inspection ground runs and checked all systems, Checked prop operation. Performed compression check hot as follows. # 1-76/80,2-76/80,3-78/80,4-78/80,5-78/80,6-78/80 all checked within limits at this time. Drained oil hot, cut filter open ,no metal found. Installed new Tempest filter AA48103-2 and serviced engine with 11 Qts. 20W50 Phillips X/C oil. Cleaned all spark plugs, gapped and reinstalled with new copper washers. Inspected exhaust system, inspected engine mount and firewall. Installed new air filter element P/N BA-3. Checked mag timing. Installed new L/H & R/H lower baffle stay rods. Washed engine. Complied with AD 11-26-04 fuel injector lines and clamps inspection, no defects noted due ea. 100 hrs./annual or whenever line maintenance is performed. AD 95-26-13 oil cooler hoses due replace by 4995.0 total time or 01-2018 whichever first. Performed post inspection ground runs and checked idle, idle mixture mag operation. Checked static power. No leaks noted for work performed .

" I certify this engine has been inspected I/A/W a 100 hour inspection was found airworthy and is approved for return to service this date."

Larry Brewer A&P 3442166

Zanny Brewer Central Aviation Southwest LLC.

| serviced engin | ne with <b>11 Qts. 20W50</b><br>W PA32R-301 mainte | Phillips X/O  | C oil. Ground run and no<br>al and Lycoming engine |                         |
|----------------|--|---------------|--|-------------------------|
| Larry Brewer   | A&P 3442166 La                                     | my Be         | Lewez Central                                      | Aviation Southwest LLC. |
|                |  | /             |  |                         |
|                |  |               |  |                         |
| 108            | 848T Engine Log<br>3/22/2013 Tach 4302             | .0            |  |                         |
|                |  |               | ut oil filter open and check                       |                         |
|                | ormal-no leaks.                                    | added 9 quart | s Phillips X-C oil. Ran up                         | -all readings           |
|                | onachan  | EVa           | mes  | rsement of a            |
| 1 1            |  |               | Construction Number                                | ig aliu<br>1.           |

|         |   | NGINE LOG   | Seria                                     | I No   |
|---------|---|---|---|--|
| Date Hr | Checked compression: Cyl : 74/80, #6 70/80. Replaced Log entry dated 03/22/2013 rotated and inverted spark procession in MIL 5606 fluid. Washed engage in the cylinder #1. Replaced air in MIL 5606 fluid. Washed engage in the cylinder #1. Replaced air in MIL 5606 fluid. Washed engage in the cylinder #1. Replaced air in MIL 5606 fluid. Washed engage in the cylinder #1. Replaced air in MIL 5606 fluid. Washed engage in the cylinder #1. Replaced air worthy condition. | Exp. Date: Loc: Genuine Piper Part Shel  Exp. Date: 10- Cure Date: #1 /6/80, #2 /2/80, #3 AN900-10 seal on oil tem for oil change information olugs. Magneto received 50 R888K. Reinstalled magne element BA-3. Replaced in duction hose P.N. 565-458 gine and ran up-all reading | : 10/29/12 AE 6641E01C  f Life: Yes -2032 | License Numbe  5 Engine ested, D&B 20 e clamp oir with |

| <b>ENGINE LO</b> | $\sim$       |
|------------------|--------------|
|                  |              |
| TIME IN          | <b>W</b> A % |

Serial No. \_

| Data | Ti  | me     |  |  | Cignoture            | License |
|------|-----|--------|--|--|----------------------|---------|
| Date | Hrs | Min    | REPAIRS - ADJUSTMENTS - SERVICE - REMARKS  | RTYDATAULGA - A                        | Signature            | Numbe   |
|      |     |        | N848T Engine Log 11/15/2013 Tach 4346.5  Changed oil and filter(AA48103-1). Cut filter o screen-no metal found. Added 9 quarts Phillips and ran up-no leaks. | pen and checked oi<br>20W50 X-C oil. W | I suction            |         |
|      |     |        | Jonathan E. Farmer<br>A&P 2693725  | 2                                      |                      |         |
|      |     | trace) | Page Total All Re  | pair Data Must Bear                    | the Endorsement of a |         |
|      |     | 100    | Brought Forward Certific   | ated Mechanic, and                     | his Rating and       |         |
| 0.5  |     |        | Total to Date  | ate Number MOST                        | Je Showii.           |         |

Serial No.

# O'NEILL AIRCRAFT SALES & SERVICE

Norman, Oklahoma

7/02/2014 Hobbs: 2577.6 N848T ACTT: 4369.7 Engine TSMOH: 374.7

Engine ran up, oil drained and filter cut open and inspected for metal. None found. Serviced with 12 qts Phillips X/C 20W50 oil. Ran compression test as follows: 1) 77/80 2) 74/80 3) 74/80 4) 72/80 5) 75/80 6) 70/80. Spark plugs cleaned, gapped and tested. Mag timing checked. Air filter PN: BA3 replaced. C/W AD 95-26-13 oil cooler hoses per Para (A) 1. C/W AD 11-26-04 fuel injection lines per Lycoming MSB-342E diagram no. 17. No defects noted, #1/#2 muffler riser assy replaced. Remaining exhaust system pressure checked ok. Engine washed down and ran up for leak checks. I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition at this time.

James Hanger IA3322759A&P fa

License Number

# O'NEILL AIRCRAFT SALES & SERVICE

Norman, Oklahoma

7/16/2015 Hobbs: 2653.0 N848T ACTT: 4443.5 Engine TSMOH: 448.5

Engine ran up, oil drained and filter cut open and inspected for metal. None found. Serviced with 11 qts Phillips X/C 20W50 oil. Ran compression test as follows: 1) 74/80 2) 70/80 3) 73/80 4) 75/80 5) 72/80 6) 71/80. Replaced #1 EGT probe. Spark plugs cleaned, gapped and tested. Mag timing checked. Air filter PN: BA3 replaced. C/W AD 95-26-13 oil cooler hoses per Para (A) 1. C/W AD 11-26-04 fuel injection lines per Lycoming MSB-342E diagram no. 17. No defects noted. Exhaust system pressure checked ok. Engine washed down and ran up for leak checks. I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition at this time.

Ryan O'Neill IA3511407AP

License Number

of a

| Lots de Empression, n'untrodulsez jamas la feuille d'éfiquettes plus d'une fois dans votre imprimante une seule fois de marque produites de marque |                   |
|--|-------------------|
| Aune fals dans   |                   |
| Tots de l'impression, n'introduises jamais la feuille d'édiquettes plus d'édiquettes du ont été introduites dans l'imprime d'édiquettes qui ont été introduites dans l'imprime d'édiquettes qui ont été introduites de marque Avery.  S'applique seulement aux feuilles d'édiquettes qui ont été introduites de marque Avery.  Pour des résultats garantis, utilisez seulement les produits de marque Avery.  Gabarits et logiciels Avery.   |                   |
| * Tots de l'impression, n'introduises jamais la feuille d'étiquettes plus s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'introduites dans l'es produits de marque Avery.  S'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites d'étiquettes qui ont été introduites dans l'uni s'applique seulement aux feuilles d'étiquettes qui ont été introduites d'étiquettes produites dans l'uni s'applique seulement aux feuilles d'étiquettes produites de marque Avery.  Pour des résultats et logicals Avery d'en des produites et des gabants.  |                   |
| and Jama's la tes qui on the de marque   |                   |
| n'introduses a étique ent les produits   |                   |
| Timples store aux feutiles seulemen  |                   |
| Tota de seule marantis, utilia de la companya de la |                   |
| s'appoint the sale of the sale |                   |
| * Joss de l'impresse seutement aux responses à toutes vos questions au sujet des produits et des gabants.  Gabarits et logiciels Avery Gabarits et logiciels Avery GRATU.  Gabarits et logiciels Avery Gabarits et des gabants.  BESOIN D'AIDE?  BESOIN D'AIDE?  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  Nous avons les réponses à toutes vos questions au sujet des produits et des gabants.  |                   |
| Gabarits et logic.  Gabarits et logic.  Gabarits et logic.  BESOIN D'AIDE?  BESOIN D'AIDE?  BESOIN D'AIDE?  Nous avons les réponses à toutes vos questions au sujet des proud.  Nous avons les réponses à toutes vos questions au sujet des proud.  Religion de la sopriones "Tipo de Para avery.com.mx para |                   |
| BESOIN D'AIDE?  BESOIN D'AIDE?  ROUS avons les réponses à toutes vos questions de la supery.com mix par le relevent good (622-8379)  ROUS avons les réponses à toutes vos questions de la supery.com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión, visita avery com mix par le relevent good (622-8379)  Consejos Básicos de Impresión (622-8379)  |                   |
| TOTAL COM D'ALL COM AGE STON   |                   |
| BEST INSTANCE (BUT IN THE PROPERTY COURSE TO THE PROPERTY COURSE T |                   |
|  |                   |
|  |                   |
| 1-05 de l'incliquelas  |                   |
| Básico Ledona Circ   |                   |
| anselos Chite: Selection   |                   |
| Commence of the commence of th |                   |
|  |                   |
| ENCINE .   |                   |
| O'NEILL AIRCDAFT   |                   |
| O'NEILL AIRCRAFT SALES & SERVIC  |                   |
| SALES & SERVICE  |                   |
| Norman Olive   |                   |
| - William, Uklahoma  | License<br>Number |
| 8/04/2016  | Number            |
| Tach: 4483 4 N848T   |                   |
| ACT: 4483 4 Engine   |                   |
| Engine ran up, oil drained and filter cut open and inspected for metal. None 78/80 2) 74/80 3) 76/80 4) 75/80 5) 77/90 and 1. Ran compression tests of the following tests of the filter cut open and inspected for metal.   |                   |
| found. Serviced with 11 qts Phillips X/C 20W50 oil. Ran compression test as follows: 1)  78/80 2) 74/80 3) 76/80 4) 75/80 5) 77/80 6) 77/80. Spark plugs cleaned gazza l. 1)  Tooker as a fine framework of the service  |                   |
| 78/80 2) 74/80 3) 76/80 4) 75/80 5) 77/80 6) 77/80. Spark plugs cleaned, gapped and rocker cover screw on #5 cylinder. Replaced.   |                   |
| tested. Mag timing checked. Reattached loose baffle at Rt. aft corner. Replaced missing 3 and 5. Insulated ignition harness at aft b. CS.  |                   |
|  |                   |
|  |                   |
| - 40-13 011 00 ol - 1  |                   |
| MSD-147F dia   |                   |
| Washed down  |                   |
| and ran up for leak at a street expansion processing   |                   |
| accordance with a 100 hr approach. I certify that this engine  |                   |
| MSB-342E diagram no. 17. No defects noted. Exhaust system pressure checked. Engine accordance with a 100 hr. annual inspection and was determined to be in airways.  |                   |

accordance with a 100 hr. annual inspection and was determined to be in airworthy

Total to Date

P. P. Ovell Ryan O'Neill

IA3511407AP
Certificate Number MUST be Shown.

#### ENICINE I OC O'NEILL AIRCRAFT **SALES & SERVICE** cense Date ımber Norman, Oklahoma Engine N848T 9/01/2017 TSMOH: 598.3 ACTT: 4593.3 Tach: 4593.3 Engine ran up, oil drained and filter cut open and inspected for metal. None found. Serviced with 11 qts Phillips X/C 20W50 oil. Ran compression test as follows: 1) 76/80 2) 72/80 3) 77/80 4) 74/80 5) 78/80 6) 75/80. Inspected fluid hoses and accessories for leaks and condition. Inspected engine mount and vibration isolators for condition. Spark plugs cleaned, gapped and tested. Mag timing checked. Reattached loose baffle at Rt. aft corner. Replaced missing rocker cover screw on #5 and #3 cylinders. Air filter PN: BA3 replaced. C/W AD 15-19-17 fuel injection lines per Lycoming MSB-342E diagram no. 17. No defects noted. Exhaust system pressure checked. Engine washed down and ran up for leak checks. I certify that this engine has been inspected in accordance with a 100 hr. annual inspection and was determined to be in airworthy condition at this time. Ryan O'Neill Certificated Mechanic, and Brought Forward Certificate Number MUST be Shown. Total to Date