1

If copper (which has a melting point of 1085°C) homogeneously nucleates at 849°C, calculate the critical radius given values of -1.77×10^9 J/m3 and 0.200 J/m2, respectively, for the latent heat of solidification and the surface free energy.

```
	extstyle 	extstyle 	extstyle 	extstyle Answer < \ r^* = rac{2\gamma T_m}{\Delta H_f \Delta T} \ = -rac{2(0.2)(1085)}{1.77 	imes 10^9 (1085 - 849)} \ = 1.04 \ nm
```

2

Suppose that a steel of eutectoid composition (0.76 wt% C) is cooled to 500°C from 760°C in less than 0.5 s and held at this temperature.

a

How long will it take for the austenite (γ)-to-pearlite(α +Fe3C) transformation to begin? Go to 50% completion? To 100% completion?

```
✓ Answer
Begin: 0.8 s
50%: 4 s
100%: 10 s
```

b

Using the convention that rate = $\frac{1}{t_{0.5}}$ what is the transformation rate at this temperature?

```
\checkmark Answer \frac{1}{4s}
```

Using the isothermal transformation diagram for a 0.45 wt% C steel alloy (Figure 11.50), determine the final microstructure (in terms of just the microconstituents present) of a small specimen that has been subjected to the following time-temperature treatments. In each case, assume that the specimen begins at 845°C, and that it has been held at this temperature long enough to have achieved a complete and homogeneous austenitic (i.e. y-iron) structure.

a

Rapidly cool to 250° C, hold for 10^{3} s, then quench to room temperature.

✓ Answer
Martensite

b

Rapidly cool to 400°C, hold for 500 s, then quench to room temperature.

✓ Answer
Bainite

C

Rapidly cool to 650°C, hold at this temperature for 3 s, rapidly cool to 400°C, hold for 10 s, then quench to room temperature.

 \checkmark Answer Ferrite/ α , pearlite, bainite, martensite

d

Rapidly cool to 625°C, hold for 1 s, then quench to room temperature.

Answer
Proeutectoid ferrite, pearlite, and mertensite

4

Consider the differences between metastable and equilibrium states.

a

Martensite is a metastable phase that can be generated in steels and other systems (including other alloys, crystals, and even proteins). Describe 2 characteristics of the martensitic transformation that distinguish it from transformations that result in equilibrium microstructures.

✓ Answer

- There is no diffusion as it does not change over time
- Its stucture highly depends on how it was cooled

b

In terms of heat treatment and the development of microstructure (especially metastable vs. equilibrium states), what are two major limitations of phase diagrams like the iron-iron carbide phase diagram?

✓ Answer

- Can't predict how long it takes for a transformation to happen
- Cannot predict when metastable phases happen

5

This week, we introduced a fourth strengthening mechanism: precipitation hardening. Compare the mechanism of strengthening involved in precipitation hardening to the mechanism underlying strain hardening (think about diffusion and dislocations).

Answer

- In both, movement is slowed, which makes the metal stronger
- Strain hardening introduces dislocations while precipitation hardening introduces θ particles