# California Closets - Exhibit B

## SIGNED PLANS VS. INSTALLED CONDITIONS

Following installation, the Customer documented the conditions below, which differ from the signed plans dated October 16, 2025 (the "Plans") and the Contract. The table compares each specification with the installed condition. Impact ratings are the Customer's own assessment.

Several conditions involve measurable dimensional differences, impaired function, and reported safety-related concerns, and could not be corrected through routine adjustment.

| No. | Category | Specification | Installed Condition | Impact (Customer-Assessed) |
|---|---|---|---|---|
| 1 | Electrical Outlet | Outlet placement specified on the Plans. Right unit: 30-36 in. in from the A wall, approx. 2-3 in. up from the ledge on the B wall; and 40-46 in. in from the E wall, approx. 20-30 in. up from the ledge (height based on TV plug).<br>**Record Ref. B1**<br>**Record Ref. B2** | Outlet openings do not align with the specified locations, resulting in obstructed and impractical access.<br>**Record Ref. B3** | **Critical**<br>Reported safety concern<br>Functional access failure<br>Usability impairment |
| 2 | Lighting Operation | Lighting to activate only through intended door or drawer engagement<br>**Record Ref. B1** | Lighting activates without engagement, flickers, and generates excess heat.<br>**Record Ref. B4** | **Critical**<br>Reported safety concern<br>Functional defect |
| 3 | Electrical Concealment | Outlet and transformer to be covered by a California Closets enclosure (left unit Plans)<br>**Record Ref. B1** | Enclosure not provided. Surge protectors and wiring remain exposed within active storage areas.<br>**Record Ref. B5** | **Critical**<br>Reported safety concern<br>Usability issue |

| No. | Category | Specification | Installed Condition | Impact (Customer-Assessed) |
|---|---|---|---|---|
| 4 | Built-In Wall Integration | Full recessed built-in appearance with flush wall terminations and minimal visible gaps<br>**Record Ref. B1** | Approx. 2-inch visible side gaps on both sides of installed units.<br>**Record Ref. B6** | **High**<br>Material dimensional non-conformance |
| 5 | Fillers / Tolerances | 0.75-inch automatic fillers. Plans note that the notch is cut in shop based on designer measurements.<br>**Record Ref. B1** | Approx. 3-inch fillers required due to fitment / measurement discrepancies.<br>**Record Ref. B6** | **High**<br>Measurement discrepancy |
| 6 | Base Alignment | Plans note: “Lower rail to have unit sit directly on ledge”<br>**Record Ref. B1** | Bases elevated on feet, creating approx. 0.5-inch visible gaps.<br>**Record Ref. B7** | **High**<br>Installation non-conformance |
| 7 | Inset Doors and Drawers | Flush and uniform inset alignment<br>**Record Ref. B1** | Excessive and inconsistent gaps at doors and drawers.<br>**Record Ref. B6** | **Moderate**<br>Fitment defect |
| 8 | Push-to-Open Hardware | Handle-free push-to-open operation<br>**Record Ref. B1** | Mechanisms failed during normal use. Adhesive components detached. Doors no longer operate as designed.<br>**Record Ref. B8** | **High**<br>Functional failure |
| 9 | Finish Orientation | Vertical grain finish specified for visible focal panel areas<br>**Record Ref. B9** | Horizontal grain installed on primary focal panel area behind television.<br>**Record Ref. B10** | **Moderate**<br>Design deviation |
| 10 | NYC DOB Inspection | Receptacle accessible for inspection (Permit M01419562-I1-EL)<br>**Record Ref. B1** | Aug 6, 2026: Electrical Inspection No. 7571390 resulted in Fail-Final. Receptacle concealed behind millwork and not accessible for inspection.<br>**Record Ref. B11** | Reinspection cannot proceed until access is restored |

**CONDITIONS NOT CORRECTABLE BY ADJUSTMENT**

Several conditions could not be corrected through routine service adjustment. On January 30, 2026, the Company's Sales Manager confirmed that certain conditions required removal. These include:

1. Obstructed outlet access

2. Dimensional gap conditions

3. Oversized filler requirements

4. Base alignment issues

5. Concealment deficiencies

**REPORTED ELECTRICAL AND SAFETY CONDITIONS**

The following conditions were reported to the Company beginning in November 2025 (Exhibit D):

1. Obstructed access to electrical infrastructure

2. Exposed surge protectors and wiring components

3. Unintended lighting activation

4. Flickering lighting behavior

5. Excess heat generation near stored contents

6. Hardware failures affecting normal operation