California Closets - Exhibit B

SIGNED PLANS VS. INSTALLED CONDITIONS

Following installation, the Customer documented the conditions below, which differ from the signed plans dated October 16, 2025 (the “Plans”) and the Contract. The table compares each specification with the installed condition. Impact ratings are the Customer’s own assessment.

Several conditions involve measurable dimensional differences, impaired function, and reported safety-related concerns, and could not be corrected through routine adjustment.

No.	Category	Specification	Installed Condition	Impact (Customer-Assessed)
1	Electrical Outlet	Outlet placement specified on the Plans. Right unit: 30-36 in. in from the A wall, approx. 2-3 in. up from the ledge on the B wall; and 40-46 in. in from the E wall, approx. 20-30 in. up from the ledge (height based on TV plug). A cutout was to be provided for access to the TV outlet. **Record Ref. B1** **Record Ref. B2**	Outlet openings do not align with the specified locations, resulting in permanently obstructed and impractical access; the outlets cannot be reached without removing the units. A licensed electrician assessed the installation on May 7, 2026 and stated in writing that the design and placement of the outlets would not pass a DOB inspection because receptacles must be in accessible locations. The letter reports that the access panel (cutout) California Closets was expected to install directly in front of the TV outlet was instead placed more than a foot from the outlet, that the wardrobe outlet cannot practically be reached, and that the TV outlet condition presents a potential fire hazard. The electrician states that its work followed the closet drawings it was provided, which are the signed Plans. **Record Ref. B3** **Record Ref. B4**	**Critical** Reported safety concern Functional access failure Usability impairment
2	Lighting Operation	Lighting to activate only through intended door or drawer engagement **Record Ref. B1**	Lighting activates without engagement, flickers, and generates excess heat. The licensed electrician's May 7, 2026 assessment also noted that the button light remains illuminated when the door is closed. **Record Ref. B5** **Record Ref. B4**	**Critical** Reported safety concern Functional defect

No.	Category	Specification	Installed Condition	Impact (Customer-Assessed)
3	Electrical Concealment	Outlet and transformer to be covered by a California Closets enclosure (left unit Plans) **Record Ref. B1**	Enclosure not provided. Surge protectors and wiring remain exposed within active storage areas. **Record Ref. B6**	**Critical** Reported safety concern Usability issue
4	Built-In Wall Integration	Full recessed built-in appearance with flush wall terminations and minimal visible gaps. Plans specify 0.75-inch automatic fillers and note that gaps are inherent on all California Closet systems. **Record Ref. B1**	Approx. 2-inch visible side gaps on both sides of installed units. **Record Ref. B7**	**High** Material dimensional non-conformance
5	Fillers / Tolerances	0.75-inch automatic fillers. Plans note that the notch is cut in shop based on designer measurements. **Record Ref. B1**	Approx. 3-inch fillers required because the measurements taken did not account for the full space at the sides. The Designer stated on Nov 21, 2025 that she sizes measurements down as a precaution (**Record Ref. G1**). The Company's repair team confirmed on Jan 16, 2026 that measurement and access issues could not be corrected in place (Exhibit D). **Record Ref. B7**	**High** Measurement discrepancy
6	Base Alignment	Plans for each of the two units note: "Lower rail to have unit sit directly on ledge" **Record Ref. B1**	Bases of both units elevated on feet, creating approx. 0.5-inch visible gaps beneath each unit. **Record Ref. B8**	**High** Installation non-conformance
7	Inset Doors and Drawers	Flush and uniform inset alignment **Record Ref. B1**	Excessive and inconsistent gaps at doors and drawers. **Record Ref. B7**	**Moderate** Fitment defect

No.	Category	Specification	Installed Condition	Impact (Customer-Assessed)
8	Push-to-Open Hardware	Handle-free push-to-open operation **Record Ref. B1**	Mechanisms failed during normal use. Adhesive components detached. Doors no longer operate as designed. **Record Ref. B9**	**High** Functional failure
9	Finish Orientation	Vertical grain finish specified for visible focal panel areas **Record Ref. B10**	Horizontal grain installed on primary focal panel area behind television. **Record Ref. B11**	**Moderate** Design deviation
10	NYC DOB Inspection	Receptacle accessible for inspection (Permit M01419562-I1-EL) **Record Ref. B1**	Aug 6, 2026: Electrical Inspection No. 7571390 resulted in Fail-Final. Receptacle concealed behind millwork and not accessible for inspection. The obstructed outlets are behind permanently installed millwork in both units (see row 1). **Record Ref. B12**	Reinspection cannot proceed until access is restored

CONDITIONS NOT CORRECTABLE BY ADJUSTMENT

Several conditions could not be corrected through routine service adjustment. On January 30, 2026, the Company's Sales Manager concluded, following an on-site review, that the excessive gaps and the blocked outlets could not be addressed without removal (**Record Ref. G2**). These include:

1. Obstructed outlet access

2. Dimensional gap conditions

3. Oversized filler requirements

4. Base alignment issues

5. Concealment deficiencies

REPORTED ELECTRICAL AND SAFETY CONDITIONS

The following conditions were reported to the Company beginning in November 2025 (Exhibit D). A licensed electrician's written assessment dated June 19, 2026 addresses the outlet access and lighting items (Record Ref. B4):

1. Obstructed access to electrical infrastructure

2. Exposed surge protectors and wiring components

3. Unintended lighting activation

4. Flickering lighting behavior

5. Excess heat generation near stored contents

6. Hardware failures affecting normal operation