

MERIDIAN INDUSTRIAL SERVICES

Contract Maintenance · Material Handling · 4471 W Dixie Hwy, Bolingbrook IL 60440 · (630) 555-0148

FIELD SERVICE WORK ORDER

W/O NUMBER: MIS-44182

DATE OF SERVICE: 04/06/2026

CUSTOMER: Northstar Retail Distribution

PO REF: NRD-MNT-2026-0331

SITE: Joliet DC, Bldg 2

ARRIVED: 07:15 DEPARTED: 15:50

EQUIPMENT: Sortation line, "SR440"

TECHNICIAN: R. Vasquez, Lead Tech

CALLED IN BY: T. Okafor, Maint Supv

BILLING: T&M, contract rate

SERVICE CLASSIFICATION (check all that apply)

☒ Corrective repair

☐ Preventive maint

☒ Parts replaced

☐ Warranty work

☒ Billable T&M

☒ Controls modified

☐ OEM authorized

☐ Full validation done

☒ Customer approved on site

REPORTED CONDITION

Customer reports intermittent stoppages on main sort line, 3-4 events per shift over prior two weeks. Maint supv states drive is "running hot" and throwing overtemp faults during peak. Requests we look at it before peak season. Customer indicates OEM lead time was quoted at 3 weeks and they cannot wait.

WORK PERFORMED

Checked drive enclosure temps at three points during run. Recorded 71C, 74C, 78C at power stage housing under sustained load. Ambient in aisle was 29C. Drive fault log showed repeated thermal cutback events. Visual on the existing unit shows discoloration on the heatsink face.

Advised customer the drive should be replaced. OEM unit not available in required window per customer. Customer authorized substitution with equivalent unit from our stock. Installed unit as follows:

Position	Removed	Installed
Main sort drive	CR-DRV-4410-B (Rev B), s/n 4410B-22781	Altek AD-5500-HD, s/n AD55-91043

Substitute unit is rated at same HP and voltage. Frame and mounting pattern required a 6mm adapter plate, fabricated on site. Unit is not a drop-in but fits within the existing guard envelope.

CONTROLS ADJUSTMENTS

Replacement drive would not hold the existing accel profile without tripping on the first divert wave. Adjusted the following parameters to get the line running:

Parameter	Was	Set to	Reason
-----------	-----	--------	--------

ACCEL_RAMP_MS	420	610	Reduce inrush on start
CURRENT_LIM_PCT	115	135	Prevent nuisance trip at divert
THERM_CUTBACK_C	68	82	Substitute unit runs warmer by spec

Line ran clean for 90 min observed after adjustment. Customer maintenance witnessed startup.

TESTING / VALIDATION

Performed run-in at operating speed for 90 minutes. Did NOT perform full OEM commissioning test sequence. We do not have the OEM test fixture or the current baseline document on file for this line. Recommended customer obtain sign-off from the OEM. Customer maintenance supervisor indicated they would "handle that side of it."

TECHNICIAN NOTES

Told the supervisor twice that raising the thermal cutback is a stopgap and the root cause of the original overheating was never established. He acknowledged. Recommend OEM review before peak. Also the aisle has poor airflow, two of the four ceiling fans in that bay are not running.

PARTS & LABOR

Item	Qty	Amount
Altek AD-5500-HD drive assembly	1	\$11,480.00
Adapter plate, fabricated	1	\$340.00
Labor, lead technician, 8.5 hr	8.5	\$1,487.50
TOTAL		\$13,307.50

Technician · R. Vasquez

Customer acceptance · T. Okafor

Illustrative document created for the FUSION 2026 demonstration. All parties are fictional.