

ENGINEERING CHANGE NOTICE

ECN Number:	2025-031	Priority:	URGENT
Date Issued:	February 28, 2025	Effectivity:	IMMEDIATE
Originated By:	R. Patel, Design Eng.	Approved By:	J. Harrison, QE

AFFECTED DOCUMENTS

Document	Current Rev	New Rev	Description
DWG 5219 — Drive Shaft Assy	B	C	Tolerance change on bearing journal

DESCRIPTION OF CHANGE

Bearing journal diameter tolerance changed from 1.0000 $\pm$ 0.0005 to 1.0000 +0.0000/-0.0003 to address interference fit issues reported during assembly. Concentricity callout tightened from 0.002 TIR to 0.001 TIR per customer requirement.

REASON FOR CHANGE

Field returns showing premature bearing failure traceable to oversized journal diameters on 3 units from Lot 2024-L47. Root cause: symmetric tolerance allowed journals up to 1.0005 which caused excessive press-fit stress on the outer race.

DISPOSITION OF EXISTING STOCK

Use as-is: Parts measuring 1.0000 or below may be used. Rework: Parts measuring 1.0001-1.0005 shall be reworked by grinding to the new tolerance. Scrap: None required at this time.