

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** February 14, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2089
License Plate	TX-9GK-1143
Make / Model	Kenworth T680
Year	2020
VIN	1XKWDB9X5LJ345678
Engine Type	PACCAR MX-13
Odometer Reading	218,740 miles
Assigned Route	Gulf Coast Long Haul
Primary Driver	B. Williams

Maintenance Summary

Service Type: Preventive Maintenance (PM-C) – 210,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-02-2089
Service Date: February 12, 2025
Technician: S. Patel (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- Coolant level low – topped off 1.2 gal, monitor for leak
- Minor coolant seepage at hose clamp – tighten and monitor

Transmission

- ✓ Fluid level checked – normal
- Slight shudder at low RPM – monitor

Braking System

- Front brake pads at 28% remaining – replacement required by 225,000 miles
- ✓ Rear brake pads at 52% remaining
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – no play
- Both front shocks showing wear – recommend replacement within 15,000 miles
- ✓ Leaf springs and bushings intact

Tires

Position	Tread Depth	Condition
Steer Axle L	5/32"	Edge wear – monitor
Steer Axle R	5/32"	Edge wear – monitor
Drive Axles	8/32" avg	Good

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- ✓ Battery voltage: 12.6V (resting)
- ✓ Alternator output within range
- Replaced headlight assembly (driver side)

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical fault code: EGR valve fault (resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	PAC-MX13-FLT	1
Fuel Filter Kit	FF-MX13-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	11
Headlight Assembly	HL-KW-DRV	1

Labor Summary

Task	Hours
Preventive Maintenance Service	4.0
Brake Inspection	1.0
Electrical Repair	0.5
Diagnostic Scan	0.5
Total Labor Hours	6.0 hrs

Cost Summary

Category	Cost
Parts	\$978.50
Labor	\$690.00
Shop Supplies	\$60.00
Total Service Cost	\$1,728.50

Upcoming Recommended Maintenance

Item	Recommended At
Front Brake Pad Replacement	225,000 miles
Shock Absorber Replacement (Front)	230,000 miles
Tire Rotation & Inspection	225,000 miles
Annual DOT Inspection	February 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	February 13, 2025
Next Scheduled Maintenance:	225,000 miles or 90 days (whichever occurs first)