

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** August 22, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2167
License Plate	TX-6VH-4430
Make / Model	Kenworth W990
Year	2022
VIN	1XKWDB9X3NJ567890
Engine Type	PACCAR MX-13
Odometer Reading	121,640 miles
Assigned Route	Gulf Coast Long Haul
Primary Driver	H. Davis

Maintenance Summary

Service Type: Preventive Maintenance (PM-B) – 120,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-08-2167
Service Date: August 20, 2025
Technician: S. Patel (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- ✓ Coolant level inspected – OK

Transmission

- ✓ Fluid level checked – normal
- ✓ No abnormal noise or vibration

Braking System

- ✓ Front brake pads at 62% remaining
- ✓ Rear brake pads at 65% remaining
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – no play

- Left front shock absorber softening – recommend replacement within 15,000 miles
- ✓ Leaf springs and bushings intact

Tires

Position	Tread Depth	Condition
Steer Axle L	8/32"	Even wear
Steer Axle R	8/32"	Even wear
Drive Axles	10/32" avg	Good

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- ✓ Battery voltage: 12.8V (resting)
- ✓ Alternator output within range
- Replaced rear marker light assembly

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical fault code: Low boost (resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	PAC-MX13-FLT	1
Fuel Filter Kit	FF-MX13-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	11
Marker Light Assembly	ML-AMB-TRK	1

Labor Summary

Task	Hours
Preventive Maintenance Service	4.0
Electrical Repair	0.5
Diagnostic Scan	0.5
Total Labor Hours	5.0 hrs

Cost Summary

Category	Cost
Parts	\$756.00
Labor	\$575.00
Shop Supplies	\$50.00
Total Service Cost	\$1,381.00

Upcoming Recommended Maintenance

Item	Recommended At
Left Front Shock Absorber	135,000 miles
PM-C Service	160,000 miles
Annual DOT Inspection	August 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	August 21, 2025
Next Scheduled Maintenance:	135,000 miles or 90 days (whichever occurs first)