

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** December 5, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2183
License Plate	TX-0XZ-3348
Make / Model	Peterbilt 389
Year	2021
VIN	1XPFD9X5MD334455
Engine Type	Cummins X15
Odometer Reading	197,810 miles
Assigned Route	Texas Corridor Express
Primary Driver	J. Anderson

Maintenance Summary

Service Type: Preventive Maintenance (PM-B) – 195,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-12-2183
Service Date: December 3, 2025
Technician: R. Thompson (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- ✓ Coolant level inspected – topped off 0.6 gal
- Minor oil seepage at rocker cover – monitor next interval

Transmission

- ✓ Fluid level checked – normal
- ✓ No abnormal noise or vibration

Braking System

- Front brake pads at 33% remaining – schedule replacement within 10,000 miles
- ✓ Rear brake pads at 58% remaining
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – no play
- Right front shock absorber worn – replace within 10,000 miles
- ✓ Leaf springs and bushings intact

Tires

Position	Tread Depth	Condition
Steer Axle L	7/32"	Even wear
Steer Axle R	6/32"	Minor inner edge wear
Drive Axles	9/32" avg	Good

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- ✓ Battery voltage: 12.7V (resting)
- ✓ Alternator output within range
- Replaced marker light (front right)

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical fault code: SCR efficiency fault (resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	CUM-X15-FLT	1
Fuel Filter Kit	FF-CX15-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	12
Marker Light Assembly	ML-AMB-TRK	1

Labor Summary

Task	Hours
Preventive Maintenance Service	4.0
Brake Inspection	1.0
Electrical Repair	0.5
Diagnostic Scan	0.5
Total Labor Hours	6.0 hrs

Cost Summary

Category	Cost
Parts	\$871.00
Labor	\$690.00
Shop Supplies	\$55.00
Total Service Cost	\$1,616.00

Upcoming Recommended Maintenance

Item	Recommended At
Front Brake Pad Replacement	205,000 miles
Right Front Shock Absorber	205,000 miles
PM-C Service	240,000 miles
Annual DOT Inspection	December 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	December 4, 2025
Next Scheduled Maintenance:	205,000 miles or 90 days (whichever occurs first)