

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** July 11, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2045
License Plate	TX-3CE-8812
Make / Model	Mack Anthem 64T
Year	2018
VIN	1M2AN07Y8JM112344
Engine Type	Mack MP8
Odometer Reading	389,210 miles
Assigned Route	Texas Corridor Express
Primary Driver	G. Martinez

Maintenance Summary

Service Type: Preventive Maintenance (PM-D) – 385,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-07-2045
Service Date: July 9, 2025
Technician: R. Thompson (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- Coolant system flushed and refilled
- Oil consumption elevated – burn-off approx 0.5 qt/5,000 miles, monitor
- Exhaust manifold gasket seeping – replacement recommended at next major service

Transmission

- Transmission fluid replaced
- Transmission shifting rough – inspection recommended within 10,000 miles

Braking System

- Front brake pads replaced – new
- Rear brake pads at 30% remaining – replace within 20,000 miles
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – some play noted – alignment check recommended
- Front shock absorbers replaced
- Rear shocks worn – replace within 20,000 miles

Tires

Position	Tread Depth	Condition
Steer Axle L	6/32"	Moderate wear
Steer Axle R	5/32"	Moderate wear
Drive Axles	7/32" avg	Moderate wear

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- Battery voltage: 12.2V – battery replaced
- ✓ Alternator output within range
- Replaced battery

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified – replaced
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- 1 active code: SCR system efficiency (DEF quality fault) – DEF drained and refilled, monitor
- Historical codes: DPF pressure fault, turbo underboost (both resolved)
- Emissions system functioning – monitor SCR

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	MCK-MP8-FLT	1
Fuel Filter Kit	FF-MP8-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	11
Transmission Fluid (qt)	TF-MCK-STD	8
Front Brake Pad Set	BP-MCK-FRT	1
Front Shock Absorber (pair)	SA-MCK-FRT	1
Battery (12V)	BAT-12V-HVY	1
Fire Extinguisher (5 lb)	FE-5LB-ABC	1

Labor Summary

Task	Hours
Preventive Maintenance Service	5.0

Brake Service	2.0
Suspension Service	2.0
Electrical Service	1.0
Diagnostic Scan	0.5
Total Labor Hours	10.5 hrs

Cost Summary

Category	Cost
Parts	\$1,875.00
Labor	\$1,207.50
Shop Supplies	\$90.00
Total Service Cost	\$3,172.50

Upcoming Recommended Maintenance

Item	Recommended At
Rear Brake Pads	405,000 miles
Rear Shock Absorbers	405,000 miles
Transmission Inspection	395,000 miles
Exhaust Manifold Gasket	Next major service
Annual DOT Inspection	July 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	July 10, 2025
Next Scheduled Maintenance:	395,000 miles or 60 days (whichever occurs first)