


2 Troubleshooting IP-79: Error codes 13, 23 2 - 211 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter Manual CD Main Index Contents Screen

IP-79 (pg 2 of 2)



	With Carousel Home Sensor blocked, check voltage(s) on Motor Driver Bd:				
	If 5V at J1-7 and NOT 1V at J4-8 Replace Motor Driver Bd (RR-8.5).				
	If NOT 5V at J1-7 Replace Digital I/O Bd (RR-7.1/7.10).				
	1V at J4-8 Replace Carousel Motor Assy (RR-3.3).				
	If (L) at J4-10 Replace Motor Driver Bd (RR-8.5).				
	If NOT 5V at J4-10	Replace Carousel Motor Assy (RR-3.3).			
	When HOME key is pressed, check voltage(s) on Motor Driver Bd:				
No transition from <3V to >15V at J4-12 Replace Motor Driver Bd (RR-8					

IP79-2.vsd

2 Troubleshooting IP-79: Error codes 13, 23 2 - 212 LCx[®] Analyzer Service Manual (Text P/N 47278-102)

No switch from 1V to 5V at J1-33

No switch from 5V to 1V at J1-36

	Chapter Contents	Manual Contents	CD Main Screen	Index
--	---------------------	--------------------	-------------------	-------

Replace Digital I/O Bd (RR-7.1/7.10).

Replace Digital I/O Bd (RR-7.1/7.10).