# EE6303D

# Dynamics of Electrical Machines (DEM)

Module 1, 2


#### Relevance

#### How to run any machine for variable speed application??





Electrical machines, despite the differences in their construction and characteristics, have a lot in common. In earlier days, different types of machine were analysed in quite different ways, until in 1934 Dr. Gabriel Kron showed that all machines are basically the same, and can be analysed with the same set of generalised matrix equations. Kron's researches started a trend towards generalised machine concepts in the analysis of all types of machines

Dr. Gabriel Kron



Permeability is the measure of magnetization that a material obtains in response to an applied magnetic field





$$E = \int_0^t V i \mathrm{d}t = \int_0^{\psi_1} i \mathrm{d}\psi$$

$$\Phi = Ni\mathscr{P} \quad (Wb)$$

$$\mathscr{P} = \mu A/l$$

$$\psi = N\Phi = N^2 i \mathscr{P}$$

Faraday-Lenz law

$$e = -\frac{\mathrm{d}\psi}{\mathrm{d}t} = -\frac{\mathrm{d}}{\mathrm{d}t}(N^2 \mathscr{P}i)$$

If the number of turns and the magnetic permeance do not change with time then

$$e = -N^2 \mathscr{P} \frac{\mathrm{d}i}{\mathrm{d}t} = -L \frac{\mathrm{d}i}{\mathrm{d}t}$$

Permeance is the property of allowing the passage of lines of magnetic flux


If the coils are in motion, this relation is no longer true and we have to write

$$e = -\frac{d(Li)}{dt}$$

$$= -L\frac{di}{dt} - i\frac{dL}{dt}$$

$$= -L\frac{di}{dt} - i\frac{\partial L}{\partial x}\frac{dx}{dt}$$

if L changes with x.



$$V = Ri + \frac{d}{dt} (Li)$$

$$= Ri + L \frac{di}{dt} + i \frac{\partial L}{\partial x} \cdot \frac{dx}{dt}$$

$$Vi = Ri^{2} + iL \frac{di}{dt} + i^{2} \frac{\partial L}{\partial x} \frac{dx}{dt}$$

 $=Ri^{2}+\frac{\mathrm{d}}{\mathrm{d}t}(\frac{1}{2}Li^{2})+\frac{1}{2}i^{2}\frac{\partial L}{\partial x}\frac{\mathrm{d}x}{\mathrm{d}t}$ 

$$P_{\rm e} = \left(\frac{1}{2}i^2\frac{\partial L}{\partial x}\right) \left(\frac{\mathrm{d}x}{\mathrm{d}t}\right)$$

First term: power loss due to the resistance of the coil

Second term: rate of change of the stored magnetic energy (i.e. reactive power).

Third term: the power necessary to accelerate the plunger and overcome the tension of the spring. This term represents the mechanical power. Since it has electrical origin it may be called electromechanical power

electromechanical force

$$f_{\rm e} = \frac{1}{2}i^2 \frac{\partial L}{\partial x}$$

 $m\frac{\mathrm{d}^2 x}{\mathrm{d}t^2} + Kx - \frac{1}{2}i^2\frac{\partial L}{\partial x} = 0$ 

(electrodynamic equation of the plunger)


K is the stiffness of the spring


involves the square of the current, this implies that irrespective of the direction of the currents through the coil the force on the plunger acts only in one direction. Reversing the polarity of the d.c. source, or replacing it by an a.c. source will not alter the direction of force.

in which direction does the force act?

Clearly fe is positive if dL/dx is positive which implies that the plunger will move in such a direction that L increases with x or that the permeance increases with x, i.e., it will tend to move into the coil. This movement will be opposed by the spring and the acceleration will depend on the resultant of these opposing forces

If the plunger overshoots through the coil, the force f will reverse its direction and combine with the restoring force from the spring to pull the plunger back into the coil. It may be generally said that the electromechanical force will act in such a direction as to make the reluctance of the magnetic path a minimum





$$\mathscr{E} = N^2 \mathscr{P} \int_0^i i \mathrm{d}i = \frac{1}{2} L i^2 \quad (\mathbf{J})$$

$$\mathscr{E}_{\rm c} = \frac{1}{2}CV^2 = \frac{1}{2}q^2/C$$

kinetic energy = 
$$\frac{1}{2}mv^2$$
  
=  $\frac{1}{2}J\omega^2$ 

$$\int_0^x F \, \mathrm{d}x = \int_0^x Kx \, \mathrm{d}x = \frac{1}{2}Kx^2$$

$$L\ddot{q} + R\dot{q} + q/C = V$$

electrical network

$$m\ddot{x} + D\dot{x} + Kx = F$$
,

mechanical system

the analogy in general form: Lagrange's equation

#### The Lagrangian

$$\mathscr{L} = \mathscr{T} - \mathscr{V}$$



Joseph-Louis Lagrange

#### Lagrangian equation in general form for a system with 'n' degrees of freedom

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} = 0$$

kinetic energy of the mass


$$\mathscr{T} = \frac{1}{2}mv^2 = \frac{1}{2}m(\dot{x})^2$$

potential energy stored in the spring

$$\mathscr{V} = \int_0^x F \, \mathrm{d}x = \int_0^x Kx \, \mathrm{d}x = Kx^2/2$$

$$\frac{\partial \mathcal{F}}{\partial \dot{x}} = \frac{\partial}{\partial \dot{x}} \left[ \frac{1}{2} m (\dot{x})^2 \right] = m \dot{x} = m v$$

$$\frac{\partial \mathscr{V}}{\partial x} = \frac{\partial}{\partial x} \left( \frac{1}{2} K x^2 \right) = K x = F$$




$$\mathscr{L} = \mathscr{T} - \mathscr{V}$$

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} = 0$$

Newton's second law of motion

$$\frac{\mathrm{d}}{\mathrm{d}t}(mv) = -F$$

negative sign appears in this case because force is a restoring force



$$\frac{\partial \mathcal{F}}{\partial \dot{x}} = \frac{\partial}{\partial i} \left( \frac{1}{2} L i^2 \right) = L i$$

$$\frac{\partial \mathscr{V}}{\partial q} = \frac{\partial}{\partial q} \left( \frac{1}{2} \frac{q^2}{C} \right) = \frac{q}{C}$$

$$\mathscr{L} = \mathscr{T} - \mathscr{V}$$

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} = 0$$

Substituting these values into Lagrange's equation

$$\frac{\mathrm{d}}{\mathrm{d}t}(Li) + \frac{q}{C} = 0 \qquad \qquad L\frac{\mathrm{d}i}{\mathrm{d}t}$$

$$L\frac{\mathrm{d}i}{\mathrm{d}t} + \frac{q}{C} = 0$$

#### The Lagrangian


$$\mathscr{L} = \mathscr{T} - \mathscr{V}$$

In order to include the effects of loss, a velocity-dependent (or current-dependent) function, the Rayleigh dissipation function is adopted

$$\frac{\partial \mathscr{F}}{\partial \dot{x}_n} = R_n \dot{x}_n \text{ represents force (or voltage)} \qquad \mathscr{F} = \sum_{n=1}^k \frac{1}{2} R_n (\dot{x}_n)^2$$

Lagrangian equation in general form for a system with 'n' degrees of freedom

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} + \frac{\partial \mathcal{F}}{\partial \dot{x}_n} = V_n$$



$$\mathcal{L} = \mathcal{T} - \mathcal{V}$$

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} + \frac{\partial \mathcal{F}}{\partial \dot{x}_n} = V_n$$


Substituting these values into Lagrange's equation

$$L\frac{\mathrm{d}^2 q}{\mathrm{d}t^2} + R\frac{\mathrm{d}q}{\mathrm{d}t} + \frac{q}{C} = V$$

$$\frac{\partial \mathcal{F}}{\partial \dot{x}} = \frac{\partial}{\partial i} \left( \frac{1}{2} L i^2 \right) = L i$$

$$\frac{\partial \mathscr{V}}{\partial q} = \frac{\partial}{\partial q} \left( \frac{1}{2} \frac{q^2}{C} \right) = \frac{q}{C}$$

$$\frac{\partial \mathscr{F}}{\partial \dot{x}_n} = R_n \dot{x}_n$$




$$\mathcal{L} = \mathcal{T} - \mathcal{V}$$

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} + \frac{\partial \mathcal{F}}{\partial \dot{x}_n} = V_n$$

Substituting these values into Lagrange's equation

$$m\frac{\mathrm{d}^2x}{\mathrm{d}t^2} + b \frac{\mathrm{d}x}{\mathrm{d}t} + Kx = F$$



Total kinetic energy

$$\mathcal{F} = \frac{1}{2}Li^2 + \frac{1}{2}mv^2$$
  $\mathcal{V} = \frac{1}{2}Kx^2$   $\mathcal{F} = \frac{1}{2}Ri^2 + \frac{1}{2}Dv^2$ 

elect mech Total potential energy

Dissipation function

$$\mathscr{V} = \frac{1}{2}Kx^2$$

$$\mathscr{F} = \frac{1}{2}Ri^2 + \frac{1}{2}Dv^2$$

mechanical

elect mech

$$\mathcal{L} = \mathcal{F} - \mathcal{V} = \frac{1}{2}L\dot{x}_1^2 + \frac{1}{2}m\dot{x}_2^2 - \frac{1}{2}Kx_2^2$$
$$\mathcal{F} = \frac{1}{2}R\dot{x}_1^2 + \frac{1}{2}D\dot{x}_2^2$$

$$\frac{\partial \mathcal{L}}{\partial \dot{x}_1} = L\dot{x}_1 \qquad \frac{\partial \mathcal{L}}{\partial x_1} = 0 \qquad \frac{\partial \mathcal{F}}{\partial \dot{x}_1} = R_1 \dot{x}_1$$

 $V_n = V_1$  = voltage applied to the coil

$$L\frac{\mathrm{d}i}{\mathrm{d}t} + Ri + i\frac{\mathrm{d}L}{\mathrm{d}t} = V_1$$

(Voltage equation of the coil)


$$\frac{\partial \mathcal{L}}{\partial \dot{x}_{2}} = m\dot{x}_{2} \qquad \frac{\partial \mathcal{L}}{\partial x_{2}} = -Kx_{2} + \frac{1}{2}\dot{x}_{1}^{2} \frac{\partial L}{\partial x_{2}}$$

$$\frac{\partial \mathcal{F}}{\partial x_{2}} = D\dot{x}_{2} \qquad V_{2} = \text{applied force} = F = 0$$

$$m\ddot{x}_{2} + D\dot{x}_{2} + Kx_{2} - \frac{1}{2}i^{2} \frac{\partial L}{\partial x_{2}} = 0$$

(Dynamic equation of the plunger)

#### **Doubly Excited Coil**



 $x_1$  represent the charge  $q_1$  through coil 1  $x_2$  represent the charge  $q_2$  through coil 2  $x_3$  represent the displacement  $\theta$  of the rotor

#### Total kinetic energy

$$\mathcal{F} = \mathcal{F}_{e} + \mathcal{F}_{m} = \frac{1}{2}L_{11}i_{1}^{2} + \frac{1}{2}L_{22}i_{2}^{2} + i_{1}i_{2}M_{12} + \frac{1}{2}J\omega^{2}$$
$$= \frac{1}{2}L_{11}\dot{x}_{1}^{2} + \frac{1}{2}L_{22}\dot{x}_{2}^{2} + \dot{x}_{1}\dot{x}_{2}M_{12} + \frac{1}{2}J\dot{x}_{3}^{2}$$

#### Total potential energy


$$\mathscr{V} = 0$$

#### **Dissipation function**

$$\mathcal{F} = \frac{1}{2}R_1 i_1^2 + \frac{1}{2}R_2 i_2^2 + \frac{1}{2}R_F \omega^2$$
$$= \frac{1}{2}R_1 \dot{x}_1^2 + \frac{1}{2}R_2 \dot{x}_2^2 + \frac{1}{2}R_F \dot{x}_3^2$$

$$\frac{\mathrm{d}}{\mathrm{d}t} \left( \frac{\partial \mathcal{L}}{\partial \dot{x}_n} \right) - \frac{\partial \mathcal{L}}{\partial x_n} + \frac{\partial \mathcal{F}}{\partial \dot{x}_n} = V_n$$

#### **Doubly Excited Coil**



 $x_1$  represent the charge  $q_1$  through coil 1  $x_2$  represent the charge  $q_2$  through coil 2  $x_3$  represent the displacement  $\theta$  of the rotor

$$\frac{\partial \mathcal{L}}{\partial \dot{x}_{1}} = \frac{\partial \mathcal{L}}{\partial i_{1}} = \frac{\partial \mathcal{F}}{\partial i_{1}} = L_{11}i_{1} + M_{12}i_{2}$$

$$\frac{\partial \mathcal{L}}{\partial \dot{x}_{2}} = \frac{\partial \mathcal{L}}{\partial i_{2}} = \frac{\partial \mathcal{F}}{\partial i_{2}} = L_{22}i_{2} + M_{12}i_{1}$$

$$\frac{\partial \mathcal{L}}{\partial \dot{x}_{3}} = \frac{\partial \mathcal{L}}{\partial \omega} = \frac{\partial \mathcal{F}}{\partial \omega} = J\omega$$

$$\frac{\partial \mathcal{F}}{\partial \dot{x}_{3}} = \frac{\partial \mathcal{F}}{\partial \omega} = \frac{\partial \mathcal{F}}{\partial \omega} = J\omega$$

$$\frac{\partial \mathcal{F}}{\partial \dot{x}_{2}} = \frac{\partial \mathcal{F}}{\partial i_{2}} = R_{2}i_{2}$$

$$\frac{\partial \mathcal{F}}{\partial \dot{x}_{3}} = \frac{\partial \mathcal{F}}{\partial \omega} = \frac{\partial \mathcal{F}}{\partial \omega} = R_{F}\omega$$


$$\frac{\partial \mathcal{F}}{\partial \dot{x}_{3}} = \frac{\partial \mathcal{F}}{\partial \omega} = R_{F}\omega$$

$$V_{1} = R_{1}i_{1} + p[L_{11}i_{1} + M_{12}i_{2}]$$

$$V_{2} = R_{2}i_{2} + p[L_{22}i_{2} + M_{12}i_{1}]$$

$$0 = R_{F}\omega + Jp\omega - \left[\frac{1}{2}i_{1}^{2}\frac{\partial L_{11}}{\partial \theta} + \frac{1}{2}i_{2}^{2}\frac{\partial L_{22}}{\partial \theta} + i_{1}i_{2}\frac{\partial M_{12}}{\partial \theta}\right]$$

#### Solution!



$$L\frac{\mathrm{d}i}{\mathrm{d}t} + Ri + i\frac{\mathrm{d}L}{\mathrm{d}t} = V_1$$

$$m\ddot{x}_2 + D\dot{x}_2 + Kx_2 - \frac{1}{2}i^2\frac{\partial L}{\partial x_2} = 0$$

How to know nature of plunger movement or supply current?

The product of the dependent variables, current and velocity in the voltage equations and the square of the current in the dynamical equation, make it difficult to derive a closed form solution.

By considering small perturbations about the operating point these equations can be linearised and a solution obtained. This is standard practice in considering small oscillations in electrical machines. Linearisation of the equations where fairly large displacements are involved leads to considerable errors and in such cases the standard practice is to obtain numerical solutions.

**Euler's Method** 

**Runge-Kutta Method** 

#### **Euler's Method**

$$y' = f(x, y)$$

'h' is a small interval defined

$$X_{n+1}-X_n$$

$$y_{n+1} = y_n + h y_n'$$

One of the major disadvantages of Euler's method is that the interval or the step length h must be very small in order to provide correct results. Selecting large step sizes often leads to divergence or numerical instability.

# Runge-Kutta Method

#### Order 2

$$y_{n+1} = y_n + \frac{1}{2}(k_1 + k_2)$$

$$k_1 = h f(x_n, y_n)$$
  
$$k_2 = h f(x_n + h , y_n + k_1)$$

#### Order 4

$$y_{n+1} = y_n + \frac{1}{6}(k_1 + 2k_2 + 2k_3 + k_4)$$

$$k_1 = h f(x_n, y_n)$$

$$k_2 = h f(x_n + h/2, y_n + k_1)$$

$$k_3 = h f(x_n + h/2, y_n + k_2)$$

$$k_4 = h f(x_n + h, y_n + k_3)$$

$$pi = -\frac{R}{L}i - \frac{1}{L}i\frac{\partial L}{\partial x}v + \frac{V}{L}$$

$$pv = -\frac{D}{m}v - \frac{Kx}{m} + \frac{1}{2m}i^2\frac{\partial L}{\partial x}$$

$$px = v$$

#### Euler's Method

$$y' = f(x, y)$$

$$y_{n+1} = y_n + h y_n'$$

'h' is a small interval defined

$$x_{n+1}-x_n$$

#### Runge-Kutta Method

$$y_{n+1} = y_n + \frac{1}{6}(k_1 + 2k_2 + 2k_3 + k_4)$$


$$k_1 = h f(x_n, y_n)$$


$$k_2 = h f(x_n + h/2, y_n + k_1)$$

$$k_3 = h f(x_n + h/2, y_n + k_2)$$

$$k_4 = h f(x_n + h, y_n + k_3)$$

# Solution using RK4





#### **Tutorial Problems #1**

# Use the Runge-Kutta method with h=0.1 to find approximate values for the solution of the problem at x=0.1, 0.2.

$$y' + 2y = x^3 e^{-2x}, \quad y(0) = 1$$
 
$$f(x,y) = -2y + x^3 e^{-2x}, \ x_0 = 0, \ \mathrm{and} \ y_0 = 1.$$

#### x = 0.1

$$\begin{aligned} k_{10} &= f(x_0,y_0) = f(0,1) = -2, \\ k_{20} &= f(x_0 + h/2,y_0 + hk_{10}/2) = f(.05,1 + (.05)(-2)) \\ &= f(.05,.9) = -2(.9) + (.05)^3 e^{-.1} = -1.799886895, \\ k_{30} &= f(x_0 + h/2,y_0 + hk_{20}/2) = f(.05,1 + (.05)(-1.799886895)) \\ &= f(.05,.910005655) = -2(.910005655) + (.05)^3 e^{-.1} = -1.819898206, \\ k_{40} &= f(x_0 + h,y_0 + hk_{30}) = f(.1,1 + (.1)(-1.819898206)) \\ &= f(.1,.818010179) = -2(.818010179) + (.1)^3 e^{-.2} = -1.635201628, \\ y_1 &= y_0 + \frac{h}{6}(k_{10} + 2k_{20} + 2k_{30} + k_{40}), \\ &= 1 + \frac{.1}{6}(-2 + 2(-1.799886895) + 2(-1.819898206) - 1.635201628) = .818753803, \end{aligned}$$

#### Cont...

#### x=0.2

$$k_{11} = f(x_1, y_1) = f(.1, .818753803) = -2(.818753803)) + (.1)^3 e^{-.2} = -1.636688875,$$

$$k_{21} = f(x_1 + h/2, y_1 + hk_{11}/2) = f(.15, .818753803 + (.05)(-1.636688875))$$

$$= f(.15, .736919359) = -2(.736919359) + (.15)^3 e^{-.3} = -1.471338457,$$

$$k_{31} = f(x_1 + h/2, y_1 + hk_{21}/2) = f(.15, .818753803 + (.05)(-1.471338457))$$

$$= f(.15, .745186880) = -2(.745186880) + (.15)^3 e^{-.3} = -1.487873498,$$

$$k_{41} = f(x_1 + h, y_1 + hk_{31}) = f(.2, .818753803 + (.1)(-1.487873498))$$

$$= f(.2, .669966453) = -2(.669966453) + (.2)^3 e^{-.4} = -1.334570346,$$

$$y_2 = y_1 + \frac{h}{6}(k_{11} + 2k_{21} + 2k_{31} + k_{41}),$$


$$= .818753803 + \frac{.1}{6}(-1.636688875 + 2(-1.471338457) + 2(-1.487873498) - 1.334570346)$$

$$= .670592417.$$


#### **Generalized Machines**


- The most numerous and the most widely used electromechanical device in existence is the magnetic field type rotating machine.
- Rotating machines occur in many different types, depending on the nature of the electrical and mechanical systems to be coupled and on the coupling characteristics desired.
- The primary purpose of most rotating machines is to convert energy between electrical and mechanical systems,
   either for electric power generation or for the production of mechanical power to do useful tasks.

Air gap field, and hence the inductances associated with, play a vital role in the analysis of the electromechanical coupling systems in rotating machines



#### **Generalized Machines**





$$\lambda_s = L_s i_s + L_{sr}(\theta) i_r,$$
 $\lambda_r = L_{sr}(\theta) i_s + L_r i_r,$ 
 $T^e = i_s i_r \frac{dL_{sr}(\theta)}{d\theta},$ 

$$\lambda_s = L_s i_s + M i_r \cos \theta,$$

$$\lambda_r = M i_s \cos \theta + L_r i_r,$$

$$T^e = -i_s i_r M \sin \theta.$$

 $L_{sr}(\theta) = M \cos \theta.$ 

$$v_s = R_s i_s + \frac{d\lambda_s}{dt}$$
 
$$v_r = R_r i_r + \frac{d\lambda_r}{dt}$$
 
$$T_m + T^e = J_r \frac{d^2\theta}{dt^2} + B_r \frac{d\theta}{dt} + T_{or} \frac{d\theta/dt}{|d\theta/dt|}.$$

# Generalized Machines/ Conditions for Conversion of Average Power

$$i_s(t) = I_s \sin \omega_s t,$$
 $i_r(t) = I_r \sin \omega_r t,$ 
 $\theta(t) = \omega_m t + \gamma,$ 


the conditions under which the machine with the steady-state excitations can convert average power between the electrical and mechanical systems

instantaneous power p<sub>m</sub>, flowing from the coupling system,

$$p_m = T^e \frac{d\theta}{dt} = T^e \omega_m.$$

$$T^e = -i_s i_r M \sin \theta.$$

$$p_m = -\omega_m I_s I_r M \sin \omega_s t \sin \omega_r t \sin (\omega_m t + \gamma).$$




# Generalized Machines/ Conditions for Conversion of Average Power

$$p_m = -\omega_m I_s I_r M \sin \omega_s t \sin \omega_r t \sin (\omega_m t + \gamma).$$

$$\sin x \sin y = \frac{1}{2} [\cos (x - y) - \cos (x + y)];$$

$$\sin x \cos y = \frac{1}{2} [\sin (x - y) + \sin (x + y)].$$



$$p_{m} = -\frac{\omega_{m}I_{s}I_{r}M}{4} \{ \sin \left[ (\omega_{m} + \omega_{s} - \omega_{r})t + \gamma \right] + \sin \left[ (\omega_{m} - \omega_{s} + \omega_{r})t + \gamma \right]$$
$$-\sin \left[ (\omega_{m} + \omega_{s} + \omega_{r})t + \gamma \right] - \sin \left[ (\omega_{m} - \omega_{s} - \omega_{r})t + \gamma \right] \}.$$

# Generalized Machines/ Conditions for Conversion of Average Power

$$p_m = -\frac{\omega_m I_s I_r M}{4} \{ \sin \left[ (\omega_m + \omega_s - \omega_r)t + \gamma \right] + \sin \left[ (\omega_m - \omega_s + \omega_r)t + \gamma \right]$$
$$-\sin \left[ (\omega_m + \omega_s + \omega_r)t + \gamma \right] - \sin \left[ (\omega_m - \omega_s - \omega_r)t + \gamma \right] \}.$$

Because a sinusoidal function of time has no average value, can have a time-average value only when one of the coefficients of 't' is zero. These four conditions, which cannot in general be satisfied simultaneously, can be written in the compact form

$$\omega_m = \pm \omega_s \pm \omega_r$$

$$\omega_m = -\omega_s + \omega_r,$$


$$p_{m(av)} = -\frac{\omega_m I_s I_r M}{4} \sin \gamma$$


It is evident from these expressions that a necessary condition for average power conversion is the frequency condition. Sufficient conditions for average power conversion are this frequency condition and  $\sin \gamma \neq 0$ 


$$\omega_m = \omega_s + \omega_r,$$

$$p_{m(av)} = \frac{\omega_m I_s I_r M}{4} \sin \gamma$$

#### **DC** machines









If the observer 'sits on one of the stator windings', the mutual inductance between the stator and the rotor coils changes as the rotor rotates. Also, if the air gap is non-uniform (as is the case with salient-pole machines) the self-inductance varies with varying reluctance of the magnetic path. Hence the impedance becomes a function of the rotor position, which makes the equations rather complicated.


We know that 3-phase voltage fed to the 3-phase winding of the stator produces a magnetic field of constant magnitude, rotating at synchronous speed. An observer 'sitting on the rotor' will see an m.m.f. of constant magnitude, stationary with respect to him, when the rotor also rotates synchronously.

#### **Synchronous machines**



#### **Synchronous machines**






4-coil primitive machine


# **Primitive Machines**

## Synchronous machines with amortisseur winding



## **Primitive Machines**

#### **Induction machines**




If the observer 'sits on the rotor', the m.m.f. vector produced by the rotor currents rotates at an angular velocity  $\omega' = 2\pi sf$  mechanical radian/second with respect to his position. To an observer on the stator, the rotor m.m.f. will appear to rotate at a frequency  $\omega' + 2\pi f(I - s) = 2\pi f$ .

Since the stator m.m.f. also rotates at an angular frequency  $2\pi f$ , the stator and rotor m.m.f. waves are again locked and stationary with respect to each other, while rotating synchronously at angular velocity  $\omega s$  in space.

#### **FUNDAMENTALS**

- Voltage induced in a coil by its own flux
- Voltage induced in a coil by external flux



voltage induced in a stator coil

$$V = Ri + d\psi/dt$$
 (transformer voltage)


equation for the applied voltage in a rotor coil will contain the terms

$$V = Ri + d\psi/dt + Bp\theta$$
app.voltage = res. + transformer + generated drop voltage voltage

Here  $Bp\theta$  is the generated voltage, which depends on the speed of the rotor and the flux density B of the magnetic field in which the coils rotate.

While calculating the transformer voltage, we assume that the conductors are stationary and the flux is changing. We then consider the flux to be constant and the conductors rotating with respect to it, in order to obtain the generated voltage.

#### Flux linkages




All these coils may not be necessary for a particular machine, in which case the appropriate coils are simply omitted and the equations are modified by deleting the corresponding rows and columns in the matrix equations.

#### Nomenclature

- The letters d and q obviously stand for direct and quadrature axes
- s for stator coils, r for rotor coils
- M<sub>d1</sub> is the mutual inductance between coil 1 on the stator and the rotor coil along the direct axis
- M<sub>d12</sub> is the mutual inductance between coils 1 and 2 in the stator along the direct axis

#### Flux linkages




# Nomenclature

- The letters d and q obviously stand for direct and quadrature axes
- s for stator coils, r for rotor coils
- M<sub>d1</sub> is the mutual inductance between coil 1 on the stator and the rotor coil along the direct axis
- M<sub>d12</sub> is the mutual inductance between coils 1 and 2 in the stator along the direct axis

$$\begin{split} \psi_{\rm dr} &= L_{\rm dr} i_{\rm dr} + M_{\rm d1} i_{\rm ds1} + M_{\rm d2} i_{\rm ds2} \\ \psi_{\rm qr} &= L_{\rm qr} i_{\rm qr} + M_{\rm q1} i_{\rm qs1} + M_{\rm q2} i_{\rm qs2} \\ \psi_{\rm ds1} &= L_{\rm ds1} i_{\rm ds1} + M_{\rm d1} i_{\rm dr} + M_{\rm d12} i_{\rm ds2} \\ \psi_{\rm qs1} &= L_{\rm qs1} i_{\rm qs1} + M_{\rm q1} i_{\rm qr} + M_{\rm q12} i_{\rm qs2} \\ \psi_{\rm ds2} &= L_{\rm ds2} i_{\rm ds2} + M_{\rm d2} i_{\rm dr} + M_{\rm d12} i_{\rm ds1} \\ \psi_{\rm qs2} &= L_{\rm qs2} i_{\rm qs2} + M_{\rm q2} i_{\rm qr} + M_{\rm q12} i_{\rm qs1} \end{split}$$

 $L_{
m dr} 
eq L_{
m qr}$  For salient pole machines

#### **Stator Voltages**



$$V_{ds1} = R_{ds1}i_{ds1} + \frac{\mathrm{d}\psi_{ds1}}{\mathrm{d}t}$$


$$V_{ds1} = R_{ds1}i_{ds1} + L_{ds1}pi_{ds1} + M_{d1}pi_{dr} + M_{d12}pi_{ds2}$$

$$V_{\rm ds2} = R_{\rm ds2}i_{\rm ds2} + L_{\rm ds2}pi_{\rm ds2} + M_{\rm d2}pi_{\rm dr} + M_{\rm d12}pi_{\rm ds1}$$

$$V_{\rm qs1} = R_{\rm qs1}i_{\rm qs1} + L_{\rm qs1}pi_{\rm qs1} + M_{\rm q1}pi_{\rm qr} + M_{\rm q12}pi_{\rm qs2}$$

$$V_{\rm qs2} = R_{\rm qs2}i_{\rm qs2} + L_{\rm qs2}pi_{\rm qs2} + M_{\rm q2}pi_{\rm qr} + M_{\rm q12}pi_{\rm qs1}$$

#### **Rotor Voltages**



$$V_{dr} = R_{dr}i_{dr} + \frac{d\psi_{dr}}{dt} + B_{qr}p\theta$$

$$V_{qr} = R_{qr}i_{qr} + \frac{d\psi_{qr}}{dt} - B_{dr}p\theta$$

flux density terms

$$B_{qr} = L'_{qr}i_{qr} + M'_{q1}i_{qs1} + M'_{q2}i_{qs2}$$


$$B_{dr} = L'_{dr}i_{dr} + M'_{d1}i_{ds1} + M'_{d2}i_{ds2}$$


$$\begin{split} V_{\rm dr} &= R_{\rm dr} i_{\rm dr} + L_{\rm dr} p i_{\rm dr} + M_{\rm d1} p i_{\rm ds1} + M_{\rm d2} p i_{\rm ds2} \\ &+ L_{\rm qr}' i_{\rm qr} p \theta + M_{\rm q1}' i_{\rm qs1} p \theta + M_{\rm q2}' i_{\rm qs2} p \theta \\ V_{\rm qr} &= R_{\rm qr} i_{\rm qr} + L_{\rm qr} p i_{\rm q2} + M_{\rm q1} p i_{\rm qs1} + M_{\rm q2} p i_{\rm qs2} \\ &- L_{\rm dr}' i_{\rm dr} p \theta - M_{\rm d1}' i_{\rm ds1} p \theta - M_{\rm d2}' i_{\rm ds2} p \theta \end{split}$$


$$[V] = [Z][i]$$

$$[V] = [R][i] + [L]p[i] + [G][i]p\theta$$

$$V = Ri + Lpi + Gip\theta$$







as 1

		usi	usz	ai ai	Чı	qs1	482	
$V_{ m ds1}$	ds1	$R_{ds1} + L_{ds1}p$	$M_{d12}p$	$M_{d1}p$				$i_{ds1}$
$V_{ m ds2}$	ds2	$M_{d12}p$	$R_{\rm ds2} + L_{\rm ds2}p$	$M_{d2}p$				$i_{ds2}$
$V_{ m dr}$	dr =	$M_{d1}p$	$M_{d2}p$	$R_{\rm r} + L_{\rm dr} p$	$L_{ m qr}' p  heta$	$M'_{q1}p\theta$	$M_{q2}'p\theta$	$i_{ m dr}$
$V_{ m qr}$	qr	$-M'_{d1}p\theta$	$-M'_{d2}p\theta$	$-L'_{ m dr}p heta$	$R_{\rm r} + L_{\rm qr} p$	$M_{q1}p$	$M_{q2}p$	$i_{qr}$
$V_{qs1}$	qs1				$M_{q1}p$	$R_{qs} + L_{qs1}p$	$M_{q12}p$	$i_{qs1}$
$V_{qs2}$	qs2				$M_{q2}p$	$M_{q12}p$	$R_{\rm qs2} + L_{\rm qs2}p$	$i_{qs2}$

dr

de2

de 1

as2

$$[V] = [Z][i]$$

$$[V] = [R][i] + [L]p[i] + [G][i]p\theta$$

$$V = Ri + Lpi + Gip\theta$$

power input to the motor

$$\mathbf{i}_{t}^{*}\mathbf{V} = \mathbf{i}_{t}^{*}\mathbf{R}\mathbf{i} + \mathbf{i}_{t}^{*}\mathbf{L}p\mathbf{i} + \mathbf{i}_{t}^{*}\mathbf{G}\mathbf{i}p\theta$$

dissipated as copper loss rate of change of stored magnetic energy

mechanical power at the output shaft

$$\frac{\mathrm{d}}{\mathrm{d}t}(\frac{1}{2}\mathrm{L}\mathrm{i}^2) = \mathrm{i}\mathrm{L}p\mathrm{i}$$

$$P_{\rm m} = \omega T = Tp\theta$$

$$T_{o} = \mathbf{i}_{t}^{*} \mathbf{G} \mathbf{i} = \mathbf{i}_{t}^{*} \mathbf{B}$$

G is the torque matrix.

B represents flux density in the air gap

$$T_{i} = Jp^{2}\theta + R_{F}p\theta - i_{t}^{*}Gi$$


T<sub>i</sub> represents the mechanical input torque


R<sub>F</sub> is a mechanical coefficient representing dissipation due to friction and windage J is the moment of inertia of the rotating mass (kg m<sup>2</sup>)


elect. mech.


elect. 
$$\begin{bmatrix} \mathbf{V} \\ T_{\mathbf{i}} \end{bmatrix} = \begin{bmatrix} \mathbf{R} + \mathbf{L}p & \mathbf{G}\mathbf{i} \\ -\mathbf{i}_{\mathbf{t}}^*\mathbf{G} & Jp + R_{\mathbf{F}} \end{bmatrix} \cdot \begin{bmatrix} \mathbf{i} \\ \omega \end{bmatrix}$$

		ds1	dr	qr	qs1	S	_	
$V_{ds1}$	ds1	$R_{ds1} + L_{ds1}p$	$M_{d1}p$					i <sub>ds1</sub>
$V_{ m dr}$	dr	$M_{d1}p$	$R_{\rm r} + L_{\rm dr} p$			$L'_{qr}i_{qr} + M'_{q1}i_{qs1}$		i <sub>dr</sub>
$V_{ m qr}$	= qr			$R_{\rm r} + L_{\rm qr} p$	$M_{q1}p$	$-M'_{d1}i_{ds1} \\ -L'_{dr}i_{dr}$		$i_{ m qr}$
$V_{qs1}$	qs1			$M_{q1}p$	$R_{\rm r} + L_{\rm qs1}p$			$i_{\mathbf{q}\mathbf{s}1}$
$T_{\rm i}$	s	$i_{ m qr}M'_{ m d1}$	$-i_{ m qr}L_{ m dr}'$	$i_{ m dr} L_{ m qr}'$	$i_{ m dr}M_{ m q1}'$	$Jp + R_{\rm F}$		$p\theta$










Impedance Transformation:  $\mathbf{Z}' = \mathbf{C}_{t}\mathbf{Z}\mathbf{C}$ 

Voltage Equation:  $C_t V$ 





 $\mathbf{Z}' = \mathbf{C}_{t} \mathbf{Z} \mathbf{C}$ 

ds2

ds1

qr


a


f a

Rx represents a control resistance in series with the field winding.

Final impedance matrix

$$\mathbf{Z} = \begin{bmatrix} R_{x} + R_{ds1} + L_{ds1}p & M_{d12}p \\ \\ M_{d12}p - M'_{d1}p\theta & (R_{r} + R_{ds2}) \\ \\ + (L_{qr} + L_{ds2})p \\ \\ - M'_{d2}p\theta \end{bmatrix}$$





Voltage Equation:  $\mathbf{C}_{t}\mathbf{V}$ 



ds1

ds2





ds2


ds1

 $V_{\rm ds2}$ 

qr

The values of  $V_{ds1}$  and  $(V_{ds2} + V_{gr})$  are known. These are equal to the applied voltage V. Hence the final voltage equation


a



a

For steady-state operation the rate of change of current in this machine is zero, and the operator to current p = d/dt = 0.

**Final Voltage Equation** 




 $R_{x} + R_{ds1} + L_{ds1}p$ 


 $M_{\rm d12}p$ 

a

 $M_{\rm d12}p - M'_{\rm d1}p\theta$ 

EE6303D Dynamics of Electrical Machines (DEM)





When the machine runs as a generator, i<sub>a</sub> becomes negative

 $-M'_{d\,1}p\theta i_{f}$ : Generated EMF due to the main field. In a motor this is the back EMF.

 $\omega = p\theta$  : Angular velocity

 $-M'_{d2}p\theta i_a$  : Series compounding

For steady-state operation the rate of change of current in this machine is zero, and the operator to current p = d/dt = 0.

### Step 1

Remove coil 2 and corresponding rows and column

Replace the operator p by  $j\omega_1$ 

$$p\theta = \omega_{\rm r}$$

$$\omega_{\rm r} = \omega_1 (1 - s)$$

		ds1	dr	qr	qs1	
$V_{ds1}$	ds1	$R_{\rm ds1} + j\omega_1 L_{\rm ds1}$	$j\omega_1 M_{d1}$			$i_{ds1}$
$V_{ m dr}$	dr –	$j\omega_1 M_{d1}$	$R_{\rm r} + j\omega_1 L_{\rm dr}$	$\omega_1(1-s)M_{q1}$	$\omega_1(1-s)M_{q1}$	$i_{dr}$
$V_{ m qr}$	= qr	$-\omega_1(1-s)M_{d1}$	$-\omega_1(1-s)L_{\rm dr}$	$R_{\rm r} + {\rm j}\omega_1 L_{\rm qr}$	$j\omega_1 M_{q1}$	$i_{qr}$
$V_{qs1}$	qs1			$j\omega_1 M_{q1}$	$R_{qs1} + j\omega_1 L_{qs1}$	$i_{qs1}$

#### Step 2

$$R_{ds1} = R_{qs1} = R_1, \qquad R_r = R_2$$
 $L_{ds1} = L_{qs1} = L_1, \qquad L_{dr} = L_{qr} = L_2$ 
 $M_{d1} = M_{q1} = M$ 
 $M'_{d1} = M_{d1} = M$ 
 $M'_{q1} = M_{q1} = M$ 

ds1

dr

qr

qs1

$V_{ds1}$	ds1	$R_1 + jX_1$	ј $X_{m}$			$i_{ds1}$
$V_{ m dr}$	= dr	$jX_{m}$	$R_2 + jX_2$	$(1-s)X_2$	$(1-s)X_{\rm m}$	i <sub>dr</sub>
$V_{ m qr}$	qr	$-(1-s)X_{\rm m}$	$-(1-s)X_2$	$R_2 + jX_2$	$jX_{m}$	$i_{\mathbf{qr}}$
$V_{qs1}$	qs1			$jX_{m}$	$R_1 + jX_1$	$i_{qs1}$

stator coils which are symmetrically distributed

air gap is uniform

flux wave is sinusoidally distributed in space and hence the coefficients of mutual inductance for transformer and generated voltages are the same

#### Step 3

		ds1	dr	qr	qs1	
V <sub>1</sub>	ds1	$R_1 + jX_1$	$jX_{m}$			$I_1$
0	= dr	$\mathrm{j}X_{\mathrm{m}}$	$R_2 + jX_2$	$(1-s)X_2$	$(1-s)X_{\rm m}$	$I_2$
0	qr	$-(1-s)X_{\rm m}$	$-(1-s)X_2$	$R_2 + jX_2$	$jX_{m}$	$-jI_2$
$-jV_1$	qs1			ј $X_{m}$	$R_1 + jX_1$	$-jI_1$

net m.m.f. they produce rotates at synchronous speed

During balanced operation  $N_1(I_1^2\sin^2\omega_1t + I_1^2\cos\omega_1t)^{\frac{1}{2}}$ 


rotor voltages are zero since the rotor coils in an induction motor are short-circuited


dr

$$0 = jX_{m}I_{1} - jI_{1}(1 - s)X_{m} + (R_{2} + jX_{2})I_{2} - j(1 - s)X_{2}I_{2}$$
$$= jI_{1}sX_{m} + (R_{2} + jsX_{2})I_{2}$$

$$= jI_1X_m + \left[\frac{R_2}{s} + jX_2\right]I_2$$

$$0 = jI_1X_m + \left[\frac{R_2}{s} + jX_2\right]I_2$$







## Clarification


 $\begin{aligned} \text{dr} \\ 0 &= jX_{\text{m}}I_{1} - jI_{1}(1-s)X_{\text{m}} + (R_{2} + jX_{2})I_{2} - j(1-s)X_{2}I_{2} \\ &= jI_{1}sX_{\text{m}} + (R_{2} + jsX_{2})I_{2} \\ &= jI_{1}X_{\text{m}} + \left\lceil \frac{R_{2}}{s} + jX_{2} \right\rceil I_{2} \end{aligned}$ 

qr

$$0 = jI_1X_m + \left[\frac{R_2}{s} + jX_2\right]I_2$$







#### Part of Assignment 1


Generalized Torque Equation


$$T = -i*Gi$$


#### **Expand**

Assume Balanced condition. Terms containing idr and iqr get cancels (substitute as currents in equal magnitudes, 90deg phase lag)

$$= -i_{qr}^* M_d i_{ds} + i_{dr}^* M_q i_{qs}$$







Part of Assignment 1

$$\frac{V}{0} = \frac{ds}{dr} \begin{bmatrix} R_{ds} + jX_{ds} & jX_{m} \\ jsX_{m} & R_{dr} + jsX_{dr} \end{bmatrix} \cdot \begin{bmatrix} i_{ds} \\ i_{dr} \end{bmatrix}$$

$$\begin{vmatrix} i_{ds} \\ i_{dr} \end{vmatrix} = \frac{1}{D} \frac{ds}{dr} \begin{vmatrix} Z_{dr} & -jX_{m} \\ -jsX_{m} & Z_{ds} \end{vmatrix} \cdot \begin{vmatrix} V \\ 0 \end{vmatrix}$$

$$i_{\rm ds} = \frac{1}{D} (Z_{\rm dr} V)$$

$$i_{\rm dr} = j s X_{\rm m} V/D$$

Part of Assignment 1

$$i_{ds} = \frac{1}{D}(Z_{dr}V)$$
  $i_{dr} = jsX_{m}V/D$ 

$$T = -i^*Gi$$

$$= -i^*_{qr}M_di_{ds} + i^*_{dr}M_qi_{qs}$$

**ωT= Synchronous Power in Watts** 

$$\omega M = X_m$$

Per phase synchronous power 
$$T_{\rm ph} = -i_{\rm ds}jX_{\rm m}i_{\rm dr}^*$$
 (synchronous W)

Part of Assignment 1

Per phase synchronous power  $T_{\rm ph} = -i_{\rm ds} j X_{\rm m} i_{\rm dr}^*$  (synchronous W)

Substitute for  $i_{ds}$  in terms of V Substitute for V in terms of  $i_{dr}$   $Z_{dr}$ = $R_r$ 

$$i_{\rm ds} = \frac{1}{D} (Z_{\rm dr} V)$$

$$i_{\rm dr} = j s X_{\rm m} V/D$$

Generated Shaft torque in Sync. Watts/phase = Per phase synchronous power - Per phase rotor copper loss

Per phase rotor copper loss=  $i_{dr}^2 R_r$ 


This part to be submitted on or before 01.12.2021

$$= i_{\rm dr}^2 R_{\rm r} \left( \frac{1}{s} - 1 \right)$$

Submission folder available at Eduserver.
All answer scripts as part of Assignment
1 to be submitted in this folder

## Inference

$$T = -\mathbf{i}^* \mathbf{G} \mathbf{i}$$
$$= -i_{qr}^* M_{d} i_{ds} + i_{dr}^* M_{q} i_{qs}$$



### **Power Invariance**

Power input to the stator of the primitive machine is

$$P_{\rm s} = V_{\rm ds1}^* I_{\rm ds1} + V_{\rm qs1}^* I_{\rm qs1}$$

For balanced operation of the induction motor

$$P_{\rm s} = 2 V_1^* I_1$$

Power input to the stator of a 3-phase induction motor in terms of phase voltage and phase current

$$P_{\rm s} = 3V_{\rm p}^*I_{\rm p}$$

power is invariant

$$2V_1^*I_1 = 3V_p^*I_p$$

equate the copper-loss in the stator windings in the 3-phase machine and its 'commutator-type' equivalent

$$I_1 = \sqrt{\frac{3}{2}}I_{p}$$

$$V_1 = \sqrt{\frac{3}{2}} V_{\rm p}$$

$$3I_p^2 R_1 = 2I_1^2 R_1$$
 assuming that the resistance  $R_{ds1} = R_1$ 

$$[V] = [Z][i]$$

$$[V] = [R][i] + [L]p[i] + [G][i]p\theta$$

$$V = Ri + Lpi + Gip\theta$$

Solution is difficult to achieve as Z contains p-terms large number of variables is involved

$$\mathbf{L}p\mathbf{i} = \mathbf{V} - \mathbf{R}\mathbf{i} - \mathbf{G}\mathbf{i}p\theta$$

 $i = Z^{-1} V$ 

$$p\mathbf{i} = \mathbf{L}^{-1}\mathbf{V} - \mathbf{L}^{-1}(\mathbf{R} + \mathbf{G}p\theta)\mathbf{i}$$

Part of Assignment 1

This part to be submitted on or before 13.12.2021

#### A three coil is considered here for simplicity of calculation

	$i_{ m ds}$		$L_{ds1}$	$M_{ m d}$	
p	$i_{ m dr}$	=	$M_{ m d}$	$L_{ m dr}$	
	$i_{ m qr}$				$L_{ m qr}$

$V_{ds1}$		$L_{ds1}$	$M_{\rm d}$	
$V_{ m dr}$	_	$M_{\rm d}$	$L_{ m dr}$	
$V_{ m qr}$				$L_{ m qr}$

$R_{ds1}$		
	$R_{\rm r}$	$L_{ m qr} \omega$
$-\omega M_{\rm d}$	$-\omega L_{ m dr}$	$R_{\rm r}$

$$egin{array}{c} L_{
m ds} \ \hline i_{
m dr} \ \hline i_{
m qr} \ \hline \end{array}$$


$$\dot{\mathbf{x}} = \mathbf{A}\mathbf{x} + \mathbf{B}\mathbf{u}$$

$$\dot{\mathbf{x}} = p\mathbf{i}$$

$$\mathbf{A} = -(\mathbf{L}^{-1}\mathbf{R} + \mathbf{L}^{-1}\mathbf{G}p\theta)$$

$$\mathbf{B}\mathbf{u} = \mathbf{L}^{-1}\mathbf{V}$$


In this case the matrices A and B have constant terms if the angular velocity  $p\theta$  does not change when currents and voltages change under sudden transient conditions. This assumption is not true in general but it is valid in many cases. For correct analysis, it is necessary to take into account changes in the rotor velocity, and we have to consider the torque equation also.





The matrix A is timedependent, and a function of current. The solution must therefore be obtained numerically.


# **Fundamentals**


- State Space
- State Vector
- Eigen Values
- Eigen Vector
- State Trajectory
- Vector space, Basis












## **Case Study**

Machines Parameters	Value	Per Unit Value
Horse Power (Hp)	50 hp	-
Voltage (V <sub>L</sub> )	460 V	-
Frequency (Hz)	60 Hz	-
Stator Resistance (r <sub>s</sub> )	$0.087~\Omega$	0.015336
Stator Reactance (X <sub>ls</sub> )	0.302 Ω	0.053235
Mutual Reactance (X <sub>M</sub> )	13.08 Ω	2.30569
Equivalent Rotor Resistance (r' <sub>r</sub> )	0.302 Ω	0.040191
Equivalent Rotor Reactance (X' <sub>lr)</sub>	0.228 Ω	0.053235
Moment of Inertia (J)	1.662 Ω	-

M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," *2007 7th International Conference on Power Electronics*, 2007, pp. 1115-1120

## **Inference**




M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," 2007 7th International Conference on Power Electronics, 2007, pp. 1115-1120

The excursion of eigen values for the rated operating condition of induction motor are depicted in Fig. Which indicate that operation becomes unstable at lower frequency. In each step of computation the applied voltage is decreased linearly with frequency. The eigen values are found to cross the boundary at low frequency of 0.116 p. u. (7 Hz) while the corresponding stator voltage is also 0.116 p. u. indicating unstable operation below this frequency.

The straight line parallel to the x-axis passing through zero value of the ordinate forms the boundary between the stable and unstable region of operation. The lower part of the boundary represents the stable region and the upper part signifies the unstable region of operation.


## Inference



M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," 2007 7th International Conference on Power Electronics, 2007, pp. 1115-1120

The effect of amplitude of the stator voltage on stability is illustrated in Fig. These curves are obtained by decreasing the stator voltage and frequency keeping volt/Hz ratio constant. The reduction of voltage and frequency simultaneously is indicating the induction motor trends to be unstable at lower frequency

## **Inference**



M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," 2007 7th International Conference on Power Electronics, 2007, pp. 1115-1120

## **Last Part of Assignment 1**


Date of Submission: on or


before 27.12.2021


## **Case Study**


Machines Parameters	Value	Per Unit Value
Horse Power (Hp)	50 hp	-
Voltage (V <sub>L</sub> )	460 V	-
Frequency (Hz)	60 Hz	-
Stator Resistance (r <sub>s</sub> )	$0.087~\Omega$	0.015336
Stator Reactance (X <sub>ls</sub> )	0.302 Ω	0.053235
Mutual Reactance (X <sub>M</sub> )	13.08 Ω	2.30569
Equivalent Rotor Resistance (r' <sub>r</sub> )	0.302 Ω	0.040191
Equivalent Rotor Reactance (X' <sub>lr)</sub>	0.228 Ω	0.053235
Moment of Inertia (J)	1.662 Ω	•

M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," *2007 7th International Conference on Power Electronics*, 2007, pp. 1115-1120









The leftward shift of the overall root locus in the region of low damping is perhaps the most significant effect of transient saturation.


Modern high efficiency machines which have increased pu magnetizing reactance and are designed to operate at reduced flux levels are likely to have larger and stronger regions of instability and to exhibit poorer damped transient response than conventional machines.

## **Case Study**

Machines Parameters	Value	Per Unit Value
Horse Power (Hp)	50 hp	-
Voltage (V <sub>L</sub> )	460 V	-
Frequency (Hz)	60 Hz	-
Stator Resistance (r <sub>s</sub> )	$0.087~\Omega$	0.015336
Stator Reactance (X <sub>ls</sub> )	0.302 Ω	0.053235
Mutual Reactance (X <sub>M</sub> )	13.08 Ω	2.30569
Equivalent Rotor Resistance (r' <sub>r</sub> )	0.302 Ω	0.040191
Equivalent Rotor Reactance (X' <sub>lr)</sub>	0.228 Ω	0.053235
Moment of Inertia (J)	1.662 Ω	•

M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," *2007 7th International Conference on Power Electronics*, 2007, pp. 1115-1120

#### **Inference**




M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," 2007 7th International Conference on Power Electronics, 2007, pp. 1115-1120

The excursion of eigen values for the rated operating condition of induction motor are depicted in Fig. Which indicate that operation becomes unstable at lower frequency. In each step of computation the applied voltage is decreased linearly with frequency. The eigen values are found to cross the boundary at low frequency of 0.116 p. u. (7 Hz) while the corresponding stator voltage is also 0.116 p. u. indicating unstable operation below this frequency.

The straight line parallel to the x-axis passing through zero value of the ordinate forms the boundary between the stable and unstable region of operation. The lower part of the boundary represents the stable region and the upper part signifies the unstable region of operation.


#### Inference



M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," 2007 7th International Conference on Power Electronics, 2007, pp. 1115-1120

The effect of amplitude of the stator voltage on stability is illustrated in Fig. These curves are obtained by decreasing the stator voltage and frequency keeping volt/Hz ratio constant. The reduction of voltage and frequency simultaneously is indicating the induction motor trends to be unstable at lower frequency

#### **Inference**



M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," 2007 7th International Conference on Power Electronics, 2007, pp. 1115-1120

#### **Last Part of Assignment 1**


Date of Submission: on or

before 27.12.2021

## **Case Study**

Machines Parameters	Value	Per Unit Value
Horse Power (Hp)	50 hp	-
Voltage (V <sub>L</sub> )	460 V	-
Frequency (Hz)	60 Hz	-
Stator Resistance (r <sub>s</sub> )	$0.087~\Omega$	0.015336
Stator Reactance (X <sub>ls</sub> )	0.302 Ω	0.053235
Mutual Reactance (X <sub>M</sub> )	13.08 Ω	2.30569
Equivalent Rotor Resistance (r' <sub>r</sub> )	0.302 Ω	0.040191
Equivalent Rotor Reactance (X' <sub>lr)</sub>	0.228 Ω	0.053235
Moment of Inertia (J)	1.662 Ω	•

M. B. Uddin, M. N. Pramanik and S. A. Reza, "Low frequency stability study of a three-phase induction motor," *2007 7th International Conference on Power Electronics*, 2007, pp. 1115-1120




### Machine Model at Various Reference Frames

#### **Induction Motor**

#### Approach 1

Develop new primitive machine according to arbitrary reference frame



### **Oscillations**

**Induction Machines** 

### **Synchronous Machines**

- 1. Isolated synchronous generator to a load
- 2. Synchronous generator connected to infinite bus
- 3. Synchronous Motor

The problem of small oscillations is encountered mainly with machines in which there is some form of feedback. This may consist of signals generated within the machine inherently, due to the configuration of windings, or externally in the form of a control system, or a voltage regulator on a d.c. generator.

Self-excited oscillations are fairly common in power systems. Usually two kinds of self-excited oscillations are encountered. One is a high-frequency electrical oscillation, to which the machine rotors, because of their high inertia, cannot respond. The analysis of the complete system using eigenvalue techniques will indicate whether or not such frequencies will be present. We are primarily concerned here with low-frequency oscillations (a few hertz) to which the rotors can respond. These are electromechanical in nature.

$$Jp^{2}\Delta\theta + T_{de}p\Delta\theta + R_{F}p\Delta\theta + T_{S}\Delta\theta = \Delta T_{i}$$

where  $T_S \Delta \theta$  = synchronising torque

 $T_{\rm de}p\Delta\theta$  = electrical damping torque

 $R_{\rm F}p\Delta\theta$  = mechanical damping torque

 $Jp^2\Delta\theta$  = rotational torque due to the inertia of the rotor

 $\Delta T_i$  = change in input/output torque


When the oscillations are self-excited  $\Delta Ti = 0$  and hence

$$Jp^{2}\Delta\theta + (T_{de} + R_{F})p\Delta\theta + T_{S}\Delta\theta = 0$$

The damping and synchronising torque coefficients not only indicate whether or not a system is stable, they clearly indicate the extent of the stability /instability region and provide physical concepts which are not obtained by other methods.

## **Primitive Machines**

#### Synchronous machines with amortisseur winding



$$Jp^{2}\Delta\theta + T_{de}p\Delta\theta + R_{F}p\Delta\theta + T_{S}\Delta\theta = \Delta T_{i}$$

where  $T_S \Delta \theta$  = synchronising torque

 $T_{\rm de}p\Delta\theta$  = electrical damping torque

 $R_{\rm F}p\Delta\theta$  = mechanical damping torque

 $Jp^2\Delta\theta$  = rotational torque due to the inertia of the rotor

 $\Delta T_i$  = change in input/output torque

When the oscillations are self-excited  $\Delta Ti = 0$  and hence

$$Jp^{2}\Delta\theta + (T_{de} + R_{F})p\Delta\theta + T_{S}\Delta\theta = 0$$

The damping and synchronising torque coefficients not only indicate whether or not a system is stable, they clearly indicate the extent of the stability /instability region and provide physical concepts which are not obtained by other methods.


$$Jp^{2}\Delta\theta + (T_{de} + R_{F})p\Delta\theta + T_{S}\Delta\theta = 0$$


- (a) if  $T_S = 0$ , the machine does not oscillate, but loses synchronism
- (b) if  $(T_{de} + R_F) = 0$  oscillations begin and are self-sustained
- (c)  $(T_{de} + R_F) < 0$  oscillations build up in magnitude and the machine loses synchronism
- (d)  $(T_{de} + R_F) > 0$  there may or may not be oscillations but in either case the system will be stable if  $T_S > 0$


Oscillations of small amplitude, the system equations may be linearised about the operating points. This makes it fairly easy to evolve criteria which will tell us whether the machines are dynamically stable or not, using methods such as the following:

- (1) the Nyquist criterion
- (2) Routh-Hurwitz criterion
- (3) computation of the eigenvalues
- (4) computation of the synchronising and damping torque coefficients
- (5) D-partition techniques
- (6) computation of rotor swing with time-the so-called swing curves

In the case of transient (nonlinear) instability, the standard approach is to compute the swing curves.







transient equation for torque

$$Jp^2\theta + R_{\rm F}p\theta - \mathbf{i}_{\rm t}^*\mathbf{G}\mathbf{i} = T_{\rm input}$$

For small oscillations, we take increments in  $\theta$ , i, and Ti;

$$Jp^{2}\Delta\theta + R_{F}p\Delta\theta - \mathbf{i}_{t}^{*}\mathbf{G}\Delta\mathbf{i} - \Delta\mathbf{i}_{t}^{*}\mathbf{G}\mathbf{i} - \mathbf{i}_{t}^{*}\frac{\partial\mathbf{G}}{\partial\theta}\Delta\theta\,\mathbf{i} = \Delta T_{i}$$

$$Jp^2\Delta\theta + R_Fp\Delta\theta - i_i^*(G + G_i)\Delta i = \Delta T_i$$

$$\mathbf{V} = \mathbf{R}\mathbf{i} + \mathbf{L}p\mathbf{i} + \mathbf{G}\mathbf{i}p\theta$$

$$V + \Delta V = \mathbf{R}(\mathbf{i} + \Delta \mathbf{i}) + \mathbf{L}p(\mathbf{i} + \Delta \mathbf{i}) + \mathbf{G}(\mathbf{i} + \Delta \mathbf{i})p\theta + \mathbf{G}\mathbf{i}p(\Delta\theta)$$

$$\Delta \mathbf{V} = \mathbf{R}\Delta \mathbf{i} + \mathbf{L}p\Delta \mathbf{i} + \mathbf{G}p\theta\Delta \mathbf{i} + \mathbf{G}\mathbf{i}p(\Delta\theta)$$

		ds	dr	qr	qs	S		
$\Delta V_{\rm ds}$	ds	$R_{\rm ds} + L_{\rm ds}p$	$M_{d}p$				Δ	i <sub>ds</sub>
$\Delta V_{ m dr}$	dr	$M_{\rm d}p$	$R_{\rm r} + L_{ m dr} p$	$L_{ m qr} p  heta$	$M_{\mathbf{q}}p\theta$	$L_{qr}i_{qr} + M_qi_{qs}$	Δ	i <sub>dr</sub>
$\Delta V_{ m qr}$	= qr	$-M_{d}p\theta$	$-L_{ m dr}p heta$	$R_{\rm r} + L_{\rm qr} p$	$M_{\mathbf{q}}p$	$-M_{\mathrm{d}}i_{\mathrm{ds}} \ -L_{\mathrm{dr}}i_{\mathrm{dr}}$	. 🛮	i <sub>qr</sub>
$\Delta V_{ m qs}$	qs			$M_{\mathbf{q}}p$	$R_{qs} + L_{qs}p$		Δ	i <sub>qs</sub>
$\Delta T_{\rm i}$	S	$-i_{qr}^*M_d$	$-i_{qs}^* M_{q}$ $-(L_{qr}-L_{dr})i_{qr}^*$	$-i_{\rm ds}^* M_{\rm d}$ $-i_{\rm dr}^* (L_{\rm qr} - L_{\rm dr})$	$-i_{ m dr}^* M_{ m q}$	$Jp + R_F$	p	$\Delta \theta$

$$\frac{\Delta \mathbf{V}}{\Delta T_{i}} = \begin{bmatrix} \mathbf{\overline{L}} & \mathbf{D} \\ \mathbf{J} \end{bmatrix} p \begin{bmatrix} \Delta \mathbf{i} \\ \Delta \omega \end{bmatrix} + \begin{bmatrix} \mathbf{R} + \mathbf{G}p\theta_{0} & \mathbf{G}\mathbf{i}_{0} \\ -\mathbf{i}_{0}^{*}(\mathbf{G} + \mathbf{G}_{t}) & R_{F} \end{bmatrix} \cdot \begin{bmatrix} \Delta \mathbf{i} \\ \Delta \omega \end{bmatrix}$$

$$\Delta \mathbf{x} = \boxed{\begin{array}{c} \Delta \mathbf{i} \\ \Delta \omega \end{array}}$$

$$\Delta \mathbf{f} = \begin{array}{|c|c|} \Delta \mathbf{V} \\ \hline \Delta T_{\mathbf{i}} \end{array}$$

$$\mathbf{L} = \begin{array}{|c|c|} \overline{\mathbf{L}} & & \\ \hline J & & \\ \hline \end{array}$$

$$\overline{\mathbf{A}} = \begin{array}{|c|c|c|} \hline \mathbf{R} + \mathbf{G}p\theta_0 & \mathbf{G}\mathbf{i}_0 \\ \hline -\mathbf{i}_0^*(\mathbf{G} + \mathbf{G}_t) & R_F \end{array}$$


$$p\Delta \mathbf{x} = -\mathbf{L}^{-1}(\overline{\mathbf{A}})\Delta \mathbf{x} + (\mathbf{L})^{-1}\Delta \mathbf{f}$$

$$\Delta \dot{\mathbf{x}} = \mathbf{A} \Delta \mathbf{x} + \mathbf{B} \Delta \mathbf{u}$$


The characteristic equation is

$$\det(s\mathbf{I} - \mathbf{A}) = 0$$

Having obtained the characteristic equation of a machine, the roots, or eigenvalues, can be computed by standard procedures. If the roots have no positive real parts, the system is stable. However, when the roots are obtained it may be found that one of the roots has a small negative real part and a low value of imaginary part. This root will predominantly influence the rotor dynamics. This will indicate that the machine will oscillate at an angular frequency determined by the imaginary part of the root and the rate of decay of the oscillations will depend on the magnitude of the real part. If a voltage regulator is present, roots with relatively small imaginary parts will be present which will also affect the dynamics of the rotor. The effect of the other roots, with faster decay rates (higher negative real values) will be apparent only at the initial stage and these will not affect the small oscillation behavior over the longer period given by the dominant root. Roots with large values of imaginary part will not affect the rotor dynamics because the rotor, due to its inertia, will not respond to high frequency oscillations. Hence we can often assume that there will be virtually one dominant root which will determine the machine kinetics during small oscillation



In industrial processes electrical machines may be used singly, in groups of identical machines, or in groups of different machines interconnected to achieve some required overall operating characteristics. A simple example of this is the use of a pilot exciter and main exciter to provide controlled and stable field current for a large alternator in a power station, all machine rotors being on one shaft. In steel production, groups of machines may operate in parallel or in controlled sequence.





In the machines which we have investigated in the foregoing analysis of torque equations, the choice of d and q axes was obvious. However, where machines of different types are interconnected, we must consider carefully the choice of reference axes. For example, the armature voltage and torque equations of synchronous machines are usually expressed along Park's axes, namely in a direct axis along the rotor field pole and a quadrature axis lying between the field poles. In the ideal synchronous machine in steady state operation, all values of voltage, current, and torque along these axes are constant with respect to time, and the operator p(=d/dt) in the equations becomes zero. With the induction motor the usual reference frame is fixed to the stator with the direct axis along one phase and the quadrature axis orthogonal to this position. The rotor axes are also fixed in this position in space. Along these axes, in steady state operation, the p operator in the equations becomes j $\omega$ , where  $\omega = 2\pi f$ . Obviously if these machines are operating together, it is essential that we select reference axes such that the operator p has the same steady-state and transient significance for all time dependent behaviour. A reference frame for the induction motor, which rotates uniformly with the synchronous flux wave gives equations of the same form as those of Park for the synchronous machine and a complex arrangement of such machines may then be treated mathematically as a single coupled dynamical system. In simple cases of a few coupled machines it may be possible in a computer programme to treat each machine separately with its own frame of reference, the computer making the adjustments in values when transformations between the reference axes become necessary as the machines interact.

For many purposes it is desirable to programme the overall dynamical behaviour of interconnected machines, using the combined equations of performance; for example when using the state A-matrices and in the study of stability conditions and eigenvalues.


## **Primitive Machines**

#### **DC** machines






assume that the prime mover driving the shunt generator is very large and runs at constant speed whatever the load on the generator



electrically coupled machines.



Considering impressed voltages on each machine, in accordance with Kron's convention, the equations for each machine are identical in form

#### generator


$$\frac{V_{f1}}{V_{a1}} = \frac{ds1}{qr1} \begin{bmatrix} R_{f1} + L_{f1}p \\ -M_{d1}p\theta & R_{a1} + L_{a1}p \end{bmatrix} \cdot \begin{bmatrix} i_{f1} \\ i_{a1} \end{bmatrix}$$


$$V_1 = Z_1 i_1$$

#### motor

$$\frac{V_{f2}}{V_{a2}} = \frac{ds2}{qr2} \begin{bmatrix} R_{f2} + L_{f2}p \\ -M_{d2}p\theta & R_{a2} + L_{a2}p \end{bmatrix} \cdot \begin{bmatrix} i_{f2} \\ i_{a2} \end{bmatrix}$$

 $V_2 = Z_2 i_2$ 





combined matrix is given by

$$\mathbf{Z}' = \mathbf{C}_{t} \mathbf{Z} \mathbf{C}$$

	ds1	qr1	ds2	qr2
ds1	$R_{f1} + L_{f1}p$			
$\mathbf{Z} = qr1$	$-M_{d1}p\theta$	$R_{a1} + L_{a1}p$		
ds2			$R_{f2} + L_{f2}p$	
qr2			$-M_{d2}p\theta$	$R_{a2} + L_{a2}p$

f1

f2

q

In the steady state, terms containing the operator p become zero

	f1	f2	q
f1	$R_{f1} + R_{a1} - M_{d1} p\theta$		$R_{a1}$
$\mathbf{Z}'_{\text{s-state}} = f2$		$R_{f2} + R_{a2} - M_{d2}p\theta$	$-R_{a2}$
q	$-M_{d1}p\theta + R_{a1}$	$M_{d2}p\theta$ $-R_{a2}$	$R_{a1} + R_{a2}$

Torque generated in each machine is given by iGi where, from matrix

	f1	f2	q
f1	$-M_{d1}$		
G = f2		$-M_{d2}$	
q	$-M_{d1}$	$M_{ m d2}$	

#### generated torque

$$T = -i_{f1}M_{d1}(i_{q} + i_{f1}) + i_{f2}M_{d2}(i_{q} - i_{f2})$$

The first term is the torque generated by current in the generator, to oppose the torque impressed upon the shaft by the prime mover. The second term gives the torque generated by the motor to meet the load torque impressed upon the motor shaft.

The new voltage vector is given by

$$\mathbf{V}' = \mathbf{C}_{\mathbf{t}} \mathbf{V}$$

$$\mathbf{V} = \begin{bmatrix} ds1 & 0 \\ qr1 & V_{qr1} \\ ds2 & 0 \end{bmatrix}$$


$$qr2 \quad V_{qr2}$$

f1 
$$V_{qr1}$$
 f1  $V_{f1}$ 

$$V' = f2 V_{qr2} = f2 V_{f2}$$


$$q V_{qr1} - V_{qr2} q V_{q}$$


#### **Case II: alternator supplying a synchronous motor**




Due to the shaft load on the motor, it operates with the armature direct and quadrature axes lagging those of the alternator by the load angle  $\delta$ . Our assumption of synchronous operation implies that p $\delta$  is zero.

**Case II: alternator supplying a synchronous motor** 








$$\mathbf{Z}' = \mathbf{C}_{t}\mathbf{Z}\mathbf{C}$$

Estimate Z', Steady state impedance matrix, Torque equation


#### **Case III: Ward-Leonard five-machine system**




#### **Case III: Ward-Leonard five-machine system**

	ds	dr	qr	qs	S
ds	$R_{\rm s} + L_{\rm s}p$	Мр			
dr	Мр	$R_{\rm r} + L_{\rm r} p$	$L_{r}p\theta$	Мрθ	
$\mathbf{Z} = \mathbf{qr}$	$-Mp\theta$	$-L_{\rm r}p heta$	$R_{\rm r} + L_{\rm r}p$	Мp	
qs			Мp	$R_{\rm s} + L_{\rm s} p$	
S	$Mi_{ m qr}$	$L_{ m r}i_{ m qr}$	$-L_{\rm r}i_{ m dr}$	$-Mi_{dr}$	$Jp + R_{\rm F}$

induction motor



**Case III: Ward-Leonard five-machine system** 




#### **Hunting analysis of interconnected machines**


C. Jing, J. D. McCalley and M. Kommareddy, "An energy approach to analysis of interarea oscillations in power systems," in IEEE Transactions on Power Systems, vol. 11, no. 2, pp. 734-740, May 1996

Y. Yu, S. Grijalva, J. J. Thomas, L. Xiong, P. Ju and Y. Min, "Oscillation Energy Analysis of Inter-Area Low-Frequency Oscillations in Power Systems," in IEEE Transactions on Power Systems, vol. 31, no. 2, pp. 1195-1203, March 2016

#### **Hunting analysis of interconnected machines**

- Modes, Modal analysis
- Motion modes
- Energy modes
- Mode shapes
- Participation factor





There are many more "energy modes" than "motion modes"