

Index	Sub-index	Name	Description	Data type	Data range	Access- ibility	Mapp- ability	Factory setting	Unit	Activate method
										on in effect
6098_h	00 _h	416 _h	Origin regression method, see section 5.7.4 for details	int8	17~45	RW	RPDO	20	1	Suspensi on in effect
6099_h	01 _h	417 _h	Find switching speed (high speed)	uint32	0~4294967295	RW	RPDO	10000	User unit/s	Suspensi on in effect
6099_h	02 _h	419 _h	Finding home speed (low speed)	int32	-2147483648~2147 483647	RW	RPDO	2730	User unit/s	Suspensi on in effect
609A_h	00 _h	41B _h	(math.) origin regression acceleration	uint32	0~4294967295	RW	RPDO	409600	User unit/s	Suspensi on in effect
60A3_h	00 _h	41D _h	Number of contours plus acceleration used, only 60A4 _h :01 _h and 60A4 _h :02 are used in this device. _h	Usint8	2	RW	RPDO	2	1	Suspensi on in effect
60A4_h	01 _h	41E _h	Contour plus acceleration	uint32	0~4294967295	RW	NO	50000	User unit/s ²	Suspensi on in effect
	02 _h	420 _h	Contour Deceleration	uint32	0~4294967295	RW	NO	50000	User unit/s ²	Suspensi on in

Index	Sub-index	Name	Description	Data type	Data range	Access-ability	Mapp-ability	Factory setting	Unit	Activate method
										effect
60B0 _h	00 _h	426 _h	position bias	int32	-2147483648~2147483647	RW	RPDO	0	user unit	Suspension in effect
			Specific description: Set the position instruction bias amount in cycle synchronized position mode, after bias: target position = 607A _h + 60B0 _h							
60B1 _h	00 _h	428 _h	Speed Bias	int32	-2147483648~2147483647	RW	RPDO	0	user unit	Suspension in effect
			Specific description: set the speed command bias amount in cycle synchronized speed mode, after bias: target speed = 60FF _h + 60B1 _h							
60B2 _h	00 _h	42A _h	Torque Bias	int32	-2147483648~2147483647	RW	RPDO	0	user unit	Suspension in effect
			Specific description: Set the torque command bias amount in cycle synchronized torque mode, after bias: target torque = 6071 _h + 60B2 _h							
60C1 _h	01 _h	42D _h	Target position for interpolation	int32	-2147483648~2147483647	RW	RPDO	0	user unit	Suspension in effect
60C2 _h	01 _h	42F _h	The interpolation cycle time constant t	uint8	0~255	RW	NO	20	s	Suspension in effect
	02 _h	430 _h	The interpolation cycle time index n	Int8	-128~127	RW	NO	-1	1	Suspension in effect

Index	Sub-index	Name	Description	Data type	Data range	Access- ibility	Mapp- ability	Factory setting	Unit	Activate method	
60C5 _h	00 _h	43B _h	Maximum profile acceleration	uint32	0~4294967295	RW	RPDO	500000	User unit/s2	Suspensi on in effect	
60C6 _h	00 _h	43D _h	Maximum contour deceleration	uint32	0~4294967295	RW	RPDO	500000	User unit/s ²	Suspensi on in effect	
60F2 _h	00 _h	43F _h	Positioning Options	uint16	0~2	RW	RPDO	0	1	Suspensi on in effect	
			Specific descriptions are as follows.								
			Bit1	Bit0	descriptive						
			0	0	Relative position shift, relative to target position (607A _h)						
			0	1	Relative position shift, relative to the entered position command (60FC _h)						
			1	0	Relative position shift, relative to the entered position command (6064 _h)						
60F4 _h	00 _h	440 _h	user position bias	int32	-2147483648~2147 483647	RO	TPDO	0	user unit	-	
60FA _h	00 _h	444 _h	Regulator Output	int32	-2147483648~2147 483647	RO	TPDO	0	unit of command (computin g)	-	

Index	Sub-index	Name	Description	Data type	Data range	Access- ibility	Mapp- ability	Factory setting	Unit	Activate method
60FC_h	00 _h	446 _h	Motor Position Command	int32	-2147483648~2147 483647	RO	TPDO	0	user unit	-
			Specific description: Position command 60FC _h = Position command 6062 _h × electronic gear ratio (6091) _h							
60FF_h	00 _h	448 _h	target speed	int32	-2147483648~2147 483647	RW	RPDO	0	User unit/s	Suspensi on in effect
			Specific description: Setting the user speed command in contour speed mode and cycle synchronized speed mode							

11 Version Information

Manual Version	Date	Revision History
A	2025/8/13	establish

- The whole or part contents of this manual is prohibited from being reprinted or copied without authorization.
- Performance, specifications and appearance of products may change without prior notice due to improvements, please understand.
- We strive to make the contents of the manual as correct as possible. if you find any problems、errors or omissions, please contact Beijing NiMotion Control Technology Co., Ltd.

Beijing NiMotion Control Technology Co., Ltd.
Building 3, yard 12, Jinxing Road, Daxing District, Beijing
Zip code: 102628
Tel: (010)60213882 Fax: (010)60213882
E-mail: nimotion@nimotion.com
<http://www.nimotion.com>