



Maintenance Items

N530BD

Make & Model (Serial)
BOMBARDIER CL 604 (5352)

Operator
Jet Linx Aviation

Reported Date
30-May-2026

Hours
8695.10

Landings
4002

- Major Components

Component	Model (Serial)	Hours	Cycles
Engine 1	CF34-3B (872215)	8695.10	4003.00
Engine 2	CF34-3B (872216)	8695.10	4003.00
APU 0	GTCP36-100(E) (P-223C)	10307.00	0.00

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
--------------------	-------------	------------	-----------	-----------	---------	----------	-----------

SB 604-30-005 R2 Part C
Airframe
SB - Open
#641

MODIFICATION - ENGINE COWL DUCTING SYSTEM - INSTALLATION OF SUPPORT BRACKET AND CLAMPS ON T2 SENSOR ANTI-ICE TUBE - MODIFICATION

Notes

(AVG MAN HRS: 3)

SB 604-30-006
Airframe
SB - Superseded
#3557

ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION

Notes

(AVG MAN HRS: 415) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED:
- CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016.
- CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016.).SEE REVISION 1.

SB 604-30-006 PART A
Airframe
SB - Superseded
#863

ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE COCKPIT WIRING PROVISION.

Notes

(AVG MAN HRS: 100) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED:
- CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016.
- CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016.).SEE REVISION 1.

SB 604-30-006 PART B
Airframe
SB - Superseded
#3414

ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE NECESSARY SUPPORTS, AND INSTALL THE CABIN-WING WIRING PROVISION

Notes

(AVG MAN HRS: 200) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED:
- CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016.
- CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016.).SEE REVISION 1.



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-006 PART E Airframe SB - Superseded #2264	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE JUNCTION BOX JB19 Notes (AVG MAN HRS: 5) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016.).SEE REVISION 1.						
SB 604-30-006 PART D Airframe SB - Superseded #3000	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE PILOT AND COPILOT LTGWAIS PANELS ON COCKPIT Notes (AVG MAN HRS: 45) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016.).SEE REVISION 1.						
SB 604-30-006 PART C Airframe SB - Superseded #1807	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE TEMPERATURE SWITCHES ON THE WINGS Notes (AVG MAN HRS: 40) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, TR 604/41-1, DATED MARCH 18, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, TR 604/45-1, DATED MARCH 18, 2016.).SEE REVISION 1.						
SB 604-30-006 PART F Airframe SB - Superseded #864	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - LTGWAIS ACTIVATION Notes (AVG MAN HRS: 25).SEE REVISION 1.						
SB 604-30-006 R1 Airframe SB - Superseded #277	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION Notes (AVG MAN HRS: 415) (NOTE: NOTE: YOU CAN DO EACH PART OF THIS SERVICE BULLETIN INDEPENDENTLY.).SEE REVISION 2.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-006 R1 PART A Airframe SB - Superseded #2951	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE COCKPIT WIRING PROVISION. Notes (AVG MAN HRS: 100) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.).SEE REVISION 2.						
SB 604-30-006 R1 PART B Airframe SB - Superseded #2961	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE NECESSARY SUPPORTS, AND INSTALL THE CABIN-WING WIRING PROVISION Notes (AVG MAN HRS: 200) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.).SEE REVISION 2.						
SB 604-30-006 R1 PART E Airframe SB - Superseded #3248	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE JUNCTION BOX JB19 Notes (AVG MAN HRS: 5) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.).SEE REVISION 2.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-006 R1 PART D Airframe SB - Superseded #3354	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE PILOT AND COPILOT LTGWAIS PANELS ON COCKPIT Notes (AVG MAN HRS: 45) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.).SEE REVISION 2.						
SB 604-30-006 R1 PART C Airframe SB - Superseded #361	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE TEMPERATURE SWITCHES ON THE WINGS Notes (AVG MAN HRS: 40) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.).SEE REVISION 2.						
SB 604-30-006 R1 PART F Airframe SB - Superseded #1199	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - LTGWAIS ACTIVATION Notes (AVG MAN HRS: 25) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.).SEE REVISION 2.						
SB 604-30-006 R2 Airframe SB - Open #1556	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION Notes (AVG MAN HRS: 415)DECLINED						

Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-006 R2 PART A Airframe SB - Open #1460	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE COCKPIT WIRING PROVISION. Notes (AVG MAN HRS: 100) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.)DECLINED						
SB 604-30-006 R2 PART B Airframe SB - Open #109	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE NECESSARY SUPPORTS, AND INSTALL THE CABIN-WING WIRING PROVISION Notes (AVG MAN HRS: 200) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.)DECLINED						
SB 604-30-006 R2 PART E Airframe SB - Open #1043	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE JUNCTION BOX JB19 Notes (AVG MAN HRS: 5) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.)DECLINED						
SB 604-30-006 R2 PART D Airframe SB - Open #2348	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE PILOT AND COPILOT LTGWAIS PANELS ON COCKPIT Notes (AVG MAN HRS: 45) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.)DECLINED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-30-006 R2 PART C Airframe SB - Open #3701	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - INSTALL THE TEMPERATURE SWITCHES ON THE WINGS Notes (AVG MAN HRS: 40) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.)DECLINED						
SB 604-30-006 R2 PART F Airframe SB - Open #2358	ICE AND RAIN PROTECTION - TAKE OFF SAFETY ENHANCEMENT (TOSE), SUPPLEMENTAL GROUND WING ANTI-ICING, DIVIDED PARTS INSTALLATION - LTGWAIS ACTIVATION Notes (AVG MAN HRS: 25) (NOTE: NOTE: THIS SERVICE BULLETIN IS MANDATED BY AIRWORTHINESS DIRECTIVE (AD) TCCA, AD CF-2017-07R1 AND EASA, AD CF-2017-07R1. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUES THAT FOLLOW OR LATER MUST BE USED: - CL-604 AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 103, DATED NOVEMBER 28, 2016. - CL-604 OPERATING MANUAL (OM), PSP 604-6, REVISION 103, DATED NOVEMBER 28, 2016.)DECLINED						
SB 604-30-007 PART A Airframe SB - Open #51	SPECIAL CHECK/MODIFICATION - POTABLE WATER SYSTEM/WATER LINE HEATERS - WATER LINE RIBBON HEATERS WIRING						
SB 604-30-007 Airframe SB - Open #2111	SPECIAL CHECK/MODIFICATION - POTABLE WATER SYSTEM/WATER LINE HEATERS - WATER LINE RIBBON HEATERS WIRING Notes (AVG MAN HRS: 60)						
SB 604-30-007 R1 Airframe SB - Open #156	SPECIAL CHECK/MODIFICATION - POTABLE WATER SYSTEM/WATER LINE HEATERS - WATER LINE RIBBON HEATERS WIRING Notes (AVG MAN HRS: 60) (NOTE: RETROACTIVE ACTION: RETROACTIVE ACTION APPLICABLE TO AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE OF THIS SERVICE BULLETIN: - THE AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE OF THE SERVICE BULLETIN MUST DO REVISION 1 OF THIS SERVICE BULLETIN TO COMPLY WITH TCCA AIRWORTHINESS DIRECTIVE.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-001 PART A Airframe SB - Open #522	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
SB 604-31-001 Airframe SB - Superseded #849	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
	Notes .SEE REVISION 1.						
SB 604-31-001 PART B Airframe SB - Open #2418	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
SB 604-31-001 R1 PART B Airframe SB - Open #2524	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
SB 604-31-001 R1 Airframe SB - Superseded #3068	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
	Notes .SEE REVISION 2.						
SB 604-31-001 R1 PART A Airframe SB - Open #1293	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
SB 604-31-001 R2 Airframe SB - Superseded #3078	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
	Notes .SEE REVISION 3.						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-001 R2 PART B Airframe SB - Open #2356	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
SB 604-31-001 R2 PART A Airframe SB - Open #3476	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION						
SB 604-31-001 R2 (RETRO) Airframe SB - Open #2867	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION - RETROACTIVE ACTION						
SB 604-31-001 R3 PART A Airframe SB - Open #2353	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION Notes (AVG MAN HRS: 150)DECLINED						
SB 604-31-001 R3 Airframe SB - Open #812	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION Notes (NOTE: RETROACTIVE ACTION NO. 1 THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: NOTE: FOR AIRCRAFT ON WHICH REVISION 1 OR 2 OF THIS SERVICE BULLETIN WAS DONE, REFER TO RETROACTIVE ACTION NO. 2. (1) DISCONNECT WIRE WB596A22 AT CONNECTOR P1WB-A FROM PIN 5K. REFER TO ATTACHED KIT DRAWING K604-53077. (2) DISCONNECT WIRE WB597A22 AT CONNECTOR P1WB-A FROM PIN 9E. REFER TO ATTACHED KIT DRAWING K604-53077. (3) CONNECT WIRE WB596A22 AT CONNECTOR P1WB-A TO PIN 9E. REFER TO ATTACHED KIT DRAWING K604-53077. (4) CONNECT WIRE WB597A22 AT CONNECTOR P1WB-A TO PIN 5K. REFER TO ATTACHED KIT DRAWING K604-53077. (5) FOR AIRCRAFT THAT HAVE						
SB 604-31-001 R3 PART B Airframe SB - Open #585	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - INSTALLATION Notes (AVG MAN HRS: 16)DECLINED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-001 R3 Airframe SB - Open #3035	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - RETROACTIVE ACTION NO.1 Notes (RETRO 1)						
SB 604-31-001 R3 Airframe SB - Open #2861	MODIFICATION - THIRD DATA CONCENTRATOR UNIT (DCU) - RETROACTIVE ACTION NO.2 Notes (RETRO 2)						
SB 604-31-002 Airframe SB - Open #579	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION Notes (AVG MAN HRS: 90)						
SB 604-31-002 R1 Airframe SB - N/A #2328	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION Notes (AVG MAN HRS: 90).TO AIRCRAFT S/N				13-FEB-2017 H: 5969.40 L: 2571		
SB 604-31-002 R1 Part A Airframe SB - N/A #2067	MODIFICATION MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF FLIGHT DATA RECORDER Notes .TO AIRCRAFT S/N				13-FEB-2017 H: 5969.40 L: 2571		
SB 604-31-002 R1 Part B Airframe SB - N/A #3332	UPGRADE MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION DATA CONCENTRATOR UNITS (DCU) FOR THE CHALLENGER 604 OPERATING UNDER FAR, PART 135 Notes .TO AIRCRAFT S/N				13-FEB-2017 H: 5969.40 L: 2571		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-003 Airframe SB - N/A #2244	MODIFICATION - ENGINE INDICATING AND CREW ALERT SYSTEM - VERSION 4.1 SOFTWARE UPGRADE						
SB 604-31-003 PART A Airframe SB - Open #1491	MODIFICATION - ENGINE INDICATING AND CREW ALERT SYSTEM - VERSION 4.1 SOFTWARE UPGRADE Notes (AVG MAN HRS: 12)						
SB 604-31-003 PART B Airframe SB - Open #1092	MODIFICATION - ENGINE INDICATING AND CREW ALERT SYSTEM - VERSION 4.1 SOFTWARE UPGRADE Notes (AVG MAN HRS: 4)						
SB 604-31-004 Airframe SB - Open #1421	MODIFICATION - CENTER INSTRUMENT PANEL - CHANGE LINEAR MARK AROUND STANDBY FLIGHT INSTRUMENTS Notes (AVG MAN HRS: 1)						
SB 604-31-005 Airframe SB - Open #1169	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR FDR						
SB 604-31-005 R1 Airframe SB - Open #1364	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR FDR						
SB 604-31-005 R2 Airframe SB - Superseded #1583	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR FDR Notes .SEE REVISION 3.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-005 R3 Airframe SB - Superseded #936	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR FDR Notes (AVG MAN HRS: 19) (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS SERVICE BULLETIN, IT IS RECOMMENDED THAT SERVICE BULLETIN 604-31-011 BE DONE TO ADD A PROTECTIVE CAP WITH A RING/CHAIN TO THE RAU INTERFACE CONNECTOR J3RR. FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE, REVISION 1 OR REVISION 2 OF THIS SERVICE BULLETIN, NO RETROACTIVE ACTION IS REQUIRED.).SEE REVISION 4.						
SB 604-31-005 R4 Airframe SB - Open #2221	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR FDR						
SB 604-31-006 Airframe SB - Open #650	MODIFICATION - GLARESHIELD - REPLACE VISOR CRASH PADS, PART NO. 604-41111-13 AND - 14 Notes (AVG MAN HRS: 1)						
SB 604-31-007 Airframe SB - Open #754	MODIFICATION - INSTRUMENT PANELS - PUSHBUTTON-ANNUNCIATOR (PBA) SWITCHES WITH CONNECTORS, PART. NO. 13739-003 Notes (AVG MAN HRS: 8)						
SB 604-31-008 Airframe SB - Superseded #1912	MODIFICATION - GLARESHIELD - BONDING OF FLIGHT CONTROL PANEL HARNESSSES Notes .SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-008 R1 Airframe SB - Complied With #37	MODIFICATION - GLARESHIELD - BONDING OF FLIGHT CONTROL PANEL HARNESSSES Notes (AVG MAN HRS: 5)	30-NOV-1999 H: 488.00 L: 201					
SB 604-31-009 Airframe SB - Complied With #3163	MODIFICATION - CIRCUIT BREAKER PANELS (CBP) - REPLACEMENT OF THE METAL PLUG BUTTONS Notes (AVG MAN HRS: 2)	17-NOV-1999 H: 477.00 L: 185					
SB 604-31-010 Airframe SB - Superseded #3478	MODIFICATION - FLIGHT DATA RECORDER SYSTEM - INSTALLATION OF EXPANDED FLIGHT DATA RECORDER Notes .SEE REVISION 1.						
SB 604-31-010 R1 Airframe SB - N/A #2724	MODIFICATION - FLIGHT DATA RECORDER SYSTEM - INSTALLATION OF EXPANDED FLIGHT DATA RECORDER Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-010 R2 Airframe SB - N/A #3250	MODIFICATION - FLIGHT DATA RECORDER SYSTEM - INSTALLATION OF EXPANDED FLIGHT DATA RECORDER Notes (AVG MAN HRS: 68) (NOTE: RETROACTIVE ACTION 1. THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: - FOR AIRCRAFT EQUIPPED WITH THE AUTOTHROTTLE (STC SA8191NM-D), IT IS RECOMMENDED TO DO SB 604-31-018. NOTES: 1. IF THE EFDR PART NO. S800-3000-00 IS NOT AVAILABLE, IT IS RECOMMENDED TO DO SB 604-31-016 TO OBTAIN THE LATEST EFDR AVIONICS CONFIGURATION. 2. FOR AIRCRAFT THAT HAVE BEEN MODIFIED BY REVISION 01 OF THIS SERVICE BULLETIN, NO RETROACTIVE ACTION IS REQUIRED.).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-010 R3 Airframe SB - N/A #948	MODIFICATION - FLIGHT DATA RECORDER SYSTEM - INSTALLATION OF EXPANDED FLIGHT DATA RECORDER Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-010 R3 Part A Airframe SB - N/A #2998	MODIFICATION MODIFICATION - FLIGHT DATA RECORDER SYSTEM - INSTALLATION OF EXPANDED FLIGHT DATA RECORDER Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-010 R3 Part B Airframe SB - N/A #444	UPGRADE MODIFICATION - FLIGHT DATA RECORDER SYSTEM - INSTALLATION OF EXPANDED FLIGHT DATA RECORDER DATA CONCENTRATOR UNITS (DCU) FOR THE CHALLENGER 604 OPERATING UNDER FAR, PART 135 Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-011 Airframe SB - Open #3297	MODIFICATION - FLIGHT DATA RECORDER (FDR) - ADDITION OF PROTECTIVE CAP Notes (AVG MAN HRS: 1)						
SB 604-31-012 Airframe SB - Complied With #713	MODIFICATION - INSTRUMENTS AND CONTROL PANELS - WIRING CHANGE TO PREVENT EXCESSIVE HEAT BUILD-UP OF THE PUSHBUTTON ANNUNCIATORS ON THE YAW DAMPER AND STAB/MACH TRIM CONTROL PANELS Notes (AVG MAN HRS: 8)	25-MAR-2001 H: 807.00 L: 307					
SB 604-31-013 Airframe SB - Open #912	MODIFICATION - ENGINE INDICATION AND CREW ALERTING (EICAS) SYSTEM - SPOILER EXTENDED ALTITUDE AND RADIO ALTIMETER ANALOG DISPLAY CHANGES TO MEET CAA CERTIFICATION REQUIREMENTS Notes (AVG MAN HRS: 6)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-014 Airframe SB - N/A #1441	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS) Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-014 PART B Airframe SB - Open #1348	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS)						
SB 604-31-014 PART C Airframe SB - Open #3370	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS)						
SB 604-31-014 PART A Airframe SB - Open #3231	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS)						
SB 604-31-014 R1 PART B Airframe SB - Open #2682	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS) Notes (AVG MAN HRS: 300)						
SB 604-31-014 R1 PART C Airframe SB - Open #1604	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS) Notes (AVG MAN HRS: 55)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-014 R1 PART A Airframe SB - Open #1860	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS) Notes (AVG MAN HRS: 16)						
SB 604-31-014 R1 Airframe SB - N/A #113	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS) Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-014 R2 PART B Airframe SB - N/A #2503	MODIFICATION - AILERON TORQUE TUBE ASSEMBLY, YOKE RUDDER PEDAL FRONT PIVOTS AND ELEVATOR SENSOR ROD MOUNTING BRACKETS Notes (AVG MAN HRS: 300).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-014 R2 PART C Airframe SB - N/A #2020	MODIFICATION - CFMS MECHANICAL/ELECTRICAL INSTALLATION Notes (AVG MAN HRS: 65).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-014 R2 Airframe SB - N/A #2516	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - INSTALLATION OF CREW FORCE MEASURING SYSTEM (CFMS) Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-014 R2 PART A Airframe SB - N/A #658	MODIFICATION - RUDDER SENSOR HARNESS CONNECTOR BRACKETS Notes (AVG MAN HRS: 16).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-015 Airframe SB - N/A #786	MODIFICATION - EICAS & ELECTRONIC FLIGHT DISPLAY - INTRODUCTION OF NEW SOFTWARE FOR DCU AND EFD TO CORRECT "C" CHORD, EXPANDED LOCALIZER & FDR DATA VALIDITY Notes (AVG MAN HRS: 9)	13-SEP-2005					
SB 604-31-016 Airframe SB - Open #175	MODIFICATION - FLIGHT DATA RECORDER (FDR) SYSTEM - FDR PART NUMBER CHANGE AND WEIGHT REDUCTION Notes (AVG MAN HRS: 4)						
SB 604-31-018 Airframe SB - N/A #1590	MODIFICATION/REWORK - FLIGHT DATA RECORDER (FDR) SYSTEM - RELOCATION OF THE ROLL DISCONNECT BRACKET AND SWITCH Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-31-018 PART B Airframe SB - Open #1464	MODIFICATION/REWORK - FLIGHT DATA RECORDER (FDR) SYSTEM - RELOCATION OF THE ROLL DISCONNECT BRACKET AND SWITCH						
SB 604-31-018 PART A Airframe SB - Open #2641	MODIFICATION/REWORK - FLIGHT DATA RECORDER (FDR) SYSTEM - RELOCATION OF THE ROLL DISCONNECT BRACKET AND SWITCH						
SB 604-31-018 R1 PART B Airframe SB - Open #2971	MODIFICATION/REWORK - FLIGHT DATA RECORDER (FDR) SYSTEM - RELOCATION OF THE ROLL DISCONNECT BRACKET AND SWITCH Notes (AVG MAN HRS: 6)						
SB 604-31-018 R1 Airframe SB - Open #3720	MODIFICATION/REWORK - FLIGHT DATA RECORDER (FDR) SYSTEM - RELOCATION OF THE ROLL DISCONNECT BRACKET AND SWITCH						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-31-018 R1 PART A Airframe SB - Open #1123	MODIFICATION/REWORK - FLIGHT DATA RECORDER (FDR) SYSTEM - RELOCATION OF THE ROLL DISCONNECT BRACKET AND SWITCH Notes (AVG MAN HRS: 2)						
SB 604-32-001 Airframe SB - N/A #3498	MODIFICATION - REPLACEMENT OF MAIN LANDING GEAR HARNESS Notes (AVG MAN HRS: 3)						
SB 604-32-002 Airframe SB - Open #2271	MODIFICATION - NOSE LANDING GEAR (NLG) DOOR ACTUATOR - IMPROVEMENT TO GROUND LOCKING CAPABILITY Notes (AVG MAN HRS: 10)						
SB 604-32-003 Airframe SB - Open #437	MODIFICATION - BRAKE-CONTROL MECHANISM ASSEMBLY - IMPROVE PARKING BRAKE LOCKING CAPABILITY Notes (AVG MAN HRS: 10)						
SB 604-32-004 Airframe SB - Open #3385	CANCELLED PRIOR TO ISSUE						
SB 604-32-005 Airframe SB - Open #1349	MODIFICATION - PROXIMITY SENSOR SYSTEM - PREVENT DISPLAY OF INCORRECT 'PROX SYS FAULT' MESSAGE Notes (AVG MAN HRS: 10)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-006 Airframe SB - N/A #329	MODIFICATION - NOSE LANDING GEAR (NLG) DOOR OPERATING MECHANISM - REPLACEMENT OF TURNBUCKLE, PART NO. 600-86057-1 Notes (AVG MAN HRS: 3)						
SB 604-32-007 Airframe SB - Complied With #2607	MODIFICATION - MAIN LANDING GEAR BAY FAIRING - ADD A PROTECTION SHIELD AGAINST ICE BUILD-UP ON AILERON CABLES Notes (AVG MAN HRS: 10)	25-FEB-2001 H: 794.00 L: 300					
SB 604-32-009 Airframe SB - Open #281	CANCELLED PRIOR TO ISSUE						
SB 604-32-010 Airframe SB - N/A #2633	MODIFICATION - LANDING GEAR CONTROL SYSTEM - REPLACEMENT OF LANDING GEAR CONTROL HANDLE ASSEMBLY DUE TO POSSIBLE CRACKING OF SLIDER Notes (AVG MAN HRS: 4).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-32-011 Airframe SB - Open #3260	CANCELLED PRIOR TO ISSUE						
SB 604-32-012 Airframe SB - N/A #1200	SPECIAL CHECK/REWORK - NOSE LANDING GEAR (NLG) EXTENSION AND RETRACTION SYSTEM - EXAMINE/REPLACE NLG UPLOCK HARNESS CONNECTOR P85 Notes (AVG MAN HRS: 5).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-32-013 Airframe SB - Open #1147	CANCELLED PRIOR TO ISSUE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-014 Airframe SB - Open #1278	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION						
SB 604-32-014 PART B Airframe SB - Complied With #1340	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION	01-JUL-2005					
SB 604-32-014 PART C Airframe SB - Open #1442	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION						
SB 604-32-014 PART A Airframe SB - Complied With #3320	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION	01-JUL-2005					
SB 604-32-014 R1 PART C Airframe SB - Open #3183	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION						
SB 604-32-014 R1 PART B Airframe SB - Open #2038	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION						
	Notes .SCHEDULED RETROACTIVE ACTION IS APPLICABLE TO AIRCRAFT THAT HAVE COMPLIED WITH SB 604-32-014 PART B (BASIC ISSUE).						
SB 604-32-014 R1 PART A Airframe SB - Complied With #646	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION						
	Notes .PREVIOUSLY SB 604-32-014 PART A (BASIC ISSUE)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-014 R1 Airframe SB - Open #431	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION						
SB 604-32-014 R2 PART B Airframe SB - Complied With #151	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION Notes (AVG MAN HRS: 4)	12-APR-2013	H: 4782.30 L: 2063				
SB 604-32-014 R2 Airframe SB - Complied With #976	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION Notes (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE, IT IS NECESSARY TO INSPECT THE NLG MAIN FITTING/Drag STAY PIN FOR SERIAL NUMBERS WITHIN THE COMPLIANCE PERIOD OF THIS SERVICE BULLETIN. IF THE PINS ARE NOT SERIALIZED, PROCEED WITH THE SERIALIZATION OF THE NLG MAIN FITTING/Drag STAY PIN, PART NO. 200811721 IN PART B OF THIS SERVICE BULLETIN. COMPLIANCE TIME FOR THESE ITEMS STARTS AT THE REVISION 01 RELEASE DATE. FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE AND/OR REVISION 01, IT IS NECESSARY TO: (1) SERIALIZED THE NLG Drag BRACE CENTRE HINGE PIN, PART NO. 200814624 IN ACCORDANCE WITH THIS REVISION 02. (2) INSPECT THE NLG Drag BRACE CROSSBEAM PINS. IF THE PINS ARE NOT S	12-APR-2013	H: 4782.30 L: 2063				
SB 604-32-014 R2 PART C Airframe SB - Complied With #1228	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION Notes (AVG MAN HRS: 2)	12-APR-2013	H: 4782.30 L: 2063				
SB 604-32-014 R2 PART A Airframe SB - Complied With #3418	MODIFICATION - NOSE LANDING GEAR (NLG) AND MAIN LANDING GEAR (MLG) SYSTEM - NLG AND MLG COMPONENT SERIALIZATION Notes (AVG MAN HRS: 4)	12-APR-2013	H: 4782.30 L: 2063				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-015 Airframe SB - Open #697	CANCELLED PRIOR TO ISSUE						
SB 604-32-016 Airframe SB - Open #2868	CANCELLED PRIOR TO ISSUE						
SB 604-32-017 Airframe SB - Open #3486	MODIFICATION - LANDING GEAR CONTROL SYSTEM - REPLACEMENT OF LANDING GEAR CONTROL HANDLE WITH IMPROVEMENTS TO THE ACTIVATION MECHANISM AND HOUSING Notes (AVG MAN HRS: 4)						
SB 604-32-019 Airframe SB - Complied With #898	MODIFICATION - MAIN LANDING GEAR SYSTEM - INTRODUCTION OF ANTI-ROTATION END CAPS TO PREVENT BUSHING ROTATION Notes (AVG MAN HRS: 7.5).PREVIOUSLY BY VISUAL INSPECTION					02-JUN-2005 H: 2522.30 L: 983	
SB 604-32-020 Airframe SB - Complied With #448	SPECIAL CHECK/MODIFICATION - MAIN GEAR EXTENSION AND RETRACTION - POSSIBLE LEAKAGE OF THE MLG EXTENSION/RETRACTION ACTUATOR IN COLD TEMPERATURE					12-JUL-2004 H: 2246.30 L: 857	
SB 604-32-020 R1 Airframe SB - Open #760	SPECIAL CHECK/MODIFICATION - MAIN GEAR EXTENSION AND RETRACTION - POSSIBLE LEAKAGE OF THE MLG EXTENSION/RETRACTION ACTUATOR IN COLD TEMPERATURE Notes (AVG MAN HRS: 11)						
SB 604-32-021 Airframe SB - Complied With #2155	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION - END CAPS ON NOSE LANDING GEAR (NLG) SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE COULD HAVE BEEN INCORRECTLY LOCKWIRED DURING ASSEMBLY					12-JUL-2004 H: 2246.30 L: 857	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-021 R1 Airframe SB - Complied With #3710	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION - END CAPS ON NOSE LANDING GEAR (NLG) SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE COULD HAVE BEEN INCORRECTLY LOCKWIRED DURING ASSEMBLY Notes .PREVIOUSLY	19-OCT-2006 H: 2790.10 L: 1108					
SB 604-32-021 R2 Airframe SB - Complied With #484	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION - END CAPS ON NOSE LANDING GEAR (NLG) SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE COULD HAVE BEEN INCORRECTLY LOCKWIRED DURING ASSEMBLY Notes .IAW THE AD CWS	16-JUL-2007 H: 3086.90 L: 1244					
SB 604-32-021 R3 Airframe SB - N/A #1707	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION - END CAPS ON NOSE LANDING GEAR (NLG) SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE COULD HAVE BEEN INCORRECTLY LOCKWIRED DURING ASSEMBLY Notes .BY PART NUMBER	18-DEC-2008 H: 3551.80 L: 1484					
SB 604-32-021 R4 Airframe SB - Complied With #2274	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION - END CAPS ON NOSE LANDING GEAR (NLG) SELECTOR VALVE AND NOSE GEAR DOOR SELECTOR VALVE COULD HAVE BEEN INCORRECTLY LOCKWIRED DURING ASSEMBLY Notes (AVG MAN HRS: 9) (NOTE: RETROACTIVE ACTION 1. FOR ALL AIRCRAFT THAT HAVE BEEN MODIFIED BY THE BASIC ISSUE, REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN, IF BOTH SELECTOR VALVES: - HAVE A SERIAL NO. WITH A SUFFIX "T", OR - ARE INK-STAMPED WITH THE MARKING 'SB750006000-1'. NO REINSPECTION OR RETROACTIVE ACTION IS REQUIRED. 2. FOR ALL AIRCRAFT THAT HAVE BEEN MODIFIED BY REVISION 03 OF THIS SERVICE BULLETIN, NO REINSPECTION OR RETROACTIVE ACTION IS REQUIRED. 3. FOR ALL AIRCRAFT THAT DO NOT COMPLY WITH THE ABOVE STEPS, IT IS RECOMMENDED THAT THIS REVISION 04 BE DONE IN ITS ENTIRETY DUE TO THE CHANGE IN THE AFFECTED SELECTOR VALVE SERIAL NO. RANGE.)IAW THE SB	23-JUL-2010 H: 3912.80 L: 1666					
SB 604-32-022 PART B Airframe SB - Open #2606	REWORK - LANDING GEAR EMERGENCY EXTENSION - ENSURE THAT THE MOUNT BOLTS FOR THE MAIN LANDING GEAR (MLG) DOWN-LOCK ASSIST ACTUATORS ARE SAFETIED WITH LOCK-WIRE Notes (AVG MAN HRS: 3)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-022 PART A Airframe SB - Open #3622	SPECIAL CHECK - LANDING GEAR EMERGENCY EXTENSION - ENSURE THAT THE MOUNT BOLTS FOR THE MAIN LANDING GEAR (MLG) DOWN-LOCK ASSIST ACTUATORS ARE SAFETIED WITH LOCK-WIRE Notes (AVG MAN HRS: 2)						
SB 604-32-022 Airframe SB - Open #2785	SPECIAL CHECK/REWORK - LANDING GEAR EMERGENCY EXTENSION - ENSURE THAT THE MOUNT BOLTS FOR THE MAIN LANDING GEAR (MLG) DOWN-LOCK ASSIST ACTUATORS ARE SAFETIED WITH LOCK-WIRE						
SB 604-32-023 PART B Airframe SB - Open #2442	MODIFICATION - MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY - REPLACEMENT OF THE MLG UPLOCK ASSEMBLY Notes (AVG MAN HRS: 3.5)						
SB 604-32-023 PART A Airframe SB - Open #1168	SPECIAL CHECK - MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY - REPLACEMENT OF THE MLG UPLOCK ASSEMBLY Notes (AVG MAN HRS: 0.5)						
SB 604-32-023 Airframe SB - Complied With #1117	SPECIAL CHECK/MODIFICATION - MAIN LANDING GEAR (MLG) UPLOCK ASSEMBLY - REPLACEMENT OF THE MLG UPLOCK ASSEMBLY					27-JUL-2005 H: 2522.30 L: 983	
SB 604-32-024 Airframe SB - Superseded #3150	MODIFICATION - GENERAL - HARD LANDING INDICATION SYSTEM (HLIS) INSTALLATION (SUPERSEDED BY SB 604-32-024 REV 1) Notes .SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-024 R1 Airframe SB - Open #2056	MODIFICATION - GENERAL -HARD LANDING INDICATION SYSTEM (HLIS) INSTALLATION Notes (AVG MAN HRS: 45)DECLINED						
SB 604-32-025 Airframe SB - N/A #1907	SPECIAL CHECK/MODIFICATION - NOSEWHEEL STEERING - REPLACE THE NOSEWHEEL STEERING SENSOR ROTARY-VARIABLE TRANSDUCER (RVT) Notes (AVG MAN HRS: 2).BY EFFECTIVITY, PART NUMBER S/N: OF UNIT DOL-430197 PN:7102-5	22-SEP-2011 H: 4323.90 L: 1859					
SB 604-32-027 Airframe SB - Open #324	MODIFICATION - MAIN LANDING GEAR BRAKE SYSTEM - REPLACEMENT OF THE HYDRAULIC SYSTEM NO. 2 BRAKE ACCUMULATOR Notes (AVG MAN HRS: 4)DECLINED						
SB 604-32-028 Airframe SB - Open #3318	MODIFICATION - MAIN LANDING GEAR BRAKE SYSTEM - REPLACEMENT OF THE HYDRAULIC SYSTEM NO.3 BRAKE ACCUMULATOR Notes (AVG MAN HRS: 4)DECLINED						
SB 604-32-029 PART B Airframe SB - N/A #480	ACCOMPLISH MODIFICATION - REPLACEMENT OF THE SPLIT BALL BEARING Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851).NOT APPLICABLE BY PART NUMBER. VERIFIED THROUGH VISUAL INSPECTION THAT L/H AND R/H SIDESTAY ACTUATORS SPLIT BALL BEARING INSTALLED IS P/N: 19011-107. NO FURTHER ACTION REQUIRED	11-JUL-2023 H: 8075.40 L: 3647					
SB 604-32-029 PART A Airframe SB - N/A #2400	ACCOMPLISH SPECIAL CHECK Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851).NOT APPLICABLE BY PART NUMBER. VERIFIED THROUGH VISUAL INSPECTION THAT L/H AND R/H SIDESTAY ACTUATORS SPLIT BALL BEARING INSTALLED IS P/N: 19011-107. NO FURTHER ACTION REQUIRED	11-JUL-2023 H: 8075.40 L: 3647					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-029 Airframe SB - N/A #2704	SPECIAL CHECK/MODIFICATION - EXTENSION AND RETRACTION, MAIN GEAR -INSPECTION AND REPLACEMENT IF NECESSARY OF THE SIDE STAY ACTUATOR SPLIT BALL BEARING Notes (AVG MAN HRS: 7).BY PART SERIAL NUMBER	12-JAN-2018 H: 6249.00 L: 2676					
SB 604-32-029 R1 Airframe SB - Open #2302	SPECIAL CHECK/MODIFICATION - EXTENSION AND RETRACTION, MAIN GEAR -INSPECTION AND REPLACEMENT IF NECESSARY OF THE SIDE STAY ACTUATOR SPLIT BALL BEARING Notes (AVG MAN HRS: 7) (NOTE: COMPLIANCE: RECOMMENDED AT OR BEFORE 3750 FLIGHT CYCLES (SINCE NEW) OR WITHIN 48 MONTHS FROM SERVICE BULLETIN RELEASE DATE (BASIC ISSUE), WHICHEVER COMES FIRST.)						
SB 604-32-029 R2 Airframe SB - N/A #1566	SPECIAL CHECK/MODIFICATION - EXTENSION AND RETRACTION, MAIN GEAR -INSPECTION AND REPLACEMENT IF NECESSARY OF THE SIDE STAY ACTUATOR SPLIT BALL BEARING Notes (AVG MAN HRS: 7) (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (NOTE: COMPLIANCE: RECOMMENDED AT OR BEFORE 3750 FLIGHT CYCLES (SINCE NEW) OR WITHIN 48 MONTHS FROM SERVICE BULLETIN RELEASE DATE (BASIC ISSUE), WHICHEVER COMES FIRST.).NOT APPLICABLE BY PART NUMBER. VERIFIED THROUGH VISUAL INSPECTION THAT L/H AND R/H SIDESTAY ACTUATORS SPLIT BALL BEARING INSTALLED IS P/N: 19011-107. NO FURTHER ACTION REQUIRED	11-JUL-2023 H: 8075.40 L: 3647					
SB 604-32-030 Airframe SB - Complied With #847	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 Notes (UPDATE NOTE: COMPLIED WITH SERVICE BULLETIN 604-32-030 PART A, LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3, BY LUBRICATION OF THE MLG SHOCK STRUT LOWER PIN IAW CL604 AMM REVISION 96 TASK 12-20-04-640-802, SB 604-32-030 PART A AND AD 2021-20-13 PAR. (G). PART A NEXT DUE 8330 HOURS OR 12-OCT-2024, PART B NEXT DUE 8530 OR 10-OCTV-2025, PART C NEXT DUE AT 3934 LANDINGS.)	12-OCT-2023 H: 8130.00 L: 3683					
SB 604-32-030 Part B Airframe SB - Complied With #18	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 - DETAILED VISUAL INSPECTION (DVI) Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH SERVICE BULLETIN 604-32-030 PART A, LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3, BY LUBRICATION OF THE MLG SHOCK STRUT LOWER PIN IAW CL604 AMM REVISION 96 TASK 12-20-04-640-802, SB 604-32-030 PART A AND AD 2021-20-13 PAR. (G). PART A NEXT DUE 8199.5 HOURS OR 04-APR-2023, PART B NEXT DUE 8399.5 OR 01-NOV-2024, PART C NEXT DUE AT 3934 LANDINGS.) (NOTE: COMPLIANCE: BELOW 600 FC, FIRST INSPECTION NO LATER THAN 750 FC, REPEAT INSPECTION EVERY 400 FH OR 24 MONTHS, WHICHEVER COMES FIRST (EVERY SECOND LUBRICATION INTERVAL) NOTE: DVI NOT REQUIRED IF IT COINCIDES WITH THE NDT INSPECTION. THE NDT INSPECTION SUPER	12-OCT-2023 H: 8130.00 L: 3683					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-030 Part A Airframe SB - Complied With #2839	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 - LUBRICATION OF MLG SHOCK STRUT LOWER JOINT	12-OCT-2023 H: 8130.00 L: 3683					
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH SERVICE BULLETIN 604-32-030 PART A, LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3, BY LUBRICATION OF THE MLG SHOCK STRUT LOWER PIN IAW CL604 AMM REVISION 96 TASK 12-20-04-640-802, SB 604-32-030 PART A AND AD 2021-20-13 PAR. (G). PART A NEXT DUE 8330 HOURS OR 12-OCT-2024, PART B NEXT DUE 8530 OR 10-OCTV-2025, PART C NEXT DUE AT 3934 LANDINGS.) (NOTE: COMPLIANCE: 200 FLIGHT HOURS OR 12 MONTHS, WHICHEVER COMES FIRST FROM RELEASE DATE OF THIS SERVICE BULLETIN (BASIC ISSUE), REPEAT LUBRICATION, 200 FH OR 12 MONTHS, WHICHEVER COMES FIRST)						
SB 604-32-030 Part C Airframe SB - Complied With #831	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 - NON-DESTRUCTIVE TESTING (NDT) EDDY CURRENT OR LIQUID PENETRANT OR MAGNETIC PARTICLE	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: INITIAL COMPLIANCE COMPLETED BY DUNCAN AVIATION CRS JGVR194F UNDER WORK ORDER FFMBA DATED 02-JUL-2021) (NOTE: COMPLIANCE: BELOW 1200 FC, FIRST INSPECTION NO LATER THAN 1500 FC, REPEAT INSPECTION EVERY 900 FC).INITIAL COMPLIANCE COMPLETED BY DUNCAN AVIATION CRS JGVR194F UNDER WORK ORDER FFMBA DATED 02-JUL-2021						
SB 604-32-030 R1 Airframe SB - N/A #1196	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3	05-JUL-2024 H: 8455.80 L: 3862					
	Notes (AVG MAN HRS: 10) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320).NA DUE TO COMPLIANCE AND INCORPORATION OF SB 604-32-031 R1						
SB 604-32-030 R1 Part B Airframe SB - Complied With #3400	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 - DVI INSPECTION OF LH/RH MLG SHOCK STRUT LOWER PIN	15-AUG-2024 H: 8508.00 L: 3896					
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH BY DIRECT MX DYLAN MULLINS A&P 4377346 ON WO# SDL240551 DATED 8/16/2024)						
SB 604-32-030 R1 Part A Airframe SB - N/A #2862	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 - LUBRICATION OF LH/RH MLG SHOCK STRUT LOWER PIN	05-JUL-2024 H: 8455.80 L: 3862					
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-030 R1 Part C Airframe SB - N/A #532	SPECIAL CHECK - MAIN LANDING GEAR - LUBRICATION AND INSPECTION OF LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN 19146-3 - NONDESTRUCTIVE TESTING (NDT) INSPECTION OF LH/RH MLG SHOCK STRUT LOWER PIN Notes (AVG MAN HRS: 4) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)	05-JUL-2024 H: 8455.80 L: 3862					
SB 604-32-031 Airframe SB - Open #168	MODIFICATION - MAIN LANDING GEAR (MLG) SYSTEM - INTRODUCTION OF IMPROVED DYNAMIC JOINT AT LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT TO TRAILING ARM Notes (AVG MAN HRS: 9) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 5 YEARS FROM THIS SB RELEASE DATE (BASIC ISSUE).)						
SB 604-32-031 R1 Airframe SB - Complied With #2493	MODIFICATION - MAIN LANDING GEAR (MLG) SYSTEM - INTRODUCTION OF IMPROVED DYNAMIC JOINT AT LH/RH MAIN LANDING GEAR (MLG) SHOCK STRUT TO TRAILING ARM Notes (AVG MAN HRS: 9) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 5 YEARS FROM THIS SB RELEASE DATE (BASIC ISSUE). NOTE: IT IS SUGGESTED TO ALIGN THE ACCOMPLISHMENT OF THIS SERVICE BULLETIN WITH ONE OF THE FOLLOWING TLMC INSPECTIONS; 48 MONTH, 96 MONTH OR 192 MONTH.)	05-JUL-2024 H: 8455.80 L: 3862					
SB 604-32-032 Airframe SB - N/A #1932	SPECIAL CHECK/MODIFICATION - NOSEWHEEL STEERING - REPLACEMENT OF ELECTRONIC CONTROL MODULE (ECM) Notes (AVG MAN HRS: 5.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 35 MONTHS FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).).DUE TO PART NUMBERS INSTALLED	05-JUL-2024 H: 8455.80 L: 3862					
SB 604-32-033 Airframe SB - Open #2540	MODIFICATION - NOSEWHEEL STEERING REPLACEMENT OF POTENTIOMETER UNIVERSAL COUPLING (T16-6) SETSCREWS Notes (AVG MAN HRS: 4) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 36 MONTHS FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-32-033 R1 Airframe SB - Open #3303	MODIFICATION - NOSEWHEEL STEERING - REPLACEMENT OF POTENTIOMETER UNIVERSAL COUPLING (T16-6) SETSCREWS Notes (AVG MAN HRS: 4)						
SB 604-33-001 Airframe SB - Open #1908	MODIFICATION - WING LANDING/TAXI LIGHT SYSTEM - INSTALLATION OF PULSATING LIGHT SYSTEM						
SB 604-33-001 R1 Airframe SB - Open #245	MODIFICATION - WING LANDING/TAXI LIGHT SYSTEM - INSTALLATION OF PULSATING LIGHT SYSTEM						
SB 604-33-001 R2 Airframe SB - Open #666	MODIFICATION - WING LANDING/TAXI LIGHT SYSTEM - INSTALLATION OF PULSATING LIGHT SYSTEM Notes (AVG MAN HRS: 40).OPEN						
SB 604-33-002 Airframe SB - Open #100	MODIFICATION - STANDBY - INSTRUMENT INTEGRAL LIGHTING - POWER SOURCE CHANGE Notes (AVG MAN HRS: 6)						
SB 604-33-003 Airframe SB - Complied With #2994	MODIFICATION - NAVIGATION LIGHTS - REPLACE NAVIGATION LIGHT AT VERTICAL STABILIZER					12-JUL-2004 H: 2246.30 L: 857	
SB 604-33-003 R1 Airframe SB - Complied With #3641	MODIFICATION - NAVIGATION LIGHTS - REPLACE NAVIGATION LIGHT AT VERTICAL STABILIZER Notes .PREVIOUSLY BASIC ISSUE						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-33-003 R2 Airframe SB - Complied With #1186	MODIFICATION - NAVIGATION LIGHTS - REPLACE NAVIGATION LIGHT AT VERTICAL STABILIZER Notes (AVG MAN HRS: 5).PREVIOUSLY BASIC ISSUE						
SB 604-33-004 Airframe SB - Complied With #1690	MODIFICATION - NAVIGATION LIGHTS - CHANGE OF CIRCUIT BREAKER RATING FROM 3 AMPS TO 2 AMPS Notes (AVG MAN HRS: 1)	10-JUN-2005 H: 2522.30 L: 983					
SB 604-33-006 PART B Airframe SB - Superseded #1493	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes .SEE REVISION 1.						
SB 604-33-006 Airframe SB - Open #982	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY						
SB 604-33-006 PART A Airframe SB - Superseded #3371	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes .SEE REVISION 1.						
SB 604-33-006 PART C Airframe SB - Superseded #3191	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes .SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-33-006 R1 PART B Airframe SB - Open #2519	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes (AVG MAN HRS: 8.5)DECLINED						
SB 604-33-006 R1 PART A Airframe SB - Open #112	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes (AVG MAN HRS: 19)DECLINED						
SB 604-33-006 R1 PART C Airframe SB - Open #455	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes (AVG MAN HRS: 1)DECLINED						
SB 604-33-006 R1 Airframe SB - Open #1524	MODIFICATION - NAVIGATION LIGHTS - INTRODUCTION OF WING TIP AND LOWER TAIL HALOGEN NAVIGATION LIGHTS TO IMPROVE RELIABILITY Notes DECLINED						
SB 604-33-007 Airframe SB - Superseded #2364	MODIFICATION - FLOODLIGHTING PANEL - COCKPIT FLOODLIGHT GASKET INSTALLATION TO PREVENT WATER INGRESS Notes (AVG MAN HRS: 2).SEE REVISION 1.						
SB 604-33-007 R1 Airframe SB - Superseded #1141	MODIFICATION - FLOODLIGHTING PANEL - COCKPIT FLOODLIGHT GASKET INSTALLATION TO PREVENT WATER INGRESS Notes (AVG MAN HRS: 2).SEE REVISION 2.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-33-007 R2 Airframe SB - Complied With #1730	MODIFICATION - FLOODLIGHTING PANEL - COCKPIT FLOODLIGHT GASKET INSTALLATION TO PREVENT WATER INGRESS	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: SB 604-33-007 R2 "MODIFICATION - FLOODLIGHTING PANEL - COCKPIT FLOODLIGHT GASKET INSTALLATION TO PREVENT WATER INGRESS." DUNCAN AVIATION WO FFMBA.) (NOTE: NOTE: THIS SERVICE BULLETIN IS IN REFERENCE TO TRANSPORT CANADA CIVIL AVIATION (TCCA), AIRWORTHINESS DIRECTIVE (AD), CF-2016-40.).SB 604-33-007 R2 "MODIFICATION - FLOODLIGHTING PANEL - COCKPIT FLOODLIGHT GASKET INSTALLATION TO PREVENT WATER INGRESS."						
SB 604-34-001 Airframe SB - Open #3447	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) INSTALLATION						
SB 604-34-001 R1 Airframe SB - Open #1833	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) INSTALLATION						
	Notes (AVG MAN HRS: 110) (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS SERVICE BULLETIN, THE TCAS SYSTEM CAN BE UPGRADED TO "CHANGE 7.0" AS AN OPTION. REFER TO SERVICE BULLETIN 604-34-027.)						
SB 604-34-002 Airframe SB - Open #1756	MODIFICATION - THIRD FLIGHT MANAGEMENT SYSTEM - INSTALLATION						
SB 604-34-002 R1 Airframe SB - Open #1763	MODIFICATION - THIRD FLIGHT MANAGEMENT SYSTEM - INSTALLATION						
SB 604-34-002 R2 Airframe SB - Complied With #1432	MODIFICATION - THIRD FLIGHT MANAGEMENT SYSTEM - INSTALLATION	03-AUG-2005 H: 2522.30 L: 983					
	Notes .PARAGRAPHS 2A,2B,2C,2D,2E AND 2F						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-002 R3 Airframe SB - Complied With #856	MODIFICATION - THIRD FLIGHT MANAGEMENT SYSTEM - INSTALLATION Notes (AVG MAN HRS: 22).PREVIOUSLY SB 604-34-002 REV 2						
SB 604-34-003 Airframe SB - Open #2343	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) INSTALLATION Notes (AVG MAN HRS: 90)						
SB 604-34-004 Airframe SB - Open #3516	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION						
SB 604-34-004 R1 Airframe SB - Open #2875	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION						
SB 604-34-004 R2 Airframe SB - Open #2827	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION Notes (AVG MAN HRS: 175) (NOTE: FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN HAS BEEN DONE, SB 604-34-022, PART B IS OFFERED AS AN OPTION (PRODUCT IMPROVEMENT) TO ADD MANUAL SELECTION OF ADC SOURCE, UNINTERRUPTED BACKUP POWER TO IRU 2 AND PREVENT THE STORAGE OF NUISANCE FAULTS IN THE NON-VOLATILE MEMORY OF THE IRS SYSTEM. THESE NUISANCE FAULTS ARE TRANSPARENT TO THE FLIGHT CREW AND DO NOT AFFECT AIRCRAFT DISPATCH. 2. OPERATORS THAT ARE CONSIDERING THIS SB 604-34-004 AT REVISION 02, ALREADY MEET THE INTENT OF SB 604-34-022 PART B, BUT MUST INCORPORATE SB 604-34-022 PART A (IF APPLICABLE) BEFORE OR AT THE SAME TIME AS THIS SERVICE BULLETIN.)						
SB 604-34-005 Airframe SB - Open #3621	MODIFICATION - RADIO ALTIMETER SYSTEM - SECOND RADIO ALTIMETER - INSTALLATION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-005 R1 Airframe SB - Open #3481	MODIFICATION - RADIO ALTIMETER SYSTEM - SECOND RADIO ALTIMETER - INSTALLATION Notes (AVG MAN HRS: 110).OPEN						
SB 604-34-006 Airframe SB - Open #3664	MODIFICATION - WEATHER RADAR SYSTEM - DUAL WEATHER RADAR CONTROL PANEL (WXP) INSTALLATION						
SB 604-34-006 R1 Airframe SB - Open #3572	MODIFICATION - WEATHER RADAR SYSTEM - DUAL WEATHER RADAR CONTROL PANEL (WXP) INSTALLATION Notes (AVG MAN HRS: 30)						
SB 604-34-007 Airframe SB - Open #1575	MODIFICATION - DUAL GLOBAL POSITIONING SYSTEM (GPS) - INSTALLATION Notes (AVG MAN HRS: 60)						
SB 604-34-008 Airframe SB - Open #83	THIS SERVICE BULLETIN IS SUPERSEDED BY SERVICE BULLETIN 604-34-063 - MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - INSTALLATION						
SB 604-34-008 R1 Airframe SB - Open #2008	THIS SERVICE BULLETIN IS SUPERSEDED BY SERVICE BULLETIN 604-34-063 - MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - INSTALLATION						
SB 604-34-009 Airframe SB - Open #1585	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - PRE-PROVISIONAL INSTALLATION						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-009 R1 Airframe SB - Open #3669	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - PRE-PROVISIONAL INSTALLATION						
SB 604-34-009 R2 Airframe SB - Open #1784	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - PRE-PROVISIONAL INSTALLATION Notes (AVG MAN HRS: 88) (NOTE: RETROACTIVE ACTION 1. FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS SERVICE BULLETIN, IT IS RECOMMENDED THAT SERVICE BULLETIN 604-34-026 IS DONE TO RELOCATE THE POWER SOURCE FOR THE DATA LOADER. 2. FOR AIRCRAFT THAT HAVE BEEN MODIFIED BY REVISION 01 OF THIS SERVICE BULLETIN, NO RETROACTIVE ACTION IS REQUIRED)						
SB 604-34-010 Airframe SB - Open #1091	MODIFICATION - METRIC ALTITUDE SWITCH INSTALLATION Notes (AVG MAN HRS: 12)						
SB 604-34-011 Airframe SB - N/A #3342	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - VERSION 4.3 SOFTWARE UPGRADE Notes (AVG MAN HRS: 12)	20-DEC-2002					
SB 604-34-012 Airframe SB - Open #2476	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 Part E1 Airframe SB - Open #824	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 Part E2 Airframe SB - Open #1984	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-012 R1 Part F Airframe SB - Open #2083	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R1 Part D Airframe SB - Open #2482	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R1 Airframe SB - Open #3156	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R2 Part F2 Airframe SB - Open #2303	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R2 Airframe SB - Open #2319	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R2 Part D Airframe SB - Open #2660	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R2 Part F1 Airframe SB - Open #3503	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R2 Part F3 Airframe SB - Open #346	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-012 R3 Part F2 Airframe SB - Open #1007	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R3 Part F1 Airframe SB - Open #1239	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R3 Part F3 Airframe SB - Open #1281	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R3 Airframe SB - Open #3580	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R4 Airframe SB - Complied With #3262	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS					14-NOV-2008 H: 3501.60 L: 1466	
	Notes .AT MANUFACTURE FOUND PREVIOUSLY COMPLIED WITH						
SB 604-34-012 R5 PART C Airframe SB - Open #2952	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-012 R5 PART A Airframe SB - Open #3583	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-012 R5 Airframe SB - Open #2004	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS Notes (AVG MAN HRS: 12)						
SB 604-34-012 R5 PART B Airframe SB - Open #779	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) TO 1000 FT. AIRCRAFT QUALIFICATION REQUIREMENTS						
SB 604-34-013 Airframe SB - Open #946	MODIFICATION - STANDBY FLIGHT INSTRUMENT - INSTALL NEW AIRSPEED INDICATOR (ASI) AND BARO-ALTIMETER Notes (AVG MAN HRS: 12)						
SB 604-34-014 PART A Airframe SB - Open #894	MODIFICATION - INERTIAL REFERENCE UNIT (IRU) MOUNTAIN TRAYS - REPLACE SUPPORT ANGLE ASSEMBLIES Notes (AVG MAN HRS: 11)						
SB 604-34-014 PART B Airframe SB - Open #1739	MODIFICATION - INERTIAL REFERENCE UNIT (IRU) MOUNTAIN TRAYS - REPLACE SUPPORT ANGLE ASSEMBLIES Notes (AVG MAN HRS: 9) (NOTE: THE INTENT OF PART B OF THIS SERVICE BULLETIN HAS BEEN MET BY RNIEO ACTION ON AIRCRAFT, SERIAL NO. 5305, 5310, 5315, 5318, 5319, 5321, 5323 TO 5326 AND 5334.)						
SB 604-34-014 Airframe SB - Open #2337	MODIFICATION - INERTIAL REFERENCE UNIT (IRU) MOUNTAIN TRAYS - REPLACE SUPPORT ANGLE ASSEMBLIES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-015 Airframe SB - Open #1999	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - INSTALLATION FOR AIRCRAFT WITH PROVISIONS FOR AFIS						
SB 604-34-015 R1 Airframe SB - Open #2981	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - INSTALLATION FOR AIRCRAFT WITH PROVISIONS FOR AFIS						
SB 604-34-015 R2 Airframe SB - Open #1064	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - INSTALLATION FOR AIRCRAFT WITH PROVISIONS FOR AFIS						
SB 604-34-015 R3 Airframe SB - Open #1501	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - INSTALLATION FOR AIRCRAFT WITH PROVISIONS FOR AFIS Notes (AVG MAN HRS: 23) (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS SERVICE BULLETIN, IT IS RECOMMENDED THAT SERVICE BULLETIN 604-34-026 IS DONE TO RELOCATE THE POWER SOURCE FOR THE DATA LOADER.)						
SB 604-34-016 Airframe SB - Open #3468	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR GPWS Notes (AVG MAN HRS: 17)						
SB 604-34-017 Airframe SB - Open #1567	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR TCAS						
SB 604-34-017 R1 Airframe SB - Open #1893	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR TCAS Notes (AVG MAN HRS: 26) (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS SERVICE BULLETIN, THE TCAS SYSTEM CAN BE UPGRADED TO "CHANGE 7.0" AS AN OPTION. REFER TO SERVICE BULLETIN 604-34-027.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-018 Airframe SB - Open #416	MODIFICATION - DUAL GLOBAL POSITIONING SYSTEM (GPS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR DUAL GPS						
SB 604-34-018 R1 Airframe SB - Open #1950	MODIFICATION - DUAL GLOBAL POSITIONING SYSTEM (GPS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR DUAL GPS Notes (AVG MAN HRS: 16)						
SB 604-34-018 R2 Airframe SB - Open #2930	MODIFICATION - DUAL GLOBAL POSITIONING SYSTEM (GPS) - INSTALLATION AN AIRCRAFT WITH PROVISIONS FOR DUAL GPS.						
SB 604-34-019 Airframe SB - Open #1353	MODIFICATION - UPGRADE AIR DATA COMPUTER, PART NO. 822-0842-138 TO PART NO. 822-0842-142 Notes (AVG MAN HRS: 4)						
SB 604-34-020 Airframe SB - Complied With #47	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS					28-JUL-2005 H: 2522.30 L: 983	
SB 604-34-020 PART B Airframe SB - Open #1032	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS						
SB 604-34-020 PART A Airframe SB - Open #882	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS						
SB 604-34-020 PART C Airframe SB - Open #3041	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-020 R1 Airframe SB - Complied With #2662	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS Notes .PARAGRAPHS 2A,2C (PART B), 2D (PART C), 2E THROUGH 2T	03-AUG-2005 H: 2522.30 L: 983					
SB 604-34-020 R1 PART C Airframe SB - Open #723	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS Notes (AVG MAN HRS: 10)						
SB 604-34-020 R1 PART A Airframe SB - Open #603	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS Notes (AVG MAN HRS: 250)						
SB 604-34-020 R1 PART B Airframe SB - Open #314	MODIFICATION - GROUND PROXIMITY WARNING SYSTEM (GPWS) - INTRODUCTION OF THE ENHANCED GPWS Notes (AVG MAN HRS: 235)						
SB 604-34-021 Airframe SB - Open #715	MODIFICATION - AIR DATA SYSTEM - CAUSE THE BAROMETRIC PRESSURE DISPLAY TO FLASH TO IMPROVE ATTENTION Notes (AVG MAN HRS: 2)						
SB 604-34-022 PART B Airframe SB - Open #1877	MODIFICATION - INERTIAL REFERENCE SYSTEM (IRS) - ADC REVERSION, IRU 2 POWER AND RECTIFICATION OF NUISANCE FAULTS Notes (AVG MAN HRS: 12)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-022 PART A Airframe SB - Open #2091	MODIFICATION - INERTIAL REFERENCE SYSTEM (IRS) - ADC REVERSION, IRU 2 POWER AND RECTIFICATION OF NUISANCE FAULTS Notes (AVG MAN HRS: 42)						
SB 604-34-022 Airframe SB - Open #2700	MODIFICATION - INERTIAL REFERENCE SYSTEM (IRS) - ADC REVERSION, IRU 2 POWER AND RECTIFICATION OF NUISANCE FAULTS						
SB 604-34-023 PART B Airframe SB - Complied With #184	REWORK - FLIGHT MANAGEMENT SYSTEM (FMS) - DISABLE FEATURE TO ALLOW AUTOMATIC INITIALIZATION OF AIRCRAFT POSITION TO SECOND FMS Notes (AVG MAN HRS: 1)	10-DEC-1998 H: 208.00 L: 85					
SB 604-34-023 PART A Airframe SB - Complied With #2087	SPECIAL CHECK - FLIGHT MANAGEMENT SYSTEM (FMS) - DISABLE FEATURE TO ALLOW AUTOMATIC INITIALIZATION OF AIRCRAFT POSITION TO SECOND FMS Notes (AVG MAN HRS: 0.15)	10-DEC-1998 H: 208.00 L: 85					
SB 604-34-023 Airframe SB - Open #3518	SPECIAL CHECK/REWORK - FLIGHT MANAGEMENT SYSTEM (FMS) - DISABLE FEATURE TO ALLOW AUTOMATIC INITIALIZATION OF AIRCRAFT POSITION TO SECOND FMS						
SB 604-34-024 Airframe SB - Open #1072	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - IMPROVE AFIS FLIGHT PLAN OPERATION AND SOFTWARE UPGRADE Notes (AVG MAN HRS: 3)						
SB 604-34-025 Airframe SB - Open #1921	MODIFICATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) - INSTALLATION OF THE EGPWS FOR AIRCRAFT WITH FULL PROVISIONS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-025 R1 Airframe SB - Open #180	MODIFICATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) - INSTALLATION OF THE EGPWS FOR AIRCRAFT WITH FULL PROVISIONS Notes (AVG MAN HRS: 40)						
SB 604-34-026 Airframe SB - Open #210	MODIFICATION - AIRBORNE FLIGHT INFORMATION SYSTEM (AFIS) - DATA LOADER POWER SOURCE RELOCATION Notes (AVG MAN HRS: 8)						
SB 604-34-027 Airframe SB - Open #307	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) - "CHANGE 7.0" UPGRADE Notes (AVG MAN HRS: 3)						
SB 604-34-028 Airframe SB - Open #1609	MODIFICATION - AIR TRAFFIC CONTROL TRANSPONDER SYSTEM - WIRING PROVISIONS TO ALLOW INSTALLATION OF ATC TRANSPONDER 622-9210-004 Notes (AVG MAN HRS: 24)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-029 Airframe SB - Open #3234	MODIFICATION - AIR DATA SYSTEM - INTRODUCTION OF ALTERNATE VMO/MMO PROFILE FOR CAA CERTIFICATION Notes (AVG MAN HRS: 4) (NOTE: FOR AIRCRAFT, SERIAL NO. 5301 TO 5499, THE SERVICE BULLETIN THAT FOLLOWS IS A PREREQUISITE TO THIS SERVICE BULLETIN. AIRCRAFT, SERIAL NO. 5500 AND SUBSEQUENT, WILL HAVE THE INTENT OF SB 604-34-031 INCORPORATED IN PRODUCTION: SERVICE BULLETIN TITLE 604-34-031 MODIFICATION - ENGINE INDICATING AND CREW ALERTING SYSTEM AND FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF BASIC MID LIFE AVIONICS 4. THE SERVICE BULLETINS THAT FOLLOW ARE ALSO REQUIRED FOR UNITED KINGDOM CAA REGISTRATION: SERVICE BULLETIN TITLE 604-27-009 MODIFICATION - ELEVATOR CONTROL SYSTEM - INTRODUCTION OF PITCH FEEL SIMULATOR WITH INCREASED STICK FORCE IN HIGH "G" MANEUVER FOR CAA CERTIFICATION 604-3						
SB 604-34-030 Airframe SB - Open #1724	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR IRS						
SB 604-34-030 R1 Airframe SB - Open #3205	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR IRS						
SB 604-34-030 R2 Airframe SB - Open #1945	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR IRS						
SB 604-34-030 R3 Airframe SB - Open #457	MODIFICATION - THIRD INERTIAL REFERENCE SYSTEM (IRS) - INSTALLATION ON AIRCRAFT WITH PROVISIONS FOR IRS Notes (AVG MAN HRS: 30)						
SB 604-34-031 Airframe SB - Open #3277	MODIFICATION - ENGINE INDICATING AND CREW ALERTING SYSTEM AND FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF BASIC PRECISIONPLUS™ AVIONICS UPGRADE						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-031 R1 Airframe SB - Open #3683	MODIFICATION - ENGINE INDICATING AND CREW ALERTING SYSTEM AND FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF BASIC PRECISIONPLUS AVIONICS UPGRADE - RETROACTIVE ACTION Notes (RETRO)						
SB 604-34-031 R1 Airframe SB - Complied With #283	MODIFICATION - ENGINE INDICATING AND CREW ALERTING SYSTEM AND FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF BASIC PRECISIONPLUS™ AVIONICS UPGRADE Notes .PARAGRAPHS 2A,B,C,D,E,F & G	03-AUG-2005 H: 2522.30 L: 983					
SB 604-34-031 R2 Airframe SB - Complied With #1128	MODIFICATION - ENGINE INDICATING AND CREW ALERTING SYSTEM AND FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF BASIC PRECISIONPLUS™ AVIONICS UPGRADE Notes (AVG MAN HRS: 20) (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: (1) SB 604-31-015 MUST BE DONE. (2) VERIFY IF YOU COMPLY WITH THE REVISED COMPLIANCE NOTES IN PARAGRAPH 1 OF REVISION 01.).PREVIOUSLY PREVIOUS ISSUE OF THIS SERVICE BULLETIN						
SB 604-34-032 Airframe SB - Complied With #279	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - UPGRADE OF THE FLIGHT MANAGEMENT COMPUTERS FOR THE NON PRECISIONPLUSTM UPGRADED AIRCRAFT	12-JUL-2004 H: 2246.30 L: 857					
SB 604-34-032 R1 Airframe SB - N/A #2186	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - UPGRADE OF THE FLIGHT MANAGEMENT COMPUTERS FOR THE NON PRECISIONPLUSTM UPGRADED AIRCRAFT Notes (AVG MAN HRS: 6)	20-DEC-2002					
SB 604-34-033 Airframe SB - Open #1027	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - 3D MAP/LONG RANGE CRUISE INSTALLATION Notes (AVG MAN HRS: 3)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-034 Airframe SB - Open #3080	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INSTALLATION OF SEARCH PATTERNS						
SB 604-34-034 R1 Airframe SB - Open #988	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INSTALLATION OF SEARCH PATTERNS Notes (AVG MAN HRS: 3).OPEN						
SB 604-34-035 Airframe SB - Complied With #2984	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF NEW V-SPEED DATA BASES Notes .NO FURTHER ACTION REQUIRED				25-JUN-2005 H: 2522.30 L: 983		
SB 604-34-035 R1 Airframe SB - Complied With #2005	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF NEW V-SPEED DATA BASES Notes (AVG MAN HRS: 3).PREVIOUSLY SB 604-34-035 BASIC ISSUE						
SB 604-34-036 Airframe SB - Open #3541	CANCELLED PRIOR TO ISSUE						
SB 604-34-037 Airframe SB - Complied With #1343	MODIFICATION - RADIO TUNING SYSTEM / AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INTRODUCTION OF ELEMENTARY MODE S SURVEILLANCE/ACAS II FOR AIRCRAFT WITH PRECISIONPLUSTM AVIONICS Notes (AVG MAN HRS: 5)				25-JAN-2007 H: 2895.70 L: 1155		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-038 Airframe SB - Open #2597	MODIFICATION - RADIO TUNING SYSTEM / AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INTRODUCTION OF ELEMENTARY MODE S SURVEILLANCE/ACAS II FOR AIRCRAFT WITHOUT PRECISIONPLUS AVIONICS Notes (AVG MAN HRS: 7)						
SB 604-34-040 Airframe SB - Complied With #2077	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INTRODUCTION OF THE MODE S ENHANCED SURVEILLANCE FOR AIRCRAFT WITH PRECISION PLUS	25-JAN-2007 H: 2895.70 L: 1155					
SB 604-34-040 R1 Airframe SB - Open #2419	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INTRODUCTION OF THE MODE S ENHANCED SURVEILLANCE FOR AIRCRAFT WITH PRECISION PLUS Notes (AVG MAN HRS: 80) (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: (1) DO THE STRAPPING CONFIGURATION CHANGE AS PER SB 604-34-054, IF NOT ALREADY DONE. NOTE: PERFORM SB 604-34-054, CHANGING THE STRAPPING CONFIGURATION FOR AIRCRAFT WITH MODE S ENHANCED SURVEILLANCE INSTALLED, TO ALLOW MODE S DETECTION.).OPEN FOR AIRCRAFT THAT HAVE ALREADY COMPLIED WITH BASIC ISSUE OF THIS SERVICE BULLETIN, THE RETROACTIVE ACTION IN SB 604-34-040 REV 1 IS RECOMMENDED						
SB 604-34-041 Airframe SB - N/A #3162	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INTRODUCTION OF THE MODE S ENHANCED SURVEILLANCE FOR AIRCRAFT WITHOUT PRECISION PLUS Notes .AIRCRAFT HAS PRECISION PLUS - SB 604-34-031 REV 1 C/W						
SB 604-34-041 R1 Airframe SB - N/A #3696	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INTRODUCTION OF THE MODE S ENHANCED SURVEILLANCE FOR AIRCRAFT WITHOUT PRECISION PLUS Notes (AVG MAN HRS: 80) (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: (1) DO THE STRAPPING CONFIGURATION CHANGE AS PER SB 604-34-054, IF NOT ALREADY DONE. NOTE: PERFORM SB 604-34-054, CHANGING THE STRAPPING CONFIGURATION FOR AIRCRAFT WITH MODE S ENHANCED SURVEILLANCE INSTALLED, TO ALLOW MODE S DETECTION.).AIRCRAFT HAS PRECISION PLUS - SB 604-34-031 REV 1 C/W						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-042 Airframe SB - Complied With #3681	MODIFICATION - FLIGHT MANAGEMENT COMPUTING - INTRODUCTION OF THE FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 3.0.3 Notes (AVG MAN HRS: 9)	16-OCT-2009 H: 3725.60 L: 1574					
SB 604-34-043 Airframe SB - Open #347	CANCELLED PRIOR TO ISSUE						
SB 604-34-050 Airframe SB - Open #3387	MODIFICATION - FLIGHT MANAGEMENT COMPUTING - INTRODUCTION OF THE FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 3.3.1						
SB 604-34-050 R1 Airframe SB - Open #1047	MODIFICATION - FLIGHT MANAGEMENT COMPUTING - INTRODUCTION OF THE FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 3.3.1 Notes (AVG MAN HRS: 9).OPEN						
SB 604-34-052 Airframe SB - Complied With #1157	SPECIAL CHECK/MODIFICATION - AIR-DATA SYSTEM - EXTENSION OF THE ADC RVSM INSPECTION INTERVAL FROM 12 MONTHS TO 24 MONTHS (INCORPORATION OF ROCKWELL COLLINS SERVICE BULLETIN ADC-850 () -34-63) Notes (AVG MAN HRS: 8).PREVIOUSLY	07-JUN-2011 H: 4207.70 L: 1818					
SB 604-34-053 Airframe SB - Open #3547	MODIFICATION - FLIGHT MANAGEMENT COMPUTER-CONFIGURATION DIFFERENCES BETWEEN FAA AND DOT TYPE CERTIFIED AIRCRAFT Notes (AVG MAN HRS: 3)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-054 Airframe SB - Complied With #32	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - STRAPPING CONFIGURATION CHANGE FOR AIRCRAFT WITH MODE S ENHANCE SURVEILLANCE	25-JAN-2007 H: 2895.70 L: 1155					
	Notes (AVG MAN HRS: 4) (NOTE: FRANCE, GERMANY AND UNITED KINGDOM ARE MANDATING THE CARRIAGE AND THE OPERATION OF THE MODE S ENHANCE SURVEILLANCE AIRBORNE EQUIPMENT. THIS MANDATE WILL BE APPLICABLE FOR ALL AIRCRAFT FLYING AS IFR/GAT EFFECTIVE AS OF 31 MARCH 2007.)						
SB 604-34-055 Airframe SB - Open #105	MODIFICATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) - INTRODUCTION OF THE STEEP APPROACH PUSH BUTTON ANNUNCIATOR (PBA)						
	Notes (AVG MAN HRS: 38).OPEN SB 604-34-020 OR SB 604-34-025 IS A PRE-REQUISITE AND MUST BE DONE BEFORE OR AT THE SAME TIME AS THIS SERVICE BULLETIN.						
SB 604-34-055 R1 Airframe SB - Open #3460	MODIFICATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) - INTRODUCTION OF THE STEEP APPROACH PUSH BUTTON ANNUNCIATOR (PBA)						
	Notes (AVG MAN HRS: 38) (NOTE: CONTROLLED EFFECTIVITY NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - AIRPLANE FLIGHT MANUAL (AFM), PSP 604-1, REVISION 105, (CHAPTER 7, SUPPLEMENT 12 AND 20, DATED MAR 13/2017. - OPERATING MANUAL (OM), PSP 604-6, REVISION 105, VOL. 1, DATED MAR 13/2017.)						
SB 604-34-056 Airframe SB - Open #3327	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER						
SB 604-34-056 PART A Airframe SB - N/A #1568	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER						
	Notes .BY EFFECTIVITY						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-056 PART C Airframe SB - Open #1510	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes .OPEN						
SB 604-34-056 PART B Airframe SB - Open #1832	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes .OPEN						
SB 604-34-056 R1 PART C Airframe SB - Open #2043	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 13)						
SB 604-34-056 R1 PART A Airframe SB - Open #2141	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 17)						
SB 604-34-056 R1 PART B Airframe SB - Open #2159	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 12)						
SB 604-34-056 R1 Airframe SB - Open #3132	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-056 R2 Airframe SB - Open #1806	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 32) (NOTE: NOTE: THE TECHNICAL CONTENT OF THIS SERVICE BULLETIN IS ONLY APPROVED BY TCCA & FAA. TO IMPLEMENT THIS MODIFICATION ON EASA AND CANADIAN REGISTERED AIRCRAFT, REFER TO THE EQUIVALENT SB 604-34-067.)						
SB 604-34-056 R2 PART C Airframe SB - Open #2835	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER - DO THE OPTIONAL "METRIC" ALTIMETER INDICATION MODIFICATION FOR THE AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 13) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE OPERATING MANUAL ISSUE THAT FOLLOWS OR LATER MUST BE USED: - PSP604-6, MODEL CL-600-2B16, VOLUME 2, REVISION 73, DATED, MAY 14/2008.)						
SB 604-34-056 R2 PART A Airframe SB - Open #1346	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER - DO THE PARTIAL INSTALLATION OF SB 604-34-013 Notes (AVG MAN HRS: 17)						
SB 604-34-056 R2 PART B Airframe SB - Open #3299	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER - REPLACE THE OLD STANDBY ALTIMETER WITH THE NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 12) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE OPERATING MANUAL ISSUE THAT FOLLOWS OR LATER MUST BE USED: - PSP604-6, MODEL CL-600-2B16, VOLUME 2, REVISION 73, DATED, MAY 14/2008.)						
SB 604-34-057 Airframe SB - Open #915	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM						
SB 604-34-057 R1 Airframe SB - Open #117	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-057 R2 Airframe SB - Open #711	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM						
SB 604-34-057 R3 Airframe SB - Open #1476	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM Notes (AVG MAN HRS: 4)						
SB 604-34-057 R4 Airframe SB - Open #2510	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM Notes (AVG MAN HRS: 4) (NOTE: CONCURRENT REQUIREMENTS. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUALS ISSUE THAT FOLLOWS OR LATER MUST BE USED: - AIRPLANE FLIGHT MANUAL, PSP 604-1, REVISION 78 DATED FEB 01/2010. - OPERATING MANUAL, PSP 604-6, REVISION 78 DATED FEB 01/2010.)						
SB 604-34-057 R5 Airframe SB - Open #3666	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM Notes (AVG MAN HRS: 4) (NOTE: CONCURRENT REQUIREMENTS: SB 604-34-007 (FOR AIRCRAFT, SERIAL NO. 5304, 5305, AND 5307 TO 5330) OR SB 604-34-018 (FOR AIRCRAFT, SERIAL NO. 5331 TO 5609) IS A PREREQUISITE AND MUST BE DONE BEFORE OR AT THE SAME TIME AS THIS SERVICE BULLETIN.)						
SB 604-34-057 R6 Airframe SB - Open #907	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INSTALL WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM Notes (AVG MAN HRS: 4) (NOTE: CONCURRENT REQUIREMENTS: SB 604-34-007 (FOR AIRCRAFT, SERIAL NO. 5304, 5305, AND 5307 TO 5330) OR SB 604-34-018 (FOR AIRCRAFT, SERIAL NO. 5331 TO 5609) IS A PREREQUISITE AND MUST BE DONE BEFORE OR AT THE SAME TIME AS THIS SERVICE BULLETIN.)						
SB 604-34-058 Airframe SB - Open #1438	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER PART NO. 622-9210-409 WITH AUTOMATIC DEPENDANT SURVEILLANCE-BROADCAST (ADS-B) OUT CAPABILITY						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-058 R1 Airframe SB - Open #494	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER PART NO. 622-9210-409 WITH AUTOMATIC DEPENDANT SURVEILLANCE-BROADCAST (ADS-B) OUT CAPABILITY						
SB 604-34-058 R2 Airframe SB - Open #2743	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER PART NO. 622-9210-409 WITH AUTOMATIC DEPENDANT SURVEILLANCE-BROADCAST (ADS-B) OUT CAPABILITY Notes (AVG MAN HRS: 32)						
SB 604-34-060 Airframe SB - Open #3652	MODIFICATION - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) - "CHANGE 7.1" UPGRADE TO MEET THE NEW REGULATION REQUIREMENT Notes (AVG MAN HRS: 3)						
SB 604-34-063 Airframe SB - Open #3335	MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - INSTALLATION OF THE LDS Notes (AVG MAN HRS: 275) (NOTE: THIS SERVICE BULLETIN SUPERSEDES SB 604-34-008.)						
SB 604-34-063 R1 Airframe SB - Open #1474	MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - INSTALLATION OF THE LDS (SUPERSEDES SB 604-34-008) Notes (AVG MAN HRS: 275)						
SB 604-34-064 Airframe SB - Open #1564	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - UPGRADE THE WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM TO PREVENT SIGNAL LOSS DURING						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-064 R1 Airframe SB - Open #44	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - UPGRADE THE WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM TO PREVENT SIGNAL LOSS DURING FLIGHT Notes (AVG MAN HRS: 2)						
SB 604-34-064 R2 Airframe SB - Open #1774	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - UPGRADE THE WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM TO PREVENT SIGNAL LOSS DURING FLIGHT Notes (AVG MAN HRS: 2)						
SB 604-34-064 R3 Airframe SB - Open #1471	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - UPGRADE THE WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE GPS SYSTEM TO PREVENT SIGNAL LOSS DURING FLIGHT Notes (AVG MAN HRS: 2)						
SB 604-34-065 Airframe SB - Open #46	MODIFICATION - PITOT-STATIC AND TEMPERATURE SENSING SYSTEM - REPLACEMENT OF PITOT-STATIC VISUAL DRAIN BOTTLES TO LARGER CAPACITY BOTTLES						
SB 604-34-065 R1 Airframe SB - Open #781	MODIFICATION - PITOT-STATIC AND TEMPERATURE SENSING SYSTEM - REPLACEMENT OF PITOT-STATIC VISUAL DRAIN BOTTLES TO LARGER CAPACITY BOTTLES						
SB 604-34-065 R2 Airframe SB - Complied With #1781	MODIFICATION - PITOT-STATIC AND TEMPERATURE SENSING SYSTEM - REPLACEMENT OF PITOT-STATIC VISUAL DRAIN BOTTLES TO LARGER CAPACITY BOTTLES Notes (AVG MAN HRS: 6.5) (UPDATE NOTE: CW SB 604-34-065 R2).CW SB 604-34-065 R2					27-NOV-2015	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-066 Airframe SB - Open #2121	MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - RELOCATION OF THE LDS Notes (AVG MAN HRS: 175) (NOTE: FOR AIRCRAFT, SERIAL NO. 5559, 5584 AND 5662 AND ALL OTHER AIRCRAFT THAT HAVE BEEN REWORKED AT MIDCOAST AVIATION/JET AVIATION TO RELOCATE THE ANTENNA/RECEIVER BETWEEN FS 736.00 AND FS 755.00 AFTER OR DURING INCORPORATION OF SB 604-34-008, ALREADY MET THE INTENT OF THIS SERVICE BULLETIN. THEREFORE, THIS SERVICE BULLETIN IS NOT APPLICABLE TO THESE AIRCRAFT.)						
SB 604-34-066 R1 Airframe SB - Open #48	MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - RELOCATION OF THE LDS Notes (AVG MAN HRS: 175)						
SB 604-34-066 R2 Airframe SB - Open #1996	MODIFICATION - LIGHTNING DETECTION SYSTEM (LDS) - RELOCATION OF THE LDS Notes (AVG MAN HRS: 175)						
SB 604-34-067 Airframe SB - Open #2823	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER (EASA APPROVAL) Notes (AVG MAN HRS: 32)						
SB 604-34-067 Part C Airframe SB - Open #1191	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER (EASA APPROVAL) - DO THE OPTIONAL "METRIC" ALTIMETER INDICATION MODIFICATION FOR THE AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 13) (NOTE: NOTE: PART C IS OPTIONAL FOR AIRCRAFT POST SB 604-34-010.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-067 Part A Airframe SB - Open #853	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER (EASA APPROVAL) - DO THE PARTIAL INSTALLATION OF SB 604-34-013 Notes (AVG MAN HRS: 17)						
SB 604-34-067 Part B Airframe SB - Open #1481	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER (EASA APPROVAL) - REPLACE THE OLD STANDBY ALTIMETER WITH THE NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 12)						
SB 604-34-067 R1 Airframe SB - Open #1869	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 32) (NOTE: NOTE: THE TECHNICAL CONTENT OF THIS SERVICE BULLETIN IS ONLY APPROVED BY TCCA & EASA. TO IMPLEMENT THIS MODIFICATION ON FAA REGISTERED AIRCRAFT, REFER TO THE EQUIVALENT SB 604-34-056.)						
SB 604-34-067 R1 Part C Airframe SB - Open #31	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER (EASA APPROVAL) - DO THE OPTIONAL "METRIC" ALTIMETER INDICATION MODIFICATION FOR THE AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 13) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE OPERATING MANUAL ISSUE THAT FOLLOWS OR LATER MUST BE USED: - PSP604-6, MODEL CL-600-2B16, VOLUME 2, REVISION 73, DATED MAY 14/2008.)						
SB 604-34-067 R1 Part A Airframe SB - Open #3331	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER - DO THE PARTIAL INSTALLATION OF SB 604-34-013 Notes (AVG MAN HRS: 17)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-067 R1 Part B Airframe SB - Open #3517	MODIFICATION - STANDBY ALTITUDE INDICATOR (SAI) - INTRODUCTION OF NEW AD20 STANDBY ALTIMETER - REPLACE THE OLD STANDBY ALTIMETER WITH THE NEW AD20 STANDBY ALTIMETER Notes (AVG MAN HRS: 12) (NOTE: NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE OPERATING MANUAL ISSUE THAT FOLLOWS OR LATER MUST BE USED: - PSP604-6, MODEL CL-600-2B16, VOLUME 2, REVISION 73, DATED MAY 14/2008.)						
SB 604-34-068 Airframe SB - Open #2725	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER WITH AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT V2 CAPABILITY Notes (AVG MAN HRS: 70) (NOTE: CONTROLLED EFFECTIVITY. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63040223, REV NC.)						
SB 604-34-068 R1 Airframe SB - Open #2374	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER WITH AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT V2 CAPABILITY Notes (AVG MAN HRS: 70) (NOTE: CONTROLLED EFFECTIVITY. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63040223, REV NC.)						
SB 604-34-068 R2 Airframe SB - Open #3511	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER WITH AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT V2 CAPABILITY Notes (AVG MAN HRS: 70) (NOTE: CONTROLLED EFFECTIVITY. NOTE: WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - AIRPLANE FLIGHT MANUAL SUPPLEMENT, BAS63040223, REV NC.)						
SB 604-34-068 R3 Airframe SB - Open #640	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER WITH AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT V2 CAPABILITY Notes (AVG MAN HRS: 70)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-068 R3 Part B Airframe SB - Open #1014	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER WITH AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT V2 CAPABILITY - MODIFICATION FOR AIRCRAFT POST-SB 604-34-058 Notes (AVG MAN HRS: 30)						
SB 604-34-068 R3 Part A Airframe SB - Open #1106	MODIFICATION - AIR TRAFFIC CONTROL (ATC) TRANSPONDER SYSTEM - INCORPORATION OF ATC TRANSPONDER WITH AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT V2 CAPABILITY - MODIFICATION FOR AIRCRAFT PRE-SB 604-34-058 Notes (AVG MAN HRS: 40)						
SB 604-34-069 Airframe SB - N/A #663	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101 Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: SERVICE BULLETIN 604-34-069, INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, NOT APPLICABLE BY P/N 822-0931-003 GPS RECEIVER INSTALLED. NO FURTHER ACTION NECESSARY.).SERVICE BULLETIN 604-34-069, INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, NOT APPLICABLE BY P/N 822-0931-003 GPS RECEIVER INSTALLED. NO FURTHER ACTION NECESSARY.	24-MAY-2023 H: 8059.50 L: 3636					
SB 604-34-069 PART A Airframe SB - N/A #3334	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101 - INSPECTION Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: SERVICE BULLETIN 604-34-069 PART A, INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, NOT APPLICABLE BY P/N 822-0931-003 GPS RECEIVER INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: EFFECTIVITY: AIRCRAFT EQUIPPED WITH COLLINS AEROSPACE GLOBAL POSITIONING SYSTEM (GPS) UNIT MODEL GPS-4000S, PART NO. 822-2189-100. COMPLIANCE: BOMBARDIER AVIATION RECOMMENDS THAT THIS SERVICE BULLETIN BE DONE ON OR BEFORE MAY 31, 2023.).SERVICE BULLETIN 604-34-069 PART A, INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, NOT APPLICABLE BY P/N 822-0931-003 GPS RECEIVER INSTALLED. NO FURTHER ACTION NECESSARY.	24-MAY-2023 H: 8059.50 L: 3636					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-069 PART B Airframe SB - N/A #555	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101 - MODIFICATION Notes (AVG MAN HRS: 2) (UPDATE NOTE: SERVICE BULLETIN 604-34-069 PART B, INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, NOT APPLICABLE BY P/N 822-0931-003 GPS RECEIVER INSTALLED. NO FURTHER ACTION NECESSARY.) (NOTE: EFFECTIVITY: AIRCRAFT EQUIPPED WITH COLLINS AEROSPACE GLOBAL POSITIONING SYSTEM (GPS) UNIT MODEL GPS-4000S, PART NO. 822-2189-100. COMPLIANCE: BOMBARDIER AVIATION RECOMMENDS THAT THIS SERVICE BULLETIN BE DONE ON OR BEFORE MAY 31, 2023.).SERVICE BULLETIN 604-34-069 PART B, INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, NOT APPLICABLE BY P/N 822-0931-003 GPS RECEIVER INSTALLED. NO FURTHER ACTION NECESSARY.	24-MAY-2023 H: 8059.50 L: 3636					
SB 604-34-071 Airframe SB - Open #3715	MODIFICATION - RADIO ALTIMETER SYSTEM - INTRODUCTION OF BANDPASS FILTER TO THE RADIO ALTIMETER TO PREVENT INTERFERENCE FROM 5G MOBILE NETWORKS Notes (AVG MAN HRS: 8)						
SB 604-34-071 R1 Airframe SB - Open #2842	MODIFICATION - RADIO ALTIMETER SYSTEM - INTRODUCTION OF BANDPASS FILTER TO THE RADIO ALTIMETER TO PREVENT INTERFERENCE FROM 5G MOBILE NETWORKS Notes (AVG MAN HRS: 4) (NOTE: EFFECTIVITY: CL-600-2B16 AIRCRAFT, SERIAL NO. 5301 TO 5665.)						
SB 604-34-072 Airframe SB - Open #1371	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-102						
SB 604-34-072 Part A Airframe SB - Open #3638	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-102 - INSPECTION Notes (AVG MAN HRS: 0.5) (NOTE: EFFECTIVITY: KINDLY SEE PAR. 1.A. TO SEE THE AFFECTED SERIAL NUMBERS. COMPLIANCE: BOMBARDIER RECOMMENDS THAT THIS SERVICE BULLETIN BE DONE ON OR BEFORE MAR 31, 2028.)					31-MAR-2028	M: 21 D: 30



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-34-072 Part B Airframe SB - Open #2870	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-102 - MODIFICATION Notes (AVG MAN HRS: 2) (NOTE: EFFECTIVITY: KINDLY SEE PAR. 1.A. TO SEE THE AFFECTED SERIAL NUMBERS. COMPLIANCE: BOMBARDIER RECOMMENDS THAT THIS SERVICE BULLETIN BE DONE ON OR BEFORE MAR 31, 2028.)					31-MAR-2028	M: 21 D: 30
SB 604-35-001 Airframe SB - Open #238	MODIFICATION - CREW AND PASSENGER OXYGEN SYSTEM - RELOCATION OF THE OVERBOARD DISCHARGE INDICATORS Notes (AVG MAN HRS: 26)						
SB 604-35-002 Airframe SB - N/A #2405	MODIFICATION - CREW OXYGEN SUPPLY SYSTEM - REPLACE OXYGEN CYLINDER AND REGULATOR ASSEMBLY Notes (NOTE: RECOMMENDED AT THE NEXT HYDROSTATIC TEST OF THE OXYGEN CYLINDERS, PART NO. 895-18015 (CL-604 TIME LIMITS/MAINTENANCE CHECKS, CHAPTER 5-21-10, TASK 35-00 -00-201).).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-35-003 Airframe SB - N/A #475	MODIFICATION - PASSENGER OXYGEN SYSTEM - REPLACEMENT OF PASSENGER OXYGEN CONTROL PANEL FOR COMPATIBILITY WITH HIGH AIRFIELD OPERATIONS OF UP TO 14,000 FT Notes .TO S/N OF AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-35-003 R1 Airframe SB - N/A #3423	MODIFICATION - PASSENGER OXYGEN SYSTEM - REPLACEMENT OF PASSENGER OXYGEN CONTROL PANEL FOR COMPATIBILITY WITH HIGH AIRFIELD OPERATIONS OF UP TO 14,000 FT Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-35-003 R2 Airframe SB - N/A #3229	MODIFICATION - PASSENGER OXYGEN SYSTEM - REPLACEMENT OF PASSENGER OXYGEN CONTROL PANEL FOR COMPATIBILITY WITH HIGH AIRFIELD OPERATIONS OF UP TO 14,000 FT Notes (AVG MAN HRS: 2).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-35-004 Airframe SB - N/A #1003	SPECIAL CHECK/MODIFICATION - CREW OXYGEN SYSTEM - VERIFICATION AND REPLACEMENT OF CREW OXYGEN MASK INFLATABLE HARNESS	25-JUL-2011 H: 4300.70 L: 1851					
	Notes (AVG MAN HRS: 1) (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO THE AIRCRAFT EQUIPPED WITH THE CREW OXYGEN MASK PART NO. MC10-13-03 AND MF10-03-03. THERE MAY BE A POSSIBILITY OF THREE UNITS AFFECTED ON THE AIRCRAFT; PILOT, CO-PILOT AND JUMP SEAT POSITIONS. THIS SERVICE BULLETIN IS ALSO APPLICABLE FOR THE MASKS PART NO MC10-13-03 AND MF10-03-03 AND/OR THE HARNESS MXH15-22 AND MXH30 IN THE OPERATOR'S STOCK ROOM. ALL REMOVAL AND INSTALLATION OPERATIONS MUST BE PERFORMED IN A PART 145 WORKSHOP AND BY CERTIFIED PERSONNEL.)BY EFFECTIVITY						
SB 604-35-005 Airframe SB - Open #1762	SPECIAL CHECK/MODIFICATION - PORTABLE OXYGEN BOTTLE - UPPER BRACKET ASSEMBLY						
	Notes (AVG MAN HRS: 1)						
SB 604-35-006 Airframe SB - Open #1063	MODIFICATION - PORTABLE OXYGEN BOTTLE - BRACKET REPLACEMENT						
	Notes (AVG MAN HRS: 2.5)						
SB 604-35-006 R1 Airframe SB - Complied With #588	MODIFICATION - PORTABLE OXYGEN BOTTLE - BRACKET REPLACEMENT	05-JUL-2024 H: 8455.80 L: 3862					
	Notes (AVG MAN HRS: 2.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 60 MONTHS FROM THIS SB RELEASE DATE (BASIC ISSUE).).REPLACED BRACKET						
SB 604-35-007 Airframe SB - Open #1096	SPECIAL CHECK/MODIFICATION - PASSENGER OXYGEN SUPPLY SYSTEM - VALIDATION AND MODIFICATION FOR INCORRECT LANYARD LENGTH OF THE PASSENGER OXYGEN MASK						
	Notes (AVG MAN HRS: 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-35-007 Part B Airframe SB - Open #2024	SPECIAL CHECK/MODIFICATION - PASSENGER OXYGEN SUPPLY SYSTEM - VALIDATION AND MODIFICATION FOR INCORRECT LANYARD LENGTH OF THE PASSENGER OXYGEN MASK - MODIFICATION Notes (AVG MAN HRS: 1)					13-DEC-2026	M: 6 D: 12
SB 604-35-007 R1 Airframe SB - Open #669	SPECIAL CHECK/MODIFICATION - PASSENGER OXYGEN SUPPLY SYSTEM - VALIDATION AND MODIFICATION FOR INCORRECT LANYARD LENGTH OF THE PASSENGER OXYGEN MASK Notes (AVG MAN HRS: 2)						
SB 604-35-007 R1 Part B Airframe SB - Open #930	SPECIAL CHECK/MODIFICATION - PASSENGER OXYGEN SUPPLY SYSTEM - VALIDATION AND MODIFICATION FOR INCORRECT LANYARD LENGTH OF THE PASSENGER OXYGEN MASK - MODIFICATION - REPLACEMENT OF OXYGEN MASK Notes (AVG MAN HRS: 1) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 5 YEARS FROM THIS SB RELEASE (BASIC ISSUE))		M: 60			13-DEC-2026	M: 6 D: 12
SB 604-35-008 Airframe SB - Open #2674	SPECIAL CHECK/MODIFICATION - PORTABLE OXYGEN EQUIPMENT - INSTALLATION OF PORTABLE PROTECTIVE BREATHING EQUIPMENT AND REPLACEMENT OF PLACARDS IN FORWARD WARDROBE Notes (AVG MAN HRS: 2) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 3 YEARS FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)						
SB 604-35-008 R1 Airframe SB - Open #1395	SPECIAL CHECK/MODIFICATION - PORTABLE OXYGEN EQUIPMENT - INSTALLATION OF PORTABLE PROTECTIVE BREATHING EQUIPMENT AND REPLACEMENT OF PLACARDS IN FORWARD WARDROBE Notes (AVG MAN HRS: 2) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 3 YEARS FROM THIS SB RELEASE DATE (BASIC ISSUE).)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-35-008 R2 Airframe SB - N/A #1538	SPECIAL CHECK/MODIFICATION - PORTABLE OXYGEN EQUIPMENT - INSTALLATION OF PORTABLE PROTECTIVE BREATHING EQUIPMENT AND REPLACEMENT OF PLACARDS IN FORWARD WARDROBE Notes (AVG MAN HRS: 2) (UPDATE NOTE: C/W SERVICE BULLETIN 604-35-008 REV2. SPECIAL CHECK/MODIFICATION - PORTABLE OXYGEN EQUIPMENT - INSTALLATION OF PORTABLE PROTECTIVE BREATHING EQUIPMENT AND REPLACEMENT OF PLACARDS IN FORWARD WARDROBE, PER S/B WITH THE PORTABLE O2 SYSTEM INSTALLED UPON DELIVERY, NO FURTHER ACTION REQUIRED. CLOSE OUT PER PARAGRAPH 2(D).) (NOTE: COMPLIANCE: RECOMMENDED WITHIN 3 YEARS FROM THIS SB RELEASE DATE (BASIC ISSUE).)C/W SERVICE BULLETIN 604-35-008 REV2. SPECIAL CHECK/MODIFICATION - PORTABLE OXYGEN EQUIPMENT - INSTALLATION OF PORTABLE PROTECTIVE BREATHING EQUIPMENT AND REPLACEMENT OF PLACARDS IN FORWARD WARDROBE. PER S/B WITH THE PORTABLE O2 SYSTEM INSTALLED UPON DELIVERY,	31-JAN-2024 H: 8254.00 L: 3749					
SB 604-36-001 Airframe SB - Open #1414	MODIFICATION - APU BLEED AIR DUCT - CHECK VALVE RELIABILITY IMPROVEMENT Notes (AVG MAN HRS: 3)						
SB 604-36-002 PART B Airframe SB - Open #136	REWORK - 10TH STAGE BLEED-AIR SYSTEM - REPLACEMENT OF LEFT-ENGINE BLEED-AIR DUCT MANUFACTURED WITH THE WRONG MATERIAL Notes (AVG MAN HRS: 4)						
SB 604-36-002 PART A Airframe SB - Open #1287	SPECIAL CHECK - 10TH STAGE BLEED-AIR SYSTEM - REPLACEMENT OF LEFT-ENGINE BLEED-AIR DUCT MANUFACTURED WITH THE WRONG MATERIAL Notes (AVG MAN HRS: 1)						
SB 604-36-002 Airframe SB - N/A #385	SPECIAL CHECK/REWORK - 10TH STAGE BLEED-AIR SYSTEM - REPLACEMENT OF LEFT-ENGINE BLEED-AIR DUCT MANUFACTURED WITH THE WRONG MATERIAL Notes .TO S/N OF AIRCRAFT	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-36-003 Airframe SB - Open #436	CANCELLED PRIOR TO ISSUE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-36-004 Airframe SB - Superseded #769	MODIFICATION - BLEED-AIR LEAK DETECTION SYSTEM - 10TH STAGE BLEED-AIR PRESSURE TRANSDUCERS RELOCATION Notes .SEE REVISION 1.						
SB 604-36-004 R1 Airframe SB - Superseded #1882	MODIFICATION - BLEED-AIR LEAK DETECTION SYSTEM - 10TH STAGE BLEED-AIR PRESSURE TRANSDUCERS RELOCATION Notes .SEE REVISION 2.						
SB 604-36-004 R2 Airframe SB - Superseded #1813	MODIFICATION - BLEED-AIR LEAK DETECTION SYSTEM - 10TH STAGE BLEED-AIR PRESSURE TRANSDUCERS RELOCATION Notes (AVG MAN HRS: 25) (NOTE: AN SRPSA HAS TO BE RAISED TO AUTHORIZE THE USE OF AN ALTERNATIVE TUBE UNION FOR ALL AIRCRAFT WHERE THE WATER SYSTEM INSTALLATION WAS PERFORMED IN ACCORDANCE WITH A MIDCOAST AVIATION STC.).BY REVISION 03						
SB 604-36-004 R3 Airframe SB - Open #291	MODIFICATION - BLEED-AIR LEAK DETECTION SYSTEM - 10TH STAGE BLEED-AIR PRESSURE TRANSDUCERS RELOCATION Notes (AVG MAN HRS: 25) (NOTE: NOTE: AN SRPSA HAS TO BE RAISED TO AUTHORIZE THE USE OF AN ALTERNATIVE TUBE UNION FOR ALL AIRCRAFT WHERE THE WATER SYSTEM INSTALLATION WAS PERFORMED IN ACCORDANCE WITH A MIDCOAST AVIATION STC.)DECLINED						
SB 604-36-005 Airframe SB - Open #1221	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS						
SB 604-36-005 PART A Airframe SB - Open #2673	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST AT THE LEFT WING ROOT, OVER THE LEFT WING CENTER FUSELAGE AND IN THE LEFT WHEEL WELL AREA Notes (AVG MAN HRS: 10)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-36-005 PART B Airframe SB - Open #2623	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST AT THE RIGHT WING ROOT, OVER THE RIGHT WING CENTER FUSELAGE AND IN THE RIGHT WHEEL WELL AREA Notes (AVG MAN HRS: 10)						
SB 604-36-005 PART C Airframe SB - Open #3620	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST BELOW THE LEFT SIDE LAVATORY AND LEFT SIDE BAGGAGE COMPARTMENT Notes (AVG MAN HRS: 1.5)						
SB 604-36-005 PART D Airframe SB - Open #3635	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST BELOW THE RIGHT SIDE LAVATORY AND RIGHT SIDE BAGGAGE COMPARTMENT Notes (AVG MAN HRS: 1.5)						
SB 604-36-005 PART F Airframe SB - Open #2850	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST IN THE LEFT PYLON AREA Notes (AVG MAN HRS: 3.5)						
SB 604-36-005 PART E Airframe SB - Open #2953	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST IN THE REAR EQUIPMENT BAY Notes (AVG MAN HRS: 7)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-36-005 PART G Airframe SB - Open #518	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST IN THE RIGHT PYLON AREA Notes (AVG MAN HRS: 3.5)						
SB 604-36-005 R1 Airframe SB - Open #1469	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS						
SB 604-36-005 R1 Part A Airframe SB - Open #3359	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST AT THE LEFT WING ROOT, OVER THE LEFT WING CENTER FUSELAGE AND IN THE LEFT WHEEL WELL AREA Notes (AVG MAN HRS: 10)						
SB 604-36-005 R1 Part B Airframe SB - Open #1360	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST AT THE RIGHT WING ROOT, OVER THE RIGHT WING CENTER FUSELAGE AND IN THE RIGHT WHEEL WELL AREA Notes (AVG MAN HRS: 10)						
SB 604-36-005 R1 Part C Airframe SB - Open #172	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST BELOW THE LEFT SIDE LAVATORY AND LEFT SIDE BAGGAGE COMPARTMENT Notes (AVG MAN HRS: 1.5)						
SB 604-36-005 R1 Part D Airframe SB - Open #873	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST BELOW THE RIGHT SIDE LAVATORY AND RIGHT SIDE BAGGAGE COMPARTMENT Notes (AVG MAN HRS: 1.5)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-36-005 R1 Part F Airframe SB - Open #2557	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST IN THE LEFT PYLON AREA Notes (AVG MAN HRS: 3.5)						
SB 604-36-005 R1 Part E Airframe SB - Open #1761	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST IN THE REAR EQUIPMENT BAY Notes (AVG MAN HRS: 7)						
SB 604-36-005 R1 Part G Airframe SB - Open #2252	SPECIAL CHECK/REWORK - BLEED-AIR LEAK DETECTION SYSTEM - SPECIAL CHECK OF THE BLEED-AIR LEAK DETECTION ELEMENTS - LDL SENSING ELEMENTS TEST IN THE RIGHT PYLON AREA Notes (AVG MAN HRS: 3.5)						
SB 604-38-001 Airframe SB - N/A #3219	SPECIAL CHECK/MODIFICATION - POTABLE WATER SYSTEM - CHECK FOR INSTALLATION OF A 10 U.S. GAL (37.8541 L) FIBERGLASS WATER TANK AND REPLACEMENT OF THE 10 U.S. GAL (37.8541 L) FIBERGLASS WATER TANK WITH A 10 U.S. GAL (37.8541 L) STAINLESS STEEL WATER TANK (SERVICE BULLETIN ON HOLD) Notes (NOTE: THIS INFORMATION SHEET IS ISSUED TO INFORM THE OPERATORS THAT THIS SERVICE BULLETIN IS ON HOLD UNTIL FURTHER NOTICE DUE TO STOCK SHORTAGES OF THE STAINLESS STEEL WATER TANK.).TO AIRCRAFT S/N				13-FEB-2017 H: 5969.40 L: 2571		
SB 604-38-002 Airframe SB - N/A #2289	MODIFICATION - POTABLE WATER SYSTEM - WATER TANK PLUMBING LINES MODIFICATION Notes (AVG MAN HRS: 8).TO AIRCRAFT S/N				13-FEB-2017 H: 5969.40 L: 2571		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-44-001 Airframe SB - Open #2543	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF THE HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM Notes (AVG MAN HRS: 900) (NOTE: CONTROLLED EFFECTIVITY. PREREQUISITE: THE SIDDHIS FINTOP RADOME, PART NO. M38-1002-3, INSTALLED VIA THE SUPPLEMENTAL TYPE CERTIFICATE (STC), (FAA: ST00929NY, TCCA: SA98-92 AND EASA: 10066792) IS A PREREQUISITE TO THIS MODIFICATION AND MUST BE DONE BEFORE OR AT THE SAME TIME AS THIS SERVICE BULLETIN.)						
SB 604-44-001 R1 Airframe SB - Open #2941	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF THE HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM Notes (AVG MAN HRS: 900)						
SB 604-44-001 R2 Airframe SB - Open #984	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF THE HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM Notes (AVG MAN HRS: 900)						
SB 604-46-004 Airframe SB - Open #1570	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM						
SB 604-46-004 Part C Airframe SB - Open #535	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM - MODIFICATION - AHMS COMPLETIONS						
SB 604-46-004 Part A Airframe SB - Open #2689	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM - MODIFICATION - AHMS STRUCTURAL AND WIRE PROVISIONS						
SB 604-46-004 Part B Airframe SB - Open #1789	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM - MODIFICATION - CABIN ROUTER OPTION PROVISIONS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-46-004 R1 Airframe SB - Open #24	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM						
SB 604-46-004 R1 Part C Airframe SB - Open #3487	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM - MODIFICATION - AHMS COMPLETIONS						
SB 604-46-004 R1 Part A Airframe SB - Open #2360	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM - MODIFICATION - AHMS STRUCTURAL AND WIRE PROVISIONS						
SB 604-46-004 R1 Part B Airframe SB - Open #3474	MODIFICATION - AIRCRAFT HEALTH MANAGEMENT INFORMATION SYSTEM - INSTALLATION OF THE LEARJET INC. STC AIRCRAFT HEALTH MANAGEMENT SYSTEM - MODIFICATION - CABIN ROUTER OPTION PROVISIONS						
SB 604-49-001 Airframe SB - Open #2531	MODIFICATION - APU GEARBOX VENT LINE ROUTING IMPROVEMENT						
SB 604-49-001 R1 Airframe SB - Open #3193	MODIFICATION - APU GEARBOX VENT LINE ROUTING IMPROVEMENT Notes (AVG MAN HRS: 12)						
SB 604-49-002 Airframe SB - Open #439	MODIFICATION - APU EXHAUST - REPLACE DRAIN TUBE, PART NO. 601-97092-29 WITH HEAT RESISTANT TUBE, PART NO. 601-97092-65 Notes (AVG MAN HRS: 1)						
SB 604-49-003 Airframe SB - Open #718	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-49-003 PART A Airframe SB - Complied With #1300	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE	17-JUN-2005 H: 2522.30 L: 983					
SB 604-49-003 PART B Airframe SB - Complied With #3539	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE	17-JUN-2005 H: 2522.30 L: 983					
SB 604-49-003 R1 PART A Airframe SB - Open #1802	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						
SB 604-49-003 R1 Airframe SB - Open #1955	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						
SB 604-49-003 R1 PART B Airframe SB - Open #1018	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						
SB 604-49-003 R2 Airframe SB - Open #189	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						
SB 604-49-003 R2 PART B Airframe SB - Open #218	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						
SB 604-49-003 R2 PART A Airframe SB - Open #2917	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-49-003 R3 PART A Airframe SB - Complied With #482	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE Notes (AVG MAN HRS: 14) (NOTE: ALTHOUGH THE APU DOES NOT HAVE TO BE REMOVED TO PERFORM THIS SERVICE BULLETIN, THE IMPROVED ACCESS GAINED INSIDE THE ENCLOSURE WITH THE APU REMOVED WILL SIMPLIFY THE MODIFICATION IN PART A AND REDUCE THE NUMBER OF MAN-HOURS REQUIRED. CONSIDERATION SHOULD BE GIVEN TO PERFORMING THIS SERVICE BULLETIN IF THE APU IS REMOVED FOR ANOTHER CAUSE).PREVIOUSLY						
SB 604-49-003 R3 Airframe SB - Complied With #810	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE Notes .PREVIOUSLY						
SB 604-49-003 R3 PART B Airframe SB - Complied With #2154	MODIFICATION - APU ENCLOSURE - IMPROVE LEAK RESISTANCE AND DRAINAGE Notes (AVG MAN HRS: 10).PREVIOUSLY						
SB 604-49-004 PART C Airframe SB - Open #2144	MODIFICATION - AUXILIARY POWER UNIT (APU) - PREVENTION OF FUSELAGE SKIN HEAT DAMAGE UNDER AND AFT OF THE APU EXHAUST SHIELD Notes (AVG MAN HRS: 2)						
SB 604-49-004 PART B Airframe SB - Open #33	MODIFICATION - AUXILIARY POWER UNIT (APU) - PREVENTION OF FUSELAGE SKIN HEAT DAMAGE UNDER AND AFT OF THE APU EXHAUST SHIELD Notes (AVG MAN HRS: 8)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-49-004 Airframe SB - Complied With #121	SPECIAL CHECK/MODIFICATION - AUXILIARY POWER UNIT (APU) - PREVENTION OF FUSELAGE SKIN HEAT DAMAGE UNDER AND AFT OF THE APU EXHAUST SHIELD Notes (NOTE: THE FOLLOWING AIRCRAFT HAVE ALREADY MET THE INTENT OF THIS SERVICE BULLETIN AS THESE AIRCRAFT HAVE BEEN PREVIOUSLY MODIFIED IN ACCORDANCE WITH DRAWING NO. 601-97000, AND THE RESPECTIVE RNIEO. RNIEO NO. 618 AIRCRAFT SERIAL NO. 5354 RNIEO NO. 619, 623 AIRCRAFT SERIAL NO. 5409)	25-MAR-2001 H: 807.00 L: 307					
SB 604-49-004 PART A Airframe SB - Open #1457	SPECIAL CHECK/MODIFICATION - AUXILIARY POWER UNIT (APU) - PREVENTION OF FUSELAGE SKIN HEAT DAMAGE UNDER AND AFT OF THE APU EXHAUST SHIELD Notes (AVG MAN HRS: 11.5)						
SB 604-49-005 Airframe SB - Open #1073	CANCELLED PRIOR TO ISSUE						
SB 604-49-006 Airframe SB - Open #1313	MODIFICATION - GENERAL - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU)						
SB 604-49-006 R1 Airframe SB - Open #2119	MODIFICATION - GENERAL - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 218)						
SB 604-49-006 R1 Airframe SB - Open #3184	MODIFICATION - GENERAL - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU) - RETROACTIVE ACTION NO.1 Notes (RETRO 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-49-006 R1 Airframe SB - Open #2345	MODIFICATION - GENERAL - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU) - RETROACTIVE ACTION NO.2 Notes (RETRO 2)						
SB 604-49-006 R2 Airframe SB - Open #2737	MODIFICATION - GENERAL - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 216) (NOTE: NOTE: SEE SB FOR RETROACTIVE ACTION NO.1 AND RETROACTIVE ACTION NO. 2. NO RETROACTIVE ACTION IS REQUIRED FOR AIRCRAFT ON WHICH THE REVISION 01 OF THIS SERVICE BULLETIN WAS DONE. WHEN THIS SERVICE BULLETIN IS DONE, THE MANUAL ISSUES THAT FOLLOW OR LATER MUST BE USED: - AIRPLANE FLIGHT MANUAL, PSP 604 1, REV. 57. - OPERATING MANUAL (OM), PSP 604 6, REV. 57, VOLUME 1 AND 2.)						
SB 604-49-007 Airframe SB - Open #1478	MODIFICATION - APU BLEED AIR - INSTALLATION OF THE RESTRICTOR IN THE APU BLEED AIR DUCTING Notes (AVG MAN HRS: 2) (NOTE: THIS SERVICE BULLETIN AFFECTS ONLY THE ABOVE AIRCRAFT WITH THE APU, MODEL NO. 36-100 E, AND APU CHECK VALVE, PART NO. 3202832-1-1 OR 3202896-1, INSTALLED)						
SB 604-49-008 PART F Airframe SB - Open #1990	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 2)						
SB 604-49-008 PART A Airframe SB - Open #384	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 18)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-49-008 PART D Airframe SB - Open #417	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 14)						
SB 604-49-008 PART E Airframe SB - Open #2703	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 11)						
SB 604-49-008 PART B Airframe SB - Open #3197	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 8)						
SB 604-49-008 Airframe SB - Open #2996	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU)						
SB 604-49-008 PART G Airframe SB - Open #3015	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 11)						
SB 604-49-008 PART C Airframe SB - Open #3593	MODIFICATION - GENERAL - INSTALLATION OF PROVISIONS FOR THE 36-150 (CL) AUXILIARY POWER UNIT (APU) Notes (AVG MAN HRS: 3)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-49-009 Airframe SB - Open #1508	CANCELLED PRIOR TO ISSUE						
SB 604-49-010 Airframe SB - Open #1799	MODIFICATION - EXHAUST - INTRODUCTION OF THE 36-150 (CL) AUXILIARY POWER UNIT (APU) STAINLESS STEEL EXHAUST SHIELD Notes (AVG MAN HRS: 5).OPEN						
SB 604-49-011 Airframe SB - Open #3135	SPECIAL CHECK/MODIFICATION - AUXILIARY POWER UNIT (APU) ENGINE OIL SYSTEM - REPLACEMENT OF THE APU OIL FILTER ELEMENT						
SB 604-49-011 R1 Airframe SB - Complied With #3488	SPECIAL CHECK/MODIFICATION - AUXILIARY POWER UNIT (APU) ENGINE OIL SYSTEM - REPLACEMENT OF THE APU OIL FILTER ELEMENT Notes (AVG MAN HRS: 1) (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)			25-APR-2022 H: 7477.20 L: 3329			
SB 604-52-001 Airframe SB - Open #2705	THIS SERVICE BULLETIN IS SUPERCEDED BY SERVICE BULLETIN 604-53-009 MODIFICATION - DOOR, AFT EQUIPMENT COMPARTMENT - ADD LIQUID DEFLECTOR Notes (AVG MAN HRS: 5)						
SB 604-52-002 Airframe SB - Open #2037	MODIFICATION - PASSENGER DOOR LATCHING MECHANISM - INTRODUCE PERMANENTLY LUBRICATED BALL BEARING ASSEMBLIES TO IMPROVE MAINTAINABILITY Notes (AVG MAN HRS: 23)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-52-003 PART A Airframe SB - Open #1895	MODIFICATION - PASSENGER DOOR - TO ELIMINATE POTENTIAL JAMMING OF DOOR OUTER HANDLE DURING CLOSING Notes (AVG MAN HRS: 16)						
SB 604-52-003 PART B Airframe SB - Open #3526	MODIFICATION - PASSENGER DOOR - TO ELIMINATE POTENTIAL JAMMING OF DOOR OUTER HANDLE DURING CLOSING Notes (AVG MAN HRS: 18)						
SB 604-52-003 Airframe SB - Open #3407	MODIFICATION - PASSENGER DOOR - TO ELIMINATE POTENTIAL JAMMING OF DOOR OUTER HANDLE DURING CLOSING						
SB 604-52-004 Airframe SB - N/A #504	SPECIAL CHECK/REWORK - ACCESS DOORS - PREVENT GALVANIC CORROSION ON THE FORWARD EQUIPMENT COMPARTMENT DOORS Notes (AVG MAN HRS: 6).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-52-005 PART B Airframe SB - Complied With #77	REWORK - PASSENGER DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORK Notes (AVG MAN HRS: 1)	25-JAN-2007 H: 2895.70 L: 1155					
SB 604-52-005 PART A Airframe SB - Complied With #2023	SPECIAL CHECK - PASSENGER DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORK	25-JAN-2007 H: 2895.70 L: 1155					
SB 604-52-005 Airframe SB - Open #3375	SPECIAL CHECK/REWORK - PASSENGER DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORK						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-52-005 R1 PART A Airframe SB - Open #68	SPECIAL CHECK - PASSENGER DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORK Notes (AVG MAN HRS: 1) (NOTE: COMPLIANCE: RECOMMENDED IN LESS THAN 400 FLIGHT HOURS OR 12 MONTHS, WHICHEVER COMES FIRST FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)						
SB 604-52-005 R1 Airframe SB - Open #3098	SPECIAL CHECK/REWORK - PASSENGER DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORK Notes (AVG MAN HRS: 1)						
SB 604-52-005 R1 PART B Airframe SB - Open #2147	TYPE DESCRIPREWORK - PASSENGER DOOR - PASSENGER DOOR FOOT INSPECTION AND REWORKTION HERE... Notes (AVG MAN HRS: 1) (NOTE: COMPLIANCE: RECOMMENDED IN LESS THAN 400 FLIGHT HOURS OR 12 MONTHS, WHICHEVER COMES FIRST FROM THIS SERVICE BULLETIN RELEASE DATE (BASIC ISSUE).)						
SB 604-52-006 Airframe SB - Superseded #473	MODIFICATION - EMERGENCY EXIT - INSTALLATION OF NEW SILICONE RUBBER SEAL TO PREVENT WATER INGRESS Notes .SEE REVISION 1.						
SB 604-52-006 R1 Airframe SB - Superseded #336	MODIFICATION - EMERGENCY EXIT - INSTALLATION OF NEW SILICONE RUBBER SEAL TO PREVENT WATER INGRESS Notes (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT THAT ARE STILL EXPERIENCING WATER INGRESS FOLLOWING THE INCORPORATION OF THE BASIC ISSUE OR REVISION 01 OF THIS SERVICE BULLETIN: (1) PROCEED TO PARAGRAPH 2.E., PART C. TO DO THE ADDITION OF THE NEW BRACKETS AND SPRING FOR THE DOOR PUSH-PLATE.).SEE REVISION 2.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-52-006 R2 PART C Airframe SB - Complied With #1013	MODIFICATION - ADDITION OF NEW BRACKETS AND SPRING FOR THE DOOR PUSH-PLATE Notes (AVG MAN HRS: 5)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-52-006 R2 PART B Airframe SB - Complied With #1130	MODIFICATION - ADDITION OF NEW SEAL AND SEALING PAD FOR THE DOOR PUSH-PLATE Notes (AVG MAN HRS: 8)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-52-006 R2 PART A Airframe SB - Complied With #2903	MODIFICATION - ADDITION OF SEALING AROUND FUSELAGE DOOR-CUTOUT Notes (AVG MAN HRS: 4)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-52-006 R2 Airframe SB - Complied With #264	MODIFICATION - EMERGENCY EXIT - INSTALLATION OF NEW SILICONE RUBBER SEAL TO PREVENT WATER INGRESS Notes (AVG MAN HRS: 17) (NOTE: RETROACTIVE ACTION: THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT THAT ARE STILL EXPERIENCING WATER INGRESS FOLLOWING THE INCORPORATION OF THE BASIC ISSUE OR REVISION 01 OF THIS SERVICE BULLETIN: (1) PROCEED TO PARAGRAPH 2.E., PART C. TO DO THE ADDITION OF THE NEW BRACKETS AND SPRING FOR THE DOOR PUSH-PLATE.)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-52-007 Airframe SB - Complied With #1299	SPECIAL CHECK/MODIFICATION - PASSENGER DOOR - EPOXY RAMP REMOVAL AND CORROSION PREVENTION Notes .SEE REVISION 1 FOR COMPLIANCE.						
SB 604-52-007 R1 Airframe SB - Complied With #2059	SPECIAL CHECK/MODIFICATION - PASSENGER DOOR - EPOXY RAMP REMOVAL AND CORROSION PREVENTION	12-APR-2013 H: 4782.30 L: 2063					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-52-007 R2 Airframe SB - Open #3722	SPECIAL CHECK/MODIFICATION - PASSENGER DOOR - EPOXY RAMP REMOVAL AND CORROSION PREVENTION Notes (AVG MAN HRS: 345)						
SB 604-52-008 Airframe SB - Open #947	MODIFICATION - PASSENGER DOOR - IMPROVE THE SUPPORT LEG MECHANISM Notes (AVG MAN HRS: 1)						
SB 604-52-010 Airframe SB - Open #2462	MODIFICATION - DOOR, PASSENGER - REPLACEMENT OF PASSENGER DOORS ALTERNATE STEP PANELS Notes (AVG MAN HRS: 4)						
SB 604-53-001 Airframe SB - Open #604	MODIFICATION - REAR FUSELAGE FRAME ASSEMBLY - INSTALL DOUBLERS FOR APU HOIST Notes (AVG MAN HRS: 3)						
SB 604-53-002 Airframe SB - Open #164	MODIFICATION - FS169.00 BULKHEAD - ADDITION OF RADOME VENT TUBE						
SB 604-53-002 R1 Airframe SB - Open #410	MODIFICATION - FS169.00 BULKHEAD - ADDITION OF RADOME VENT TUBE Notes (AVG MAN HRS: 3)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-003 Airframe SB - Open #79	MODIFICATION - TAIL FUEL TANK ASSEMBLY INCREASE STROBE LIGHT RELIABILITY Notes (AVG MAN HRS: 2)						
SB 604-53-005 Airframe SB - Open #2824	CANCELLED PRIOR TO ISSUE						
SB 604-53-006 Airframe SB - Complied With #3247	SPECIAL CHECK/MODIFICATION - MIDDLE FUSELAGE - FS409.00 PRESSURE BULKHEAD REINFORCEMENT					16-JUN-2005 H: 2522.30 L: 983	
SB 604-53-006 R1 Airframe SB - Complied With #1085	SPECIAL CHECK/MODIFICATION - MIDDLE FUSELAGE - FS409.00 PRESSURE BULKHEAD REINFORCEMENT Notes (AVG MAN HRS: 300) (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE IF A CRACK IS FOUND IN THE PRESSURE BULKHEAD AT FS409.00, AND/OR THE PRESSURE BULKHEAD WAS PREVIOUSLY REPAIRED AS PER CHALLENGER SERVICE ENGINEERING INSTRUCTIONS. THIS MODIFICATION CAN BE DONE AT THE NEXT INTERIOR REMOVAL.).PREVIOUSLY BY SB 604-53-006 BASIC ISSUE						
SB 604-53-007 Airframe SB - Complied With #1382	SPECIAL CHECK - INSPECTION OF THE UNDERFLOOR PRESSURE BULKHEAD AT FS409.00 Notes (AVG MAN HRS: 2).THIS SB IS NOW TERMINATED BY INCORPORATION OF S/B 604-53-007 - ALSO TERMINATED AD 97-24-02 REV 2					18-MAY-2005 H: 2522.30 L: 983	
SB 604-53-008 Airframe SB - Open #1074	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS						
SB 604-53-008 PART A Airframe SB - Open #2959	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-008 PART B Airframe SB - Open #2465	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS						
SB 604-53-008 PART C Airframe SB - Open #3466	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS						
SB 604-53-008 R1 Airframe SB - Open #2548	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS Notes DECLINED						
SB 604-53-008 R1 PART A Airframe SB - Open #2415	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS Notes DECLINED						
SB 604-53-008 R1 PART B Airframe SB - Open #3275	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS Notes DECLINED						
SB 604-53-008 R1 PART C Airframe SB - Open #1864	MODIFICATION - MIDDLE AND AFT FUSELAGE - STRUCTURAL PROVISION FOR THE ROYAL DANISH AIR FORCE REQUIREMENTS Notes DECLINED						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-009 Airframe SB - Complied With #6	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR	26-NOV-2002 H: 1492.40 L: 551					
SB 604-53-009 PART B Airframe SB - Open #3088	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						
SB 604-53-009 PART A Airframe SB - Open #2718	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						
SB 604-53-009 PART C Airframe SB - Open #2686	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						
SB 604-53-009 R1 PART A Airframe SB - Open #3115	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						
SB 604-53-009 R1 Airframe SB - Open #2999	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						
SB 604-53-009 R1 PART C Airframe SB - Open #260	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						
SB 604-53-009 R1 PART B Airframe SB - Open #1619	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-009 R2 Airframe SB - Open #1562	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR Notes (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OR REVISION 01 OF THIS SERVICE BULLETIN WAS DONE: RELOCATE THE BATTERY VENT INLET HOLE AS GIVEN IN PART C OF THIS SERVICE BULLETIN.)						
SB 604-53-009 R2 PART A Airframe SB - Complied With #1495	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR Notes (AVG MAN HRS: 11)	12-JUL-2004 H: 2246.30 L: 857					
SB 604-53-009 R2 PART C Airframe SB - Complied With #2474	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR Notes (AVG MAN HRS: 4)	12-JUL-2004 H: 2246.30 L: 857					
SB 604-53-009 R2 PART B Airframe SB - Open #3522	MODIFICATION - MAIN FRAME - ADDITION OF A LIQUID DEFLECTOR AROUND AFT EQUIPMENT COMPARTMENT DOOR Notes (AVG MAN HRS: 4)						
SB 604-53-010 Airframe SB - Complied With #3147	SPECIAL CHECK/MODIFICATION - MIDDLE FUSELAGE - NONDESTRUCTIVE INSPECTION (NDI) CHECK AND REINFORCEMENT OF FS 484.00 BETWEEN STRINGER 15L AND STRINGER 16L Notes (AVG MAN HRS: 5)	23-JUN-2005 H: 2522.30 L: 983					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-011 Airframe SB - Complied With #1735	MODIFICATION - TAIL CONE - INSTALLATION OF DECALS ON THE TAIL CONE ASSEMBLY Notes (AVG MAN HRS: 2)	27-DEC-2018 H: 6424.10 L: 2747					
SB 604-53-012 PART B Airframe SB - Complied With #3291	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND Notes .SEE REVISIOIN 1.						
SB 604-53-012 Airframe SB - Open #3384	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND						
SB 604-53-012 PART A Airframe SB - Complied With #2775	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND Notes .SEE REVISION 1.						
SB 604-53-012 R1 Airframe SB - Open #2804	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND						
SB 604-53-012 R1 PART B Airframe SB - Complied With #3567	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND	03-JUN-2009 H: 3637.60 L: 1526					
SB 604-53-012 R1 PART A Airframe SB - Complied With #926	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND	03-JUN-2009 H: 3637.60 L: 1526					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-012 R2 PART B Airframe SB - Open #2167	MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND Notes (AVG MAN HRS: 9)						
SB 604-53-012 R2 PART A Airframe SB - Open #3397	SPECIAL CHECK - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND Notes (AVG MAN HRS: 9)						
SB 604-53-012 R2 Airframe SB - Open #202	SPECIAL CHECK/MODIFICATION - AFT FUSELAGE - INSPECTION OF THE SADDLE TANK SHROUD ASSEMBLY ROOF AND APPLICATION OF CORROSION INHIBITING COMPOUND Notes (NOTE: RETROACTIVE ACTION THE BASIC ISSUE OF THIS SERVICE BULLETIN DID NOT REQUIRE THE REMOVAL OF THE ACU DUCT TO GAIN FULL ACCESS FOR THE APPLICATION OF CORROSION INHIBITING COMPOUND AND SEALANT AND CONSEQUENTLY, AREAS MAY HAVE BEEN MISSED. THIS RETROACTIVE ACTION IS REQUIRED TO MAKE SURE THAT THE INTENT OF THE MODIFICATION IS COMPLIED WITH. THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE: (1) INSPECT AND VERIFY THAT CORROSION INHIBITING COMPOUND AND SEALANT HAS BEEN APPLIED PER DRAWING REQUIREMENTS, IF EITHER IS MISSING, YOU MUST PERFORM THE STEPS THAT FOLLOWS: (A) REMOVE THE REFRIGERATION-PACK EXHAUST-DUCT TO IMPROVE AC						
SB 604-53-013 PART B Airframe SB - N/A #680	SPECIAL CHECK - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes .SUPERSEDED BY SB 604-53-013 REV 1						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-013 PART A Airframe SB - N/A #2640	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes .SUPERSEDED BY SB 604-53-013 REV 1						
SB 604-53-013 Airframe SB - Open #2301	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS						
SB 604-53-013 R1 PART B Airframe SB - N/A #710	MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes .SUPERSEDED BY SB 604-53-013 REV 2 PART B						
SB 604-53-013 R1 PART A Airframe SB - N/A #3467	SPECIAL CHECK - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes .SUPERSEDED BY SB 604-53-013 REV 2 PART A						
SB 604-53-013 R1 Airframe SB - Open #3305	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS						
SB 604-53-013 R2 PART B Airframe SB - N/A #397	MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes .SUPERSEDED BY SB 604-53-013 REV 3						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-013 R2 PART A Airframe SB - N/A #1665	SPECIAL CHECK - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes .SUPERSEDED BY SB 604-53-013 REV 3						
SB 604-53-013 R2 Airframe SB - Open #2286	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS						
SB 604-53-013 R2 Airframe SB - N/A #1119	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS - RETROACTIVE ACTION Notes .SUPERSEDED BY SB 604-53-013 REV 3(RETRO)						
SB 604-53-013 R3 PART B Airframe SB - Complied With #3189	MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes (AVG MAN HRS: 39)				04-JUN-2009 H: 3637.60 L: 1526		
SB 604-53-013 R3 PART A Airframe SB - Complied With #2966	SPECIAL CHECK - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes (AVG MAN HRS: 1)				03-JUN-2009 H: 3637.60 L: 1526		
SB 604-53-013 R3 Airframe SB - Open #3668	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS Notes (NOTE: RETROACTIVE ACTION THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OR REVISION 01 OR REVISION 02 OF THIS SERVICE BULLETIN WAS DONE: IT IS RECOMMENDED TO DO SERVICE BULLETIN 604-53-014.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-013 R3 Airframe SB - Open #1638	SPECIAL CHECK/MODIFICATION - FLOOR - ADDITION OF SEAT TRACK EXTENSIONS - RETROACTIVE ACTION Notes .SCHEDULED(RETRO)						
SB 604-53-014 Airframe SB - N/A #3142	SPECIAL CHECK/REWORK - FLOOR - INSPECT THE UNDER FLOOR SUPPORT CHANNEL FOR FOD AND CLEAN THE AREA Notes (AVG MAN HRS: 2)					04-JUN-2009 H: 3637.60 L: 1526	
SB 604-53-015 Airframe SB - Complied With #2483	SPECIAL CHECK - FLOOR STRUCTURE - INSPECTION AND TORQUE, IF REQUIRED, OF THE BOLTS ATTACHING THE FLOOR BEAM ASSEMBLY INSTALLED OVER THE FWD AND AFT AUXILIARY FUEL TANKS Notes (AVG MAN HRS: 10)					12-APR-2013 H: 4782.30 L: 2063	
SB 604-53-016 Airframe SB - N/A #1632	MODIFICATION - FLOORS - INSPECTION OF SEAT TRACKS FOR CORROSION Notes .TO AIRCRAFT S/N					13-FEB-2017 H: 5969.40 L: 2571	
SB 604-53-016 PART C Airframe SB - N/A #931	MODIFICATION - FLOORS - INSPECTION OF SEAT TRACKS FOR CORROSION Notes (AVG MAN HRS: 12).TO AIRCRAFT S/N					13-FEB-2017 H: 5969.40 L: 2571	
SB 604-53-016 PART B Airframe SB - N/A #251	MODIFICATION - FLOORS - INSPECTION OF SEAT TRACKS FOR CORROSION Notes (AVG MAN HRS: 6).TO AIRCRAFT S/N					13-FEB-2017 H: 5969.40 L: 2571	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-53-016 PART A Airframe SB - N/A #217	MODIFICATION - FLOORS - INSPECTION OF SEAT TRACKS FOR CORROSION Notes (AVG MAN HRS: 6).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-54-001 Airframe SB - N/A #1097	REWORK - PYLONS MAIN STRUCTURE - INCORRECT TORQUE APPLIED TO 110 HI-LITE FASTENERS Notes (AVG MAN HRS: 35).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-55-002 PART B Airframe SB - N/A #1224	REWORK - HORIZONTAL STABILIZER - POSSIBILITY OF MISSING FASTENERS ON THE HORIZONTAL STABILIZER LEADING EDGE Notes (AVG MAN HRS: 14).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-55-002 PART A Airframe SB - N/A #3713	SPECIAL CHECK - HORIZONTAL STABILIZER - POSSIBILITY OF MISSING FASTENERS ON THE HORIZONTAL STABILIZER LEADING EDGE Notes (AVG MAN HRS: 1).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-55-002 Airframe SB - N/A #2639	SPECIAL CHECK/REWORK - HORIZONTAL STABILIZER - POSSIBILITY OF MISSING FASTENERS ON THE HORIZONTAL STABILIZER LEADING EDGE Notes .TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB 604-56-001 Airframe SB - Open #485	MODIFICATION - CABIN WINDOWS - ADDITIONAL INSTALLATION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-56-001 R1 Airframe SB - Open #299	MODIFICATION - CABIN WINDOWS - ADDITIONAL INSTALLATION Notes (AVG MAN HRS: 15)DECLINED						
SB 604-56-003 Airframe SB - Open #3532	SPECIAL CHECK/MODIFICATION - WINDSHIELD - INSTALLATION OF A FACEPLY VOLTAGE DRAIN TAB Notes (AVG MAN HRS: 4)						
SB 604-57-001 Airframe SB - Complied With #2708	SPECIAL CHECK - GENERAL - POSSIBILITY OF LOW PITCH CONDITION AND OVERSIZE FASTENERS ON LOWER AND UPPER WING PLANK WS148 Notes (AVG MAN HRS: 2)				18-DEC-2008 H: 3551.80 L: 1484		
SB 604-57-002 Airframe SB - Open #2140	SPECIAL CHECK/REWORK - GENERAL - HARNESS FOULING IN THE RIGHT HAND WING LEADING EDGE Notes (AVG MAN HRS: 6)						
SB 604-57-003 Airframe SB - Superseded #2401	SPECIAL CHECK - INBOARD FLAPS - FORWARD LUGS Notes .SEE REVISION 1.						
SB 604-57-003 R1 Airframe SB - Complied With #3651	SPECIAL CHECK - INBOARD FLAPS - FORWARD LUGS Notes (AVG MAN HRS: 2)				23-MAR-2017 H: 5979.10 L: 2576		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-57-004 Airframe SB - Open #1563	REWORK/MODIFICATION - AILERONS AND ELEVONS - ADDITION OF DRAIN HOLES ON AILERON PCU ACCESS PANELS Notes (AVG MAN HRS: 3)						
SB 604-57-005 Airframe SB - Complied With #250	SPECIAL CHECK/REWORK - ATTACHMENT FITTINGS - SERIALIZATION OF MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING-SHAFT PART NO. 601R10237-1/-3 Notes (AVG MAN HRS: 1) (NOTE: PLEASE USE THE TRAXXALL PROVIDED WORK CARDS TO REPORT THE PN, SN AND THE LANDING FOR THE MLG SIDE-BRACE FITTING SHAFT)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-57-007 Airframe SB - Superseded #3491	SPECIAL CHECK - FLAP HINGE BOX - FORWARD LUGS EDGE TO EDGE DISTANCE Notes (AVG MAN HRS: 45).SEE REVISION 1.						
SB 604-57-007 R1 Airframe SB - Complied With #1516	SPECIAL CHECK - FLAP HINGE BOX - FORWARD LUGS EDGE TO EDGE DISTANCE (THIS REVISION HAS NO EFFECT FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS SERVICE BULLETIN WAS DONE THUS NO OTHER ACTION IS NECESSARY.)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-57-007 R1 PART A Airframe SB - Complied With #2062	SPECIAL CHECK - FLAP HINGE BOX - MEASUREMENT OF THE INBOARD FORWARD-LUG EDGE TO EDGE DISTANCE OF THE FLAP-HINGE-BOXES, PART NO. 600-10116, 600-10117. Notes (AVG MAN HRS: 18)	23-MAR-2017 H: 5979.10 L: 2576					
SB 604-57-007 R1 PART B Airframe SB - Complied With #295	SPECIAL CHECK - FLAP HINGE BOX - MEASUREMENT OF THE OUTBOARD FORWARD-LUG EDGE TO EDGE DISTANCE OF THE FLAP-HINGE-BOXES, PART NO. 600-10118, 600-10119, AND 600-10120 Notes (AVG MAN HRS: 27)	23-MAR-2017 H: 5979.10 L: 2576					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-71-001 Airframe SB - Open #733	SPECIAL CHECK/REWORK - MOUNTS - SERIALIZATION OF ENGINE MOUNTS AND YOKE FITTING ASSEMBLY						
SB 604-71-001 PART B Airframe SB - Open #2287	SPECIAL CHECK/REWORK - MOUNTS - SERIALIZATION OF ENGINE MOUNTS AND YOKE FITTING ASSEMBLY Notes (AVG MAN HRS: 3)						
SB 604-71-001 PART C Airframe SB - Open #3497	SPECIAL CHECK/REWORK - MOUNTS - SERIALIZATION OF ENGINE MOUNTS AND YOKE FITTING ASSEMBLY Notes (AVG MAN HRS: 5)						
SB 604-71-001 PART A Airframe SB - Open #3311	SPECIAL CHECK/REWORK - MOUNTS - SERIALIZATION OF ENGINE MOUNTS AND YOKE FITTING ASSEMBLY Notes (AVG MAN HRS: 3)						
SB 604-71-002 Airframe SB - Open #3307	CANCELLED PRIOR TO ISSUE						
SB 604-71-003 Airframe SB - Complied With #1930	SPECIAL CHECK/MODIFICATION - ENGINE DRAINS - POSSIBLE CHAFING CONDITION BETWEEN C-SUMP OIL SUPPLY TUBE AND ITS ATTACHING CLAMP Notes (AVG MAN HRS: 13)				12-JUL-2004 H: 2246.30 L: 857		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-71-004 Airframe SB - Open #1057	MODIFICATION - COWLINGS - ADDITION OF WARNING PLACARDS TO CORRECTLY INSTALL FASTENERS Notes (AVG MAN HRS: 1).RECOMMENDED SB, CUSTOMER OPS NOT TO C/W AT THIS TIMEDECLINED						
SB 604-71-005 Airframe SB - Complied With #3348	MODIFICATION - CORE COWL DOORS - INSTALLATION OF A HOLD OPEN ROD BRACKET TO PREVENT MALFUNCTION OF THE L/H ENGINE FUEL CONTROL UNIT Notes (AVG MAN HRS: 3).REF BOMBARDIER FORM ONE,FORM TRACKING # 890100993057-1,DATED 09/JUL/2011 FOR KIT 605K71-002,INFORMATION COMPLIED WITH BOMBARDIER SB 604-71-005						
SB 604-72-001 Airframe SB - Open #809	MODIFICATION - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL TO REMOVE THE 30 HOURS INSPECTION INTERVAL LIMITATION OF THE MASTER CHIP DETECTOR						
SB 604-73-003 Airframe SB - Open #1113	SPECIAL CHECK/MODIFICATION - FUEL SYSTEM - RUSSIAN AND UKRAINIAN FUEL REQUIREMENT						
SB 604-73-003 PART B Airframe SB - Superseded #508	SPECIAL CHECK/MODIFICATION - FUEL SYSTEM - RUSSIAN AND UKRAINIAN FUEL REQUIREMENT Notes .SEE REVISION 1.						
SB 604-73-003 PART A Airframe SB - Superseded #2371	SPECIAL CHECK/MODIFICATION - FUEL SYSTEM - RUSSIAN AND UKRAINIAN FUEL REQUIREMENT Notes .SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-73-003 R1 PART A Airframe SB - Open #1957	SPECIAL CHECK/MODIFICATION - FUEL SYSTEM - RUSSIAN AND UKRAINIAN FUEL REQUIREMENT Notes (AVG MAN HRS: 4)						
SB 604-73-003 R1 PART B Airframe SB - Open #1372	SPECIAL CHECK/MODIFICATION - FUEL SYSTEM - RUSSIAN AND UKRAINIAN FUEL REQUIREMENT						
SB 604-73-003 R1 Airframe SB - Open #1329	SPECIAL CHECK/MODIFICATION - FUEL SYSTEM - RUSSIAN AND UKRAINIAN FUEL REQUIREMENT						
SB 604-76-001 Airframe SB - N/A #908	MODIFICATION - THROTTLE QUADRANT ASSEMBLY - THROTTLE LEVERS CAN POSSIBLY LOCK IN THE IDLE POSITION Notes (AVG MAN HRS: 5)						
SB 604-76-002 Airframe SB - Complied With #3301	SPECIAL CHECK/MODIFICATION - ENGINE CONTROLS - POSSIBLE FAILURE OF ENGINE THROTTLE PUSH/PULL CONTROL-ASSEMBLY Notes (AVG MAN HRS: 16)				12-JUL-2004 H: 2246.30 L: 857		
SB 604-76-004 PART B Airframe SB - Complied With #2065	MODIFICATION - POWER CONTROLS - INSPECTION/REPLACEMENT OF THE THROTTLE GEAR BOX PART NO. 2100140-005 AND 2100140-007 Notes (AVG MAN HRS: 13)				18-DEC-2008		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-76-004 PART A Airframe SB - Complied With #1898	SPECIAL CHECK - POWER CONTROLS - INSPECTION/REPLACEMENT OF THE THROTTLE GEAR BOX PART NO. 2100140-005 AND 2100140-007 Notes (AVG MAN HRS: 6).IAW THE AD	18-JAN-2010 H: 3778.90 L: 1593					
SB 604-76-004 Airframe SB - Open #1530	SPECIAL CHECK/MODIFICATION - POWER CONTROLS - INSPECTION/REPLACEMENT OF THE THROTTLE GEAR BOX PART NO. 2100140-005 AND 2100140-007						
SB 604-77-001 Airframe SB - Open #2174	MODIFICATION - ENGINE VIBRATION SYSTEM - ENGINE VIBRATION DIAGNOSTIC PANEL AND HARNESS ASSEMBLY						
SB 604-77-001 PART A Airframe SB - Open #447	MODIFICATION - INSTALLATION OF ENGINE VIBRATION DIAGNOSTIC PANEL AND HARNESS ASSEMBLY Notes (AVG MAN HRS: 2)						
SB 604-77-001 PART B Airframe SB - Open #1280	MODIFICATION - REMOVAL OF ENGINE VIBRATION DIAGNOSTIC PANEL AND HARNESS ASSEMBLY Notes (AVG MAN HRS: 1.5)						
SB 604-78-001 Airframe SB - N/A #2832	MODIFICATION - THRUST REVERSER - PREVENT POWER INTERRUPTION AND RELOCATE STOW AND THROTTLE LOCKOUT MICROSWITCHES Notes (AVG MAN HRS: 100).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-78-002 PART B Airframe SB - Open #693	MODIFICATION - THRUST REVERSER - REPLACEMENT OF THE PNEUMATIC DRIVE UNIT (PDU) Notes (AVG MAN HRS: 6)						
SB 604-78-002 PART A Airframe SB - Open #390	SPECIAL CHECK - THRUST REVERSER - REPLACEMENT OF THE PNEUMATIC DRIVE UNIT (PDU) Notes (AVG MAN HRS: 2)						
SB 604-78-002 Airframe SB - N/A #1325	SPECIAL CHECK/MODIFICATION - THRUST REVERSER - REPLACEMENT OF THE PNEUMATIC DRIVE UNIT (PDU) Notes .TO AIRCRAFT S/N				13-FEB-2017 H: 5969.40 L: 2571		
SB 604-78-003 PART A Airframe SB - Open #335	MODIFICATION - THRUST REVERSER - REPLACEMENT OF PDU ENGINE NOSE COWL INTERNAL POCKETS Notes (AVG MAN HRS: 19)DECLINED						
SB 604-78-003 Airframe SB - Open #97	MODIFICATION - THRUST REVERSER - REPLACEMENT OF PDU ENGINE NOSE COWL INTERNAL POCKETS						
SB 604-78-003 PART B Airframe SB - Open #3281	MODIFICATION - THRUST REVERSER - REPLACEMENT OF PDU ENGINE NOSE COWL INTERNAL POCKETS Notes (AVG MAN HRS: 19)DECLINED						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-78-004 Airframe SB - Open #3398	MODIFICATION - EXHAUST NOZZLE ASSEMBLY - REPLACEMENT OF THE EXHAUST NOZZLE AND TAIL PIPE ATTACHMENT BOLTS Notes (AVG MAN HRS: 8)DEFERRED	28-AUG-2006 H: 3113.60 L: 1258					
SB 604-78-005 Airframe SB - Open #1586	MODIFICATION - EXHAUST NOZZLE FAIRING - INTRODUCTION OF A NEW FIRE DETECTION MOUNTING COVER Notes (AVG MAN HRS: 2)						
SB 604-78-006 Airframe SB - Open #1335	MODIFICATION - THRUST REVERSER - REPLACEMENT OF MAIN TRACK SLIDER BLOCKS Notes (AVG MAN HRS: 8)						
SB 604-78-007 Airframe SB - Open #2914	MODIFICATION - TORQUE BOX, TRACK AND SLIDERS - INTRODUCTION OF NEW BOLTS TO THE TORQUE BOX STOP ASSEMBLIES AND HINGE ASSEMBLIES Notes (AVG MAN HRS: 8)						
SB 604-78-008 Airframe SB - Open #2380	MODIFICATION - THRUST REVERSER - REPLACEMENT OF STANG FAIRING ASSEMBLIES						
SB 604-78-009 Airframe SB - Open #1962	MODIFICATION - THRUST REVERSER - BLOCKER DOOR AND LINK ARM ASSEMBLIES - INTRODUCTION OF HARDENED BUSHINGS Notes (AVG MAN HRS: 30)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 604-79-001 Airframe SB - Open #3508	MODIFICATION - ENGINE OIL INDICATION BOARD - INSTALL NEW PRINTED CIRCUIT BOARD ASSEMBLY IN JUNCTION BOX JB5 Notes (AVG MAN HRS: 10)						
SB 604-79-002 Airframe SB - Open #672	MODIFICATION - ENGINE OIL INDICATION BOARD - ADD AN ON/OFF POWER SWITCH FOR THE ENGINE OIL INDICATING BOARD IN JUNCTION BOX JB5 Notes (AVG MAN HRS: 6)						
SB 70721597-49-8166 APU SB - Open #51	BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721597-1, ON MULTIPLE APUS						
SB 70721597-49-8166 R1 APU SB - Open #174	BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721597-1, ON MULTIPLE APUS						
SB 70721597-49-8166 R2 APU SB - Open #116	BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721597-1, ON MULTIPLE APUS						
SB 70721597-49-8166 R3 APU SB - Open #54	BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721597-1, ON MULTIPLE APUS Notes (AVG MAN HRS: 1) (NOTE: COMPLIANCE: HONEYWELL RECOMMENDS THIS SERVICE BULLETIN BE DONE FOR THE BALANCE REPAIR OF THE COMPRESSOR ROTOR, PN 70721597-1.)						
SB 70721598-49-8168 APU SB - Open #163	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 70721598-49-8168 R1 APU SB - Open #13	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS						
SB 70721598-49-8168 R2 APU SB - Open #100	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS						
SB 70721598-49-8168 R3 APU SB - Open #20	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS						
	Notes (AVG MAN HRS: 1)						
SB 70721725-49-8152 APU SB - Open #177	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS						
SB 70721725-49-8152 R1 APU SB - Open #154	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS						
SB 70721725-49-8152 R2 APU SB - Open #67	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS						
SB 70721725-49-8152 R3 APU SB - Open #90	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS						
SB 70721725-49-8152 R4 APU SB - Open #65	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 71-0000 Engine 1 SB - Open #864	POWER PLANT - GENERAL (71-00-00) - CONSOLIDATED ON-WING INSPECTION RECOMMENDATIONS AND SERVICING TASKS LIST						
SB 71-0000 Engine 2 SB - Open #345	POWER PLANT - GENERAL (71-00-00) - CONSOLIDATED ON-WING INSPECTION RECOMMENDATIONS AND SERVICING TASKS LIST						
SB 71-0000 R1 Engine 1 SB - Open #676	POWER PLANT - GENERAL (71-00-00) - CONSOLIDATED ON-WING INSPECTION RECOMMENDATIONS AND SERVICING TASKS LIST						
SB 71-0000 R1 Engine 2 SB - Open #441	POWER PLANT - GENERAL (71-00-00) - CONSOLIDATED ON-WING INSPECTION RECOMMENDATIONS AND SERVICING TASKS LIST						
SB 71-0000 R2 Engine 1 SB - Open #876	POWER PLANT - GENERAL (71-00-00) - CONSOLIDATED ON-WING INSPECTION - RECOMMENDATIONS AND SERVICING TASKS LIST						
SB 71-0000 R2 Engine 2 SB - Open #685	POWER PLANT - GENERAL (71-00-00) - CONSOLIDATED ON-WING INSPECTION - RECOMMENDATIONS AND SERVICING TASKS LIST						
SB 72-0000 Engine 1 SB - Open #394	ENGINE - GENERAL (72-00-00) - RECOMMENDED ENGINE MAINTENANCE ACTIONS TO BE TAKEN WHEN AN ENGINE IS IN A SERVICE CENTER						
SB 72-0000 Engine 2 SB - Open #543	ENGINE - GENERAL (72-00-00) - RECOMMENDED ENGINE MAINTENANCE ACTIONS TO BE TAKEN WHEN AN ENGINE IS IN A SERVICE CENTER						
SB 72-0000 R1 Engine 1 SB - Open #115	ENGINE - GENERAL (72-00-00) - RECOMMENDED ENGINE MAINTENANCE ACTIONS TO BE TAKEN WHEN AN ENGINE IS IN A SERVICE CENTER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0000 R1 Engine 2 SB - Open #603	ENGINE - GENERAL (72-00-00) - RECOMMENDED ENGINE MAINTENANCE ACTIONS TO BE TAKEN WHEN AN ENGINE IS IN A SERVICE CENTER						
SB 72-0005 R6 Engine 1 SB - Open #243	ENGINE - LIFE IMPROVEMENT OF CERTAIN HIGH-PRESSURE AND LOW-PRESSURE TURBINE PARTS BY REWORK						
SB 72-0005 R6 Engine 2 SB - Open #245	ENGINE - LIFE IMPROVEMENT OF CERTAIN HIGH-PRESSURE AND LOW-PRESSURE TURBINE PARTS BY REWORK						
SB 72-0010 R2 Engine 1 SB - Open #494	ENGINE - POWER TAKEOFF (PTO) DRIVE ASSEMBLY: REPLACEMENT OF DUPLEX BALL BEARING						
SB 72-0010 R2 Engine 2 SB - Open #488	ENGINE - POWER TAKEOFF (PTO) DRIVE ASSEMBLY: REPLACEMENT OF DUPLEX BALL BEARING						
SB 72-0013 Engine 1 SB - Open #891	ENGINE - POWER TAKE OFF (PTO) DRIVE ASSEMBLY: INCREASED TORQUE ON HORIZONTAL AND VERTICAL AXIS LOCKNUTS						
SB 72-0013 Engine 2 SB - Open #152	ENGINE - POWER TAKE OFF (PTO) DRIVE ASSEMBLY: INCREASED TORQUE ON HORIZONTAL AND VERTICAL AXIS LOCKNUTS						
SB 72-0015 R2 Engine 1 SB - Open #898	ENGINE - ON-WING REPLACEMENT OF ACCESSORY DRIVE GEARBOX (AGB) AXIS-BB BALL BEARING						
SB 72-0015 R2 Engine 2 SB - Open #827	ENGINE - ON-WING REPLACEMENT OF ACCESSORY DRIVE GEARBOX (AGB) AXIS-BB BALL BEARING						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0017 R2 Engine 1 SB - Open #181	ENGINE - REWORK OF FAN DISK PN 6020T62G04 USING ENLARGED BUSHINGS						
SB 72-0017 R2 Engine 2 SB - Open #336	ENGINE - REWORK OF FAN DISK PN 6020T62G04 USING ENLARGED BUSHINGS						
SB 72-0019 R2 Engine 1 SB - Open #386	ENGINE - IMPROVED COATING FOR COMPRESSOR STATOR CASING AND COMPRESSOR ROTOR FRONT AND REAR SPOOLS						
SB 72-0019 R2 Engine 2 SB - Open #512	ENGINE - IMPROVED COATING FOR COMPRESSOR STATOR CASING AND COMPRESSOR ROTOR FRONT AND REAR SPOOLS						
SB 72-0022 R1 Engine 1 SB - Open #320	ENGINE - REPLACEMENT OF COMBUSTION LINER PRIMARY SWIRLERS						
SB 72-0022 R1 Engine 2 SB - Open #460	ENGINE - REPLACEMENT OF COMBUSTION LINER PRIMARY SWIRLERS						
SB 72-0023 R3 Engine 1 SB - Open #76	ENGINE - REPLACEMENT OF CF34-3A/-3A2 STAGE 1 HIGH-PRESSURE TURBINE (HPT) BLADES, AND STAGES 1 AND 2 WIRE SEALS						
SB 72-0023 R3 Engine 2 SB - Open #623	ENGINE - REPLACEMENT OF CF34-3A/-3A2 STAGE 1 HIGH-PRESSURE TURBINE (HPT) BLADES, AND STAGES 1 AND 2 WIRE SEALS						
SB 72-0027 R1 Engine 1 SB - Open #143	ENGINE - INSPECTION OF LOW-PRESSURE TURBINE (LPT) BORESCOPE PLUGS PN 5071T39G02 AND INSTALLATION OF LPT BORESCOPE PLUG COVERS PN 3904T92P01						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0027 R1 Engine 2 SB - Open #426	ENGINE - INSPECTION OF LOW-PRESSURE TURBINE (LPT) BORESCOPE PLUGS PN 5071T39G02 AND INSTALLATION OF LPT BORESCOPE PLUG COVERS PN 3904T92P01						
SB 72-0031 R1 Engine 1 SB - Open #160	ENGINE - REPLACEMENT OF CF34-1A/-3A/-3A2 STAGE 1 HIGH-PRESSURE TURBINE (HPT) BLADES, STAGE 1 HIGH-PRESSURE TURBINE (HPT) BAFFLES, AND STAGES 1 AND 2 WIRE SEALS						
SB 72-0031 R1 Engine 2 SB - Open #45	ENGINE - REPLACEMENT OF CF34-1A/-3A/-3A2 STAGE 1 HIGH-PRESSURE TURBINE (HPT) BLADES, STAGE 1 HIGH-PRESSURE TURBINE (HPT) BAFFLES, AND STAGES 1 AND 2 WIRE SEALS						
SB 72-0032 R1 Engine 1 SB - Open #811	ENGINE - BORESCOPE INSPECTION OF THE TURBINE TRANSITION ASSEMBLY OUTER LINER						
SB 72-0032 R1 Engine 2 SB - Open #591	ENGINE - BORESCOPE INSPECTION OF THE TURBINE TRANSITION ASSEMBLY OUTER LINER						
SB 72-0034 R1 Engine 1 SB - Open #165	ENGINE - REPLACEMENT OF CF34-1A STAGE 1 HIGH-PRESSURE TURBINE (HPT) BLADES, AND STAGES 1 AND 2 WIRE SEALS						
SB 72-0034 R1 Engine 2 SB - Open #473	ENGINE - REPLACEMENT OF CF34-1A STAGE 1 HIGH-PRESSURE TURBINE (HPT) BLADES, AND STAGES 1 AND 2 WIRE SEALS						
SB 72-0035 Engine 1 SB - Open #387	ENGINE - REAR MAIN MOUNT: REWORK OF ADDITIONAL HOLE FOR FIRE DETECTION SYSTEM HARNESS						
SB 72-0035 Engine 2 SB - Open #779	ENGINE - REAR MAIN MOUNT: REWORK OF ADDITIONAL HOLE FOR FIRE DETECTION SYSTEM HARNESS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0035 R1 Engine 1 SB - Open #321	ENGINE - REAR MAIN MOUNT: REWORK OF ADDITIONAL HOLE FOR FIRE DETECTION SYSTEM HARNESS						
SB 72-0035 R1 Engine 2 SB - Open #727	ENGINE - REAR MAIN MOUNT: REWORK OF ADDITIONAL HOLE FOR FIRE DETECTION SYSTEM HARNESS						
SB 72-0037 R1 Engine 1 SB - Open #879	ENGINE - REWORK OF THE BOREScope PLUG BOSSES ON THE LOW-PRESSURE TURBINE CASING						
SB 72-0037 R1 Engine 2 SB - Open #477	ENGINE - REWORK OF THE BOREScope PLUG BOSSES ON THE LOW-PRESSURE TURBINE CASING						
SB 72-0038 R2 Engine 1 SB - Open #159	ENGINE - REPLACEMENT OF FORWARD TRANSITION LINER SEAL AND TURBINE TRANSITION OUTER LINER						
SB 72-0038 R2 Engine 2 SB - Open #824	ENGINE - REPLACEMENT OF FORWARD TRANSITION LINER SEAL AND TURBINE TRANSITION OUTER LINER						
SB 72-0039 Engine 1 SB - Open #934	ENGINE - REWORK OF REAR C-SUMP COVER: VENT TUBE SCREEN						
SB 72-0039 Engine 2 SB - Open #586	ENGINE - REWORK OF REAR C-SUMP COVER: VENT TUBE SCREEN						
SB 72-0040 Engine 1 SB - Open #603	ENGINE - REWORK OF THE COMPRESSOR ROTOR ASSEMBLY						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0040 Engine 2 SB - Open #655	ENGINE - REWORK OF THE COMPRESSOR ROTOR ASSEMBLY						
SB 72-0040 R1 Engine 1 SB - Open #841	ENGINE - REWORK OF THE COMPRESSOR ROTOR ASSEMBLY						
SB 72-0040 R1 Engine 2 SB - Open #651	ENGINE - REWORK OF THE COMPRESSOR ROTOR ASSEMBLY						
SB 72-0041 Engine 1 SB - Open #246	ENGINE - REPLACEMENT OF THE BOREScope PLUG IN THE HIGH-PRESSURE TURBINE CASING						
SB 72-0041 Engine 2 SB - Open #496	ENGINE - REPLACEMENT OF THE BOREScope PLUG IN THE HIGH-PRESSURE TURBINE CASING						
SB 72-0048 Engine 1 SB - Open #640	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 Engine 2 SB - Open #892	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R1 Engine 1 SB - Open #566	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R1 Engine 2 SB - Open #785	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0048 R10 Engine 1 SB - Open #141	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R10 Engine 2 SB - Open #866	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R11 Engine 1 SB - Open #750	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R11 Engine 2 SB - Open #128	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R12 Engine 1 SB - Open #569	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R12 Engine 2 SB - Open #923	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R13 Engine 1 SB - Open #271	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
Notes (NOTE: COMPLIANCE: ANY AFFECTED PART THAT WAS INSTALLED PRIOR TO RECEIPT OF THE INITIAL ISSUE OF THIS SERVICE BULLETIN AND HAS NOT MET THE SPECIAL WORKSCOPE REQUIREMENTS PROVIDED BY GE AIRCRAFT ENGINES IN SUPPORT OF PREVIOUS REVISIONS OF CF34-BJ S/B 72-0048, MUST BE REMOVED FROM SERVICE NOT LATER THAN THE NEXT ENGINE SHOP VISIT. TERMINATE (SCRAP) ANY AFFECTED PART THAT IS NOW, OR MAY BECOME, IN THE POSSESSION OF THE OPERATOR.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0048 R13 Engine 2 SB - Open #269	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS Notes (NOTE: COMPLIANCE: ANY AFFECTED PART THAT WAS INSTALLED PRIOR TO RECEIPT OF THE INITIAL ISSUE OF THIS SERVICE BULLETIN AND HAS NOT MET THE SPECIAL WORKSCOPE REQUIREMENTS PROVIDED BY GE AIRCRAFT ENGINES IN SUPPORT OF PREVIOUS REVISIONS OF CF34-BJ S/B 72-0048, MUST BE REMOVED FROM SERVICE NOT LATER THAN THE NEXT ENGINE SHOP VISIT. TERMINATE (SCRAP) ANY AFFECTED PART THAT IS NOW, OR MAY BECOME, IN THE POSSESSION OF THE OPERATOR.)						
SB 72-0048 R14 Engine 1 SB - Open #434	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS Notes (NOTE: COMPLIANCE: ANY AFFECTED PART THAT WAS INSTALLED PRIOR TO RECEIPT OF THE INITIAL ISSUE OF THIS SERVICE BULLETIN AND HAS NOT MET THE SPECIAL WORKSCOPE REQUIREMENTS PROVIDED BY GE AIRCRAFT ENGINES IN SUPPORT OF PREVIOUS REVISIONS OF CF34-BJ S/B 72-0048, MUST BE REMOVED FROM SERVICE NOT LATER THAN THE NEXT ENGINE SHOP VISIT. TERMINATE (SCRAP) ANY AFFECTED PART THAT IS NOW, OR MAY BECOME, IN THE POSSESSION OF THE OPERATOR.)						
SB 72-0048 R14 Engine 2 SB - Open #529	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS Notes (NOTE: COMPLIANCE: ANY AFFECTED PART THAT WAS INSTALLED PRIOR TO RECEIPT OF THE INITIAL ISSUE OF THIS SERVICE BULLETIN AND HAS NOT MET THE SPECIAL WORKSCOPE REQUIREMENTS PROVIDED BY GE AIRCRAFT ENGINES IN SUPPORT OF PREVIOUS REVISIONS OF CF34-BJ S/B 72-0048, MUST BE REMOVED FROM SERVICE NOT LATER THAN THE NEXT ENGINE SHOP VISIT. TERMINATE (SCRAP) ANY AFFECTED PART THAT IS NOW, OR MAY BECOME, IN THE POSSESSION OF THE OPERATOR.)						
SB 72-0048 R15 Engine 1 SB - Open #73	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R15 Engine 2 SB - Open #276	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R16 Engine 1 SB - Open #93	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0048 R16 Engine 2 SB - Open #886	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R2 Engine 1 SB - Open #1	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R2 Engine 2 SB - Open #103	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R3 Engine 1 SB - Open #503	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R3 Engine 2 SB - Open #303	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R4 Engine 1 SB - Open #567	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R4 Engine 2 SB - Open #188	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R5 Engine 1 SB - Open #15	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R5 Engine 2 SB - Open #646	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0048 R6 Engine 1 SB - Open #545	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R6 Engine 2 SB - Open #808	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R7 Engine 1 SB - Open #749	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R7 Engine 2 SB - Open #436	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R8 Engine 1 SB - Open #120	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R8 Engine 2 SB - Open #130	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R9 Engine 1 SB - Open #829	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0048 R9 Engine 2 SB - Open #748	ENGINE - GENERAL - HARDWARE EXPOSED TO ABNORMAL OPERATING EVENTS						
SB 72-0050 R7 Engine 1 SB - Open #261	ENGINE - GENERAL - INTRODUCTION OF THE IMPROVED DESIGN HIGH-PRESSURE TURBINE ROTOR ASSEMBLIES PN 5079T61G02/G04 AND ASSOCIATED HARDWARE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0050 R7 Engine 2 SB - Open #178	ENGINE - GENERAL - INTRODUCTION OF THE IMPROVED DESIGN HIGH-PRESSURE TURBINE ROTOR ASSEMBLIES PN 5079T61G02/G04 AND ASSOCIATED HARDWARE						
SB 72-0051 Engine 1 SB - Open #917	ENGINE - GENERAL (72-00-00) - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CF34-BJ SERVICE BULLETINS						
SB 72-0051 Engine 2 SB - Open #535	ENGINE - GENERAL (72-00-00) - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CF34-BJ SERVICE BULLETINS						
SB 72-0051 R1 Engine 1 SB - Open #554	ENGINE - GENERAL (72-00-00) - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CF34-BJ SERVICE BULLETINS						
SB 72-0051 R1 Engine 2 SB - Open #74	ENGINE - GENERAL (72-00-00) - COMPLIANCE AND INTERCHANGEABILITY STATEMENTS USED IN CF34-BJ SERVICE BULLETINS						
SB 72-0054 R1 Engine 1 SB - Open #741	ENGINE - REWORK OF THE HIGH-PRESSURE TURBINE STATOR BORESCOPE PLUGS TO THREADED CONFIGURATION						
SB 72-0054 R1 Engine 2 SB - Open #142	ENGINE - REWORK OF THE HIGH-PRESSURE TURBINE STATOR BORESCOPE PLUGS TO THREADED CONFIGURATION						
SB 72-0054 R3 Engine 1 SB - Open #549	ENGINE - REWORK OF THE HIGH-PRESSURE TURBINE STATOR BORESCOPE PLUGS TO THREADED CONFIGURATION						
SB 72-0054 R3 Engine 2 SB - Open #387	ENGINE - REWORK OF THE HIGH-PRESSURE TURBINE STATOR BORESCOPE PLUGS TO THREADED CONFIGURATION						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0055 Engine 1 SB - Open #301	ENGINE - FAN ROTOR - INTRODUCTION OF IMPROVED LCF FAN DISKS						
SB 72-0055 Engine 2 SB - Open #363	ENGINE - FAN ROTOR - INTRODUCTION OF IMPROVED LCF FAN DISKS						
SB 72-0055 R1 Engine 1 SB - Open #21	ENGINE - FAN ROTOR - INTRODUCTION OF IMPROVED LCF FAN DISKS						
SB 72-0055 R1 Engine 2 SB - Open #124	ENGINE - FAN ROTOR - INTRODUCTION OF IMPROVED LCF FAN DISKS						
SB 72-0058 Engine 1 SB - Open #724	ENGINE - COMPRESSOR VANE-TO--BLADE AXIAL CLEARANCE INCREASE						
SB 72-0058 Engine 2 SB - Open #237	ENGINE - COMPRESSOR VANE-TO--BLADE AXIAL CLEARANCE INCREASE						
SB 72-0058 R1 Engine 1 SB - Open #256	ENGINE - COMPRESSOR VANE-TO--BLADE AXIAL CLEARANCE INCREASE						
SB 72-0058 R1 Engine 2 SB - Open #647	ENGINE - COMPRESSOR VANE-TO--BLADE AXIAL CLEARANCE INCREASE						
SB 72-0058 R2 Engine 1 SB - Open #849	ENGINE - COMPRESSOR VANE-TO-BLADE AXIAL CLEARANCE INCREASE						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0058 R2 Engine 2 SB - Open #28	ENGINE - COMPRESSOR VANE-TO-BLADE AXIAL CLEARANCE INCREASE						
SB 72-0058 R3 Engine 1 SB - Open #167	ENGINE - COMPRESSOR VANE-TO-BLADE AXIAL CLEARANCE INCREASE						
SB 72-0058 R3 Engine 2 SB - Open #507	ENGINE - COMPRESSOR VANE-TO-BLADE AXIAL CLEARANCE INCREASE						
SB 72-0059 Engine 1 SB - Open #904	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 Engine 2 SB - Open #561	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R1 Engine 1 SB - Open #502	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R1 Engine 2 SB - Open #196	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R2 Engine 1 SB - Open #249	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R2 Engine 2 SB - Open #212	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0059 R3 Engine 1 SB - Open #737	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R3 Engine 2 SB - Open #268	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R4 Engine 1 SB - Open #223	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R4 Engine 2 SB - Open #563	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R5 Engine 1 SB - Open #684	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0059 R5 Engine 2 SB - Open #321	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF NEW COMBUSTION LINER WITH IMPROVED WEAR-COATED IGNITER FERRULE HARDWARE AND IGNITER WITH WEAR-COATED TIP						
SB 72-0060 Engine 1 SB - Open #752	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0060 Engine 2 SB - Open #236	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0060 R1 Engine 1 SB - Open #292	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0060 R1 Engine 2 SB - Open #883	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0060 R2 Engine 1 SB - Open #848	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0060 R2 Engine 2 SB - Open #927	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0060 R3 Engine 1 SB - Open #35	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0060 R3 Engine 2 SB - Open #456	ENGINE - REWORK OF THE POWER TAKEOFF (PTO) ASSEMBLIES PN 6037T72G12/G16/G17 AND INTRODUCTION OF PTO ASSEMBLY PN 6037T72G18						
SB 72-0062 Engine 1 SB - Open #107	ENGINE - INTRODUCTION OF IMPROVED HIGH-PRESSURE TURBINE (HPT) STAGE 1 BLADES WITH INTERNAL COATING						
SB 72-0062 Engine 2 SB - Open #704	ENGINE - INTRODUCTION OF IMPROVED HIGH-PRESSURE TURBINE (HPT) STAGE 1 BLADES WITH INTERNAL COATING						
SB 72-0063 Engine 1 SB - Open #136	ENGINE - REWORK OF COMPRESSOR FORWARD SHAFT PN 5037T01P03 TO PN 5037T01P04 AND INTRODUCTION OF NEW COMPRESSOR FORWARD SHAFT PN 5037T01P04						
SB 72-0063 Engine 2 SB - Open #940	ENGINE - REWORK OF COMPRESSOR FORWARD SHAFT PN 5037T01P03 TO PN 5037T01P04 AND INTRODUCTION OF NEW COMPRESSOR FORWARD SHAFT PN 5037T01P04						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0063 R1 Engine 1 SB - Open #519	ENGINE - REWORK OF COMPRESSOR FORWARD SHAFT PN 5037T01P03 TO PN 5037T01P04 AND INTRODUCTION OF NEW COMPRESSOR FORWARD SHAFT PN 5037T01P04						
SB 72-0063 R1 Engine 2 SB - Open #96	ENGINE - REWORK OF COMPRESSOR FORWARD SHAFT PN 5037T01P03 TO PN 5037T01P04 AND INTRODUCTION OF NEW COMPRESSOR FORWARD SHAFT PN 5037T01P04						
SB 72-0064 Engine 1 SB - Open #733	ENGINE - COMPRESSOR STATOR - ELIMINATION OF SPLITLINE PINS FROM COMPRESSOR INNER SHROUDS						
SB 72-0064 Engine 2 SB - Open #286	ENGINE - COMPRESSOR STATOR - ELIMINATION OF SPLITLINE PINS FROM COMPRESSOR INNER SHROUDS						
SB 72-0065 Engine 1 SB - Open #339	ENGINE - INTERCHANGEABILITY OF CF34-3B AND CF34-3B1 ENGINE MODELS						
SB 72-0065 Engine 2 SB - Open #716	ENGINE - INTERCHANGEABILITY OF CF34-3B AND CF34-3B1 ENGINE MODELS						
SB 72-0065 R1 Engine 1 SB - Open #782	ENGINE - INTERCHANGEABILITY OF CF34-3B AND CF34-3B1 ENGINE MODELS						
SB 72-0065 R1 Engine 2 SB - Open #895	ENGINE - INTERCHANGEABILITY OF CF34-3B AND CF34-3B1 ENGINE MODELS						
SB 72-0066 Engine 1 SB - Open #795	ENGINE - FAN ROTOR - FORWARD FAN SHAFT DESIGN CHANGE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0066 Engine 2 SB - Open #467	ENGINE - FAN ROTOR - FORWARD FAN SHAFT DESIGN CHANGE						
SB 72-0067 R2 Engine 1 SB - Open #355	ENGINE - CF34-3B FLEET LEADER SAMPLING PROGRAM Notes (NOTE: A CF34-3B TURBOFAN ENGINE WHICH IS IDENTIFIED AS A "FLEET LEADER" (A FLEET LEADER IS AN ENGINE THAT HAS ACCUMULATED MORE HOURS AND/OR MORE CYCLES THAN OTHER ENGINES).)						
SB 72-0067 R2 Engine 2 SB - Open #328	ENGINE - CF34-3B FLEET LEADER SAMPLING PROGRAM Notes (NOTE: A CF34-3B TURBOFAN ENGINE WHICH IS IDENTIFIED AS A "FLEET LEADER" (A FLEET LEADER IS AN ENGINE THAT HAS ACCUMULATED MORE HOURS AND/OR MORE CYCLES THAN OTHER ENGINES).)						
SB 72-0068 Engine 1 SB - Open #654	ENGINE - GENERAL - ENGINE SERVICE RECORD (LOGBOOK) ENTRY FOR THE CF34-3B HPT BALANCE PISTON SEAL						
SB 72-0068 Engine 2 SB - Open #795	ENGINE - GENERAL - ENGINE SERVICE RECORD (LOGBOOK) ENTRY FOR THE CF34-3B HPT BALANCE PISTON SEAL						
SB 72-0069 Engine 1 SB - Open #77	ENGINE - TURBINE TRANSITION ASSEMBLY - REPLACEMENT OF THE SELF-LOCKING NUTS ON THE THERMOCOUPLE PROBES AND ON THE PT5 PRESSURE PROBE OR PLUG						
SB 72-0069 Engine 2 SB - Open #249	ENGINE - TURBINE TRANSITION ASSEMBLY - REPLACEMENT OF THE SELF-LOCKING NUTS ON THE THERMOCOUPLE PROBES AND ON THE PT5 PRESSURE PROBE OR PLUG						
SB 72-0069 R1 Engine 1 SB - Open #408	ENGINE - TURBINE TRANSITION ASSEMBLY - REPLACEMENT OF THE SELF-LOCKING NUTS ON THE THERMOCOUPLE PROBES AND ON THE PT5 PRESSURE PROBE OR PLUG						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0069 R1 Engine 2 SB - Open #898	ENGINE - TURBINE TRANSITION ASSEMBLY - REPLACEMENT OF THE SELF-LOCKING NUTS ON THE THERMOCOUPLE PROBES AND ON THE PT5 PRESSURE PROBE OR PLUG						
SB 72-0070 Engine 1 SB - Open #356	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS						
SB 72-0070 Engine 2 SB - Open #49	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS						
SB 72-0070 R1 Engine 1 SB - Open #360	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS						
SB 72-0070 R1 Engine 2 SB - Open #625	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS						
SB 72-0070 R2 Engine 1 SB - Open #808	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS						
SB 72-0070 R2 Engine 2 SB - Open #405	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS						
SB 72-0070 R3 Engine 1 SB - N/A #220	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS					12-APR-2012 H: 4516.10 C: 1934	
SB 72-0070 R3 Engine 2 SB - N/A #115	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK CLEVIS					12-APR-2012 H: 4516.10 C: 1934	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0070 R4 Engine 1 SB - Open #836	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK AND CLEVIS BUSHING Notes (NOTE: FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-NEW (TSN), OR FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-REPAIR (TSR) (REFER TO STEP 1.D.(7)), IT IS RECOMMENDED THAT AN INITIAL CLEVIS BUSHING INSPECTION BE PERFORMED AT THE NEXT OPPORTUNITY, BUT NOT TO EXCEED 5,000 HOURS TSN OR TSR. ALL FOUR BUSHINGS (FOR EACH ENGINE) SHOULD BE INSPECTED.)						
SB 72-0070 R4 Engine 2 SB - Open #12	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK AND CLEVIS BUSHING Notes (NOTE: FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-NEW (TSN), OR FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-REPAIR (TSR) (REFER TO STEP 1.D.(7)), IT IS RECOMMENDED THAT AN INITIAL CLEVIS BUSHING INSPECTION BE PERFORMED AT THE NEXT OPPORTUNITY, BUT NOT TO EXCEED 5,000 HOURS TSN OR TSR. ALL FOUR BUSHINGS (FOR EACH ENGINE) SHOULD BE INSPECTED.)						
SB 72-0070 R5 Engine 1 SB - Open #703	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK AND CLEVIS BUSHING Notes (NOTE: FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-NEW (TSN), OR FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-REPAIR (TSR) (REFER TO STEP 1.D.(7)), IT IS RECOMMENDED THAT AN INITIAL CLEVIS BUSHING INSPECTION BE PERFORMED AT THE NEXT OPPORTUNITY, BUT NOT TO EXCEED 5,000 HOURS TSN OR TSR. ALL FOUR BUSHINGS (FOR EACH ENGINE) SHOULD BE INSPECTED.)						
SB 72-0070 R5 Engine 2 SB - Open #485	ENGINE - COMPRESSOR STATOR - INSPECTION AND REWORK OF VG ACTUATOR BELLCRANK AND CLEVIS BUSHING Notes (NOTE: FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-NEW (TSN), OR FOR ENGINES WITH LESS THAN 5,000 HOURS TIME-SINCE-REPAIR (TSR) (REFER TO STEP 1.D.(7)), IT IS RECOMMENDED THAT AN INITIAL CLEVIS BUSHING INSPECTION BE PERFORMED AT THE NEXT OPPORTUNITY, BUT NOT TO EXCEED 5,000 HOURS TSN OR TSR. ALL FOUR BUSHINGS (FOR EACH ENGINE) SHOULD BE INSPECTED.)						
SB 72-0071 Engine 1 SB - Open #523	ENGINE - COMPRESSOR ROTOR - INTRODUCTION OF STAGES 5 THROUGH 9 COMPRESSOR ROTOR BLADES WITH IMPROVED WEAR-RESISTANT DOVETAIL COATING						
SB 72-0071 Engine 2 SB - Open #254	ENGINE - COMPRESSOR ROTOR - INTRODUCTION OF STAGES 5 THROUGH 9 COMPRESSOR ROTOR BLADES WITH IMPROVED WEAR-RESISTANT DOVETAIL COATING						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0072 Engine 1 SB - Open #697	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF IMPROVED VG ACTUATOR RINGS						
SB 72-0072 Engine 2 SB - Open #146	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF IMPROVED VG ACTUATOR RINGS						
SB 72-0072 R1 Engine 1 SB - Open #139	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF IMPROVED VG ACTUATOR RINGS						
SB 72-0072 R1 Engine 2 SB - Open #602	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF IMPROVED VG ACTUATOR RINGS						
SB 72-0072 R2 Engine 1 SB - Open #78	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF IMPROVED VG ACTUATOR RINGS						
SB 72-0072 R2 Engine 2 SB - Open #111	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF IMPROVED VG ACTUATOR RINGS						
SB 72-0074 Engine 1 SB - Open #43	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 Engine 2 SB - Open #782	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R1 Engine 1 SB - Open #67	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0074 R1 Engine 2 SB - Open #562	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R2 Engine 1 SB - Open #775	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R2 Engine 2 SB - Open #354	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R3 Engine 1 SB - Open #532	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R3 Engine 2 SB - Open #855	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R4 Engine 1 SB - Open #276	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R4 Engine 2 SB - Open #767	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R5 Engine 1 SB - Open #426	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						
SB 72-0074 R5 Engine 2 SB - Open #501	ENGINE - COMPRESSOR (72-30-00) - INTRODUCTION OF IMPROVED VG ACTUATOR SHAFT AND BELLCRANK ASSEMBLY						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0075 Engine 1 SB - Open #58	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 Engine 2 SB - Open #728	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 R1 Engine 1 SB - Open #192	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 R1 Engine 2 SB - Open #179	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 R2 Engine 1 SB - Open #534	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 R2 Engine 2 SB - Open #75	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 R3 Engine 1 SB - Open #200	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0075 R3 Engine 2 SB - Open #468	ENGINE - COMBUSTION SECTION - IMPROVED REAR MAIN MOUNT FIREWALL SEALS						
SB 72-0079 R1 Engine 1 SB - Open #282	ENGINE - TURBINE SECTION - IMPROVED HPT STATOR ASSEMBLY AND TURBINE TRANSITION ASSEMBLY						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0079 R1 Engine 2 SB - Open #897	ENGINE - TURBINE SECTION - IMPROVED HPT STATOR ASSEMBLY AND TURBINE TRANSITION ASSEMBLY						
SB 72-0080 R1 Engine 1 SB - Open #437	ENGINE - FAN ROTOR - REPLACEMENT OF NO. 1 BALL BEARING MANUFACTURING LOT						
SB 72-0080 R1 Engine 2 SB - Open #618	ENGINE - FAN ROTOR - REPLACEMENT OF NO. 1 BALL BEARING MANUFACTURING LOT						
SB 72-0081 Engine 1 SB - Open #687	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - CF34 COMBUSTION LINER SHELL AND DOME PART NUMBER AND SERIAL NUMBER TRACKING Notes (NOTE: COMPLIANCE WITH THIS SERVICE BULLETIN IS ACCOMPLISHED WITH RESPECT TO A NEW SHELL(S) OR DOME AT THE TIME OF INSTALLATION OF THE NEW SHELL(S) OR DOME.)						
SB 72-0081 Engine 2 SB - Open #885	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - CF34 COMBUSTION LINER SHELL AND DOME PART NUMBER AND SERIAL NUMBER TRACKING Notes (NOTE: COMPLIANCE WITH THIS SERVICE BULLETIN IS ACCOMPLISHED WITH RESPECT TO A NEW SHELL(S) OR DOME AT THE TIME OF INSTALLATION OF THE NEW SHELL(S) OR DOME.)						
SB 72-0082 R1 Engine 1 SB - Open #147	COMPRESSOR VARIABLE VANE ACTUATOR ARM WEAR AT COMPRESS SPLITLINE						
SB 72-0082 R1 Engine 2 SB - Open #39	COMPRESSOR VARIABLE VANE ACTUATOR ARM WEAR AT COMPRESS SPLITLINE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0082 R2 Engine 1 SB - Open #326	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - CF34 COMPRESSOR VARIABLE VANE ACTUATING ARM WEAR AT THE COMPRESSOR SPLITLINE Notes (NOTE: FOR ENGINES WITH LESS THAN 10,000 HOURS TSN, IT IS RECOMMENDED THAT AN INITIAL INSPECTION OF THE STAGE 1 AND STAGE 2 ACTUATING ARMS BE PERFORMED AT THE NEXT OPPORTUNITY, NOT TO EXCEED 10,000 HOURS TSN. FOR ENGINES WITH 10,000 - 11,200 HOURS TSN, IT IS RECOMMENDED THAT AN INSPECTION OF THE STAGE 1 AND STAGE 2 ACTUATING ARMS BE PERFORMED AT THE NEXT OPPORTUNITY, BUT NOT TO EXCEED 800 ADDITIONAL OPERATING HOURS AFTER RECEIPT OF THIS SERVICE BULLETIN. FOR ENGINES WITH MORE THAN 11,200 HOURS TSN, IT IS RECOMMENDED THAT AN INSPECTION OF THE STAGE						
SB 72-0082 R2 Engine 2 SB - Open #690	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - CF34 COMPRESSOR VARIABLE VANE ACTUATING ARM WEAR AT THE COMPRESSOR SPLITLINE Notes (NOTE: FOR ENGINES WITH LESS THAN 10,000 HOURS TSN, IT IS RECOMMENDED THAT AN INITIAL INSPECTION OF THE STAGE 1 AND STAGE 2 ACTUATING ARMS BE PERFORMED AT THE NEXT OPPORTUNITY, NOT TO EXCEED 10,000 HOURS TSN. FOR ENGINES WITH 10,000 - 11,200 HOURS TSN, IT IS RECOMMENDED THAT AN INSPECTION OF THE STAGE 1 AND STAGE 2 ACTUATING ARMS BE PERFORMED AT THE NEXT OPPORTUNITY, BUT NOT TO EXCEED 800 ADDITIONAL OPERATING HOURS AFTER RECEIPT OF THIS SERVICE BULLETIN. FOR ENGINES WITH MORE THAN 11,200 HOURS TSN, IT IS RECOMMENDED THAT AN INSPECTION OF THE STAGE						
SB 72-0083 Engine 1 SB - Open #45	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - REWORK OF HPT STATOR ASSEMBLY AND INTRODUCTION OF IMPROVED DURABILITY STAGE 2 HPT NOZZLE AND HPT INNER CASE AND SPLINE SEALS						
SB 72-0083 Engine 2 SB - Open #756	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - REWORK OF HPT STATOR ASSEMBLY AND INTRODUCTION OF IMPROVED DURABILITY STAGE 2 HPT NOZZLE AND HPT INNER CASE AND SPLINE SEALS						
SB 72-0083 R1 Engine 1 SB - Open #400	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - REWORK OF HPT STATOR ASSEMBLY AND INTRODUCTION OF IMPROVED DURABILITY STAGE 2 HPT NOZZLE AND HPT INNER CASE AND SPLINE SEALS						
SB 72-0083 R1 Engine 2 SB - Open #156	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - REWORK OF HPT STATOR ASSEMBLY AND INTRODUCTION OF IMPROVED DURABILITY STAGE 2 HPT NOZZLE AND HPT INNER CASE AND SPLINE SEALS						
SB 72-0085 Engine 1 SB - Open #661	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0085 Engine 2 SB - Open #375	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R1 Engine 1 SB - Open #253	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R1 Engine 2 SB - Open #882	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R2 Engine 1 SB - Open #692	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R2 Engine 2 SB - Open #768	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R3 Engine 1 SB - Open #87	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R3 Engine 2 SB - Open #240	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R4 Engine 1 SB - N/A #823	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS					18-MAR-2015 H: 5435.90 C: 2357	
Notes .PER SERIAL NUMBER DO NOT APPEAR ON ANY OF THE TABLE 1,2 OR 3 LISTS							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0085 R4 Engine 2 SB - N/A #155	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS Notes .PER SERIAL NUMBER DO NOT APPEAR ON ANY OF THE TABLE 1,2 OR 3 LISTS	18-MAR-2015 H: 5435.90 C: 2357					
SB 72-0085 R5 Engine 1 SB - Open #889	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R5 Engine 2 SB - Open #131	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R6 Engine 1 SB - Open #346	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0085 R6 Engine 2 SB - Open #896	ENGINE - AGB ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX AXIS-P GEARS						
SB 72-0086 Engine 1 SB - Open #289	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (724100) - ONE-TIME BOREScope INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0086 Engine 2 SB - Open #108	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (724100) - ONE-TIME BOREScope INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0086 R1 Engine 1 SB - Open #727	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - ONE-TIME BOREScope INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0086 R1 Engine 2 SB - Open #517	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - ONE-TIME BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0086 R2 Engine 1 SB - Open #825	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - ONE-TIME BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0086 R2 Engine 2 SB - Open #635	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - ONE-TIME BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0086 R3 Engine 1 SB - Open #89	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - ONE-TIME BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0086 R3 Engine 2 SB - Open #373	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - ONE-TIME BORESCOPE INSPECTION OF THE COMBUSTION CHAMBER FRAME SCAVENGE TUBE BRAZE JOINTS						
SB 72-0087 Engine 1 SB - Open #706	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED COMBUSTION LINER						
SB 72-0087 Engine 2 SB - Open #664	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED COMBUSTION LINER						
SB 72-0087 R1 Engine 1 SB - Open #530	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED COMBUSTION LINER						
SB 72-0087 R1 Engine 2 SB - Open #681	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED COMBUSTION LINER						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0087 R2 Engine 1 SB - Open #275	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED COMBUSTION LINER						
SB 72-0087 R2 Engine 2 SB - Open #307	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED COMBUSTION LINER						
SB 72-0089 Engine 1 SB - Open #240	ENGINE - HPT ROTOR (72-46-00) - INTRODUCTION OF IMPROVED STAGE 2 HPT BLADES						
SB 72-0089 Engine 2 SB - Open #312	ENGINE - HPT ROTOR (72-46-00) - INTRODUCTION OF IMPROVED STAGE 2 HPT BLADES						
SB 72-0090 Engine 1 SB - Open #178	ENGINE - ADD SAFETY WIRE AT THE TOTAL TEMPERATURE AND PRESSURE BOSS CAP						
SB 72-0090 Engine 2 SB - Open #751	ENGINE - ADD SAFETY WIRE AT THE TOTAL TEMPERATURE AND PRESSURE BOSS CAP						
SB 72-0090 R1 Engine 1 SB - Open #598	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - ADD SAFETY WIRE AT THE TOTAL TEMPERATURE AND PRESSURE BOSS CAP Notes (AVG MAN HRS: 1)						
SB 72-0090 R1 Engine 2 SB - Open #875	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - ADD SAFETY WIRE AT THE TOTAL TEMPERATURE AND PRESSURE BOSS CAP Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0091 Engine 1 SB - Open #709	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION						
SB 72-0091 Engine 2 SB - Open #734	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION						
SB 72-0091 R1 Engine 1 SB - Open #206	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R1 Engine 2 SB - Open #695	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0091 R2 Engine 1 SB - Open #64	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R2 Engine 2 SB - Open #713	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R3 Engine 1 SB - Open #683	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0091 R3 Engine 2 SB - Open #723	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R4 Engine 1 SB - Open #299	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R4 Engine 2 SB - Open #194	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0091 R5 Engine 1 SB - Open #440	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R5 Engine 2 SB - Open #378	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.)						
SB 72-0091 R6 Engine 1 SB - N/A #98	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.).BY SERIAL NUMBER NA TO FAN BLADE S/N'S			28-JUN-2011 H: 4244.20 C: 1829			



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0091 R6 Engine 2 SB - N/A #549	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION	28-JUN-2011 H: 4244.20 C: 1829					
Notes (NOTE: IF IT IS RECORDED IN THE ENGINE LOG BOOK THAT THE FAN BLADE PIN HOLES WERE INSPECTED WHILE IN AN OVERHAUL SHOP IN ACCORDANCE WITH ONE OF THE DOCUMENTS LISTED BELOW, THE INTENT OF THE 18,000 CSN REQUIREMENT OF THIS SERVICE BULLETIN HAS BEEN MET. • IFM 20 (DATED 04-28-00) • IFM 20 REVISION 1 (DATED 05-05-00) • IFM 20 REVISION 2 (DATED 05-08-00) GE RECOMMENDS SUBSEQUENT RE-INSPECTION OF THE AFFECTED FAN BLADES, IN COMPLIANCE WITH THIS SERVICE BULLETIN, AT 3,000 CYCLE INTERVALS UNTIL FAN BLADES WITH REWORKED PIN HOLES ARE AVAILABLE AND INSTALLED ON THE ENGINE.).BY SERIAL NUMBER NA TO FAN BLADE S/N'S							
SB 72-0091 R7 Engine 1 SB - Open #191	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION		C: 18000			C: 18000.00	C: 13997
SB 72-0091 R7 Engine 2 SB - Open #386	ENGINE - FAN SECTION MODULE (72-21-00) - FAN BLADE PIN HOLE INSPECTION		C: 18000			C: 18000.00	C: 13997
SB 72-0092 Engine 1 SB - Open #52	HPT STATOR ASSEMBLY - INTRO OF IMPROVED BOREScope PLUG						
SB 72-0092 Engine 2 SB - Open #687	HPT STATOR ASSEMBLY - INTRO OF IMPROVED BOREScope PLUG						
SB 72-0092 R1 Engine 1 SB - Complied With #924	ENGINE - HPT STATOR ASSEMBLY - INTRODUCTION OF IMPROVED BOREScope PLUG	14-OCT-2009 H: 3725.60 C: 1574					
SB 72-0092 R1 Engine 2 SB - Complied With #297	ENGINE - HPT STATOR ASSEMBLY - INTRODUCTION OF IMPROVED BOREScope PLUG	14-OCT-2009 H: 3725.60 C: 1574					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0093 Engine 1 SB - Complied With #507	HPT ROTOR ASSEMBLY (72-46-00) - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL	07-OCT-2009 H: 3725.60 C: 1574					
SB 72-0093 Engine 2 SB - Complied With #258	HPT ROTOR ASSEMBLY (72-46-00) - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL	07-OCT-2009 H: 3725.60 C: 1574					
SB 72-0093 R1 Engine 1 SB - Complied With #510	HPT ROTOR ASSEMBLY (72-46-00) - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL Notes .PREVIOUSLY						
SB 72-0093 R1 Engine 2 SB - Complied With #229	HPT ROTOR ASSEMBLY (72-46-00) - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL Notes .PREVIOUSLY						
SB 72-0093 R2 Engine 1 SB - Open #535	HPT ROTOR ASSEMBLY (72-46-00) - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL						
SB 72-0093 R2 Engine 2 SB - Open #702	HPT ROTOR ASSEMBLY (72-46-00) - INTRODUCTION OF IMPROVED NO. 5 BEARING ROTATING AIR SEAL						
SB 72-0094 Engine 1 SB - Open #695	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0094 Engine 2 SB - Open #199	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0094 R1 Engine 1 SB - Open #492	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0094 R1 Engine 2 SB - Open #173	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0094 R2 Engine 1 SB - Open #392	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0094 R2 Engine 2 SB - Open #825	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0094 R3 Engine 1 SB - Open #902	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0094 R3 Engine 2 SB - Open #565	ENGINE - HPT ROTOR ASSEMBLY (72-46-00) - HPT STAGE 2 BLADE PN 6078T11P01 REPLACEMENT PLAN						
SB 72-0095 Engine 1 SB - Open #267	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED-DURABILITY STAGE 1 TURBINE NOZZLE						
SB 72-0095 Engine 2 SB - Open #147	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED-DURABILITY STAGE 1 TURBINE NOZZLE						
SB 72-0095 R1 Engine 1 SB - Open #210	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED-DURABILITY STAGE 1 TURBINE NOZZLE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0095 R1 Engine 2 SB - Open #537	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - INTRODUCTION OF IMPROVED-DURABILITY STAGE 1 TURBINE NOZZLE						
SB 72-0096 Engine 1 SB - Open #550	ENGINE - COMPRESSOR SECTION (72-30-00) - INSPECTION OF COMPRESSOR CASINGS AND SPOOLS						
SB 72-0096 Engine 2 SB - Open #950	ENGINE - COMPRESSOR SECTION (72-30-00) - INSPECTION OF COMPRESSOR CASINGS AND SPOOLS						
SB 72-0098 Engine 1 SB - Open #768	ENGINE - LOW-PRESSURE TURBINE ROTOR (725300) REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE DISKS						
SB 72-0098 Engine 2 SB - Open #654	ENGINE - LOW-PRESSURE TURBINE ROTOR (725300) REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE DISKS						
SB 72-0098 R1 Engine 1 SB - Open #612	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE DISKS						
SB 72-0098 R1 Engine 2 SB - Open #652	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE DISKS						
SB 72-0098 R2 Engine 1 SB - Open #303	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE DISKS						
SB 72-0098 R2 Engine 2 SB - Open #408	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE DISKS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0098 R2 Engine 1 SB - Open #100	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE STAGE 4 DISKS. Notes (LPT STAGE 4 DISK)						
SB 72-0098 R2 Engine 2 SB - Open #210	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE STAGE 4 DISKS. Notes (LPT STAGE 4 DISK)						
SB 72-0098 R2 Engine 1 SB - Open #438	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE STAGE 5 DISKS. Notes (LPT STAGE 5 DISK)						
SB 72-0098 R2 Engine 2 SB - Open #413	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE STAGE 5 DISKS. Notes (LPT STAGE 5 DISK)						
SB 72-0098 R2 Engine 1 SB - Open #948	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE STAGE 6 DISKS. Notes (LPT STAGE 6 DISK)						
SB 72-0098 R2 Engine 2 SB - Open #171	ENGINE - LOW-PRESSURE TURBINE ROTOR (72-53-00) - REPLACEMENT OF SELECTED CF34 LOW-PRESSURE TURBINE STAGE 6 DISKS. Notes (LPT STAGE 6 DISK)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0099 Engine 1 SB - Open #634	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0099 Engine 2 SB - Open #822	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0101 Engine 1 SB - Open #414	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0101 Engine 2 SB - Open #185	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0102 Engine 1 SB - Open #920	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED BALL BEARING DESIGN FOR AXES -P, -J, AND -K BEARINGS Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO THE CF34 TURBOFAN ENGINES AFFECTED THAT HAVE ACCESSORY GEARBOX ASSEMBLIES WITH AGB BEARINGS PN 5071T20P01 INSTALLED)						
SB 72-0102 Engine 2 SB - Open #83	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF IMPROVED BALL BEARING DESIGN FOR AXES -P, -J, AND -K BEARINGS Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO THE CF34 TURBOFAN ENGINES AFFECTED THAT HAVE ACCESSORY GEARBOX ASSEMBLIES WITH AGB BEARINGS PN 5071T20P01 INSTALLED)						
SB 72-0104 Engine 1 SB - Open #91	ENGINE -- HIGH--PRESSURE TURBINE ROTOR (72-46-00) INTRODUCTION OF IMPROVED HPT STAGE 1 BLADES PN 6078T19P10 AND PN 6078T19P11						
SB 72-0104 Engine 2 SB - Open #184	ENGINE -- HIGH--PRESSURE TURBINE ROTOR (72-46-00) INTRODUCTION OF IMPROVED HPT STAGE 1 BLADES PN 6078T19P10 AND PN 6078T19P11						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0104 R1 Engine 1 SB - Open #489	ENGINE - HIGH-PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF IMPROVED HPT STAGE 1 BLADES PN 6078T19P10 AND PN 6078T19P11						
SB 72-0104 R1 Engine 2 SB - Open #718	ENGINE - HIGH-PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF IMPROVED HPT STAGE 1 BLADES PN 6078T19P10 AND PN 6078T19P11						
SB 72-0104 R2 Engine 1 SB - Open #538	ENGINE - HIGH-PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF IMPROVED HPT STAGE 1 BLADES PN 6078T19P10 AND PN 6078T19P11						
SB 72-0104 R2 Engine 2 SB - Open #334	ENGINE - HIGH-PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF IMPROVED HPT STAGE 1 BLADES PN 6078T19P10 AND PN 6078T19P11						
SB 72-0105 Engine 1 SB - Open #185	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB ASSEMBLY PN 6014T81G32 WITH METAL PEENING ON AXES L, P, AND K GEARS						
SB 72-0105 Engine 2 SB - Open #773	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB ASSEMBLY PN 6014T81G32 WITH METAL PEENING ON AXES L, P, AND K GEARS						
SB 72-0105 R1 Engine 1 SB - Open #479	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB ASSEMBLY PN 6014T81G32 WITH METAL PEENING ON AXES L, P, AND K GEARS						
SB 72-0105 R1 Engine 2 SB - Open #544	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB ASSEMBLY PN 6014T81G32 WITH METAL PEENING ON AXES L, P, AND K GEARS						
SB 72-0105 R2 Engine 1 SB - Open #587	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB ASSEMBLY PN 6014T81G32 WITH METAL PEENING ON AXES L, P, AND K GEARS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0105 R2 Engine 2 SB - Open #13	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB ASSEMBLY PN 6014T81G32 WITH METAL PEENING ON AXES L, P, AND K GEARS						
SB 72-0106 Engine 1 SB - Open #632	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 Engine 2 SB - Open #584	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R1 Engine 1 SB - Open #459	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R1 Engine 2 SB - Open #729	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R2 Engine 1 SB - Open #471	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R2 Engine 2 SB - Open #216	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R3 Engine 1 SB - Open #24	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R3 Engine 2 SB - Open #874	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0106 R4 Engine 1 SB - Open #476	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R4 Engine 2 SB - Open #472	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R5 Engine 1 SB - Open #668	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R5 Engine 2 SB - Open #434	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R6 Engine 1 SB - Open #832	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R6 Engine 2 SB - Open #521	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R7 Engine 1 SB - Open #10	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0106 R7 Engine 2 SB - Open #610	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 9 COMPRESSOR ROTOR BLADE REPLACEMENT						
SB 72-0107 Engine 1 SB - Open #843	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0107 Engine 2 SB - Open #483	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0107 R1 Engine 1 SB - Open #505	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0107 R1 Engine 2 SB - Open #781	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0108 Engine 1 SB - Open #377	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 Engine 2 SB - Open #726	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R1 Engine 1 SB - Open #268	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R1 Engine 2 SB - Open #261	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R2 Engine 1 SB - Open #509	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R2 Engine 2 SB - Open #140	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0108 R3 Engine 1 SB - Open #46	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R3 Engine 2 SB - Open #14	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R4 Engine 1 SB - Open #144	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R4 Engine 2 SB - Open #181	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R5 Engine 1 SB - Open #599	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0108 R5 Engine 2 SB - Open #91	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) OR HIGH PRESSURE TURBINE ROTOR (72-52-00) - IMPROVED DURABILITY STAGE 2 HPT BLADE WITH AIRFOIL CAVITY COATING						
SB 72-0109 Engine 1 SB - N/A #99	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND REWORK OF VG SHAFT AFT BEARING SUPPORT	28-NOV-2002					
	Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORT HAS BEEN IDENTIFIED WITH THE "R" MARKING.).BY SERIAL NUMBER						
SB 72-0109 Engine 2 SB - N/A #888	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND REWORK OF VG SHAFT AFT BEARING SUPPORT	28-NOV-2002					
	Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORT HAS BEEN IDENTIFIED WITH THE "R" MARKING.).BY SERIAL NUMBER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0109 R1 Engine 1 SB - Open #285	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND REWORK OF VG SHAFT AFT BEARING SUPPORT						
SB 72-0109 R1 Engine 2 SB - Open #135	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND REWORK OF VG SHAFT AFT BEARING SUPPORT						
SB 72-0110 Engine 1 SB - Open #294	ENGINE - COMPRESSOR STATOR (72-32-00) - REPLACEMENT OF VG SHAFT AFT BEARING SUPPORT Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORT HAS BEEN IDENTIFIED WITH THE REWORK "R" MARKING. FOR EACH OF THE AFFECTED ENGINES IT IS RECOMMENDED THAT BOTH VG SHAFT AFT SUPPORTS BE REMOVED AND REPLACED AT THE NEXT SHOP VISIT AFTER RECEIPT OF THIS SERVICE BULLETIN.)						
SB 72-0110 Engine 2 SB - Open #438	ENGINE - COMPRESSOR STATOR (72-32-00) - REPLACEMENT OF VG SHAFT AFT BEARING SUPPORT Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORT HAS BEEN IDENTIFIED WITH THE REWORK "R" MARKING. FOR EACH OF THE AFFECTED ENGINES IT IS RECOMMENDED THAT BOTH VG SHAFT AFT SUPPORTS BE REMOVED AND REPLACED AT THE NEXT SHOP VISIT AFTER RECEIPT OF THIS SERVICE BULLETIN.)						
SB 72-0110 R1 Engine 1 SB - Open #104	ENGINE - COMPRESSOR STATOR (72-32-00) - REPLACEMENT OF VG SHAFT AFT BEARING SUPPORT						
SB 72-0110 R1 Engine 2 SB - Open #624	ENGINE - COMPRESSOR STATOR (72-32-00) - REPLACEMENT OF VG SHAFT AFT BEARING SUPPORT						
SB 72-0111 Engine 1 SB - N/A #462	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND TEMPORARY LOCTITE REWORK OF VG SHAFT AFT BEARING SUPPORT Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORTS AT BOTH THE 2:00 AND 8:00 VG SHAFT LOCATIONS HAVE BEEN IDENTIFIED WITH THE REWORK "R" MARKING.).BY SERIAL NUMBER	28-NOV-2002					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0111 Engine 2 SB - N/A #531	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND TEMPORARY LOCTITE REWORK OF VG SHAFT AFT BEARING SUPPORT	28-NOV-2002					
Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORTS AT BOTH THE 2:00 AND 8:00 VG SHAFT LOCATIONS HAVE BEEN IDENTIFIED WITH THE REWORK "R" MARKING.)BY SERIAL NUMBER							
SB 72-0111 R1 Engine 1 SB - Open #838	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND TEMPORARY LOCTITE REWORK OF VG SHAFT AFT BEARING SUPPORT						
Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORTS AT BOTH THE 2:00 AND 8:00 VG SHAFT LOCATIONS HAVE BEEN IDENTIFIED WITH THE REWORK "R" MARKING.)							
SB 72-0111 R1 Engine 2 SB - Open #492	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND TEMPORARY LOCTITE REWORK OF VG SHAFT AFT BEARING SUPPORT						
Notes (NOTE: THIS SERVICE BULLETIN IS NOT APPLICABLE TO CF34 TURBOFAN ENGINES WITH VG ACTUATOR SHAFT AFT BEARING SUPPORT PN 5024T65G03 IDENTIFIED WITH SUPPLIER CODE 56946 IF THE SUPPORTS AT BOTH THE 2:00 AND 8:00 VG SHAFT LOCATIONS HAVE BEEN IDENTIFIED WITH THE REWORK "R" MARKING.)							
SB 72-0111 R2 Engine 1 SB - N/A #643	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND TEMPORARY LOCTITE REWORK OF VG SHAFT AFT BEARING SUPPORT	13-SEP-2005					
Notes .BY ENGINE S/N							
SB 72-0111 R2 Engine 2 SB - N/A #66	ENGINE - COMPRESSOR STATOR (72-32-00) - INSPECTION AND TEMPORARY LOCTITE REWORK OF VG SHAFT AFT BEARING SUPPORT	13-SEP-2005					
Notes .BY ENGINE S/N							
SB 72-0112 Engine 1 SB - Open #42	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0112 Engine 2 SB - Open #264	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0112 R1 Engine 1 SB - Open #258	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0112 R1 Engine 2 SB - Open #248	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0113 Engine 1 SB - Open #818	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX INSPECTION AND MARKING AT OVERHAUL.						
SB 72-0113 Engine 2 SB - Open #816	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX INSPECTION AND MARKING AT OVERHAUL.						
SB 72-0113 R1 Engine 1 SB - Open #94	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX INSPECTION AND MARKING AT OVERHAUL.						
SB 72-0113 R1 Engine 2 SB - Open #120	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX INSPECTION AND MARKING AT OVERHAUL.						
SB 72-0114 Engine 1 SB - Open #636	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - STAGE 1 HPT BLADE BORESCOPE INSPECTION AND REPLACEMENT PLAN						
SB 72-0114 Engine 2 SB - Open #857	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - STAGE 1 HPT BLADE BORESCOPE INSPECTION AND REPLACEMENT PLAN						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0115 Engine 1 SB - Open #361	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0115 Engine 2 SB - Open #390	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0116 Engine 1 SB - Open #552	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0116 Engine 2 SB - Open #105	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0117 Engine 1 SB - Open #102	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - RE-IDENTIFICATION OF HPT ROTOR ASSEMBLY						
SB 72-0117 Engine 2 SB - Open #122	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - RE-IDENTIFICATION OF HPT ROTOR ASSEMBLY						
SB 72-0118 Engine 1 SB - Open #445	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN						
SB 72-0118 Engine 2 SB - Open #736	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0118 R1 Engine 1 SB - Open #807	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN Notes (NOTE: THIS SERVICE BULLETIN PROVIDES INSTRUCTIONS TO INSPECT ALL ACCESSORY GEARBOXES THAT ARE IN THE AFFECTED POPULATION. THIS SERVICE BULLETIN ALSO RECOMMENDS THE REMOVAL AND UPGRADE OF GEARBOXES IN THE AFFECTED POPULATION THAT SHOW WEAR ON THE AXIS -BB GEAR OR DISTRESS ON THE AXIS-P GEAR)						
SB 72-0118 R1 Engine 2 SB - Open #764	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN Notes (NOTE: THIS SERVICE BULLETIN PROVIDES INSTRUCTIONS TO INSPECT ALL ACCESSORY GEARBOXES THAT ARE IN THE AFFECTED POPULATION. THIS SERVICE BULLETIN ALSO RECOMMENDS THE REMOVAL AND UPGRADE OF GEARBOXES IN THE AFFECTED POPULATION THAT SHOW WEAR ON THE AXIS -BB GEAR OR DISTRESS ON THE AXIS-P GEAR)						
SB 72-0118 R2 Engine 1 SB - Open #343	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN Notes (AVG MAN HRS: 57)						
SB 72-0118 R2 Engine 2 SB - Open #755	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN Notes (AVG MAN HRS: 57)						
SB 72-0118 R3 Engine 1 SB - Open #450	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN Notes (AVG MAN HRS: 57) (NOTE: EFFECTIVITY: REFER TO PAR. 1.A. OF THIS SB FOR MORE INFORMATION. COMPLIANCE: GE RECOMMENDS YOU PERFORM A ONE-TIME BORESCOPE INSPECTION ON THE AFFECTED AGBS NOT EARLIER THAN 7,500 HOURS TSN AND NOT LATER THAN 10,000 HOURS TSN OR NOT LATER THAN 10,000 HOURS SINCE LAST AGB REPAIR. FOR AGBS THAT HAVE REACHED THE 10,000-HOUR THRESHOLD BY THE ISSUE DATE OF THIS SERVICE BULLETIN, AN INSPECTION AS DIRECTED BY THIS SERVICE BULLETIN, SHOULD BE PERFORMED WITHIN THE NEXT 500 HOURS FOLLOWING THE ISSUE DATE OF THIS SERVICE BULLETIN. GE RECOMMENDS THAT YOU GIVE PRIORITY TO AGBS THAT HAVE THE HIGHEST TIME. NOTE: FOR AGBS THAT DO NOT EXHIBIT AXIS-BB WEAR, NO FURTHER INSPECTION IS REC	17-OCT-1997 H: 0.00	H: 10000.00			H: 10000.00	H: 1304.90



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0118 R3 Engine 2 SB - Open #694	ENGINE - AGB ASSEMBLY (72-62-00) - ACCESSORY GEARBOX FIELD MANAGEMENT PLAN	15-OCT-1997 H: 0.00	H: 10000.00			H: 10000.00	H: 1304.90
Notes (AVG MAN HRS: 57) (NOTE: EFFECTIVITY: REFER TO PAR. 1.A. OF THIS SB FOR MORE INFORMATION. COMPLIANCE: GE RECOMMENDS YOU PERFORM A ONE-TIME BOREScope INSPECTION ON THE AFFECTED AGBS NOT EARLIER THAN 7,500 HOURS TSN AND NOT LATER THAN 10,000 HOURS TSN OR NOT LATER THAN 10,000 HOURS SINCE LAST AGB REPAIR. FOR AGBS THAT HAVE REACHED THE 10,000-HOUR THRESHOLD BY THE ISSUE DATE OF THIS SERVICE BULLETIN, AN INSPECTION AS DIRECTED BY THIS SERVICE BULLETIN, SHOULD BE PERFORMED WITHIN THE NEXT 500 HOURS FOLLOWING THE ISSUE DATE OF THIS SERVICE BULLETIN. GE RECOMMENDS THAT YOU GIVE PRIORITY TO AGBS THAT HAVE THE HIGHEST TIME. NOTE: FOR AGBS THAT DO NOT EXHIBIT AXIS-BB WEAR, NO FURTHER INSPECTION IS REC							
SB 72-0120 Engine 1 SB - Open #581	ENGINE - COMPRESSOR ROTOR COMPONENTS (72-33-00) - INTRODUCTION OF IMPROVED STAGES 3 AND 5 COMPRESSOR ROTOR LOCKING NUT HALVES						
SB 72-0120 Engine 2 SB - Open #332	ENGINE - COMPRESSOR ROTOR COMPONENTS (72-33-00) - INTRODUCTION OF IMPROVED STAGES 3 AND 5 COMPRESSOR ROTOR LOCKING NUT HALVES						
SB 72-0121 Engine 1 SB - Open #260	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0121 Engine 2 SB - Open #260	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0122 Engine 1 SB - Open #310	ENGINE - GENERAL (72-00-00) - NEW IDENTIFICATION PLATES PN 1022T98P02 AND PN 1023T19P02						
SB 72-0122 Engine 2 SB - Open #18	ENGINE - GENERAL (72-00-00) - NEW IDENTIFICATION PLATES PN 1022T98P02 AND PN 1023T19P02						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0122 R1 Engine 1 SB - Open #3	ENGINE - GENERAL (72-00-00) - NEW IDENTIFICATION PLATES PN 1022T98P02 AND PN 1023T19P02						
SB 72-0122 R1 Engine 2 SB - Open #513	ENGINE - GENERAL (72-00-00) - NEW IDENTIFICATION PLATES PN 1022T98P02 AND PN 1023T19P02						
SB 72-0123 Engine 1 SB - Open #607	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 Engine 2 SB - Open #525	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R1 Engine 1 SB - Open #469	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R1 Engine 2 SB - Open #394	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R2 Engine 1 SB - Open #397	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R2 Engine 2 SB - Open #852	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R3 Engine 1 SB - Open #231	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0123 R3 Engine 2 SB - Open #341	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R4 Engine 1 SB - Open #644	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0123 R4 Engine 2 SB - Open #836	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF FAN BLADE BUSHING REPAIR						
SB 72-0124 Engine 1 SB - Open #873	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0124 Engine 2 SB - Open #335	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0125 Engine 1 SB - Open #789	ENGINE - FAN ROTOR ASSEMBLY (72-33-00) - REWORK OF FAN BLADES PN 6018T30P06 AND PN 6018T30P13						
SB 72-0125 Engine 2 SB - Open #794	ENGINE - FAN ROTOR ASSEMBLY (72-33-00) - REWORK OF FAN BLADES PN 6018T30P06 AND PN 6018T30P13						
SB 72-0125 R1 Engine 1 SB - Open #241	ENGINE - FAN ROTOR ASSEMBLY (72-33-00) - REWORK OF FAN BLADES PN 6018T30P03 PN 6018T30P05 PN 6018T30P06 PN 6018T30P07 PN 6018T30P13 AND PN 5922T34P01						
SB 72-0125 R1 Engine 2 SB - Open #76	ENGINE - FAN ROTOR ASSEMBLY (72-33-00) - REWORK OF FAN BLADES PN 6018T30P03 PN 6018T30P05 PN 6018T30P06 PN 6018T30P07 PN 6018T30P13 AND PN 5922T34P01						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0125 R2 Engine 1 SB - Open #770	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REWORK OF FAN BLADES P/N 4923T56G02 P/N 4923T56G05 P/N 4923T56G07 P/N 4923T56G09 P/N 5922T34P01 P/N 6018T30P03 P/N 6018T30P06 AND P/N 6018T30P13						
SB 72-0125 R2 Engine 2 SB - Open #381	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REWORK OF FAN BLADES P/N 4923T56G02 P/N 4923T56G05 P/N 4923T56G07 P/N 4923T56G09 P/N 5922T34P01 P/N 6018T30P03 P/N 6018T30P06 AND P/N 6018T30P13						
SB 72-0126 Engine 1 SB - Open #174	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REWORK OF FAN CASE OUTER SPACERS AND INTRODUCTION OF A NEW AFT FAN CASE						
SB 72-0126 Engine 2 SB - Open #689	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REWORK OF FAN CASE OUTER SPACERS AND INTRODUCTION OF A NEW AFT FAN CASE						
SB 72-0126 R1 Engine 1 SB - Open #145	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REWORK OF FAN CASE OUTER SPACERS AND INTRODUCTION OF A NEW AFT FAN CASE						
SB 72-0126 R1 Engine 2 SB - Open #55	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REWORK OF FAN CASE OUTER SPACERS AND INTRODUCTION OF A NEW AFT FAN CASE						
SB 72-0127 Engine 1 SB - Open #30	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0127 Engine 2 SB - Open #868	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0127 R1 Engine 1 SB - Open #694	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0127 R1 Engine 2 SB - Open #643	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0128 Engine 1 SB - Open #370	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INTRODUCTION OF NEW STAGE 1 AND STAGE 2 COMPRESSOR SHROUD SEALS PN 5026T64G14 PN 5026T64G13 AND PN 5026T62G11						
SB 72-0128 Engine 2 SB - Open #579	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INTRODUCTION OF NEW STAGE 1 AND STAGE 2 COMPRESSOR SHROUD SEALS PN 5026T64G14 PN 5026T64G13 AND PN 5026T62G11						
SB 72-0128 R1 Engine 1 SB - Open #313	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INTRODUCTION OF NEW STAGE 1 AND STAGE 2 COMPRESSOR SHROUD SEALS PN 5026T64G14 PN 5026T64G13 AND PN 5026T62G11						
SB 72-0128 R1 Engine 2 SB - Open #29	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INTRODUCTION OF NEW STAGE 1 AND STAGE 2 COMPRESSOR SHROUD SEALS PN 5026T64G14 PN 5026T64G13 AND PN 5026T62G11						
SB 72-0129 Engine 1 SB - Open #511	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0129 Engine 2 SB - Open #157	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0129 R1 Engine 1 SB - Open #886	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0129 R1 Engine 2 SB - Open #865	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0129 R2 Engine 1 SB - Open #391	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0129 R2 Engine 2 SB - Open #932	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0130 Engine 1 SB - Open #701	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34 TURBOFAN ENGINES						
SB 72-0130 Engine 2 SB - Open #607	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34 TURBOFAN ENGINES						
SB 72-0131 Engine 1 SB - Open #461	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 Engine 2 SB - Open #283	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R1 Engine 1 SB - Open #117	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R1 Engine 2 SB - Open #680	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R2 Engine 1 SB - Open #498	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0131 R2 Engine 2 SB - Open #598	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R3 Engine 1 SB - Open #432	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R3 Engine 2 SB - Open #40	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R4 Engine 1 SB - Open #790	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0131 R4 Engine 2 SB - Open #585	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - REPLACEMENT OF THE FAN BLADE CASE FORWARD GANG CHANNEL NUT ASSEMBLIES						
SB 72-0132 Engine 1 SB - Open #255	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0132 Engine 2 SB - Open #663	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0133 Engine 1 SB - Open #908	ENGINE - AGB (72-62-00) - INTRODUCTION OF NEW O-RING PN 3035T70P06FOR CF34-3A1/-3B TURBOFAN ENGINE						
SB 72-0133 Engine 2 SB - Open #744	ENGINE - AGB (72-62-00) - INTRODUCTION OF NEW O-RING PN 3035T70P06FOR CF34-3A1/-3B TURBOFAN ENGINE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0133 R1 Engine 1 SB - Open #366	ENGINE - AGB (72-62-00) - INTRODUCTION OF NEW O-RING PN 3035T70P06 FOR CF34-3A1/-3B TURBOFAN ENGINE						
SB 72-0133 R1 Engine 2 SB - Open #741	ENGINE - AGB (72-62-00) - INTRODUCTION OF NEW O-RING PN 3035T70P06 FOR CF34-3A1/-3B TURBOFAN ENGINE						
SB 72-0134 Engine 1 SB - Open #296	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - CF34 COMPRESSOR VARIABLE VANE ACTUATING ARM WEAR AT THE COMPRESSOR SPLITLINE						
SB 72-0134 Engine 2 SB - Open #299	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - CF34 COMPRESSOR VARIABLE VANE ACTUATING ARM WEAR AT THE COMPRESSOR SPLITLINE						
SB 72-0134 R1 Engine 1 SB - Open #720	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - CF34 COMPRESSOR VARIABLE VANE ACTUATING ARM WEAR AT THE COMPRESSOR SPLITLINE		H: 10000.00			H: 10000.00	H: 1304.90
SB 72-0134 R1 Engine 2 SB - Open #864	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - CF34 COMPRESSOR VARIABLE VANE ACTUATING ARM WEAR AT THE COMPRESSOR SPLITLINE		H: 10000.00			H: 10000.00	H: 1304.90
SB 72-0135 Engine 1 SB - Open #373	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0135 Engine 2 SB - Open #289	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0137 Engine 1 SB - Open #218	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0137 Engine 2 SB - Open #809	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0138 Engine 1 SB - Open #863	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX(AGB) REWORK						
SB 72-0138 Engine 2 SB - Open #440	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX(AGB) REWORK						
SB 72-0138 R1 Engine 1 SB - Open #671	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R1 Engine 2 SB - Open #272	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R2 Engine 1 SB - Open #725	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R2 Engine 2 SB - Open #594	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R3 Engine 1 SB - Open #869	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R3 Engine 2 SB - Open #534	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0138 R4 Engine 1 SB - Open #512	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R4 Engine 2 SB - Open #62	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R5 Engine 1 SB - Open #88	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R5 Engine 2 SB - Open #612	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R6 Engine 1 SB - Open #647	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R6 Engine 2 SB - Open #144	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
SB 72-0138 R7 Engine 1 SB - Open #819	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
	Notes (NOTE: NOTE: THE ACCESSORY GEARBOX MODULE ASSEMBLY (AGB MODULE) P/N 6087T15G01 IS AFFECTED BY THIS SERVICE BULLETIN)						
SB 72-0138 R7 Engine 2 SB - Open #186	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) REWORK						
	Notes (NOTE: NOTE: THE ACCESSORY GEARBOX MODULE ASSEMBLY (AGB MODULE) P/N 6087T15G01 IS AFFECTED BY THIS SERVICE BULLETIN)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0139 Engine 1 SB - Open #315	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0139 Engine 2 SB - Open #343	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0141 Engine 1 SB - Open #778	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3BTURBOFAN ENGINES						
SB 72-0141 Engine 2 SB - Open #953	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3BTURBOFAN ENGINES						
SB 72-0141 R1 Engine 1 SB - Open #588	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0141 R1 Engine 2 SB - Open #150	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0142 Engine 1 SB - Open #332	ENGINE - COMPRESSOR ROTOR (72-33-00) - LIFE LIMITED STAGES 3 THRU 8COMPRESSOR ROTOR SPOOL PN 6078T56P05 PART INTRODUCTION						
SB 72-0142 Engine 2 SB - Open #406	ENGINE - COMPRESSOR ROTOR (72-33-00) - LIFE LIMITED STAGES 3 THRU 8COMPRESSOR ROTOR SPOOL PN 6078T56P05 PART INTRODUCTION						
SB 72-0142 R1 Engine 1 SB - Open #909	ENGINE - COMPRESSOR ROTOR (72-33-00) - LIFE LIMITED STAGES 3 THRU 8COMPRESSOR ROTOR SPOOL PN 6078T56P05 PART INTRODUCTION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0142 R1 Engine 2 SB - Open #826	ENGINE - COMPRESSOR ROTOR (72-33-00) - LIFE LIMITED STAGES 3 THRU 8COMPRESSOR ROTOR SPOOL PN 6078T56P05 PART INTRODUCTION						
SB 72-0142 R2 Engine 1 SB - Open #767	ENGINE - COMPRESSOR ROTOR (72-33-00) - LIFE LIMITED STAGES 3 THRU 8 COMPRESSOR ROTOR SPOOL PN 6078T56P05 PART INTRODUCTION						
SB 72-0142 R2 Engine 2 SB - Open #556	ENGINE - COMPRESSOR ROTOR (72-33-00) - LIFE LIMITED STAGES 3 THRU 8 COMPRESSOR ROTOR SPOOL PN 6078T56P05 PART INTRODUCTION						
SB 72-0143 Engine 1 SB - Open #791	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0143 Engine 2 SB - Open #153	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0144 Engine 1 SB - Open #123	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0144 Engine 2 SB - Open #540	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0145 Engine 1 SB - Open #618	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0145 Engine 2 SB - Open #263	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0145 R1 Engine 1 SB - Open #719	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0145 R1 Engine 2 SB - Open #909	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0147 Engine 1 SB - Open #751	ENGINE - COMPRESSOR STATOR (72-32-00) - REMOVAL OF INLET GUIDE VANE (IGV) AND STAGES 1 THROUGH 5 SELF-LOCKING NUT PN 4037T84P03 (NO LONGER VALID) Notes (NOTE: GE IS REQUESTING OPERATORS NOT TO COMPLY WITH THIS SERVICE BULLETIN)						
SB 72-0147 Engine 2 SB - Open #514	ENGINE - COMPRESSOR STATOR (72-32-00) - REMOVAL OF INLET GUIDE VANE (IGV) AND STAGES 1 THROUGH 5 SELF-LOCKING NUT PN 4037T84P03 (NO LONGER VALID) Notes (NOTE: GE IS REQUESTING OPERATORS NOT TO COMPLY WITH THIS SERVICE BULLETIN)						
SB 72-0147 R1 Engine 1 SB - Open #942	ENGINE - COMPRESSOR STATOR (72-32-00) - REMOVAL OF INLET GUIDE VANE (IGV) AND STAGES 1 THROUGH 5 SELF-LOCKING NUT PN 4037T84P03 (NO LONGER VALID) Notes (NOTE: GE IS REQUESTING OPERATORS NOT TO COMPLY WITH THIS SERVICE BULLETIN)						
SB 72-0147 R1 Engine 2 SB - Open #129	ENGINE - COMPRESSOR STATOR (72-32-00) - REMOVAL OF INLET GUIDE VANE (IGV) AND STAGES 1 THROUGH 5 SELF-LOCKING NUT PN 4037T84P03 (NO LONGER VALID) Notes (NOTE: GE IS REQUESTING OPERATORS NOT TO COMPLY WITH THIS SERVICE BULLETIN)						
SB 72-0149 Engine 1 SB - Open #729	ENGINE - HPC (72-33-00) - STAGES 3 THROUGH 8 COMPRESSOR ROTOR SPOOL PART NUMBER MARKING INSPECTION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0149 Engine 2 SB - Open #746	ENGINE - HPC (72-33-00) - STAGES 3 THROUGH 8 COMPRESSOR ROTOR SPOOL PART NUMBER MARKING INSPECTION						
SB 72-0150 Engine 1 SB - Open #483	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0150 Engine 2 SB - Open #937	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0151 Engine 1 SB - Open #342	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0151 Engine 2 SB - Open #322	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0153 Engine 1 SB - Open #105	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF STAGE 2 TURBINE SHROUD AND SEAL SEGMENT PN 6047T95G14 (20 PIECE CONFIGURATION)						
SB 72-0153 Engine 2 SB - Open #701	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF STAGE 2 TURBINE SHROUD AND SEAL SEGMENT PN 6047T95G14 (20 PIECE CONFIGURATION)						
SB 72-0153 R1 Engine 1 SB - Open #293	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF STAGE 2 TURBINE SHROUD AND SEAL SEGMENT PN 6047T95G14 (20 PIECE CONFIGURATION)						
SB 72-0153 R1 Engine 2 SB - Open #461	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF STAGE 2 TURBINE SHROUD AND SEAL SEGMENT PN 6047T95G14 (20 PIECE CONFIGURATION)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0154 Engine 1 SB - Open #433	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF REWORKED STAGE 2 HPT STATOR SHROUD PN 5099T09P02 (18 PIECE CONFIGURATION)						
SB 72-0154 Engine 2 SB - Open #908	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF REWORKED STAGE 2 HPT STATOR SHROUD PN 5099T09P02 (18 PIECE CONFIGURATION)						
SB 72-0155 Engine 1 SB - Open #380	ENGINE - COMPRESSOR ROTOR (72-33-00) INTRODUCTION OF VENDOR CODES FOR STAGES 10-14 COMPRESSOR ROTOR BLADES						
SB 72-0155 Engine 2 SB - Open #801	ENGINE - COMPRESSOR ROTOR (72-33-00) INTRODUCTION OF VENDOR CODES FOR STAGES 10-14 COMPRESSOR ROTOR BLADES						
SB 72-0156 Engine 1 SB - Open #658	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0156 Engine 2 SB - Open #676	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0157 Engine 1 SB - N/A #947	ENGINE - COMPRESSOR STATOR (72-32-00) - STAGES IGV THRU 5 SELF-LOCKING NUT FIELD INSPECTION						
	Notes .SUPERSEDED						
SB 72-0157 Engine 2 SB - N/A #221	ENGINE - COMPRESSOR STATOR (72-32-00) - STAGES IGV THRU 5 SELF-LOCKING NUT FIELD INSPECTION						
	Notes .SUPERSEDED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0157 R1 Engine 1 SB - N/A #626	ENGINE - COMPRESSOR STATOR (72-32-00) - STAGES IGV THRU 5 SELF-LOCKING NUT FIELD INSPECTION Notes .SUPERSEDED						
SB 72-0157 R1 Engine 2 SB - N/A #506	ENGINE - COMPRESSOR STATOR (72-32-00) - STAGES IGV THRU 5 SELF-LOCKING NUT FIELD INSPECTION Notes .SUPERSEDED						
SB 72-0157 R2 Engine 1 SB - Complied With #949	ENGINE - COMPRESSOR STATOR (72-32-00) - STAGES IGV THRU 5 SELF-LOCKING NUT FIELD INSPECTION Notes (NOTE: GE RECOMMENDS THAT ALL ENGINES THAT HAVE REUSED STAGES IGV THRU 5 SELF-LOCKING NUTS, WITH A SINGLE TAB ENGAGED ON THE TAB WASHER BE INSPECTED WITHIN 4,000 FLIGHT HOURS TIME SINCE OVERHAUL (TSO).)			02-DEC-2011 H: 4383.90 C: 1887			
SB 72-0157 R2 Engine 2 SB - Complied With #349	ENGINE - COMPRESSOR STATOR (72-32-00) - STAGES IGV THRU 5 SELF-LOCKING NUT FIELD INSPECTION Notes (NOTE: GE RECOMMENDS THAT ALL ENGINES THAT HAVE REUSED STAGES IGV THRU 5 SELF-LOCKING NUTS, WITH A SINGLE TAB ENGAGED ON THE TAB WASHER BE INSPECTED WITHIN 4,000 FLIGHT HOURS TIME SINCE OVERHAUL (TSO).)			02-DEC-2011 H: 4383.90 C: 1887			
SB 72-0158 R1 Engine 1 SB - Open #305	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - INTRODUCTION OF NEW LPT TURBINE SEALS PN 5023T59P06 PN 5023T67P02 AND PN 5023T64P04						
SB 72-0158 R1 Engine 2 SB - Open #539	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - INTRODUCTION OF NEW LPT TURBINE SEALS PN 5023T59P06 PN 5023T67P02 AND PN 5023T64P04						
SB 72-0159 Engine 1 SB - Open #188	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0159 Engine 2 SB - Open #645	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-0160 Engine 1 SB - Open #135	ENGINE ~ LOW PRESSURE TURBINE ROTOR (72-53-00) - LIFE LIMITED LOW PRESSURE TURBINE DISKS STAGES 3 THRU 6 PN 6078T91P02 PN 6078T02P04 PN 6078T92P02 AND PN 6078T89P03 PARTS INTRODUCTION.						
SB 72-0160 Engine 2 SB - Open #162	ENGINE ~ LOW PRESSURE TURBINE ROTOR (72-53-00) - LIFE LIMITED LOW PRESSURE TURBINE DISKS STAGES 3 THRU 6 PN 6078T91P02 PN 6078T02P04 PN 6078T92P02 AND PN 6078T89P03 PARTS INTRODUCTION.						
SB 72-0160 R1 Engine 1 SB - Open #813	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - LIFE LIMITED LOW PRESSURE TURBINE DISKS STAGES 3 THRU 6 PN 6078T91P02 PN 6078T02P04 PN 6078T92P02 AND PN 6078T89P03 PARTS INTRODUCTION.						
SB 72-0160 R1 Engine 2 SB - Open #771	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - LIFE LIMITED LOW PRESSURE TURBINE DISKS STAGES 3 THRU 6 PN 6078T91P02 PN 6078T02P04 PN 6078T92P02 AND PN 6078T89P03 PARTS INTRODUCTION.						
SB 72-0162 Engine 1 SB - Open #284	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF REWORKED STAGE 1 HIGH PRESSURE TURBINE SEAL SHROUD SEGMENTS PN 5902T32G01						
SB 72-0162 Engine 2 SB - Open #649	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF REWORKED STAGE 1 HIGH PRESSURE TURBINE SEAL SHROUD SEGMENTS PN 5902T32G01						
SB 72-0163 Engine 1 SB - Open #726	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 Engine 2 SB - Open #447	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0163 R1 Engine 1 SB - Open #286	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R1 Engine 2 SB - Open #34	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R2 Engine 1 SB - Open #875	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R2 Engine 2 SB - Open #778	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R3 Engine 1 SB - Open #242	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R3 Engine 2 SB - Open #774	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R4 Engine 1 SB - Open #582	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R4 Engine 2 SB - Open #89	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R5 Engine 1 SB - Open #250	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0163 R5 Engine 2 SB - Open #213	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R6 Engine 1 SB - Open #85	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R6 Engine 2 SB - Open #692	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R7 Engine 1 SB - Open #48	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R7 Engine 2 SB - Open #325	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
SB 72-0163 R8 Engine 1 SB - Open #508	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
	Notes .OPEN						
SB 72-0163 R8 Engine 2 SB - Open #662	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY - (72-64-00) - INTRODUCTION OF PTO DRIVE ASSEMBLY PN 6037T72G19 AND FRONT FRAME-TO-PTO OIL TUBE ASSEMBLY PN 6012T90G02						
	Notes .OPEN						
SB 72-0164 Engine 1 SB - Open #184	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0164 Engine 2 SB - Open #841	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0165 Engine 1 SB - Open #745	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0165 Engine 2 SB - Open #479	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0166 Engine 1 SB - Open #806	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF DESTRUCTIVE EVALUATION METHOD FOR STAGE 1 HIGH PRESSURE TURBINE BLADES						
SB 72-0166 Engine 2 SB - Open #899	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF DESTRUCTIVE EVALUATION METHOD FOR STAGE 1 HIGH PRESSURE TURBINE BLADES						
SB 72-0166 R1 Engine 1 SB - Open #556	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF DESTRUCTIVE EVALUATION METHOD FOR STAGE 1 HIGH PRESSURE TURBINE BLADES						
SB 72-0166 R1 Engine 2 SB - Open #600	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF DESTRUCTIVE EVALUATION METHOD FOR STAGE 1 HIGH PRESSURE TURBINE BLADES						
SB 72-0167 Engine 1 SB - Open #308	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF AN EVALUATION METHOD FOR STAGE 2 HIGH PRESSURE TURBINE BLADES						
SB 72-0167 Engine 2 SB - Open #656	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - INTRODUCTION OF AN EVALUATION METHOD FOR STAGE 2 HIGH PRESSURE TURBINE BLADES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0168 Engine 1 SB - Open #846	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - REWORK OF STAGE 1 HIGH PRESSURE TURBINE BLADES						
SB 72-0168 Engine 2 SB - Open #762	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - REWORK OF STAGE 1 HIGH PRESSURE TURBINE BLADES						
SB 72-0169 Engine 1 SB - Open #602	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - REWORK OF STAGE 2 HIGH PRESSURE TURBINE BLADES						
SB 72-0169 Engine 2 SB - Open #36	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - REWORK OF STAGE 2 HIGH PRESSURE TURBINE BLADES						
SB 72-0170 Engine 1 SB - Open #927	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0170 Engine 2 SB - Open #541	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0171 Engine 1 SB - Open #504	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - INTRODUCTION OF NEW NO. 1 AND 2 BEARING HOUSING ASSEMBLY PN 6047T69G04						
SB 72-0171 Engine 2 SB - Open #711	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - INTRODUCTION OF NEW NO. 1 AND 2 BEARING HOUSING ASSEMBLY PN 6047T69G04						
SB 72-0171 R1 Engine 1 SB - Open #329	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - INTRODUCTION OF NEW NO. 1 AND 2 BEARING HOUSING ASSEMBLY PN 6047T69G04						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0171 R1 Engine 2 SB - Open #611	ENGINE - FAN STATOR ASSEMBLY (72-23-00) - INTRODUCTION OF NEW NO. 1 AND 2 BEARING HOUSING ASSEMBLY PN 6047T69G04						
SB 72-0173 Engine 1 SB - Open #283	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0173 Engine 2 SB - Open #724	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0176 Engine 1 SB - Open #685	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 Engine 2 SB - Open #278	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 R1 Engine 1 SB - Open #457	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 R1 Engine 2 SB - Open #765	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 R2 Engine 1 SB - Open #442	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 R2 Engine 2 SB - Open #564	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0176 R3 Engine 1 SB - Open #86	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 R3 Engine 2 SB - Open #900	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05						
SB 72-0176 R4 Engine 1 SB - Complied With #623	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05					12-OCT-2009 H: 3725.60 C: 1574	
SB 72-0176 R4 Engine 2 SB - Complied With #919	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF NO. 5 ROLLER BEARINGS PN 5042T13P04 PN 5042T13P05 PN 5022T87P04 AND PN 5022T87P05					12-OCT-2009 H: 3725.60 C: 1574	
SB 72-0177 Engine 1 SB - Open #589	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0177 Engine 2 SB - Open #519	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0178 Engine 1 SB - Open #228	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AXIS-L SPUR GEARSHAFT PN 5019T38P04 - INSPECTION						
SB 72-0178 Engine 2 SB - Open #70	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AXIS-L SPUR GEARSHAFT PN 5019T38P04 - INSPECTION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0179 Engine 1 SB - Open #761	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 Engine 2 SB - Open #532	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R1 Engine 1 SB - Open #193	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R1 Engine 2 SB - Open #920	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0179 R2 Engine 1 SB - Open #738	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R2 Engine 2 SB - Open #658	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R3 Engine 1 SB - Open #428	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R3 Engine 2 SB - Open #699	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0179 R4 Engine 1 SB - Open #291	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R4 Engine 2 SB - Open #678	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R5 Engine 1 SB - Open #521	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R5 Engine 2 SB - Open #159	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD PN 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0179 R6 Engine 1 SB - Open #330	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R6 Engine 2 SB - Open #880	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.)						
SB 72-0179 R7 Engine 1 SB - Open #617	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.).CATEGORY 3 - DO AT NEXT SHOP VISIT OF ENGINE						
SB 72-0179 R7 Engine 2 SB - Open #225	ENGINE - COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF A NEW REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 Notes (NOTE: FOR CF34-3B ENGINES: CATEGORY 3 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 AT NEXT ENGINE SHOP VISIT. FOR CF34-1A AND CF34-3A ENGINES: CATEGORY 5 GE RECOMMENDS THAT THE IGV INNER SUPPORT SHROUD P/N 5026T65G05 BE REPLACED WITH THE REDESIGNED IGV INNER SUPPORT SHROUD P/N 5026T65G06 WHEN THE PART IS REMOVED FROM THE ENGINE.).CATEGORY 3 - DO AT NEXT SHOP VISIT OF ENGINE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0180 Engine 1 SB - Open #606	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF STAGE 1 TURBINE NOZZLE WITH ALUMINIDE COATING STAGE 1 TURBINE NOZZLE SEGMENTS HPT STATOR ASSEMBLY TURBINE SEGMENT SEALS AND STAGE 2 FLOWMETER WASHER						
SB 72-0180 Engine 2 SB - Open #835	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF STAGE 1 TURBINE NOZZLE WITH ALUMINIDE COATING STAGE 1 TURBINE NOZZLE SEGMENTS HPT STATOR ASSEMBLY TURBINE SEGMENT SEALS AND STAGE 2 FLOWMETER WASHER						
SB 72-0180 R1 Engine 1 SB - Open #637	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 1 HP TURBINE NOZZLE SEGMENTS						
SB 72-0180 R1 Engine 2 SB - Open #271	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 1 HP TURBINE NOZZLE SEGMENTS						
SB 72-0181 Engine 1 SB - Open #663	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF STAGE 1 HPT STATOR SHROUDS PN 4124T42P16 HPT STATOR SHROUD HANGERS PN 5099T05G12 AND TURBINE SEGMENT SEALS PN 5099T21P39						
SB 72-0181 Engine 2 SB - Open #320	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF STAGE 1 HPT STATOR SHROUDS PN 4124T42P16 HPT STATOR SHROUD HANGERS PN 5099T05G12 AND TURBINE SEGMENT SEALS PN 5099T21P39						
SB 72-0181 R1 Engine 1 SB - Open #900	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS AND SEGMENT SEALS						
SB 72-0181 R1 Engine 2 SB - Open #750	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS AND SEGMENT SEALS						
SB 72-0181 R2 Engine 1 SB - Open #257	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS AND REWORKED HPT STATOR SHROUD HANGERS PNS 4923T61G01 G02 G03 G04						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0181 R2 Engine 2 SB - Open #902	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS AND REWORKED HPT STATOR SHROUD HANGERS PNS 4923T61G01 G02 G03 G04						
SB 72-0181 R3 Engine 1 SB - Open #665	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS						
SB 72-0181 R3 Engine 2 SB - Open #317	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS						
SB 72-0181 R4 Engine 1 SB - Open #800	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS						
SB 72-0181 R4 Engine 2 SB - Open #1	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS						
SB 72-0181 R5 Engine 1 SB - Open #827	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS						
SB 72-0181 R5 Engine 2 SB - Open #587	ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - INTRODUCTION OF N2 ALLOY STAGE 1 HP TURBINE SHROUDS SHROUD HANGERS SEGMENT SEALS						
SB 72-0182 Engine 1 SB - Open #420	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0182 Engine 2 SB - Open #691	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0182 R1 Engine 1 SB - Open #616	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0182 R1 Engine 2 SB - Open #252	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0182 R2 Engine 1 SB - Open #620	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0182 R2 Engine 2 SB - Open #292	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0182 R3 Engine 1 SB - Open #899	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0182 R3 Engine 2 SB - Open #285	ENGINE - COMBUSTION LINER ASSEMBLY (72-41-00) - COMBUSTION LINER FIELD MODIFICATION AND REPAIR CONFIGURATION						
SB 72-0183 Engine 1 SB - Open #826	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF REWORKED FRONT-OIL COOLER BRACKET PN 4159T34G01 AND FUEL-OIL COOLER TUBE TO FUEL FILTER PN 5085T60G02						
SB 72-0183 Engine 2 SB - Open #559	ENGINE - GENERAL (72-00-00) - INTRODUCTION OF REWORKED FRONT-OIL COOLER BRACKET PN 4159T34G01 AND FUEL-OIL COOLER TUBE TO FUEL FILTER PN 5085T60G02						
SB 72-0184 Engine 1 SB - Open #901	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0184 Engine 2 SB - Open #938	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0184 R1 Engine 1 SB - Open #148	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0184 R1 Engine 2 SB - Open #640	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0185 Engine 1 SB - Open #247	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - INTRODUCTION OF REWORKED B-SUMP HOUSING PN 4923T00G01						
SB 72-0185 Engine 2 SB - Open #205	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP ASSEMBLY (72-41-00) - INTRODUCTION OF REWORKED B-SUMP HOUSING PN 4923T00G01						
SB 72-0186 Engine 1 SB - Open #562	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-0186 Engine 2 SB - Open #215	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-0187 Engine 1 SB - Open #128	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS SEALS AND FLOWMETER WASHERS						
SB 72-0187 Engine 2 SB - Open #238	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS SEALS AND FLOWMETER WASHERS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0187 R1 Engine 1 SB - Open #454	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS SEALS AND FLOWMETER WASHERS						
SB 72-0187 R1 Engine 2 SB - Open #20	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS SEALS AND FLOWMETER WASHERS						
SB 72-0187 R2 Engine 1 SB - Open #9	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS SEALS AND FLOWMETER WASHERS						
SB 72-0187 R2 Engine 2 SB - Open #665	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS SEALS AND FLOWMETER WASHERS						
SB 72-0187 R3 Engine 1 SB - Open #574	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS, SEALS, AND FLOWMETER WASHERS Notes (NOTE: CONCURRENT REQUIREMENTS: CF34-BJ S/B 72-0083, ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - REWORK OF HPT STATOR ASSEMBLY AND INTRODUCTION OF IMPROVED DURABILITY STAGE 2 HPT NOZZLE AND HPT INNER CASE AND SPLINE SEALS.)						
SB 72-0187 R3 Engine 2 SB - Open #739	ENGINE - HPT MODULE (72-00-03) - INTRODUCTION OF N5 ALLOY STAGE 2 HP TURBINE NOZZLE SEGMENTS, SEALS, AND FLOWMETER WASHERS Notes (NOTE: CONCURRENT REQUIREMENTS: CF34-BJ S/B 72-0083, ENGINE - HIGH PRESSURE TURBINE STATOR (72-45-00) - REWORK OF HPT STATOR ASSEMBLY AND INTRODUCTION OF IMPROVED DURABILITY STAGE 2 HPT NOZZLE AND HPT INNER CASE AND SPLINE SEALS.)						
SB 72-0188 Engine 1 SB - Open #269	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0188 Engine 2 SB - Open #761	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0189 Engine 1 SB - Open #23	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0189 Engine 2 SB - Open #134	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0189 R1 Engine 1 SB - Open #460	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0189 R1 Engine 2 SB - Open #890	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0190 Engine 1 SB - Open #707	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 5018T49P05 5016T32P05 AND 4138T09P03						
SB 72-0190 Engine 2 SB - Open #432	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 5018T49P05 5016T32P05 AND 4138T09P03						
SB 72-0190 R1 Engine 1 SB - Open #631	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 4138T09P02 4138T09P03 5016T32P05 5016T32P06 5018T48P04 5018T48P05 5018T49P05 AND 5018T49P06						
SB 72-0190 R1 Engine 2 SB - Open #423	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 4138T09P02 4138T09P03 5016T32P05 5016T32P06 5018T48P04 5018T48P05 5018T49P05 AND 5018T49P06						
SB 72-0190 R2 Engine 1 SB - Open #675	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 4138T09P02 4138T09P03 5016T32P05 5016T32P06 5018T48P04 5018T48P05 5018T49P05 AND 5018T49P06						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0190 R2 Engine 2 SB - Open #191	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 4138T09P02 4138T09P03 5016T32P05 5016T32P06 5018T48P04 5018T48P05 5018T49P05 AND 5018T49P06						
SB 72-0190 R3 Engine 1 SB - Open #69	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 4138T09P02 4138T09P03 5016T32P05 5016T32P06 5018T48P04 5018T48P05 5018T49P05 AND 5018T49P06						
SB 72-0190 R3 Engine 2 SB - Open #617	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - INTRODUCTION OF AGB CARBON SEALS PNS 4138T09P02 4138T09P03 5016T32P05 5016T32P06 5018T48P04 5018T48P05 5018T49P05 AND 5018T49P06						
SB 72-0191 Engine 1 SB - Open #274	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-0191 Engine 2 SB - Open #8	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-0192 Engine 1 SB - Open #779	ENGINE - COMBUSTION SECTION (72-41-00) - INTRODUCTION OF STAGE 1 TURBINE NOZZLE SEGMENT AIRFOIL REPLACEMENT REPAIR						
SB 72-0192 Engine 2 SB - Open #860	ENGINE - COMBUSTION SECTION (72-41-00) - INTRODUCTION OF STAGE 1 TURBINE NOZZLE SEGMENT AIRFOIL REPLACEMENT REPAIR						
SB 72-0193 Engine 1 SB - Open #802	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION OF HPC STAGE 2 VG TURNBUCKLES						
SB 72-0193 Engine 2 SB - Open #843	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION OF HPC STAGE 2 VG TURNBUCKLES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0194 Engine 1 SB - Open #248	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - REPLACEMENT OF SWIRLER ASSEMBLY PN 5071T48G01						
SB 72-0194 Engine 2 SB - Open #242	ENGINE - COMBUSTION LINER AND STAGE 1 NOZZLE (72-42-00) - REPLACEMENT OF SWIRLER ASSEMBLY PN 5071T48G01						
SB 72-0196 Engine 1 SB - Open #49	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0196 Engine 2 SB - Open #578	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0197 Engine 1 SB - Open #669	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAIN RING PN AS3217-127						
SB 72-0197 Engine 2 SB - Open #620	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAIN RING PN AS3217-127						
SB 72-0197 R1 Engine 1 SB - Open #601	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAIN RING PN AS3217-127						
SB 72-0197 R1 Engine 2 SB - Open #169	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAIN RING PN AS3217-127						
SB 72-0197 R2 Engine 1 SB - Open #473	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAIN RING PN AS3217-127						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0197 R2 Engine 2 SB - Open #318	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAIN RING PN AS3217-127						
SB 72-0197 R3 Engine 1 SB - Complied With #13	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAINER RING PN AS3217-127		02-OCT-2009 H: 3725.60 C: 1574				
SB 72-0197 R3 Engine 2 SB - Complied With #415	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAINER RING PN AS3217-127		02-OCT-2009 H: 3725.60 C: 1574				
SB 72-0197 R4 Engine 1 SB - Open #946	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAINER RING PN AS3217-127						
SB 72-0197 R4 Engine 2 SB - Open #769	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAINER RING PN AS3217-127						
SB 72-0197 R5 Engine 1 SB - Open #834	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAINER RING PN AS3217-127						
SB 72-0197 R5 Engine 2 SB - Open #298	ENGINE - ACCESSORY DRIVE SECTION (72-62-00) - INTRODUCTION OF IMPROVED ACCESSORY GEAR BOX AXIS K CRANKING PLUG PN 4189T24G01 AND RETAINER RING PN AS3217-127						
SB 72-0198 Engine 1 SB - Open #423	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0198 Engine 2 SB - Open #453	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0201 Engine 1 SB - Open #31	ENGINE - (72-42-00) - REWORK OF THE STAGE 1 HPT NOZZLE SUPPORT						
SB 72-0201 Engine 2 SB - Open #165	ENGINE - (72-42-00) - REWORK OF THE STAGE 1 HPT NOZZLE SUPPORT						
SB 72-0201 R1 Engine 1 SB - Open #798	ENGINE - (72-42-00) - REWORK OF THE STAGE 1 HPT NOZZLE SUPPORT						
SB 72-0201 R1 Engine 2 SB - Open #469	ENGINE - (72-42-00) - REWORK OF THE STAGE 1 HPT NOZZLE SUPPORT						
SB 72-0202 Engine 1 SB - Open #527	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 Engine 2 SB - Open #505	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R1 Engine 1 SB - Open #710	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R1 Engine 2 SB - Open #783	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R2 Engine 1 SB - Complied With #597	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS					19-OCT-2009 H: 3725.60 C: 1574	



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0202 R2 Engine 2 SB - Complied With #100	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS	19-OCT-2009 H: 3725.60 C: 1574					
SB 72-0202 R3 Engine 1 SB - Open #435	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R3 Engine 2 SB - Open #830	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R4 Engine 1 SB - Open #161	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R4 Engine 2 SB - Open #740	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
SB 72-0202 R5 Engine 1 SB - Open #850	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
	Notes (NOTE: NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO THE CF34 TURBOFAN ENGINES CONTAINING THE FOLLOWING LOW PRESSURE TURBINE (LPT) MODULES: •CF34-3B LPT MODULE, SERIAL NUMBERS GED872001 AND UP. •CF34-3B LPT MODULE, SERIAL NUMBERS GED873001 AND UP. •CF34-3B LPT MODULE, SERIAL NUMBERS GED950001 AND UP.)						
SB 72-0202 R5 Engine 2 SB - Open #557	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3B ENGINE MODELS						
	Notes (NOTE: NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO THE CF34 TURBOFAN ENGINES CONTAINING THE FOLLOWING LOW PRESSURE TURBINE (LPT) MODULES: •CF34-3B LPT MODULE, SERIAL NUMBERS GED872001 AND UP. •CF34-3B LPT MODULE, SERIAL NUMBERS GED873001 AND UP. •CF34-3B LPT MODULE, SERIAL NUMBERS GED950001 AND UP.)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0203 Engine 1 SB - Open #319	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3A1 ENGINE MODELS						
SB 72-0203 Engine 2 SB - Open #838	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3A1 ENGINE MODELS						
SB 72-0203 R1 Engine 1 SB - Open #759	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3A1 ENGINE MODELS						
SB 72-0203 R1 Engine 2 SB - Open #725	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3A1 ENGINE MODELS						
SB 72-0203 R2 Engine 1 SB - Open #657	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3A1 ENGINE MODELS						
SB 72-0203 R2 Engine 2 SB - Open #445	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 FOR CF34-3A1 ENGINE MODELS						
SB 72-0203 R3 Engine 1 SB - Open #33	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 PN 6020T00G04 AND PN 6020T00G06 FOR USE ON CF34-1A/-3A/-3A2/-3A1 ENGINE MODELS.						
SB 72-0203 R3 Engine 2 SB - Open #914	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF STAGE 3 SHROUD SECTOR PN 5099T32G02 PN 6020T00G04 AND PN 6020T00G06 FOR USE ON CF34-1A/-3A/-3A2/-3A1 ENGINE MODELS.						
SB 72-0205 Engine 1 SB - Open #137	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0205 Engine 2 SB - Open #851	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0205 R1 Engine 1 SB - Open #776	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0205 R1 Engine 2 SB - Open #494	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0205 R2 Engine 1 SB - Open #244	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0205 R2 Engine 2 SB - Open #931	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0206 Engine 1 SB - Open #467	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF ALTERNATE BLIND RIVETS TO REPLACE AFT FLANGE GANG CHANNELS						
SB 72-0206 Engine 2 SB - Open #546	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF ALTERNATE BLIND RIVETS TO REPLACE AFT FLANGE GANG CHANNELS						
SB 72-0206 R1 Engine 1 SB - Open #667	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF ALTERNATE BLIND RIVETS TO REPLACE AFT FLANGE GANG CHANNELS						
SB 72-0206 R1 Engine 2 SB - Open #279	ENGINE - HIGH PRESSURE TURBINE STATOR ASSEMBLY (72-45-00) - INTRODUCTION OF ALTERNATE BLIND RIVETS TO REPLACE AFT FLANGE GANG CHANNELS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0207 Engine 1 SB - Open #376	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0207 Engine 2 SB - Open #752	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0209 Engine 1 SB - Open #59	ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN Notes (NOTE: GE RECOMMENDS IF THE ENGINE IS OVER 18,000 CYCLES TO REPLACE WITH THE NEW FAN BLADE RETAINING PINS AT THE NEXT SHOP VISIT.).REC IF ENGINE OVER 18000 CYC TO REPLACE FAN BLADE RETAINING PINS AT NEXT SHOP VISIT						
SB 72-0209 Engine 2 SB - Open #442	ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN Notes (NOTE: GE RECOMMENDS IF THE ENGINE IS OVER 18,000 CYCLES TO REPLACE WITH THE NEW FAN BLADE RETAINING PINS AT THE NEXT SHOP VISIT.).REC IF ENGINE OVER 18000 CYC TO REPLACE FAN BLADE RETAINING PINS AT NEXT SHOP VISIT						
SB 72-0209 R1 (2) Engine 1 SB - Open #150	Par. C ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN - INSPECT						
SB 72-0209 R1 (2) Engine 2 SB - Open #435	Par. C ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN - INSPECT						
SB 72-0209 R1 (1) Engine 1 SB - Open #933	Par. C ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN - REPLACE Notes (AVG MAN HRS: 4)		C: 18000			C: 18000.00	C: 13997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0209 R1 Par. C (1) Engine 2 SB - Open #697	ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN - REPLACE Notes (AVG MAN HRS: 4)		C: 18000			C: 18000.00	C: 13997
SB 72-0209 R1 Engine 1 SB - Open #906	ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN - REPLACE/ INSPECT						
SB 72-0209 R1 Engine 2 SB - Open #911	ENGINE - FAN ROTOR (72-21-00) - INTRODUCTION OF A REDESIGNED FAN BLADE RETAINING PIN - REPLACE/ INSPECT Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-1A/3A/3A1/3A2/3B ENGINES. THIS SERVICE BULLETIN HAS BEEN INTRODUCED IN PRODUCTION TO THESE CF34-BJ ENGINES: *CF34-BJ ENGINES, SERIAL NUMBERS 950606 AND UP. THE FAN BLADE RETAINING PINS PN 4029T16P01, PN 4029T16P03, PN 4029T16P04, PN 4029T16P06, PN 4029T16P13, AND PN 4029T16P15 ARE AFFECTED BY THIS SERVICE BULLETIN.)						
SB 72-0210 Engine 1 SB - Open #930	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0210 Engine 2 SB - Open #90	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0214 Engine 1 SB - Open #708	ENGINE - FAN ROTOR ASSEMBLY AND COMPONENTS (72-21-00) - INTRODUCTION OF SPIRAL PAINTING TO THE FORWARD OUTER SPINNER Notes .OPEN						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0214 Engine 2 SB - Open #674	ENGINE - FAN ROTOR ASSEMBLY AND COMPONENTS (72-21-00) - INTRODUCTION OF SPIRAL PAINTING TO THE FORWARD OUTER SPINNER Notes .OPEN						
SB 72-0215 Engine 1 SB - Open #25	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (NOTE: INSPECTION RECOMMENDED ANYTIME FAN BLADES ARE IN FOR SHOP VISIT, PROVIDED BLADES HAVE BEEN IN SERVICE 3,000 CYCLES OR MORE SINCE PRIOR SHOP VISIT INSPECTION.)						
SB 72-0215 Engine 2 SB - Open #377	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (NOTE: INSPECTION RECOMMENDED ANYTIME FAN BLADES ARE IN FOR SHOP VISIT, PROVIDED BLADES HAVE BEEN IN SERVICE 3,000 CYCLES OR MORE SINCE PRIOR SHOP VISIT INSPECTION.)						
SB 72-0215 R1 Engine 1 SB - Open #36	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (NOTE: INSPECTION RECOMMENDED ANYTIME FAN BLADES ARE IN FOR SHOP VISIT, PROVIDED BLADES HAVE BEEN IN SERVICE 3,000 CYCLES OR MORE SINCE PRIOR SHOP VISIT INSPECTION.)						
SB 72-0215 R1 Engine 2 SB - Open #698	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (NOTE: INSPECTION RECOMMENDED ANYTIME FAN BLADES ARE IN FOR SHOP VISIT, PROVIDED BLADES HAVE BEEN IN SERVICE 3,000 CYCLES OR MORE SINCE PRIOR SHOP VISIT INSPECTION.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0215 R2 Engine 1 SB - N/A #444	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (NOTE: INSPECTION RECOMMENDED ANYTIME FAN BLADES ARE IN FOR SHOP VISIT, PROVIDED BLADES HAVE BEEN IN SERVICE 3,000 CYCLES OR MORE SINCE PRIOR SHOP VISIT INSPECTION.) BY SERIAL NUMBER	28-JUN-2011 H: 4244.20 C: 1829					
SB 72-0215 R2 Engine 2 SB - N/A #326	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (NOTE: INSPECTION RECOMMENDED ANYTIME FAN BLADES ARE IN FOR SHOP VISIT, PROVIDED BLADES HAVE BEEN IN SERVICE 3,000 CYCLES OR MORE SINCE PRIOR SHOP VISIT INSPECTION.) BY SERIAL NUMBER NA TO FAN BLADE S/N'S	28-JUN-2011 H: 4244.20 C: 1829					
SB 72-0215 R3 Engine 1 SB - Open #90	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (AVG MAN HRS: 7) (NOTE: THE FAN BLADES P/N 6018T30P14 WITH SERIAL NUMBERS (S/N) THAT START WITH "MAE" ARE AFFECTED BY THIS SERVICE BULLETIN)						
SB 72-0215 R3 Engine 2 SB - Open #470	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ECI INSPECTION OF FAN BLADE PIN HOLE Notes (AVG MAN HRS: 7) (NOTE: THE FAN BLADES P/N 6018T30P14 WITH SERIAL NUMBERS (S/N) THAT START WITH "MAE" ARE AFFECTED BY THIS SERVICE BULLETIN)						
SB 72-0216 Engine 1 SB - Open #348	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0216 Engine 2 SB - Open #402	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0217 Engine 1 SB - Complied With #792	ENGINE - (72-42-00) - REWORK OF THE AIR BALANCE PISTON STATIONARY SEAL	13-OCT-2009 H: 3725.60 C: 1574					
SB 72-0217 Engine 2 SB - Complied With #700	ENGINE - (72-42-00) - REWORK OF THE AIR BALANCE PISTON STATIONARY SEAL	13-OCT-2009 H: 3725.60 C: 1574					
SB 72-0218 Engine 1 SB - Open #743	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0218 Engine 2 SB - Open #19	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B TURBOFAN ENGINES						
SB 72-0219 Engine 1 SB - Open #56	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0219 Engine 2 SB - Open #791	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0221 Engine 1 SB - Open #466	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - INTRODUCTION OF FAN BLADE P/N 6018T30P15						
SB 72-0221 Engine 2 SB - Open #374	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - INTRODUCTION OF FAN BLADE P/N 6018T30P15						
SB 72-0221 R1 Engine 1 SB - Open #451	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - INTRODUCTION OF FAN BLADE P/N 6018T30P15						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0221 R1 Engine 2 SB - Open #410	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - INTRODUCTION OF FAN BLADE P/N 6018T30P15						
SB 72-0222 Engine 1 SB - Open #756	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE						
SB 72-0222 Engine 2 SB - Open #396	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE						
SB 72-0222 R1 Engine 1 SB - Complied With #571	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes .PER REVISION 4.						
SB 72-0222 R1 Engine 2 SB - Complied With #948	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes .PER REVISION 4.						
SB 72-0222 R2 Engine 1 SB - Complied With #406	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes .PER REVISION 4.						
SB 72-0222 R2 Engine 2 SB - Complied With #684	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes .PER REVISION 4.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0222 R3 Engine 1 SB - Complied With #557	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes (AVG MAN HRS: 1).PER REVISION 4.						
SB 72-0222 R3 Engine 2 SB - Complied With #37	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes (AVG MAN HRS: 1).PER REVISION 4.						
SB 72-0222 R4 Engine 1 SB - Complied With #226	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes (AVG MAN HRS: 1)				23-MAR-2017 H: 5979.10 C: 2576		
SB 72-0222 R4 Engine 2 SB - Complied With #69	ENGINE - GENERAL - INTRODUCTION OF A NEW HYDRAULIC DRAIN LINE Notes (AVG MAN HRS: 1)				23-MAR-2017 H: 5979.10 C: 2576		
SB 72-0223 Engine 1 SB - Open #526	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0223 Engine 2 SB - Open #484	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0224 R1 Engine 1 SB - Open #642	ENGINE - LPT STATOR ASSEMBLY (72-52-00) - CLARIFICATION OF CONFIGURATION AND USAGE OF THE STAGES 3, 4 AND 5 SHROUD SECTORS Notes (NOTE: THE STAGE 3-5 SHROUD SECTORS (SHROUDS SECTORS) P/N 5099T32G01, P/N 5099T34G02, P/N 6020T00G03, P/N 6020T01G03, P/N 6020T02G01, P/N 6020T04G03, STAGE 4-5 SHROUD, AND SEAL SECTORS (SHROUD SECTORS) P/N 6020T03G01 AND 6020T05G03 ARE AFFECTED BY THIS SERVICE BULLETIN)						
SB 72-0224 R1 Engine 2 SB - Open #259	ENGINE - LPT STATOR ASSEMBLY (72-52-00) - CLARIFICATION OF CONFIGURATION AND USAGE OF THE STAGES 3, 4 AND 5 SHROUD SECTORS Notes (NOTE: THE STAGE 3-5 SHROUD SECTORS (SHROUDS SECTORS) P/N 5099T32G01, P/N 5099T34G02, P/N 6020T00G03, P/N 6020T01G03, P/N 6020T02G01, P/N 6020T04G03, STAGE 4-5 SHROUD, AND SEAL SECTORS (SHROUD SECTORS) P/N 6020T03G01 AND 6020T05G03 ARE AFFECTED BY THIS SERVICE BULLETIN)						
SB 72-0225 Engine 1 SB - Open #381	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - REBLADE OF ENGINES SHIPPED WITH NON-STANDARD STAGE 9 COMPRESSOR BLADE COUNT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION)						
SB 72-0225 Engine 2 SB - Open #551	ENGINE - COMPRESSOR ROTOR ASSEMBLY (72-33-00) - REBLADE OF ENGINES SHIPPED WITH NON-STANDARD STAGE 9 COMPRESSOR BLADE COUNT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION)						
SB 72-0226 Engine 1 SB - Open #417	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0226 Engine 2 SB - Open #310	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0228 Engine 1 SB - Open #344	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0228 Engine 2 SB - Open #163	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0229 Engine 1 SB - N/A #682	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes (NOTE: IF THE CSN ON THE PART REACHES 1,200 CSN PRIOR TO COMPLETING THE ECI PER THIS SERVICE BULLETIN, IT IS RECOMMENDED THAT A VISUAL INSPECTION OF THE FAN CONTAINMENT CASE ABRADABLE RUB STRIP BE COMPLETED AT REPEAT INTERVALS AS DESCRIBED IN CF34-BJ S/B 72-0231 UNTIL THE ECI OR FAN BLADE REPLACEMENT CAN BE COMPLIED WITH. IT DOES NOT APPLY TO FIELD MODIFIED FAN BLADES P/N 4923T56G08, EVEN IF THE SERIAL NUMBER IS LISTED IN PARAGRAPH 4., APPENDIX A AND PARAGRAPH 5., APPENDIX B. REFER TO CF34-BJ S/B 72-0230 FOR THESE BLADES.).SUPERSEDED BY SB 72-0229 R1						
SB 72-0229 Engine 2 SB - N/A #149	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes (NOTE: IF THE CSN ON THE PART REACHES 1,200 CSN PRIOR TO COMPLETING THE ECI PER THIS SERVICE BULLETIN, IT IS RECOMMENDED THAT A VISUAL INSPECTION OF THE FAN CONTAINMENT CASE ABRADABLE RUB STRIP BE COMPLETED AT REPEAT INTERVALS AS DESCRIBED IN CF34-BJ S/B 72-0231 UNTIL THE ECI OR FAN BLADE REPLACEMENT CAN BE COMPLIED WITH. IT DOES NOT APPLY TO FIELD MODIFIED FAN BLADES P/N 4923T56G08, EVEN IF THE SERIAL NUMBER IS LISTED IN PARAGRAPH 4., APPENDIX A AND PARAGRAPH 5., APPENDIX B. REFER TO CF34-BJ S/B 72-0230 FOR THESE BLADES.).SUPERSEDED BY SB 72-0229 R1						
SB 72-0229 R1 Engine 1 SB - N/A #718	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .BY SERIAL NUMBER				18-DEC-2008 H: 3551.80 C: 1484		
SB 72-0229 R1 Engine 2 SB - N/A #589	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .BY SERIAL NUMBER				18-DEC-2008 H: 3551.80 C: 1484		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0229 R1 PART B Engine 1 SB - N/A #910	FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .BY SERIAL NUMBER	30-DEC-2009 H: 3756.90 C: 1587					
SB 72-0229 R1 PART A Engine 1 SB - N/A #456	FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .BY SERIAL NUMBER	30-DEC-2009 H: 3756.90 C: 1587					
SB 72-0229 R1 PART A Engine 2 SB - N/A #182	FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .BY SERIAL NUMBER	30-DEC-2009 H: 3756.90 C: 1587					
SB 72-0229 R1 PART B Engine 2 SB - N/A #788	FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 6018T30P14 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .BY SERIAL NUMBER	30-DEC-2009 H: 3756.90 C: 1587					
SB 72-0230 Engine 1 SB - Open #62	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 4923T56G08 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .SCHEDULED -						
SB 72-0230 Engine 2 SB - Open #693	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 4923T56G08 MADE FROM VSMPO MILL SOURCE MATERIAL Notes .SCHEDULED -						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0230 R1 Engine 1 SB - N/A #940	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 4923T56G08 MADE FROM VSMPO MILL SOURCE MATERIAL Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN WITHOUT EFFECT ON REVENUE SERVICE AS CLOSE AS POSSIBLE, BUT PRIOR TO 1,200 ADDITIONAL FLIGHT CYCLES FROM WHEN THE PINHOLE BUSHING WAS INSTALLED.)						
SB 72-0230 R1 Engine 2 SB - N/A #686	ENGINE - FAN ROTOR (72-21-00) - FIELD MANAGEMENT PROGRAM OF FAN BLADES P/N 4923T56G08 MADE FROM VSMPO MILL SOURCE MATERIAL Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN WITHOUT EFFECT ON REVENUE SERVICE AS CLOSE AS POSSIBLE, BUT PRIOR TO 1,200 ADDITIONAL FLIGHT CYCLES FROM WHEN THE PINHOLE BUSHING WAS INSTALLED.)						
SB 72-0231 Engine 1 SB - N/A #625	ENGINE - FAN STATOR (72-23-00) - VISUAL INSPECTION OF FAN CASE ABRADABLE RUB STRIP FOR FAN BLADE TIP CONTACT				16-DEC-2008 H: 3551.80 C: 1484		
SB 72-0231 Engine 2 SB - N/A #916	ENGINE - FAN STATOR (72-23-00) - VISUAL INSPECTION OF FAN CASE ABRADABLE RUB STRIP FOR FAN BLADE TIP CONTACT				16-DEC-2008 H: 3551.80 C: 1484		
SB 72-0231 R1 Engine 1 SB - Open #369	ENGINE - FAN STATOR (72-23-00) - VISUAL INSPECTION OF FAN CASE ABRADABLE RUB STRIP FOR FAN BLADE TIP CONTACT						
SB 72-0231 R1 Engine 2 SB - Open #817	ENGINE - FAN STATOR (72-23-00) - VISUAL INSPECTION OF FAN CASE ABRADABLE RUB STRIP FOR FAN BLADE TIP CONTACT						
SB 72-0231 R2 Engine 1 SB - N/A #8	ENGINE - FAN STATOR (72-23-00) - VISUAL INSPECTION OF FAN CASE ABRADABLE RUB STRIP FOR FAN BLADE TIP CONTACT				19-JUL-2010 H: 3903.70 C: 1663		
SB 72-0231 R2 Engine 2 SB - N/A #859	ENGINE - FAN STATOR (72-23-00) - VISUAL INSPECTION OF FAN CASE ABRADABLE RUB STRIP FOR FAN BLADE TIP CONTACT				19-JUL-2010 H: 3903.70 C: 1663		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0236 Engine 1 SB - Open #362	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0236 Engine 2 SB - Open #915	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0236 R1 Engine 1 SB - Open #114	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0236 R1 Engine 2 SB - Open #430	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0237 Engine 1 SB - Open #666	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A2/-3B ENGINES						
SB 72-0237 Engine 2 SB - Open #784	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A2/-3B ENGINES						
SB 72-0239 Engine 1 SB - Open #570	ENGINE - COMBUSTOR ASSEMBLY (72-00-40) - INTRODUCTION OF FLAT WASHER P/N AN960C10L TO HEAT SHIELD THRUST LINK COVERS ATTACHING PARTS						
SB 72-0239 Engine 2 SB - Open #270	ENGINE - COMBUSTOR ASSEMBLY (72-00-40) - INTRODUCTION OF FLAT WASHER P/N AN960C10L TO HEAT SHIELD THRUST LINK COVERS ATTACHING PARTS						
SB 72-0240 Engine 1 SB - Open #517	ENGINE - COMBUSTION LINER ASSEMBLY (72-42-00) - INTRODUCTION OF COMBUSTOR INNER LINER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0240 Engine 2 SB - Open #823	ENGINE - COMBUSTION LINER ASSEMBLY (72-42-00) - INTRODUCTION OF COMBUSTOR INNER LINER						
SB 72-0241 Engine 1 SB - Open #921	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF SHROUD SECTOR PART NUMBERS FOR STAGE 4 AND STAGE 5						
SB 72-0241 Engine 2 SB - Open #720	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF SHROUD SECTOR PART NUMBERS FOR STAGE 4 AND STAGE 5						
SB 72-0241 R1 Engine 1 SB - Open #177	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF SHROUD SECTOR PART NUMBERS FOR STAGE 4 AND STAGE 5						
SB 72-0241 R1 Engine 2 SB - Open #929	ENGINE - LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INTRODUCTION OF SHROUD SECTOR PART NUMBERS FOR STAGE 4 AND STAGE 5						
SB 72-0242 Engine 1 SB - Open #533	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0242 Engine 2 SB - Open #296	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0243 Engine 1 SB - Open #757	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						
SB 72-0243 Engine 2 SB - Open #58	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-1A/-3A/-3A1/-3A2/-3B ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0244 Engine 1 SB - Open #639	ENGINE - COMPRESSOR ROTOR (72-33-00) - INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P03						
SB 72-0244 Engine 2 SB - Open #304	ENGINE - COMPRESSOR ROTOR (72-33-00) - INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P03						
SB 72-0247 Engine 1 SB - Open #560	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF NEW VG SPINDLE NUT P/N 4037T84P04						
SB 72-0247 Engine 2 SB - Open #86	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF NEW VG SPINDLE NUT P/N 4037T84P04						
SB 72-0247 R1 Engine 1 SB - Open #195	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF NEW VG SPINDLE NUT P/N 4037T84P04						
SB 72-0247 R1 Engine 2 SB - Open #400	ENGINE - COMPRESSOR STATOR - INTRODUCTION OF NEW VG SPINDLE NUT P/N 4037T84P04						
SB 72-0249 Engine 1 SB - Open #172	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0249 Engine 2 SB - Open #770	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0250 Engine 1 SB - Open #183	ENGINE - FAN ROTOR (72-21-00) - REPLACEMENT OF FAN BLADES P/N 6018T30P14 OR P/N 4923T56G08 MADE FROM ALLVAC MILL SOURCE MATERIAL						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0250 Engine 2 SB - Open #593	ENGINE - FAN ROTOR (72-21-00) - REPLACEMENT OF FAN BLADES P/N 6018T30P14 OR P/N 4923T56G08 MADE FROM ALLVAC MILL SOURCE MATERIAL						
SB 72-0250 R1 Engine 1 SB - Open #44	ENGINE - FAN ROTOR (72-21-00) - REPLACEMENT OF FAN BLADES P/N 6018T30P14 OR P/N 4923T56G08 MADE FROM ALLVAC MILL SOURCE MATERIAL Notes DEFERRED		12-APR-2012 H: 4516.10 C: 1934				
SB 72-0250 R1 Engine 2 SB - Open #891	ENGINE - FAN ROTOR (72-21-00) - REPLACEMENT OF FAN BLADES P/N 6018T30P14 OR P/N 4923T56G08 MADE FROM ALLVAC MILL SOURCE MATERIAL Notes DEFERRED		12-APR-2012 H: 4516.10 C: 1934				
SB 72-0251 Engine 1 SB - Open #878	ENGINE - COMPRESSOR ROTOR (72-33-00) - INSPECTION FOR PART NUMBER REMARKING AND INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P02						
SB 72-0251 Engine 2 SB - Open #104	ENGINE - COMPRESSOR ROTOR (72-33-00) - INSPECTION FOR PART NUMBER REMARKING AND INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P02						
SB 72-0251 R1 Engine 1 SB - Open #441	ENGINE - COMPRESSOR ROTOR (72-33-00) - INSPECTION FOR PART NUMBER REMARKING AND INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P02						
SB 72-0251 R1 Engine 2 SB - Open #294	ENGINE - COMPRESSOR ROTOR (72-33-00) - INSPECTION FOR PART NUMBER REMARKING AND INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P02						
SB 72-0251 R2 Engine 1 SB - Open #478	ENGINE - COMPRESSOR ROTOR (72-33-00) - INSPECTION FOR PART NUMBER REMARKING AND INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P02						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0251 R2 Engine 2 SB - Open #803	ENGINE - COMPRESSOR ROTOR (72-33-00) - INSPECTION FOR PART NUMBER REMARKING AND INTRODUCTION OF STAGE 1 COMPRESSOR ROTOR BLISK P/N 5087T84P02						
SB 72-0252 Engine 1 SB - Open #605	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF IMPROVED NO. 5 ROLLER BEARING P/N 5042T13P06						
SB 72-0252 Engine 2 SB - Open #616	ENGINE - COMBUSTION CHAMBER FRAME AND B-SUMP (72-41-00) - INTRODUCTION OF IMPROVED NO. 5 ROLLER BEARING P/N 5042T13P06						
SB 72-0253 Engine 1 SB - Open #477	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0253 Engine 2 SB - Open #48	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0254 Engine 1 SB - Open #923	ENGINE - GENERAL (72-00-00) - CF34-BJ ENGINE SERIALIZATION - MANUFACTURING SEQUENCE						
SB 72-0254 Engine 2 SB - Open #812	ENGINE - GENERAL (72-00-00) - CF34-BJ ENGINE SERIALIZATION - MANUFACTURING SEQUENCE						
SB 72-0255 Engine 1 SB - Open #474	ENGINE - FAN STATOR (72-23-00) - ENGINE MOUNT QUALITY ISSUE						
SB 72-0255 Engine 2 SB - Open #401	ENGINE - FAN STATOR (72-23-00) - ENGINE MOUNT QUALITY ISSUE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0255 R1 Engine 1 SB - Open #583	ENGINE - FAN STATOR (72-23-00) - ENGINE MOUNT QUALITY ISSUE Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION)						
SB 72-0255 R1 Engine 2 SB - Open #789	ENGINE - FAN STATOR (72-23-00) - ENGINE MOUNT QUALITY ISSUE Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION)						
SB 72-0256 Engine 1 SB - Open #488	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED PINNED IGV INNER SUPPORT SHROUD IGV OUTER BUSHING IGV BUSHING AND IGV UPPER AND LOWER SHROUD RING SEGMENTS Notes DEFERRED					12-APR-2012 H: 4516.10 C: 1934	
SB 72-0256 Engine 2 SB - Open #138	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED PINNED IGV INNER SUPPORT SHROUD IGV OUTER BUSHING IGV BUSHING AND IGV UPPER AND LOWER SHROUD RING SEGMENTS Notes DEFERRED					12-APR-2012 H: 4516.10 C: 1934	
SB 72-0256 R1 Engine 1 SB - Open #816	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED PINNED IGV INNER SUPPORT SHROUD IGV OUTER BUSHING IGV BUSHING AND IGV UPPER AND LOWER SHROUD RING SEGMENTS Notes (NOTE: CATEGORY 3 GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AT THE NEXT SHOP VISIT OF THE ENGINE/MODULE. CATEGORY 5 GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE COMPRESSOR STATOR IS REMOVED FROM THE ENGINE. (THIS CATEGORY IS FOR CF34-1A, 3A, 3A2 AND CF34-3A1 ENGINES ONLY).).REVIEW AT NEXT SHOP VISIT						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0256 R1 Engine 2 SB - Open #47	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED PINNED IGV INNER SUPPORT SHROUD IGV OUTER BUSHING IGV BUSHING AND IGV UPPER AND LOWER SHROUD RING SEGMENTS Notes (NOTE: CATEGORY 3 GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AT THE NEXT SHOP VISIT OF THE ENGINE/MODULE. CATEGORY 5 GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE COMPRESSOR STATOR IS REMOVED FROM THE ENGINE. (THIS CATEGORY IS FOR CF34-1A, 3A, 3A2 AND CF34-3A1 ENGINES ONLY).).REVIEW AT NEXT SHOP VISIT						
SB 72-0257 Engine 1 SB - Open #859	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED COMPRESSOR IGV THROUGH STAGE 3 LEVER ARMS						
SB 72-0257 Engine 2 SB - Open #145	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED COMPRESSOR IGV THROUGH STAGE 3 LEVER ARMS						
SB 72-0257 R1 Engine 1 SB - Open #458	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED COMPRESSOR IGV THROUGH STAGE 3 LEVER ARMS						
SB 72-0257 R1 Engine 2 SB - Open #491	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED COMPRESSOR IGV THROUGH STAGE 3 LEVER ARMS						
SB 72-0257 R2 Engine 1 SB - Open #627	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED COMPRESSOR IGV THROUGH STAGE 3 LEVER ARMS Notes (AVG MAN HRS: 8) (NOTE: NOTE: THE IMPLEMENTATION OF THIS SERVICE BULLETIN ELIMINATES THE APPLICABILITY OF CF34-BJ SB 72-0294.)						
SB 72-0257 R2 Engine 2 SB - Open #604	ENGINE - STAGES IGV THROUGH 13 COMPRESSOR STATOR (72-32-00) - INTRODUCTION OF REDESIGNED COMPRESSOR IGV THROUGH STAGE 3 LEVER ARMS Notes (AVG MAN HRS: 8) (NOTE: NOTE: THE IMPLEMENTATION OF THIS SERVICE BULLETIN ELIMINATES THE APPLICABILITY OF CF34-BJ SB 72-0294.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0258 Engine 1 SB - Open #317	ENGINE - FAN STATOR (72-23-00) - INTRODUCTION OF NEW SHIM P/N 2448M31P01						
SB 72-0258 Engine 2 SB - Open #710	ENGINE - FAN STATOR (72-23-00) - INTRODUCTION OF NEW SHIM P/N 2448M31P01						
SB 72-0259 Engine 1 SB - Open #593	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0259 Engine 2 SB - Open #351	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0264 Engine 1 SB - Open #905	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0264 Engine 2 SB - Open #50	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0266 Engine 1 SB - Open #152	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - PART USAGE CLARIFICATION						
SB 72-0266 Engine 2 SB - Open #951	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - PART USAGE CLARIFICATION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0268 Engine 1 SB - Open #166	ENGINE - REAR MAIN MOUNT ASSEMBLY (72-44-00) - SPOT FLUORESCENT PENETRANT INSPECTION OF LH AND RH AFT MOUNT RING LUGS Notes .REVIEW AT NEXT SHOP VISIT						
SB 72-0268 Engine 2 SB - Open #605	ENGINE - REAR MAIN MOUNT ASSEMBLY (72-44-00) - SPOT FLUORESCENT PENETRANT INSPECTION OF LH AND RH AFT MOUNT RING LUGS Notes .REVIEW AT NEXT SHOP VISIT						
SB 72-0268 R1 Engine 1 SB - Open #608	ENGINE - REAR MAIN MOUNT ASSEMBLY (72-44-00) - SPOT FLUORESCENT PENETRANT INSPECTION OF LH AND RH AFT MOUNT RING LUGS						
SB 72-0268 R1 Engine 2 SB - Open #87	ENGINE - REAR MAIN MOUNT ASSEMBLY (72-44-00) - SPOT FLUORESCENT PENETRANT INSPECTION OF LH AND RH AFT MOUNT RING LUGS						
SB 72-0268 R2 Engine 1 SB - Open #34	ENGINE - REAR MAIN MOUNT ASSEMBLY (72-44-00) - SPOT FLUORESCENT PENETRANT INSPECTION OF LH AND RH AFT MOUNT RING LUGS						
SB 72-0268 R2 Engine 2 SB - Open #939	ENGINE - REAR MAIN MOUNT ASSEMBLY (72-44-00) - SPOT FLUORESCENT PENETRANT INSPECTION OF LH AND RH AFT MOUNT RING LUGS						
SB 72-0269 Engine 1 SB - Open #950	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AGB ASSEMBLY REPLACEMENT						
SB 72-0269 Engine 2 SB - Open #6	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AGB ASSEMBLY REPLACEMENT						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0269 R1 Engine 1 SB - Open #158	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AGB ASSEMBLY REPLACEMENT						
SB 72-0269 R1 Engine 2 SB - Open #846	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AGB ASSEMBLY REPLACEMENT						
SB 72-0270 Engine 1 SB - Open #424	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
	Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE BEEN REMOVED FROM WING AT LEAST ONE TIME.)						
SB 72-0270 Engine 2 SB - Open #418	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
	Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE BEEN REMOVED FROM WING AT LEAST ONE TIME.)						
SB 72-0270 R1 Engine 1 SB - Open #842	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
	Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE BEEN REMOVED FROM WING AT LEAST ONE TIME.)						
SB 72-0270 R1 Engine 2 SB - Open #449	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
	Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE BEEN REMOVED FROM WING AT LEAST ONE TIME.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0270 R2 Engine 1 SB - Open #198	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE BEEN REMOVED FROM WING AT LEAST ONE TIME.)						
SB 72-0270 R2 Engine 2 SB - Open #733	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE BEEN REMOVED FROM WING AT LEAST ONE TIME.)						
SB 72-0270 R3 Engine 1 SB - Open #871	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
SB 72-0270 R3 Engine 2 SB - Open #913	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
SB 72-0270 R4 Engine 1 SB - Open #614	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
SB 72-0270 R4 Engine 2 SB - Open #588	ENGINE - FAN STATOR ASSEMBLY (72-00-23) - FORWARD MOUNT RIB INSPECTION						
SB 72-0272 Engine 1 SB - Open #753	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0272 Engine 2 SB - Open #207	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0275 Engine 1 SB - Open #764	ENGINE - GENERAL (72-00-00) - SPARE PART RELEASE FOR CF34-BJ ENGINES						
SB 72-0275 Engine 2 SB - Open #554	ENGINE - GENERAL (72-00-00) - SPARE PART RELEASE FOR CF34-BJ ENGINES						
SB 72-0276 Engine 1 SB - Open #564	ENGINE - EXHAUST COMPONENTS (72-54-00) - RELEASE OF NEW IMPROVED SCAVENGE ADAPTER AND SCAVENGE CONNECTOR TO THE CF34-BJ ENGINE MODELS						
SB 72-0276 Engine 2 SB - Open #148	ENGINE - EXHAUST COMPONENTS (72-54-00) - RELEASE OF NEW IMPROVED SCAVENGE ADAPTER AND SCAVENGE CONNECTOR TO THE CF34-BJ ENGINE MODELS						
SB 72-0277 Engine 1 SB - Open #84	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - INTRODUCTION OF NEW SELF-WRENCHING BOLT P/N 4020T53P04						
SB 72-0277 Engine 2 SB - Open #766	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - INTRODUCTION OF NEW SELF-WRENCHING BOLT P/N 4020T53P04						
SB 72-0279 Engine 1 SB - Open #425	ACCESSORY DRIVE GEARBOX ASSEMBLY (72-61-00) - INTRODUCTION OF WASHERS TO ELIMINATE SPLIT LINE FLANGE INTERFERENCE						
SB 72-0279 Engine 2 SB - Open #933	ACCESSORY DRIVE GEARBOX ASSEMBLY (72-61-00) - INTRODUCTION OF WASHERS TO ELIMINATE SPLIT LINE FLANGE INTERFERENCE						
SB 72-0279 R1 Engine 1 SB - Open #646	ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY (72-61-00) - INTRODUCTION OF WASHERS TO ELIMINATE SPLIT LINE FLANGE INTERFERENCE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0279 R1 Engine 2 SB - Open #117	ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY (72-61-00) - INTRODUCTION OF WASHERS TO ELIMINATE SPLIT LINE FLANGE INTERFERENCE						
SB 72-0279 R2 Engine 1 SB - Open #378	ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY (72-61-00) - INTRODUCTION OF WASHERS TO ELIMINATE SPLIT LINE FLANGE INTERFERENCE						
SB 72-0279 R2 Engine 2 SB - Open #735	ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY (72-61-00) - INTRODUCTION OF WASHERS TO ELIMINATE SPLIT LINE FLANGE INTERFERENCE						
SB 72-0280 Engine 1 SB - Open #760	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0280 Engine 2 SB - Open #666	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0281 Engine 1 SB - Open #857	ENGINE - COMBUSTION SECTION (72-43-00) - INTRODUCTION OF NEW SUPPORT BRACKET P/N 2583M77G01 FOR WHITE W3 CABLE ASSEMBLY Notes (AVG MAN HRS: 2)						
SB 72-0281 Engine 2 SB - Open #246	ENGINE - COMBUSTION SECTION (72-43-00) - INTRODUCTION OF NEW SUPPORT BRACKET P/N 2583M77G01 FOR WHITE W3 CABLE ASSEMBLY Notes (AVG MAN HRS: 2)						
SB 72-0281 R1 Engine 1 SB - Open #169	ENGINE - COMBUSTION SECTION (72-43-00) - INTRODUCTION OF NEW SUPPORT BRACKET P/N 2583M77G01 FOR WHITE W3 CABLE ASSEMBLY						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0281 R1 Engine 2 SB - Open #660	ENGINE - COMBUSTION SECTION (72-43-00) - INTRODUCTION OF NEW SUPPORT BRACKET P/N 2583M77G01 FOR WHITE W3 CABLE ASSEMBLY						
SB 72-0284 Engine 1 SB - Open #884	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0284 Engine 2 SB - Open #217	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0287 Engine 1 SB - Open #298	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) INTERCHANGEABILITY MODIFICATIONS Notes (AVG MAN HRS: 6)						
SB 72-0287 Engine 2 SB - Open #754	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) INTERCHANGEABILITY MODIFICATIONS Notes (AVG MAN HRS: 6)						
SB 72-0287 R1 Engine 1 SB - Open #880	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) INTERCHANGEABILITY MODIFICATIONS						
SB 72-0287 R1 Engine 2 SB - Open #344	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - CF34 ACCESSORY GEARBOX (AGB) INTERCHANGEABILITY MODIFICATIONS						
SB 72-0288 Engine 1 SB - Open #830	ENGINE - GENERAL - REMOVAL OF PARTS FROM IPC						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0288 Engine 2 SB - Open #657	ENGINE - GENERAL - REMOVAL OF PARTS FROM IPC						
SB 72-0289 Engine 1 SB - Open #888	EXHAUST COMPONENTS (72-54-00) - QUANTITY CORRECTION FOR MACHINE BOLTS P/N MS9565-04						
SB 72-0289 Engine 2 SB - Open #893	EXHAUST COMPONENTS (72-54-00) - QUANTITY CORRECTION FOR MACHINE BOLTS P/N MS9565-04						
SB 72-0290 Engine 1 SB - N/A #57	LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INSPECTION OF SHROUD SECTORS ON LPT STATOR ASSEMBLIES P/N 6020T15G30 AND P/N 6020T15G31					08-FEB-2017 H: 5949.70 C: 2567	
	Notes (AVG MAN HRS: 2).TO THE ENGINE LP TURBINE STATOR P/NS AND S/NS INSTALLED ON #1 ENGINE						
SB 72-0290 Engine 2 SB - N/A #352	LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - INSPECTION OF SHROUD SECTORS ON LPT STATOR ASSEMBLIES P/N 6020T15G30 AND P/N 6020T15G31					08-FEB-2017 H: 5949.70 C: 2567	
	Notes (AVG MAN HRS: 2).TO THE ENGINE LP TURBINE STATOR P/NS AND S/NS INSTALLED ON #2 ENGINE						
SB 72-0291 Engine 1 SB - N/A #121	LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - REPLACEMENT OF LPT STAGE 3 AND STAGE 4 SHROUD SECTORS ON LPT STATOR ASSEMBLIES P/N 6020T15G30 AND P/N 6020T15G31					22-JAN-2018 H: 6257.50 C: 2678	
	Notes (AVG MAN HRS: 2).BY ENGINE SERIAL NUMBER.NO FURTHER ACTION REQUIRED AT THIS TIME						
SB 72-0291 Engine 2 SB - N/A #93	LOW PRESSURE TURBINE STATOR ASSEMBLY (72-52-00) - REPLACEMENT OF LPT STAGE 3 AND STAGE 4 SHROUD SECTORS ON LPT STATOR ASSEMBLIES P/N 6020T15G30 AND P/N 6020T15G31					22-JAN-2018 H: 6257.50 C: 2678	
	Notes (AVG MAN HRS: 2).BY ENGINE SERIAL NUMBER.NO FURTHER ACTION REQUIRED AT THIS TIME						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0292 Engine 1 SB - Open #915	OPERATION OF CF34-3B ENGINES IN BOMBARDIER CHALLENGER 650 AIRCRAFT WITH MAXIMUM TAKE-OFF AND REDUCED THRUST TAKE-OFF CAPABILITIES Notes (AVG MAN HRS: 1) (NOTE: GE RECOMMENDS THAT THIS SERVICE BULLETIN IS COMPLIED WITH PRIOR TO USE OR INSTALLATION OF CF34-3B ENGINES CONVERTED FOR USE ON THE BOMBARDIER CHALLENGER 650 AIRCRAFT WITH MTO AND FLEX CAPABILITIES.)						
SB 72-0292 Engine 2 SB - Open #580	OPERATION OF CF34-3B ENGINES IN BOMBARDIER CHALLENGER 650 AIRCRAFT WITH MAXIMUM TAKE-OFF AND REDUCED THRUST TAKE-OFF CAPABILITIES Notes (AVG MAN HRS: 1) (NOTE: GE RECOMMENDS THAT THIS SERVICE BULLETIN IS COMPLIED WITH PRIOR TO USE OR INSTALLATION OF CF34-3B ENGINES CONVERTED FOR USE ON THE BOMBARDIER CHALLENGER 650 AIRCRAFT WITH MTO AND FLEX CAPABILITIES.)						
SB 72-0293 Engine 1 SB - Open #464	ENGINE - COMPRESSOR STATOR (72-32-00) - WEIGHT INSPECTION OF THE COMPRESSOR CASE ASSEMBLY						
SB 72-0293 Engine 2 SB - Open #810	ENGINE - COMPRESSOR STATOR (72-32-00) - WEIGHT INSPECTION OF THE COMPRESSOR CASE ASSEMBLY						
SB 72-0294 Engine 1 SB - Open #794	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-00-32) - INSPECTION OF VG SYSTEM TO CHECK FOR LOOSENESS Notes (AVG MAN HRS: 8)						
SB 72-0294 Engine 2 SB - Open #884	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-00-32) - INSPECTION OF VG SYSTEM TO CHECK FOR LOOSENESS Notes (AVG MAN HRS: 8)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0294 R1 Engine 1 SB - Open #577	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-00-32) - INSPECTION OF VG SYSTEM TO CHECK FOR LOOSENESS Notes (AVG MAN HRS: 8)						
SB 72-0294 R1 Engine 2 SB - Open #641	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-00-32) - INSPECTION OF VG SYSTEM TO CHECK FOR LOOSENESS Notes (AVG MAN HRS: 8)						
SB 72-0295 Engine 1 SB - Open #932	REPLACEMENT OF SILVER PLATED NUTS WITH DRY-FILM COATED NUTS ON THERMOCOUPLE PROBES AND PT5 PROBE OR PLUG Notes (AVG MAN HRS: 4) (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES. THE PLAIN NUT P/N MS9357-10, WASHER TAB LOCK (WASHER) P/N 3056T13P01, AND SELF-LOCKING NUT P/N R1181P004 (USED WITH NO WASHER) ARE AFFECTED BY THIS SERVICE BULLETIN.)						
SB 72-0295 Engine 2 SB - Open #804	REPLACEMENT OF SILVER PLATED NUTS WITH DRY-FILM COATED NUTS ON THERMOCOUPLE PROBES AND PT5 PROBE OR PLUG Notes (AVG MAN HRS: 4) (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES. THE PLAIN NUT P/N MS9357-10, WASHER TAB LOCK (WASHER) P/N 3056T13P01, AND SELF-LOCKING NUT P/N R1181P004 (USED WITH NO WASHER) ARE AFFECTED BY THIS SERVICE BULLETIN.)						
SB 72-0298 Engine 1 SB - Open #539	COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 10 COMPRESSOR BLADES REPLACEMENT PLAN Notes (AVG MAN HRS: 4) (NOTE: NOTE: CF34-3 ENGINES THAT ALREADY HAD HIGH PRESSURE COMPRESSOR (HPC) AFT SPOOL REPLACEMENT SHOP VISIT* AND HAVE NOT COMPLIED TO SEI-782, 72-33-00, COMPRESSOR ROTOR ASSEMBLY - INSPECTION (RELEASED IN SEI-782 - REV 56, 02/01/2016 OR LATER) ARE APPLICABLE TO THIS SERVICE BULLETIN)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0298 Engine 2 SB - Open #452	COMPRESSOR ROTOR ASSEMBLY (72-33-00) - STAGE 10 COMPRESSOR BLADES REPLACEMENT PLAN Notes (AVG MAN HRS: 4) (NOTE: NOTE: CF34-3 ENGINES THAT ALREADY HAD HIGH PRESSURE COMPRESSOR (HPC) AFT SPOOL REPLACEMENT SHOP VISIT* AND HAVE NOT COMPLIED TO SEI-782, 72-33-00, COMPRESSOR ROTOR ASSEMBLY - INSPECTION (RELEASED IN SEI-782 - REV 56, 02/01/2016 OR LATER) ARE APPLICABLE TO THIS SERVICE BULLETIN)						
SB 72-0299 Engine 1 SB - Open #304	REPLACEMENT OF MISMARKED LPT MODULE ID PLATES (THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION) Notes (NOTE: NOTE: THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						
SB 72-0299 Engine 2 SB - Open #682	REPLACEMENT OF MISMARKED LPT MODULE ID PLATES (THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION) Notes (NOTE: NOTE: THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						
SB 72-0300 Engine 1 SB - Open #133	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0300 Engine 2 SB - Open #528	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0302 Engine 1 SB - Open #32	ENGINE - GENERAL - ADMINISTRATIVE CHANGE TO UPDATE CF34-BJ EIPC MODEL APPLICABILITY						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0302 Engine 2 SB - Open #670	ENGINE - GENERAL - ADMINISTRATIVE CHANGE TO UPDATE CF34-BJ EIPC MODEL APPLICABILITY						
SB 72-0303 Engine 1 SB - Open #855	COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION OF VG SHAFT FORWARD BEARING SUPPORT Notes (AVG MAN HRS: 1)						
SB 72-0303 Engine 2 SB - Open #847	COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION OF VG SHAFT FORWARD BEARING SUPPORT Notes (AVG MAN HRS: 1)						
SB 72-0303 R1 Engine 1 SB - Open #481	COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION OF VG SHAFT FORWARD BEARING SUPPORT Notes (AVG MAN HRS: 1)						
SB 72-0303 R1 Engine 2 SB - Open #542	COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION OF VG SHAFT FORWARD BEARING SUPPORT Notes (AVG MAN HRS: 1)						
SB 72-0303 R2 Engine 1 SB - Open #272	COMPRESSOR STATOR ASSEMBLY - INSPECTION OF VG SHAFT FORWARD BEARING SUPPORT Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0303 R2 Engine 2 SB - Open #555	COMPRESSOR STATOR ASSEMBLY - INSPECTION OF VG SHAFT FORWARD BEARING SUPPORT Notes (AVG MAN HRS: 1)						
SB 72-0304 Engine 1 SB - Open #395	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0304 Engine 2 SB - Open #9	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0304 R1 Engine 1 SB - Open #311	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0304 R1 Engine 2 SB - Open #119	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0305 Engine 1 SB - Open #662	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0305 Engine 2 SB - Open #705	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0306 Engine 1 SB - N/A #771	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING Notes (AVG MAN HRS: 2) (NOTE: EFFECTIVITY: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE ANY FAN BLADE WHICH HAS BEEN REPAIRED BY ATI-UK UNDER SEI-582, 72-21-12, REPAIR 01, REPAIR 02 OR REI-13471 OR SEI-782, 72-21-12 REPAIR 01, REPAIR 02, OR REI-13471 WITH THE SERIAL NUMBERS LISTED IN PARAGRAPH 4.).BY SUSPECTED SERIAL NUMBERS DID NOT MATCH ANY OF THE FAN BLADES ON THE #1 ENGINE					12-OCT-2017 H: 6181.40 C: 2646	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0306 Engine 2 SB - N/A #228	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING	12-OCT-2017 H: 6181.40 C: 2646					
	Notes (AVG MAN HRS: 2) (NOTE: EFFECTIVITY: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE ANY FAN BLADE WHICH HAS BEEN REPAIRED BY ATI-UK UNDER SEI-582, 72-21-12, REPAIR 01, REPAIR 02 OR REI-13471 OR SEI-782, 72-21-12 REPAIR 01, REPAIR 02, OR REI-13471 WITH THE SERIAL NUMBERS LISTED IN PARAGRAPH 4.) BY SUSPECTED SERIAL NUMBERS DID NOT MATCH ANY OF THE FAN BLADES ON THE #2 ENGINE						
SB 72-0306 Par. 3B Engine 1 SB - Open #273	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - INSPECT (ALTERNATIVE PROCEDURE)						
	Notes (NOTE: COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE BUT NO LATER THAN THE FIRST OVERNIGHT MAINTENANCE PERIOD AFTER IDENTIFYING AN AFFECTED FAN BLADE. NOTE: THIS ALTERNATIVE PROCEDURE IS RECOMMENDED ONLY IF THE AFFECTED ENGINE IS OUTSTATION OR A REPLACEMENT FAN BLADE(S) IS NOT IMMEDIATELY AVAILABLE.)						
SB 72-0306 Par. 3B Engine 2 SB - Open #226	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - INSPECT (ALTERNATIVE PROCEDURE)						
	Notes (NOTE: COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE BUT NO LATER THAN THE FIRST OVERNIGHT MAINTENANCE PERIOD AFTER IDENTIFYING AN AFFECTED FAN BLADE. NOTE: THIS ALTERNATIVE PROCEDURE IS RECOMMENDED ONLY IF THE AFFECTED ENGINE IS OUTSTATION OR A REPLACEMENT FAN BLADE(S) IS NOT IMMEDIATELY AVAILABLE.)						
SB 72-0306 Par. 1C (2) Engine 1 SB - Open #227	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REPLACE						
	Notes (NOTE: COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE BUT NO LATER THAN THE FIRST OVERNIGHT MAINTENANCE PERIOD AFTER IDENTIFYING AN AFFECTED FAN BLADE.)						
SB 72-0306 Par. 1C (2) Engine 2 SB - Open #137	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REPLACE						
	Notes (NOTE: COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE BUT NO LATER THAN THE FIRST OVERNIGHT MAINTENANCE PERIOD AFTER IDENTIFYING AN AFFECTED FAN BLADE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0306 Par. 1C (1) Engine 1 SB - Open #499	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REVIEW RECORDS Notes (NOTE: NOTE: ANY FAN BLADE FOUND IN A RECORD SEARCH SHOULD BE REMOVED FROM REVENUE SERVICE AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES. OPERATOR HAS THE DISCRETION TO PERFORM THE REPAIR PER CF34-BJ S/B 72-0123.)						
SB 72-0306 Par. 1C (1) Engine 2 SB - Open #530	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REVIEW RECORDS Notes (NOTE: NOTE: ANY FAN BLADE FOUND IN A RECORD SEARCH SHOULD BE REMOVED FROM REVENUE SERVICE AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES. OPERATOR HAS THE DISCRETION TO PERFORM THE REPAIR PER CF34-BJ S/B 72-0123.)						
SB 72-0306 R1 Engine 1 SB - Open #418	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING Notes (AVG MAN HRS: 2) (NOTE: EFFECTIVITY: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE ANY FAN BLADE WHICH HAS BEEN REPAIRED BY ATI-UK UNDER SEI-582, 72-21-12, REPAIR 01, REPAIR 02 OR REI-13471 OR SEI-782, 72-21-12 REPAIR 01, REPAIR 02, OR REI-13471 WITH THE SERIAL NUMBERS LISTED IN PARAGRAPH 4.)						
SB 72-0306 R1 Engine 2 SB - Open #466	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING Notes (AVG MAN HRS: 2) (NOTE: EFFECTIVITY: THIS SERVICE BULLETIN IS APPLICABLE TO ALL CF34-BJ ENGINES THAT HAVE ANY FAN BLADE WHICH HAS BEEN REPAIRED BY ATI-UK UNDER SEI-582, 72-21-12, REPAIR 01, REPAIR 02 OR REI-13471 OR SEI-782, 72-21-12 REPAIR 01, REPAIR 02, OR REI-13471 WITH THE SERIAL NUMBERS LISTED IN PARAGRAPH 4.)						
SB 72-0306 R1 Par. 3B Engine 1 SB - Open #595	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - INSPECT (ALTERNATIVE PROCEDURE) Notes (NOTE: NOTE: THIS ALTERNATIVE PROCEDURE IS RECOMMENDED ONLY IF THE AFFECTED ENGINE IS OUTSTATION OR A REPLACEMENT FAN BLADE(S) IS NOT IMMEDIATELY AVAILABLE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0306 R1 Par. 3B Engine 2 SB - Open #471	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - INSPECT (ALTERNATIVE PROCEDURE) Notes (NOTE: NOTE: THIS ALTERNATIVE PROCEDURE IS RECOMMENDED ONLY IF THE AFFECTED ENGINE IS OUTSTATION OR A REPLACEMENT FAN BLADE(S) IS NOT IMMEDIATELY AVAILABLE.)						
SB 72-0306 R1 Par. 1C(2) Engine 1 SB - Open #563	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REPLACE Notes (AVG MAN HRS: 2) (NOTE: COMPLIANCE: AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES.)						
SB 72-0306 R1 Par. 1C(2) Engine 2 SB - Open #35	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REPLACE Notes (AVG MAN HRS: 2) (NOTE: COMPLIANCE: AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES.)						
SB 72-0306 R1 Par. 1C(1) Engine 1 SB - Open #812	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REVIEW RECORDS Notes (AVG MAN HRS: 2) (NOTE: NOTE: ANY FAN BLADE FOUND IN A RECORD SEARCH SHOULD BE REMOVED FROM REVENUE SERVICE AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES. OPERATOR HAS THE DISCRETION TO PERFORM THE REPAIR PER CF34-BJ S/B 72-0123.)						
SB 72-0306 R1 Par. 1C(1) Engine 2 SB - Open #614	FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REVIEW RECORDS Notes (AVG MAN HRS: 2) (NOTE: NOTE: ANY FAN BLADE FOUND IN A RECORD SEARCH SHOULD BE REMOVED FROM REVENUE SERVICE AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES. OPERATOR HAS THE DISCRETION TO PERFORM THE REPAIR PER CF34-BJ S/B 72-0123.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0306 R2 Engine 1 SB - N/A #609	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING	24-DEC-2019 H: 6528.70 C: 2803					
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: SERVICE BULLETIN 72-0306 R02 ISSUED SEPTEMBER 27, 2017 REPLACEMENT OF FAN BLADES IS N/A TO THIS ENGINE AT THIS TIME. NONE OF THE EFFECTIVE S/N BLADES LISTED IN SB ARE ON THIS ENGINE.).S/N'S BLADES NOT INSTALLED						
SB 72-0306 R2 Engine 2 SB - N/A #127	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING	24-DEC-2019 H: 6528.70 C: 2803					
	Notes (AVG MAN HRS: 1) (UPDATE NOTE: SERVICE BULLETIN 72-0306 R02 ISSUED SEPTEMBER 27, 2017 REPLACEMENT OF FAN BLADES IS N/A TO THIS ENGINE AT THIS TIME. NONE OF THE EFFECTIVE S/N BLADES LISTED IN SB ARE ON THIS ENGINE.).S/N'S BLADES NOT INSTALLED						
SB 72-0306 R2 Par. 1C(2) Engine 1 SB - N/A #112	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REPLACE	24-DEC-2019 H: 6528.70 C: 2803					
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: SERVICE BULLETIN 72-0306 R02 ISSUED SEPTEMBER 27, 2017 REPLACEMENT OF FAN BLADES IS N/A TO THIS ENGINE AT THIS TIME. NONE OF THE EFFECTIVE S/N BLADES LISTED IN SB ARE ON THIS ENGINE.) (NOTE: COMPLIANCE: AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES.).S/N'S BLADES NOT INSTALLED						
SB 72-0306 R2 Par. 1C(2) Engine 2 SB - N/A #54	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REPLACE	24-DEC-2019 H: 6528.70 C: 2803					
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: SERVICE BULLETIN 72-0306 R02 ISSUED SEPTEMBER 27, 2017 REPLACEMENT OF FAN BLADES IS N/A TO THIS ENGINE AT THIS TIME. NONE OF THE EFFECTIVE S/N BLADES LISTED IN SB ARE ON THIS ENGINE.) (NOTE: COMPLIANCE: AT THE NEXT OVERNIGHT MAINTENANCE PERIOD OR FROM READY TO INSTALL SPARES.).S/N'S BLADES NOT INSTALLED						
SB 72-0306 R2 Par. 1C(1) Engine 1 SB - N/A #513	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REVIEW RECORDS	24-DEC-2019 H: 6528.70 C: 2803					
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: SERVICE BULLETIN 72-0306 R02 ISSUED SEPTEMBER 27, 2017 REPLACEMENT OF FAN BLADES IS N/A TO THIS ENGINE AT THIS TIME. NONE OF THE EFFECTIVE S/N BLADES LISTED IN SB ARE ON THIS ENGINE.) (NOTE: COMPLIANCE: OPERATORS SHOULD COMPLETE A REVIEW OF THEIR RECORDS FOR THIS SUBGROUP NO LATER THAN 14 DAYS FROM THE ISSUANCE OF THIS SERVICE BULLETIN.).S/N'S BLADES NOT INSTALLED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0306 R2 Par. 1C(1) Engine 2 SB - N/A #92	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - REPLACEMENT OF FAN BLADES WITH MISSING AFTER-REPAIR LANCE PEENING - REVIEW RECORDS Notes (AVG MAN HRS: 2) (UPDATE NOTE: SERVICE BULLETIN 72-0306 R02 ISSUED SEPTEMBER 27, 2017 REPLACEMENT OF FAN BLADES IS N/A TO THIS ENGINE AT THIS TIME. NONE OF THE EFFECTIVE S/N BLADES LISTED IN SB ARE ON THIS ENGINE.) (NOTE: COMPLIANCE: OPERATORS SHOULD COMPLETE A REVIEW OF THEIR RECORDS FOR THIS SUBGROUP NO LATER THAN 14 DAYS FROM THE ISSUANCE OF THIS SERVICE BULLETIN.) S/N'S BLADES NOT INSTALLED	24-DEC-2019 H: 6528.70 C: 2803					
SB 72-0307 Engine 1 SB - Open #748	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0307 Engine 2 SB - Open #190	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0308 Engine 1 SB - N/A #638	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SEARCH OF FAN BLADES SENT TO ATI-UK BETWEEN 2007 AND 2009 WITHIN EVERY OPERATOR FLEET Notes (AVG MAN HRS: 2).THE FAN BLADES HAVE NOT BEEN REMOVED AND SENT TO ATI-UK. NO FURTHER ACTION REQUIRED AT THIS TIME.	12-JAN-2018 H: 6249.00 C: 2676					
SB 72-0308 Engine 2 SB - N/A #309	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SEARCH OF FAN BLADES SENT TO ATI-UK BETWEEN 2007 AND 2009 WITHIN EVERY OPERATOR FLEET Notes (AVG MAN HRS: 2).THE FAN BLADES HAVE NOT BEEN REMOVED AND SENT TO ATI-UK. NO FURTHER ACTION REQUIRED AT THIS TIME.	12-JAN-2018 H: 6249.00 C: 2676					
SB 72-0309 Engine 1 SB - Open #396	GENERAL (72-00-00) - INTRODUCTION OF NEW VARIABLE GEOMETRY LINKAGE ASSEMBLY WITH IMPROVED BEARING SUPPORT						
SB 72-0309 Engine 2 SB - Open #454	GENERAL (72-00-00) - INTRODUCTION OF NEW VARIABLE GEOMETRY LINKAGE ASSEMBLY WITH IMPROVED BEARING SUPPORT						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0309 R1 Engine 1 SB - Open #189	GENERAL (72-00-00) - INTRODUCTION OF NEW VARIABLE GEOMETRY LINKAGE ASSEMBLY WITH IMPROVED BEARING SUPPORT						
SB 72-0309 R1 Engine 2 SB - Open #330	GENERAL (72-00-00) - INTRODUCTION OF NEW VARIABLE GEOMETRY LINKAGE ASSEMBLY WITH IMPROVED BEARING SUPPORT						
SB 72-0310 Engine 1 SB - Open #92	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0310 Engine 2 SB - Open #877	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0311 Engine 1 SB - Open #914	NO. 1 CARBON SEAL REKITTED - ONE-TIME VISUAL INSPECTION OF THE RETAINING JOINT AND RING ENGAGEMENT						
SB 72-0311 Engine 2 SB - Open #834	NO. 1 CARBON SEAL REKITTED - ONE-TIME VISUAL INSPECTION OF THE RETAINING JOINT AND RING ENGAGEMENT						
SB 72-0312 Engine 1 SB - Open #622	SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0312 Engine 2 SB - Open #566	SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0313 Engine 1 SB - Open #696	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0313 Engine 2 SB - Open #667	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0314 Engine 1 SB - Open #797	FAN STATOR (72-23-00) - INTRODUCTION OF NEW NO. 1 BEARING CARBON SEAL P/N 6047T63P09						
SB 72-0314 Engine 2 SB - Open #3	FAN STATOR (72-23-00) - INTRODUCTION OF NEW NO. 1 BEARING CARBON SEAL P/N 6047T63P09						
SB 72-0315 Engine 1 SB - Open #81	ENGINE - GENERAL (72-00-00) - REMOVAL OF SPARE PARTS SUPPORT FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0315 Engine 2 SB - Open #85	ENGINE - GENERAL (72-00-00) - REMOVAL OF SPARE PARTS SUPPORT FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0315 R1 Engine 1 SB - Open #277	ENGINE - GENERAL (72-00-00) - REMOVAL OF SPARE PARTS SUPPORT FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0315 R1 Engine 2 SB - Open #46	ENGINE - GENERAL (72-00-00) - REMOVAL OF SPARE PARTS SUPPORT FOR CF34-BJ TURBOFAN ENGINES						
SB 72-0316 Engine 1 SB - Open #363	ENGINE - GENERAL (72-00-00) - RE-CONVERSION OF CF34-3B ENGINES THAT WERE OPERATED IN A CHALLENGER 650 AIRCRAFT WITH MTO AND FLEX CAPABILITIES						
	Notes (AVG MAN HRS: 1) (NOTE: EFFECTIVITY: PLEASE SEE EFFECTIVITY)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0316 Engine 2 SB - Open #371	ENGINE - GENERAL (72-00-00) - RE-CONVERSION OF CF34-3B ENGINES THAT WERE OPERATED IN A CHALLENGER 650 AIRCRAFT WITH MTO AND FLEX CAPABILITIES Notes (AVG MAN HRS: 1) (NOTE: EFFECTIVITY: PLEASE SEE EFFECTIVITY)						
SB 72-0318 Engine 1 SB - Open #815	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0318 Engine 2 SB - Open #650	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0319 Engine 1 SB - Open #202	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY (72-64-00) - REPLACEMENT OF PTO ROLLER BEARINGS P/N 5071T30P03 AND P/N 5071T30P04 WITH INNER/OUTER RACE SERIAL NUMBERS MISMATCH Notes (AVG MAN HRS: 44)						
SB 72-0319 Engine 2 SB - Open #102	ENGINE - POWER TAKEOFF DRIVE ASSEMBLY (72-64-00) - REPLACEMENT OF PTO ROLLER BEARINGS P/N 5071T30P03 AND P/N 5071T30P04 WITH INNER/OUTER RACE SERIAL NUMBERS MISMATCH Notes (AVG MAN HRS: 44)						
SB 72-0321 Engine 1 SB - Open #596	ONE-TIME BSI OF NO. 1 AND 2 BEARING HOUSING ASSEMBLY PLATE HOLES, OIL MANIFOLD, AND OIL SCAVENGE TUBE FOR METAL-TO-METAL CONDITION Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0321 Engine 2 SB - Open #731	ONE-TIME BSI OF NO. 1 AND 2 BEARING HOUSING ASSEMBLY PLATE HOLES, OIL MANIFOLD, AND OIL SCAVENGE TUBE FOR METAL-TO-METAL CONDITION Notes (AVG MAN HRS: 1)						
SB 72-0321 R1 Engine 1 SB - Open #877	ONE-TIME BSI OF NO. 1 AND 2 BEARING HOUSING ASSEMBLY PLATE HOLES, OIL MANIFOLD, AND OIL SCAVENGE TUBE FOR METAL-TO-METAL CONDITION Notes (AVG MAN HRS: 1)						
SB 72-0321 R1 Engine 2 SB - Open #293	ONE-TIME BSI OF NO. 1 AND 2 BEARING HOUSING ASSEMBLY PLATE HOLES, OIL MANIFOLD, AND OIL SCAVENGE TUBE FOR METAL-TO-METAL CONDITION Notes (AVG MAN HRS: 1)						
SB 72-0322 Engine 1 SB - Open #470	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0322 Engine 2 SB - Open #57	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0323 Engine 1 SB - Open #359	ENGINE - FAN STATOR (72-21-00) - INTRODUCTION OF NO. 1 AND NO. 2 BEARING HOUSING P/N 6047T69G05 AND SCAVENGE TUBE P/N 2799M22G01						
SB 72-0323 Engine 2 SB - Open #189	ENGINE - FAN STATOR (72-21-00) - INTRODUCTION OF NO. 1 AND NO. 2 BEARING HOUSING P/N 6047T69G05 AND SCAVENGE TUBE P/N 2799M22G01						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0324 Engine 1 SB - Open #465	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - EVALUATION OF THE STAGE 4-STAGE 5, STAGE 5-STAGE 6 LPT DISKS AND TURBINE REAR SHAFT DRIVE CONE BOLTED JOINTS Notes (AVG MAN HRS: 2)						
SB 72-0324 Engine 2 SB - Open #417	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - EVALUATION OF THE STAGE 4-STAGE 5, STAGE 5-STAGE 6 LPT DISKS AND TURBINE REAR SHAFT DRIVE CONE BOLTED JOINTS Notes (AVG MAN HRS: 2)						
SB 72-0325 Engine 1 SB - Open #655	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - REPLACEMENT OF DRIVE CONE BOLT AND SELF-RETAINING BOLT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY IF THIS SB IS APPLICABLE TO YOU, PLEASE CONTACT YOUR TRAXXALL ANALYST.)						
SB 72-0325 Engine 2 SB - Open #51	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - REPLACEMENT OF DRIVE CONE BOLT AND SELF-RETAINING BOLT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY IF THIS SB IS APPLICABLE TO YOU, PLEASE CONTACT YOUR TRAXXALL ANALYST.)						
SB 72-0325 R1 Engine 1 SB - Open #578	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - REPLACEMENT OF DRIVE CONE BOLT AND SELF-RETAINING BOLT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION. THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0325 R1 Engine 2 SB - Open #63	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - REPLACEMENT OF DRIVE CONE BOLT AND SELF-RETAINING BOLT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION. THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						
SB 72-0325 R2 Engine 1 SB - Open #288	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - REPLACEMENT OF DRIVE CONE BOLT AND SELF-RETAINING BOLT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION. THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						
SB 72-0325 R2 Engine 2 SB - Open #391	ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY (72-53-00) - REPLACEMENT OF DRIVE CONE BOLT AND SELF-RETAINING BOLT Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION. THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						
SB 72-0326 Engine 1 SB - Open #548	ENGINE - COMPRESSOR STATOR (72-32-00) - BSI OF THE COMPRESSOR MODULE WITH SPECIAL EQUIPMENT (LIMITED DISTRIBUTION SB) Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION. THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						
SB 72-0326 Engine 2 SB - Open #16	ENGINE - COMPRESSOR STATOR (72-32-00) - BSI OF THE COMPRESSOR MODULE WITH SPECIAL EQUIPMENT (LIMITED DISTRIBUTION SB) Notes (NOTE: THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION. THIS SERVICE BULLETIN DOES NOT IMPACT ALL OPERATORS AND IS APPLICABLE TO AFFECTED OPERATORS ONLY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0330 Engine 1 SB - Open #211	ENGINE - FAN STATOR ASSEMBLY (72-21-00) - INTRODUCTION OF NO. 1 AND NO. 2 BEARING HOUSING P/N 6047T69G06 AND PREFORMED PACKING P/N J1438P278 Notes (NOTE: EFFECTIVITY: THIS SERVICE BULLETIN HAS BEEN INTRODUCED IN PRODUCTION TO THESE CF34-BJ ENGINES: CF34-BJ ENGINES, SERIAL NUMBERS 801-646 AND UP. THE NO. 1 AND NO. 2 BEARING HOUSING ASSEMBLY P/N 6047T69G05 AND THE PREFORMED PACKING P/N R1310P032 ARE AFFECTED BY THIS SERVICE BULLETIN. COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN WHEN THE NO. 1 AND NO. 2 BEARING HOUSING ASSEMBLY IS EXPOSED.)						
SB 72-0330 Engine 2 SB - Open #820	ENGINE - FAN STATOR ASSEMBLY (72-21-00) - INTRODUCTION OF NO. 1 AND NO. 2 BEARING HOUSING P/N 6047T69G06 AND PREFORMED PACKING P/N J1438P278 Notes (NOTE: EFFECTIVITY: THIS SERVICE BULLETIN HAS BEEN INTRODUCED IN PRODUCTION TO THESE CF34-BJ ENGINES: CF34-BJ ENGINES, SERIAL NUMBERS 801-646 AND UP. THE NO. 1 AND NO. 2 BEARING HOUSING ASSEMBLY P/N 6047T69G05 AND THE PREFORMED PACKING P/N R1310P032 ARE AFFECTED BY THIS SERVICE BULLETIN. COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN WHEN THE NO. 1 AND NO. 2 BEARING HOUSING ASSEMBLY IS EXPOSED.)						
SB 72-0331 Engine 1 SB - Open #335	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION AND REPLACEMENT OF RING CONNECTORS						
SB 72-0331 Engine 2 SB - Open #170	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION AND REPLACEMENT OF RING CONNECTORS						
SB 72-0332 Engine 1 SB - Open #714	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION AND REPLACEMENT OF RING CONNECTORS						
SB 72-0332 Engine 2 SB - Open #760	ENGINE - COMPRESSOR STATOR ASSEMBLY (72-32-00) - INSPECTION AND REPLACEMENT OF RING CONNECTORS						
SB 72-0333 Engine 1 SB - Open #16	ENGINE - REAR MOUNT ASSEMBLY (72-44-00) - INTRODUCTION OF THRUST MOUNT ASSEMBLY P/N 6030T56G04 WITH A NEW FULLY MACHINED AFT ENGINE MOUNT LINK ASSEMBLY P/N 5023T22G04						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0333 Engine 2 SB - Open #380	ENGINE - REAR MOUNT ASSEMBLY (72-44-00) - INTRODUCTION OF THRUST MOUNT ASSEMBLY P/N 6030T56G04 WITH A NEW FULLY MACHINED AFT ENGINE MOUNT LINK ASSEMBLY P/N 5023T22G04						
SB 72-0335 Engine 1 SB - Open #130	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0335 Engine 2 SB - Open #73	GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0336 Engine 1 SB - Open #809	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0336 Engine 2 SB - Open #201	ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 72-0347 Engine 1 SB - Open #407	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK						
SB 72-0347 Engine 2 SB - Open #757	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK						
SB 72-0347 Engine 1 SB - Open #60	Par. 3.B. ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - ENGINE HEAT SOAK RESTART TEST						
	Notes (AVG MAN HRS: 1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0347 Par. 3.B. Engine 2 SB - Open #32	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - ENGINE HEAT SOAK RESTART TEST Notes (AVG MAN HRS: 1)						
SB 72-0347 Par. 3.C. Engine 1 SB - Open #265	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - INSPECTION OF COMPRESSOR CASE STAGE 6 FRONT SIDE AND STAGE 5 REAR SIDE FLOW-PATH						
SB 72-0347 Par. 3.C. Engine 2 SB - Open #719	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - INSPECTION OF COMPRESSOR CASE STAGE 6 FRONT SIDE AND STAGE 5 REAR SIDE FLOW-PATH						
SB 72-0347 Par. 3.D. and Par. 3.E. Engine 1 SB - Open #715	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - VG SYSTEM - FUNCTIONAL CHECK AND DISPOSITION OF RESULTS AND FOLLOW UP REQUIREMENTS (IF NECESSARY) Notes (AVG MAN HRS: 12)						
SB 72-0347 Par. 3.D. and Par. 3.E. Engine 2 SB - Open #707	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - VG SYSTEM - FUNCTIONAL CHECK AND DISPOSITION OF RESULTS AND FOLLOW UP REQUIREMENTS (IF NECESSARY) Notes (AVG MAN HRS: 12)						
SB 72-0347 R1 Engine 1 SB - Open #561	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK						
SB 72-0347 R1 Engine 2 SB - Open #606	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0347 R1 Par. 3.B. Engine 1 SB - Open #72	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - ENGINE HEAT SOAK RESTART TEST Notes (AVG MAN HRS: 1) (NOTE: EFFECTIVITY: PLEASE REFER TO PAR. 1.A. FOR MORE INFORMATION. COMPLIANCE: PERFORM AN ENGINE HEAT SOAK RESTART TEST ON EACH ENGINE MOUNTED ON AN AIRCRAFT PER PARAGRAPH 3.B., ENGINE HEAT SOAK RESTART TEST EVERY 3 MONTHS AFTER THE ISSUE DATE OF THIS SERVICE BULLETIN UNTIL INSPECTION FROM CASE 1 OR CASE 2 BELOW ARE COMPLETED. IF HUNG START IS DETECTED, INSPECT ENGINE PER THE APPLICABLE SEI-580, 72-00-00, SPECIAL MAINTENANCE PRACTICES, PARAGRAPH 14., VARIABLE GEOMETRY SYSTEM - MAINTENANCE PRACTICE 68 OR SEI-780, 72-00-00, MAINTENANCE PRACTICE 68.)						
SB 72-0347 R1 Par. 3.B. Engine 2 SB - Open #234	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - ENGINE HEAT SOAK RESTART TEST Notes (AVG MAN HRS: 1) (NOTE: EFFECTIVITY: PLEASE REFER TO PAR. 1.A. FOR MORE INFORMATION. COMPLIANCE: PERFORM AN ENGINE HEAT SOAK RESTART TEST ON EACH ENGINE MOUNTED ON AN AIRCRAFT PER PARAGRAPH 3.B., ENGINE HEAT SOAK RESTART TEST EVERY 3 MONTHS AFTER THE ISSUE DATE OF THIS SERVICE BULLETIN UNTIL INSPECTION FROM CASE 1 OR CASE 2 BELOW ARE COMPLETED. IF HUNG START IS DETECTED, INSPECT ENGINE PER THE APPLICABLE SEI-580, 72-00-00, SPECIAL MAINTENANCE PRACTICES, PARAGRAPH 14., VARIABLE GEOMETRY SYSTEM - MAINTENANCE PRACTICE 68 OR SEI-780, 72-00-00, MAINTENANCE PRACTICE 68.)						
SB 72-0347 R1 Par. 3.C. Engine 1 SB - Open #245	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - INSPECTION OF COMPRESSOR CASE STAGE 6 FRONT SIDE AND STAGE 5 REAR SIDE FLOW-PATH Notes (NOTE: EFFECTIVITY: PLEASE REFER TO PAR. 1.A. FOR MORE INFORMATION. APPLICABILITY: IF 12 MONTHS ROLLING AVERAGE ENGINE UTILIZATION IS LESS THAN 250 HOURS/YEAR. COMPLIANCE: CASE 1: INSPECT ENGINES INSTALLED ON AN AIRCRAFT WITHIN 12 MONTHS FROM THE ISSUE DATE OF THIS SERVICE BULLETIN PER PARAGRAPH 3., ACCOMPLISHMENT INSTRUCTIONS. NOTE: IF IT CANNOT BE DETERMINED WHICH APPLICABLE CASE APPLIES TO YOUR ENGINE DUE TO LACK OF AVAILABLE DATA, SELECT CASE 1 AS THE APPLICABLE CONDITION FOR THE ENGINE.)						
SB 72-0347 R1 Par. 3.C. Engine 2 SB - Open #176	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - INSPECTION OF COMPRESSOR CASE STAGE 6 FRONT SIDE AND STAGE 5 REAR SIDE FLOW-PATH Notes (NOTE: EFFECTIVITY: PLEASE REFER TO PAR. 1.A. FOR MORE INFORMATION. APPLICABILITY: IF 12 MONTHS ROLLING AVERAGE ENGINE UTILIZATION IS LESS THAN 250 HOURS/YEAR. COMPLIANCE: CASE 1: INSPECT ENGINES INSTALLED ON AN AIRCRAFT WITHIN 12 MONTHS FROM THE ISSUE DATE OF THIS SERVICE BULLETIN PER PARAGRAPH 3., ACCOMPLISHMENT INSTRUCTIONS. NOTE: IF IT CANNOT BE DETERMINED WHICH APPLICABLE CASE APPLIES TO YOUR ENGINE DUE TO LACK OF AVAILABLE DATA, SELECT CASE 1 AS THE APPLICABLE CONDITION FOR THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0347 R1 Par. 3.D. and Par. 3.E. Engine 1 SB - Open #903	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - VG SYSTEM - FUNCTIONAL CHECK AND DISPOSITION OF RESULTS AND FOLLOW UP REQUIREMENTS (IF NECESSARY) Notes (AVG MAN HRS: 12) (NOTE: PARAGRAPH 3.E.(2).(A).2: IF THE PRESSURE NECESSARY TO FULLY EXTEND OR FULLY RETRACT THE ACTUATOR IS EQUAL OR MORE THAN 50 PSI (345 KPA) AND EQUAL OR LESS THAN 65 PSI (448 KPA): DO THE INSPECTION AGAIN IN ACCORDANCE WITH PARAGRAPH 3.D., VG SYSTEM -FUNCTIONAL CHECK, WITHIN 6 MONTHS.)						
SB 72-0347 R1 Par. 3.D. and Par. 3.E. Engine 2 SB - Open #116	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - VG SYSTEM - FUNCTIONAL CHECK AND DISPOSITION OF RESULTS AND FOLLOW UP REQUIREMENTS (IF NECESSARY) Notes (AVG MAN HRS: 12) (NOTE: PARAGRAPH 3.E.(2).(A).2: IF THE PRESSURE NECESSARY TO FULLY EXTEND OR FULLY RETRACT THE ACTUATOR IS EQUAL OR MORE THAN 50 PSI (345 KPA) AND EQUAL OR LESS THAN 65 PSI (448 KPA): DO THE INSPECTION AGAIN IN ACCORDANCE WITH PARAGRAPH 3.D., VG SYSTEM -FUNCTIONAL CHECK, WITHIN 6 MONTHS.)						
SB 72-0347 R2 Engine 1 SB - Open #913	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK Notes (NOTE: CF34-1A/-3A/-3A2 ENGINES, SERIAL NUMBERS 350103 THROUGH 350525. CF34-3A1 ENGINES, SERIAL NUMBERS 807001 THROUGH 807661. CF34-3B ENGINES, SERIAL NUMBERS 872001 THROUGH 873999, 950000 THROUGH 950999, AND 801001 THROUGH 801714.)						
SB 72-0347 R2 Engine 2 SB - Open #845	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK Notes (NOTE: CF34-1A/-3A/-3A2 ENGINES, SERIAL NUMBERS 350103 THROUGH 350525. CF34-3A1 ENGINES, SERIAL NUMBERS 807001 THROUGH 807661. CF34-3B ENGINES, SERIAL NUMBERS 872001 THROUGH 873999, 950000 THROUGH 950999, AND 801001 THROUGH 801714.)						
SB 72-0347 R2 Par.3.B. Engine 1 SB - Complied With #937	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - ENGINE HEAT SOAK RESTART TEST Notes (AVG MAN HRS: 1)				21-APR-2026 H: 8686.90 C: 4000		



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0347 R2 Par.3.B. Engine 2 SB - Complied With #113	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - ENGINE HEAT SOAK RESTART TEST Notes (AVG MAN HRS: 1)	21-APR-2026 H: 8686.90 C: 4000					
SB 72-0347 R2 Par.3.C. Engine 1 SB - Complied With #591	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - INSPECTION OF COMPRESSOR CASE STAGE 6 FRONT SIDE AND STAGE 5 REAR SIDE FLOW-PATH	21-APR-2026 H: 8686.90 C: 4000					
SB 72-0347 R2 Par.3.C. Engine 2 SB - Complied With #671	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - INSPECTION OF COMPRESSOR CASE STAGE 6 FRONT SIDE AND STAGE 5 REAR SIDE FLOW-PATH	21-APR-2026 H: 8686.90 C: 4000					
SB 72-0347 R2 Par. 3.D. and Par. 3.E. Engine 1 SB - Open #529	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - VG SYSTEM - FUNCTIONAL CHECK AND DISPOSITION OF RESULTS AND FOLLOW UP REQUIREMENTS (IF NECESSARY) Notes (AVG MAN HRS: 12)						
SB 72-0347 R2 Par. 3.D. and Par. 3.E. Engine 2 SB - Open #475	ENGINE - GENERAL (72-00-00) - ONE-TIME COMPRESSOR INNER DIAMETER INSPECTION FOR CORROSION AND VARIABLE GEOMETRY SYSTEM FUNCTIONAL CHECK - VG SYSTEM - FUNCTIONAL CHECK AND DISPOSITION OF RESULTS AND FOLLOW UP REQUIREMENTS (IF NECESSARY) Notes (AVG MAN HRS: 12)						
SB 72-0348 Engine 1 SB - Open #862	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AGB ASSEMBLY FLAT WASHER INSTALLATION ON DEFINED POPULATION Notes (NOTE: EFFECTIVITY: PLEASE REFER TO PAR. 1.A. OF THIS SB FOR MORE INFORMATION.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-0348 Engine 2 SB - Open #357	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - AGB ASSEMBLY FLAT WASHER INSTALLATION ON DEFINED POPULATION Notes (NOTE: EFFECTIVITY: PLEASE REFER TO PAR. 1.A. OF THIS SB FOR MORE INFORMATION.)						
SB 72-0349 Engine 1 SB - Open #604	ENGINE - SB 72-0349 R00 ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34- BJ ENGINES						
SB 72-0349 Engine 2 SB - Open #849	ENGINE - SB 72-0349 R00 ENGINE - GENERAL (72-00-00) - SPARE PARTS RELEASE FOR CF34- BJ ENGINES						
SB 72-A0076 Engine 1 SB - Open #613	ENGINE - ONE-TIME TORQUE INSPECTION OF THE TOTAL TEMPERATURE AND PRESSURE BOSS CAP						
SB 72-A0076 Engine 2 SB - Open #233	ENGINE - ONE-TIME TORQUE INSPECTION OF THE TOTAL TEMPERATURE AND PRESSURE BOSS CAP						
SB 72-A0088 Engine 1 SB - Open #215	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
SB 72-A0088 Engine 2 SB - Open #389	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
SB 72-A0088 R1 Engine 1 SB - Open #4	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0088 R1 Engine 2 SB - Open #458	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
SB 72-A0088 R2 Engine 1 SB - Complied With #579	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN		12-JUL-2004 H: 2246.20				
SB 72-A0088 R2 Engine 2 SB - Complied With #510	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN		12-JUL-2004 H: 2246.20				
SB 72-A0088 R3 Engine 1 SB - Open #810	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
	Notes (NOTE: INFORMATION ONLY. GE RECOMMENDS YOU NO LONGER DO THIS ALERT SERVICE BULLETIN. THIS ALERT SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 72-A0212.)						
SB 72-A0088 R3 Engine 2 SB - Open #621	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
	Notes (NOTE: INFORMATION ONLY. GE RECOMMENDS YOU NO LONGER DO THIS ALERT SERVICE BULLETIN. THIS ALERT SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 72-A0212.)						
SB 72-A0088 R4 Engine 1 SB - Open #385	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
	Notes (NOTE: INFORMATION ONLY. GE RECOMMENDS YOU NO LONGER DO THIS ALERT SERVICE BULLETIN. THIS ALERT SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 72-A0212.)						
SB 72-A0088 R4 Engine 2 SB - Open #52	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK FIELD MANAGEMENT PLAN						
	Notes (NOTE: INFORMATION ONLY. GE RECOMMENDS YOU NO LONGER DO THIS ALERT SERVICE BULLETIN. THIS ALERT SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 72-A0212.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0136 Engine 1 SB - Open #635	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136)						
SB 72-A0136 Engine 2 SB - Open #613	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136)						
SB 72-A0136 R1 Engine 1 SB - Open #854	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136)						
SB 72-A0136 R1 Engine 2 SB - Open #198	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136)						
SB 72-A0136 R2 Engine 1 SB - Open #325	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0136 R2 Engine 2 SB - Open #337	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136)						
SB 72-A0136 R3 Engine 1 SB - N/A #536	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136).DUE TO SB 72-0197 R3	02-OCT-2009 H: 3725.60 C: 1574					
SB 72-A0136 R3 Engine 2 SB - N/A #5	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS THE BORESCOPE PLUG IS REMOVED, BUT BEFORE 4,000 FLIGHT HOURS. IF THE ENGINE HAS MORE THAN 4,000 FLIGHT HOURS, GE RECOMMENDS COMPLIANCE THE NEXT TIME THE COWL IS OPENED. IT IS RECOMMENDED THAT THE SHORTS SERVICE BULLETIN, CF34 NAC-71-033, BE CARRIED OUT CONCURRENTLY WITH CF34-BJ S/B 72-A0136).DUE TO SB 72-0197 R3	02-OCT-2009 H: 3725.60 C: 1574					
SB 72-A0136 R4 Engine 1 SB - Open #496	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-A0136 R4 Engine 2 SB - Open #10	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 72-A0136 R5 Engine 1 SB - Open #12	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (AVG MAN HRS: 0.1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0136 R5 Engine 2 SB - Open #331	ENGINE - AGB ASSEMBLY (72-62-00) - RELOCATION OF AXIS K LANYARD AND PLUG ASSEMBLY FOR HIGHER VISIBILITY FOR CF34-3A1/-3B TURBOFAN ENGINES Notes (AVG MAN HRS: 0.1)						
SB 72-A0140 Engine 1 SB - Open #179	ENGINE - COMPRESSOR ROTOR (72-33-00) - COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 FIELD MANAGEMENT PLAN Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN ON THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, PN 6078T56P03 AND PN 6078T56P04, WITH GREATER THAN 6,000 ACCUMULATED CYCLES AS FOLLOWS (REFER TO MAINTENANCE MANUAL SEI-580, CHAPTER 5-11-02 OR SEI-780, CHAPTER 5-11-02 AS APPLICABLE): (A) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT FOR THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, IS LESS THAN 22,000 PART OPERATING CYCLES-SINCE-NEW (CSN), DO AT PIECE PART EXPOSURE FOR COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 WITH GREATER THAN 6,000 ACCUMULATED CYCLES, OR AT THE CHAPTER 5 LIFE LIMIT, WHICHEVER IS LOWER. (B) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT		C: 20000			C: 20343.00	C: 16340
SB 72-A0140 Engine 2 SB - Open #65	ENGINE - COMPRESSOR ROTOR (72-33-00) - COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 FIELD MANAGEMENT PLAN Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN ON THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, PN 6078T56P03 AND PN 6078T56P04, WITH GREATER THAN 6,000 ACCUMULATED CYCLES AS FOLLOWS (REFER TO MAINTENANCE MANUAL SEI-580, CHAPTER 5-11-02 OR SEI-780, CHAPTER 5-11-02 AS APPLICABLE): (A) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT FOR THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, IS LESS THAN 22,000 PART OPERATING CYCLES-SINCE-NEW (CSN), DO AT PIECE PART EXPOSURE FOR COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 WITH GREATER THAN 6,000 ACCUMULATED CYCLES, OR AT THE CHAPTER 5 LIFE LIMIT, WHICHEVER IS LOWER. (B) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT		C: 20000			C: 20343.00	C: 16340
SB 72-A0140 R1 Engine 1 SB - Open #546	ENGINE - COMPRESSOR ROTOR (72-33-00) - COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 FIELD MANAGEMENT PLAN Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN ON THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, PN 6078T56P03 AND PN 6078T56P04, WITH GREATER THAN 6,000 ACCUMULATED CYCLES AS FOLLOWS (REFER TO MAINTENANCE MANUAL SEI-580, CHAPTER 5-11-02 OR SEI-780, CHAPTER 5-11-02 AS APPLICABLE): (A) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT FOR THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, IS LESS THAN 22,000 PART OPERATING CYCLES-SINCE-NEW (CSN), DO AT PIECE PART EXPOSURE FOR COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 WITH GREATER THAN 6,000 ACCUMULATED CYCLES, OR AT THE CHAPTER 5 LIFE LIMIT, WHICHEVER IS LOWER. (B) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT		C: 22000			C: 23332.16	C: 19329.16



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0140 R1 Engine 2 SB - Open #451	ENGINE - COMPRESSOR ROTOR (72-33-00) - COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 FIELD MANAGEMENT PLAN		C: 22000			C: 23332.16	C: 19329.16
Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN ON THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, PN 6078T56P03 AND PN 6078T56P04, WITH GREATER THAN 6,000 ACCUMULATED CYCLES AS FOLLOWS (REFER TO MAINTENANCE MANUAL SEI-580, CHAPTER 5-11-02 OR SEI-780, CHAPTER 5-11-02 AS APPLICABLE): (A) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT FOR THE AFFECTED COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8, IS LESS THAN 22,000 PART OPERATING CYCLES-SINCE-NEW (CSN), DO AT PIECE PART EXPOSURE FOR COMPRESSOR ROTOR SPOOL STAGES 3 THRU 8 WITH GREATER THAN 6,000 ACCUMULATED CYCLES, OR AT THE CHAPTER 5 LIFE LIMIT, WHICHEVER IS LOWER. (B) IF THE APPLICABLE ENGINE MANUAL CHAPTER 5 LIFE LIMIT							
SB 72-A0148 Engine 1 SB - Open #945	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT						
Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC							
SB 72-A0148 Engine 2 SB - Open #887	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT						
Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0148 R1 Engine 1 SB - Open #280	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC						
SB 72-A0148 R1 Engine 2 SB - Open #814	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC						
SB 72-A0148 R2 Engine 1 SB - Open #297	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0148 R2 Engine 2 SB - Open #166	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC						
SB 72-A0148 R3 Engine 1 SB - Complied With #784	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC	19-OCT-2009					H: 3725.60 C: 1574
SB 72-A0148 R3 Engine 2 SB - Complied With #575	ENGINE - LOW PRESSURE TURBINE (LPT) ROTOR (72-53-00) - REPLACEMENT OR INSPECTION OF STAGES 5 AND 6 LPT ROTOR DISKS AND INSPECTION OF STAGES 3 AND 4 LPT DISK ARMS FOR ARC OUT Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT PIECE PART EXPOSURE OF AFFECTED STAGE 5 AND/OR STAGE 6 LPT DISKS. NOTE: ALERT SERVICE BULLETIN CF34-BJ 72-A0152 REQUIRES REMOVAL OF LPT MODULES OR ENGINES WHICH CONTAIN STAGE 5 AND/OR STAGE 6 DISK LIST IN APPENDIX (TABLE 1 OR TABLE 2) WITHIN SPECIFIC INTERVALS, BASED ON ACCUMULATED CYCLES ON THE AFFECTED STAGE 5 AND STAGE 6 LPT DISK, FOR REPLACEMENT OR PERFORMANCE OF THE INSPECTIONS IN THIS ALERT SERVICE BULLETIN CF34-BJ 72-A0148. REFER TO ALERT SERVICE BULLETIN CF34-BJ 72-A0152, REMOVAL PLAN TO INSPECT OR REPLACE LPT DISKS FOR ARC-OUT INDICATIONS. INSPECTION LIMITATIONS: A. PRIOR TO JANUARY 1, 2010, AFFEC	19-OCT-2009					H: 3725.60 C: 1574



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0152 Engine 1 SB - Open #758	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - REMOVAL PLAN TO REPLACE OR INSPECT LPT DISKS FOR ARC-OUT INDICATIONS						
	Notes (NOTE: IT IS RECOMMENDED THAT ALL CF34-1A, -3A, -3A1, -3A2 AND CF34-3B ENGINES OR LPT MODULES, THAT HAVE THE AFFECTED STAGE 5 OR STAGE 6 LPT DISKS INSTALLED, BE REMOVED WITHIN THE FOLLOWING INTERVALS, FOR REPLACEMENT OR PERFORMANCE OF THE LPT DISK INSPECTIONS IN CF34-BJ ALERT SERVICE BULLETIN 72-A0148: (A) LPT STAGE 5 AND 6 DISKS WITH GREATER THAN OR EQUAL TO 14,750 CYCLES SINCE NEW (CSN) ON THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN AND WHICH HAVE NOT BEEN FLUORESCENT PENETRANT INSPECTED (FPI) AT A PRIOR PIECE PART EXPOSURE, PRIOR TO ACCUMULATING AN ADDITIONAL 250 CYCLES IN SERVICE (CIS) SINCE THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN. (B) LPT STAGE 5 AND 6 DISKS WITH GREATER						
SB 72-A0152 Engine 2 SB - Open #407	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - REMOVAL PLAN TO REPLACE OR INSPECT LPT DISKS FOR ARC-OUT INDICATIONS						
	Notes (NOTE: IT IS RECOMMENDED THAT ALL CF34-1A, -3A, -3A1, -3A2 AND CF34-3B ENGINES OR LPT MODULES, THAT HAVE THE AFFECTED STAGE 5 OR STAGE 6 LPT DISKS INSTALLED, BE REMOVED WITHIN THE FOLLOWING INTERVALS, FOR REPLACEMENT OR PERFORMANCE OF THE LPT DISK INSPECTIONS IN CF34-BJ ALERT SERVICE BULLETIN 72-A0148: (A) LPT STAGE 5 AND 6 DISKS WITH GREATER THAN OR EQUAL TO 14,750 CYCLES SINCE NEW (CSN) ON THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN AND WHICH HAVE NOT BEEN FLUORESCENT PENETRANT INSPECTED (FPI) AT A PRIOR PIECE PART EXPOSURE, PRIOR TO ACCUMULATING AN ADDITIONAL 250 CYCLES IN SERVICE (CIS) SINCE THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN. (B) LPT STAGE 5 AND 6 DISKS WITH GREATER						
SB 72-A0152 R1 Engine 1 SB - Complied With #774	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - REMOVAL PLAN TO REPLACE OR INSPECT LPT DISKS FOR ARC-OUT INDICATIONS	19-OCT-2009 H: 3725.60 C: 1574					
	Notes (NOTE: IT IS RECOMMENDED THAT ALL CF34-1A, -3A, -3A1, -3A2 AND CF34-3B ENGINES OR LPT MODULES, THAT HAVE THE AFFECTED STAGE 5 OR STAGE 6 LPT DISKS INSTALLED, BE REMOVED WITHIN THE FOLLOWING INTERVALS, FOR REPLACEMENT OR PERFORMANCE OF THE LPT DISK INSPECTIONS IN CF34-BJ ALERT SERVICE BULLETIN 72-A0148: (A) LPT STAGE 5 AND 6 DISKS WITH GREATER THAN OR EQUAL TO 14,750 CYCLES SINCE NEW (CSN) ON THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN AND WHICH HAVE NOT BEEN FLUORESCENT PENETRANT INSPECTED (FPI) AT A PRIOR PIECE PART EXPOSURE, PRIOR TO ACCUMULATING AN ADDITIONAL 250 CYCLES IN SERVICE (CIS) SINCE THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN. (B) LPT STAGE 5 AND 6 DISKS WITH GREATER						
SB 72-A0152 R1 Engine 2 SB - Complied With #266	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - REMOVAL PLAN TO REPLACE OR INSPECT LPT DISKS FOR ARC-OUT INDICATIONS	19-OCT-2009 H: 3725.60 C: 1574					
	Notes (NOTE: IT IS RECOMMENDED THAT ALL CF34-1A, -3A, -3A1, -3A2 AND CF34-3B ENGINES OR LPT MODULES, THAT HAVE THE AFFECTED STAGE 5 OR STAGE 6 LPT DISKS INSTALLED, BE REMOVED WITHIN THE FOLLOWING INTERVALS, FOR REPLACEMENT OR PERFORMANCE OF THE LPT DISK INSPECTIONS IN CF34-BJ ALERT SERVICE BULLETIN 72-A0148: (A) LPT STAGE 5 AND 6 DISKS WITH GREATER THAN OR EQUAL TO 14,750 CYCLES SINCE NEW (CSN) ON THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN AND WHICH HAVE NOT BEEN FLUORESCENT PENETRANT INSPECTED (FPI) AT A PRIOR PIECE PART EXPOSURE, PRIOR TO ACCUMULATING AN ADDITIONAL 250 CYCLES IN SERVICE (CIS) SINCE THE EFFECTIVE DATE OF THIS ALERT SERVICE BULLETIN. (B) LPT STAGE 5 AND 6 DISKS WITH GREATER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0152 R2 Engine 1 SB - Complied With #739	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - REMOVAL PLAN TO REPLACE OR INSPECT LPT DISKS FOR ARC-OUT INDICATIONS Notes .PREVIOUSLY						
SB 72-A0152 R2 Engine 2 SB - Complied With #180	ENGINE - LOW PRESSURE TURBINE ROTOR (72-53-00) - REMOVAL PLAN TO REPLACE OR INSPECT LPT DISKS FOR ARC-OUT INDICATIONS Notes .PREVIOUSLY						
SB 72-A0200 Engine 1 SB - Open #931	ENGINE - LOW PRESSURE TURBINE (72-53-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1)						
SB 72-A0200 Engine 2 SB - Open #7	ENGINE - LOW PRESSURE TURBINE (72-53-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1)						
SB 72-A0200 R1 Engine 1 SB - Open #565	ENGINE - LOW PRESSURE TURBINE (72-53-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0200 R1 Engine 2 SB - Open #749	ENGINE - LOW PRESSURE TURBINE (72-53-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1)						
SB 72-A0200 R2 Engine 1 SB - Complied With #722	ENGINE - LOW PRESSURE TURBINE (72-53-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1)	19-OCT-2009 H: 3725.60 C: 1574					
SB 72-A0200 R2 Engine 2 SB - Complied With #548	ENGINE - LOW PRESSURE TURBINE (72-53-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1)	19-OCT-2009 H: 3725.60 C: 1574					
SB 72-A0200 R3 Engine 1 SB - Complied With #712	ENGINE - LOW PRESSURE TURBINE (72-52-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1).PREVIOUSLY 72-A0200 R2 IS PCW, NO ACTION REQUIRED FOR R3	19-JUL-2010 H: 3903.70 C: 1663					
SB 72-A0200 R3 Engine 2 SB - Complied With #243	ENGINE - LOW PRESSURE TURBINE (72-52-00) - INSPECTION OF LPT MODULES Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT DO NOT HAVE NEW/REWORKED STAGE 3 SHROUD SECTOR P/N 5099T32G02 FEATURING AN IMPROVED INTEGRAL HEAT SHIELD AS WELL AS CF34-3A1 ENGINES THAT ARE CONVERTED TO CF34-3B1).PREVIOUSLY 72-A0200 R2 IS PCW, NO ACTION REQUIRED FOR R3	19-JUL-2010 H: 3903.70 C: 1663					
SB 72-A0200 R4 Engine 1 SB - Open #349	ENGINE - LOW PRESSURE TURBINE (72-52-00) - INSPECTION OF LPT MODULES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0200 R4 Engine 2 SB - Open #572	ENGINE - LOW PRESSURE TURBINE (72-52-00) - INSPECTION OF LPT MODULES						
SB 72-A0200 R5 Engine 1 SB - Open #916	ENGINE - LOW PRESSURE TURBINE (72-52-00) - INSPECTION OF LPT MODULES Notes (AVG MAN HRS: 4)						
SB 72-A0200 R5 Engine 2 SB - Open #806	ENGINE - LOW PRESSURE TURBINE (72-52-00) - INSPECTION OF LPT MODULES Notes (AVG MAN HRS: 4)						
SB 72-A0212 Engine 1 SB - Open #844	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS						
SB 72-A0212 Engine 2 SB - Open #416	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS						
SB 72-A0212 R1 Engine 1 SB - Open #540	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK BORE TACTILE AND VISUAL INSPECTION						
SB 72-A0212 R1 Engine 1 SB - Open #230	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS						
SB 72-A0212 R1 Engine 2 SB - Open #384	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0212 R2 Engine 1 SB - Open #500	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS						
SB 72-A0212 R2 Engine 2 SB - Open #637	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS						
SB 72-A0212 R3 Engine 1 SB - N/A #180	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes .SUPERSEDED						
SB 72-A0212 R3 Engine 2 SB - N/A #648	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes .SUPERSEDED						
SB 72-A0212 R4 Engine 1 SB - Complied With #443	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS					19-OCT-2009 H: 3725.60 C: 1574	
SB 72-A0212 R4 Engine 1 SB - Open #388	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (TIER 1)						
SB 72-A0212 R4 Engine 1 SB - Open #419	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (TIER 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0212 R4 Engine 1 SB - Open #796	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (TIER 3)						
SB 72-A0212 R4 Engine 2 SB - Open #315	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (TIER 1)						
SB 72-A0212 R4 Engine 2 SB - Open #250	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (TIER 2)						
SB 72-A0212 R4 Engine 2 SB - Complied With #231	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS					19-OCT-2009 H: 3725.60 C: 1574	
SB 72-A0212 R4 Engine 2 SB - Open #133	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (TIER 3)						
SB 72-A0212 R5 Engine 1 SB - Open #374	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 3)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0212 R5 Engine 1 SB - Open #295	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 2)						
SB 72-A0212 R5 Engine 1 SB - Open #164	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 1)						
SB 72-A0212 R5 Engine 1 SB - Open #111	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)						
SB 72-A0212 R5 Engine 2 SB - Open #141	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 3)						
SB 72-A0212 R5 Engine 2 SB - Open #274	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)						
SB 72-A0212 R5 Engine 2 SB - Open #356	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0212 R5 Engine 2 SB - Open #747	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 1)						
SB 72-A0212 R6 Engine 1 SB - Open #831	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 1)						
SB 72-A0212 R6 Engine 1 SB - Open #372	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 3)						
SB 72-A0212 R6 Engine 1 SB - Open #490	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 2)						
SB 72-A0212 R6 Engine 1 SB - Open #524	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)						
SB 72-A0212 R6 Engine 2 SB - Open #151	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0212 R6 Engine 2 SB - Open #175	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 2)						
SB 72-A0212 R6 Engine 2 SB - Open #208	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 3)						
SB 72-A0212 R6 Engine 2 SB - Open #257	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 12)(TIER 1)						
SB 72-A0213 Engine 1 SB - N/A #216	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK BORE TACTILE AND VISUAL INSPECTION Notes (NOTE: FAN DISKS ORIGINALLY INSTALLED IN ENGINES AFFECTED MAY HAVE BEEN REWORKED AND HAD THEIR PART NUMBERS REVISED. NOTE THAT THOSE PARTS WILL HAVE THE SAME, UNCHANGED, SERIAL NUMBER EVEN THOUGH THE PART NUMBER HAS BEEN REVISED.FOR ANY FAN DISK AFFECTED THAT HAS ALREADY HAD A SHOP INSPECTION PER 72-21-00 (FULL EDDY CURRENT INSPECTION (ECI) AND FLUORESCENT PENETRANT INSPECTION (FPI)), IT IS NOT NECESSARY TO PERFORM THIS REQUESTED DISK BORE INSPECTION AT THIS TIME.).BY SERIAL NUMBER			21-FEB-2007 H: 2928.20 C: 1171			
SB 72-A0213 Engine 2 SB - N/A #287	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK BORE TACTILE AND VISUAL INSPECTION Notes (NOTE: FAN DISKS ORIGINALLY INSTALLED IN ENGINES AFFECTED MAY HAVE BEEN REWORKED AND HAD THEIR PART NUMBERS REVISED. NOTE THAT THOSE PARTS WILL HAVE THE SAME, UNCHANGED, SERIAL NUMBER EVEN THOUGH THE PART NUMBER HAS BEEN REVISED.FOR ANY FAN DISK AFFECTED THAT HAS ALREADY HAD A SHOP INSPECTION PER 72-21-00 (FULL EDDY CURRENT INSPECTION (ECI) AND FLUORESCENT PENETRANT INSPECTION (FPI)), IT IS NOT NECESSARY TO PERFORM THIS REQUESTED DISK BORE INSPECTION AT THIS TIME.).BY SERIAL NUMBER			21-FEB-2007 H: 2928.20 C: 1171			



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0213 R1 Engine 2 SB - Open #43	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - FAN DISK BORE TACTILE AND VISUAL INSPECTION						
SB 72-A0234 Engine 1 SB - Open #887	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL EDDY CURRENT AND REDUNDANT TACTILE ENHANCED VISUAL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (NOTE: FAN DISKS ORIGINALLY INSTALLED IN ENGINES AFFECTED MAY HAVE BEEN REWORKED AND HAD THEIR PART NUMBERS REVISED. NOTE THAT THOSE PARTS WILL HAVE THE SAME, UNCHANGED, SERIAL NUMBER EVEN THOUGH THE PART NUMBER HAS BEEN REVISED. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES.)						
SB 72-A0234 Engine 2 SB - Open #360	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL EDDY CURRENT AND REDUNDANT TACTILE ENHANCED VISUAL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (NOTE: FAN DISKS ORIGINALLY INSTALLED IN ENGINES AFFECTED MAY HAVE BEEN REWORKED AND HAD THEIR PART NUMBERS REVISED. NOTE THAT THOSE PARTS WILL HAVE THE SAME, UNCHANGED, SERIAL NUMBER EVEN THOUGH THE PART NUMBER HAS BEEN REVISED. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES.)						
SB 72-A0234 R1 Engine 1 SB - Open #735	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL EDDY CURRENT AND REDUNDANT TACTILE ENHANCED VISUAL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 4) (NOTE: COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT SHOP VISIT. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES.)					C: 24300.00	C: 20297



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0234 R1 Engine 2 SB - Open #608	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - SHOP LEVEL EDDY CURRENT AND REDUNDANT TACTILE ENHANCED VISUAL INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 4) (NOTE: COMPLIANCE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AT THE NEXT SHOP VISIT. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES.)					C: 24300.00	C: 20297
SB 72-A0235 Engine 1 SB - N/A #364	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ON WING REPETITIVE EDDY CURRENT INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN WITHIN 3,000 CYCLES OF OPERATION FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, REPEAT THIS ALERT SERVICE BULLETIN AT INTERVALS NOT TO EXCEED 3,000 CYCLES OF OPERATION, AND REMOVE THE AFFECTED PARTS FROM SERVICE NO LATER THAN SEPTEMBER 30, 2018. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES. FOR PARTS WITH 2,500 CYCLES OF OPERATION OR MORE (AS OF THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN) FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE		07-APR-2017 H: 5984.80 C: 2580				
SB 72-A0235 Engine 2 SB - N/A #247	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ON WING REPETITIVE EDDY CURRENT INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN WITHIN 3,000 CYCLES OF OPERATION FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, REPEAT THIS ALERT SERVICE BULLETIN AT INTERVALS NOT TO EXCEED 3,000 CYCLES OF OPERATION, AND REMOVE THE AFFECTED PARTS FROM SERVICE NO LATER THAN SEPTEMBER 30, 2018. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES. FOR PARTS WITH 2,500 CYCLES OF OPERATION OR MORE (AS OF THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN) FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE		07-APR-2017 H: 5984.80 C: 2580				
SB 72-A0235 R1 Engine 1 SB - N/A #390	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ON WING REPETITIVE EDDY CURRENT INSPECTION FOR FAN DISK ARC-OUT INDICATIONS Notes (AVG MAN HRS: 2) (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN WITHIN 3,000 CYCLES OF OPERATION FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, REPEAT THIS ALERT SERVICE BULLETIN AT INTERVALS NOT TO EXCEED 3,000 CYCLES OF OPERATION, AND REMOVE THE AFFECTED PARTS FROM SERVICE NO LATER THAN SEPTEMBER 30, 2018. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES. FOR PARTS WITH 2,500 CYCLES OF OPERATION OR MORE (AS OF THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN) FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT		07-APR-2017 H: 5984.80 C: 2580				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0235 R1 Engine 2 SB - N/A #807	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ON WING REPETITIVE EDDY CURRENT INSPECTION FOR FAN DISK ARC-OUT INDICATIONS	07-APR-2017 H: 5984.80 C: 2580					
	Notes (AVG MAN HRS: 2) (NOTE: GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN WITHIN 3,000 CYCLES OF OPERATION FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, REPEAT THIS ALERT SERVICE BULLETIN AT INTERVALS NOT TO EXCEED 3,000 CYCLES OF OPERATION, AND REMOVE THE AFFECTED PARTS FROM SERVICE NO LATER THAN SEPTEMBER 30, 2018. FOR AFFECTED FAN DISKS P/N 6078T57G04, P/N 6078T57G05, AND P/N 6078T57G06 REMOVE FROM SERVICE PRIOR TO REACHING 24,300 TOTAL ACCUMULATED CYCLES. FOR PARTS WITH 2,500 CYCLES OF OPERATION OR MORE (AS OF THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN) FROM COMPLIANCE WITH CF34-BJ S/B 72-A0212, GE RECOMMENDS THAT YOU DO THIS ALERT SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT						
SB 72-A0235 R2 Engine 1 SB - N/A #656	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ON WING REPETITIVE EDDY CURRENT INSPECTION FOR FAN DISK ARC-OUT INDICATIONS	07-APR-2017 H: 5984.80 C: 2580					
	Notes (AVG MAN HRS: 2).TO THE S/N OF FAN DISK INSTALLED						
SB 72-A0235 R2 Engine 2 SB - N/A #273	ENGINE - FAN ROTOR ASSEMBLY (72-21-00) - ON WING REPETITIVE EDDY CURRENT INSPECTION FOR FAN DISK ARC-OUT INDICATIONS	07-APR-2017 H: 5984.80 C: 2580					
	Notes (AVG MAN HRS: 2).TO THE S/N OF FAN DISK INSTALLED						
SB 72-A0245 Engine 1 SB - Open #525	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - REMOVAL OF STAGE 1 HPTR REAR COOLING PLATE						
SB 72-A0245 Engine 2 SB - Open #301	ENGINE - HIGH PRESSURE TURBINE ROTOR (72-46-00) - REMOVAL OF STAGE 1 HPTR REAR COOLING PLATE						
SB 72-A0285 Engine 1 SB - Open #290	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - IDENTIFICATION AND REPLACEMENT OF SUSPECT AGB						
	Notes (AVG MAN HRS: 56)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0285 Engine 2 SB - Open #553	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - IDENTIFICATION AND REPLACEMENT OF SUSPECT AGB Notes (AVG MAN HRS: 56)						
SB 72-A0285 R1 Engine 1 SB - Open #868	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - IDENTIFICATION AND REPLACEMENT OF SUSPECT AGB						
SB 72-A0285 R1 Engine 2 SB - Open #197	ENGINE - ACCESSORY GEARBOX ASSEMBLY (72-62-00) - IDENTIFICATION AND REPLACEMENT OF SUSPECT AGB						
SB 72-A0286 Engine 1 SB - Open #580	ENGINE - AGB ASSEMBLY (72-62-00) - INSPECTION OF AGB ASSEMBLIES P/N 6014T81G26, P/N 6014T81G27, AND P/N 6014T81G28 Notes (AVG MAN HRS: 1)						
SB 72-A0286 Engine 2 SB - Open #251	ENGINE - AGB ASSEMBLY (72-62-00) - INSPECTION OF AGB ASSEMBLIES P/N 6014T81G26, P/N 6014T81G27, AND P/N 6014T81G28 Notes (AVG MAN HRS: 1)						
SB 72-A0286 R1 Engine 1 SB - Open #142	ENGINE - AGB ASSEMBLY (72-62-00) - INSPECTION OF AGB ASSEMBLIES P/N 6014T81G26, P/N 6014T81G27, AND P/N 6014T81G28						
SB 72-A0286 R1 Engine 2 SB - Open #599	ENGINE - AGB ASSEMBLY (72-62-00) - INSPECTION OF AGB ASSEMBLIES P/N 6014T81G26, P/N 6014T81G27, AND P/N 6014T81G28						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 72-A0286 R2 Engine 1 SB - N/A #61	ENGINE - AGB ASSEMBLY (72-62-00) - INSPECTION OF AGB ASSEMBLIES P/N 6014T81G26, P/N 6014T81G27, AND P/N 6014T81G28	18-MAR-2015 H: 5435.90 C: 2357					
	Notes .PER AGB ASSEMBLY DOES NOT MEET CONDITION 2 OF EFFECTIVITY .SB 72-0085 IS N/A						
SB 72-A0286 R2 Engine 2 SB - N/A #439	ENGINE - AGB ASSEMBLY (72-62-00) - INSPECTION OF AGB ASSEMBLIES P/N 6014T81G26, P/N 6014T81G27, AND P/N 6014T81G28	18-MAR-2015 H: 5435.90 C: 2357					
	Notes .PER AGB ASSEMBLY DOES NOT MEET CONDITION 2 OF EFFECTIVITY .SB 72-0085 IS N/A						
SB 73-0003 Engine 1 SB - Open #300	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 Engine 2 SB - Open #515	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R1 Engine 1 SB - Open #686	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R1 Engine 2 SB - Open #518	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R2 Engine 1 SB - Open #732	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R2 Engine 2 SB - Open #930	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0003 R3 Engine 1 SB - Open #866	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R3 Engine 2 SB - Open #219	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R4 Engine 1 SB - Open #334	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0003 R4 Engine 2 SB - Open #738	FUEL SYSTEM - SERVICING/INSPECTION (73-00-00) - USE OF FUEL SYSTEM ANTI-ICING ADDITIVE AND INSPECTION OF FUEL HEATER						
SB 73-0011 R1 Engine 1 SB - Open #173	FUEL SYSTEM - MAIN FUEL CONTROL - IMPROVED MAIN FUEL CONTROL PN 6047T74P09						
SB 73-0011 R1 Engine 2 SB - Open #161	FUEL SYSTEM - MAIN FUEL CONTROL - IMPROVED MAIN FUEL CONTROL PN 6047T74P09						
SB 73-0024 R1 Engine 1 SB - Open #551	FUEL SYSTEM - INTRODUCTION OF NEW FUEL PUMP P/N 6078T39P04 WITH CAVITATION-RESISTANT GEARS AND BEARINGS AND IMPROVED HIGH-PRESSURE RELIEF VALVE						
SB 73-0024 R1 Engine 2 SB - Open #393	FUEL SYSTEM - INTRODUCTION OF NEW FUEL PUMP P/N 6078T39P04 WITH CAVITATION-RESISTANT GEARS AND BEARINGS AND IMPROVED HIGH-PRESSURE RELIEF VALVE						
SB 73-0026 R1 Engine 1 SB - Open #429	FUEL SYSTEM - INTRODUCTION OF MAIN FUEL CONTROL PNS 6078T55P08/P09/ P10 WITH IMPROVED VG CABLE BRACKET						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0026 R1 Engine 2 SB - Open #508	FUEL SYSTEM - INTRODUCTION OF MAIN FUEL CONTROL PNS 6078T55P08/P09/ P10 WITH IMPROVED VG CABLE BRACKET						
SB 73-0027 Engine 1 SB - Open #453	FUEL SYSTEM - REPLACEMENT OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0027 Engine 2 SB - Open #327	FUEL SYSTEM - REPLACEMENT OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0027 R1 Paragr. 1,(D),(1) Engine 1 SB - Open #938	FUEL SYSTEM - INSPECTION OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0027 R1 Paragr. 1,(D),(1) Engine 2 SB - Open #99	FUEL SYSTEM - INSPECTION OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0027 R1 Engine 1 SB - Open #327	FUEL SYSTEM - INSPECTION/REPLACEMENT OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0027 R1 Engine 2 SB - Open #800	FUEL SYSTEM - INSPECTION/REPLACEMENT OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0027 R1 Paragr. 1,(D),(2) Engine 1 SB - Open #542	FUEL SYSTEM - REPLACEMENT OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0027 R1 Paragr. 1,(D),(2) Engine 2 SB - Open #878	FUEL SYSTEM - REPLACEMENT OF FUEL FILTER ASSEMBLY (PN 5071T70P01)						
SB 73-0029 Engine 1 SB - Open #302	FUEL SYSTEM - MAIN FUEL PUMP PN 6052T06P03/P05, PULSATION ELIMINATION (CANCELLED)						
SB 73-0029 Engine 2 SB - Open #230	FUEL SYSTEM - MAIN FUEL PUMP PN 6052T06P03/P05, PULSATION ELIMINATION (CANCELLED)						
SB 73-0029 R1 Engine 1 SB - Open #645	FUEL SYSTEM - MAIN FUEL PUMP PN 6052T06P03/P05, PULSATION ELIMINATION (CANCELLED)						
SB 73-0029 R1 Engine 2 SB - Open #481	FUEL SYSTEM - MAIN FUEL PUMP PN 6052T06P03/P05, PULSATION ELIMINATION (CANCELLED)						
SB 73-0029 R2 Engine 1 SB - Open #805	FUEL SYSTEM - MAIN FUEL PUMP PN 6052T06P03/P05 PULSATION ELIMINATION (CANCELLED)						
	Notes (NOTE: REVISION 2 IS ISSUED TO ADVISE OVERHAUL AND MAINTENANCE FACILITIES AND AIRCRAFT OWNERS THAT CF34-BJ S/B 73-0029 IS NO LONGER VALID. GE IS REQUESTING THAT OPERATORS NOT COMPLY WITH THIS SERVICE BULLETIN.)						
SB 73-0029 R2 Engine 2 SB - Open #523	FUEL SYSTEM - MAIN FUEL PUMP PN 6052T06P03/P05 PULSATION ELIMINATION (CANCELLED)						
	Notes (NOTE: REVISION 2 IS ISSUED TO ADVISE OVERHAUL AND MAINTENANCE FACILITIES AND AIRCRAFT OWNERS THAT CF34-BJ S/B 73-0029 IS NO LONGER VALID. GE IS REQUESTING THAT OPERATORS NOT COMPLY WITH THIS SERVICE BULLETIN.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0031 R1 Engine 1 SB - Open #615	FUEL SYSTEM - SERVICE INTRODUCTION PROGRAM FOR OPERATION OF GENERAL ELECTRIC CF34 ENGINES USING CIS FUELS AND ADDITIVES (SUPERSEDED BY VF34-BJ-0047) Notes (NOTE: THIS SERVICE BULLETIN IS REVISED TO NOTIFY USERS THAT THIS SERVICE BULLETIN HAS BEEN SUPERSEDED BY CF34-BJ 73-0047.)						
SB 73-0031 R1 Engine 2 SB - Open #609	FUEL SYSTEM - SERVICE INTRODUCTION PROGRAM FOR OPERATION OF GENERAL ELECTRIC CF34 ENGINES USING CIS FUELS AND ADDITIVES (SUPERSEDED BY VF34-BJ-0047) Notes (NOTE: THIS SERVICE BULLETIN IS REVISED TO NOTIFY USERS THAT THIS SERVICE BULLETIN HAS BEEN SUPERSEDED BY CF34-BJ 73-0047.)						
SB 73-0032 R3 Engine 1 SB - Open #328	ENGINE FUEL AND CONTROL - REWORK OF MAIN FUEL CONTROL TO ADD FORWARD FLANGE VENT GROOVE						
SB 73-0032 R3 Engine 2 SB - Open #629	ENGINE FUEL AND CONTROL - REWORK OF MAIN FUEL CONTROL TO ADD FORWARD FLANGE VENT GROOVE						
SB 73-0034 Engine 1 SB - Open #678	FUEL SYSTEM - IMPROVED PREFORMED PACKINGS ON THE MAIN FUEL CONTROL-TO-FUEL PUMP INTERFACE						
SB 73-0034 Engine 2 SB - Open #160	FUEL SYSTEM - IMPROVED PREFORMED PACKINGS ON THE MAIN FUEL CONTROL-TO-FUEL PUMP INTERFACE						
SB 73-0036 Engine 1 SB - Open #323	FUEL SYSTEM - INSPECTION OF MAIN FUEL FILTER FOR NON-TORQUED FILTER BOWL						
SB 73-0036 Engine 2 SB - Open #903	FUEL SYSTEM - INSPECTION OF MAIN FUEL FILTER FOR NON-TORQUED FILTER BOWL						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0038 Engine 1 SB - Complied With #155	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF IMPROVED AGB-TO-FUEL PUMP CLAMP COUPLING	11-MAY-2005 H: 2522.30					
SB 73-0038 Engine 2 SB - Complied With #590	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF IMPROVED AGB-TO-FUEL PUMP CLAMP COUPLING	11-MAY-2005 H: 2522.30					
SB 73-0041 Engine 1 SB - Open #74	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH RELOCATED PRESSURE-RELIEF GROOVE						
SB 73-0041 Engine 2 SB - Open #60	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH RELOCATED PRESSURE-RELIEF GROOVE						
SB 73-0041 R1 Engine 1 SB - N/A #594	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH RELOCATED PRESSURE-RELIEF GROOVE	18-APR-2008 H: 3314.40					
	Notes .BY PART NUMBER N/A DUE TO P/N 6078T55P26 MFC INSTALLED						
SB 73-0041 R1 Engine 2 SB - N/A #167	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH RELOCATED PRESSURE-RELIEF GROOVE	18-APR-2008 H: 3314.40					
	Notes .BY PART NUMBER N/A DUE TO P/N 6078T55P26 MFC INSTALLED						
SB 73-0041 R2 Engine 1 SB - Open #126	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH RELOCATED PRESSURE-RELIEF GROOVE						
SB 73-0041 R2 Engine 2 SB - Open #382	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH RELOCATED PRESSURE-RELIEF GROOVE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0042 Engine 1 SB - Open #717	ENGINE FUEL AND CONTROL - FUEL CONTROL - REPLACEMENT OF FUEL VALVE BUSHING PREFORMED PACKING						
SB 73-0042 Engine 2 SB - Open #203	ENGINE FUEL AND CONTROL - FUEL CONTROL - REPLACEMENT OF FUEL VALVE BUSHING PREFORMED PACKING						
SB 73-0042 R1 Engine 1 SB - Open #324	ENGINE FUEL AND CONTROL - FUEL CONTROL - REPLACEMENT OF FUEL VALVE BUSHING PREFORMED PACKING						
SB 73-0042 R1 Engine 2 SB - Open #743	ENGINE FUEL AND CONTROL - FUEL CONTROL - REPLACEMENT OF FUEL VALVE BUSHING PREFORMED PACKING						
SB 73-0043 Engine 1 SB - Open #259	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0043 Engine 2 SB - Open #881	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0043 R1 Engine 1 SB - Open #149	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0043 R1 Engine 2 SB - Open #433	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0043 R2 Engine 1 SB - Open #584	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0043 R2 Engine 2 SB - Open #696	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0043 R3 Engine 1 SB - Open #693	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0043 R3 Engine 2 SB - Open #284	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF VARIABLE GEOMETRY ACTUATOR PN 5050T37G01						
SB 73-0044 Engine 1 SB - Open #236	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0044 Engine 2 SB - Open #582	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0044 R1 Engine 1 SB - Open #201	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0044 R1 Engine 2 SB - Open #853	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0044 R2 Engine 1 SB - Open #383	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0044 R2 Engine 2 SB - Open #193	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0044 R3 Engine 1 SB - Open #132	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0044 R3 Engine 2 SB - Open #569	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF CF34 MAIN FUEL CONTROLS WITH PRODUCT IMPROVEMENT PACKAGE						
SB 73-0045 Engine 1 SB - Open #340	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF MODIFIED FUEL VALVE BUSHING INTO MFC						
SB 73-0045 Engine 2 SB - Open #503	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF MODIFIED FUEL VALVE BUSHING INTO MFC						
SB 73-0045 R1 Engine 1 SB - Open #867	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF MODIFIED FUEL VALVE BUSHING INTO MFC						
SB 73-0045 R1 Engine 2 SB - Open #659	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF MODIFIED FUEL VALVE BUSHING INTO MFC						
SB 73-0045 R2 Engine 1 SB - Open #926	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF MODIFIED FUEL VALVE BUSHING INTO MFC						
SB 73-0045 R2 Engine 2 SB - Open #355	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INTRODUCTION OF MODIFIED FUEL VALVE BUSHING INTO MFC						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0046 Engine 1 SB - Complied With #338	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROLS FOR THROTTLE BODY LEAKAGE Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO THESE CF34 TURBOFAN ENGINES THAT HAVE THE FOLLOWING SERIAL NUMBERS AND THAT HAVE MAIN FUEL CONTROLS (MFC) THAT HAVE NOT PREVIOUSLY COMPLIED WITH CF34-BJ SERVICE BULLETINS 73-0042 AND 73-0044, OR 73-0045).PER P/N 6078T55P26 MEETS INTENT	04-JUN-2009 H: 3637.60					
SB 73-0046 Engine 2 SB - Complied With #495	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROLS FOR THROTTLE BODY LEAKAGE Notes (NOTE: THIS SERVICE BULLETIN IS APPLICABLE TO THESE CF34 TURBOFAN ENGINES THAT HAVE THE FOLLOWING SERIAL NUMBERS AND THAT HAVE MAIN FUEL CONTROLS (MFC) THAT HAVE NOT PREVIOUSLY COMPLIED WITH CF34-BJ SERVICE BULLETINS 73-0042 AND 73-0044, OR 73-0045).PER P/N 6078T55P26 MEETS INTENT	04-JUN-2009 H: 3637.60					
SB 73-0047 Engine 1 SB - Open #47	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) CF34-1A/-3A/-3A1/-3A2/-3B TS-1 FUELS FLEET LEADER SAMPLING PROGRAM (CANCELLED)						
SB 73-0047 Engine 2 SB - Open #833	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) CF34-1A/-3A/-3A1/-3A2/-3B TS-1 FUELS FLEET LEADER SAMPLING PROGRAM (CANCELLED)						
SB 73-0047 R1 Engine 1 SB - Open #497	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - CF34-1A/-3A/-3A1/-3A2/-3B TS-1 FUELS FLEET LEADER SAMPLING PROGRAM (CANCELLED) Notes (NOTE: THIS SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 73-0060.)						
SB 73-0047 R1 Engine 2 SB - Open #255	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - CF34-1A/-3A/-3A1/-3A2/-3B TS-1 FUELS FLEET LEADER SAMPLING PROGRAM (CANCELLED) Notes (NOTE: THIS SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 73-0060.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0047 R2 Engine 1 SB - Open #170	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - CF34-1A/-3A/-3A1/-3A2/-3B TS-1 FUELS FLEET LEADER SAMPLING PROGRAM (CANCELLED) Notes (NOTE: THIS SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 73-0060.)						
SB 73-0047 R2 Engine 2 SB - Open #547	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - CF34-1A/-3A/-3A1/-3A2/-3B TS-1 FUELS FLEET LEADER SAMPLING PROGRAM (CANCELLED) Notes (NOTE: THIS SERVICE BULLETIN IS SUPERSEDED BY CF34-BJ S/B 73-0060.)						
SB 73-0048 Engine 1 SB - Open #742	ENGINE FUEL AND CONTROL - VARIABLE GEOMETRY ACTUATION SYSTEM (73-00-00) - SPARE PARTS RELEASE FOR VARIABLE GEOMETRY ACTUATOR REPAIR KIT						
SB 73-0048 Engine 2 SB - Open #574	ENGINE FUEL AND CONTROL - VARIABLE GEOMETRY ACTUATION SYSTEM (73-00-00) - SPARE PARTS RELEASE FOR VARIABLE GEOMETRY ACTUATOR REPAIR KIT						
SB 73-0049 Engine 1 SB - Open #822	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS						
SB 73-0049 Engine 2 SB - Open #708	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS						
SB 73-0049 R1 Engine 1 SB - Open #839	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS						
SB 73-0049 R1 Engine 2 SB - Open #121	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0049 R2 Engine 1 SB - N/A #214	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS Notes .BY PART NUMBER & SERIAL NUMBER						
SB 73-0049 R2 Engine 2 SB - N/A #867	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS Notes .BY PART NUMBER & SERIAL NUMBER						
SB 73-0049 R3 Engine 1 SB - Open #673	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS Notes (NOTE: IF BOTH ENGINES ON THE SAME AIRCRAFT HAVE MFCS AFFECTED, GE RECOMMENDS THAT THIS SERVICE BULLETIN BE COMPLIED WITH, ON ONE ENGINE WITHIN THE NEXT 2,000 FLIGHT HOURS OF OPERATION, BUT NOT TO EXCEED 1 YEAR FROM THE ISSUE DATE OF THIS SERVICE BULLETIN, REVISION 2, AND ON THE OTHER ENGINE WITHIN THE NEXT 4,000 FLIGHT HOURS, BUT NOT TO EXCEED 2 YEARS FROM THE ISSUE DATE OF THIS SERVICE BULLETIN, REVISION 2. FOR AIRCRAFT HAVING ONLY ONE ENGINE WITH A MFC AFFECTED, GE RECOMMENDS THAT THIS SERVICE BULLETIN BE COMPLIED WITH, ON THAT ENGINE WITHIN THE NEXT 4,000 FLIGHT HOURS, BUT NOT TO EXCEED TWO YEARS FROM THE ISSUE DATE OF THIS SERVICE BULLETIN, REVISION 2.)						
SB 73-0049 R3 Engine 2 SB - Open #200	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS Notes (NOTE: IF BOTH ENGINES ON THE SAME AIRCRAFT HAVE MFCS AFFECTED, GE RECOMMENDS THAT THIS SERVICE BULLETIN BE COMPLIED WITH, ON ONE ENGINE WITHIN THE NEXT 2,000 FLIGHT HOURS OF OPERATION, BUT NOT TO EXCEED 1 YEAR FROM THE ISSUE DATE OF THIS SERVICE BULLETIN, REVISION 2, AND ON THE OTHER ENGINE WITHIN THE NEXT 4,000 FLIGHT HOURS, BUT NOT TO EXCEED 2 YEARS FROM THE ISSUE DATE OF THIS SERVICE BULLETIN, REVISION 2. FOR AIRCRAFT HAVING ONLY ONE ENGINE WITH A MFC AFFECTED, GE RECOMMENDS THAT THIS SERVICE BULLETIN BE COMPLIED WITH, ON THAT ENGINE WITHIN THE NEXT 4,000 FLIGHT HOURS, BUT NOT TO EXCEED TWO YEARS FROM THE ISSUE DATE OF THIS SERVICE BULLETIN, REVISION 2.)						
SB 73-0051 Engine 1 SB - Open #131	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0051 Engine 2 SB - Open #429	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R1 Engine 1 SB - Open #897	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R1 Engine 2 SB - Open #462	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R2 Engine 1 SB - Open #925	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 5083T10P03 PN 5083T11P03 PN 5083T12P03 PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R2 Engine 2 SB - Open #861	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 5083T10P03 PN 5083T11P03 PN 5083T12P03 PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R3 Engine 1 SB - Open #127	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 5083T10P03 PN 5083T11P03 PN 5083T12P03 PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0051 R3 Engine 2 SB - Open #829	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 5083T10P03 PN 5083T11P03 PN 5083T12P03 PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R4 Engine 1 SB - Open #50	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 5083T10P03 PN 5083T11P03 PN 5083T12P03 PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0051 R4 Engine 2 SB - Open #737	FUEL SYSTEM - FUEL MANIFOLD (73-00-00) - INTRODUCTION OF FUEL INJECTORS PN 5083T10P03 PN 5083T11P03 PN 5083T12P03 PN 6078T63P07 AND PN 6078T64P07 Notes (NOTE: GE RECOMMENDS YOU DO THIS SERVICE BULLETIN AT NEXT SHOP VISIT FIELD OR OVERHAUL, BEYOND 10,000 HOURS, OF THE ENGINE.)						
SB 73-0052 Engine 1 SB - Open #853	FUEL SYSTEM - (730000) ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT						
SB 73-0052 Engine 2 SB - Open #168	FUEL SYSTEM - (730000) ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT						
SB 73-0052 R1 Engine 1 SB - Open #740	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0052 R1 Engine 2 SB - Open #597	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						
SB 73-0052 R2 Engine 1 SB - Open #929	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						
SB 73-0052 R2 Engine 2 SB - Open #300	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						
SB 73-0052 R3 Engine 1 SB - Open #653	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						
SB 73-0052 R3 Engine 2 SB - Open #214	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						
SB 73-0052 R4 Engine 1 SB - Open #690	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0052 R4 Engine 2 SB - Open #863	FUEL SYSTEM - (73-00-00) - ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT Notes (NOTE: REVISION 04 INFORMS AIRCRAFT OWNERS THAT SERVICE BULLETIN CF34-BJ S/B 73-0052 HAS BEEN SUPERSEDED BY SERVICE BULLETIN CF34-BJ S/B 73-0057.)						
SB 73-0054 Engine 1 SB - Open #762	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF LOOP-CUSHIONED CLAMP PN J1220G18 FOR IMPROVED VG ACTUATOR HOSE CLAMPING Notes (NOTE: FOR THOSE ENGINES THAT HAVE THE IMPROVED VARIABLE GEOMETRY (VG) ACTUATOR HOSES INSTALLED PER THE ORIGINAL ISSUE OR REVISION 1 OF CF34-BJ S/B 73-0052, THIS SERVICE BULLETIN MUST BE COMPLIED WITH AT THE NEXT OPPORTUNITY.)						
SB 73-0054 Engine 2 SB - Open #404	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF LOOP-CUSHIONED CLAMP PN J1220G18 FOR IMPROVED VG ACTUATOR HOSE CLAMPING Notes (NOTE: FOR THOSE ENGINES THAT HAVE THE IMPROVED VARIABLE GEOMETRY (VG) ACTUATOR HOSES INSTALLED PER THE ORIGINAL ISSUE OR REVISION 1 OF CF34-BJ S/B 73-0052, THIS SERVICE BULLETIN MUST BE COMPLIED WITH AT THE NEXT OPPORTUNITY.)						
SB 73-0054 R1 Engine 1 SB - Open #11	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF LOOP-CUSHIONED CLAMP PN J1220G18 FOR IMPROVED VG ACTUATOR HOSE CLAMPING Notes (NOTE: FOR THOSE ENGINES THAT HAVE THE IMPROVED VARIABLE GEOMETRY (VG) ACTUATOR HOSES INSTALLED PER THE ORIGINAL ISSUE OR REVISION 1 OF CF34-BJ S/B 73-0052, THIS SERVICE BULLETIN MUST BE COMPLIED WITH AT THE NEXT OPPORTUNITY.)						
SB 73-0054 R1 Engine 2 SB - Open #339	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF LOOP-CUSHIONED CLAMP PN J1220G18 FOR IMPROVED VG ACTUATOR HOSE CLAMPING Notes (NOTE: FOR THOSE ENGINES THAT HAVE THE IMPROVED VARIABLE GEOMETRY (VG) ACTUATOR HOSES INSTALLED PER THE ORIGINAL ISSUE OR REVISION 1 OF CF34-BJ S/B 73-0052, THIS SERVICE BULLETIN MUST BE COMPLIED WITH AT THE NEXT OPPORTUNITY.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0054 R2 Engine 1 SB - Open #217	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF LOOP-CUSHIONED CLAMP P/N J1220G18 FOR IMPROVED VG ACTUATOR HOSE CLAMPING Notes (NOTE: FOR THOSE ENGINES THAT HAVE THE IMPROVED VARIABLE GEOMETRY (VG) ACTUATOR HOSES INSTALLED PER THE ORIGINAL ISSUE OR REVISION 1 OF CF34-BJ S/B 73-0052, THIS SERVICE BULLETIN MUST BE COMPLIED WITH AT THE NEXT OPPORTUNITY.)						
SB 73-0054 R2 Engine 2 SB - Open #172	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF LOOP-CUSHIONED CLAMP P/N J1220G18 FOR IMPROVED VG ACTUATOR HOSE CLAMPING Notes (NOTE: FOR THOSE ENGINES THAT HAVE THE IMPROVED VARIABLE GEOMETRY (VG) ACTUATOR HOSES INSTALLED PER THE ORIGINAL ISSUE OR REVISION 1 OF CF34-BJ S/B 73-0052, THIS SERVICE BULLETIN MUST BE COMPLIED WITH AT THE NEXT OPPORTUNITY.)						
SB 73-0055 R1 Engine 1 SB - Open #416	ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT						
SB 73-0055 R1 Engine 2 SB - Open #949	ACTUATOR HOSE FIRE SLEEVE IMPROVEMENT						
SB 73-0056 Engine 1 SB - Open #919	INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0056 Engine 2 SB - Open #511	INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 Engine 1 SB - Open #129	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 Engine 2 SB - Open #632	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0057 R1 Engine 1 SB - Open #944	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R1 Engine 2 SB - Open #222	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R2 Engine 1 SB - Open #68	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R2 Engine 2 SB - Open #730	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R3 Engine 1 SB - Open #755	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R3 Engine 2 SB - Open #450	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R4 Engine 1 SB - Open #18	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0057 R4 Engine 2 SB - Open #15	FUEL SYSTEM - (73-00-00) - INTRODUCTION OF IMPROVED VG ACTUATOR HOSE (FINAL FIX)						
SB 73-0059 Engine 1 SB - Open #430	FUEL SYSTEM - (73-00-00) - MAIN FUEL CONTROL (MFC) - CDP RESTORING SPRING INSPECTION ON BUSINESS JET MODELS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0059 Engine 2 SB - Open #177	FUEL SYSTEM - (73-00-00) - MAIN FUEL CONTROL (MFC) - CDP RESTORING SPRING INSPECTION ON BUSINESS JET MODELS						
SB 73-0059 R1 Engine 1 SB - Open #125	FUEL SYSTEM - (73-00-00) - MAIN FUEL CONTROL (MFC) - CDP RESTORING SPRING INSPECTION ON BUSINESS JET MODELS						
SB 73-0059 R1 Engine 2 SB - Open #17	FUEL SYSTEM - (73-00-00) - MAIN FUEL CONTROL (MFC) - CDP RESTORING SPRING INSPECTION ON BUSINESS JET MODELS						
SB 73-0059 R2 Engine 1 SB - Open #837	FUEL SYSTEM - (73-00-00) - MAIN FUEL CONTROL (MFC) - CDP RESTORING SPRING INSPECTION ON BUSINESS JET MODELS						
SB 73-0059 R2 Engine 2 SB - Open #95	FUEL SYSTEM - (73-00-00) - MAIN FUEL CONTROL (MFC) - CDP RESTORING SPRING INSPECTION ON BUSINESS JET MODELS						
SB 73-0060 Engine 1 SB - Open #936	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 Engine 2 SB - Open #80	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R1 Engine 1 SB - Open #205	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R1 Engine 2 SB - Open #934	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0060 R2 Engine 1 SB - Open #824	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R2 Engine 2 SB - Open #329	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R3 Engine 1 SB - Open #943	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R3 Engine 2 SB - Open #943	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R4 Engine 1 SB - Open #312	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R4 Engine 2 SB - Open #634	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R5 Engine 1 SB - Open #384	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R5 Engine 2 SB - Open #64	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVES - REQUIREMENTS FOR, AND APPROVAL OF						
SB 73-0060 R6 Engine 1 SB - Open #232	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVE REQUIREMENTS AND RESTRICTIONS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0060 R6 Engine 2 SB - Open #567	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - FUEL AND ADDITIVE REQUIREMENTS AND RESTRICTIONS						
SB 73-0062 Engine 1 SB - Open #506	ENGINE - FUEL SYSTEM (73-00-00) - INSPECTION OF CONNECTION ORIENTATION BETWEEN THE AFT ACTUATOR HEAD HOSE ASSEMBLY AND THE MAIN FUEL CONTROL						
SB 73-0062 Engine 2 SB - Open #628	ENGINE - FUEL SYSTEM (73-00-00) - INSPECTION OF CONNECTION ORIENTATION BETWEEN THE AFT ACTUATOR HEAD HOSE ASSEMBLY AND THE MAIN FUEL CONTROL						
SB 73-0062 R1 Engine 1 SB - Open #186	ENGINE - FUEL SYSTEM (73-00-00) - INSPECTION OF CONNECTION ORIENTATION BETWEEN THE AFT ACTUATOR HEAD HOSE ASSEMBLY AND THE MAIN FUEL CONTROL						
SB 73-0062 R1 Engine 2 SB - Open #154	ENGINE - FUEL SYSTEM (73-00-00) - INSPECTION OF CONNECTION ORIENTATION BETWEEN THE AFT ACTUATOR HEAD HOSE ASSEMBLY AND THE MAIN FUEL CONTROL						
SB 73-0062 R2 Engine 1 SB - Open #781	ENGINE - FUEL SYSTEM (73-00-00) - INSPECTION OF CONNECTION ORIENTATION BETWEEN THE AFT ACTUATOR HEAD HOSE ASSEMBLY AND THE MAIN FUEL CONTROL						
SB 73-0063 Engine 1 SB - Open #316	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF HIGH TIME FUEL VALVE THRUST BUSHING AND CLIP						
Notes (NOTE: BASED ON FIELD EVENT HISTORY, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE ACCOMPLISHED BEFORE THE MFC THRUST BUSHING AND CLIP HAVE ACCUMULATED MORE THAN 10,000 HOURS OF FIELD SERVICE. IF UTILIZATION HISTORY (HOURS) OF THE BUSHING AND CLIP ARE UNKNOWN, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE INCORPORATED AT THE NEXT MFC SHOP VISIT. DESIGN IMPROVEMENTS INTRODUCED PER CF34-BJ S/B 73-0044 ARE AVAILABLE FOR SOME MODELS AND WOULD ELIMINATE THE NEED FOR THIS SERVICE BULLETIN. IF CF34-BJ S/B 73-0044 IS NOT ACCOMPLISHED OR IS NOT APPLICABLE, THIS SERVICE BULLETIN SHOULD CONTINUE TO BE REPEATED PER THE DESCRIBED COMPLIANCE RECOMMENDATION.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0063 Engine 2 SB - Open #792	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF HIGH TIME FUEL VALVE THRUST BUSHING AND CLIP Notes (NOTE: BASED ON FIELD EVENT HISTORY, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE ACCOMPLISHED BEFORE THE MFC THRUST BUSHING AND CLIP HAVE ACCUMULATED MORE THAN 10,000 HOURS OF FIELD SERVICE. IF UTILIZATION HISTORY (HOURS) OF THE BUSHING AND CLIP ARE UNKNOWN, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE INCORPORATED AT THE NEXT MFC SHOP VISIT. DESIGN IMPROVEMENTS INTRODUCED PER CF34-BJ S/B 73-0044 ARE AVAILABLE FOR SOME MODELS AND WOULD ELIMINATE THE NEED FOR THIS SERVICE BULLETIN. IF CF34-BJ S/B 73-0044 IS NOT ACCOMPLISHED OR IS NOT APPLICABLE, THIS SERVICE BULLETIN SHOULD CONTINUE TO BE REPEATED PER THE DESCRIBED COMPLIANCE RECOMMENDATION.)						
SB 73-0063 R1 Engine 1 SB - Open #704	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF HIGH TIME FUEL VALVE THRUST BUSHING AND CLIP Notes (NOTE: BASED ON FIELD EVENT HISTORY, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE ACCOMPLISHED BEFORE THE MFC THRUST BUSHING AND CLIP HAVE ACCUMULATED MORE THAN 10,000 HOURS OF FIELD SERVICE. IF UTILIZATION HISTORY (HOURS) OF THE BUSHING AND CLIP ARE UNKNOWN, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE INCORPORATED AT THE NEXT MFC SHOP VISIT. DESIGN IMPROVEMENTS INTRODUCED PER CF34-BJ S/B 73-0044 ARE AVAILABLE FOR SOME MODELS AND WOULD ELIMINATE THE NEED FOR THIS SERVICE BULLETIN. IF CF34-BJ S/B 73-0044 IS NOT ACCOMPLISHED OR IS NOT APPLICABLE, THIS SERVICE BULLETIN SHOULD CONTINUE TO BE REPEATED PER THE DESCRIBED COMPLIANCE RECOMMENDATION.)		H: 10000.00			H: 10000.00	H: 1304.90
SB 73-0063 R1 Engine 2 SB - Open #132	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF HIGH TIME FUEL VALVE THRUST BUSHING AND CLIP Notes (NOTE: BASED ON FIELD EVENT HISTORY, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE ACCOMPLISHED BEFORE THE MFC THRUST BUSHING AND CLIP HAVE ACCUMULATED MORE THAN 10,000 HOURS OF FIELD SERVICE. IF UTILIZATION HISTORY (HOURS) OF THE BUSHING AND CLIP ARE UNKNOWN, IT IS RECOMMENDED THAT THIS SERVICE BULLETIN BE INCORPORATED AT THE NEXT MFC SHOP VISIT. DESIGN IMPROVEMENTS INTRODUCED PER CF34-BJ S/B 73-0044 ARE AVAILABLE FOR SOME MODELS AND WOULD ELIMINATE THE NEED FOR THIS SERVICE BULLETIN. IF CF34-BJ S/B 73-0044 IS NOT ACCOMPLISHED OR IS NOT APPLICABLE, THIS SERVICE BULLETIN SHOULD CONTINUE TO BE REPEATED PER THE DESCRIBED COMPLIANCE RECOMMENDATION.)		H: 10000.00			H: 10000.00	H: 1304.90
SB 73-0064 Engine 1 SB - Open #187	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF MIN SPEED ADJUSTMENT LEVER						
SB 73-0064 Engine 2 SB - Open #11	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF MIN SPEED ADJUSTMENT LEVER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0064 R1 Engine 1 SB - Open #894	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF MIN SPEED ADJUSTMENT LEVER Notes (AVG MAN HRS: 2)						
SB 73-0064 R1 Engine 2 SB - Open #721	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF MIN SPEED ADJUSTMENT LEVER Notes (AVG MAN HRS: 2)						
SB 73-0065 Engine 1 SB - Open #672	ENGINE FUEL AND CONTROL - FUEL CONTROL (73-00-00) - REPLACEMENT OF MFC GOVERNOR/CDP BODY Notes (AVG MAN HRS: 1)						
SB 73-0065 Engine 2 SB - Open #844	ENGINE FUEL AND CONTROL - FUEL CONTROL (73-00-00) - REPLACEMENT OF MFC GOVERNOR/CDP BODY Notes (AVG MAN HRS: 1)						
SB 73-0065 R1 Engine 1 SB - Open #101	ENGINE FUEL AND CONTROL - FUEL CONTROL (73-00-00) - REPLACEMENT OF MFC GOVERNOR/CDP BODY Notes (AVG MAN HRS: 1)						
SB 73-0065 R1 Engine 2 SB - Open #633	ENGINE FUEL AND CONTROL - FUEL CONTROL (73-00-00) - REPLACEMENT OF MFC GOVERNOR/CDP BODY Notes (AVG MAN HRS: 1)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0066 Engine 1 SB - Open #922	SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 73-0066 Engine 2 SB - Open #714	SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 73-0067 Engine 1 SB - Open #482	ENGINE FUEL AND CONTROL - VARIABLE GEOMETRY LINKAGE ACTUATION SYSTEM (73-00-00) - INSPECTION AND RETORQUE OF VG ACTUATOR PLAIN NUT Notes (AVG MAN HRS: 1.5)						
SB 73-0067 Engine 2 SB - Open #367	ENGINE FUEL AND CONTROL - VARIABLE GEOMETRY LINKAGE ACTUATION SYSTEM (73-00-00) - INSPECTION AND RETORQUE OF VG ACTUATOR PLAIN NUT Notes (AVG MAN HRS: 1.5)						
SB 73-0067 R1 Engine 1 SB - Open #468	ENGINE FUEL AND CONTROL - VARIABLE GEOMETRY LINKAGE ACTUATION SYSTEM (73-00-00) - INSPECTION AND RETORQUE OF VG ACTUATOR PLAIN NUT Notes (AVG MAN HRS: 2)						
SB 73-0067 R1 Engine 2 SB - Open #109	ENGINE FUEL AND CONTROL - VARIABLE GEOMETRY LINKAGE ACTUATION SYSTEM (73-00-00) - INSPECTION AND RETORQUE OF VG ACTUATOR PLAIN NUT Notes (AVG MAN HRS: 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-0069 Engine 1 SB - Open #472	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SUSPECTED NON-CONFORMING MFC Notes (AVG MAN HRS: 12)						
SB 73-0069 Engine 2 SB - Open #2	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF SUSPECTED NON-CONFORMING MFC Notes (AVG MAN HRS: 12)						
SB 73-34 R Engine 1 SB - Complied With #852	IMPROV PREFORM PACKING ON MAIN FUEL CONTROL-FUEL PUMP INTRFAC					13-APR-2013 H: 4782.30 C: 2063	
SB 73-34 R Engine 2 SB - Complied With #21	IMPROV PREFORM PACKING ON MAIN FUEL CONTROL-FUEL PUMP INTRFAC					13-APR-2013 H: 4782.30 C: 2063	
SB 73-A0032 R2 Engine 1 SB - Open #367	ENGINE FUEL AND CONTROL - REWORK OF MAIN FUEL CONTROL TO ADD FORWARD FLANGE VENT GROOVE						
SB 73-A0032 R2 Engine 2 SB - Open #638	ENGINE FUEL AND CONTROL - REWORK OF MAIN FUEL CONTROL TO ADD FORWARD FLANGE VENT GROOVE						
SB 73-A0033 Engine 1 SB - Open #736	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 Engine 2 SB - Open #862	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0033 R1 Engine 1 SB - Open #788	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R1 Engine 2 SB - Open #202	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R2 Engine 1 SB - Open #681	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R2 Engine 2 SB - Open #813	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R3 Engine 1 SB - Open #814	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R3 Engine 2 SB - Open #125	ENGINE FUEL AND CONTROL - FUEL SYSTEM (730000) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R4 Engine 1 SB - N/A #911	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
	Notes .SUPERSEDED						
SB 73-A0033 R4 Engine 2 SB - N/A #581	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
	Notes .SUPERSEDED						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0033 R5 Engine 1 SB - Open #689	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R5 Engine 2 SB - Open #290	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
SB 73-A0033 R6 Engine 1 SB - Complied With #769	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION	26-MAY-2005 H: 2522.30					
SB 73-A0033 R6 Engine 2 SB - Complied With #644	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION	07-JUN-2005 H: 2522.30					
SB 73-A0033 R7 Engine 1 SB - Complied With #828	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
	Notes .PREVIOUSLY						
SB 73-A0033 R7 Engine 2 SB - Complied With #871	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REWORK OF MAIN FUEL CONTROL FOR OVERSPEED PROTECTION						
	Notes .PREVIOUSLY						
SB 73-A0037 Engine 1 SB - Open #935	FUEL SYSTEM - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS						
SB 73-A0037 Engine 2 SB - Open #560	FUEL SYSTEM - REPLACEMENT OF SELECTED CF34 MAIN FUEL CONTROLS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0039 Engine 1 SB - Open #207	FUEL SYSTEM - INSPECTION AND REPLACEMENT OF MAIN FUEL FILTER PN 4106T62P01						
SB 73-A0039 Engine 2 SB - Open #372	FUEL SYSTEM - INSPECTION AND REPLACEMENT OF MAIN FUEL FILTER PN 4106T62P01						
SB 73-A0040 Engine 1 SB - Open #747	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF BUNA-N MATERIAL PREFORMED PACKING Notes (NOTE: THE IMPROVEMENT DESCRIBED IN THIS SERVICE BULLETIN HAS BEEN INTRODUCED ON THESE CF34 TURBOFAN PRODUCTION ENGINES. HOWEVER, IF THE MAIN FUEL CONTROL WAS REPLACED IN THE FIELD USING BUNA-N MATERIAL PREFORMED PACKINGS, THE PACKINGS MUST BE REPLACED. CF34-3A1 ENGINES, SERIAL NUMBERS 807515 AND UP CF34-3B ENGINES, SERIAL NUMBERS 872272 AND UP.)						
SB 73-A0040 Engine 2 SB - Open #858	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - REPLACEMENT OF BUNA-N MATERIAL PREFORMED PACKING Notes (NOTE: THE IMPROVEMENT DESCRIBED IN THIS SERVICE BULLETIN HAS BEEN INTRODUCED ON THESE CF34 TURBOFAN PRODUCTION ENGINES. HOWEVER, IF THE MAIN FUEL CONTROL WAS REPLACED IN THE FIELD USING BUNA-N MATERIAL PREFORMED PACKINGS, THE PACKINGS MUST BE REPLACED. CF34-3A1 ENGINES, SERIAL NUMBERS 807515 AND UP CF34-3B ENGINES, SERIAL NUMBERS 872272 AND UP.)						
SB 73-A0050 Engine 1 SB - N/A #518	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -	26-MAY-2005 H: 2522.30					
SB 73-A0050 Engine 2 SB - N/A #516	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0050 R1 Engine 1 SB - N/A #307	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -						
SB 73-A0050 R1 Engine 2 SB - N/A #780	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -	07-JUN-2005 H: 2522.30					
SB 73-A0050 R10 Engine 1 SB - Open #522	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes (AVG MAN HRS: 25) (NOTE: CHINA, INDIA, NORTH AMERICA:. INSPECT AT EVERY SHOP VISIT OR 20,000 OPERATING HOURS, WHICHEVER OCCURS LATER. IF THE AIRCRAFT IS RE-FUELED IN THE ASIAN REGION MORE THAN 50 PERCENT OF THE TIME SINCE THE INITIAL SERVICE BULLETIN INSPECTION, RE-INSPECT PER THE ASIAN REGION INSPECTION INTERVALS. IF THE AIRCRAFT IS RE-FUELED OUTSIDE THIS REGION SINCE THE INITIAL SERVICE BULLETIN INSPECTION, AND HAS NOT BEEN OPERATED IN THE ASIAN REGION, RE-INSPECT EVERY 10,000 OPERATING HOURS)		H: 20000.00			H: 25823.20	H: 17128.10
SB 73-A0050 R10 Engine 2 SB - Open #526	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes (AVG MAN HRS: 25) (NOTE: CHINA, INDIA, NORTH AMERICA:. INSPECT AT EVERY SHOP VISIT OR 20,000 OPERATING HOURS, WHICHEVER OCCURS LATER. IF THE AIRCRAFT IS RE-FUELED IN THE ASIAN REGION MORE THAN 50 PERCENT OF THE TIME SINCE THE INITIAL SERVICE BULLETIN INSPECTION, RE-INSPECT PER THE ASIAN REGION INSPECTION INTERVALS. IF THE AIRCRAFT IS RE-FUELED OUTSIDE THIS REGION SINCE THE INITIAL SERVICE BULLETIN INSPECTION, AND HAS NOT BEEN OPERATED IN THE ASIAN REGION, RE-INSPECT EVERY 10,000 OPERATING HOURS)		H: 20000.00			H: 25823.20	H: 17128.10
SB 73-A0050 R2 Engine 1 SB - N/A #51	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -	H: 0.00					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0050 R2 Engine 2 SB - N/A #570	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -	H: 0.00					
SB 73-A0050 R3 Engine 1 SB - N/A #543	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -						
SB 73-A0050 R3 Engine 2 SB - N/A #854	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .SUPERSEDED -						
SB 73-A0050 R4 Engine 1 SB - Complied With #113	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .PCW BY REV 1 OF SAME BULLETIN REPEAT INSPECTION DONE AT NEXT SHOP VISIT	13-OCT-2009 H: 3725.60 C: 1574					
SB 73-A0050 R4 Engine 2 SB - Complied With #79	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .PCW BY REV 1 OF SAME BULLETIN REPEAT INSPECTION DONE AT NEXT SHOP VISIT	13-OCT-2009 H: 3725.60 C: 1574					
SB 73-A0050 R5 Engine 1 SB - Open #29	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO ALL CF34-1A, -3A, -3A1, -3A2, -3B, TURBOFAN ENGINE MAIN FUEL CONTROLS (MFCS) AND MAIN FUEL PUMPS (MFPS). THESE REGIONS APPLY TO OPERATORS RE-FUELING IN THAT REGION MORE THAN 50 PERCENT OF THE TIME. FOR MFCS THAT HAVE ALREADY ACCUMULATED THE OPERATING HOURS BELOW, DO WITHIN 500 OPERATING HOURS FROM THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN. (B) REPEAT THIS SERVICE BULLETIN INSPECTION PROCEDURE AT INTERVA						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0050 R5 Engine 2 SB - Open #209	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO ALL CF34-1A, -3A, -3A1, -3A2, -3B, TURBOFAN ENGINE MAIN FUEL CONTROLS (MFCS) AND MAIN FUEL PUMPS (MFPS). THESE REGIONS APPLY TO OPERATORS RE-FUELING IN THAT REGION MORE THAN 50 PERCENT OF THE TIME. FOR MFCS THAT HAVE ALREADY ACCUMULATED THE OPERATING HOURS BELOW, DO WITHIN 500 OPERATING HOURS FROM THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN. (B) REPEAT THIS SERVICE BULLETIN INSPECTION PROCEDURE AT INTERVAL						
SB 73-A0050 R6 Engine 1 SB - Open #833	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE						
SB 73-A0050 R6 Engine 2 SB - Open #946	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE						
SB 73-A0050 R7 Engine 1 SB - Complied With #65	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE						
SB 73-A0050 R7 Engine 2 SB - Complied With #622	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE						
SB 73-A0050 R8 Engine 1 SB - Open #621	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO ALL CF34-1A, -3A, -3A1, -3A2, -3B, TURBOFAN ENGINE MAIN FUEL CONTROLS (MFCS) AND MAIN FUEL PUMPS (MFPS). THESE REGIONS APPLY TO OPERATORS RE-FUELING IN THAT REGION MORE THAN 50 PERCENT OF THE TIME. FOR MFCS THAT HAVE ALREADY ACCUMULATED THE OPERATING HOURS BELOW, DO WITHIN 500 OPERATING HOURS FROM THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN. (B) REPEAT THIS SERVICE BULLETIN INSPECTION PROCEDURE AT INTERVAL						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 73-A0050 R8 Engine 2 SB - Open #342	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes (NOTE: THIS ALERT SERVICE BULLETIN IS APPLICABLE TO ALL CF34-1A, -3A, -3A1, -3A2, -3B, TURBOFAN ENGINE MAIN FUEL CONTROLS (MFCS) AND MAIN FUEL PUMPS (MFPS). THESE REGIONS APPLY TO OPERATORS RE-FUELING IN THAT REGION MORE THAN 50 PERCENT OF THE TIME. FOR MFCS THAT HAVE ALREADY ACCUMULATED THE OPERATING HOURS BELOW, DO WITHIN 500 OPERATING HOURS FROM THE ISSUE DATE OF THIS ALERT SERVICE BULLETIN. (B) REPEAT THIS SERVICE BULLETIN INSPECTION PROCEDURE AT INTERVALS OF 500 OPERATING HOURS.)						
SB 73-A0050 R9 Engine 1 SB - Complied With #264	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .REVISION 7 P/C/W 4/12/13.	12-APR-2013 H: 4782.30 C: 2063					
SB 73-A0050 R9 Engine 2 SB - Complied With #350	ENGINE FUEL AND CONTROL - FUEL SYSTEM (73-00-00) - INSPECTION OF MAIN FUEL CONTROL INPUT DRIVE SHAFT SPLINE MAIN FUEL PUMP CONTROL DRIVE SHAFT SPLINE AND MAIN FUEL PUMP SECONDARY DRIVE SHAFT SPLINE Notes .REVISION 7 P/C/W 4/12/13.	12-APR-2013 H: 4782.30 C: 2063					
SB 73-A0068 Engine 1 SB - Open #239	ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SUSPENSION OF THE USE OF KATHON FP 1.5 BIOCIDES TREATMENT Notes (NOTE: NOTE: PLEASE SEE COMPLIANCE.)						
SB 73-A0068 Engine 2 SB - Open #333	ENGINE FUEL AND CONTROL - GENERAL (73-00-00) - SUSPENSION OF THE USE OF KATHON FP 1.5 BIOCIDES TREATMENT Notes (NOTE: NOTE: PLEASE SEE COMPLIANCE.)						
SB 74-0002 R2 Engine 1 SB - Open #801	ELECTRICAL SYSTEM - INSTALLATION OF N2 ELECTRICAL FILTER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 74-0002 R2 Engine 2 SB - Open #235	ELECTRICAL SYSTEM - INSTALLATION OF N2 ELECTRICAL FILTER						
SB 74-0007 Engine 1 SB - Open #199	ELECTRICAL SYSTEM - UPGRADE OF THE ENGINE IGNITION LEADS						
SB 74-0007 Engine 2 SB - Open #364	ELECTRICAL SYSTEM - UPGRADE OF THE ENGINE IGNITION LEADS						
SB 74-0008 Engine 1 SB - Open #804	ELECTRICAL SYSTEM - REPLACEMENT OF THE GREEN JUMPER CABLE ON CF34-3A2 ENGINES						
SB 74-0008 Engine 2 SB - Open #917	ELECTRICAL SYSTEM - REPLACEMENT OF THE GREEN JUMPER CABLE ON CF34-3A2 ENGINES						
SB 74-0009 Engine 1 SB - Open #410	ELECTRICAL SYSTEM - IGNITION EXCITER REPLACEMENT						
SB 74-0009 Engine 2 SB - Open #596	ELECTRICAL SYSTEM - IGNITION EXCITER REPLACEMENT						
SB 74-0011 Engine 1 SB - Open #860	IGNITION - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF IMPROVED W2 BLUE CABLE ASSEMBLY						
SB 74-0011 Engine 2 SB - Open #106	IGNITION - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF IMPROVED W2 BLUE CABLE ASSEMBLY						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 74-0012 Engine 1 SB - Open #368	ENGINE - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW N1 CONTROL AMPLIFIER PN 5071T98P05 WITH A CIRCUIT BOARD REDESIGN						
SB 74-0012 Engine 2 SB - Open #56	ENGINE - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW N1 CONTROL AMPLIFIER PN 5071T98P05 WITH A CIRCUIT BOARD REDESIGN						
SB 74-0012 R1 Engine 1 SB - Open #357	ENGINE - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW N1 CONTROL AMPLIFIER PN 5071T98P05 WITH A CIRCUIT BOARD REDESIGN						
SB 74-0012 R1 Engine 2 SB - Open #926	ENGINE - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW N1 CONTROL AMPLIFIER PN 5071T98P05 WITH A CIRCUIT BOARD REDESIGN						
SB 74-0014 Engine 1 SB - Open #731	ELECTRICAL SYSTEM - W8 CABLE AND CONTROL AMPLIFIER (74-00-00) - MICROCIRCUIT INSPECTION						
SB 74-0014 Engine 2 SB - Open #67	ELECTRICAL SYSTEM - W8 CABLE AND CONTROL AMPLIFIER (74-00-00) - MICROCIRCUIT INSPECTION						
SB 74-0015 Engine 1 SB - Open #845	IGNITION - ELECTRICAL SYSTEM (74-00-00) - IGNITION EXCITER P/N 9238M66P08 INSPECTION						
SB 74-0015 Engine 2 SB - Open #850	IGNITION - ELECTRICAL SYSTEM (74-00-00) - IGNITION EXCITER P/N 9238M66P08 INSPECTION						
SB 74-0016 Engine 1 SB - Open #140	IGNITION - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW IGNITION EXCITER VIN 10-631045-3 (P/N 9238M66P11)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 74-0016 Engine 2 SB - Open #77	IGNITION - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW IGNITION EXCITER VIN 10-631045-3 (P/N 9238M66P11)						
SB 74-0016 R1 Engine 1 SB - Open #421	IGNITION - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW IGNITION EXCITER VIN 10-631045-3 (P/N 9238M66P11)						
SB 74-0016 R1 Engine 2 SB - Open #480	IGNITION - ELECTRICAL SYSTEM (74-00-00) - INTRODUCTION OF NEW IGNITION EXCITER VIN 10-631045-3 (P/N 9238M66P11)						
SB 75-0002 Engine 1 SB - Open #402	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 Engine 2 SB - Open #642	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R1 Engine 1 SB - Open #698	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R1 Engine 2 SB - Open #536	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R2 Engine 1 SB - Open #528	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R2 Engine 2 SB - Open #282	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 75-0002 R3 Engine 1 SB - Open #124	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R3 Engine 2 SB - Open #376	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R4 Engine 1 SB - Open #872	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0002 R4 Engine 2 SB - Open #910	AIR - INTRODUCTION OF NEW AND REWORKED B-SUMP VENT REGULATOR VALVES						
SB 75-0003 Engine 1 SB - Open #345	ENGINE - AIR SYSTEM - INTRODUCTION OF AIR TUBE SPACER PN 3049T28P01						
SB 75-0003 Engine 2 SB - Open #444	ENGINE - AIR SYSTEM - INTRODUCTION OF AIR TUBE SPACER PN 3049T28P01						
SB 75-0004 Engine 1 SB - Open #336	AIR - AIR SYSTEM (75-00-00) - INTRODUCTION OF NEW T2 SENSOR ANTI-ICING AIR TUBE						
SB 75-0004 Engine 2 SB - Open #717	AIR - AIR SYSTEM (75-00-00) - INTRODUCTION OF NEW T2 SENSOR ANTI-ICING AIR TUBE						
SB 79-0007 R1 Engine 1 SB - Open #754	OIL SYSTEM - REPLACEMENT OF LUBE AND SCAVENGE PUMP SPUR GEAR						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0007 R1 Engine 2 SB - Open #894	OIL SYSTEM - REPLACEMENT OF LUBE AND SCAVENGE PUMP SPUR GEAR						
SB 79-0008 R1 Engine 1 SB - Open #371	OIL SYSTEM - INTRODUCTION OF IMPROVED (NON-COATED) OIL TANK ON FIELDIED ENGINES AND NEW PRODUCTION ENGINES, AND ELIMINATION OF A-SUMP SCAVENGE PUMP ON NEW PRODUCTION ENGINES						
SB 79-0008 R1 Engine 2 SB - Open #601	OIL SYSTEM - INTRODUCTION OF IMPROVED (NON-COATED) OIL TANK ON FIELDIED ENGINES AND NEW PRODUCTION ENGINES, AND ELIMINATION OF A-SUMP SCAVENGE PUMP ON NEW PRODUCTION ENGINES						
SB 79-0010 Engine 1 SB - Open #38	OIL SYSTEM - ENGINE OIL TANK AND TUBING (79-00-00) - INSPECTION OF NON-COATED OIL TANK P/N 5122T11G01						
SB 79-0010 Engine 2 SB - Open #308	OIL SYSTEM - ENGINE OIL TANK AND TUBING (79-00-00) - INSPECTION OF NON-COATED OIL TANK P/N 5122T11G01						
SB 79-0010 R1 Engine 1 SB - Complied With #156	OIL SYSTEM - ENGINE OIL TANK AND TUBING (79-00-00) - INSPECTION OF NON-COATED OIL TANK P/N 5122T11G01 Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)	25-APR-2022 H: 7477.20 C: 3329		H: 40.00			
SB 79-0010 R1 Engine 2 SB - Complied With #840	OIL SYSTEM - ENGINE OIL TANK AND TUBING (79-00-00) - INSPECTION OF NON-COATED OIL TANK P/N 5122T11G01 Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906)	25-APR-2022 H: 7477.20 C: 3329		H: 40.00			
SB 79-0012 Engine 1 SB - Open #455	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0012 Engine 2 SB - Open #211	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						
SB 79-0012 R1 Engine 1 SB - Open #558	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						
SB 79-0012 R1 Engine 2 SB - Open #324	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						
SB 79-0012 R2 Engine 1 SB - Complied With #222	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL					08-APR-2008 H: 3311.30	
SB 79-0012 R2 Engine 2 SB - Complied With #420	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL					08-APR-2008 H: 3311.30	
SB 79-0012 R3 Engine 1 SB - Open #700	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						
SB 79-0012 R3 Engine 2 SB - Open #4	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						
SB 79-0012 R4 Engine 1 SB - Open #229	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL						
	Notes (AVG MAN HRS: 0.1)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0012 R4 Engine 2 SB - Open #568	OIL - OIL SYSTEM (79-00-00) - REDUCED MASTER CHIP DETECTOR CHECK INTERVAL Notes (AVG MAN HRS: 0.1)						
SB 79-0014 Engine 1 SB - Open #723	OIL - SERVICE EVALUATION FOR LUBE AND SCAVENGE PUMP ASSEMBLY Notes (NOTE: THIS SERVICE EVALUATION SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT HAVE EXPERIENCED LOW OR FLUCTUATING OIL PRESSURE AT ALTITUDES THAT WERE MORE THAN 37,000 FEET (11,278 METERS).)						
SB 79-0014 Engine 2 SB - Open #428	OIL - SERVICE EVALUATION FOR LUBE AND SCAVENGE PUMP ASSEMBLY Notes (NOTE: THIS SERVICE EVALUATION SERVICE BULLETIN IS APPLICABLE TO CF34-3B TURBOFAN ENGINES THAT HAVE EXPERIENCED LOW OR FLUCTUATING OIL PRESSURE AT ALTITUDES THAT WERE MORE THAN 37,000 FEET (11,278 METERS).)						
SB 79-0016 Engine 1 SB - Open #865	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF IMPROVED LUBE AND SCAVENGE PUMP ASSEMBLY PN 6087T04P06 Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN ON ENGINES THAT EXPERIENCE A LOW OR FLUCTUATING OIL PRESSURE AT ALTITUDES OF 37,000 FEET (11,278 M) OR ABOVE, AS SOON AS POSSIBLE FOLLOWING THE LOW PRESSURE EVENT WITHOUT EFFECT ON REVENUE SERVICE. GE ALSO RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE, STARTING WITH THE LOWEST TIME SINCE NEW.)						
SB 79-0016 Engine 2 SB - Open #520	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF IMPROVED LUBE AND SCAVENGE PUMP ASSEMBLY PN 6087T04P06 Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN ON ENGINES THAT EXPERIENCE A LOW OR FLUCTUATING OIL PRESSURE AT ALTITUDES OF 37,000 FEET (11,278 M) OR ABOVE, AS SOON AS POSSIBLE FOLLOWING THE LOW PRESSURE EVENT WITHOUT EFFECT ON REVENUE SERVICE. GE ALSO RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE, STARTING WITH THE LOWEST TIME SINCE NEW.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0017 R2 Engine 1 SB - Complied With #885	OIL - BPTO 2197 OIL SERVICE EVALUATION Notes .NO REWORK REQUIRED NO ACTION REQUIRED	04-JUN-2009 H: 3637.60					
SB 79-0017 R2 Engine 2 SB - Complied With #869	OIL - BPTO 2197 OIL SERVICE EVALUATION Notes .NO ACTION REQUIRED	04-JUN-2009 H: 3637.60					
SB 79-0018 Engine 1 SB - Open #337	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESSFITTINGS - FIELD REWORK PROGRAM						
SB 79-0018 Engine 2 SB - Open #901	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESSFITTINGS - FIELD REWORK PROGRAM						
SB 79-0018 R1 Engine 1 SB - Open #765	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
SB 79-0018 R1 Engine 2 SB - Open #414	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
SB 79-0018 R2 Engine 1 SB - Complied With #559	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM	26-NOV-2007 H: 3169.60					
SB 79-0018 R2 Engine 2 SB - Complied With #26	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM	26-NOV-2007 H: 3169.60					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0018 R3 Engine 1 SB - Open #28	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
SB 79-0018 R3 Engine 2 SB - Open #319	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - C-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
SB 79-0019 Engine 1 SB - Open #333	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 79-0019 Engine 2 SB - Open #669	ENGINE - GENERAL - SPARE PARTS RELEASE FOR CF34-3A1/-3B TURBOFAN ENGINES						
SB 79-0020 Engine 1 SB - Open #633	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF REWORKED LUBE AND SCAVENGE PUMP ASSEMBLY PN 6087T04P09						
SB 79-0020 Engine 2 SB - Open #500	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF REWORKED LUBE AND SCAVENGE PUMP ASSEMBLY PN 6087T04P09						
SB 79-0021 Engine 1 SB - Open #487	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF A AND B SUMP SUPPLY TUBE ASSEMBLIES PN 4159T69P01 PN 4159T69P02 AND HEAT EXCHANGER TUBE PN 4096T90G03						
SB 79-0021 Engine 2 SB - Open #821	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF A AND B SUMP SUPPLY TUBE ASSEMBLIES PN 4159T69P01 PN 4159T69P02 AND HEAT EXCHANGER TUBE PN 4096T90G03						
SB 79-0024 Engine 1 SB - Open #851	OIL - GENERAL (79-00-00) - APPROVED OILS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0024 Engine 2 SB - Open #524	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R1 Engine 1 SB - Open #840	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R1 Engine 2 SB - Open #675	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R2 Engine 1 SB - Open #664	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R2 Engine 2 SB - Open #872	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R3 Engine 1 SB - Open #586	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R3 Engine 2 SB - Open #97	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R4 Engine 1 SB - Open #55	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R4 Engine 2 SB - Open #763	OIL - GENERAL (79-00-00) - APPROVED OILS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0024 R5 Engine 1 SB - Open #585	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R5 Engine 2 SB - Open #397	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0024 R6 Engine 1 SB - Open #590	OIL - GENERAL (79-00-00) - APPROVED OILS Notes (NOTE: CONCURRENT REQUIREMENTS)						
SB 79-0024 R6 Engine 2 SB - Open #489	OIL - GENERAL (79-00-00) - APPROVED OILS Notes (NOTE: CONCURRENT REQUIREMENTS)						
SB 79-0025 Engine 1 SB - Open #882	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0025 Engine 2 SB - Open #112	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0025 R1 Engine 1 SB - Open #721	OIL - GENERAL (79-00-00) - APPROVED OILS						
SB 79-0025 R1 Engine 2 SB - Open #399	OIL - GENERAL (79-00-00) - APPROVED OILS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0026 Engine 1 SB - Open #138	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - RECALL OF THE LUBE AND SCAVENGE PUMP ASSEMBLY P/N 6087T04P10 FOR CF34-3B ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE BUT BEFORE 50 ENGINE FLIGHT HOURS IF ONLY ONE ENGINE ON AN AIRCRAFT IS AFFECTED AND BEFORE 10 ENGINE FLIGHT HOURS IF BOTH ENGINES ON AN AIRCRAFT ARE AFFECTED)						
SB 79-0026 Engine 2 SB - Open #786	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - RECALL OF THE LUBE AND SCAVENGE PUMP ASSEMBLY P/N 6087T04P10 FOR CF34-3B ENGINES Notes (NOTE: GE RECOMMENDS THAT YOU DO THIS SERVICE BULLETIN AS SOON AS POSSIBLE WITHOUT EFFECT ON REVENUE SERVICE BUT BEFORE 50 ENGINE FLIGHT HOURS IF ONLY ONE ENGINE ON AN AIRCRAFT IS AFFECTED AND BEFORE 10 ENGINE FLIGHT HOURS IF BOTH ENGINES ON AN AIRCRAFT ARE AFFECTED)						
SB 79-0026 R1 Engine 1 SB - Open #146	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - RECALL OF THE LUBE AND SCAVENGE PUMP ASSEMBLY P/N 6087T04P10 FOR CF34-3B ENGINES						
SB 79-0026 R1 Engine 2 SB - Open #206	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - RECALL OF THE LUBE AND SCAVENGE PUMP ASSEMBLY P/N 6087T04P10 FOR CF34-3B ENGINES						
SB 79-0027 Engine 1 SB - Open #5	OIL - OIL SYSTEM (79-00-00) - INTRODUCTION OF HTS OIL COMPATIBLE PREFORMED PACKINGS						
SB 79-0027 Engine 2 SB - Open #879	OIL - OIL SYSTEM (79-00-00) - INTRODUCTION OF HTS OIL COMPATIBLE PREFORMED PACKINGS						
SB 79-0028 Engine 1 SB - Open #835	OIL - OIL SYSTEM (79-00-00) - INTRODUCTION OF IMPROVED OIL FILTER BYPASS SENSOR P/N 4060T64P04						
SB 79-0028 Engine 2 SB - Open #256	OIL - OIL SYSTEM (79-00-00) - INTRODUCTION OF IMPROVED OIL FILTER BYPASS SENSOR P/N 4060T64P04						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0030 Engine 2 SB - N/A #538	INSPECT OIL - OIL SYSTEM (79-00-00) - ENGINE OIL TANK INSPECTION INTERVAL OIL TANK Notes INSPECT .PER ENGINE SERIAL NUMBER.	22-MAY-2013 H: 4815.90 C: 2073					
SB 79-0030 Engine 1 SB - N/A #918	OIL - OIL SYSTEM (79-00-00) - ENGINE OIL TANK INSPECTION INTERVAL Notes .PER ENGINE SERIAL NUMBER.	22-MAY-2013 H: 4815.90 C: 2073					
SB 79-0030 Engine 2 SB - N/A #772	OIL - OIL SYSTEM (79-00-00) - ENGINE OIL TANK INSPECTION INTERVAL Notes .PER ENGINE SERIAL NUMBER.	22-MAY-2013 H: 4815.90 C: 2073					
SB 79-0030 Engine 2 SB - N/A #758	REPLACE OIL - OIL SYSTEM (79-00-00) - ENGINE OIL TANK INSPECTION INTERVAL OIL TANK Notes REPLACE. PER ENGINE SERIAL NUMBER.	22-MAY-2013 H: 4815.90 C: 2073					
SB 79-0031 Engine 1 SB - Open #856	OIL SYSTEM - HEAT EXCHANGER AND OIL SUPPLY LINES - INSPECTION AND REPLACEMENT OF THE HEAT EXCHANGER						
SB 79-0031 Engine 2 SB - Open #241	OIL SYSTEM - HEAT EXCHANGER AND OIL SUPPLY LINES - INSPECTION AND REPLACEMENT OF THE HEAT EXCHANGER						
SB 79-0032 Engine 1 SB - Open #484	OIL - GENERAL (79-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-0032 Engine 2 SB - Open #82	OIL - GENERAL (79-00-00) - SPARE PARTS RELEASE FOR CF34-BJ ENGINES						
SB 79-0033 Engine 1 SB - Open #403	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF NEW SUMP DRAIN TUBE HOSE P/N 2834M14P01 AND REDUCER ELBOW P/N 4085T91P02 Notes (AVG MAN HRS: 1)						
SB 79-0033 Engine 2 SB - Open #848	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - INTRODUCTION OF NEW SUMP DRAIN TUBE HOSE P/N 2834M14P01 AND REDUCER ELBOW P/N 4085T91P02 Notes (AVG MAN HRS: 1)						
SB 79-A0015 Engine 1 SB - Open #515	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 Engine 2 SB - Open #490	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 R1 Engine 1 SB - Open #928	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 R1 Engine 2 SB - Open #72	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 R2 Engine 1 SB - Open #204	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-A0015 R2 Engine 2 SB - Open #302	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 R3 Engine 1 SB - Complied With #194	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS Notes (NOTE: BY 4,000 HOURS TSN* OR BY 1,000 HOURS SINCE LAST OVERHAUL)	26-NOV-2002 H: 1515.00					
SB 79-A0015 R3 Engine 2 SB - Complied With #945	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS Notes (NOTE: BY 4,000 HOURS TSN* OR BY 1,000 HOURS SINCE LAST OVERHAUL)	26-NOV-2002 H: 1515.00					
SB 79-A0015 R4 Engine 1 SB - Open #75	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 R4 Engine 2 SB - Open #639	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS						
SB 79-A0015 R5 Engine 1 SB - Open #648	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS Notes (AVG MAN HRS: 2)						
SB 79-A0015 R5 Engine 2 SB - Open #265	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - FIELD MANAGEMENT PROGRAM TO PREVENT B-SUMP OIL RELEASE EVENTS Notes (AVG MAN HRS: 2)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-A0017 Engine 1 SB - Complied With #352	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM	26-NOV-2002 H: 1515.00					
	Notes (NOTE: THE BULLETIN SHOULD BE ACCOMPLISHED ON ENGINES WITH MORE THAN 4000 HOURS TSN OR WITHIN 1000 HOURS SINCE LAST OVERHAUL)						
SB 79-A0017 Engine 2 SB - Complied With #474	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM	26-NOV-2002 H: 1515.00					
	Notes (NOTE: THE BULLETIN SHOULD BE ACCOMPLISHED ON ENGINES WITH MORE THAN 4000 HOURS TSN OR WITHIN 1000 HOURS SINCE LAST OVERHAUL)						
SB 79-A0017 R1 Engine 1 SB - Open #493	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
SB 79-A0017 R1 Engine 2 SB - Open #359	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
SB 79-A0017 R2 Engine 1 SB - Open #787	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
	Notes (NOTE: THE BULLETIN SHOULD BE ACCOMPLISHED ON ENGINES WITH MORE THAN 4000 HOURS TSN OR WITHIN 1000 HOURS SINCE LAST OVERHAUL)						
SB 79-A0017 R2 Engine 2 SB - Open #281	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM						
	Notes (NOTE: THE BULLETIN SHOULD BE ACCOMPLISHED ON ENGINES WITH MORE THAN 4000 HOURS TSN OR WITHIN 1000 HOURS SINCE LAST OVERHAUL)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB 79-A0017 R3 Engine 1 SB - Open #309	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM Notes (AVG MAN HRS: 3)						
SB 79-A0017 R3 Engine 2 SB - Open #244	OIL - LUBE AND SCAVENGE COMPONENTS (79-00-00) - B-SUMP SCAVENGE SCREENLESS FITTINGS - FIELD REWORK PROGRAM Notes (AVG MAN HRS: 3)						
SB 957330 Airframe SB - N/A #3245	(CF34)A73-32 REV. 2 L/E		15-OCT-1997				
SB 957331 Airframe SB - N/A #1925	(CF34)A73-32 REV. 2 R/E		15-OCT-1997				
SB 957910 Airframe SB - Open #818	INSP OIL TANK L/E Notes DEFERRED		12-APR-2012 H: 4516.10 L: 1934				
SB 957911 Airframe SB - Open #655	INSP OIL TANK, R/E Notes DEFERRED		12-APR-2012 H: 4516.10 L: 1934				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-11-009 PART B Airframe SB - N/A #2157	REWORK - STALL PROTECTION SYSTEM - INSPECTION & REPLACEMENT OF ANGLE-OF-ATTACK (AOA) VANE DECALS	05-JUL-2024 H: 8455.80 L: 3862					
Notes (AVG MAN HRS: 6) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320).PREVIOUS COMPLIANCE							
SB A604-11-009 PART A Airframe SB - Complied With #2929	SPECIAL CHECK- STALL PROTECTION SYSTEM - INSPECTION & REPLACEMENT OF ANGLE-OF-ATTACK (AOA) VANE DECALS	05-JUL-2024 H: 8455.80 L: 3862					
Notes (AVG MAN HRS: 0.25) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320).COMPLIED WITH BY INSPECTION							
SB A604-11-009 Airframe SB - Complied With #1214	SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - INSPECTION & REPLACEMENT OF ANGLE-OF-ATTACK (AOA) VANE DECALS	05-JUL-2024 H: 8455.80 L: 3862					
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)							
SB A604-24-008 Airframe SB - Open #1108	SPECIAL CHECK/MODIFICATION - EMERGENCY AC GENERATION SYSTEM - REPLACEMENT OF DRY AIR-DRIVEN GENERATOR (ADG) DOWNLOCK PIN AND INTRODUCTION OF BLADE ALIGNMENT ARROWS						
SB A604-24-008 PART A Airframe SB - N/A #2969	SPECIAL CHECK/MODIFICATION - EMERGENCY AC GENERATION SYSTEM - REPLACEMENT OF DRY AIR-DRIVEN GENERATOR (ADG) DOWNLOCK PIN AND INTRODUCTION OF BLADE ALIGNMENT ARROWS	13-FEB-2017 H: 5969.40 L: 2571					
Notes (AVG MAN HRS: 40).TO AIRCRAFT S/N							
SB A604-24-008 PART B Airframe SB - N/A #3168	SPECIAL CHECK/MODIFICATION - EMERGENCY AC GENERATION SYSTEM - REPLACEMENT OF DRY AIR-DRIVEN GENERATOR (ADG) DOWNLOCK PIN AND INTRODUCTION OF BLADE ALIGNMENT ARROWS	13-FEB-2017 H: 5969.40 L: 2571					
Notes (AVG MAN HRS: 1.5).TO AIRCRAFT S/N							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-24-009 PART C Airframe SB - N/A #2575	REWORK - AC ELECTRICAL POWER DISTRIBUTION - REPLACEMENT OF FAULTILY MAUNFACTURED LEACH "H" SERIES RELAYS Notes (AVG MAN HRS: 2.5).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB A604-24-009 PART D Airframe SB - N/A #1915	REWORK - AC ELECTRICAL POWER DISTRIBUTION - REPLACEMENT OF FAULTILY MAUNFACTURED LEACH "H" SERIES RELAYS Notes (AVG MAN HRS: 1.5).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB A604-24-009 PART B Airframe SB - N/A #1943	REWORK - AC ELECTRICAL POWER DISTRIBUTION - REPLACEMENT OF FAULTILY MAUNFACTURED LEACH "H" SERIES RELAYS Notes (AVG MAN HRS: 2.5).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB A604-24-009 PART A Airframe SB - N/A #271	SPECIAL CHECK - AC ELECTRICAL POWER DISTRIBUTION - REPLACEMENT OF FAULTILY MAUNFACTURED LEACH "H" SERIES RELAYS Notes (AVG MAN HRS: 1).TO AIRCRAFT S/N	13-FEB-2017 H: 5969.40 L: 2571					
SB A604-24-009 Airframe SB - Open #722	SPECIAL CHECK/REWORK - AC ELECTRICAL POWER DISTRIBUTION - REPLACEMENT OF FAULTILY MAUNFACTURED LEACH "H" SERIES RELAYS						
SB A604-24-017 Airframe SB - Superseded #1515	SPECIAL CHECK/MODIFICATION - EMERGENCY AC GENERATION SYSTEM - CHECK FOR CRACKS IN STRUT AND GENERATOR HOUSING Notes .SEE REVISION 1.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-24-017 R1 Airframe SB - N/A #1039	SPECIAL CHECK/MODIFICATION - EMERGENCY AC GENERATION SYSTEM - CHECK FOR CRACKS IN STRUT AND GENERATOR HOUSING Notes .BY EFFECTIVITY	26-JUL-2019 H: 6476.10 L: 2770					
SB A604-27-002 Airframe SB - N/A #550	SPECIAL CHECK/FLIGHT CONTROLS, ENGINE CONTROLS, NLG/MLG EMERGENCY RELEASE AND ADG MANUAL RELEASE SYSTEMS - FASTENERS AND SAFETY DEVICES Notes (AVG MAN HRS: 90)						
SB A604-27-006 Airframe SB - Complied With #2198	SPECIAL CHECK/MODIFICATION - FLAPS - FLAP ACTUATOR BEAM REPLACEMENT AND INSPECT FOR GAPS BETWEEN VANE BRACKET 600-14306-1 AND -2 AND THE ADJACENT SKIN	04-OCT-2000 H: 674.00 L: 257					
SB A604-27-006 R1 Airframe SB - Complied With #1403	SPECIAL CHECK/MODIFICATION - FLAPS - FLAP ACTUATOR BEAM REPLACEMENT AND INSPECT FOR GAPS BETWEEN VANE BRACKET 600-14306-1 AND -2 AND THE ADJACENT SKIN Notes (AVG MAN HRS: 4) (UPDATE NOTE: CW SB A604-27-006 R1).CW SB A604-27-006 R1	04-OCT-2000 H: 674.00 L: 257					
SB A604-27-007 PART C Airframe SB - Open #1231	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES						
SB A604-27-007 PART B Airframe SB - Complied With #573	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES	26-NOV-2002 H: 1515.00 L: 559					
SB A604-27-007 PART A Airframe SB - Complied With #488	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES	26-NOV-2002 H: 1515.00 L: 559					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-27-007 Airframe SB - Open #592	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES						
SB A604-27-007 R1 PART C Airframe SB - Complied With #2241	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018	H: 6372.80 L: 2715				
SB A604-27-007 R1 PART A Airframe SB - Complied With #2794	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018	H: 6372.80 L: 2715				
SB A604-27-007 R1 PART B Airframe SB - Complied With #2500	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018	H: 6372.80 L: 2715				
SB A604-27-007 R1 Airframe SB - Complied With #2327	SPECIAL CHECK/MODIFICATION - FLAPS - INSPECT VANE BRACKETS FOR CRACKS, REPLACE BRACKETS AND REMOVE GAPS BETWEEN BRACKETS AND MATING SURFACES - RETROACTIVE ACTION Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002) (NOTE: RETROACTIVE ACTION THE RETROACTIVE ACTION IS RECOMMENDED IN LESS THAN 400 LANDINGS FROM THIS ALERT SERVICE BULLETIN RELEASE DATE (REV. 01). THE ACTION THAT FOLLOWS IS RECOMMENDED FOR AIRCRAFT ON WHICH THE BASIC ISSUE OF THIS ALERT SERVICE BULLETIN WAS DONE AND ARE NOT LISTED IN THE RNIEO TABLE GIVEN IN THE EFFECTIVITY STATEMENT IN PARAGRAPH 1.C.).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018	H: 6372.80 L: 2715				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-27-010 Airframe SB - Complied With #2246	SPECIAL CHECK - FLAPS - VISUALLY EXAMINE FLAP ACTUATOR BEAM VANE BRACKETS FOR POSSIBLE CRACKS - SUPERSEDED BY SB A604-27-007	25-FEB-2001 H: 794.00 L: 300					
SB A604-27-011 Part C2 Airframe SB - Open #2278	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES	28-JUL-2005 H: 2522.30 L: 983					
SB A604-27-011 Airframe SB - Open #2096	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES						
SB A604-27-011 Part B2 Airframe SB - Complied With #1890	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES	28-JUL-2005 H: 2522.30 L: 983					
SB A604-27-011 Part C1 Airframe SB - Complied With #730	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES	28-JUL-2005 H: 2522.30 L: 983					
SB A604-27-011 Part A Airframe SB - Complied With #2852	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES	28-JUL-2005 H: 2522.30 L: 983					
SB A604-27-011 R1 Part A Airframe SB - Complied With #1749	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES	28-JUL-2005 H: 2522.30 L: 983					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-27-011 R1 Part B Airframe SB - Complied With #1675	SPECIAL CHECK/MODIFICATION - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER ASSEMBLY TOLERANCE CHECK AND REPLACEMENT OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES Notes (UPDATE NOTE: COMPLIED WITH SB A604-27-011 REV 1 PART B, SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES. PART B NEXT DUE 8430.0).COMPLIED WITH SB A604-27-011 REV 1 PART B, SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES. PART B NEXT DUE 8430.0	12-OCT-2023 H: 8130.00 L: 3683					
SB A604-27-011 R1 Airframe SB - Complied With #320	SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES Notes (UPDATE NOTE: COMPLIED WITH SB A604-27-011 REV 1 PART B, SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES. PART B NEXT DUE 8430.0).COMPLIED WITH SB A604-27-011 REV 1 PART B, SPECIAL CHECK/REWORK - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER TOLERANCE CHECK AND REWORK OF OUT-OF-TOLERANCE AOA TRANSDUCER ASSEMBLIES. PART B NEXT DUE 8430.0	12-OCT-2023 H: 8130.00 L: 3683					
SB A604-27-026 Part B Airframe SB - N/A #3095	REPEAT CHECK - AOA TRANSDUCER LINEARITY CHECK Notes (UPDATE NOTE: NA TO PART NUMBERS INSTALLED)	03-AUG-2005					
SB A604-27-026 Airframe SB - N/A #569	SPECIAL CHECK - STALL PROTECTION SYSTEM - ANGLE-OF-ATTACK (AOA) TRANSDUCER LINEARITY CHECK	03-AUG-2005					
SB A604-27-029 PART B Airframe SB - Complied With #359	MODIFICATION - HORIZONTAL STABILIZER CONTROL SYSTEM - HORIZONTAL STABILIZER TRIM CONTROL UNIT (HSTCU) Notes .IAW THE SB	06-AUG-2007 H: 3099.20 L: 1251					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-27-029 PART A Airframe SB - N/A #2926	MODIFICATION - HORIZONTAL STABILIZER CONTROL SYSTEM - HORIZONTAL STABILIZER TRIM CONTROL UNIT (HSTCU) Notes (UPDATE NOTE: COMPLIED WITH SB A604-27-029 PART B)	03-MAY-2007					
SB A604-27-029 Airframe SB - Complied With #2684	MODIFICATION - HORIZONTAL STABILIZER CONTROL SYSTEM - HORIZONTAL STABILIZER TRIM CONTROL UNIT (HSTCU) Notes (UPDATE NOTE: COMPLIED WITH SB A604-27-029 PART B)	03-MAY-2007					
SB A604-30-001 PART B Airframe SB - Complied With #3054	REWORK - WING ANTI-ICING DUCT MANIFOLD SYSTEM - EXAMINE PICCOLO TUBE AND CONNECTING DUCT INSTALLATION ON LEFT AND RIGHT WINGS Notes (AVG MAN HRS: 17).AT MANUFACTURE	01-MAY-2003 H: 1671.00 L: 609					
SB A604-30-001 PART D Airframe SB - Complied With #659	REWORK - WING ANTI-ICING DUCT MANIFOLD SYSTEM - EXAMINE PICCOLO TUBE AND CONNECTING DUCT INSTALLATION ON LEFT AND RIGHT WINGS Notes (AVG MAN HRS: 7).AT MANUFACTURE	01-MAY-2003 H: 1671.00 L: 609					
SB A604-30-001 PART C Airframe SB - Complied With #990	REWORK - WING ANTI-ICING DUCT MANIFOLD SYSTEM - EXAMINE PICCOLO TUBE AND CONNECTING DUCT INSTALLATION ON LEFT AND RIGHT WINGS Notes (AVG MAN HRS: 8).AT MANUFACTURE	01-MAY-2003 H: 1671.00 L: 609					
SB A604-30-001 PART A Airframe SB - Complied With #29	SPECIAL CHECK - WING ANTI-ICING DUCT MANIFOLD SYSTEM - EXAMINE PICCOLO TUBE AND CONNECTING DUCT INSTALLATION ON LEFT AND RIGHT WINGS Notes (AVG MAN HRS: 4).AT MANUFACTURE	01-MAY-2003 H: 1671.00 L: 609					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-30-001 Airframe SB - Open #2586	SPECIAL CHECK/REWORK - WING ANTI-ICING DUCT MANIFOLD SYSTEM - EXAMINE PICCOLO TUBE AND CONNECTING DUCT INSTALLATION ON LEFT AND RIGHT WINGS						
SB A604-32-008 Airframe SB - Open #1121	MODIFICATION - LANDING GEAR CONTROL SYSTEM - REPLACEMENT OF LANDING GEAR CONTROL HANDLE WITH DEFECTIVE MICROSWITCH ACTIVATION MECHANISM Notes (AVG MAN HRS: 8) (NOTE: SUFFIX A)						
SB A604-32-018 Airframe SB - Superseded #691	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS Notes .SEE REVISION 1.						
SB A604-32-018 PART A Airframe SB - Open #1194	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS						
SB A604-32-018 PART B Airframe SB - Open #3065	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS						
SB A604-32-018 PART C Airframe SB - Open #3393	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS						
SB A604-32-018 R1 PART A Airframe SB - N/A #2893	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS Notes (AVG MAN HRS: 16)					26-NOV-2002 H: 1515.00	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-32-018 R1 PART C Airframe SB - N/A #2812	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS Notes (AVG MAN HRS: 5)	26-NOV-2002 H: 1515.00					
SB A604-32-018 R1 PART B Airframe SB - Complied With #2255	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS Notes (AVG MAN HRS: 16)	26-NOV-2002 H: 1515.00					
SB A604-32-018 R1 Airframe SB - Open #654	SPECIAL CHECK/REWORK - EXTENSION AND RETRACTION, MAIN GEAR - REPLACEMENT OF THE MAIN LANDING GEAR (MLG) SIDE-BRACE FITTING SHAFTS Notes (NOTE: RETROACTIVE ACTION FOR AIRCRAFT THAT HAVE DONE THE BASIC ISSUE OF THIS ALERT SERVICE BULLETIN, DO PART C.)						
SB A604-53-004 PART A Airframe SB - Open #1914	SPECIAL CHECK/REWORK - REAR FUSELAGE CHANNELS, PART NO. 600-21033-33 AND -34 Notes (AVG MAN HRS: 0.3)						
SB A604-53-004 PART B Airframe SB - Open #1226	SPECIAL CHECK/REWORK - REAR FUSELAGE CHANNELS, PART NO. 600-21033-33 AND -34 Notes (AVG MAN HRS: 28)						
SB A604-53-004 Airframe SB - N/A #2568	SPECIAL CHECK/REWORK - REAR FUSELAGE CHANNELS, PART NO. 600-21033-33 AND -34						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-56-002 Airframe SB - Open #19	SPECIAL CHECK/MODIFICATION - FLIGHT COMPARTMENT WINDOWS - REPLACEMENT OF THE HI-LITES AND THE COLLARS ON THE WINDSHIELD, PART NO. 604-33030-1/-2						
SB A604-56-002 R1 Airframe SB - Open #2120	SPECIAL CHECK/MODIFICATION - FLIGHT COMPARTMENT WINDOWS - REPLACEMENT OF THE HI-LITES AND THE COLLARS ON THE WINDSHIELD, PART NO. 604-33030-1/-2., ALERT SERVICE BULLETIN						
SB A604-57-006 PART B Airframe SB - Complied With #213	MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						
	Notes .SEE REVISION 1.						
SB A604-57-006 PART C Airframe SB - Open #152	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						
SB A604-57-006 PART A Airframe SB - Complied With #1720	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						
	Notes .SEE REVISION 1.						
SB A604-57-006 Airframe SB - Complied With #966	SPECIAL CHECK/MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						
	Notes .SEE REVISION 1.						
SB A604-57-006 R1 PART B Airframe SB - Open #3274	MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-57-006 R1 PART C Airframe SB - Complied With #1079	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes .FASTENERS FOUND INSTALLED CORRECTLY(ALL) AS SHOWN IN FIG 1	21-OCT-2013 H: 4934.50 L: 2130					
SB A604-57-006 R1 PART A Airframe SB - Complied With #17	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes .FASTENERS FOUND INSTALLED CORRECTLY(ALL) AS SHOWN IN FIG 1	21-OCT-2013 H: 4934.50 L: 2130					
SB A604-57-006 R1 Airframe SB - Complied With #2317	SPECIAL CHECK/MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes .FASTENERS FOUND INSTALLED CORRECTLY(ALL) AS SHOWN IN FIG 1	21-OCT-2013 H: 4934.50 L: 2130					
SB A604-57-006 R2 PART B Airframe SB - Open #2909	MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes (AVG MAN HRS: 58)						
SB A604-57-006 R2 PART A Airframe SB - Open #2555	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes (AVG MAN HRS: 1)						
SB A604-57-006 R2 PART C Airframe SB - Open #968	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-57-006 R2 Airframe SB - Open #3562	SPECIAL CHECK/MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes (NOTE: RETROACTIVE ACTION 1. RETROACTIVE ACTION APPLICABLE TO AIRCRAFT THAT HAVE INCORPORATED THE BASIC ISSUE OF THIS SERVICE BULLETIN: A. FOR THE AIRCRAFT WITH THE INCORRECTLY ORIENTED FORWARD FASTENERS HEADS (FIGURE 2 IN PART A), PART A MUST BE REPEATED EVERY 100 LANDINGS UNTIL PART B IS COMPLIED WITH. - NO FURTHER ACTION IS REQUIRED, ONCE PART B IS INCORPORATED. OR B. FOR THE AIRCRAFT WITH THE CORRECTLY ORIENTED FORWARD FASTENERS HEADS (FIGURE 1 IN PART A). - NO FURTHER ACTION IS REQUIRED, ONCE PART C IS COMPLETED. 2. NO RETROACTIVE ACTION IS REQUIRED FOR AIRCRAFT THAT HAVE INCORPORATED THE REVISION 01 OF THIS SERVICE BULLETIN.)						
SB A604-57-006 R3 PART B Airframe SB - Open #1089	MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes (AVG MAN HRS: 58)						
SB A604-57-006 R3 PART C Airframe SB - Open #3524	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						
SB A604-57-006 R3 PART A Airframe SB - Open #3286	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes (AVG MAN HRS: 1)						
SB A604-57-006 R3 Airframe SB - Open #1539	SPECIAL CHECK/MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-57-006 R4 PART B Airframe SB - Open #2291	MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS Notes (AVG MAN HRS: 58)						
SB A604-57-006 R4 PART A Airframe SB - Open #1582	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS - INSPECTION Notes (AVG MAN HRS: 1)						
SB A604-57-006 R4 PART C Airframe SB - Open #645	SPECIAL CHECK - INBOARD FLAP HINGE BOX - FORWARD FASTENERS HEADS ARE CORRECTLY ORIENTED						
SB A604-57-006 R4 Airframe SB - Open #1818	SPECIAL CHECK/MODIFICATION - INBOARD FLAP HINGE BOX - FORWARD ATTACHMENT FITTINGS FASTENERS						
SB A604-73-001 PART A Airframe SB - Complied With #1854	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) /FUEL CONTROL UNIT - INSPECT IDG CABLE HARNESS FOR PROPER CLEARANCE AND POSSIBLE CHAFING AND INSPECT THE FUEL MANIFOLD FOR PROPER CLEARANCE WITH THE 10TH STAGE BLEED AIR CHECK VALVE Notes (AVG MAN HRS: 4.5).PARAGRAPHS 2A,2B (PART A), 2C (PART B), 2F & 2G				03-AUG-2005 H: 2522.30		
SB A604-73-001 Airframe SB - Open #2139	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) /FUEL CONTROL UNIT - INSPECT IDG CABLE HARNESS FOR PROPER CLEARANCE AND POSSIBLE CHAFING AND INSPECT THE FUEL MANIFOLD FOR PROPER CLEARANCE WITH THE 10TH STAGE BLEED AIR CHECK VALVE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB A604-73-001 PART C Airframe SB - Complied With #292	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) /FUEL CONTROL UNIT - INSPECT IDG CABLE HARNESS FOR PROPER CLEARANCE AND POSSIBLE CHAFING AND INSPECT THE FUEL MANIFOLD FOR PROPER CLEARANCE WITH THE 10TH STAGE BLEED AIR CHECK VALVE Notes (AVG MAN HRS: 8).PARAGRAPHS 2A,2B (PART A), 2C (PART B), 2F & 2G	03-AUG-2005 H: 2522.30					
SB A604-73-001 PART B Airframe SB - Complied With #2709	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) /FUEL CONTROL UNIT - INSPECT IDG CABLE HARNESS FOR PROPER CLEARANCE AND POSSIBLE CHAFING AND INSPECT THE FUEL MANIFOLD FOR PROPER CLEARANCE WITH THE 10TH STAGE BLEED AIR CHECK VALVE Notes (AVG MAN HRS: 21).PARAGRAPHS 2A,2B (PART A), 2C (PART B), 2F & 2G	03-AUG-2005 H: 2522.30					
SB A604-73-002 Airframe SB - Open #581	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) - INSPECT LEFT AND RIGHT ENGINE IDG CABLE HARNESS FOR POSSIBLE CHAFING						
SB A604-73-002 PART B Airframe SB - Complied With #1040	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) - INSPECT LEFT AND RIGHT ENGINE IDG CABLE HARNESS FOR POSSIBLE CHAFING - IDG CABLE HARNESS PROTECTIVE HARDWARE ADDITION (LEFT AND RIGHT ENGINE) Notes (AVG MAN HRS: 9).PCW BY COMPLIANCE WITH SB A604-073-002 PARA B. REF: LOG ENTRY DATED 3/25/2001 - TO PREVENT ELECTRICAL ARCING BETWEEN THE IDG CABLE AND ENGINE COWLING	03-AUG-2005 H: 2522.30					
SB A604-73-002 PART A Airframe SB - Complied With #2090	SPECIAL CHECK/MODIFICATION - INTEGRATED DRIVE GENERATOR (IDG) - INSPECT LEFT AND RIGHT ENGINE IDG CABLE HARNESS FOR POSSIBLE CHAFING - IDG CABLE HARNESS SPECIAL CHECK/REPAIR Notes (AVG MAN HRS: 23).PCW BY COMPLIANCE WITH SB A604-073-002 PARA B. REF: LOG ENTRY DATED 3/25/2001 - TO PREVENT ELECTRICAL ARCING BETWEEN THE IDG CABLE AND ENGINE COWLING	03-AUG-2005 H: 2522.30					
SB A604-76-003 Airframe SB - N/A #512	RIGGING CHECK OF THE ENGINE CONTROLS WITH AUTOTHROTTLE SYSTEM (ATS) INSTALLED Notes (AVG MAN HRS: 3).BY EFFECTIVITY	20-DEC-2002					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB APU-146 APU SB - Open #132	SPECIAL ON-WING TROUBLESHOOTING CHECK SHEET FOR OIL "SMELL-IN-CABIN" (SIC) COMPLAINTS						
SB APU-151 APU SB - Open #176	HONEYWELL COMMERCIAL AUXILIARY POWER UNIT (APU) OIL APPROVALS.						
SB APU-41 APU SB - Open #103	PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS						
SB APU-41 R1 APU SB - Open #113	PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS						
SB APU-42 APU SB - Open #96	IMPROPER SERVICING PROCEDURES - UNAUTHORIZED USE OF SILICONE BASEDLUBRICANTS ON OIL-WETTED COMPONENTS WITHIN THE APU'SLUBRICATION SYSTEM						
SB APU-46 APU SB - Open #92	RECOMMENDED ONE-TIME INSPECTION OF NAMEPLATE RIVETS FOR PROPERINSTALLATION						
SB APU-49 R10 APU SB - Open #18	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER						
SB APU-7 APU SB - Open #111	AIRCRAFT DE-ICING AND ITS POSSIBLE EFFECTS ON HONEYWELL AUXILIARY POWER UNITS (APUS)						
SB APU-7 R1 APU SB - Open #161	AIRCRAFT DE-ICING AND ITS POSSIBLE EFFECTS ON HONEYWELL AUXILIARY POWER UNITS (APUS)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB APU-7 R2 APU SB - Open #2	AIRCRAFT DE-ICING AND ITS POSSIBLE EFFECTS ON HONEYWELL AUXILIARY POWER UNITS (APUS)						
SB APU-78 APU SB - Open #188	AUXILIARY POWER UNIT (APU) OPERATIONAL INSTRUCTIONS						
SB APU-78 R1 APU SB - Open #186	AUXILIARY POWER UNIT (APU) OPERATIONAL INSTRUCTIONS						
SB APU-78 R2 APU SB - Open #30	AUXILIARY POWER UNIT (APU) OPERATIONAL INSTRUCTIONS						
SB APU-83 APU SB - Open #56	SPOTLIGHT TROUBLESHOOTING SYSTEM						
SB APU-83 R1 APU SB - Open #105	SPOTLIGHT TROUBLESHOOTING SYSTEM						
SB APU-83 R2 APU SB - Open #33	SPOTLIGHT TROUBLESHOOTING SYSTEM						
SB CF34-NAC-78-027 Engine 1 SB - Complied With #405	POWERPLANT - NACELLE - REWORK OF THRUST REVERSER DIVERTER FAIRINGS						
	Notes						
	.LH AND RH ENGINES						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB CF34-NAC-78-027 Engine 2 SB - Open #947	POWERPLANT - NACELLE - REWORK OF THRUST REVERSER DIVERTER FAIRINGS						
SB D200904000013 APU SB - Open #61	TO ADVISE THE FIELD OF THE RELEASE OF SERVICE BULLETIN GTCP36-49-7969.						
SB D200906000072 APU SB - Open #191	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB D200906000072 R1 APU SB - Open #95	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB D200906000072 R2 APU SB - Open #153	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB D200906000072 R3 APU SB - Open #35	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB D200906000072 R4 APU SB - Open #189	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES						
SB D201010000068 APU SB - Open #58	OPERATIONS IN VOLCANICALLY ACTIVE AREAS						
SB D201012000013 APU SB - Open #49	GENERAL HANDLING INFORMATION FOR IGNITION EXCITERS CONTAINING THE RADIOACTIVE ELEMENT KRYPTON-85(KRYPTON 85) ABOVE 10,000 BECQUERELS						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB D201012000013 R1 APU SB - Open #137	GENERAL HANDLING INFORMATION FOR IGNITION EXCITERS CONTAINING THE RADIOACTIVE ELEMENT KRYPTON-85(KRYPTON 85) ABOVE 10,000 BECQUERELS						
SB D201107000024 APU SB - Open #118	APPROVED USE OF HYDROPROCESSED ESTERS AND FATTY ACIDS (HEFA) BIOFUEL BLENDS FOR ALL HONEYWELL COMMERCIAL AUXILIARY POWER UNITS (APU)						
SB D201107000024 R1 APU SB - Open #107	APPROVED USE OF BIOFUEL BLENDS FOR ALL HONEYWELL COMMERCIAL AND MILITARY AUXILIARY POWER UNITS (APU)						
SB D201107000065 APU SB - Open #143	AUXILIARY POWER UNIT OPERATIONS IN VOLCANICALLY ACTIVE AREAS						
SB D201110000029 APU SB - Open #6	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB D201110000029 R1 APU SB - Open #45	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB D201110000029 R2 APU SB - Open #150	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB D201110000029 R3 APU SB - Open #55	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB D201110000029 R4 APU SB - Open #172	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB D201110000029 R5 APU SB - Open #50	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						
SB D201112000050 APU SB - Open #72	ACCEPTANCE CRITERIA FOR ON-WING BORESCOPE INSPECTIONS						
SB D201112000050 R1 APU SB - Open #73	ACCEPTANCE CRITERIA FOR ON-WING BORESCOPE INSPECTIONS						
SB D201112000050 R2 APU SB - Open #76	ACCEPTANCE CRITERIA FOR ON-WING BORESCOPE INSPECTIONS						
SB D201112000050 R3 APU SB - Open #75	ACCEPTANCE CRITERIA FOR ON-WING BORESCOPE INSPECTIONS						
SB D201608000071 R1 APU SB - Open #37	PROCEDURE TO CLEAN BRUSH DUST FROM AND MEASURE BRUSH WEAR ON 36-150 AUXILIARY POWER UNIT (APU) STARTER MOTORS, PN 519892-X AND PN 2704458-X						
SB D2020050000806 APU SB - Open #115	BIOCIDE TREATMENT PROCESS						
SB EFD-4077-34-31 R1 Airframe SB - Open #280	ROCKWELL - NAVIGATION EFD-4077 ELECTRONIC FLIGHT DISPLAY (CPN 622-9978 110/112/114/116/118/120/122/124/126/304/306/308/310/312/314/402/404/406) HIGH VOLTAGE POWER SUPPLY A11 (CPN 827-4032-001/002/003) SERVICE BULLETIN 31 REVISION N0. 1 REDUCE OCCURRENCES OF DISPLAY DEGRADATION DUE TO HVPS FAILURE.						
SB GTCP36-49-7885 APU SB - Open #43	APU - CONVERSION OF ENGINE GTCP36-100[E], PN 3800050-1/-2/-3/-4/-5 TO 36-150[CL], PN 3800804-1 ENGINE						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SB GTCP36-49-7886 APU SB - Open #70	REPLACE TURBINE NOZZLE PART NO. 3613101-8 WITH TURBINE NOZZLE PART NO. 3846779-1						
SB GTCP36-49-7886 R1 APU SB - Open #168	APU - REPLACE TURBINE NOZZLE PN 3613101-8 WITH TURBINE NOZZLE PN 3846779-1, SERVICE BULLETIN						
SB GTCP36-49-7924 APU SB - Open #167	APU - INSTALL WASHER, PART NO. NAS1149C0363R BEHIND THE IGNITION UNIT BRACKET TO INCREASE THE						
SB GTCP36-49-7970 R APU SB - Open #26	APU - REPLACE THE COMBUSTION CHAMBER (COMBUSTOR), PART NUMBER 3830450-1 WITH COMBUSTOR, PART						
SB GTCP36-49-8021 R APU SB - Open #1	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE SEAL, PN 3606514-3 WITH PN 3617897-1,						
SIL 78 APU SB - Open #125	36-150 EMB APU LIFT FIXTURE, RETROFIT OF SUB-COMPONENT PN 31060 SHOULDER BOLT						
SIL APU-152 APU SB - Open #46	NOTIFY FIELD AND HONEYWELL OPERATORS OF THE BACKGROUND AND CURRENT SITUATION REGARDING POSSIBLE FAME (FATTY ACID METHYL ESTER) CONTAMINATION IN AVIATION TURBINE FUEL						
SIL APU-152 R1 APU SB - Open #157	NOTIFY FIELD AND HONEYWELL OPERATORS OF THE BACKGROUND AND CURRENT SITUATION REGARDING POSSIBLE FAME (FATTY ACID METHYL ESTER) CONTAMINATION IN AVIATION TURBINE FUEL						
SIL APU-152 R2 APU SB - Open #169	NOTIFY FIELD AND HONEYWELL OPERATORS OF THE BACKGROUND AND CURRENT SITUATION REGARDING POSSIBLE FAME (FATTY ACID METHYL ESTER) CONTAMINATION IN AVIATION TURBINE FUEL						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SIL APU-152 R3 APU SB - Open #128	NOTIFY FIELD AND HONEYWELL OPERATORS OF THE BACKGROUND AND CURRENT SITUATION REGARDING POSSIBLE FAME (FATTY ACID METHYL ESTER) CONTAMINATION IN AVIATION TURBINE FUEL						
SIL APU-152 R4 APU SB - Open #173	NOTIFY FIELD AND HONEYWELL OPERATORS OF THE BACKGROUND AND CURRENT SITUATION REGARDING POSSIBLE FAME (FATTY ACID METHYL ESTER) CONTAMINATION IN AVIATION TURBINE FUEL						
SIL APU-56 APU SB - Open #131	RECOMMENDED LIFE LIMITS FOR TURBINE AND COMPRESSOR ROTORS ON GTCP36-100, - 150 AUXILIARY POWER UNITS (APUS)						
SIL APU-56 R1 APU SB - Open #98	RECOMMENDED LIFE LIMITS FOR TURBINE AND COMPRESSOR ROTORS ON GTCP36-100, - 150 AUXILIARY POWER UNITS (APUS)						
SIL APU-56 R2 APU SB - Open #126	RECOMMENDED LIFE LIMITS FOR TURBINE AND COMPRESSOR ROTORS ON GTCP36-100, - 150 AUXILIARY POWER UNITS (APUS)						
SIL APU-7 APU SB - Open #29	AIRCRAFT DE-ICING AND ITS POSSIBLE EFFECTS ON HONEYWELL AUXILIARY POWER UNITS (APUS)						
SIL APU-7 R1 APU SB - Open #97	AIRCRAFT DE-ICING AND ITS POSSIBLE EFFECTS ON HONEYWELL AUXILIARY POWER UNITS (APUS)						
SIL APU-7 R2 APU SB - Open #162	AIRCRAFT DE-ICING AND ITS POSSIBLE EFFECTS ON HONEYWELL AUXILIARY POWER UNITS (APUS)						
SIL D201701000026 APU SB - Open #127	AIRBORN AUXILIARY POWER - GAS TURBINE ENGINE - HONEYWELL AUXILIARY POWER UNIT (APU) RENTAL ENGINE WORKSHEET FOR 36-100, 36-150, RE100, AND RE220 APUS						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SIL D201701000026 R1 APU SB - Open #39	AIRBORN AUXILIARY POWER - GAS TURBINE ENGINE - HONEYWELL AUXILIARY POWER UNIT (APU) RENTAL ENGINE WORKSHEET FOR 36-100, 36-150, RE100, AND RE220 APUS						
SIL D201701000026 R2 APU SB - Open #23	AIRBORN AUXILIARY POWER - GAS TURBINE ENGINE - HONEYWELL AUXILIARY POWER UNIT (APU) RENTAL ENGINE WORKSHEET FOR 36-100, 36-150, RE100, AND RE220 APUS						
SIL No. APU-49 R1 APU SB - Open #10	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APU'S)						
SIL No. APU-49 R10 APU SB - Open #164	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS) Notes (NOTE: COMPLIANCE: EVERY AIRCRAFT 'A' CHECK OR EVERY 500 APU HOURS OR PER AMM OR MM CRITERIA (CUSTOMER OPTION).)						
SIL No. APU-49 R11 APU SB - Open #179	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS(APUS) Notes (NOTE: ANALYST/OPERATOR WILL NEED TO MANUALLY SET THE CALENDAR START. COMPLIANCE: EVERY AIRCRAFT 'A' CHECK OR EVERY 500 APU HOURS OR PER AMM OR MM CRITERIA (CUSTOMER OPTION).)						
SIL No. APU-49 R12 APU SB - Open #64	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS) Notes (NOTE: COMPLIANCE: FIRST AND SUBSEQUENT OIL AND FILTER SAMPLE. EVERY AIRCRAFT 'A' CHECK OR EVERY 500 APU HOURS OR PER AMM OR MM CRITERIA (CUSTOMER OPTION).)						
SIL No. APU-49 R13 APU SB - Recurring #22	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS) Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320)	05-JUL-2024 H: 10002.00	H: 500.00			H: 10502.00	H: 195.00



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SIL No. APU-49 R14 APU SB - Open #135	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)						
SIL No. APU-49 R2 APU SB - Open #86	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APU'S)						
SIL No. APU-49 R3 APU SB - Open #48	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APU'S)						
SIL No. APU-49 R4 APU SB - Open #160	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APU'S)						
SIL No. APU-49 R5 APU SB - Open #14	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APU'S)						
SIL No. APU-49 R6 APU SB - Open #158	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APU'S)						
SIL No. APU-49 R7 APU SB - Open #11	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)						
SIL No. APU-49 R8 APU SB - Open #190	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS).						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
SIL No. APU-49 R9 APU SB - Open #138	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS) Notes (NOTE: THE SOAP AND FILTER ANALYSIS PROGRAM WAS INITIALLY LIMITED TO THE OPERATORS OF THE GTCP36-100/-150 SERIES AUXILIARY POWER UNITS ENROLLED IN THE HONEYWELL ENGINES, SYSTEMS & SERVICES APU MAINTENANCE SERVICE PLAN (MSP). THE PROGRAM IS NOW OFFERED TO ALL OPERATORS OF THE HONEYWELL GTCP36-100/-150, RE100 AND RE220 SERIES APUS.)						
SIL-APU-49 R7 APU SB - Open #53	APU SPECTROMETRIC OIL ANALYSIS, SERVICE INFORMATION LETTER						
SL-600L-11106 Airframe SB - Complied With #3430	TRANSFORMER RECTIFIER UNIT AC FILTER CAPACITOR INSPECTION		10-NOV-2000				
SL-604L-0702 Airframe SB - Complied With #21	BC-1301, MOD6: ELIMINATE POTENTIAL INTERNAL FAIL MODE		28-MAR-2001 H: 821.00 L: 310				
SL6XX-32-001 Airframe SB - Open #3120	IDENTIFICATION OF THE STEERING SELECTOR VALVE Notes (NOTE: EFFECTIVITY: THE SERVICE LETTER APPLIES TO THE STEERING SELECTOR VALVES WITH THE PART NUMBER 150446002 FOR 600 SERIES CHALLENGERS.)						
TUC-33-30-01-1 Airframe SB - N/A #2637	FUEL PORT DOOR LIGHTS GROUND REWIRING		06-JUN-2001 H: 904.00 L: 332				
SB 71-0000 R4 Engine 1 SB - Open #951	SERVICE BULLETIN - POWER PLANT GENERAL 71-00-00 CONSOLIDATED ON-WING INSPECTION RECOMMENDATIONS AND SERVICING TASK LIST						
SB 71-0000 R4 Engine 2 SB - Open #954	SERVICE BULLETIN - POWER PLANT GENERAL 71-00-00 CONSOLIDATED ON-WING INSPECTION RECOMMENDATIONS AND SERVICING TASK LIST						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1997-01-12 Airframe AD - N/A FAA #1968	AIRELL INTERNATIONAL, INC., - CENTAURUS MODEL C3-100 GROUND PROXIMITY WARNING SYSTEM Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 1997-04-04 Airframe AD - Open FAA #3390	ALLIEDSIGNAL AUXILIARY POWER UNITS (GTCP85 SERIES) - INSTALL A CONTAINMENT AUGMENTATION RING (SUPERSEDES AD 93-07-13) Notes (ISSUING AUTHORITY: FAA) (NOTE: FOR FLIGHT OPERABLE APUS, WITHIN 24 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD)						
AD 1997-04-15 Airframe AD - N/A FAA #1830	PACIFIC SCIENTIFIC COMPANY, HTL/KIN-TECH DIVISION, FIRE EXTINGUISHER BOTTLE CARTRIDGES Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 1997-05-03 Airframe AD - N/A FAA #3114	ALLIEDSIGNAL AVIONICS, INC. MODELS GNS-XLS AND GNS-XL FLIGHT MANAGEMENT SYSTEMS (SUPERSEDED BY FAA AD 97-05-03 R1) Notes (ISSUING AUTHORITY: FAA).BY EQUIPMENT UNSTALLED, NO FURTHER ACTION REQUIRED AT THIS TIME.	30-MAY-2018 H: 6371.80 L: 2714					
AD 1997-05-03 R1 Airframe AD - N/A FAA #2211	ALLIEDSIGNAL AVIONICS, INC. MODELS GNS-XLS AND GNS-XL FLIGHT MANAGEMENT SYSTEMS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1997-11-10 Airframe AD - N/A FAA #944	CONSTANT FLOW PORTABLE OXYGEN 174290-14/-24/-34/-44/- MASKS Notes (ISSUING AUTHORITY: FAA).BY PART NUMBERS NOT INSTALLED. NO FURTHER ACTION REQUIRED AT THIS TIME.	30-MAY-2018 H: 6371.80 L: 2714					
AD 1997-18-03 Airframe AD - N/A FAA #2270	PURITAN-BENNETT AERO SYSTEMS CO. - CONE AND SEAL ASSEMBLIES Notes (ISSUING AUTHORITY: FAA).BY EQUIPMENT NOT INSTALLED	13-APR-2013 H: 4782.30 L: 2063					
AD 1997-19-18 Airframe AD - N/A FAA #2964	AUXILIARY POWER UNITS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 1997-24-02 R1 AMD Para (c) Airframe AD - Complied With FAA #801	PRESSURE BULKHEAD - OPTIONAL TERMINATING MODIFICATION Notes (ISSUING AUTHORITY: FAA).TERMINATES AD	03-AUG-2005 H: 2522.30 L: 983					
AD 1997-25-11 Airframe AD - N/A FAA #1870	DISABLE THE REMOTE FUEL/DEFUEL PANEL Notes (UPDATE NOTE: AD NA BY TYPE DESIGN) (ISSUING AUTHORITY: FAA).AD NA BY TYPE DESIGN	18-MAR-1998					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1997-25-11 R1 Airframe AD - N/A FAA #428	REMOTE FUEL/DEFUEL PANEL Notes (UPDATE NOTE: AD NA BY TYPE DESIGN) (ISSUING AUTHORITY: FAA).AD NA BY TYPE DESIGN	18-JAN-1998					
AD 1998-14-03 Airframe AD - N/A FAA #3310	ALLIEDSIGNAL, INC. - KT 76A TRANSPONDERS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.	11-NOV-2008					
AD 1998-24-27 Airframe AD - N/A FAA #3699	FIRST TECHNOLOGY FIRE AND SAFETY LTD. TOILET COMPARTMENT FIRE EXTINGUISHER Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 1998-25-02 Airframe AD - N/A FAA #3493	BF GOODRICH AVIONICS SYSTEMS, INC. SKYWATCH SKY497 INSTALLATIONS WITH A TOP-MOUNTED ANTENNA Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.	03-AUG-2005					
AD 1998-25-10 R1 Airframe AD - N/A FAA #50	AIRCRAFT BELTS, INC - SEAT RESTRAINT SYSTEMS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1999-01-14 Airframe AD - N/A FAA #2885	TO PREVENT A "RANDOM RESET" CONDITION OF THE ELECTRONIC FLIGHT INSTRUMENT SYSTEM	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 1999-04-10 Airframe AD - N/A FAA #617	PREVENT FIRE IN THE PASSENGER COMPARTMENT RESULTING FROM FAILURE OF THE FLUORESCENT LIGHT BALLAST OF THE CABIN SIDEWALL	11-NOV-2008					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 1999-08-21 Airframe AD - N/A FAA #2826	PURITAN-BENNETT AERO SYSTEMS COMPANY C351-2000 SERIES PASSENGER OXYGEN MASKS AND PORTABLE OXYGEN MASKS - PASSENGER OXYGEN MASKS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 1999-11-08 Engine 1 AD - Superseded FAA #83	PREVENT UNCOMMANDED ENGINE ACCELERATIONS/OVERSPEED/FAILURE (SUPERSEDED AD 99-23-26)	17-AUG-2019 H: 6485.50 C: 2778					
Notes (UPDATE NOTE: AD SUPERSEDED BY AD 99-23-26) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 99-23-26							
AD 1999-11-08 Engine 2 AD - Superseded FAA #33	PREVENT UNCOMMANDED ENGINE ACCELERATIONS/OVERSPEED/FAILURE (SUPERSEDED AD 99-23-26)	17-AUG-2019 H: 6485.50 C: 2778					
Notes (UPDATE NOTE: AD SUPERSEDED BY AD 99-23-26) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 99-23-26							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1999-12-06 Airframe AD - N/A FAA #3676	ALLIEDSIGNAL - VHF NAVIGATION RECEIVER MOD	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.							
AD 1999-23-22 R1 Airframe AD - N/A FAA #3502	MODE C TRANSPONDER(S) WITH SINGLE GILLHAM CODE ALTITUDE INPUT	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.							
AD 1999-23-22 R2 Airframe AD - N/A FAA #2520	MODE C TRANSPONDER(S) WITH SINGLE GILLHAM CODE ALTITUDE INPUT	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.) (ISSUING AUTHORITY: FAA) (NOTE: RESCINDED).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.							
AD 1999-23-24 Airframe AD - N/A FAA #2655	ALLIEDSIGNAL, INC. - RIA-32A NAVIGATION RECEIVERS	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME.							
AD 1999-23-26 AMD Para (a)(1) Engine 1 AD - Complied With FAA #650	PREVENT UNCOMMANDED ENG ACCEL REPLACE BUNA-N O-RINGS (MANDATORY)	03-MAY-2004					
Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ORIGINAL ON THE ENGINE BLD UP FROM FACTORY MFC P/N 6078T55P10							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 1999-25-07 Airframe AD - N/A FAA #89	MAIN BRAKE ASSEMBLIES	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 1999-26-16 Airframe AD - N/A FAA #2614	MLG HYDRAULIC AND FUEL LINES	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER							
AD 2000-01-51 Airframe AD - Superseded FAA #3	TO PREVENT ELECTRICAL SPARKS FROM A GROUNDER OBJECT FROM COMING INTO CONTACT WITH THE FUEL PORT FLOOD LIGHT HOUSING OF THE FUEL SERVICE	04-NOV-2019					
Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2001-02-5) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2001-02-5							
AD 2000-04-24 Airframe AD - N/A FAA #921	AUXILIARY POWER UNITS - LOAD COMPRESSOR IMPELLERS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2000-05-24 Airframe AD - N/A FAA #835	HONEYWELL KAP 140/KFC 225 AUTOPILOT SYSTEM	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2000-07-27 Airframe AD - N/A FAA #2676	HONEYWELL - PREVENT LOSS OF AIR DATA SOURCES	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2000-14-14 Airframe AD - N/A FAA #2573	MAIN LANDING GEAR (MLG)	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER							
AD 2000-18-04 Airframe AD - N/A FAA #3563	INSPECT AVIOINTERIORS SEATS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2000-23-02 Airframe AD - Complied With FAA #2382	INBOARD FLAP ACTUATOR BEAM ASSEMBLY	04-OCT-2000 H: 674.00 L: 257					
Notes (UPDATE NOTE: CW SB A604-27-006 R1).CW SB A604-27-006 R1. LEFT							
AD 2000-23-02 Airframe AD - Complied With FAA #3364	INBOARD FLAP ACTUATOR BEAM ASSEMBLY	04-OCT-2000 H: 674.00 L: 257					
Notes (UPDATE NOTE: CW SB A604-27-006 R1) (ISSUING AUTHORITY: FAA).CW SB A604-27-006 R1							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2000-23-02 RIGHT Airframe AD - Complied With FAA #3267	INBOARD FLAP ACTUATOR BEAM ASSEMBLY Notes (UPDATE NOTE: CW SB A604-27-006 R1) (ISSUING AUTHORITY: FAA).CW SB A604-27-006 R1	04-OCT-2000 H: 674.00 L: 257					
AD 2000-24-01 Airframe AD - Complied With FAA #559	MAIN LANDING GEAR WHEEL BAY PROTECTION SHIELDS Notes (UPDATE NOTE: CW SB 604-32-007) (ISSUING AUTHORITY: FAA).CW SB 604-32-007	02-FEB-2001					
AD 2001-02-05 Airframe AD - N/A FAA #2545	FUEL SERVICE PANEL Notes (UPDATE NOTE: AD NA TUC-33-30-01-1) (ISSUING AUTHORITY: FAA).AD NA TUC-33-30-01-1	06-JUN-2001					
AD 2001-03-52 Airframe AD - Complied With FAA #3104	FUEL MIGRATION Notes (UPDATE NOTE: COMPLIED WITH AFM REVISION) (ISSUING AUTHORITY: FAA).COMPLIED WITH AFM REVISION	07-MAR-2001 H: 807.00 L: 307					
AD 2001-08-01 Airframe AD - Superseded FAA #565	FUEL REGULATOR AND SHUT-OFF VALVES (SUPERSEDED BY FAA AD 2001-17-13) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2001-17-13) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2001-17-13	04-NOV-2019					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2001-10-03 Engine 1 AD - Superseded FAA #389	RUPTURE OF FAN DISK (SUPERSEDED BY FAA AD 2006-05-04) Notes (UPDATE NOTE: SUPERSEDED BY AD 2006-05-04) (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2006-05-04	08-JUL-2001 H: 915.00 C: 343					
AD 2001-10-03 Engine 2 AD - Superseded FAA #340	RUPTURE OF FAN DISK (SUPERSEDED BY FAA AD 2006-05-04) Notes (UPDATE NOTE: SUPERSEDED BY AD 2006-05-04) (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2006-05-04	08-JUL-2001 H: 915.00 C: 343					
AD 2001-10-09 Airframe AD - N/A FAA #2051	AUTOMATIC FLIGHT CONTROL SYSTEMS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2008					
AD 2001-10-13 Airframe AD - N/A FAA #2321	COFFEE MAKER/WATER HEATER WIRING Notes (UPDATE NOTE: BY AIRCRAFT DATE OF MANUFACTURE, NO FURTHER ACTION REQUIRED AT THIS TIME.) (ISSUING AUTHORITY: FAA).BY AIRCRAFT DATE OF MANUFACTURE, NO FURTHER ACTION REQUIRED AT THIS TIME.	11-NOV-2008					
AD 2001-12-06 Engine 1 AD - Complied With FAA #411	GENERAL ELECTRIC COMPANY - LUBRICATION SYSTEM FOR THE ENGINE BEARINGS Notes (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF AIR SEAL) (ISSUING AUTHORITY: FAA).COMPLIED WITH REPLACEMENT OF AIR SEAL	21-OCT-2009					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2001-12-06 Engine 2 AD - Complied With FAA #504	GENERAL ELECTRIC COMPANY - LUBRICATION SYSTEM FOR THE ENGINE BEARINGS	21-OCT-2009					
	Notes (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF AIR SEAL) (ISSUING AUTHORITY: FAA).COMPLIED WITH REPLACEMENT OF AIR SEAL						
AD 2001-12-06 AMD Paragraph (a) Engine 1 AD - Complied With FAA #858	GENERAL ELECTRIC COMPANY - LUBRICATION SYSTEM FOR THE ENGINE BEARINGS - MAGNETIC CHIP DETECTOR INDICATOR CHECK	17-SEP-2009 H: 3710.80 C: 1565					
	Notes (ISSUING AUTHORITY: FAA).IAW THE AD						
AD 2001-12-06 AMD Paragraph (a) Engine 2 AD - Complied With FAA #815	GENERAL ELECTRIC COMPANY - LUBRICATION SYSTEM FOR THE ENGINE BEARINGS - MAGNETIC CHIP DETECTOR INDICATOR CHECK	17-SEP-2009 H: 3710.80 C: 1565					
	Notes (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF AIR SEAL) (ISSUING AUTHORITY: FAA).COMPLIED WITH REPLACEMENT OF AIR SEAL						
AD 2001-12-06 AMD Paragraph (d) Engine 1 AD - Complied With FAA #347	GENERAL ELECTRIC COMPANY - LUBRICATION SYSTEM FOR THE ENGINE BEARINGS - REPLACEMENT OF AIR SEAL	07-OCT-2009 H: 3725.60 C: 1574					
	Notes (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF AIR SEAL) (ISSUING AUTHORITY: FAA).COMPLIED WITH REPLACEMENT OF AIR SEAL						
AD 2001-12-06 AMD Paragraph (d) Engine 2 AD - Complied With FAA #227	GENERAL ELECTRIC COMPANY - LUBRICATION SYSTEM FOR THE ENGINE BEARINGS - REPLACEMENT OF AIR SEAL	07-OCT-2009 H: 3725.60 C: 1574					
	Notes (UPDATE NOTE: COMPLIED WITH REPLACEMENT OF AIR SEAL) (ISSUING AUTHORITY: FAA).COMPLIED WITH REPLACEMENT OF AIR SEAL						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2001-14-09 Airframe AD - Open FAA #1454	WIRING OF THE LANDING LIGHT SWITCH AND THE J-BOX FAIRING LIGHT RELAYS Notes (ISSUING AUTHORITY: FAA)						
AD 2001-14-51 Airframe AD - N/A FAA #1122	UPS AVIATION TECHNOLOGIES, INC., MODEL APOLLO SL30 VHF NAV/COMM RADIO Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					
AD 2001-15-17 Airframe AD - N/A FAA #293	ROCKWELL COLLINS. CTL-92 - TRANSPONDER CONTROL PANELS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					
AD 2001-15-24 Airframe AD - N/A FAA #1213	WIRING FOR THE INTERNAL FUEL/DEFUEL PANEL Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER	05-NOV-2019					
AD 2001-17-13 Airframe AD - Superseded FAA #1084	KELLY AEROSPACE POWER SYSTEMS (SUPERSEDED BY FAA AD 2004-25-16) Notes (UPDATE NOTE: SUPERSEDED BY AD 2004-25-16) (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2004-25-16	04-NOV-2019					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2001-18-05 Airframe AD - N/A FAA #1205	FLIGHT EAGLE TIRES	05-NOV-2019					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2001-19-02 Engine 1 AD - Open FAA #691	GENERAL ELECTRIC COMPANY - ENGINE - PERFORM VISUAL INSPECTION AND CLEANING OF THE SCAVENGE SCREENS						
Notes (ISSUING AUTHORITY: FAA) (NOTE: THIS FAA AD HAS BEEN SUPERSEDED BY FAA AD 2003-05-10)							
AD 2001-19-02 Engine 2 AD - Open FAA #31	GENERAL ELECTRIC COMPANY - ENGINE - PERFORM VISUAL INSPECTION AND CLEANING OF THE SCAVENGE SCREENS						
Notes (ISSUING AUTHORITY: FAA) (NOTE: THIS FAA AD HAS BEEN SUPERSEDED BY FAA AD 2003-05-10)							
AD 2001-22-14 Airframe AD - N/A FAA #2803	OVERLAND AVIATION SERVICES - FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGES - CHECK/ REPLACE	28-AUG-2002					
Notes (AVG MAN HRS: 8) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2001-23-17 Airframe AD - N/A FAA #2075	GARMIN GNS 430 UNITS	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2002-06-05 Airframe AD - N/A FAA #3079	MODE C 621A-3 AIR TRAFFIC CONTROL (ATC) TRANSPONDERS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2002-06-06 Airframe AD - N/A FAA #1238	ROCKWELL COLLINS TDR-94 AND TDR-94D MODE S TRANSPONDERS	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2002-08-08 Airframe AD - Complied With FAA #846	INTEGRATED DRIVE GENERATOR (IDG) CABLE	25-MAR-2005					
Notes (UPDATE NOTE: COMPLIED WITH SB A604-73-002) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB A604-73-002							
AD 2002-08-08 AMD Par. (b) Airframe AD - Complied With FAA #170	INTEGRATED DRIVE GENERATOR (IDG) CABLE - INSTALLATION OF TEFLON TUBING AND CLAMPS	03-AUG-2005 H: 2522.30					
Notes (ISSUING AUTHORITY: FAA).PCW BY COMPLIANCE WITH SB A604-073-002 PARA B. REF: LOG ENTRY DATED 3/25/2001 - TO PREVENT ELECTRICAL ARCING BETWEEN THE IDG CABLE AND ENGINE COWLING							
AD 2002-08-08 AMD Par. (a) Airframe AD - Complied With FAA #3012	INTEGRATED DRIVE GENERATOR (IDG) CABLE - PERFORM A DETAILED INSPECTION OF THE IDG CABLES ON BOTH LEFT AND RIGHT ENGINES TO DETECT CHAFING AND OTHER DAMAGE BETWEEN THE SERVICE PYLONS TO THE IDG	03-AUG-2005 H: 2522.30					
Notes (ISSUING AUTHORITY: FAA).PCW BY COMPLIANCE WITH SB A604-073-002 PARA B. REF: LOG ENTRY DATED 3/25/2001 - TO PREVENT ELECTRICAL ARCING BETWEEN THE IDG CABLE AND ENGINE COWLING							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2002-13-07 Airframe AD - N/A FAA #2739	HONEYWELL - INERTIAL REFERENCE UNITS (IRU)	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2002-14-19 Airframe AD - N/A FAA #3640	ROCKWELL COLLINS, INC. ADC-85, ADC-85A, ADC-850D, AND ADC-850F AIR DATA COMPUTERS	03-AUG-2005					
Notes (AVG MAN HRS: 6) (APX COST: 1,040) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2002-15-02 Airframe AD - N/A FAA #985	HAMILTON SUNDSTRAND POWER SYSTEMS (FORMERLY SUNDSTRAND POWER SYSTEMS, TURBOMACH, AND SOLAR) T-62T SERIES AUXILIARY POWER UNITS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (ZONE: -) (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2002-20-09 Airframe AD - N/A FAA #2983	ROCKWELL COLLINS - AFD-3010 ADAPTIVE FLIGHT DISPLAY UNITS	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2002-21-01 Airframe AD - N/A FAA #927	ELECTRICAL TERMINAL CONTACT PINS - BRITAX SELL GMBH & CO. OHG WATER BOILERS, COFFEE MAKERS, AND BEVERAGE MAKERS	03-AUG-2005					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2002-22-13 Airframe AD - N/A FAA #1653	ROCKWELL COLLINS, INC. - FLIGHT MANAGEMENT COMPUTERS (FMC) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2003-04-06 Airframe AD - Superseded FAA #3658	INSPECT PRIMUS INTEGRATED NAV UNIT/REVISE AFM (SUPERSEDED BY AD 2006- 22-05) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2006-22-05) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2006-22-05	04-NOV-2019 H: 6485.50 L: 2778					
AD 2003-05-10 Engine 1 AD - Complied With FAA #176	B-SUMP SCAVENGE SCREENS Notes (UPDATE NOTE: COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017	26-NOV-2002 H: 1515.00					
AD 2003-05-10 Engine 2 AD - Complied With FAA #136	B-SUMP SCAVENGE SCREENS Notes (UPDATE NOTE: COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017	26-NOV-2002 H: 1515.00					
AD 2003-05-10 AMD Paragraph (c) Engine 1 AD - Complied With FAA #520	TERMINATING ACTION - INSTALL NEW OR REWORKED SCREENS Notes (UPDATE NOTE: COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017	26-NOV-2002 H: 1515.00					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-05-10 AMD Paragraph (c) Engine 2 AD - Complied With FAA #409	TERMINATING ACTION - INSTALL NEW OR REWORKED SCREENS Notes (UPDATE NOTE: COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017	26-NOV-2002 H: 1515.00					
AD 2003-05-10R1 Engine 1 AD - Complied With FAA #322	B-SUMP SCAVENGE SCREENS Notes (UPDATE NOTE: PREVIOUSLY COMPLIED WITH COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017) (ISSUING AUTHORITY: FAA).PREVIOUSLY COMPLIED WITH COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017	11-NOV-2008					
AD 2003-05-10R1 Engine 2 AD - Complied With FAA #110	B-SUMP SCAVENGE SCREENS Notes (UPDATE NOTE: PREVIOUSLY COMPLIED WITH COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017) (ISSUING AUTHORITY: FAA).PREVIOUSLY COMPLIED WITH COMPLIED WITH SB CF34BJ 79-0016 AND SB CF34BJ 79-0017	11-NOV-2008					
AD 2003-08-12 AMD Par. (a) Airframe AD - Complied With FAA #716	DO A DETAILED INSPECTION TO DETECT CRACKS OF THE VANE BRACKETS OF THE INBOARD FLAP ACTUATOR BEAM (SUPERSEDED BY AD 2004-09-37) Notes (UPDATE NOTE: CW SB 604-27-007) (ISSUING AUTHORITY: FAA).CW SB 604-27-007	26-NOV-2002 H: 1515.00 L: 581					
AD 2003-08-12 Airframe AD - Complied With FAA #3461	FLAP VANE BRACKET AND VANE ACTUATOR BEAM OF WING FLAP SYSTEMS (SUPERSEDED BY AD 2004-09-37) Notes (UPDATE NOTE: CW SB 604-27-007) (ISSUING AUTHORITY: FAA).CW SB 604-27-007	26-NOV-2002 H: 1515.00 L: 581					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-08-12 AMD PART D Airframe AD - Complied With FAA #78	INSP GAP/CRACK IN VANE BRACKET AND REPLACE CRACKED BRACKETS Notes (UPDATE NOTE: CW SB 604-27-007) (ISSUING AUTHORITY: FAA).CW SB 604-27-007	26-NOV-2002 H: 1515.00 L: 581					
AD 2003-08-12 AMD Par. (f) Airframe AD - Complied With FAA #1839	INSP/MOD PER PT B OR C OF SB & MED DIMENSION CHECK FOR FLAP (SUPERSEDED BY AD 2004-09-37) Notes (UPDATE NOTE: CW SB 604-27-007) (ISSUING AUTHORITY: FAA).CW SB 604-27-007	26-NOV-2002 H: 1515.00 L: 581					
AD 2003-08-12 AMD Par. (e) Airframe AD - Complied With FAA #3196	REPLACE ALL 12 VANE BRACKETS (SUPERSEDED BY AD 2004-09-37) Notes (UPDATE NOTE: CW SB 604-27-007) (ISSUING AUTHORITY: FAA).CW SB 604-27-007	26-NOV-2002 H: 1515.00 L: 581					
AD 2003-13-08 Airframe AD - N/A FAA #1883	GOODRICH - TAWS8000 TERRAIN AWARENESS WARNING SYSTEM (TAWS) (SUPERSEDED BY FAA AD 2004-08-15) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2003-22-12 Airframe AD - Complied With FAA #1987	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (ISSUING AUTHORITY: FAA).NEXT DUE 8755.8	05-JUL-2024 H: 8455.80 L: 3862					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-22-12 AMD Par. (j)(3) Airframe AD - Open FAA #377	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - INSPECT THE LEFT- AND RIGHT-SIDE AOA VANE DECAL TO VERIFY THAT THE CORRECT DECAL IS INSTALLED. FOR MODEL CL-600-2B16 (CL-604). Notes (ISSUING AUTHORITY: FAA)						
AD 2003-22-12 AMD Par. (d) Airframe AD - Open FAA #1917	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - ALL AOA VANE ANGLES WITHIN TOLERANCES: DISCONNECTION AND MEASUREMENT Notes (ISSUING AUTHORITY: FAA)	28-JUL-2005 H: 2522.30 L: 983					
AD 2003-22-12 AMD Par. (n) Airframe AD - Complied With FAA #859	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - ALTERNATIVE METHODS OF COMPLIANCE. (REFER TO TLMC CHAPTER 5 TASK 27-35-04-101* FOR RECURRING INSPECTION) Notes (ISSUING AUTHORITY: FAA)	02-JUL-2021 H: 6939.60 L: 3034					
AD 2003-22-12 AMD Par. (f) Airframe AD - Open FAA #2410	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - ANY AOA VANE ANGLE OUTSIDE TOLERANCES Notes (ISSUING AUTHORITY: FAA)						
AD 2003-22-12 AMD Par. (l) Airframe AD - Open FAA #2745	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - CONCURRENT REQUIREMENTS: CORRECTIVE ACTIONS - REMOVE EXISTING DECAL(S), AND DO THE ALIGNMENT CHECK(S) OF THE AOA VANE TRANSDUCER. Notes (ISSUING AUTHORITY: FAA)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-22-12 AMD Par. (k) Airframe AD - Open FAA #2168	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - CONCURRENT REQUIREMENTS: CORRECTIVE ACTIONS - REPLACE THE AOA VANE DECAL(S) WITH NEW VANE DECAL(S), AND ENSURE THAT THE NEW DECAL(S) IS THE CORRECT TYPE. Notes (ISSUING AUTHORITY: FAA)						
AD 2003-22-12 AMD Par. (b) Airframe AD - Complied With FAA #492	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - MEASUREMENT (INITIAL) Notes (ISSUING AUTHORITY: FAA).NEXT DUE AT 2822.3 HOURS	28-JUL-2005 H: 2522.30 L: 983					
AD 2003-22-12 AMD Par. (e) Airframe AD - Open FAA #265	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - ONE OR MORE AOA VANE ANGLES OUTSIDE TOLERANCES, BUT ALL AOA VANE ANGLES WITHIN EXPANDED TOLERANCES. Notes (ISSUING AUTHORITY: FAA)						
AD 2003-22-12 AMD Par. (a) Airframe AD - Open FAA #2290	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - REVISION OF AIRPLANE FLIGHT MANUAL (AFM) Notes (ISSUING AUTHORITY: FAA)						
AD 2003-22-12 AMD Par. (g) Airframe AD - Open FAA #3436	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - TRANSDUCER ASSEMBLY REWORK AND BASELINE RESISTANCE MEASUREMENT Notes (ISSUING AUTHORITY: FAA)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2003-22-12 (Left) AMD Par. (h) Airframe AD - Recurring FAA #237	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - MEASUREMENT, REPETITIVE MEASUREMENT AND CORRECTIVE ACTIONS	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
Notes (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (ISSUING AUTHORITY: FAA).PERFORMED FUNCTIONAL TEST							
AD 2003-22-12 (Right) AMD Par. (h) Airframe AD - Recurring FAA #2421	ELECTRONIC FLIGHT INSTRUMENT SYSTEM (EFIS) - MEASUREMENT, REPETITIVE MEASUREMENT AND CORRECTIVE ACTIONS	05-JUL-2024 H: 8455.80 L: 3862	H: 300.00			H: 8755.80	H: 60.70
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: WORK PERFORMED BY STANDARD AERO CRS UO2R221L ON WO 377320) (ISSUING AUTHORITY: FAA).PERFORMED FUNCTIONAL TEST							
AD 2003-26-06 Airframe AD - N/A FAA #2010	ANJOU - SAFETY BELTS AND RESTRAINT SYSTEMS	11-NOV-2008					
Notes (AVG MAN HRS: 1) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2003-26-14 Airframe AD - N/A FAA #2899	KIDDE AEROSPACE - HAND-HELD HALON FIRE EXTINGUISHERS REMOVAL	11-FEB-2003					
Notes (AVG MAN HRS: 1) (APX COST: 60) (ISSUING AUTHORITY: FAA) (NOTE: THIS AD AFFECTS AIRCRAFT THAT ARE CERTIFICATED IN ANY CATEGORY AND INCORPORATE HAND-HELD HALON FIRE EXTINGUISHERS WITH THE FOLLOWING: (1) PART NUMBER (P/N) 898052; AND (2) A SERIAL NUMBER IN THE RANGE OF V-432001 THROUGH W-389653 INCLUSIVE THAT WERE MANUFACTURED SOMETIME FROM 1995-2002).BY PART NUMBER							
AD 2004-08-15 Airframe AD - N/A FAA #823	GOODRICH AVIONICS SYSTEMS, INC - TAWS8000 TERRAIN AWARENESS WARNING SYSTEMS (TAWS)	11-NOV-2008					
Notes (AVG MAN HRS: 3) (APX COST: 195) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2004-09-37 Airframe AD - Complied With FAA #911	INBOARD FLAP ACTUATOR BEAM Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002) (ISSUING AUTHORITY: FAA).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018 H: 6372.80 L: 2715					
AD 2004-09-37 AMD Paragraph (a)(b) Airframe AD - Complied With FAA #3160	INBOARD FLAP ACTUATOR BEAM - INSPECTION/REPETITIVE INSPECTION Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002) (ISSUING AUTHORITY: FAA).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018 H: 6372.80 L: 2715					
AD 2004-09-37 AMD Paragraph (d)(e) Airframe AD - Complied With FAA #738	INBOARD FLAP ACTUATOR BEAM - TERMINATING ACTIONS (USING PARAGRAPH (E)) Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002) (ISSUING AUTHORITY: FAA).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018 H: 6372.80 L: 2715					
AD 2004-09-37 AMD Paragraph (d)(f) Airframe AD - Complied With FAA #3002	INBOARD FLAP ACTUATOR BEAM - TERMINATING ACTIONS (USING PARAGRAPH (F)) Notes (UPDATE NOTE: PCW SB A604-27-007 R! 26-NOV-2002) (ISSUING AUTHORITY: FAA).PCW SB A604-27-007 R! 26-NOV-2002	16-JUN-2018 H: 6372.80 L: 2715					
AD 2004-10-15 Airframe AD - N/A FAA #1330	GARMIN TRANSPONDER SOFTWARE (SUPERSEDED BY AD 2005- 01-19) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2004-13-20 Airframe AD - N/A FAA #1155	GPS NAVIGATION UNITS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					
AD 2004-16-14 Airframe AD - N/A FAA #1540	THALES AVIONICS TA/RA VSI-TCAS INDICATORS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					
AD 2004-21-04 Airframe AD - N/A FAA #2561	BECKER FLUGFUNKWERK AR-4201 VERY HIGH FREQUENCY (VHF) AM TRANSCEIVER - AIRCRAFT FLIGHT MANUAL (AFM) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					
AD 2004-22-01 Airframe AD - N/A FAA #2685	CARGO RESTRAINT STRAP ASSEMBLIES - AFM AND WEIGHT & BALANCE CHANGES - LIMITATION Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABLE TO CARGO RESTRAINT STRAP ASSEMBLIES PART NUMBER (P/N) 1519-MCIDS HAVE BEEN INSTALLED PER SUPPLEMENTAL TYPE CERTIFICATE (STC) ST01004NY).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2004-24-03 Airframe AD - N/A FAA #2478	HAMILTON SUNDSTRAND POWER SYSTEMS T-62T SERIES AUXILIARY POWER UNITS (APUS) (AIRWORTHINESS) Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2004-25-16 R2 Engine 2 AD - Open FAA #798	ENGINE - FUEL SYSTEM (73-00-00) - INSPECTION OF CONNECTION ORIENTATION BETWEEN THE AFT ACTUATOR HEAD HOSE ASSEMBLY AND THE MAIN FUEL CONTROL						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2004-25-19 Airframe AD - Complied With FAA #3087	PREMATURE WEAR OF THE POTENTIOMETERS IN AOA TRANSDUCERS HAVING A CERTAIN PART NUMBER. Notes (UPDATE NOTE: AD NA TO PART NUMBERS INSTALLED) (ISSUING AUTHORITY: FAA).AD NA TO PART NUMBERS INSTALLED	03-AUG-2005					
AD 2004-25-19 AMD Par. (f) Airframe AD - N/A FAA #414	PREMATURE WEAR OF THE POTENTIOMETERS IN AOA TRANSDUCERS HAVING A CERTAIN PART NUMBER - AIRPLANE FLIGHT MANUAL (AFM) REVISIONS. Notes (UPDATE NOTE: AD NA TO PART NUMBERS INSTALLED) (ISSUING AUTHORITY: FAA).AD NA TO PART NUMBERS INSTALLED	03-AUG-2005					
AD 2004-25-19 AMD Par. (g) Right Airframe AD - N/A FAA #1871	PREMATURE WEAR OF THE POTENTIOMETERS IN AOA TRANSDUCERS HAVING CERTAIN PART NUMBER - REPETITIVE TESTS Notes (UPDATE NOTE: AD NA TO PART NUMBERS INSTALLED) (ISSUING AUTHORITY: FAA).AD NA TO PART NUMBERS INSTALLED	03-AUG-2005					
AD 2004-25-19 AMD Par. (g) Left Airframe AD - N/A FAA #2501	PREMATURE WEAR OF THE POTENTIOMETERS IN AOA TRANSDUCERS HAVING CERTAIN PART NUMBER - REPETITIVE TESTS Notes (UPDATE NOTE: AD NA TO PART NUMBERS INSTALLED) (ISSUING AUTHORITY: FAA).AD NA TO PART NUMBERS INSTALLED	03-AUG-2005					
AD 2004-26-02 Engine 1 AD - Open FAA #537	CERTAIN HIGH PRESSURE COMPRESSOR (HPC) Notes (ISSUING AUTHORITY: FAA)		C: 20000			C: 20000.00	C: 15997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2004-26-02 Engine 2 AD - Open FAA #187	CERTAIN HIGH PRESSURE COMPRESSOR (HPC) Notes (ISSUING AUTHORITY: FAA)		C: 20000			C: 20000.00	C: 15997
AD 2005-01-19 Airframe AD - N/A FAA #2268	GARMIN INTERNATIONAL INC. - MODE S TRANSPONDERS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	03-AUG-2005					
AD 2005-04-07 Airframe AD - Complied With FAA #727	REVISION TO AIRPLANE FLIGHT MANUAL (AFM) - NEW COLD WEATHER OPERATIONS LIMITATION - CANCELLED Notes (ISSUING AUTHORITY: FAA).PERFORMED IN AFM	27-FEB-2005 H: 2496.00 L: 975					
AD 2005-07-27 Airframe AD - N/A FAA #1660	AVIOINTERIORS S.P.A - SEAT CENTRAL CROSSMEMBER Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2005-11-04 Airframe AD - N/A FAA #2795	MICROPHONE JACK ASSEMBLIES. Notes (UPDATE NOTE: AD NA TO MODIFICATION) (ISSUING AUTHORITY: FAA).AD NA TO MODIFICATION	03-AUG-2005					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2005-11-04 AMD Par. (f) Airframe AD - N/A FAA #3237	MICROPHONE JACK ASSEMBLY - AIRPLANE FLIGHT MANUAL (AFM) REVISION - REVISE THE LIMITATIONS AND NORMAL PROCEDURES SECTION (AIRWORTHINESS) Notes (UPDATE NOTE: AD NA TO MODIFICATION) (ISSUING AUTHORITY: FAA).AD NA TO MODIFICATION	03-AUG-2005					
AD 2005-15-04 Airframe AD - Complied With FAA #2730	LANDING GEAR PARTS Notes (UPDATE NOTE: CW SB 604-32-014 PAR A) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2014-15-13).CW SB 604-32-014 PAR A	03-APR-2013					
AD 2005-15-04 AMD Par. (f)(3) Airframe AD - Complied With FAA #616	LANDING GEAR PARTS - ADD SERIAL NUMBERS OR PART NUMBERS Notes (UPDATE NOTE: CW SB 604-32-014 PAR A) (ISSUING AUTHORITY: FAA).CW SB 604-32-014 PAR A	03-APR-2013					
AD 2005-15-04 AMD Par. (h) Airframe AD - Complied With FAA #523	LANDING GEAR PARTS - REVISE THE AIRWORTHINESS LIMITATIONS SECTION (ALS) Notes (UPDATE NOTE: CW SB 604-32-014 PAR A) (ISSUING AUTHORITY: FAA).CW SB 604-32-014 PAR A	03-APR-2013					
AD 2005-20-26 Airframe AD - N/A FAA #3356	AVIOINTERIORS S.P.A. (FORMERLY ALVEN), - SERISES 312 BOX MOUNTED SEATS - SEAT ATTACHMENTS. Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2005-20-31 Airframe AD - N/A FAA #60	HONEYWELL - FLIGHT MANAGEMENT SYSTEM (FMS) ONE MILLION WORD (1M OR 700K) DATA BASES (9104 CYCLE OR EARLIER) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2006-22-05) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2006-22-05	04-NOV-2019 H: 6485.50 L: 2778					
AD 2005-25-08 Airframe AD - N/A FAA #1822	SHADIN ADC-2000 AIR DATA COMPUTERS - ELECTRONIC FLIGHT INFORMATION SYSTEM (EFIS) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2006-02-04 Airframe AD - Complied With FAA #372	RUDDER BALANCE SPRING ASSEMBLY Notes (UPDATE NOTE: PREVIOUSLY CW SB 604-27-013 07-12-04) (ISSUING AUTHORITY: FAA).PREVIOUSLY CW SB 604-27-013 07-12-04	19-OCT-2006 H: 2790.10 L: 1108					
AD 2006-04-12 AMD Paragraph (f)(2)(h)(1) Engine 1 AD - Recurring FAA #251	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - INSPECTION - FOR ENGINES INSTALLED ON BOMBARDIER CANADAI R BJ AIRPLANES Notes (ISSUING AUTHORITY: FAA)	19-OCT-2009 H: 3725.60 C: 1574	C: 3100			C: 4674.00	C: 671
AD 2006-04-12 AMD Paragraph (f)(2)(h)(1) Engine 2 AD - Recurring FAA #677	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - INSPECTION - FOR ENGINES INSTALLED ON BOMBARDIER CANADAI R BJ AIRPLANES Notes (ISSUING AUTHORITY: FAA)	19-OCT-2009 H: 3725.60 C: 1574	C: 3100			C: 4674.00	C: 671



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-04-12 Engine 1 AD - Open FAA #486	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - INSPECTION/ REPLACEMENT (THIS AD SUPERSEDES AD 2004-15-03R1) Notes (ISSUING AUTHORITY: FAA)						
AD 2006-04-12 Engine 2 AD - Open FAA #224	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - INSPECTION/ REPLACEMENT (THIS AD SUPERSEDES AD 2004-15-03R1) Notes (ISSUING AUTHORITY: FAA)						
AD 2006-04-12 AMD Paragraph (m) Engine 1 AD - Open FAA #17	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - REPLACEMENT (OPTIONAL TERMINATING ACTION) Notes (ISSUING AUTHORITY: FAA)						
AD 2006-04-12 AMD Paragraph (m) Engine 2 AD - Open FAA #71	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - REPLACEMENT (OPTIONAL TERMINATING ACTION) Notes (ISSUING AUTHORITY: FAA)						
AD 2006-04-12 AMD Paragraph (n) Engine 1 AD - Open FAA #912	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - REPLACEMENT (TERMINATING ACTION) Notes (ISSUING AUTHORITY: FAA)						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-04-12 AMD Paragraph (n) Engine 2 AD - Open FAA #164	STAGE 5 LPT DISKS AND STAGE 6 LPT DISKS - REPLACEMENT (TERMINATING ACTION) Notes (ISSUING AUTHORITY: FAA)						
AD 2006-05-04 Engine 1 AD - Superseded FAA #122	FAN DISK Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2007-07-07) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2007-07-07).AD SUPERSEDED BY AD 2007-07-07	05-NOV-2019					
AD 2006-05-04 Engine 2 AD - Superseded FAA #918	FAN DISK Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2007-07-07) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2007-07-07).AD SUPERSEDED BY AD 2007-07-07	05-NOV-2019					
AD 2006-08-03 Airframe AD - N/A FAA #3595	BOTTOM SEAT FOLDING MECHANISMS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2006-16-18 Airframe AD - N/A FAA #131	SANDEL AVIONICS INCORPORATED - INSTALLING A WARNING PLACARD ON THE TAWS/RMI Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-16-18 R1 Airframe AD - N/A FAA #1153	SANDEL AVIONICS INCORPORATED - INSTALLING A WARNING PLACARD ON THE TAWS/RMI Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: ANY INSTALLATION COMPRISED OF: ST3400 WITH VOR BEARING POINTER CONFIGURED IN COMPOSITE NAV - AND - 3.05 OR A3.05 SOFTWARE OR EARLIER).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2006-17-13 Airframe AD - N/A FAA #3441	REPLACING THE EXISTING ATTACHMENT BOLTS FOR THE SEAT BELTS WITH LONGER ATTACHMENT BOLTS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2006-18-04 Airframe AD - Complied With FAA #2622	UNCOMMANDED HORIZONTAL STABILIZER TRIM MOTION - CANCELLED Notes (ISSUING AUTHORITY: FAA).INSERTED FM CHANGE	06-SEP-2006 H: 2769.00 L: 1094					
AD 2006-18-08 Airframe AD - N/A FAA #2116	GOODYEAR AVIATION - NOSEWHEEL TIRES Notes (UPDATE NOTE: AD N A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2006-19-04 Airframe AD - N/A FAA #1603	HONEYWELL INTERNATIONAL, INC - COM UNIT AND MODE S TRANSPONDER Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2006-22-06 AMD Paragraph (h) Airframe AD - Complied With FAA #3140	EMERGENCY AND ABNORMAL PROCEDURES SECTION OF THE AFM - APPLY AFM REVISIONS (SUPERSEDED BY AD 2007-05-11) Notes (UPDATE NOTE: INSTALLED HSTCU P/N 7076-10) (ISSUING AUTHORITY: FAA).INSTALLED HSTCU P/N 7076-10	06-AUG-2007 H: 2844.50 L: 1127					
AD 2006-22-06 AMD Paragraph (m) Airframe AD - Complied With FAA #704	EMERGENCY AND ABNORMAL PROCEDURES SECTION OF THE AFM - OPTIONAL TERMINATING ACTION (SUPERSEDED BY AD 2007-05-11) Notes (UPDATE NOTE: INSTALLED HSTCU P/N 7076-10) (ISSUING AUTHORITY: FAA).IAW THE AD	06-AUG-2007 H: 3099.20 L: 1251					
AD 2006-25-15 Airframe AD - N/A FAA #1578	SICMA AERO SEAT - TWO HEADREST BUSHINGS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2007-04-15 Airframe AD - N/A FAA #2853	SICMA AERO SEAT - INSTALLING NEW TAB LOCKS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	11-NOV-2008					
AD 2007-04-51 Engine 1 AD - N/A FAA #651	INSPECTION OF FAN DISK - VISUAL CHECK & TACTILE INSPECTION OF THE BORE AREA ON THE FAN DISKS Notes (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2007-05-16).BY SERIAL NUMBER	21-FEB-2007 H: 2928.20 C: 1171					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2007-04-51 Engine 2 AD - N/A FAA #455	INSPECTION OF FAN DISK - VISUAL CHECK & TACTILE INSPECTION OF THE BORE AREA ON THE FAN DISKS Notes (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2007-05-16).BY SERIAL NUMBER	21-FEB-2007 H: 2928.20 C: 1171					
AD 2007-05-11 Airframe AD - Complied With FAA #1711	HORIZONTAL STABILIZER TRIM CONTROL UNIT (HSTCU) Notes (UPDATE NOTE: COMPLIED WITH SB A604-27-029 PART B) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB A604-27-029 PART B	03-MAY-2007					
AD 2007-05-11 AMD Paragraph (g) Airframe AD - Complied With FAA #80	HORIZONTAL STABILIZER TRIM CONTROL UNIT (HSTCU) - AIRPLANE FLIGHT MANUAL (AFM) REVISIONS Notes (UPDATE NOTE: REVISED THE AFM) (ISSUING AUTHORITY: FAA).REVISED THE AFM	31-MAR-2007 H: 2946.40 L: 1180					
AD 2007-05-11 AMD Paragraph (o) Airframe AD - Complied With FAA #1182	HORIZONTAL STABILIZER TRIM CONTROL UNIT (HSTCU) - TERMINATING ACTION - INSTALLATION OF NEW, IMPROVED PART Notes (UPDATE NOTE: COMPLIED WITH SB A604-27-029 PART B) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB A604-27-029 PART B	03-MAY-2007 H: 3002.20 L: 1206					
AD 2007-05-16 Engine 1 AD - N/A FAA #531	INSPECTION OF THE FAN DISK Notes (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2009-26-09).BY SERIAL NUMBER	14-MAR-2007 H: 2946.40 C: 1171					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2007-05-16 Engine 2 AD - N/A FAA #487	INSPECTION OF THE FAN DISK Notes (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2009-26-09).BY SERIAL NUMBER	14-MAR-2007 H: 2946.40 C: 1171					
AD 2007-05-20 Airframe AD - N/A FAA #551	OVERSPEED OF THE GAS GENERATOR ROTOR Notes (AVG MAN HRS: 10) (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO MICROTURBO SAPHIR 20 MODELS 095 AUXILIARY POWER UNITS (APU).).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2007-07-07 Engine 1 AD - Complied With FAA #252	FAN DISK INSPECTION Notes (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2009-26-09)	19-OCT-2009 H: 3725.60 C: 1574					
AD 2007-07-07 Engine 2 AD - Superseded FAA #220	FAN DISK INSPECTION Notes (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2009-26-09)	19-OCT-2009 H: 3725.60 C: 1574					
AD 2007-07-07R1 Engine 1 AD - Superseded FAA #19	FAN DISK INSPECTION Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2009-26-09) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2009-26-09).AD SUPERSEDED BY AD 2009-26-09	21-OCT-2009					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2007-07-07R1 Engine 2 AD - Superseded FAA #348	FAN DISK INSPECTION	21-OCT-2009					
Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2009-26-09) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2009-26-09).AD SUPERSEDED BY AD 2009-26-09							
AD 2007-07-12 Airframe AD - Complied With FAA #1581	HONEYWELL NZ-2000, IC-800, OR IC-800E NAVIGATION COMPUTERS	18-APR-2009					
Notes (UPDATE NOTE: CW HONEYWELL SB 6111-008R1) (ISSUING AUTHORITY: FAA).CW HONEYWELL SB 6111-008R1							
AD 2007-14-02 Airframe AD - Complied With FAA #402	UNCOMMANDED PARTIAL RETRACTIONS OF THE NOSE LANDING GEAR (NLG) - PREVENT INTERNAL LEAKAGE OF THE SELECTOR VALVE - CANCELLED	16-JUL-2007 H: 3086.90 L: 1244					
Notes (UPDATE NOTE: COMPLIED WITH SB 604-32-021 R2) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB 604-32-021 R2							
AD 2007-14-06 Airframe AD - N/A FAA #1944	ACAS II SYSTEM - ISOLATION DIODE	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2007-19-12 Airframe AD - N/A FAA #3175	SICMA AERO SEAT	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2007-19-13 Airframe AD - N/A FAA #1639	B/E AEROSPACE SKYLUXE II (AA2) PASSENGER SEATS - HYDROLOK RETAINING PIN	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2007-23-01 Airframe AD - Superseded FAA #591	GOODRICH EVACUATION SYSTEMS - INSPECT	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: SUPERSEDED BY AD 2012-06-25) (ISSUING AUTHORITY: FAA) (NOTE: THIS AD APPLIES TO GOODRICH EVACUATION SYSTEMS APPROVED UNDER TECHNICAL STANDARD ORDER (TSO) TSO-C69B, AS INSTALLED ON AIRBUS MODEL A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, AND -343 AIRPLANES; MODEL A340-211, -212, -213, -311, -312, AND -313 AIRPLANES; AND MODEL A340-541 AND -642 AIRPLANES; CERTIFICATED IN ANY CATEGORY.).SUPERSEDED BY AD 2012-06-25							
AD 2007-26-11 Airframe AD - N/A FAA #893	INTERTECHNIQUE ZODIAC AIRCRAFT SYSTEMS - F5341 HIGH-PRESSURE OXYGEN CYLINDER	11-NOV-2008					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED							
AD 2008-02-06 Airframe AD - N/A FAA #1406	GARMIN INTERNATIONAL - GSM 85 SERVO GEARBOX UNITS	11-NOV-2008					
Notes (AVG MAN HRS: 7) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2008-06-27 Airframe AD - N/A FAA #3016	EVACUATION SYSTEM'S SHEAR-PIN - INSPECTION / REPLACEMENT	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: FOR GOODRICH EVACUATION SYSTEMS INSTALLED ON BOEING MODEL 767 AIRPLANES).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2008-06-28 Airframe AD - Superseded FAA #2834	AVIDYNE CORPORATION (AVIDYNE) - PRIMARY FLIGHT DISPLAYS (SUPERSEDED BY FAA AD 2009-05-05) Notes (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2009-05-05	04-NOV-2019 H: 6485.50 L: 2778					
AD 2008-06-28 R1 Airframe AD - Superseded FAA #2052	AVIDYNE CORPORATION (AVIDYNE) - PRIMARY FLIGHT DISPLAYS (SUPERSEDED BY FAA AD 2009-05-05) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2009-05-05) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2009-05-05	04-NOV-2019 H: 6485.50 L: 2778					
AD 2008-08-06 Airframe AD - Complied With FAA #2042	REVISION TO AIRPLANE FLIGHT MANUAL (AFM) - NEW COLD WEATHER OPERATIONS LIMITATIONS - CANCELLED Notes (UPDATE NOTE: REVISION INSTALLED IN AFM) (ISSUING AUTHORITY: FAA).REVISION INSTALLED IN AFM	14-APR-2008 H: 3311.30 L: 1366					
AD 2008-19-01 Airframe AD - N/A FAA #1751	HARCO LABS - AOA PROBES Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED	29-SEP-2008					
AD 2008-21-09 Airframe AD - Complied With FAA #344	COLD WEATHER OPERATION LIMITATIONS Notes (UPDATE NOTE: IAW THE AD REVISED THE AFM) (ISSUING AUTHORITY: FAA).IAW THE AD REVISED THE AFM	16-OCT-2008 H: 3486.90 L: 1456					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-05-05 Airframe AD - N/A FAA #507	AVIDYNE CORPORATION (AVIDYNE) - PRIMARY FLIGHT DISPLAYS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2009-05-08 Airframe AD - N/A FAA #2030	TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GLOBAL POSITIONING SYSTEM (GPS)) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	13-APR-2013					
AD 2009-06-05 Airframe AD - N/A FAA #2432	WING ANTI-ICE PICCOLO DUCT FAILURE Notes (UPDATE NOTE: AD NA TO SERIAL NUMBER INSTALLED) (ISSUING AUTHORITY: FAA).AD NA TO SERIAL NUMBER INSTALLED	12-APR-2013 H: 4782.30 L: 2063					
AD 2009-06-05 R1 Airframe AD - N/A FAA #838	WING ANTI-ICE PICCOLO DUCT FAILURE Notes (ISSUING AUTHORITY: FAA).NO ACTION REQUIRED	04-MAR-2010 H: 3788.90 L: 1597					
AD 2009-07-12 Engine 1 AD - Complied With FAA #270	GENERAL ELECTRIC COMPANY - HIGH-PRESSURE (HP) - REMOVE THE 4-STEP SEALS, P/NS 4923T54G01, 6019T90G03, 6037T99G01, 6037T99G02, AND 6037T99G03. INCORPORATE AN 8-STEP SEAL, EITHER BY MODIFYING THE EXISTING 4-STEP SEAL TO AN 8-STEP SEAL, OR BY REPLACING IT WITH AN 8-STEP SEAL. Notes (UPDATE NOTE: CW INSTRUCTIONS IN SB CF34-BJ-72-0217) (ISSUING AUTHORITY: FAA) (NOTE: PERFORMED AT THE NEXT PIECEPART EXPOSURE AFTER THE EFFECTIVE DATE OF THIS AD).CW INSTRUCTIONS IN SB CF34-BJ-72-0217	14-OCT-2009 H: 3725.60 C: 1574					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-07-12 Engine 2 AD - Complied With FAA #275	GENERAL ELECTRIC COMPANY - HIGH-PRESSURE (HP) - REMOVE THE 4-STEP SEALS, P/NS 4923T54G01, 6019T90G03, 6037T99G01, 6037T99G02, AND 6037T99G03. INCORPORATE AN 8-STEP SEAL, EITHER BY MODIFYING THE EXISTING 4-STEP SEAL TO AN 8-STEP SEAL, OR BY REPLACING IT WITH AN 8-STEP SEAL. Notes (UPDATE NOTE: CW INSTRUCTIONS IN SB CF34-BJ-72-0217) (ISSUING AUTHORITY: FAA) (NOTE: PERFORMED AT THE NEXT PIECEPART EXPOSURE AFTER THE EFFECTIVE DATE OF THIS AD).CW INSTRUCTIONS IN SB CF34-BJ-72-0217	14-OCT-2009 H: 3725.60 C: 1574					
AD 2009-08-01 Airframe AD - N/A FAA #2764	HONEYWELL, INC - FMSS Notes (ISSUING AUTHORITY: FAA).BY PART NUMBER NOT INSTALLED, ALL EQUIP IS COLLINS	06-MAY-2009 H: 3633.70 L: 1524					
AD 2009-14-03 Airframe AD - Complied With FAA #3265	FLIGHT CONTROLS Notes (UPDATE NOTE: IAW THE AD REVISED THE AFM) (ISSUING AUTHORITY: FAA).IAW THE AD REVISED THE AFM	09-JUL-2009 H: 3655.70 L: 1540					
AD 2009-14-03 AMD Para (f)(3) Airframe AD - Complied With FAA #3167	REVISE STICK PUSHER CAPSTAN SHAFT FAILURES THE AIRWORTHINESS LIMITATIONS SECTION OF THE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS (MANDATORY) Notes (ISSUING AUTHORITY: FAA).IAW THE AD	09-JUL-2009 H: 3655.70 L: 1540					
AD 2009-14-03 AMD Para (f)(1) Airframe AD - Complied With FAA #2937	REVISE STICK PUSHER CAPSTAN SHAFT FAILURES THE NORMAL PROCEDURES SECTION OF THE APPLICABLE AIRPLANE FLIGHT MANUAL (AFM) (MANDATORY) Notes (ISSUING AUTHORITY: FAA).IAW THE AD INCORPORATED IN AFM REV 66	09-JUL-2009 H: 3655.70 L: 1540					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-21-03 Airframe AD - N/A FAA #326	APU FULL- AUTHORITY DIGITAL CONTROLLER (FADEC)	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2009-21-10 Airframe AD - N/A FAA #186	AVOX SYSTEMS AND B/E AEROSPACE OXYGEN CYLINDER ASSEMBLIES	13-APR-2013					
	Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED						
AD 2009-21-10 R1 Airframe AD - N/A FAA #2164	AVOX SYSTEMS AND B/E AEROSPACE OXYGEN CYLINDER ASSEMBLIES	11-APR-2013					
	Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED						
AD 2009-24-11 AMD PARA (L)(9) Engine 1 AD - Superseded FAA #495	ACCOMPLISH FAN BLADE (THIS AD HAS BEEN SUPERSEDED BY AD 2010-01-04) FOR ENGINES WITH FAN BLADES, P/N 6018T30P14, INSTALLED, IF YOU HAVE PERFORMED AN ECI OF THE FAN BLADE, YOU DON'T NEED TO INSPECT THE FAN BLADE ABRADABLE RUB STRIP FOR WEAR.	30-DEC-2009					
	Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2010-01-04).AD SUPERSEDED BY AD 2010-01-04						
AD 2009-24-11 AMD PARA (L)(9) Engine 2 AD - Superseded FAA #928	ACCOMPLISH FAN BLADE (THIS AD HAS BEEN SUPERSEDED BY AD 2010-01-04) FOR ENGINES WITH FAN BLADES, P/N 6018T30P14, INSTALLED, IF YOU HAVE PERFORMED AN ECI OF THE FAN BLADE, YOU DON'T NEED TO INSPECT THE FAN BLADE ABRADABLE RUB STRIP FOR WEAR.	30-DEC-2009					
	Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2010-01-04).AD SUPERSEDED BY AD 2010-01-04						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-24-11 AMD Paragraph (l)(5) Engine 1 AD - N/A FAA #209	ACCOMPLISH FAN BLADE (THIS AD HAS BEEN SUPERSEDED BY AD2010-01-04) IF YOU FIND A CRACK IN THE RETAINING PIN HOLES OF THE FAN BLADE, REMOVE THE BLADE FROM SERVICE. Notes (ISSUING AUTHORITY: FAA).BY EFFECTIVITY N/A PER ENG P/N	30-DEC-2009 H: 3756.90 C: 1587					
AD 2009-24-11 AMD Paragraph (l)(5) Engine 2 AD - N/A FAA #777	ACCOMPLISH FAN BLADE (THIS AD HAS BEEN SUPERSEDED BY AD2010-01-04) IF YOU FIND A CRACK IN THE RETAINING PIN HOLES OF THE FAN BLADE, REMOVE THE BLADE FROM SERVICE. Notes (ISSUING AUTHORITY: FAA).BY EFFECTIVITY N/A PER ENG P/N	30-DEC-2009 H: 3756.90 C: 1587					
AD 2009-24-11 Engine 1 AD - Superseded FAA #375	FAN BLADE AND AFT ACTUATOR HEAD HOSES (SUPERSEDED BY FAA AD 2010-01-04) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2010-01-04) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2010-01-04).AD SUPERSEDED BY AD 2010-01-04	30-DEC-2009					
AD 2009-24-11 Engine 2 AD - Superseded FAA #30	FAN BLADE AND AFT ACTUATOR HEAD HOSES (SUPERSEDED BY FAA AD 2010-01-04) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2010-01-04) (ISSUING AUTHORITY: FAA) (NOTE: SUPERSEDED BY FAA AD 2010-01-04).AD SUPERSEDED BY AD 2010-01-04	30-DEC-2009					
AD 2009-24-11 AMD Paragraph (l)(3)(4)(6) Engine 1 AD - N/A FAA #713	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1- INITIAL / REPETITIVE EDDY CURRENT INSPECTION (ECI) OF THE FAN BLADES. (SUPERSEDED BY FAA AD 2010-01-04) Notes (ISSUING AUTHORITY: FAA).BY EFFECTIVITY	30-DEC-2009 H: 3756.90 C: 1587					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-24-11 AMD Paragraph (l)(3)(4)(6) Engine 2 AD - N/A FAA #313	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1- INITIAL / REPETITIVE EDDY CURRENT INSPECTION (ECI) OF THE FAN BLADES. (SUPERSEDED BY FAA AD 2010-01-04) Notes (ISSUING AUTHORITY: FAA).BY PART NUMBER	30-DEC-2009 H: 3756.90 C: 1587					
AD 2009-24-11 AMD Paragraph (l)(8)(9)(10) Engine 1 AD - Complied With FAA #705	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1- INITIAL / REPETITIVE INSPECTION OF THE FAN BLADE ABRADABLE RUB STRIP FOR WEAR. (SUPERSEDED BY FAA AD 2010-01-04) Notes (ISSUING AUTHORITY: FAA)	19-JUL-2010 H: 3903.70 C: 1663					
AD 2009-24-11 AMD Paragraph (l)(8)(9)(10) Engine 2 AD - Complied With FAA #346	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1- INITIAL / REPETITIVE INSPECTION OF THE FAN BLADE ABRADABLE RUB STRIP FOR WEAR. (SUPERSEDED BY FAA AD 2010-01-04) Notes (ISSUING AUTHORITY: FAA)	19-JUL-2010 H: 3903.70 C: 1663					
AD 2009-24-11 AMD Paragraph (l)(1)(2) Engine 1 AD - N/A FAA #817	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1- REMOVE FAN BLADES FROM SERVICE. (SUPERSEDED BY FAA AD 2010-01-04) Notes (ISSUING AUTHORITY: FAA).BY EFFECTIVITY	30-DEC-2009 H: 3756.90 C: 1587					
AD 2009-24-11 AMD Paragraph (l)(1)(2) Engine 2 AD - N/A FAA #114	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1- REMOVE FAN BLADES FROM SERVICE. (SUPERSEDED BY FAA AD 2010-01-04) Notes (ISSUING AUTHORITY: FAA).BY EFFECTIVITY	30-DEC-2009 H: 3756.90 C: 1587					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-24-11 AMD Paragraph (I)(12) Engine 1 AD - N/A FAA #20	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-3B - INSPECTION OF THE AFT ACTUATOR HEAD HOSE FITTING. (SUPERSEDED BY FAA AD 2010-01-04) Notes (UPDATE NOTE: NA BY EFFECTIVITY) (ISSUING AUTHORITY: FAA).NA BY EFFECTIVITY	30-DEC-2009					
AD 2009-24-11 AMD Paragraph (I)(12) Engine 2 AD - N/A FAA #27	FAN BLADE AND AFT ACTUATOR HEAD HOSES CF34-3B - INSPECTION OF THE AFT ACTUATOR HEAD HOSE FITTING. (SUPERSEDED BY FAA AD 2010-01-04) Notes (UPDATE NOTE: NA BY EFFECTIVITY) (ISSUING AUTHORITY: FAA).NA BY EFFECTIVITY	30-DEC-2009					
AD 2009-24-18 Airframe AD - Complied With FAA #2831	ENGINE CONTROLS. Notes (UPDATE NOTE: IAW THE AD SB 604-76-004 PCW SEE LOG ENTRY DATED 12/18/08) (ISSUING AUTHORITY: FAA).IAW THE AD SB 604-76-004 PCW SEE LOG ENTRY DATED 12/18/08	18-JAN-2010 H: 3778.90 L: 1593					
AD 2009-26-09 Engine 1 AD - Open FAA #409	GENERAL ELECTRIC COMPANY - FAN DISKS Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 Engine 2 AD - Open FAA #464	GENERAL ELECTRIC COMPANY - FAN DISKS Notes (ISSUING AUTHORITY: FAA)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-26-09 AMD Paragraph (k) Engine 1 AD - Open FAA #793	GENERAL ELECTRIC COMPANY - FAN DISKS - FOR CF34-3A1, CF34-1A, CF34-3A, CF34-3A2 AND CF34-3B, INSPECTIONS OF TIER 1 FAN DISKS Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 AMD Paragraph (k) Engine 2 AD - Open FAA #745	GENERAL ELECTRIC COMPANY - FAN DISKS - FOR CF34-3A1, CF34-1A, CF34-3A, CF34-3A2 AND CF34-3B, INSPECTIONS OF TIER 1 FAN DISKS Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 AMD Paragraph (l) Engine 1 AD - Open FAA #847	GENERAL ELECTRIC COMPANY - FAN DISKS - FOR CF34-3A1, CF34-1A, CF34-3A, CF34-3A2 AND CF34-3B, INSPECTIONS OF TIER 2 FAN DISKS Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 AMD Paragraph (l) Engine 2 AD - Open FAA #448	GENERAL ELECTRIC COMPANY - FAN DISKS - FOR CF34-3A1, CF34-1A, CF34-3A, CF34-3A2 AND CF34-3B, INSPECTIONS OF TIER 2 FAN DISKS Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 AMD Paragraph (m) Engine 1 AD - Complied With FAA #79	GENERAL ELECTRIC COMPANY - FAN DISKS - FOR CF34-3A1, CF34-1A, CF34-3A, CF34-3A2 AND CF34-3B, INSPECTIONS OF TIER 3 FAN DISKS Notes (ISSUING AUTHORITY: FAA).BY COMPLIANCE WITH ASB 72-A0212 R4 ON 08/OCT/2009 . REF LUFTHANSA TECHNIK EASA FORM WO# 13609092 CERT# DE.145.0015.						
		18-AUG-2022					
		H: 7700.90					
		C: 3450					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2009-26-09 AMD Paragraph (m) Engine 2 AD - Complied With FAA #776	GENERAL ELECTRIC COMPANY - FAN DISKS - FOR CF34-3A1, CF34-1A, CF34-3A, CF34-3A2 AND CF34-3B, INSPECTIONS OF TIER 3 FAN DISKS Notes (ISSUING AUTHORITY: FAA).BY COMPLIANCE WITH ASB 72-A0212 R4 ON 08/OCT/2009 . REF LUFTHANSA TECHNIK EASA FORM WO# 13609092 CERT# DE.145.0015.	18-AUG-2022 H: 7700.90 C: 3450					
AD 2009-26-09 AMD Paragraph (o) Engine 1 AD - Open FAA #278	GENERAL ELECTRIC COMPANY - FAN DISKS - MANDATORY TERMINATING ACTION Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 AMD Paragraph (o) Engine 2 AD - Open FAA #683	GENERAL ELECTRIC COMPANY - FAN DISKS - MANDATORY TERMINATING ACTION Notes (ISSUING AUTHORITY: FAA)						
AD 2009-26-09 AMD Paragraph (f)(g) Engine 1 AD - Open FAA #680	GENERAL ELECTRIC COMPANY - FAN DISKS - REMOVING CERTAIN FAN DISKS FROM SERVICE Notes (ISSUING AUTHORITY: FAA)		C: 8000			C: 8000.00	C: 3997
AD 2009-26-09 AMD Paragraph (f)(g) Engine 2 AD - Open FAA #437	GENERAL ELECTRIC COMPANY - FAN DISKS - REMOVING CERTAIN FAN DISKS FROM SERVICE Notes (ISSUING AUTHORITY: FAA)		C: 8000			C: 8000.00	C: 3997



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-01-03 Airframe AD - N/A FAA #3439	FIRE FIGHTING ENTERPRISES LIMITED - FIRE PROTECTION	13-APR-2013					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2010-01-04 AMD Paragraph (i)(5) Engine 1 AD - N/A FAA #763	ACCOMPLISH FAN BLADE IF YOU FIND A CRACK IN THE RETAINING PIN HOLES OF THE FAN BLADE,REMOVE THE BLADE FROM SERVICE.	18-JAN-2010 H: 3778.90 C: 1593					
Notes (ISSUING AUTHORITY: FAA).BY SERIAL NUMBER							
AD 2010-01-04 AMD Paragraph (i)(5) Engine 2 AD - N/A FAA #944	ACCOMPLISH FAN BLADE IF YOU FIND A CRACK IN THE RETAINING PIN HOLES OF THE FAN BLADE,REMOVE THE BLADE FROM SERVICE.	18-JAN-2010 H: 3778.90 C: 1593					
Notes (ISSUING AUTHORITY: FAA).BY SERIAL NUMBER							
AD 2010-01-04 Engine 1 AD - Complied With FAA #893	GENERAL ELECTRIC COMPANY - FAN BLADE	12-APR-2013 H: 4782.30 C: 2063					
Notes (UPDATE NOTE: INSPECTED AFT ACTUATOR HEAD FITTING, NO FAULTS FOUND) (ISSUING AUTHORITY: FAA).INSPECTED AFT ACTUATOR HEAD FITTING, NO FAULTS FOUND							
AD 2010-01-04 Engine 2 AD - Complied With FAA #790	GENERAL ELECTRIC COMPANY - FAN BLADE	12-APR-2013 H: 4782.30 C: 2063					
Notes (UPDATE NOTE: INSPECTED AFT ACTUATOR HEAD FITTING, NO FAULTS FOUND) (ISSUING AUTHORITY: FAA).INSPECTED AFT ACTUATOR HEAD FITTING, NO FAULTS FOUND							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-01-04 AMD Paragraph (l)(1)(2) Engine 1 AD - N/A FAA #881	GENERAL ELECTRIC COMPANY - FAN BLADE - FOR CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1 - REMOVE FAN BLADES FROM SERVICE.	18-JAN-2010 H: 3778.90 C: 1593					
	Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABLE IF FAN BLADES P/N 6018T30P14 ARE INSTALLED).BY SERIAL NUMBER						
AD 2010-01-04 AMD Paragraph (l)(1)(2) Engine 2 AD - N/A FAA #630	GENERAL ELECTRIC COMPANY - FAN BLADE - FOR CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1 - REMOVE FAN BLADES FROM SERVICE.	18-JAN-2010 H: 3778.90 C: 1593					
	Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABLE IF FAN BLADES P/N 6018T30P14 ARE INSTALLED).BY SERIAL NUMBER						
AD 2010-01-04 AMD Paragraph (l)(3)(4)(6) Engine 1 AD - N/A FAA #54	GENERAL ELECTRIC COMPANY - FAN BLADE - FOR CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1, INITIAL / REPETITIVE EDDY CURRENT INSPECTION OF THE FAN BLADES	18-JAN-2010 H: 3778.90 C: 1593					
	Notes (ISSUING AUTHORITY: FAA).BY SERIAL NUMBER						
AD 2010-01-04 AMD Paragraph (l)(3)(4)(6) Engine 2 AD - N/A FAA #424	GENERAL ELECTRIC COMPANY - FAN BLADE - FOR CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1, INITIAL / REPETITIVE EDDY CURRENT INSPECTION OF THE FAN BLADES	18-JAN-2010 H: 3778.90 C: 1593					
	Notes (ISSUING AUTHORITY: FAA).BY SERIAL NUMBER						
AD 2010-01-04 AMD Paragraph (l)(8)(9)(10) Engine 1 AD - N/A FAA #446	GENERAL ELECTRIC COMPANY - FAN BLADE - FOR CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1, INITIAL / REPETITIVE VISUAL INSPECTION OF THE FAN BLADE ABRADABLE RUB STRIP FOR WEAR	18-JAN-2010 H: 3778.90 C: 1593					
	Notes (ISSUING AUTHORITY: FAA).BY SERIAL NUMBER						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-01-04 AMD Paragraph (l)(8)(9)(10) Engine 2 AD - N/A FAA #811	GENERAL ELECTRIC COMPANY - FAN BLADE - FOR CF34-1A, CF34-3A, CF34-3A2, CF34-3B AND CF34-3A1, INITIAL / REPETITIVE VISUAL INSPECTION OF THE FAN BLADE ABRADABLE RUB STRIP FOR WEAR Notes (ISSUING AUTHORITY: FAA).BY SERIAL NUMBER	18-JAN-2010 H: 3778.90 C: 1593					
AD 2010-01-04 AMD Paragraph (l)(12) Engine 1 AD - Complied With FAA #39	GENERAL ELECTRIC COMPANY - FAN BLADE- FOR CF34-3B, INSPECTION OF THE AFT ACTUATOR HEAD HOSE FITTING. Notes (ISSUING AUTHORITY: FAA)	12-APR-2013 H: 4782.30 C: 2063					
AD 2010-01-04 AMD Paragraph (l)(12) Engine 2 AD - Open FAA #316	GENERAL ELECTRIC COMPANY - FAN BLADE- FOR CF34-3B, INSPECTION OF THE AFT ACTUATOR HEAD HOSE FITTING. Notes (ISSUING AUTHORITY: FAA)	12-APR-2013 H: 4782.30 C: 2063					
AD 2010-02-06 Airframe AD - N/A FAA #3626	SICMA AERO SEAT 90XX AND 92XX SERIES PASSENGER SEATS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2010-04-16 Airframe AD - N/A FAA #887	SICLI - IDENTIFICATION & REMOVAL OF TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: WITHIN 90 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, REPLACE ALL TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI, HAVING P/N 1708337B4 AND HAVING ANY SERIAL NUMBER LISTED IN TABLE 1 OF THIS AD, WITH SERVICEABLE FIRE EXTINGUISHERS).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	13-APR-2013					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-07-02 Airframe AD - N/A FAA #2793	INTEGRATED NAVIGATION UNITS (INUS) - HONEYWELL PRIMUS II RNZ-850()/-851() (THIS AD SUPERSEDES AD 2006-22-05)	13-APR-2013					
	Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2010-09-04 Airframe AD - N/A FAA #3239	HONEYWELL INTERNATIONAL INC - PRIMUS EPIC AND PRIMUS APEX FLIGHT MANAGEMENT SYSTEMS (FMS) REVISION	13-APR-2013					
	Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2010-10-26 Airframe AD - Complied With FAA #914	LANDING GEAR	23-JUL-2010 H: 3912.80 L: 1666					
	Notes (ISSUING AUTHORITY: FAA).IAW THE AD NO ACTION REQUIRED NLG SELECTOR VLAVE P/N 750006000 S/N 0583 POST SB 750006000-1 NLG DOOR SELECTOR VLAVE P/N 601R75146-1 S/N 9357						
AD 2010-11-05 Airframe AD - N/A FAA #1801	AVOX SYSTEMS AND B/E AEROSPACE - TYPE 2HT OXYGEN CYLINDERS	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (AVG MAN HRS: 0.5) (APX COST: 42.5) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, INSPECT THE OXYGEN CYLINDER INSTALLED IN THE AIRPLANE TO DETERMINE THE SERIAL NUMBER AND REPLACE IF NEEDED).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2010-12-09 Airframe AD - N/A FAA #1687	HONEYWELL INTERNATIONAL INC.	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (ZONE: CUSTOM) (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-14-02 AMD PARA (F)(2) Airframe AD - N/A FAA #278	THE PART NUMBER OF THE INSTALLED ADG,INITIAL AND SUBSEQUENT REPEAT FLUORESCENT PENETRANT INSPECTIONS, RE-IDENTIFICATION (WHERE APPLICABLE) FOR AIRPLANES HAVING A STRUT AND GENERATOR HOUSING ASSEMBLY IDENTIFIED IN PARAGRAPH F(1)(II)(C)(1) OF THE AD, EXCEPT FOR AIRPLANES WITH SERIAL NUMBER 5611 THROUGH 5665 - DO A FLUORESCENT PENETRANT INSPECTION OF THE ADG STRUT, AND REPLACE THE ADG, AS APPLICABLE Notes .BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.	29-MAY-2018 H: 6371.80 L: 2714					
AD 2010-14-02 AMD Paragraph (f)(3) Airframe AD - N/A FAA #2632	CHECK THE PART NUMBER OF THE INSTALLED ADG,INITIAL AND SUBSEQUENT REPEAT FLUORESCENT PENETRANT INSPECTIONS, RE-IDENTIFICATION (WHERE APPLICABLE) ACCOMPLISHMENT OF THE FLUORESCENT PENETRANT INSPECTION BEFORE THE EFFECTIVE DATE OF THIS AD. Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.	29-MAY-2018 H: 6371.80 L: 2714					
AD 2010-14-02 Airframe AD - N/A FAA #23	ELECTRICAL POWER Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.	29-MAY-2018 H: 6371.80 L: 2714					
AD 2010-14-02 AMD Paragraph (f)(2)(4) Airframe AD - N/A FAA #2944	ELECTRICAL POWER - DO A FLUORESCENT PENETRANT INSPECTION Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.	29-MAY-2018 H: 6371.80 L: 2714					
AD 2010-14-02 AMD Paragraph (f)(5) Airframe AD - N/A FAA #1253	ELECTRICAL POWER - DO A GENERAL VISUAL INSPECTION OF THE ADG (IF UNSCHEDULED IN-FLIGHT ADG DEPLOYMENT OCCURS) Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.	29-MAY-2018 H: 6371.80 L: 2714					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-14-02 AMD Paragraph (f)(7) Airframe AD - N/A FAA #2104	ELECTRICAL POWER - DO A GENERAL VISUAL INSPECTION OF THE ADG STRUT FOR CRACKS (IF AN UNSCHEDULED ON-GROUND ADG DEPLOYMENT OCCURS)	29-MAY-2018 H: 6371.80 L: 2714					
	Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.						
AD 2010-14-02 AMD Paragraph (f)(1) Airframe AD - N/A FAA #3059	ELECTRICAL POWER - INSPECT TO DETERMINE THE PART NUMBER OF THE INSTALLED ADG.	29-MAY-2018 H: 6371.80 L: 2714					
	Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.						
AD 2010-14-02 AMD Paragraph (f)(6) Airframe AD - N/A FAA #2227	ELECTRICAL POWER - PERFORM A FLUORESCENT PENETRANT INSPECTION (IF AN UNSCHEDULED IN-FLIGHT DEPLOYMENT OCCURS)	29-MAY-2018 H: 6371.80 L: 2714					
	Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.						
AD 2010-14-02 AMD Paragraph (f)(8) Airframe AD - N/A FAA #72	ELECTRICAL POWER - RE-IDENTIFY THE ADG	29-MAY-2018 H: 6371.80 L: 2714					
	Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.						
AD 2010-14-05 Airframe AD - N/A FAA #3343	HYDRAULIC POWER (SUPERSEDED BY AD 2019-08-08)	22-JUL-2010 H: 3912.80 L: 1666					
	Notes (UPDATE NOTE: BY PART NUMBER NO ACTION REQUIRED NO EFFECTED P/N ACCUMULATORS INSTALLED) (ISSUING AUTHORITY: FAA).BY PART NUMBER NO ACTION REQUIRED NO EFFECTED P/N ACCUMULATORS INSTALLED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2010-20-03 Airframe AD - N/A FAA #1309	ELECTRICAL POWER	13-FEB-2017					
Notes (UPDATE NOTE: NA TO AC SERIAL NUMBER) (ISSUING AUTHORITY: FAA).NA TO AC SERIAL NUMBER							
AD 2011-01-09 Airframe AD - N/A FAA #1429	B/E AEROSPACE - OXYGEN - PBE UNITS HAVING PN 119003-11- INSPECTION / REPLACEMENT	13-JAN-2011 H: 4067.10 L: 1751					
Notes (AVG MAN HRS: 1) (APX COST: 85) (ISSUING AUTHORITY: FAA) (NOTE: (PBE) UNITS HAVING PART NUMBER (P/N) 119003-11 AND HAS A SERIAL NUMBER FROM 003-50730M TO 003-51329M INCLUSIVE).EQUIPMENT IS NOT INSTALLED							
AD 2011-04-09 Airframe AD - Superseded FAA #1722	CHEMICAL OXYGEN GENERATOR DEACTIVATION (SUPERSEDED BY FAA AD 2012-11-09)	04-NOV-2019					
Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2012-11-09) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2012-11-09							
AD 2011-07-05 Airframe AD - N/A FAA #2957	SICMA AERO SEATS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2011-09-09 Airframe AD - Complied With FAA #1569	ICE AND RAIN PROTECTION AND PNEUMATIC, RESPECTIVELY	12-APR-2013 H: 4782.30 L: 2063					
Notes (UPDATE NOTE: CW FUNCTION CHECK) (ISSUING AUTHORITY: FAA).CW FUNCTION CHECK							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2011-09-09 AMD Par. (h) Airframe AD - Complied With FAA #1451	ICE AND RAIN PROTECTION AND PNEUMATIC, RESPECTIVELY - INITIAL COMPLIANCE TIMES FOR AIRWORTHINESS LIMITATIONS TASKS.	12-APR-2013 H: 4782.30 L: 2063					
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION IAW SB 604-28-022) (ISSUING AUTHORITY: FAA).CW FUNCTION CHECK						
AD 2011-09-09 AMD Par. (g) Airframe AD - Complied With FAA #11	ICE AND RAIN PROTECTION AND PNEUMATIC, RESPECTIVELY - REVISE THE AIRWORTHINESS LIMITATIONS SECTION OF THE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS	21-SEP-2011 H: 4323.90 L: 1859					
	Notes (ISSUING AUTHORITY: FAA).IAW THE AD, 30-11-00-101 & 36-21-101 DUE @ 6400 ACTH OR NEXT SHEDULED ACCOMPLISHMENT OF TASK 57-10-10-208 DUE 06/2013						
AD 2011-11-04 Airframe AD - N/A FAA #3653	L'HOTELLIER PORTABLE HALON 1211 FIRE EXTINGUISHERS	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2011-12-01 Airframe AD - N/A FAA #954	EQUIPMENT/FURNISHINGS - PASSENGER SEAT - REPLACEMENT	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2011-14-08 Airframe AD - N/A FAA #1227	B/E AEROSPACE, CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY	13-APR-2013					
	Notes (AVG MAN HRS: 0.5) (APX COST: 48.5) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2011-21-05 Airframe AD - N/A FAA #2202	EQUIPMENT/FURNISHINGS	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2011-21-08 Airframe AD - N/A FAA #3495	SICMA AERO SEAT - EQUIPMENT/FURNISHINGS - PASSENGER SEAT ASSEMBLIES	13-APR-2013					
Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2011-23-06 Airframe AD - Superseded FAA #979	EQUIPMENT/FURNISHING - TO DETECT CRACKS IN THE CENTRAL AND LATERAL SPREADERS ON PASSENGER SEATS. (SUPERSEDED BY FAA AD 2012-08-07)	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: SUPERSEDED BY AD 2012-08-07) (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2012-08-07							
AD 2011-25-01 Airframe AD - N/A FAA #1004	TO INSTALL PLACARDS TO AID IN LOCATING AND DEPLOYING LIFE RAFTS TO PREVENT FURTHER INJURY OR LOSS OF LIFE IN THE EVENT OF A HELICOPTER LANDING IN THE WATER	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2012-02-08 Airframe AD - N/A FAA #487	AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS - NAVIGATION	13-APR-2013					
Notes (AVG MAN HRS: 2) (APX COST: 3,040) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-04-12 Airframe AD - Complied With FAA #2081	ELECTRICAL POWER - REPLACE THE ADG POWER FEEDER CABLE Notes (UPDATE NOTE: COMPLIED WITH SB 604-24-024) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB 604-24-024	12-APR-2013 H: 4782.30 L: 2063					
AD 2012-06-25 Airframe AD - N/A FAA #1093	EMERGENCY EQUIPMENT Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2012-08-07 Airframe AD - N/A FAA #1646	EQUIPMENT/FURNISHINGS - TO DETECT CRACKS IN THE CENTRAL AND LATERAL SPREADERS ON PASSENGER SEATS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	13-APR-2013					
AD 2012-08-10 Airframe AD - N/A FAA #1748	ELECTRICAL POWER - REMOVE THE ADG GCU, BOMBARDIER PART NUMBER (P/N) 604-90800-7 (HAMILTON SUNDSTRAND P/N 761341A), AND INSTALL A NEW OR SERVICEABLE ADG GCU BOMBARDIER P/N 604-90800-27 (HAMILTON SUNDSTRAND P/N 761341B) Notes (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED AT THIS TIME.	29-MAY-2018 H: 6371.80 L: 2714					
AD 2012-08-15 Airframe AD - N/A FAA #1829	ELECTRICAL POWER Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER	04-NOV-2019 H: 6485.50 L: 2778					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-08-15 AMD Par. (h) Airframe AD - N/A FAA #958	ELECTRICAL POWER - INSPECTIONS AND CORRECTIVE ACTIONS	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER						
AD 2012-08-15 AMD Par. (g) Airframe AD - N/A FAA #199	ELECTRICAL POWER - INSPECTIONS, BUS BAR ACTIONS, AND CORRECTIVE ACTIONS	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER						
AD 2012-11-09 Airframe AD - N/A FAA #2484	CHEMICAL OXYGEN GENERATOR INSTALLATION	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (AVG MAN HRS: 26) (APX COST: 8,210) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2012-11-09 R1 Airframe AD - N/A FAA #1498	CHEMICAL OXYGEN GENERATOR INSTALLATION	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2012-14-15 Airframe AD - N/A FAA #2948	HONEYWELL INTERNATIONAL, INC. - GLOBAL NAVIGATION SATELLITE SENSOR UNITS	13-APR-2013					
	Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2012-17-01 Airframe AD - N/A FAA #699	GOODYEAR - LANDING GEAR Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	13-APR-2013					
AD 2012-21-11 Airframe AD - N/A FAA #1104	DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON THE OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRAS), AND AN ELECTRICAL WIRING HARNESS IN THE AREA OF THE OXYGEN CYLINDER WITH NO PROTECTIVE CONDUIT SLEEVING Notes (UPDATE NOTE: AD NA TO AIRCRAFT SERIAL NUMBER) (ISSUING AUTHORITY: FAA).AD NA TO AIRCRAFT SERIAL NUMBER	04-NOV-2019 H: 6485.50 L: 2778					
AD 2012-26-15 R1 Airframe AD - N/A FAA #1487	HONEYWELL INTERNATIONAL INC. - AIR DATA PRESSURE TRANSDUCERS (THIS ACTION RESCINDS AD 2012-26-15, AMENDMENT 39-17310 (78 FR 1735, JANUARY 9, 2013).) Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	13-APR-2013					
AD 2013-03-08 Airframe AD - Complied With FAA #2177	PERIODIC INSPECTIONS Notes (UPDATE NOTE: VERIFIED MAINTENANCE MANUAL REVISION) (ISSUING AUTHORITY: FAA).VERIFIED MAINTENANCE MANUAL REVISION	14-MAY-2018					
AD 2013-03-08 AMD Par. (h) Airframe AD - Complied With FAA #933	PERIODIC INSPECTIONS - INITIAL COMPLIANCE TIMES FOR INSPECTIONS Notes (UPDATE NOTE: VERIFIED MAINTENANCE MANUAL REVISION) (ISSUING AUTHORITY: FAA).VERIFIED MAINTENANCE MANUAL REVISION	14-MAY-2018					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2013-03-08 AMD Par. (g) Airframe AD - Complied With FAA #3480	PERIODIC INSPECTIONS - TIME LIMITS/MAINTENANCE CHECKS (TLMC) MANUAL REVISION Notes (UPDATE NOTE: VERIFIED MAINTENANCE MANUAL REVISION) (ISSUING AUTHORITY: FAA).VERIFIED MAINTENANCE MANUAL REVISION	14-MAY-2018					
AD 2013-05-06 Airframe AD - Complied With FAA #1175	MODIFICATION OF THE LEFT-HAND ENGINE THRUST CONTROL MECHANISM Notes (UPDATE NOTE: REF BOMBARDIER FORM ONE,FORM TRACKING # 890100993057-1,DATED 09/JUL/2011 FOR KIT 605K71-002,INFORMATION COMPLIED WITH AD 2013-05-06 PER BOMBARDIER SB 604-71-005.NO FURTHER ACTION REQUIRED) (ISSUING AUTHORITY: FAA).REF BOMBARDIER FORM ONE,FORM TRACKING # 890100993057-1,DATED 09/JUL/2011 FOR KIT 605K71-002,INFORMATION COMPLIED WITH AD 2013-05-06 PER BOMBARDIER SB 604-71-005.NO FURTHER ACTION REQUIRED	09-MAR-2016 H: 5692.70 L: 2472					
AD 2013-18-09 Airframe AD - Superseded FAA #1136	HONEYWELL ASCA INC - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES (SUPERSEDED BY FAA AD 2014-17-02) Notes (UPDATE NOTE: SUPERSEDED BY AD 2014-07-02) (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2014-07-02	22-OCT-2018					
AD 2013-22-05 Airframe AD - Complied With FAA #661	NAVIGATION - AIRSPEED MISMATCH BETWEEN THE PILOT AND CO-PILOT'S AIRSPEED INDICATORS Notes (AVG MAN HRS: 5) (APX COST: 3,364) (UPDATE NOTE: CW SB 604-34-065 R2) (ISSUING AUTHORITY: FAA).CW SB 604-34-065 R2	27-NOV-2015					
AD 2013-22-05 AMD Par. (h) Airframe AD - Complied With FAA #2809	NAVIGATION - AIRSPEED MISMATCH BETWEEN THE PILOT AND CO-PILOT'S AIRSPEED INDICATORS - REPLACEMENT FOR CERTAIN MODEL CL-600-2B16 (CL-604 VARIANT) AIRPLANES Notes (UPDATE NOTE: CW SB 604-34-065 R2) (ISSUING AUTHORITY: FAA).CW SB 604-34-065 R2	27-NOV-2015					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-03-17 Airframe AD - Complied With FAA #674	WINGS - FRACTURED FASTENER HEADS FOUND ON THE INBOARD FLAP HINGE-BOX FORWARD FITTING AT WING STATION (WS) 76.50 Notes (UPDATE NOTE: I.A.W ASB A604-57-006 REV1 PART (A) ALL FASTENERS INSTALLED CORRECTLY AS SHOWN IN FIGURE 1 NO FURTHER ACTION IS REQUIRED I.A.W PART (C)) (ISSUING AUTHORITY: FAA).I.A.W ASB A604-57-006 REV1 PART (A) ALL FASTENERS INSTALLED CORRECTLY AS SHOWN IN FIGURE 1 NO FURTHER ACTION IS REQUIRED I.A.W PART (C)	13-MAR-2014 H: 5080.70 L: 2203					
AD 2014-03-17 AMD Paragraph (g) Airframe AD - Complied With FAA #453	WINGS - FRACTURED FASTENER HEADS FOUND ON THE INBOARD FLAP HINGE-BOX FORWARD FITTING AT WING STATION (WS) 76.50 - DO A DETAILED VISUAL INSPECTION FOR INCORRECT ORIENTATION AND ANY FRACTURING (MISSING FASTENER HEADS) OF EACH INBOARD FLAP FASTENER OF THE HINGE-BOX FORWARD FITTING AT WS 76.50 AND WS 127.25, ON BOTH WINGS Notes (UPDATE NOTE: I.A.W ASB A604-57-006 REV1 PART (A) ALL FASTENERS INSTALLED CORRECTLY AS SHOWN IN FIGURE 1 NO FURTHER ACTION IS REQUIRED I.A.W PART (C)) (ISSUING AUTHORITY: FAA).I.A.W ASB A604-57-006 REV1 PART (A) ALL FASTENERS INSTALLED CORRECTLY AS SHOWN IN FIGURE 1 NO FURTHER ACTION IS REQUIRED I.A.W PART (C)	13-MAR-2014 H: 5080.70 L: 2203					
AD 2014-05-27 Airframe AD - N/A FAA #3242	ROCKWELL COLLINS, INC - NAVIGATION - TPR-720 AND TPR-900 MODE S TRANSPONDERS TEST AND CALIBRATION Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2014-15-13 AMD Paragraph (I)(1)(II) Airframe AD - Recurring FAA #2729	ADD SERIAL NUMBERS AND PART NUMBERS TO NLG CROSSBEAM PINS HAVING P/N 200814601 AND NLG CENTER HINGE PINS HAVING P/N 200814624 Notes (UPDATE NOTE: COMPLIED WITH AD 2014-15-13 PAR. (I)(II), ADD SERIAL NUMBERS AND PART NUMBERS TO LANDING GEAR COMPONENTS, BY VERIFYING PREVIOUS COMPLIANCE WITH BOMBARDIER SERVICE BULLETIN SB 604-32-014 REVISION 2 ON 12-APR-2013 BY DUNCAN AVIATION UNDER WORK ORDER #QYSVC AND PART NUMBERS AND SERIAL NUMBERS ARE BEING TRACKED ACCORDINGLY. NO FURTHER ACTION NECESSARY.).COMPLIED WITH AD 2014-15-13 PAR. (I)(II), ADD SERIAL NUMBERS AND PART NUMBERS TO LANDING GEAR COMPONENTS, BY VERIFYING PREVIOUS COMPLIANCE WITH BOMBARDIER SERVICE BULLETIN SB 604-32-014 REVISION 2 ON 12-APR-2013 BY DUNCAN AVIATION UNDER WORK ORDER #QYSVC AND PART NUMBERS AND SERIAL NUMBERS ARE BEING TRACKED ACCORDINGLY. NO FURTHER A	25-AUG-2022 H: 7715.60 L: 3455	M: 96			25-AUG-2030	M: 50 D: 24

N530BD





Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-15-13 AMD Par. (i) Airframe AD - Complied With FAA #586	LANDING GEAR - ALS REVISION	25-AUG-2022 H: 7715.60 L: 3455					
	Notes (UPDATE NOTE: COMPLIED WITH AD 2014-15-13 PAR. (I), ADD SERIAL NUMBERS AND PART NUMBERS TO LANDING GEAR COMPONENTS/ALS REVISION, BY VERIFYING PREVIOUS COMPLIANCE WITH BOMBARDIER SERVICE BULLETIN SB 604-32-014 REVISION 2 ON 12-APR-2013 BY DUNCAN AVIATION UNDER WORK ORDER #QYSVC AND BY VERIFYING TLMC HAS BEEN UPDATED WITH REQUIRED ALS REVISIONS AND COMPONENT LIFE LIMITS ARE BEING TRACKED ACCORDINGLY.. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).COMPLIED WITH AD 2014-15-13 PAR. (I), ADD SERIAL NUMBERS AND PART NUMBERS TO LANDING GEAR COMPONENTS/ALS REVISION, BY VERIFYING PREVIOUS COMPLIANCE WITH BOMBARDIER SERVICE BULLETIN SB 604-32-014 REVISION 2 ON 12-APR-2013 BY DUNCAN AVIATION UN						
AD 2014-15-13 AMD Paragraph (n) Airframe AD - Complied With FAA #703	RECORD ANY NEWLY CALCULATED CSN, NEW PART NUMBERS, AND NEW SERIAL NUMBERS IN THE AIRPLANE TECHNICAL RECORDS AND MANUALS (CONCURRENTLY WITH THE ACTIONS SPECIFIED IN PARAGRAPHS (L) AND (M) OF THIS AD)	25-AUG-2022 H: 7715.60 L: 3455					
	Notes (UPDATE NOTE: COMPLIED WITH AD 2014-15-13 PAR. (I)(1), ADD SERIAL NUMBERS AND PART NUMBERS TO LANDING GEAR COMPONENTS, BY VERIFYING PREVIOUS COMPLIANCE WITH BOMBARDIER SERVICE BULLETIN SB 604-32-014 REVISION 2 ON 12-APR-2013 BY DUNCAN AVIATION UNDER WORK ORDER #QYSVC AND ALL AFFECTED PART NUMBERS AND SERIAL NUMBERS ARE BEING TRACKED ACCORDINGLY. NO FURTHER ACTION NECESSARY.).COMPLIED WITH AD 2014-15-13 PAR. (I)(1), ADD SERIAL NUMBERS AND PART NUMBERS TO LANDING GEAR COMPONENTS, BY VERIFYING PREVIOUS COMPLIANCE WITH BOMBARDIER SERVICE BULLETIN SB 604-32-014 REVISION 2 ON 12-APR-2013 BY DUNCAN AVIATION UNDER WORK ORDER #QYSVC AND ALL AFFECTED PART NUMBERS AND SERIAL NUMBERS ARE BEING TRACKED A						
AD 2014-15-17 Airframe AD - Complied With FAA #2844	POTENTIAL FOR FUEL LEAKAGE FROM AUXILIARY POWER UNIT (APU) BOOST PUMP COMPONENT INSTALLATIONS IN THE RIGHT-HAND LANDING LIGHTS COMPARTMENT - AIRPLANE FLIGHT MANUAL (AFM) REVISION	01-AUG-2014 H: 5238.50 L: 2265					
	Notes (ISSUING AUTHORITY: FAA).PARA.(G) BY INSERTING TR 604/38 INTO THE AFM. NO FURTHER ACTION REQUIRED						
AD 2014-16-06 Airframe AD - Complied With FAA #3296	AUTOPILOT SYSTEM AND RUDDER ACTUATOR - AIRPLANE FLIGHT MANUAL (AFM) REVISION	21-OCT-2014 H: 5310.00 L: 2295					
	Notes VERIFIED THAT REVISION 89 HAS BEEN INCORPORATED IN THE AFM. NO FURTHER ACTION REQUIRED.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-17-02 Airframe AD - N/A FAA #2085	COMMUNICATIONS - ELT MODEL RESCU 406AF AND 406AFN (THIS AD REPLACES AD 2013-18-09) Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA).N/A, AFFECTED EQUIPMENT NOT INSTALLED	23-MAR-2017 H: 5979.10 L: 2576					
AD 2014-17-51 AMD Paragraph (g) Airframe AD - N/A FAA #2716	WING - AIRPLANES NOT PREVIOUSLY INSPECTED - DO A DETAILED VISUAL INSPECTION OF EACH INBOARD FLAP FASTENER OF THE HINGE-BOX FORWARD FITTING AT WS 76.50 AND WS 127.25, ON BOTH WINGS, TO DETERMINE IF THE FASTENERS ARE CORRECTLY ORIENTED AND INTACT. Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2016-08-15.						
AD 2014-17-51 AMD Paragraph (h) Airframe AD - N/A FAA #925	WINGS - AIRPLANES PREVIOUSLY INSPECTED, WITH INCORRECTLY ORIENTED FASTENER(S) - DO A DETAILED VISUAL INSPECTION OF ALL INBOARD FLAP FASTENERS OF THE HINGE-BOX FORWARD FITTING AT WS 76.50 AND WS 127.25, ON BOTH WINGS, TO DETERMINE IF THE FASTENERS ARE INTACT. Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2016-08-15.						
AD 2014-17-51 AMD Paragraph (g) Airframe AD - Complied With FAA #373	WINGS - FRACTURED FASTENER HEADS - AIRPLANES NOT PREVIOUSLY INSPECTED Notes (ISSUING AUTHORITY: FAA).A02014-17-51 P.C.W IN ACCORDANCE WITH A02014-03-17, CFW 3/13/2014 PER PARA (G)(3)(H) ALL FASTENERS PREVIOUSLY FOUND CORRECTLY ORIENTED AND INTACT.(EMERGENCY)	20-AUG-2014 H: 5242.80 L: 2267					
AD 2014-17-51 Airframe AD - N/A FAA #1862	WINGS - FRACTURED FASTENER HEADS ON THE INBOARD FLAP HINGE-BOX FORWARD FITTING AT WING STATION (WS) 76.50 DUE TO INCORRECT INSTALLATION. Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2016-08-15.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2014-17-51 Airframe AD - Complied With FAA #3392	WINGS - FRACTURED FASTENER HEADS ON THE INBOARD FLAP HINGE-BOX FORWARD FITTING AT WING STATION (WS) 76.50 DUE TO INCORRECT INSTALLATION. Notes (ISSUING AUTHORITY: FAA).A02014-17-51 P.C.W IN ACCORDANCE WITH A02014-03-17, CFW 3/13/2014 PER PARA (G)(3)(H) ALL FASTENERS PREVIOUSLY FOUND CORRECTLY ORIENTED AND INTACT.	20-AUG-2014 H: 5242.80 L: 2267					
AD 2014-17-51 AMD Paragraph (h) Airframe AD - Complied With FAA #2236	WINGS -FRACTURED FASTENER HEADS - AIRPLANES PREVIOUSLY INSPECTED, WITH INCORRECTLY ORIENTED FASTENER(S) Notes (ISSUING AUTHORITY: FAA).A02014-17-51 P.C.W IN ACCORDANCE WITH A02014-03-17, CFW 3/13/2014 PER PARA (G)(3)(H) ALL FASTENERS PREVIOUSLY FOUND CORRECTLY ORIENTED AND INTACT.(EMERGENCY)	20-AUG-2014 H: 5242.80 L: 2267					
AD 2014-18-01 Airframe AD - N/A FAA #2201	ROCKWELL COLLINS, INC. - NAVIGATION - INSPECT THE AIRPLANE TYPE CODE CATEGORY STRAPPING SETTING FOR A VALUE OF ZERO (0) OR ONE (1) FOLLOWING ROCKWELL COLLINS, INC. SERVICE INFORMATION LETTER 07-2, 523-0810069-101000, TDR-94() SIL 07-02. Notes (AVG MAN HRS: 4) (APX COST: 85) (ISSUING AUTHORITY: FAA).DUE TO EXCEPTED AIRPLANE MODEL PER TRANSPONDERS INSTALLED AND INCORPORATED PER SB 604-34-054. NO FURTHER ACTION REQUIRED.	21-OCT-2014 H: 5310.00 L: 2295					
AD 2014-20-01 Airframe AD - N/A FAA #1159	FUEL LEAKS Notes (ISSUING AUTHORITY: FAA).PER AIRCRAFT SERIAL NUMBER. NO FURTHER ACTION REQUIRED	21-OCT-2014 H: 5310.00 L: 2295					
AD 2014-20-11 Airframe AD - N/A FAA #3663	ZODIAC SEATS FRANCE - EQUIPMENT/FURNISHINGS - SEATS Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-02-06 AMD PARA (H)(2) Airframe AD - N/A FAA #376	ACCOMPLISH THE ACTIONS SPECIFIED IN THE MAINTENANCE OR INSPECTION PROGRAM Notes .SUPERSEDED BY AD 2015-05-07						
AD 2015-02-06 Airframe AD - N/A FAA #2748	FLIGHT CONTROLS - DETECT AND CORRECT LOOSE SPUR GEAR BOLTS ON THE HSTA (THIS AD HAS BEEN SUPERSEDED BY AD 2015-05-07) Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2015-05-07						
AD 2015-02-06 AMD Paragraph (g) Airframe AD - N/A FAA #3070	FLIGHT CONTROLS - DETECT AND CORRECT LOOSE SPUR GEAR BOLTS ON THE HSTA - AIRPLANE FLIGHT MANUAL (AFM) REVISION Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2015-05-07						
AD 2015-02-06 AMD Paragraph (j) Airframe AD - N/A FAA #1272	FLIGHT CONTROLS - DETECT AND CORRECT LOOSE SPUR GEAR BOLTS ON THE HSTA - HSTA REPLACEMENT Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2015-05-07						
AD 2015-02-06 AMD Paragraph (h) Airframe AD - N/A FAA #3138	FLIGHT CONTROLS - DETECT AND CORRECT LOOSE SPUR GEAR BOLTS ON THE HSTA - MAINTENANCE OR INSPECTION PROGRAM REVISION Notes (ISSUING AUTHORITY: FAA).SUPERSEDED BY AD 2015-05-07						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-02-23 Airframe AD - Superseded FAA #3164	WINGS (SUPERSEDED BY FAA AD 2016-21-06) Notes (UPDATE NOTE: AD SUPERSEDED BY AD 2016-21-06) (ISSUING AUTHORITY: FAA).AD SUPERSEDED BY AD 2016-21-06	04-NOV-2019					
AD 2015-05-07 AMD PARA (H)(2) Airframe AD - Complied With FAA #1311	ACCOMPLISH THE ACTIONS SPECIFIED IN THE MAINTENANCE OR INSPECTION PROGRAM Notes (UPDATE NOTE: COMPLIED WITH SB 604-27-032 R2).COMPLIED WITH SB 604-27-032 R2	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-05-07 AMD Par. (g) Airframe AD - Complied With FAA #717	FLIGHT CONTROLS - RETAINED AIRPLANE FLIGHT MANUAL (AFM) REVISION, WITH NO CHANGES Notes (ISSUING AUTHORITY: FAA).PARA(G) CONFIRMING T/R 604/37 HAS BEEN INSERTED.	18-MAR-2015 H: 5435.90 L: 2357					
AD 2015-05-07 Airframe AD - Complied With FAA #1497	FLIGHT CONTROLS - DETECT AND CORRECT LOOSE SPUR GEAR BOLTS ON THE HSTA (THIS AD SUPERSEDES AD 2015-02-06) Notes (UPDATE NOTE: COMPLIED WITH SB 604-27-032 R2) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB 604-27-032 R2	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-05-07 AMD Par. (j) Airframe AD - Complied With FAA #3101	RETAINED HSTA REPLACEMENT, WITH CORRECTED VENDOR PART NUMBER Notes (UPDATE NOTE: COMPLIED WITH SB 604-27-032 R2) (ISSUING AUTHORITY: FAA).COMPLIED WITH SB 604-27-032 R2	23-MAR-2017 H: 5979.10 L: 2576					



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-05-07 AMD Par. (h) Airframe AD - Complied With FAA #989	RETAINED MAINTENANCE OR INSPECTION PROGRAM REVISION, WITH NO CHANGES Notes (ISSUING AUTHORITY: FAA).PARA (H) BY CONFIRM TASK 27-41-00-101 "OPERATIONAL TEST(BITE) OF HSTC SYSTEM HAS BEEN IMPLEMENTED IN THR TMLC,	18-MAR-2015 H: 5435.90 L: 2357					
AD 2015-07-02 Airframe AD - Complied With FAA #127	WINGS Notes (UPDATE NOTE: CW SB 604-27-32 R2) (ISSUING AUTHORITY: FAA).CW SB 604-27-32 R2	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-07-02 AMD Paragraph (i) Airframe AD - Complied With FAA #821	WINGS - CORRECTIVE ACTIONS Notes (ISSUING AUTHORITY: FAA).PARA I(1)	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-07-02 AMD Paragraph (k) Airframe AD - N/A FAA #746	WINGS - CREDIT FOR PREVIOUS ACTIONS Notes (UPDATE NOTE: CW SB 604-57-007 R1) (ISSUING AUTHORITY: FAA).CW SB 604-57-007 R1	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-07-02 AMD Paragraph (h)(Outb) Airframe AD - Complied With FAA #2727	WINGS - LUG EDGE MEASUREMENT AND INSPECTION Notes (UPDATE NOTE: CW SB 604-57-007 R1) (ISSUING AUTHORITY: FAA).CW SB 604-57-007 R1	23-MAR-2017 H: 5979.10 L: 2576					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-07-02 AMD Paragraph (h)(Inbd) Airframe AD - Complied With FAA #3644	WINGS - LUG EDGE MEASUREMENT AND INSPECTION Notes (UPDATE NOTE: CW SB 604-57-007 R1) (ISSUING AUTHORITY: FAA).CW SB 604-57-007 R1	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-07-02 AMD Paragraph (g) Airframe AD - Complied With FAA #2212	WINGS - MAINTENANCE OR INSPECTION PROGRAM REVISION Notes (UPDATE NOTE: BY INCORPORATION OF REVISION 20 DATED JULY, 2013 INTO THE MAINTENANCE / INSPECTION PROGRAM. INITIAL COMPLIANCE DUE AT 7800 TOTAL FLIGHT CYCLES) (ISSUING AUTHORITY: FAA).BY INCORPORATION OF REVISION 20 DATED JULY, 2013 INTO THE MAINTENANCE / INSPECTION PROGRAM. INITIAL COMPLIANCE DUE AT 7800 TOTAL FLIGHT CYCLES	16-JUN-2015 H: 5513.80 L: 2387					
AD 2015-07-02 AMD Paragraph (l) Airframe AD - N/A FAA #1752	WINGS - OTHER FAA AD PROVISIONS Notes (UPDATE NOTE: CW SB 604-57-007 R1) (ISSUING AUTHORITY: FAA).CW SB 604-57-007 R1	23-MAR-2017 H: 5979.10 L: 2576					
AD 2015-08-07 Airframe AD - N/A FAA #1980	ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) - OXYGEN - FLIGHTCREW OXYGEN MASK REGULATORS Notes (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED	21-MAY-2018					
AD 2015-10-02 Airframe AD - N/A FAA #1629	ZODIAC SEATS FRANCE PASSENGER SEAT ASSEMBLIES (THIS AD REPLACES AD 2014-20-11) Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)	23-MAR-2017 H: 5979.10 L: 2576					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-10-51 Airframe AD - N/A FAA #2447	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD) - NAVIGATION - INCORPORATE OPERATIONAL LIMITATIONS INTO AIRPLANE FLIGHT MANUAL (AFM) OR AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) LIMITATION.	23-MAR-2017 H: 5979.10 L: 2576					
	Notes (ISSUING AUTHORITY: FAA).AD IS NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.						
AD 2015-15-14 Airframe AD - N/A FAA #2466	FIRE EXTINGUISHERS - FRANGIBLE PLUGS - INSPECTION	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2015-16-04 Airframe AD - N/A FAA #750	FIRE PROTECTION	23-MAR-2017 H: 5979.10 L: 2576					
	Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME						
AD 2015-23-09 AMD Para (h)(2)(ii) Airframe AD - N/A FAA #216	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	14-JAN-2016 H: 5673.20 L: 2461					
	Notes (ISSUING AUTHORITY: FAA).BY PART NUMBER						
AD 2015-23-09 AMD Para (g) Airframe AD - N/A FAA #75	OXYGEN - INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	14-JAN-2016 H: 5673.20 L: 2461					
	Notes (ISSUING AUTHORITY: FAA).PILOT PN MC10-13-03 SN 10433 COPILOT PN MC10-13-03 SN 84703						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2015-23-09 AMD Para (i) Airframe AD - N/A FAA #3529	OXYGEN - REGULATOR REPLACEMENT Notes (ISSUING AUTHORITY: FAA).BY PART NUMBER	14-JAN-2016 H: 5673.20 L: 2461					
AD 2015-23-09 Airframe AD - N/A FAA #438	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS Notes (ISSUING AUTHORITY: FAA).PILOT PN MC10-13-03 SN 10433 COPILOT PN MC10-13-03 SN 84703. NO FURTHER ACTION REQUIRED	14-JAN-2016 H: 5673.20 L: 2461					
AD 2015-23-09 AMD Para (h)(1) Airframe AD - N/A FAA #1095	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II). Notes (ISSUING AUTHORITY: FAA).BY PART NUMBER	14-JAN-2016 H: 5673.20 L: 2461					
AD 2015-23-09 AMD Para (h)(2)(i) Airframe AD - N/A FAA #2584	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1 Notes (ISSUING AUTHORITY: FAA).BY PART NUMBER	14-JAN-2016 H: 5673.20 L: 2461					
AD 2015-25-05 Airframe AD - Complied With FAA #1699	DETECT AND CORRECT BROKEN SUPPORT BRACKETS OF THE HYDRAULIC LINES - PERFORM A ONE TIME DETAILED INSPECTION OF THE IDG POWER CABLES Notes (UPDATE NOTE: COMPLIED WITH INSPECTION, NO DAMAGE NOTED) (ISSUING AUTHORITY: FAA).COMPLIED WITH INSPECTION, NO DAMAGE NOTED	14-JAN-2016 H: 5673.20 L: 2461					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-08-15 AMD Paragraph (h) Airframe AD - Complied With FAA #1188	ACCOMPLISH A DETAILED VISUAL INSPECTION OF ALL INBOARD FLAP FASTENERS OF THE HINGE-BOX FORWARD FITTING AT WS 76.50 AND WS 127.25, ON BOTH WINGS, TO DETERMINE IF THE FASTENERS ARE INTACT (NON-FRACTURED, WITH INTACT FASTENER HEAD) AND REPEAT (IF ALL FASTENERS ARE FOUND INTACT)	05-JUL-2016 H: 5782.40 L: 2503					
	Notes .P/C/W PER AD 2014-03-17, AD 2014-17-51 AND SB A604-57-006 R1 PARTS A & C, ALL FASTNERS WERE FOUND PROPERLY ORIENTED AND INTACT.						
AD 2016-08-15 AMD Paragraph (h)(2) Airframe AD - Complied With FAA #2275	REMOVE AND REPLACE ALL FORWARD AND AFT FASTENERS AT WS 76.50 AND WS 127.25, REGARDLESS OF CONDITION OR ORIENTATION, ON BOTH WINGS (IF ANY FASTENER IS FOUND FRACTURED)	05-JUL-2016 H: 5782.40 L: 2503					
	Notes .P/C/W PER AD 2014-03-17, AD 2014-17-51 AND SB A604-57-006 R1 PARTS A & C, ALL FASTNERS WERE FOUND PROPERLY ORIENTED AND INTACT.						
AD 2016-08-15 AMD Paragraph (g)(2) Airframe AD - Complied With FAA #3060	REMOVE AND REPLACE ALL FORWARD AND AFT FASTENERS AT WS 76.50 AND WS 127.25, REGARDLESS OF CONDITION OR ORIENTATION, ON BOTH WINGS, IF ANY FASTENER IS FOUND FRACTURED	05-JUL-2016 H: 5782.40 L: 2503					
	Notes .P/C/W PER AD 2014-03-17, AD 2014-17-51 AND SB A604-57-006 R1 PARTS A & C, ALL FASTNERS WERE FOUND PROPERLY ORIENTED AND INTACT.						
AD 2016-08-15 Airframe AD - Complied With FAA #2001	WINGS	05-JUL-2016 H: 5782.40 L: 2503					
	Notes (ISSUING AUTHORITY: FAA).P/C/W PER AD 2014-03-17, AD 2014-17-51 AND SB A604-57-006 R1 PARTS A & C, ALL FASTNERS WERE FOUND PROPERLY ORIENTED AND INTACT.						
AD 2016-08-15 AMD Paragraph (g),(h) Airframe AD - Complied With FAA #1796	WINGS - DETAILED VISUAL INSPECTION (RETAINED INSPECTION)	05-JUL-2016 H: 5782.40 L: 2503					
	Notes (ISSUING AUTHORITY: FAA).P/C/W PER AD 2014-03-17, AD 2014-17-51 AND SB A604-57-006 R1 PARTS A & C, ALL FASTNERS WERE FOUND PROPERLY ORIENTED AND INTACT.						



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-08-15 AMD Paragraph (k) Airframe AD - N/A FAA #3009	WINGS - POST-INSPECTION FASTENER REPLACEMENT Notes (ISSUING AUTHORITY: FAA).DUE TO NO INCORRECTLY ORIENTED FASTENERS WERE PREVIOUSLY FOUND WHEN COMPLYING WITH PARAGRAPHS (G) & (H).NO FURTHER ACTION REQUIRED,	05-JUL-2016 H: 5782.40 L: 2503					
AD 2016-08-15 AMD Paragraph (i) Airframe AD - Complied With FAA #1647	WINGS - POST-INSPECTION FASTENER REPLACEMENT (TERMINATING ACTION) Notes (ISSUING AUTHORITY: FAA).P/C/W PER AD 2014-03-17, AD 2014-17-51 AND SB A604-57-006 R1 PARTS A & C, ALL FASTNERS WERE FOUND PROPERLY ORIENTED AND INTACT.	05-JUL-2016 H: 5782.40 L: 2503					
AD 2016-10-10 Airframe AD - N/A FAA #1209	FUEL Notes (ISSUING AUTHORITY: FAA).PER AIRCRAFT SERIAL NUMBER	05-JUL-2016 H: 5782.40 L: 2503					
AD 2016-11-20 Airframe AD - N/A FAA #3405	OXYGEN - AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER (P/N) 119003-11 Notes (ISSUING AUTHORITY: FAA).NO PBE INSTALLED.	05-JUL-2016 H: 5782.40 L: 2503					
AD 2016-11-20 AMD Paragraph (g) Airframe AD - N/A FAA #2872	OXYGEN - AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER (P/N) 119003-11 - INSPECTION Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER (P/N) 119003-11, THAT IS INSTALLED ON AIRPLANES).NO PBE INSTALLED.	05-JUL-2016 H: 5782.40 L: 2503					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-11-20 AMD Par. (H)(1) Airframe AD - N/A FAA #1088	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. Notes (ISSUING AUTHORITY: FAA).NO PBE INSTALLED.	05-JUL-2016 H: 5782.40 L: 2503					
AD 2016-11-20 AMD PARA (H.2) Airframe AD - N/A FAA #1484	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12 Notes .NO PBE INSTALLED.	05-JUL-2016 H: 5782.40 L: 2503					
AD 2016-13-09 Airframe AD - Complied With FAA #1468	FLGIHT CONTROLS - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA).PARAGRAPH (G)(I)BY VERIFYING THAT TASKS 27-42-01-109 AND 27-42-01-111 HAVE BEEN INCORPARATED INTO SECTION 5-10-40 OF THE TLMC AND THAT THE TASKS ARE TRACKING IN THE MAINTENANCE TRACKING PROGRAM(CAMP).	26-AUG-2016 H: 5832.00 L: 2522					
AD 2016-20-09 Airframe AD - Complied With FAA #3198	FUEL - APU NEGATIVE-G FUEL FEED DRAIN LINE Notes (ISSUING AUTHORITY: FAA).AD 2016-20-09 PARAGRAPH (G) BY COMPLIANCE OF SB 604-28-021 PART A. PART B NOT REQUIRED DUE TO PROPER CLEARANCE OF DRAIN LINE .NO FUTHUR ACTION REQUIRED	18-JAN-2017 H: 5949.70 L: 2567					
AD 2016-20-09 AMD Par. (h) Airframe AD - Complied With FAA #1670	FUEL - APU NEGATIVE-G FUEL FEED DRAIN LINE - MODIFICATION FOR CERTAIN OTHER AIRPLANES Notes (ISSUING AUTHORITY: FAA) (NOTE: NOTE 1 TO PARAGRAPH (H) OF THIS AD: AN INSPECTION IS NOT REQUIRED).AD 2016-20-09 PARAGRAPH (G) BY COMPLIANCE OF SB 604-28-021 PART A. PART B NOT REQUIRED DUE TO PROPER CLEARANCE OF DRAIN LINE .NO FUTHUR ACTION REQUIRED	18-JAN-2017 H: 5949.70 L: 2567					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2016-20-09 AMD Par. (g) Airframe AD - Complied With FAA #1977	FUEL - APU NEGATIVE-G FUEL FEED DRAIN LINE INSPECTION AND CORRECTIVE ACTION FOR CERTAIN AIRPLANES Notes (ISSUING AUTHORITY: FAA).AD 2016-20-09 PARAGRAPH (G) BY COMPLIANCE OF SB 604-28-021 PART A. PART B NOT REQUIRED DUE TO PROPER CLEARANCE OF DRAIN LINE .NO FUTUR ACTION REQUIRED	18-JAN-2017 H: 5949.70 L: 2567					
AD 2017-04-06 Airframe AD - N/A FAA #1167	ALTIMETER - UNITED INSTRUMENTS MODEL 5934 SERIES - SLOW DIAPHRAGM LEAK Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO UNITED INSTRUMENTS, INC. 5934 SERIES ALTIMETERS THAT WERE MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016 AND INSTALLED IN AIRPLANES AND HELICOPTERS. NOTE: REFER TO UNITED INSTRUMENTS, INC. SERVICE BULLETIN NO. 13, DATED MARCH 25, 2016.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					
AD 2017-09-09 Airframe AD - N/A FAA #1889	PASSENGER COMPARTMENT EQUIPMENT - ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS - REMOVAL Notes (AVG MAN HRS: 1) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	16-JUN-2018					
AD 2017-11-11 Airframe AD - N/A FAA #2171	ATC TRANSPONDER SYSTEM - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO THE FOLLOWING NAVWORX, INC., AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS (UNIT) INSTALLED ON AIRCRAFT CERTIFICATED IN ANY CATEGORY, INCLUDING EXPERIMENTAL: (1) MODEL ADS600-B PART NUMBER (P/N) 200-0012; (2) MODEL ADS600-B P/N 200-0013; AND (3) MODEL ADS600-EXP P/N 200-8013.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-16-01 AMD Par. 2(g) Airframe AD - N/A FAA #868	EMERGENCY LOCATOR BEACON (AMERI-KING CORPORATION) - INSPECT	12-OCT-2017					
Notes (AVG MAN HRS: 2) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2017-16-01 Airframe AD - N/A FAA #1010	EMERGENCY LOCATOR BEACON (AMERI-KING CORPORATION) - INSPECT/ REPLACE	12-OCT-2017					
Notes (AVG MAN HRS: 6) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2017-16-01 AMD Par. 2(j)(1)(2) Airframe AD - N/A FAA #2509	EMERGENCY LOCATOR BEACON (AMERI-KING CORPORATION) - REPLACE (TERMINATING ACTION)	12-OCT-2017					
Notes (AVG MAN HRS: 4) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2017-16-04 Airframe AD - N/A FAA #2195	CABIN EQUIPMENT/FURNISHINGS - ROMTEX TORSO RESTRAINT SYSTEMS WITH A ROTARY BUCKLE SUBASSEMBLY	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2017-16-13 Airframe AD - N/A FAA #3029	OXYGEN - REPLACEMENT OF OXYGEN MASK LANYARDS - TO PREVENT IMPROPER OXYGEN FLOW FUNCTIONALITY TO THE PASSENGER OXYGEN MASKS IN THE EVENT OF AN EMERGENCY	30-MAY-2018 H: 6371.80 L: 2714					
Notes (AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA).BY AIRCRAFT SERIAL NUMBER, NO FURTHER ACTION REQUIRED							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-18-12 AMD Par. (g) Airframe AD - N/A FAA #2209	OXYGEN - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS - INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					
Notes (AVG MAN HRS: 0.5) (ISSUING AUTHORITY: FAA) (NOTE: SCHEDULING/COMPLIANCE REVIEW NEEDED. THIS PARAGRAPH RETAINS THE REQUIREMENTS OF AD 2016-11-20, WHICH WAS DUE 3 MONTHS FROM JULY 15, 2016. REFER TO B/E AEROSPACE SERVICE BULLETIN (SB) NO. 119003-35-011, REV. 000, DATED FEBRUARY 4, 2015.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED							
AD 2017-18-12 AMD Par. (i) Airframe AD - N/A FAA #2567	OXYGEN - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS - NEW INSPECTION FOR AIRPLANES WITH PBE, P/N 119003-21, INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					
Notes (AVG MAN HRS: 0.5) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO B/E AEROSPACE SB NO. 119003-35-013, REV. 002, DATED JULY 19, 2017.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED							
AD 2017-18-12 AMD Par. (j) Airframe AD - N/A FAA #3024	OXYGEN - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS - NEW REPLACEMENT FOR AIRPLANES WITH PBE, P/N 119003-21, INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					
Notes (AVG MAN HRS: 0.5) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO B/E AEROSPACE SB NO. 119003-35-013, REV. 002, DATED JULY 19, 2017.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED							
AD 2017-18-12 AMD Par. (h) Airframe AD - N/A FAA #2469	OXYGEN - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS - REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					
Notes (AVG MAN HRS: 0.5) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: IF A PBE POUCH IS FOUND WHERE THE VACUUM SEAL IS INTACT. NOTE: REFER TO B/E AEROSPACE SB NO. 119003-35-009, REV. 001, DATED APRIL 12, 2016.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED							



Maintenance Items

01-Jun-2026

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-18-12 Airframe AD - N/A FAA #1379	OXYGEN - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS, P/N 119003-11 AND 119003-21 - INSPECT/ REPLACE (THIS AD REPLACES AD 2016-11-20)	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						
AD 2017-19-05 AMD Par. (f)(2.1) Airframe AD - N/A FAA #767	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						
AD 2017-19-05 AMD Par. (f)(2.2) Airframe AD - N/A FAA #1911	REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						
AD 2017-19-05 AMD Par. (f)(2.3) Airframe AD - N/A FAA #2183	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						
AD 2017-19-05 AMD Par. (g) Airframe AD - N/A FAA #2776	SMOKE DETECTION - DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-19-05 AMD Par. 2(f)(1) Airframe AD - N/A FAA #3008	SMOKE DETECTION - INSPECTION	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (AVG MAN HRS: 0.2) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD ALSO APPLIES TO THOSE SMOKE DETECTORS WITH P/NS AND S/NS LISTED IN FIGURE 1 TO PARAGRAPH (C) OF THIS AD; INSTALLED ON, BUT NOT LIMITED TO, ANY AIRPLANE, CERTIFICATED IN ANY CATEGORY, LISTED IN PARAGRAPHS (C)(2)(I) OR (II) OF THIS AD. NOTE: REFER TO SIEMENS SERVICE INFORMATION LETTER (SIL) NO. PMC-26-002, REVISION NO. 1, DATED JANUARY 2016; OR SIEMENS SIL NO. PMC-26-003, REVISION NO. 2, DATED FEBRUARY 2016.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						
AD 2017-19-05 Airframe AD - N/A FAA #440	SMOKE DETECTION - INSPECTION / REPLACEMENT	16-JUN-2018 H: 6372.80 L: 2715					
	Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED						
AD 2017-19-06 Airframe AD - Complied With FAA #3643	WINGS - NEW LIFE LIMITATION - SIDE BRACE FITTING SHAFT AND SIDE BRACE-TO-AIRPLANE FITTING PIN OF THE MAIN LANDING GEAR (MLG) - INSPECT	12-OCT-2017 H: 6181.40 L: 2646					
	Notes (AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA).PER AD INSTRUCTIONS SEE CARDS FOR 2017-19-06 PARA (G) & PARA (H)						
AD 2017-19-06 AMD Par. 2(h) Airframe AD - Complied With FAA #3085	WINGS - NEW LIFE LIMITATION - SIDE BRACE FITTING SHAFT AND SIDE BRACE-TO-AIRPLANE FITTING PIN OF THE MAIN LANDING GEAR (MLG) - INSPECTION, SERIALIZATION, AND RECORDING OF LIFE LIMITED PARTS	12-OCT-2017 H: 6181.40 L: 2646					
	Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA).THE AFFECTED PARTS HAVE BEEN IDENTIFIED AND SERIAL NUMBERS HAVE BEEN RECORDED ALONG WITH ACCUMULATED TIME/ CYCLES.						
AD 2017-19-06 AMD Par. 2(g) Airframe AD - Complied With FAA #1631	WINGS - NEW LIFE LIMITATION - SIDE BRACE FITTING SHAFT AND SIDE BRACE-TO-AIRPLANE FITTING PIN OF THE MAIN LANDING GEAR (MLG) - REVISION OF MAINTENANCE OR INSPECTION PROGRAM	12-OCT-2017 H: 6181.40 L: 2646					
	Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA).THE MAINTENANCE / INSPECTIONS PROGRAM HAS BEEN UPDATED TO INCORPORATE THE LIFE LIMITS OF THE AFFECTED PARTS.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-20-11 Airframe AD - N/A FAA #815	FUSELAGE - MAINTENANCE OR INSPECTION PROGRAM REVISION - TO DETECT AND CORRECT DEGRADATION OF THE STRUCTURAL INTEGRITY OF THE AFFECTED TIE BEAM, WHICH COULD RESULT IN CRACKING OF THE PRESSURE FLOOR	30-MAY-2018 H: 6371.80 L: 2714					
Notes (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO MANDATORY CONTINUING AIRWORTHINESS INFORMATION (MCAI) CANADIAN AIRWORTHINESS DIRECTIVE CF-2016-34, DATED OCTOBER 14, 2016.) BY A/C SERIAL NUMBER, NO FURTHER ACTION REQUIRED							
AD 2017-22-02 Airframe AD - N/A FAA #2489	PILOT AND CO-PILOT SEATS - MODIFICATION/ RE-IDENTIFICATION (THIS AD HAS BEEN REPLACED BY AD 2019-21-06)	16-JUN-2018					
Notes (AVG MAN HRS: 2) (UPDATE NOTE: AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO IPECO HOLDINGS LTD. (IPECO) PILOT AND CO-PILOT SEATS WITH A PART NUMBER LISTED IN THE PLANNING INFORMATION SECTION OF IPECO SERVICE BULLETINS (SBS) NUMBER 063-25-08, REVISION 00; NUMBER 063-25-09, REVISION 00; AND NUMBER 063-25-10, REVISION 00; ALL DATED MAY 31, 2016.) AD NA AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2017-22-06 Airframe AD - Complied With FAA #200	FUEL LEAKS IN THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER ELECTRICAL CONNECTORS AND CONDUITS (SUPERSEDED BY FAA AD 2021-26-23)	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: AD 2017-22-06 EFFECTIVE DATE 30 NOV 2017 "TO DETECT AND CORRECT FUEL LEAKS IN CERTAIN FUEL PUMPS" PER PARAGRAPH (G)(1), (G)(2), (G)(3) USING AMOC LETTER LOG #18-41, WTS NUMBER 18 DOC 12424 AND SB 604-28-022 R03. NOTE: FOR CONTINUED AIRWORTHINESS NEXT INSPECTION DUE AT THE NEXT 600 FLIGHT HOUR INTERVAL OR 12 MONTHS, WHICHEVER OCCURS FIRST REF DUNCAN AVIATION WO FFMBA.) (ISSUING AUTHORITY: FAA) AD 2017-22-06 EFFECTIVE DATE 30 NOV 2017 "TO DETECT AND CORRECT FUEL LEAKS IN CERTAIN FUEL PUMPS" PER PARAGRAPH (G)(1), (G)(2), (G)(3) USING AMOC LETTER LOG #18-41, WTS NUMBER 18 DOC 12424 AND SB 604-28-022 R03. NOTE: FOR CONTINUED AIRWORTHINESS NEXT INSPECTION DUE AT THE NEXT 600 FLIGHT H							
AD 2017-22-06 AMD Par. 2(g)(1)(2)(3) Airframe AD - Complied With FAA #1755	FUEL LEAKS IN THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER ELECTRICAL CONNECTORS AND CONDUITS - GENERAL VISUAL INSPECTIONS AND CORRECTIVE ACTIONS-MODEL CL-600-2B16 AIRPLANES, SERIAL NUMBERS 5301 THROUGH 5665 INCLUSIVE (SUPERSEDED BY FAA AD 2021-26-23)	02-JUL-2021 H: 6939.60 L: 3034					
Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2017-22-06 AMD Par. 2(h)(1)(2)(3) Airframe AD - Complied With FAA #3637	FUEL LEAKS IN THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER ELECTRICAL CONNECTORS AND CONDUITS - GENERAL VISUAL INSPECTIONS AND RELATED INVESTIGATIVE AND CORRECTIVE ACTIONS-MODEL CL-600-2B16 AIRPLANES HAVING SERIAL NUMBERS 5701 THROUGH 5955 INCLUSIVE, 5957, 5960 THROUGH 5966 INCLUSIVE, 5968 THROUGH 5971 INCLUSIVE, AND 5981 (SUPERSEDED BY FAA AD 2021-26-23) Notes (UPDATE NOTE: COMPLIED WITH INSPECTION IAW SB 604-28-022) (ISSUING AUTHORITY: FAA).COMPLIED WITH INSPECTION IAW SB 604-28-022	26-JUL-2019 H: 6476.10 L: 2770					
AD 2017-22-11 Airframe AD - Complied With FAA #709	NAVIGATION - AIR DATA SYSTEM - AFM REVISION Notes (ISSUING AUTHORITY: FAA).BY PREVIOUS REVISION OF AFM (CURRENT REV IS 107) NO FURTHER ACTION REQUIRED AT THIS TIME	22-DEC-2017 H: 6236.60 L: 2672					
AD 2017-22-14 Airframe AD - N/A FAA #2012	NAVIGATION - UPGRADE THE ROCKWELL COLLINS, INC. TSSA-4100 FLS TO RCPN 810-0052-013 OR 810-0052-102 Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO ROCKWELL COLLINS SERVICE INFORMATION LETTER, TSSA-4100-SIL-10-1, REVISION NO. 9, DATED MARCH 31, 2017; OR ROCKWELL COLLINS SERVICE INFORMATION LETTER TSSA-4100-SIL-10-1, REVISION NO. 10, DATED JULY 10, 2017.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					
AD 2017-23-09 Airframe AD - Complied With FAA #1437	REVISION OF MAINTENANCE OR INSPECTION PROGRAM - INCORPORATE INSPECTIONS FOR FATIGUE CRACKING OF THE ENGINE MOUNT RIB Notes (ISSUING AUTHORITY: FAA).BY VERIFYING THE MAINTENANCE /INSPECTION PROGRAM HAS BEEN REVISED. NO FURTHER ACTION REQUIRED AT THIS TIME	22-DEC-2017 H: 6236.60 L: 2672					
AD 2018-03-04 AMD Par. 2(g) Airframe AD - N/A FAA #1252	AIRSPPEED/MACH INDICATOR - PITOT PROBE - DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ROSEMOUNT AEROSPACE, INC. MODEL 851AK PITOT PROBES THAT WERE REPAIRED BY CSI AEROSPACE INC. AND HAVE A SERIAL NUMBER LISTED IN PARAGRAPH (C)(1) OF THIS AD THAT ARE KNOWN TO BE INSTALLED ON BUT NOT LIMITED TO THE AIRPLANES LISTED IN PARAGRAPH (C)(2) OF THIS AD. PITOT PROBES THAT WERE REPAIRED BY CSI AEROSPACE INC. THAT HAVE A REPAIR DATE OF AUGUST 1, 2014, OR LATER, ARE EXCLUDED FROM THE APPLICABILITY.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED	16-JUN-2018 H: 6372.80 L: 2715					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-03-04 Airframe AD - N/A FAA #3045	AIRSPEED/MACH INDICATOR - PITOT PROBE - INSPECT/ REPLACE	16-JUN-2018 H: 6372.80 L: 2715					
Notes (AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA).DUE TO AFFECTED EQUIPMENT NOT INSTALLED							
AD 2018-03-04 AMD Par. 2(h) Airframe AD - N/A FAA #3202	AIRSPEED/MACH INDICATOR - PITOT PROBE - REPLACE AFFECTED PITOT PROBES	16-JUN-2018 H: 6372.80 L: 2715					
Notes (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ROSEMOUNT AEROSPACE, INC. MODEL 851AK PITOT PROBES THAT WERE REPAIRED BY CSI AEROSPACE INC. AND HAVE A SERIAL NUMBER LISTED IN PARAGRAPH (C)(1) OF THIS AD THAT ARE KNOWN TO BE INSTALLED ON BUT NOT LIMITED TO THE AIRPLANES LISTED IN PARAGRAPH (C)(2) OF THIS AD. PITOT PROBES THAT WERE REPAIRED BY CSI AEROSPACE INC. THAT HAVE A REPAIR DATE OF AUGUST 1, 2014, OR LATER, ARE EXCLUDED FROM THE APPLICABILITY.).DUE TO AFFECTED EQUIPMENT NOT INSTALLED							
AD 2018-06-06 Airframe AD - Complied With FAA #2879	AUTOPILOT SYSTEM - MODIFY THE WIRING HARNESS FOR THE YAW DAMPER CONTROL SYSTEM	02-JUL-2021 H: 6939.60 L: 3034					
Notes (AVG MAN HRS: 50) (APX COST: 4,728) (UPDATE NOTE: AD 2018-06-06 EFFECTIVE DATE 19 APR 2018 "AUTOPILOT SYSTEM - RUDDER CONTROLS - YAW DAMPER UNCOMMANDED MOVEMENT" IAW PARAGRAPH (G) (1). REF DUNCAN WO FFMB) (ISSUING AUTHORITY: FAA) (NOTE: EFFECTIVITY: CL-600-2B16 (CL-604 VARIANT) AIRPLANES, SERIAL NUMBERS 5301 THROUGH 5665, 5701 THROUGH 5911, 5913, AND 5914.).AD 2018-06-06 EFFECTIVE DATE 19 APR 2018 "AUTOPILOT SYSTEM - RUDDER CONTROLS - YAW DAMPER UNCOMMANDED MOVEMENT" IAW PARAGRAPH (G) (1). REF DUNCAN WO FFMB							
AD 2018-09-17 AMD Par. (g) Airframe AD - Open FAA #1701	FLIGHT CONTROLS - RUDDER PEDAL TUBES ON THE PILOT-SIDE RUDDER BAR ASSEMBLY - DETAILED OR EDDY CURRENT INSPECTION	15-OCT-1997	L: 9000			L: 9000	L: 4998
Notes (AVG MAN HRS: 10) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: FOR DETAILED INSPECTION. APPLICABILITY: AIRPLANES WITH FEWER THAN 8,250 TOTAL FLIGHT CYCLES AS OF THE EFFECTIVE DATE OF THIS AD.)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-09-17 Airframe AD - Open FAA #1745	FLIGHT CONTROLS - RUDDER PEDAL TUBES ON THE PILOT-SIDE RUDDER BAR ASSEMBLY - INSPECT/ REPLACE Notes (AVG MAN HRS: 12) (ISSUING AUTHORITY: FAA)						
AD 2018-09-17 AMD Par. (h)(i)(j) Airframe AD - Open FAA #1771	FLIGHT CONTROLS - RUDDER PEDAL TUBES ON THE PILOT-SIDE RUDDER BAR ASSEMBLY - REPLACE (TERMINATING ACTION) Notes (AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REPLACEMENT OF BOTH PILOT-SIDE RUDDER BAR ASSEMBLIES USING PART B OF THE ACCOMPLISHMENT INSTRUCTIONS OF BOMBARDIER SERVICE BULLETIN 600-0770, DATED AUGUST 31, 2015; OR BOMBARDIER SERVICE BULLETIN 601-0643, DATED AUGUST 31, 2015; IS NOT A TERMINATING ACTION FOR THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD.)						
AD 2018-16-01 Airframe AD - N/A FAA #1109	ATTENDANT SEAT NG AND PILOT SEAT 120/335 - REPLACEMENT Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016.).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2018-16-13 Airframe AD - N/A FAA #2310	ZODIAC SEATS FRANCE - 537-SERIES CABIN ATTENDANT SEATS - SAFETY BELT WEBBING - INSPECTION/ MODIFICATION Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01, DATED JULY 31, 2015, AND THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPHS 2.A. THROUGH 2.B., OF ZODIAC SEATS FRANCE SERVICE BULLETIN NO. 537-25-003, REVISION 1, DATED AUGUST 29, 2016.).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2018-17-02 AMD Par. (g)(h) Part II Airframe AD - Open FAA #3357	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - INCORPORATE LIFE LIMIT AWL TASKS Notes (ISSUING AUTHORITY: FAA)		L: 7800			L: 7800	L: 3798



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-17-02 AMD Par. (g)(h) Part I Airframe AD - Complied With FAA #1897	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - MAINTENANCE OR INSPECTION PROGRAM REVISION	14-JUL-2022 H: 7631.90 L: 3410					
Notes (UPDATE NOTE: AD 2018-17-02 PAR.(H), HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - MAINTENANCE OR INSPECTION PROGRAM REVISION, COMPLIED WITH BY VERIFYING INSPECTION REQUIREMENTS OF AD 2018-17-02(H) ARE INCORPORATED INTO THE MAINTENANCE PROGRAM., TASK 27-42-01-112 DUE AT 7800 CYCLES, TASK 27-42-01-108 DUE AT 20,000 CYCLES.) (ISSUING AUTHORITY: FAA).AD 2018-17-02 PAR.(H), HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - MAINTENANCE OR INSPECTION PROGRAM REVISION, COMPLIED WITH BY VERIFYING INSPECTION REQUIREMENTS OF AD 2018-17-02(H) ARE INCORPORATED INTO THE MAINTENANCE PROGRAM., TASK 27-42-01-112 DUE AT 7800 CYCLES, TASK 27-42-01-108 DUE							
AD 2018-17-02 Airframe AD - Complied With FAA #1825	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - MAINTENANCE OR INSPECTION PROGRAM REVISION/ SERIALIZATION/ REPAIR	14-JUL-2022 H: 7631.90 L: 3410					
Notes (UPDATE NOTE: AD 2018-17-02 PAR.(H), HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - MAINTENANCE OR INSPECTION PROGRAM REVISION, COMPLIED WITH BY VERIFYING INSPECTION REQUIREMENTS OF AD 2018-17-02(H) ARE INCORPORATED INTO THE MAINTENANCE PROGRAM., TASK 27-42-01-112 DUE AT 7800 CYCLES, TASK 27-42-01-108 DUE AT 20,000 CYCLES. AD 2018-17-02 PAR.(I), HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - SERIALIZATION/ REPAIR, COMPLIED WITH BY DUNCAN AVIATION DURING INCORPORATION OF SB 604-27-034 UNDER WORK ORDER Z6GC, SEE MAINTENANCE ENTRY DATED 23-MAR-2017 FOR DETAILS, NO FURTHER ACTION NECESSARY FOR PAR. (I).) (ISSUING AUTHORITY: FAA).AD 2018-17							
AD 2018-17-02 AMD Par. (i) Airframe AD - Complied With FAA #2650	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - SERIALIZATION/ REPAIR	14-JUL-2022 H: 7631.90 L: 3410					
Notes (UPDATE NOTE: AD 2018-17-02 PAR.(I), HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - SERIALIZATION/ REPAIR, COMPLIED WITH BY DUNCAN AVIATION DURING INCORPORATION OF SB 604-27-034 UNDER WORK ORDER Z6GC, SEE MAINTENANCE ENTRY DATED 23-MAR-2017 FOR DETAILS, NO FURTHER ACTION NECESSARY FOR PAR. (I).) (ISSUING AUTHORITY: FAA).AD 2018-17-02 PAR.(I), HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) ATTACHMENT PINS AND TRUNNIONS - SERIALIZATION/ REPAIR, COMPLIED WITH BY DUNCAN AVIATION DURING INCORPORATION OF SB 604-27-034 UNDER WORK ORDER Z6GC, SEE MAINTENANCE ENTRY DATED 23-MAR-2017 FOR DETAILS, NO FURTHER ACTION NECESSARY FOR PAR. (I).							
AD 2018-19-15 Airframe AD - N/A FAA #2976	GEVEN S.P.A. (GEVEN) TYPE D1-02 AND D1-03 IN-ARM TABLE, STANDARD, AND LAST ROW SEATS - MODIFICATION	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO GEVEN SB NO. D103-25-004, REVISION 4, DATED MARCH 15, 2016.).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2018-20-21 Airframe AD - Complied With FAA #3403	FLOODLIGHT FIXTURES - NEW GASKET SEALS - INSTALLATION Notes (AVG MAN HRS: 2) (UPDATE NOTE: COMPLIED WITH PER PARAGRAPH (G)(1) BY INCORPORATION OF SB 604-33-007 R2 ON DUNCAN AVIATION WO FFMBA.) (ISSUING AUTHORITY: FAA).COMPLIED WITH PER PARAGRAPH (G)(1) BY INCORPORATION OF SB 604-33-007 R2 ON DUNCAN AVIATION WO FFMBA.	02-JUL-2021 H: 6939.60 L: 3034					
AD 2018-21-14 Airframe AD - N/A FAA #386	MC10 SERIES CREW OXYGEN MASK REGULATORS - INFLATABLE HARNESS ASSEMBLY, P/N MXH20-1 OR MXH21-1 - INSPECTION/ REPLACEMENT Notes (UPDATE NOTE: COMPLIED WITH AD 2018-21-14, MC10 SERIES CREW OXYGEN MASK REGULATORS - INFLATABLE HARNESS ASSEMBLY, P/N MXH20-1 OR MXH21-1, BY INSPECTION OF THE CREW OXYGEN MASK REGULATORS. NOT APPLICABLE BY AFFECTED MASKS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).COMPLIED WITH AD 2018-21-14, MC10 SERIES CREW OXYGEN MASK REGULATORS - INFLATABLE HARNESS ASSEMBLY, P/N MXH20-1 OR MXH21-1, BY INSPECTION OF THE CREW OXYGEN MASK REGULATORS. NOT APPLICABLE BY AFFECTED MASKS NOT INSTALLED. NO FURTHER ACTION NECESSARY.	25-FEB-2022 H: 7441.20 L: 3309					
AD 2018-23-01 Airframe AD - N/A FAA #2182	ZODIAC SEATS FRANCE CABIN ATTENDANT SEATS, 536 SERIES, P/N 53600 WITH SEAT PAN P/N F0433453 - INSPECTION/ MODIFICATION/ REPLACEMENT Notes (ISSUING AUTHORITY: FAA)	04-NOV-2019 H: 6485.50 L: 2778					
AD 2019-01-02 Airframe AD - N/A FAA #771	ATTITUDE AND DIRECTION DATA SYSTEM - AUTOMATIC DEPENDENT SURVEILLANCE- BROADCAST (ADS-B) IN FUNCTION - DISABLE/ REVISE AFM SUPPLEMENT Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: BEFORE THE NEXT FLIGHT IN IMC OR AT NIGHT.).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					
AD 2019-07-03 Airframe AD - N/A FAA #2985	ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEATS - INSPECTION/ MODIFICATION Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA).AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME	04-NOV-2019 H: 6485.50 L: 2778					

N530BD





Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2019-12-09 Airframe AD - N/A FAA #2187	NAVIGATION - ROCKWELL COLLINS, INC. (ROCKWELL COLLINS) FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 - REVISE AFM/ FABRICATE PLACARD	04-NOV-2019 H: 6485.50 L: 2778					
	Notes (UPDATE NOTE: AIRWORTHINESS DIRECTIVE 2019-12-09 AMENDMENT 39-19664 FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 EFFECTIVE JULY 23, 2019 IS N/A AT THIS TIME EQUIPMENT ON AD IS NOT INSTALLED ON AIRCRAFT AT THIS TIME.) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: THIS AD APPLIES TO ROCKWELL COLLINS, INC. (ROCKWELL COLLINS) FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, AND 810-0234-4B0001.).EQUIP NOT INSTAALED						
AD 2019-15-01 AMD Par. (g) Airframe AD - N/A FAA #185	MAIN LANDING GEAR - SIDE-STAY ACTUATORS - SPLIT BALL BEARINGS - INSPECTION TO VERIFY THE SERIAL NUMBER	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: FOR AIRPLANE EQUIPPED WITH ANY MLG SIDE STAY ACTUATOR ASSEMBLY CONTAINING SPLIT BALL BEARING P/N 104467672: FOR THE LEFT AND RIGHT MLG SIDE STAY ACTUATOR ASSEMBLIES HAVING P/NS 19011-103 AND 19011-105, AS OF THE EFFECTIVE DATE OF THIS AD HAS 3,350 TOTAL FLIGHT CYCLES OR FEWER ON AN MLG SIDE STAY ACTUATOR ASSEMBLY.).NOT APPLICABLE BY PART NUMBER. VERIFIED BY VISUAL INSPECTION, ACTUATOR SPLIT BALL BEARINGS INSTALLED ARE P/N: 19011-107. THIS IS A TERMINATING ACTION FOR THIS AD AT THIS TIME, NO FURTHER ACTION REQUIRED						
AD 2019-15-01 Airframe AD - N/A FAA #1262	MAIN LANDING GEAR - SIDE-STAY ACTUATORS - SPLIT BALL BEARINGS - INSPECTION/ REPLACEMENT	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (ISSUING AUTHORITY: FAA).NOT APPLICABLE BY PART NUMBER. VERIFIED BY VISUAL INSPECTION, ACTUATOR SPLIT BALL BEARINGS INSTALLED ARE P/N: 19011-107. THIS IS A TERMINATING ACTION FOR THIS AD AT THIS TIME, NO FURTHER ACTION REQUIRED						
AD 2019-15-01 AMD Par. (h) Airframe AD - N/A FAA #1408	MAIN LANDING GEAR - SIDE-STAY ACTUATORS - SPLIT BALL BEARINGS - REPLACEMENT	11-JUL-2023 H: 8075.40 L: 3647					
	Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS 3WTR399B ON WO CL5851) (ISSUING AUTHORITY: FAA).NOT APPLICABLE BY PART NUMBER. VERIFIED BY VISUAL INSPECTION, ACTUATOR SPLIT BALL BEARINGS INSTALLED ARE P/N: 19011-107. THIS IS A TERMINATING ACTION FOR THIS AD AT THIS TIME, NO FURTHER ACTION REQUIRED						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2019-15-10 Airframe AD - N/A FAA #3484	SAFRAN AEROSYSTEMS LIFE JACKETS WITH P/N 210225-2, P/N 216200-0, OR P/N 216203-0 - INSPECT/ REPLACE/ REPAIR	04-NOV-2019 H: 6485.50 L: 2778					
Notes (UPDATE NOTE: AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: REFER TO ZODIAC AEROSPACE SERVICES SERVICE BULLETIN (SB) 25-65-33, REVISION 02, DATED MARCH 15, 2019.)AD N/A AFFECTED EQUIPMENT NOT INSTALLED AT THIS TIME							
AD 2019-20-03 Airframe AD - N/A FAA #159	UNIVERSAL SERIAL BUS (USB) RECEPTACLE (LONE STAR AVIATION, CORPORATION) P/N LS03-05050-A - MODIFICATION (THIS AD IS SUPERSEDED BY FAA AD 2022-15-08)	17-NOV-2020 H: 6678.60 L: 2901					
Notes (AVG MAN HRS: 3) (UPDATE NOTE: AD 2019-20-03 NOT APPLICABLE BY EFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY EACH AFFECTED PART IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE FOKKER SERVICES B.V. SERVICE INFORMATION IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (13) OF THIS AD.)AD 2019-20-03 NOT APPLICABLE BY EFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.							
AD 2020-08-01 Engine 1 AD - N/A FAA #907	FAN BLADE REPLACEMENT	12-MAY-2020 H: 6562.30 C: 2835					
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: AD 2020-08-01 FAN BLADE REPLACEMENT , GENERAL ELECTRIC COMPANY: AMENDMENT 39-21107, EFFECTIVE MAY 15, 2020, IS N/A. S/N OF EFFECTED PARTS IN SB CF34-BJ 72-0306 DATED SEPT 27, 2017 REFERENCED BY AD ARE NOT INSTALLED ON THIS ENGINE AT THIS TIME.) (ISSUING AUTHORITY: FAA).BY SUSPECTED SERIAL NUMBERS DID NOT MATCH ANY OF THE FAN BLADES ON THE #1 ENGINE							
AD 2020-08-01 Engine 2 AD - N/A FAA #361	FAN BLADE REPLACEMENT	12-MAY-2020 H: 6562.30 C: 2835					
Notes (AVG MAN HRS: 0.5) (UPDATE NOTE: AD 2020-08-01 FAN BLADE REPLACEMENT , GENERAL ELECTRIC COMPANY: AMENDMENT 39-21107, EFFECTIVE MAY 15, 2020, IS N/A. S/N OF EFFECTED PARTS IN SB CF34-BJ 72-0306 DATED SEPT 27, 2017 REFERENCED BY AD ARE NOT INSTALLED ON THIS ENGINE AT THIS TIME.) (ISSUING AUTHORITY: FAA).BY SUSPECTED SERIAL NUMBERS DID NOT MATCH ANY OF THE FAN BLADES ON THE #2 ENGINE							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2020-08-02 Airframe AD - N/A FAA #197	GLOBAL POSITIONING SYSTEM - THALES GPS/SBAS RECEIVERS	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-08-02 EFFECTIVE 19 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2020-08-02 EFFECTIVE 19 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							
AD 2020-08-02 AMD Par. (g)(2)(i) Airframe AD - N/A FAA #1537	GLOBAL POSITIONING SYSTEM - THALES GPS/SBAS RECEIVERS - AMEND AIRPLANE FLIGHT MANUAL	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-08-02 EFFECTIVE 19 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: (2) FOR OPERATORS OF AFFECTED ATR MODEL ATR42 AND ATR72 AIRPLANES: (I) WITHIN 30 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, AMEND SECTION 1.2 "EACH FLIGHT CHECKS" OF THE PRE-FLIGHT SECTION IN THE APPLICABLE AIRPLANE FLIGHT MANUAL BY INSERTING THE CHANGE SHOWN IN FIGURE 1 AND FIGURE 2 TO PARAGRAPH (G)(2)(I) OF THIS AD.).AD 2020-08-02 EFFECTIVE 19 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							
AD 2020-08-02 AMD Par. (g)(1)(i) Airframe AD - N/A FAA #3458	GLOBAL POSITIONING SYSTEM - THALES GPS/SBAS RECEIVERS - UPDATE NAVIGATION DATABASE	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-08-02 EFFECTIVE 19 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: (1) FOR OPERATORS OF AFFECTED ATR MODEL ATR42 AND ATR72 AIRPLANES: (I) UPDATE THE AIRCRAFT'S NAVIGATION DATABASE WITHIN 30 DAYS AFTER THE EFFECTIVE DATE OF THIS AD USING THE SOFTWARE UPLOAD INSTRUCTIONS, AS APPLICABLE).AD 2020-08-02 EFFECTIVE 19 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							
AD 2020-09-02 AMD Par. (h) Airframe AD - Open FAA #157	CABIN EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS - INSPECTION/REPLACEMENT/INSTALLATION PROHIBITION - DO NOT INSTALL ON ANY AIRCRAFT AN ANJOU AERONAUTIQUE RESTRAINT SYSTEM, P/N 358XX-XXX-YY-ZZZ, HAVING S/NS 738-1619 (INCLUSIVE), EVEN IF THE RESTRAINT SYSTEM IS LABELED IN COMPLIANCE WITH ANJOU AERO SB 358SB-14-101 R01, DATED DECEMBER 12, 2014						
Notes (ISSUING AUTHORITY: FAA)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2020-09-02 Airframe AD - N/A FAA #2486	CABIN EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS - INSPECTION/REPLACEMENT/INSTALLATION PROHIBITION (THIS AD REPLACES AD 2017-16-04)	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							
AD 2020-09-02 AMD Par. (g)(1) Airframe AD - N/A FAA #1667	CABIN EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS - RESTRAINT SYSTEMS LISTED ON ANJOU AERO SB NO. 358SB-14-101 - INSPECTION	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							
AD 2020-09-02 AMD Par. (g)(1)(i)(ii) Airframe AD - N/A FAA #1729	CABIN EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS - RESTRAINT SYSTEMS LISTED ON ANJOU AERO SB NO. 358SB-14-101 - REPLACEMENT	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: NOTE: IF THE STRAPS DO NOT RELEASE FROM THE RESTRAINT SYSTEM, BEFORE FURTHER FLIGHT, PLACARD THE SEAT AS INOPERATIVE.).AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							
AD 2020-09-02 AMD Par. (g)(2) Airframe AD - N/A FAA #2272	CABIN EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS - RESTRAINT SYSTEMS P/N 358XX-XXX-YY-ZZZ - INSPECTION	23-NOV-2020 H: 6688.40 L: 2904					
Notes (UPDATE NOTE: AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2020-09-02 AMD Par. (g)(2)(i)(ii) Airframe AD - N/A FAA #3457	CABIN EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE MODEL 358 TORSO RESTRAINT SYSTEMS - RESTRAINT SYSTEMS P/N 358XX-XXX-YY-ZZZ - REPLACEMENT	23-NOV-2020 H: 6688.40 L: 2904					
	Notes (UPDATE NOTE: AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF THE STRAPS DO NOT RELEASE FROM THE RESTRAINT SYSTEM, BEFORE FURTHER FLIGHT, PLACARD THE SEAT AS INOPERATIVE AND WITHIN 180 HOURS TIS AFTER THE EFFECTIVE DATE OF THIS AD, REMOVE THE RESTRAINT SYSTEM FROM SERVICE AND REPLACE IT WITH A PART ELIGIBLE FOR INSTALLATION.)AD 2020-09-02 EFFECTIVE 29 MAY 2020, NOT APPLICABLE BY EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.						
AD 2020-10-05 Airframe AD - N/A FAA #2220	FLIGHT MANAGEMENT COMPUTING HARDWARE SYSTEM - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (ISSUING AUTHORITY: FAA)						
AD 2020-10-05 AMD Par. (g) Airframe AD - N/A FAA #3223	FLIGHT MANAGEMENT COMPUTING HARDWARE SYSTEM - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS - DISABLE TEMPERATURE COMPENSATION	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: AD 2020-10-05 EFFECTIVE DATE 24 JUN 2020 "NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEM." AIRCRAFT IS NOT EQUIPPED WITH APPLICABLE FMCS. NO CHANGES TO AFM LIMITATIONS SECTION APPLY. REF DUNCAN WO FFMB) (ISSUING AUTHORITY: FAA) (NOTE: WITHIN THE NEXT 12 MONTHS AFTER JUNE 24, 2020 (THE EFFECTIVE DATE OF THIS AD), DISABLE THE AUTOMATIC TEMPERATURE COMPENSATION FEATURE ON THE CSU BY FOLLOWING STEPS (2) THROUGH (6) OF THE INSTRUCTIONS IN ROCKWELL COLLINS SERVICE INFORMATION LETTER CSU-XX00-18-1, DATED JUNE 27, 2018.)AD 2020-10-05 EFFECTIVE DATE 24 JUN 2020 "NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEM." AIRCRAFT IS NOT EQUIPPED WITH APPLICABLE FMCS. NO CHANGES TO AFM LIMITATIONS SECTION APPLY.						
AD 2020-10-05 AMD Par. (h) Airframe AD - N/A FAA #2751	FLIGHT MANAGEMENT COMPUTING HARDWARE SYSTEM - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS - REVISE THE AIRPLANE FLIGHT MANUAL LIMITATIONS	02-JUL-2021 H: 6939.60 L: 3034					
	Notes (UPDATE NOTE: AD 2020-10-05 EFFECTIVE DATE 24 JUN 2020 "NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEM." AIRCRAFT IS NOT EQUIPPED WITH APPLICABLE FMCS. NO CHANGES TO AFM LIMITATIONS SECTION APPLY. REF DUNCAN WO FFMB) (ISSUING AUTHORITY: FAA) (NOTE: WITHIN THE NEXT 12 MONTHS AFTER JUNE 24, 2020 (THE EFFECTIVE DATE OF THIS AD), REVISE THE AIRPLANE FLIGHT MANUAL BY ADDING THE INFORMATION FROM STEP 2 OF THE AIRCRAFT FLIGHT MANUAL RECOMMENDATION IN ROCKWELL COLLINS SERVICE INFORMATION LETTER FMC-XX00-18-1, REVISION 1, DATED FEBRUARY 5, 2019, INTO THE LIMITATIONS SECTION OF THE AFM.)AD 2020-10-05 EFFECTIVE DATE 24 JUN 2020 "NAVIGATION - ROCKWELL COLLINS PRO LINE						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2020-16-08 Airframe AD - N/A FAA #2758	FLIGHT ENVIRONMENT DATA, ATTITUDE AND DIRECTION DATA SYSTEM Notes (UPDATE NOTE: COMPLIED WITH AD 2020-16-08, FLIGHT ENVIRONMENT DATA, ATTITUDE AND DIRECTION DATA SYSTEM, BY REVIEW OF APPLICABLE AIRCRAFT. NOT APPLICABLE BY AIRCRAFT MAKE AND MODEL. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: (1) BEFORE FURTHER FLIGHT, REVISE THE LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE BY INSERTING A COPY OF THIS AD OR BY MAKING A PEN AND INK CHANGE TO ADD: "OPERATION UNDER INSTRUMENT FLIGHT RULES (IFR) OR NIGHT VISUAL FLIGHT RULES (VFR) IS PROHIBITED.") NOT APPLICABLE BY AIRCRAFT MAKE AND MODEL.	07-AUG-2020 H: 6606.80 L: 2859					
AD 2020-18-51 Airframe AD - N/A FAA #3588	ATTITUDE AND DIRECTION DATA SYSTEM - BENDIXKING/SANDIA Notes (UPDATE NOTE: AD 2020-18-51, ATTITUDE AND DIRECTION DATA SYSTEM - BENDIXKING/SANDIA, EFFECTIVE 28-SEP-2020, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: (1) BEFORE FURTHER FLIGHT, REVISE THE LIMITATIONS SECTION OF THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE BY INSERTING A COPY OF THIS AD OR BY MAKING A PEN AND INK CHANGE TO ADD:).AD 2020-18-51, ATTITUDE AND DIRECTION DATA SYSTEM - BENDIXKING/SANDIA, EFFECTIVE 28-SEP-2020, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.	24-JAN-2023 H: 7925.20 L: 3563					
AD 2020-19-13 Airframe AD - Open FAA #2511	OXYGEN - SCOTT (AVOX/ZODIAC) 5500 OR 5600 SERIES (SUPERSEDED BY FAA AD 2025-07-09) Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: PARAGRAPH (G)(H)(I))						
AD 2020-21-02 Airframe AD - N/A FAA #858	FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE - CARGO FIRE EXTINGUISHER HALON BOTTLES Notes (UPDATE NOTE: AD 2020-21-02, KIDDE AEROSPACE & DEFENSE - CARGO FIRE EXTINGUISHER HALON BOTTLES, NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2020-21-02, KIDDE AEROSPACE & DEFENSE - CARGO FIRE EXTINGUISHER HALON BOTTLES, NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.	25-AUG-2022 H: 7715.60 L: 3455					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-0234 Airframe AD - N/A EASA #3656	INFORMATION SYSTEMS - ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE - MODIFICATION Notes (UPDATE NOTE: COMPLIED WITH EASA AD 2021-0234, ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE, BY INSPECTION FOR INSTALLED USB RECEPTACLES. AD NOT APPLICABLE BY AFFECTED USB RECEPTACLES NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: EASA) (NOTE: AFFECTED PART: LONE STAR AVIATION, CORP. USB RECEPTACLES, HAVING PART NUMBER (P/N) LS03-05050-A. COMPLIANCE: GROUP 1 - WITHIN 12 MONTHS AFTER 14 DECEMBER 2018 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF EASA AD 2018-0259])	24-NOV-2021 H: 7198.00 L: 3181					
AD 2021-05-17 Airframe AD - N/A FAA #593	NAVIGATION SYSTEM - ROCKWELL COLLINS, INC. (ROCKWELL COLLINS) FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 Notes (UPDATE NOTE: COMPLIED WITH AD 2021-05-17, ROCKWELL COLLINS, INC. FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, BY INSPECTION OF THE INSTALLED DISPLAY UNIT PART NUMBERS. AD NOT APPLICABLE BY AFFECTED DISPLAY UNIT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ROCKWELL COLLINS, INC., (ROCKWELL COLLINS) FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 PART NUMBERS (P/NS) 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, AND 810-0234-4B0001.).COMPLIED WITH AD 2021-05-17, ROCKWELL COLLINS, INC. FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, BY INSPECTION OF THE INSTALLED DISPLAY UNIT PART	24-NOV-2021 H: 7198.00 L: 3181					
AD 2021-05-17 AMD Par. (g)(1) Airframe AD - N/A FAA #1559	NAVIGATION SYSTEM - ROCKWELL COLLINS, INC. (ROCKWELL COLLINS) FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500: REVISE AFM/AFMS, FABRICATE PLACARD AND INSTALL PLACARD Notes (UPDATE NOTE: COMPLIED WITH AD 2021-05-17, ROCKWELL COLLINS, INC. FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, BY INSPECTION OF THE INSTALLED DISPLAY UNIT PART NUMBERS. AD NOT APPLICABLE BY AFFECTED DISPLAY UNIT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: WITHIN 30 DAYS AFTER JULY 23, 2019 (THE EFFECTIVE DATE OF AD 2019-12-09), DO THE FOLLOWING).COMPLIED WITH AD 2021-05-17, ROCKWELL COLLINS, INC. FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, BY INSPECTION OF THE INSTALLED DISPLAY UNIT PART NUMBERS. AD NOT APPLICABLE BY AFFECTED DISPLAY UNIT NOT INSTALLED. NO FURTHER ACTION NECESSARY.	24-NOV-2021 H: 7198.00 L: 3181					
AD 2021-05-17 AMD Par. (g)(3) Airframe AD - N/A FAA #891	NAVIGATION SYSTEM - ROCKWELL COLLINS, INC. (ROCKWELL COLLINS) FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500: UPGRADE SOFTWARE, REMOVE AFM/AFMS REVISION AND PLACARD Notes (UPDATE NOTE: COMPLIED WITH AD 2021-05-17, ROCKWELL COLLINS, INC. FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, BY INSPECTION OF THE INSTALLED DISPLAY UNIT PART NUMBERS. AD NOT APPLICABLE BY AFFECTED DISPLAY UNIT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: "WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE FOR YOUR AIRPLANE...AIRPLANE FLIGHT MANUAL REVISION AND PLACARDS REQUIRED BY PARAGRAPH (G)(1) OF THIS AD MAY BE REMOVED AFTER COMPLETING THE SOFTWARE UPGRADE...").COMPLIED WITH AD 2021-05-17, ROCKWELL COLLINS, INC. FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500, BY INSPECTION OF THE INSTALLED DISPLAY UNIT PART N	24-NOV-2021 H: 7198.00 L: 3181					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-07-06 Airframe AD - Complied With FAA #2325	NAVIGATION - AIRPLANE FLIGHT MANUAL (AFM) REVISION	09-APR-2021 H: 6886.60 L: 3007					
	Notes (UPDATE NOTE: COMPLIED WITH AD 2021-07-06 BY INSPECTING AFM FOR REVISION 116 OR LATER. REVISION 120 DATED 12-08-2020 CURRENTLY ON BOARD AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: "WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD: REVISE THE EXISTING AFM...")						
AD 2021-07-13 Airframe AD - N/A FAA #3006	PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475	25-OCT-2021 H: 7130.60 L: 3148					
	Notes (UPDATE NOTE: AD 2021-07-13, PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2021-07-13, PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.						
AD 2021-07-13 AMD Par. (e)(1) Airframe AD - N/A FAA #2115	PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475 - INSPECT THE BUCKLE HANDLE FOR A CRACK	25-OCT-2021 H: 7130.60 L: 3148					
	Notes (UPDATE NOTE: AD 2021-07-13, PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 6 MONTHS, INSPECT THE BUCKLE HANDLE FOR A CRACK. IF THE BUCKLE HANDLE IS CRACKED, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE AS DEPICTED IN FIGURE 5 AND BY FOLLOWING THE PROCEDURES, PARAGRAPH 9, OF SB 25-1111432, AND REPLACE IT WITH AN AIRWORTHY BUCKLE, EXCEPT YOU ARE NOT REQUIRED TO RETURN THE REMOVED BUCKLE TO PACIFIC SCIENTIFIC.).AD 2021-07-13, PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475, NOT APPLICABLE BY AFFECTED PARTS NOT INS						
AD 2021-07-13 AMD Par. (e)(2) Airframe AD - N/A FAA #3642	PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475 - MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE	25-OCT-2021 H: 7130.60 L: 3148					
	Notes (UPDATE NOTE: AD 2021-07-13, PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 12 MONTHS, MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE AS DEPICTED IN FIGURE 3 OF SB 25-1111432. IF THE HANDLE VANE THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE.).AD 2021-07-13, PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY, P/NS 1111430 AND 1111475, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-08-07 Airframe AD - Complied With FAA #2756	NAVIGATION SYSTEM - GPS-4000S GLOBAL POSITIONING SYSTEM Notes (UPDATE NOTE: COMPLIED WITH AD 2021-08-07 BY INSPECTION OF AIRCRAFT RECORDS OF INSTALLED GPS PART NUMBERS. INSTALLED GPS PART NUMBER, 822-0931-003. AFFECTED GPS PART NUMBER NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ROCKWELL COLLINS, INC. GPS-4000S GLOBAL POSITIONING SYSTEM (GPS) PART NUMBER (P/N) 822-2189-100 INSTALLED ON AIRPLANES, CERTIFICATED IN ANY CATEGORY.)	09-APR-2021 H: 6886.60 L: 3007					
AD 2021-08-15 Airframe AD - N/A FAA #338	GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS Notes (UPDATE NOTE: AD 2021-08-15, GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, EFFECTIVE 05-17-2021, NOT APPLICABLE BY AFFECTED PART NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: REQUIRED ACTION AND COMPLIANCE: WITHIN 24 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, UPDATE THE GTS PROCESSOR SOFTWARE TO A VERSION THAT IS NOT 3.13 OR EARLIER, EXCEPT 3.12.1. SOFTWARE VERSION 3.12.1 DOES NOT CONTAIN THE UNSAFE CONDITION.)AD 2021-08-15, GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, EFFECTIVE 05-17-2021, NOT APPLICABLE BY AFFECTED PART NOT INSTALLED. NO FURTHER ACTION NECESSARY.	09-MAY-2023 H: 8044.10 L: 3628					
AD 2021-13-12 Airframe AD - Complied With FAA #3328	TIME LIMITS/MAINTENANCE CHECKS - CORROSION ON THE PASSENGER DOOR INTERNAL STRUCTURE OF IN-SERVICE AIRPLANES - MAINTENANCE OR INSPECTION PROGRAM REVISION Notes (AVG MAN HRS: 90) (UPDATE NOTE: COMPLIED WITH AD 2021-13-12, TIME LIMITS/MAINTENANCE CHECKS - CORROSION ON THE PASSENGER DOOR INTERNAL STRUCTURE OF IN-SERVICE AIRPLANES - MAINTENANCE OR INSPECTION PROGRAM REVISION, BY VERIFYING TASK 53-20-00-188, SPECIAL DETAILED INSPECTION OF THE UPPER LATCH PINS OF THE PASSENGER DOOR, TIME LIMITS ARE INCORPORATED IN THE THE INSPECTION PROGRAM PER CL604 TIME LIMITS/MAINTENANCE CHECKS REVISION 32. PROGRAM TRACKING TASK TO BE DUE AT 7800 LANDINGS. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 30 DAYS AFTER THE EFFECTIVE DATE OF THIS AD: REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE, TO INCORPORATE THE	21-SEP-2021 H: 7063.80 L: 3109					
AD 2021-20-13 Airframe AD - Complied With FAA #423	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN (THIS AD IS SUPERSEDED BY FAA AD 2024-03-06) Notes (UPDATE NOTE: COMPLIED WITH AD 2021-20-13 PAR. (G) AND PAR. (H) LH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN, BY LUBRICATION AND DETAILED VISUAL INSPECTION OF THE MLG SHOCK STRUT LOWER PIN IAW CL604 AMM REVISION 100, TASK 12-20-04-640-802, SB 604-32-030 PART A & PART B AND AD 2021-20-13 PAR. (G) & PAR. (H). PAR (G) NEXT DUE 8330 HOURS OR 12-OCT-2024, WHICHEVER OCCURS FIRST, PAR (H) NEXT DUE 8530 HOURS OR 12-OCT-2025, WHICHEVER OCCURS FIRST, PAR (I) NEXT DUE AT 3934 LANDINGS.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, SERIAL NUMBERS (S/N) 5301 THROUGH 5665 INCLUSIVE, 5701 THROUGH 5988 INCLUSIVE, AND 6050	12-OCT-2023 H: 8130.00 L: 3683					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-20-13 AMD Par. (h) LH Airframe AD - Complied With FAA #1380	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - REPETITIVE DETAILED VISUAL INSPECTIONS (DVI)	12-OCT-2023 H: 8130.00 L: 3683					
Notes (AVG MAN HRS: 9.5) (UPDATE NOTE: COMPLIED WITH AD 2021-20-13 PAR. (H) LH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN, DETAILED VISUAL INSPECTION OF THE MLG SHOCK STRUT LOWER PIN IAW SAFRAN SERVICE BULLETIN NO. SB19090-32-9, SB 604-32-030 PART B AND AD 2021-20-13 PAR. (H). PAR. (G) NEXT DUE 8330 HOURS OR 12-OCT-2024, WHICHEVER OCCURS FIRST, PAR (H) NEXT DUE 8530 HOURS OR 12-OCT-2025, WHICHEVER OCCURS FIRST, PAR (I) NEXT DUE AT 3934 LANDINGS.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR AIRPLANES WITH AN ORIGINAL AIRWORTHINESS CERTIFICATE OR ORIGINAL EXPORT CERTIFICATE OF AIRWORTHINESS ISSUED ON OR BEFORE THE EFFECTIVE DATE OF THIS AD AND ON WHICH AN MLG SHOCK STRUT LOWER PIN HAS ACCUMUL							
AD 2021-20-13 AMD Par. (h) RH Airframe AD - Complied With FAA #2636	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - REPETITIVE DETAILED VISUAL INSPECTIONS (DVI)	12-OCT-2023 H: 8130.00 L: 3683					
Notes (UPDATE NOTE: COMPLIED WITH AD 2021-20-13 PAR. (H) RH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN, DETAILED VISUAL INSPECTION OF THE MLG SHOCK STRUT LOWER PIN IAW SAFRAN SERVICE BULLETIN NO. SB19090-32-9, SB 604-32-030 PART B AND AD 2021-20-13 PAR. (H). PAR. (G) NEXT DUE 8330 HOURS OR 12-OCT-2024, WHICHEVER OCCURS FIRST, PAR (H) NEXT DUE 8530 HOURS OR 12-OCT-2025, WHICHEVER OCCURS FIRST, PAR (I) NEXT DUE AT 3934 LANDINGS.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR AIRPLANES WITH AN ORIGINAL AIRWORTHINESS CERTIFICATE OR ORIGINAL EXPORT CERTIFICATE OF AIRWORTHINESS ISSUED ON OR BEFORE THE EFFECTIVE DATE OF THIS AD AND ON WHICH AN MLG SHOCK STRUT LOWER PIN HAS ACCUMULATED 600 TOTAL FC O							
AD 2021-20-13 AMD Par. (g) LH Airframe AD - Complied With FAA #2653	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - REPETITIVE LUBRICATION	12-MAR-2024 H: 8313.50 L: 3779					
Notes (AVG MAN HRS: 1.5) (APX COST: 80.7) (UPDATE NOTE: COMPLIED WITH DIRECT MX AVIATION SEE WORK ORDER SDL240221) (ISSUING AUTHORITY: FAA)							
AD 2021-20-13 AMD Par. (g) RH Airframe AD - Complied With FAA #364	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - REPETITIVE LUBRICATION	12-MAR-2024 H: 8313.50 L: 3779					
Notes (UPDATE NOTE: COMPLIED WITH DIRECT MX AVIATION SEE WORK ORDER SDL240221) (ISSUING AUTHORITY: FAA)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-20-13 AMD Par. (i) LH Airframe AD - Complied With FAA #529	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - REPETITIVE NDT INSPECTION	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: INITIAL COMPLIANCE COMPLETED BY DUNCAN AVIATION CRS JGVR194F UNDER WORK ORDER FFMBA DATED 02-JUL-2021) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR AIRPLANES WITH AN ORIGINAL AIRWORTHINESS CERTIFICATE OR ORIGINAL EXPORT CERTIFICATE OF AIRWORTHINESS ISSUED ON OR BEFORE THE EFFECTIVE DATE OF THIS AD AND ON WHICH AN MLG SHOCK STRUT LOWER PIN THAT HAS ACCUMULATED 2,000 TOTAL FC OR MORE ON THE PIN AS OF THE EFFECTIVE DATE OF THIS AD: WITHIN 200 FC AFTER THE EFFECTIVE DATE OF THIS AD. PERFORM THE NDT INSPECTION FOR CRACKING AND DAMAGE OF THE LH AND RH MLG SHOCK STRUT LOWER PINS HAVING P/N 19146-3, IN ACCORDANCE WITH PARAGRAPH 2.D., "PART C," OF THE ACCOMPLISHMENT INSTRUCTIONS OF T							
AD 2021-20-13 AMD Par. (i) RH Airframe AD - Complied With FAA #1189	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - REPETITIVE NDT INSPECTION	02-JUL-2021 H: 6939.60 L: 3034					
Notes (UPDATE NOTE: COMPLIED WITH AD 2021-20-13 PAR. (G) LH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN, BY LUBRICATION OF THE MLG SHOCK STRUT LOWER PIN IAW CL604 AMM REVISION 96 TASK 12-20-04-640-802, SB 604-32-030 PART A AND AD 2021-20-13 PAR. (G). PAR. (G) NEXT DUE 8199.5 HOURS OR 04-APR-2024, WHICHEVER OCCURS FIRST, PAR (H) NEXT DUE 8399.5 HOURS OR 01-NOV-2024, WHICHEVER OCCURS FIRST, PAR (I) NEXT DUE AT 3934 LANDINGS.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR AIRPLANES WITH AN ORIGINAL AIRWORTHINESS CERTIFICATE OR ORIGINAL EXPORT CERTIFICATE OF AIRWORTHINESS ISSUED ON OR BEFORE THE EFFECTIVE DATE OF THIS AD AND ON WHICH AN MLG SHOCK STRUT LOWER PIN THAT HAS ACCUMULATED 2,000 TOTAL FC							
AD 2021-22-07 Airframe AD - N/A FAA #1342	FIRE PROTECTION - IMPAIRED FIRE EXTINGUISHER	24-NOV-2021 H: 7198.00 L: 3181					
Notes (UPDATE NOTE: COMPLIED WITH AD 2021-22-07, IMPAIRED FIRE EXTINGUISHER, BY INSPECTION OF THE INSTALLED PORTABLE FIRE EXTINGUISHERS. AD NOT APPLICABLE BY AFFECTED FIRE EXTINGUISHERS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).COMPLIED WITH AD 2021-22-07, IMPAIRED FIRE EXTINGUISHER, BY INSPECTION OF THE INSTALLED PORTABLE FIRE EXTINGUISHERS. AD NOT APPLICABLE BY AFFECTED FIRE EXTINGUISHERS NOT INSTALLED. NO FURTHER ACTION NECESSARY.							
AD 2021-23-12 Airframe AD - Complied With FAA #3469	INDICATING/RECORDING SYSTEM, NAVIGATION - RADIO ALTIMETER (TRANSPORT AND COMMUTER CATEGORY AIRPLANES) (THIS AD IS SUPERSEDED BY FAA AD 2023-10-02)	28-DEC-2021 H: 7285.70 L: 3229					
Notes (UPDATE NOTE: COMPLIED WITH AD 2021-23-12, RADIO ALTIMETER (TRANSPORT AND COMMUTER CATEGORY AIRPLANES, BY INSERTING A COPY OF THE AIRWORTHINESS DIRECTIVE INTO THE AIRCRAFT FLIGHT MANUAL SUPPLEMENT SECTION. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: ON OR BEFORE JANUARY 4, 2022: REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM BY INCORPORATING THE LIMITATIONS SPECIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD. THIS MAY BE DONE BY INSERTING A COPY OF THIS AD INTO THE EXISTING AFM.).COMPLIED WITH AD 2021-23-12, RADIO ALTIMETER (TRANSPORT AND COMMUTER CATEGORY AIRPLANES, BY INSERTING A COPY OF THE AIRWORTHINESS DIRECTIVE INTO THE AIRCRAFT FLIGHT MANUAL SUPPLEMENT							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-25-13 Airframe AD - Complied With FAA #74	TIME LIMITS/MAINTENANCE CHECKS - CIRCUMFERENTIAL SPLICE JOINT Notes (UPDATE NOTE: COMPLIED WITH FAA AD 2021-25-13 "TIME LIMITS/MAINTENANCE CHECKS - CIRCUMFERENTIAL SPLICE JOINT" BY INCORPORATING THE INFORMATION SPECIFIED IN FIGURE 1 TO PARAGRAPH(G) OF THIS AD INTO THE APPLICABLE INSPECTION PROGRAM. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE, TO INCORPORATE THE INFORMATION SPECIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD. THE INITIAL COMPLIANCE TIME FOR DOING THE TASKS IS AT THE TIME SPECIFIED IN THE APPLICABLE DOCUMENT SPECIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD, OR WITHIN 60 DAYS AFTER THE EFFECTIVE D	06-APR-2022 H: 7470.80 L: 3326					
AD 2021-26-23 AMD Par. (h) Airframe AD - N/A FAA #1176	FUEL - FUEL LEAKS FROM ELECTRICAL CONNECTORS AND CONDUITS OF THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER: RETAINED ACTIONS FOR CERTAIN OTHER AIRPLANES, WITH REVISED SERVICE INFORMATION AND COMPLIANCE METHOD PROVISIONS Notes (UPDATE NOTE: NA PER AIRCRAFT SN ON JET EAST CRS VYQR491Y ON WO DALM-21906) (ISSUING AUTHORITY: FAA)	25-APR-2022 H: 7477.20 L: 3329					
AD 2021-26-23 Airframe AD - Complied With FAA #1424	FUEL - FUEL LEAKS FROM ELECTRICAL CONNECTORS AND CONDUITS OF THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER Notes (UPDATE NOTE: WORK PERFORMED BY WEST STAR AVIATION CRS# 4W5R536D UNDER WO 20820 - COMPLIED WITH PARA (J) - MOC: INCORPORATED SB 604-28-024 R1 - PER PARA (L), COMPLIANCE WITH PARA (J) OF THIS AD TERMINATES ALL REQUIREMENTS OF THIS AD) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., MODEL CL-600-2B16 (601-3A, 601-3R, AND 604 VARIANTS) AIRPLANES, CERTIFICATED IN ANY CATEGORY, SERIAL NUMBERS 5301 THROUGH 5665 INCLUSIVE, 5701 THROUGH 5990 INCLUSIVE, AND 6050 THROUGH 6163 INCLUSIVE.) ENGINE AND APU FUEL BOOST PUMP SEALING IMPROVEMENT - COMPLIED WITH PARA (J) - MOC: INCORPORATED SB 604-28-024 R1 - PER PARA (L), COMPLIANCE WITH PARA (J) OF THIS AD TERMINATES ALL R	08-FEB-2023 H: 7925.20 L: 3563					
AD 2021-26-23 AMD Par. (j) Airframe AD - Complied With FAA #1874	FUEL - FUEL LEAKS FROM ELECTRICAL CONNECTORS AND CONDUITS OF THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER: NEW REQUIREMENTS OF THIS AD: INSPECTION AND MODIFICATION Notes (UPDATE NOTE: INCORPORATED SB 604-28-024 R1 WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD: DO A DETAILED VISUAL INSPECTION OF THE APU FOR ANY DAMAGE OR DEFORMATIONS, AND MODIFY THE ENGINE EFP INSTALLATION, IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE INFORMATION SPECIFIED IN FIGURE 2 TO PARAGRAPH (J) OF THIS AD. IF ANY DAMAGE OR DEFORMATIONS ARE FOUND DURING THE DETAILED VISUAL INSPECTION, BEFORE FURTHER FLIGHT, DO THE REPAIR IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE INFORMATION SPECIFIED IN FIGURE 2 TO PARAGRA	08-FEB-2023 H: 7925.20 L: 3563					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2021-26-23 AMD Par. (i) Airframe AD - N/A FAA #1673	FUEL - FUEL LEAKS FROM ELECTRICAL CONNECTORS AND CONDUITS OF THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER: NEW REQUIREMENTS OF THIS AD: INSPECTIONS AND RECTIFICATIONS	25-APR-2022 H: 7477.20 L: 3329					
	Notes (UPDATE NOTE: NA DUE TO AIRCRAFT SN ON JET EAST CRS VYQR491Y ON WO DALM-21906) (ISSUING AUTHORITY: FAA)						
AD 2021-26-23 AMD Par. (g) Airframe AD - Complied With FAA #1143	FUEL - FUEL LEAKS FROM ELECTRICAL CONNECTORS AND CONDUITS OF THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER: RETAINED ACTIONS FOR CERTAIN AIRPLANES, WITH REVISED SERVICE INFORMATION AND METHOD OF COMPLIANCE PROVISIONS	25-APR-2022 H: 7477.20 L: 3329					
	Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906) (ISSUING AUTHORITY: FAA)						
AD 2021-26-23 AMD Par. (l) Airframe AD - Complied With FAA #481	FUEL - FUEL LEAKS FROM ELECTRICAL CONNECTORS AND CONDUITS OF THE ENGINE AND AUXILIARY POWER UNIT (APU) ELECTRICAL FUEL PUMP (EFP) CARTRIDGE/CANISTER: TERMINATING ACTIONS	08-FEB-2023 H: 7925.20 L: 3563					
	Notes (UPDATE NOTE: INCORPORATED SB 604-28-024 R1 WORK PERFORMED BY WEST STAR AVIATION CRS 4W5R536D ON WO 20820.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: ACCOMPLISHING THE ACTIONS REQUIRED BY PARAGRAPH (J) OF THIS AD TERMINATES ALL REQUIREMENTS OF THIS AD.)ENGINE AND APU FUEL BOOST PUMP SEALING IMPROVEMENT - COMPLIED WITH PARA (J) - MOC: INCORPORATED SB 604-28-024 R1 - PER PARA (L), COMPLIANCE WITH PARA (J) OF THIS AD TERMINATES ALL REQUIREMENTS OF THIS AD.						
AD 2022-01-03 Airframe AD - N/A FAA #1034	FIRE BOTTLE, PORTABLE - HAFEX (HALON-FREE) HAND-HELD P3HAFEX FIRE EXTINGUISHER	03-MAR-2023 H: 7948.90 L: 3579					
	Notes (UPDATE NOTE: AD 2022-01-03, HAFEX (HALON-FREE) HAND-HELD P3HAFEX FIRE EXTINGUISHER, EFFECTIVE 07-MAR-2022, NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: REQUIRED ACTIONS: (1) WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, REMOVE EACH FIRE EXTINGUISHER IDENTIFIED IN THE INTRODUCTORY TEXT OF PARAGRAPH (C) FROM SERVICE.)AD 2022-01-03, HAFEX (HALON-FREE) HAND-HELD P3HAFEX FIRE EXTINGUISHER, EFFECTIVE 07-MAR-2022, NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2022-04-09 Airframe AD - N/A FAA #27	VALVE ASSEMBLY VENT - AVOX SYSTEMS INC. OXYGEN CYLINDER AND VALVE ASSEMBLIES (SUPERSEDED BY FAA AD 2023-13-11) Notes (UPDATE NOTE: AD 2022-04-09, VALVE ASSEMBLY VENT - AVOX SYSTEMS INC. OXYGEN CYLINDER AND VALVE ASSEMBLIES, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF THE SERIAL NUMBERS OF THE VALVE, CYLINDER, AND ENTIRE ASSEMBLY, ARE LISTED IN APPENDIX 1, "AFFECTED SHIPMENTS," OF THE APPLICABLE SERVICE INFORMATION IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (3) OF THIS AD. A REVIEW OF AIRPLANE MAINTENANCE RECORDS IS ACCEPTABLE IN LIEU OF THIS INSPECTION IF THE SERIAL NUMBERS CAN BE CONCLUS	13-MAY-2022 H: 7519.50 L: 3350					
AD 2022-09-01 Airframe AD - Open FAA #91	ICE AND RAIN PROTECTION, POTABLE WATER SYSTEM: INSPECTION OF POTABLE WATER-LINE RIBBON HEATER INSTALLATION AND INSULATION Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., AIRPLANES CERTIFICATED IN ANY CATEGORY, IDENTIFIED IN PARAGRAPHS (C)(1) THROUGH (3) OF THIS AD AND EQUIPPED WITH ANY COX & CO. 3043 OR 3044 SERIES (POTABLE WATER-LINE) RIBBON HEATER. (1) MODEL CL-600-1A11 (600) AIRPLANES. (2) MODEL CL-600-2A12 (601) AIRPLANES. (3) MODEL CL-600-2B16 (601-3A, 601-3R, AND 604 VARIANTS) AIRPLANES.)		M: 6			31-MAY-2028	M: 23 D: 30
AD 2022-10-10 Airframe AD - Complied With FAA #2558	ICE AND RAIN PROTECTION - AIRPLANE FLIGHT MANUAL (AFM) REVISION - LIMITATIONS AND PROCEDURES FOR THE WING ANTI-ICE (WAI) SYSTEM Notes (UPDATE NOTE: COMPLIED WITH AD 2022-10-10, AIRPLANE FLIGHT MANUAL (AFM) REVISION - LIMITATIONS AND PROCEDURES FOR THE WING ANTI-ICE (WAI) SYSTEM, BY VERIFYING AFM REVISION 116 OR LATER IS ON BOARD AIRCRAFT. CURRENTLY INSTALLED REVISION IS 127 DATED JUN 24/22. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD.)COMPLIED WITH AD 2022-10-10, AIRPLANE FLIGHT MANUAL (AFM) REVISION - LIMITATIONS AND PROCEDURES FOR THE WING ANTI-ICE (WAI) SYSTEM, BY VERIFYING AFM REVISION 116 OR LATER IS ON BOARD AIRCRAFT. CURRENTLY INSTALLED REVISION IS 127 DATED JUN 24/22. NO FURTHER ACTION NECESSARY.	25-AUG-2022 H: 7715.60 L: 3455					
AD 2022-15-08 Airframe AD - N/A FAA #1065	INFORMATION SYSTEMS - ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE - MODIFICATION Notes (UPDATE NOTE: AD 2022-15-08, ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE - MODIFICATION, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: "WITHIN 12 MONTHS. PLEASE REFER TO FAA AD 2022-15-08 PAR. (H) FOR EFFECTIVE DATE AND COMPLIANCE.")AD 2022-15-08, ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE - MODIFICATION, NOT APPLICABLE BY AFFECTED PARTS NOT INSTALLED. NO FURTHER ACTION NECESSARY.	19-JUL-2023 H: 8087.10 L: 3657					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2022-20-05 Airframe AD - Open FAA #2284	FLIGHT CONTROLS - RUDDER PCU LOAD LIMITERS Notes (ISSUING AUTHORITY: FAA)						
AD 2022-20-05 AMD Par. (g)(1)(2) Airframe AD - Open FAA #3123	FLIGHT CONTROLS - RUDDER PCU LOAD LIMITERS - INSPECTION AND REPLACEMENT FOR CERTAIN AIRPLANES Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR MODEL CL-600-2B16 AIRPLANES HAVING S/NS 5301 THROUGH 5665 INCLUSIVE: INSPECT WITHIN 2,200 FLIGHT HOURS AFTER THE EFFECTIVE DATE OF THIS AD.)		H: 2200.00			H: 10062.10	H: 1367.00
AD 2023-06-02 Airframe AD - Complied With FAA #2296	EQUIPMENT/FURNISHINGS - SMOKE HOOD (P/N MR-10008N) Notes (UPDATE NOTE: COMPLIED WITH AD 2023-06-02 REVISION ORIGINAL, AMENDMENT 39-22388 EFFECTIVE 18 MAY 2023 BY INSPECTION, NO PART NUMBER MR-10008N SMOKE HOODS ARE INSTALLED IN THE AIRCRAFT, THIS IS A TERMINATING ACTION.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ALL BOMBARDIER, INC., AIRPLANES, CERTIFICATED IN ANY CATEGORY, AS IDENTIFIED IN PARAGRAPHS (C)(1) THROUGH (3) OF THIS AD. (1) MODEL CL-600-1A11 (600) AIRPLANES. (2) MODEL CL-600-2A12 (601) AIRPLANES. (3) MODEL CL-600-2B16 (601-3A, 601-3R, AND 604 VARIANTS) AIRPLANES.)		20-MAY-2024 H: 8412.90 L: 3840				
AD 2023-06-02 AMD Par. (h) Airframe AD - N/A FAA #1298	EQUIPMENT/FURNISHINGS - SMOKE HOOD (P/N MR-10008N) - CORRECTIVE ACTION/REMOVAL Notes (UPDATE NOTE: AD 2023-06-02 REVISION ORIGINAL, AMENDMENT 39-22388 EFFECTIVE 18 MAY 2023 PARAGRAPH (H) NOT APPLICABLE, NO PART NUMBER MR-10008N SMOKE HOODS ARE INSTALLED IN THE AIRCRAFT, THIS IS A TERMINATING ACTION.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF, DURING THE INSPECTION OR RECORDS REVIEW REQUIRED BY PARAGRAPH (G) OF THIS AD, ANY SMOKE HOOD HAVING P/N MR-10008N IS FOUND ON THE AIRPLANE, WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, REMOVE THE SMOKE HOOD, INCLUDING ANY ASSOCIATED PLACARDS, AND INSTALL A NEW PLACARD, IN ACCORDANCE WITH SECTION 2.B. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE BOMBARDIER SERVICE BULLETIN SPECIFIED IN PARAGRAPHS (H)(1) THROUGH (5)		20-MAY-2024 H: 8412.90 L: 3840				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-06-02 AMD Par. (g) Airframe AD - Complied With FAA #2045	EQUIPMENT/FURNISHINGS - SMOKE HOOD (P/N MR-10008N) - INSPECTION Notes (UPDATE NOTE: COMPLIED WITH AD 2023-06-02 REVISION ORIGINAL, AMENDMENT 39-22388 EFFECTIVE 18 MAY 2023 BY INSPECTION, NO PART NUMBER MR-10008N SMOKE HOODS ARE INSTALLED IN THE AIRCRAFT, THIS IS A TERMINATING ACTION.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD: DO AN INSPECTION TO DETERMINE IF ANY SMOKE HOOD HAVING PART NUMBER (P/N) MR-10008N IS INSTALLED IN THE FLIGHT DECK, FORWARD WARDROBE, OR ANY OTHER LOCATION IN THE AIRPLANE. A REVIEW OF AIRPLANE MAINTENANCE RECORDS IS ACCEPTABLE IN LIEU OF THIS INSPECTION IF THE PART NUMBER OF THE SMOKE HOOD CAN BE CONCLUSIVELY DETERMINED FROM THAT REVIEW.)	20-MAY-2024 H: 8412.90 L: 3840					
AD 2023-06-04 Airframe AD - Open FAA #2918	OXYGEN SYSTEM - PASSENGER OXYGEN MASK DISPENSING UNITS (MDUS) - INSPECTION AND REPLACEMENT Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., AIRPLANES, CERTIFICATED IN ANY CATEGORY, WITH SERIAL NUMBERS AS IDENTIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAGRAPHS (C)(1) THROUGH (4) OF THIS AD. (1) MODEL CL-600-1A11 (600) AIRPLANES: BOMBARDIER SERVICE BULLETIN 600-0777, DATED DECEMBER 13, 2021. (2) MODEL CL-600-2A12 (601) AIRPLANES: BOMBARDIER SERVICE BULLETIN 601-1109, REVISION 01, DATED MAY 6, 2022. (3) MODEL CL-600-2B16 (601-3A, 601-3R) AIRPLANES: BOMBARDIER SERVICE BULLETIN 601-1109, REVISION 01, DATED MAY 6, 2022. (4) MODEL CL-600-2B16 (604) AIRPLANES: BOMBARDIER SERVICE BULLETIN 604-35-007, REVISION 01, DATED MAY 6, 2022. COMPLIANCE: WITHI		M: 60			18-MAY-2028	M: 23 D: 17
AD 2023-07-04 Airframe AD - Complied With FAA #3084	AUTO FLIGHT - REVISION OF EXISTING AIRPLANE FLIGHT MANUAL (AFM) Notes (UPDATE NOTE: COMPLIED WITH AD 2023-07-04, REVISION OF EXISTING AIRPLANE FLIGHT MANUAL (AFM), EFFECTIVE 05-30-2023, BY VERIFYING AFM IS REVISION 120 OR LATER. REVISION 130 DATED APR 21/23 INSTALLED ON AIRCRAFT. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, CERTIFICATED IN ANY CATEGORY, SERIAL NUMBERS (S/N) 5301 THROUGH 5665 INCLUSIVE, 5701 THROUGH 5988 INCLUSIVE, AND 6050 THROUGH 6160 INCLUSIVE. COMPLIANCE: WITHIN 30 DAYS AFTER THE EFFECTIVE DATE OF THIS AD: DO THE APPLICABLE ACTIONS SPECIFIED IN PARAGRAPH (G) (1) THROUGH (3) OF THIS AD.).COMPLIED WITH AD 2023-07-04, REVISION OF EXI	09-MAY-2023 H: 8044.10 L: 3628					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-10-02 Airframe AD - Complied With FAA #25	NAVIGATION - RADIO ALTIMETERS (THIS AD REPLACES AD 2021-23-12) Notes (UPDATE NOTE: COMPLIED WITH AD 2023-10-02, RADIO ALTIMETERS (THIS AD REPLACES AD 2021-23-12), BY UPDATING ONBOARD ELECTRONIC BOMBARDIER FLIGHTDECK APPLICATION. THE CURRENT UPDATE PLACES A COPY OF THE AD IN THE SUPPORTING DOCUMENTATION OF THE ELECTRONIC AFM AND A HYPERLINK IS PROVIDED IN THE AFM LIMITATIONS SECTION TO ACCESS THE CONTENT OF THE AD, PER BOMBARDIER ADVISORY WIRE AW000-34-0010, REV. 06. FLIGHT CREWS HAVE BEEN MADE AWARE OF THE CONTENT AND AVAILABILITY OF THE AD IN THE AFM. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ALL TRANSPORT AND COMMUTER CATEGORY AIRPLANES EQUIPPED WITH A RADIO (ALSO KNOWN AS RADAR) ALTIMETER. THESE RADIO A	30-JUN-2023 H: 8075.40 L: 3647					
AD 2023-10-02 AMD Par. (i) Airframe AD - Complied With FAA #1101	NAVIGATION - RADIO ALTIMETERS - AFM REVISION AFTER JUNE 30, 2023 Notes (UPDATE NOTE: COMPLIED WITH AD 2023-10-02, RADIO ALTIMETERS (THIS AD REPLACES AD 2021-23-12), BY UPDATING ONBOARD ELECTRONIC BOMBARDIER FLIGHTDECK APPLICATION. THE CURRENT UPDATE PLACES A COPY OF THE AD IN THE SUPPORTING DOCUMENTATION OF THE ELECTRONIC AFM AND A HYPERLINK IS PROVIDED IN THE AFM LIMITATIONS SECTION TO ACCESS THE CONTENT OF THE AD, PER BOMBARDIER ADVISORY WIRE AW000-34-0010, REV. 06. FLIGHT CREWS HAVE BEEN MADE AWARE OF THE CONTENT AND AVAILABILITY OF THE AD IN THE AFM. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: ON OR BEFORE JUNE 30, 2023, REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 4 TO PARAG	30-JUN-2023 H: 8075.40 L: 3647					
AD 2023-10-02 AMD Par. (h) Airframe AD - Complied With FAA #3341	NAVIGATION - RADIO ALTIMETERS - AIRPLANE FLIGHT MANUAL (AFM) REVISION UNTIL JUNE 30, 2023 Notes (UPDATE NOTE: COMPLIED WITH AD 2023-10-02 PAR. (H), RADIO ALTIMETERS - AIRPLANE FLIGHT MANUAL (AFM) REVISION UNTIL JUNE 30, 2023, EFFECTIVE 26-MAY-2023, BY VERIFYING TEMPORARY REVISION TR 604/46 IS INCORPORATED IN THE AFM AND ONBOARD THE AIRCRAFT. TEMPORARY REVISION TR 604/46 INCORPORATES THE LIMITATIONS SPECIFIED IN AD2023-10-02 PAR. (H) IN THE SYSTEMS LIMITATIONS SECTION. AD 2023-10-02 PAR. (I) DUE 30-JUN-2023.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR NON-RADIO ALTIMETER TOLERANT AIRPLANES, BEFORE FURTHER FLIGHT, REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 3 TO PARAGRAPH (H) OF THIS AD. THIS MAY BE DONE BY INSERTING A COPY OF FI	30-MAY-2023 H: 8061.40 L: 3637					
AD 2023-10-02 AMD Par. (j) Airframe AD - Open FAA #2170	NAVIGATION - RADIO ALTIMETERS - TERMINATING ACTION FOR AFM LIMITATIONS Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: MODIFYING THE AIRPLANE FROM A NON-RADIO ALTIMETER TOLERANT AIRPLANE TO A RADIO ALTIMETER TOLERANT AIRPLANE TERMINATES THE LIMITATIONS IN PARAGRAPH (I) OF THIS AD FOR THAT AIRPLANE. AFTER MODIFYING THE AIRPLANE TO A RADIO ALTIMETER TOLERANT AIRPLANE, THE LIMITATIONS SPECIFIED BY PARAGRAPH (I) OF THIS AD MAY BE REMOVED FROM THE AFM.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-12-25 Airframe AD - N/A FAA #3279	EQUIPMENT/FURNISHINGS - SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) TYPE 102 MK 3, 102 MK 4, AND 105 MK 1 LIFE JACKETS	12-OCT-2023 H: 8130.00 L: 3683					
Notes (UPDATE NOTE: AD 2023-12-25 SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) TYPE 102 MK 3, 102 MK 4, AND 105 MK 1 LIFE JACKETS. THIS AD IS NOT APPLICABLE DUE TO PART NUMBER LISTED NOT INSTALLED. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) LIFE JACKETS IDENTIFIED IN PARAGRAPHS (C) (1) AND (2) OF THIS AD, HAVING A PART NUMBER AND SERIAL NUMBER IDENTIFIED IN TABLES 2 THROUGH 13 OF SURVITEC [RFD] ALERT SERVICE BULLETIN 25-207-A, VERSION 1, DATED NOVEMBER 24, 2021, AND A DATE OF MANUFACTURE BETWEEN OCTOBER 1, 2018, AND APRIL 30, 2019, INCLUSIVE.).AD 2023-12-25 SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) TYPE 1							
AD 2023-12-25 AMD Par. (h) Airframe AD - Open FAA #3336	EQUIPMENT/FURNISHINGS - SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) TYPE 102 MK 3, 102 MK 4, AND 105 MK 1 LIFE JACKETS - FOLLOW-ON AND CORRECTIVE ACTION						
Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: BEFORE FURTHER FLIGHT AFTER ACCOMPLISHING THE REQUIREMENTS OF PARAGRAPH (G) OF THIS AD, DO THE APPLICABLE ACTIONS REQUIRED BY PARAGRAPH (H)(1) AND (2) OF THIS AD.)							
AD 2023-12-25 AMD Par. (g) Airframe AD - N/A FAA #1326	EQUIPMENT/FURNISHINGS - SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) TYPE 102 MK 3, 102 MK 4, AND 105 MK 1 LIFE JACKETS - INSPECTION	12-OCT-2023 H: 8130.00 L: 3683					
Notes (AVG MAN HRS: 2) (UPDATE NOTE: AD 2023-12-25 SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.) TYPE 102 MK 3, 102 MK 4, AND 105 MK 1 LIFE JACKETS. THIS AD IS NOT APPLICABLE DUE TO PART NUMBER LISTED NOT INSTALLED. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 4 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, DO A GENERAL VISUAL INSPECTION FOR A DISCREPANCY (MISMATCH OF THE VALISE/CONTAINER DESCRIPTION AND LIFE JACKET TYPE) OF THE LIFE JACKET, IN ACCORDANCE WITH PARAGRAPHS 2.A. THROUGH 2.C. OF THE ACCOMPLISHMENT INSTRUCTIONS OF SURVITEC [RFD] ALERT SERVICE BULLETIN 25-207-A, VERSION 1, DATED NOVEMBER 24, 2021.).AD 2023-12-25 SURVITEC GROUP LIMITED (RFD BEAUFORT LTD.)							
AD 2023-13-11 Airframe AD - N/A FAA #2644	OXYGEN - AVOX SYSTEMS INC. (FORMERLY SCOTT AVIATION) OXYGEN CYLINDER AND VALVE ASSEMBLIES (SUPERSEDES FAA AD 2022-04-09) (THIS AD IS SUPERSEDED BY AD 2024-19-15)	24-AUG-2023 H: 8098.80 L: 3663					
Notes (UPDATE NOTE: AD 2023-13-11, AVOX SYSTEMS INC. (FORMERLY SCOTT AVIATION) OXYGEN CYLINDER AND VALVE ASSEMBLIES (SUPERSEDES FAA AD 2022-04-09), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO AVOX SYSTEMS INC. (FORMERLY SCOTT AVIATION) OXYGEN CYLINDER AND VALVE ASSEMBLIES HAVING PART NUMBER (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, OR 891311-14; AND OXYGEN VALVE ASSEMBLIES (BODY AND GAGE ASSEMBLIES) HAVING P/N 807206-01. THESE ASSEMBLIES MIGHT BE INSTALLED ON, BUT NOT LIMITED TO, THE AIRCRAFT IDENTIFIED IN PARAGRAPHS (C)(1) THROUGH (12) OF THIS AD, CERTIFICATED IN ANY							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-14-10 Airframe AD - N/A FAA #2269	FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06)	24-AUG-2023 H: 8098.80 L: 3663					
Notes (UPDATE NOTE: AD 2023-14-10, IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO: (I) IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS WITH A PART NUMBER (P/N) LISTED IN PARAGRAPH 1.A., PLANNING INFORMATION, TABLES 1 AND 2, OF IPECO SERVICE BULLETIN (SB) NUMBER 063-25-14, REVISION 00, DATED AUGUST 14, 2018, AND (II) IPECO PILOT SEAT P/N 3A063-0099-01-1 AND IPECO CO-PILOT SEAT P/N 3A063-0100-01-1. (2) THESE SEATS ARE INSTALLED ON, BUT NOT LIMITED TO, ATR-GIE AVIONS DE TRANSPORT REGIONAL ATR 42 AND ATR							
AD 2023-14-10 AMD Par. (g)(2)(i) Airframe AD - N/A FAA #528	FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - INSPECT THE TRACK LOCK SPRING OF EACH SEAT	24-AUG-2023 H: 8098.80 L: 3663					
Notes (UPDATE NOTE: AD 2023-14-10, IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2023-14-10, IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.							
AD 2023-14-10 AMD Par. (g)(1) Airframe AD - N/A FAA #1835	FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT	24-AUG-2023 H: 8098.80 L: 3663					
Notes (UPDATE NOTE: AD 2023-14-10, IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR SEATS THAT HAVE NOT INSTALLED THE TRACK LOCK SPRING MODIFICATION KIT, WITHIN TWO YEARS AFTER DECEMBER 12, 2017 (THE EFFECTIVE DATE OF AD 2017-22-02, AMENDMENT 39-19082 (82 FR 51552, NOVEMBER 7, 2017)), MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT USING THE ACCOMPLISHMENT INSTRUCTIONS OF IPECO SB NUMBER 063-25-08, REVISION 00; IPECO SB NUMBER 063-25-09, REVISION 00; OR IPECO SB NUMBER 063-25-10, REVISION 00; ALL DATED MAY 31, 2016, AS							
AD 2023-14-10 AMD Par. (h) Airframe AD - N/A FAA #294	FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - NEW MANDATORY TERMINATING ACTION	24-AUG-2023 H: 8098.80 L: 3663					
Notes (UPDATE NOTE: AD 2023-14-10, IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: AS A MANDATORY TERMINATING ACTION TO THE INSPECTIONS REQUIRED BY PARAGRAPH (G)(2)(I) OF THIS AD, WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, OR AT THE NEXT BASE MAINTENANCE CHECK, WHICHEVER OCCURS LATER, MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF IPECO SB NUMBER 063-25-15, ISSUE 2; SB NUMBER 063-25-16, ISSUE 2; SB NUMBER 063-25-17, ISSUE 2; OR SB NUMBER 063-25-18, ISSUE 2; ALL DATED MARCH 8,							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-14-10 AMD Par. (g)(2)(ii) Airframe AD - N/A FAA #575	FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - REPLACE BOTH TRACK LOCK SPRINGS OF THE AFFECTED SEAT	24-AUG-2023 H: 8098.80 L: 3663					
	Notes (UPDATE NOTE: AD 2023-14-10, IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS (SUPERSEDES FAA AD 2019-21-06), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF, DURING ANY INSPECTION AS REQUIRED BY PARAGRAPH (G)(2)(I) OF THIS AD, ANY DAMAGE ON, OR INCORRECT INSTALLATION OF, ANY TRACK LOCK SPRING IS FOUND ON THE PILOT OR CO-PILOT SEAT, BEFORE FURTHER FLIGHT, REPLACE BOTH TRACK LOCK SPRINGS OF THE AFFECTED SEAT WITH A PART ELIGIBLE FOR INSTALLATION USING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 3.3.3.1 OR 3.3.3.2, AS APPLICABLE, OF IPECO SB NUMBER 063-25-14, REVISION 00, DATED AUGUST 14, 2018.).AD 2023-14-1						
AD 2023-17-06 Airframe AD - Recurring FAA #2668	FLIGHT CONTROLS - FLAP CONTROL SYSTEM - INITIAL OPERATIONAL TEST / REPETITIVE OPERATIONAL TESTS	31-MAY-2025 H: 8649.70 L: 3986	H: 400.00			H: 9049.70	H: 354.60
	Notes (AVG MAN HRS: 2) (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 100 FLIGHT HOURS OR 15 MONTHS, WHICHEVER OCCURS FIRST AFTER THE EFFECTIVE DATE OF THIS AD, PERFORM AN INITIAL OPERATIONAL TEST OF THE INBOARD AND OUTBOARD FLAPS, AND ALL APPLICABLE CORRECTIVE ACTIONS, IN ACCORDANCE WITH SECTION 2.B. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE INFORMATION IDENTIFIED IN PARAGRAPHS (G)(1) THROUGH (5) OF THIS AD. CORRECTIVE ACTIONS MUST BE DONE BEFORE FURTHER FLIGHT AFTER THE TEST. REPEAT THE TEST AT INTERVALS NOT TO EXCEED 400 FLIGHT HOURS.).AD 2023-17-06 EFFECTIVE DATE 19 OCT 2023 INITIAL OPE						
AD 2023-21-05 Airframe AD - N/A FAA #132	NAVIGATION - THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM)	15-NOV-2023 H: 8167.00 L: 3699					
	Notes (UPDATE NOTE: AD 2023-21-05, THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA).AD 2023-21-05, THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.						
AD 2023-21-05 AMD Par. (g)(1) Airframe AD - N/A FAA #814	NAVIGATION - THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM) - REVISE THE LIMITATIONS SECTION OF THE EXISTING AIRPLANE FLIGHT MANUAL	15-NOV-2023 H: 8167.00 L: 3699					
	Notes (UPDATE NOTE: AD 2023-21-05, THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM), PART NUMBER (P/N) C13084CA03, INSTALLED ON, BUT NOT LIMITED TO AIRPLANES, CERTIFICATED IN ANY CATEGORY. COMPLIANCE: WITHIN 30 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, REVISE THE LIMITATIONS SECTION OF THE EXISTING AIRPLANE FLIGHT MANUAL (AFM) FOR YOUR AIRPLANE BY ADDING THE INFORMATION IN TABLE 1 TO THE INTRODUCTORY TEXT OF PARAGRAPH (G)(1) OF THIS AD AND TA						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-21-05 AMD Par. (g)(2) Airframe AD - N/A FAA #687	NAVIGATION - THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM) - UPDATE THE DATABASE FOR THALES FMC2 NAVM - P/N C13084CA03 Notes (UPDATE NOTE: AD 2023-21-05, THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM), NOT APPLICABLE BY AFFECTED EQUIPMENT NOT INSTALLED. NO FURTHER ACTION NECESSARY.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO THALES AVS FRANCE SAS FLIGHT MANAGEMENT COMPUTER NAVIGATION MODULES (FMC2 NAVM), PART NUMBER (P/N) C13084CA03, INSTALLED ON, BUT NOT LIMITED TO AIRPLANES, CERTIFICATED IN ANY CATEGORY. COMPLIANCE: WITHIN 30 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, UPDATE THE DATABASE FOR YOUR THALES FMC2 NAVM, P/N C13084CA03, WITH A DATABASE THAT DOES NOT CONTAIN THE PROCEDURES SPECIFIED IN SECTION II OF THALES SERVICE INFORMATION LETTER F9111-J70859DN-0	15-NOV-2023 H: 8167.00 L: 3699					
AD 2023-22-16 Airframe AD - Open FAA #862	PNEUMATIC - SENSING ELEMENTS OF THE BLEED AIR LEAK DETECTION SYSTEM - TESTING Notes (ISSUING AUTHORITY: FAA)						
AD 2023-24-05 Airframe AD - Open FAA #1407	OXYGEN SYSTEM - OXYGEN MASK LANYARDS Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, CERTIFICATED IN ANY CATEGORY, SERIAL NUMBERS IDENTIFIED IN BOMBARDIER SERVICE BULLETIN 605-35-008, DATED OCTOBER 28, 2022. COMPLIANCE: WITHIN 48 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, VISUALLY INSPECT THE PASSENGER OXYGEN MASK LANYARDS IN THE CABIN OR LAVATORY OXYGEN BOX ASSEMBLIES AS APPLICABLE FOR CRIMPED LANYARDS AND SEALED ENDS, IN ACCORDANCE WITH PARAGRAPH 2.C. OF THE ACCOMPLISHMENT INSTRUCTIONS OF BOMBARDIER SERVICE BULLETIN 605-35-008, DATED OCTOBER 28, 2022.)		M: 48			22-JAN-2028	M: 19 D: 21
AD 2023-25-13 Airframe AD - N/A FAA #1979	OXYGEN - PORTABLE PROTECTIVE BREATHING EQUIPMENT (PBE) DEVICE - VISUAL INSPECTION Notes (AVG MAN HRS: 2) (UPDATE NOTE: C/W AD 2023-25-13 OXYGEN - PORTABLE PROTECTIVE BREATHING EQUIPMENT (PBE) DEVICE - VISUAL INSPECTION. THIS AD IS NOT APPLICABLE DUE TO THE AIRCRAFT BEING DELIVERED WITH A PORTABLE O2 SYSTEM INSTALLED. NO FURTHER ACTION REQUIRED. REFERENCE SB 604-35-008 REV 2 PARAGRAPH 2(D).) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 12 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, DO A GENERAL VISUAL INSPECTION OF THE LEFT-SIDE FORWARD WARDROBE, FLIGHT DECK, OR PASSENGER CABIN AREA OF THE AIRPLANE AND VERIFY IF A PORTABLE PBE DEVICE, MARKED WITH TECHNICAL STANDARD ORDER (TSO) C116 OR C116A, IS INSTALLED AND PLACARDED, IN ACCORDANCE WITH PARAGRAPH 2.B.(1) OF THE ACCOMPLISH	31-JAN-2024 H: 8254.00 L: 3749					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2023-26-08 Airframe AD - Complied With FAA #1939	FLIGHT CONTROLS - GROUND SPOILER DEPLOYMENT Notes (UPDATE NOTE: COMPLIED WITH AD 2023-26-08 EFFECTIVE DATE MARCH 20, 2024, AMENDMENT 39-22651 PARAGRAPH (G)(1) THROUGH (3) BY VERIFYING AFM REVISION INCORPORATING INFORMATION SPECIFIED IN PARAGRAPHS (G)(2)(I) AND (II) OF THE AD. CURRENT AFM REVISION IS REV 131 DATED 5 SEPT 23 AND INCORPORATES THE DATA AS SPECIFIED IN PARAGRAPH (G)(1) THROUGH (3) OF THE AD. THIS IS A TERMINATING ACTION.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD: DO THE APPLICABLE ACTIONS SPECIFIED IN PARAGRAPHS (G)(1) THROUGH (3) OF THIS AD.)	20-MAY-2024 H: 8412.90 L: 3840					
AD 2024-0024 Airframe AD - Open EASA #992	NAVIGATION - DIGITAL AIR DATA COMPUTER - REPLACEMENT Notes (ISSUING AUTHORITY: EASA) (NOTE: COMPLIANCE: FOR GROUP 1 AIRCRAFT: WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, REMOVE EACH AFFECTED PART FROM SERVICE AND REPLACE IT WITH A SERVICEABLE PART IN ACCORDANCE WITH THE INSTRUCTIONS OF THE SB.)						
AD 2024-03-06 Airframe AD - Complied With FAA #3050	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN (THIS AD REPLACES AD 2021-20-13) Notes (UPDATE NOTE: COMPLIED WITH AD 2024-03-06 LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN (THIS AD REPLACES AD 2021-20-13), EFFECTIVE DATE APRIL 16, 2024, BY PERFORMING LOG BOOK RESEARCH. FOUND SB 604-32-031 COMPLIED WITH BY STANDARD AERO CRS UO2R221L ON WO 377320 DATED JULY 5, 2024. THIS SB IS THE TERMINATING ACTION FOR PAR (M) OF THIS AD. THE SB TERMINATES THE INITIAL AND REPETITIVE LUBRICATION AND INSPECTIONS REQUIRED BY PARAGRAPHS (G), (H), AND (I) OF THIS AD FOR THAT AIRPLANE. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, SERIAL NUMBERS (S/N) 5301 THROUGH 5665 INCL	10-SEP-2024 H: 8541.00 L: 3920					
AD 2024-03-06 AMD Par. (I) Airframe AD - Complied With FAA #3075	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - NEW REQUIREMENT OF THE AD: TESTING Notes (UPDATE NOTE: COMPLIED WITH AD 2024-03-06 PAR. (L) LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN-NEW REQUIREMENT OF THIS AD: TESTING, EFFECTIVE DATE APRIL 16, 2024, BY PERFORMING LOG BOOK RESEARCH. FOUND SB 604-32-031 COMPLIED WITH BY STANDARD AERO CRS UO2R221L ON WO 377320 DATED JULY 5, 2024. THIS SB IS THE NEW REQUIREMENT LISTED IN PAR (L).THIS SB IS THE TERMINATING ACTION FOR PAR (M) OF THIS AD. THE SB TERMINATES THE INITIAL AND REPETITIVE LUBRICATION AND INSPECTIONS REQUIRED BY PARAGRAPHS (G), (H), AND (I) OF THIS AD FOR THAT AIRPLANE. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: BEFORE FURTHER FLIGHT AFTER COMPLETING THE ACTIONS REQUIRED BY PA	10-SEP-2024 H: 8541.00 L: 3920					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-03-06 AMD Par. (k) Airframe AD - Complied With FAA #1433	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - NEW REQUIREMENT OF THIS AD: MODIFICATION	10-SEP-2024 H: 8541.00 L: 3920					
	Notes (UPDATE NOTE: COMPLIED WITH AD 2024-03-06 PAR. (K) LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN-NEW REQUIREMENT OF THIS AD: MODIFICATION, EFFECTIVE DATE APRIL 16, 2024, BY PERFORMING LOG BOOK RESEARCH. FOUND SB 604-32-031 COMPLIED WITH BY STANDARD AERO CRS UO2R221L ON WO 377320 DATED JULY 5, 2024. THIS SB IS THE NEW REQUIREMENT LISTED IN PAR (K).THIS SB IS THE TERMINATING ACTION FOR PAR (M) OF THIS AD. THE SB TERMINATES THE INITIAL AND REPETITIVE LUBRICATION AND INSPECTIONS REQUIRED BY PARAGRAPHS (G), (H), AND (I) OF THIS AD FOR THAT AIRPLANE. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, MODIFY						
AD 2024-03-06 AMD Par. (h) Airframe AD - Complied With FAA #993	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - RETAINED DETAILED VISUAL INSPECTIONS (DVI), WITH NO CHANGES	15-AUG-2024 H: 8508.00 L: 3896					
	Notes (AVG MAN HRS: 4) (UPDATE NOTE: COMPLIED WITH BY DIRECT MX DYLAN MULLINS A&P 4377346 ON WO# SDL240551 DATED 8/16/2024) (ISSUING AUTHORITY: FAA)						
AD 2024-03-06 AMD Par. (i) Airframe AD - Complied With FAA #45	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - RETAINED NDT INSPECTION, WITH NO CHANGES	02-JUL-2021					
	Notes (UPDATE NOTE: COMPLIED WITH AD 2021-20-13 PAR. (G) LH MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN, BY LUBRICATION OF THE MLG SHOCK STRUT LOWER PIN IAW CL604 AMM REVISION 96 TASK 12-20-04-640-802, SB 604-32-030 PART A AND AD 2021-20-13 PAR. (G). PAR. (G) NEXT DUE 8199.5 HOURS OR 04-APR-2024, WHICHEVER OCCURS FIRST, PAR (H) NEXT DUE 8399.5 HOURS OR 01-NOV-2024, WHICHEVER OCCURS FIRST, PAR (I) NEXT DUE AT 3934 LANDINGS.) (NOTE: COMPLIANCE: FOR AIRPLANES WITH AN ORIGINAL AIRWORTHINESS CERTIFICATE OR ORIGINAL EXPORT CERTIFICATE OF AIRWORTHINESS ISSUED ON OR BEFORE THE EFFECTIVE DATE OF THIS AD AND ON WHICH AN MLG SHOCK STRUT LOWER PIN THAT HAS ACCUMULATED 2,000 TOTAL FC OR MORE ON THE PIN AS OF						
AD 2024-03-06 AMD Par. (g) Airframe AD - Complied With FAA #3190	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - RETAINED REPETITIVE LUBRICATION, WITH REVISED APPLICABILITY	08-AUG-2024 H: 8505.70 L: 3893					
	Notes (UPDATE NOTE: COMPLIED WITH AD 2024-03-06 PARAGRAPH (G) LEFT HAND AND RIGHT HAND MLG PINS BY LUBRICATION .LUBRICATED ON 08 AUG 2024 AT 8,505.7 HRS 3,893 CYCLES, NEXT DUE 8,705.7 HRS OR 08 AUG 2025 WHICHEVER COMES FIRST.) (ISSUING AUTHORITY: FAA) (NOTE: PREVIOUSLY COMPLIED WITH UNDER AD 2021-20-13 PARA. (G) LEFT HAND AND RIGHT HAND MLG PINS BY LUBRICATION, SEE DIRECT MX WO SDL240221 BY ADAM ORTIZ AP 4569414 ON 3.12.2024 AT 8,313.5 HRS 3,779 CYCLES, NEXT DUE 8,513.5 HRS OR 12 MARCH 2025 WHICHEVER COMES FIRST.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-03-06 AMD Par. (j) Airframe AD - Open FAA #1934	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - RETAINED REPLACEMENT, WITH NO CHANGES						
	Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: THIS PARAGRAPH RESTATES THE REQUIREMENTS OF PARAGRAPH (J) OF AD 2021-20-13, WITH NO CHANGES. IF, DURING ANY INSPECTION REQUIRED BY THIS AD, ANY CRACK OR DAMAGE OF THE MLG SHOCK STRUT LOWER PIN IS DETECTED, BEFORE FURTHER FLIGHT, REPLACE THE AFFECTED MLG SHOCK STRUT LOWER PIN WITH A NEW PART IN ACCORDANCE WITH PARAGRAPH 2.E., "PART D," OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE BULLETIN, AS SPECIFIED IN PARAGRAPHS (G)(1) THROUGH (3) OF THIS AD.)						
AD 2024-03-06 AMD Par. (m) Airframe AD - Complied With FAA #191	LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN - TERMINATING ACTION					10-SEP-2024 H: 8541.00 L: 3920	
	Notes (UPDATE NOTE: COMPLIED WITH AD 2024-03-06 PAR. (M) LANDING GEAR - MAIN LANDING GEAR (MLG) SHOCK STRUT LOWER PIN-TERMINATING ACTION, EFFECTIVE DATE APRIL 16, 2024, BY PERFORMING LOG BOOK RESEARCH. FOUND SB 604-32-031 COMPLIED WITH BY STANDARD AERO CRS UO2R221L ON WO 377320 DATED JULY 5, 2024. THIS SB IS THE TERMINATING ACTION FOR PAR (M) OF THIS AD. THE SB TERMINATES THE INITIAL AND REPETITIVE LUBRICATION AND INSPECTIONS REQUIRED BY PARAGRAPHS (G), (H), AND (I) OF THIS AD FOR THAT AIRPLANE. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: MODIFYING AND TESTING AN AIRPLANE AS REQUIRED BY PARAGRAPHS (K) AND (L) OF THIS AD TERMINATES THE INITIAL AND REPETITIVE LUBRICATIO						
AD 2024-04-01 Airframe AD - Open ANAC #1475	AIRPLANE FLIGHT MANUAL (AFM) REVISION - 5G INTERFERENCE						
	Notes (ISSUING AUTHORITY: ANAC) (NOTE: APPLICABILITY: THIS AIRWORTHINESS DIRECTIVE (AD) APPLIES TO ALL TRANSPORT, COMMUTER, AND NORMAL LEVEL 4 CATEGORY AIRPLANES CERTIFIED FOR AUTOLAND OR AUTHORIZED FOR ANY OF THE FOLLOWING SPECIAL OPERATIONS: (I) INSTRUMENT LANDING SYSTEM (ILS) INSTRUMENT APPROACH PROCEDURES (IAP) CAT II. (II) INSTRUMENT LANDING SYSTEM (ILS) INSTRUMENT APPROACH PROCEDURES (IAP) CAT III. (III) OPERATION WITH HEAD-UP DISPLAY (HUD) TO TOUCHDOWN OPERATION. (IV) OPERATION WITH ENHANCED FLIGHT VISION SYSTEM (EFVS) TO TOUCHDOWN NOTE: NORMAL LEVEL 4 CATEGORY AIRPLANE REFERS TO THE AIRPLANE CERTIFICATION LEVEL, ACCORDING TO SECTION 23.2005 OF RBAC 23, AMENDMENT 64 OR LATER AMENDMENTS. IN						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-04-01 AMD Par. (b)(1) Airframe AD - Open ANAC #3211	AIRPLANE FLIGHT MANUAL (AFM) REVISION - 5G INTERFERENCE - REVISED LIMITATIONS SECTION Notes (ISSUING AUTHORITY: ANAC) (NOTE: COMPLIANCE: FOR AIRPLANES IDENTIFIED IN PARAGRAPH (A) OF THIS AD, THAT DO NOT MEET THE CRITERIA FOR A "RADIO ALTIMETER TOLERANT AIRCRAFT", AS ESTABLISHED BY PORTARIA NO 14.318/SAR, OF APRIL 10, 2024, OR FURTHER ORDINANCE THAT SUPERSEDES IT, WITHIN 10 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE FOLLOWING INFORMATION: NOTE 1: THE AFM ALTERATION REQUIRED BY THIS AD MAY BE ACCOMPLISHED BY INSERTING A COPY OF THIS AD INTO THE AIRCRAFT FLIGHT MANUAL. NOTE 2: FOR THIS AD, A "RADIO ALTIMETER TOLERANT AIRPLANE" IS THE ONE FOR WHICH ANAC ACCEPTS THAT THE COMBINATION AIRPLANE-RADIO ALTIMETER IS SUFFICIENT						
AD 2024-04-01 AMD Par. (c) Airframe AD - Open ANAC #2118	AIRPLANE FLIGHT MANUAL (AFM) REVISION - 5G INTERFERENCE - TERMINATING ACTION TO THE AFM REVISION Notes (ISSUING AUTHORITY: ANAC) (NOTE: COMPLIANCE: MODIFICATION OF A "NON-RADIO ALTIMETER TOLERANT AIRCRAFT" TO A "RADIO ALTIMETER TOLERANT AIRCRAFT", ACCORDING TO PORTARIA NO 14.318/SAR, DE 10 DE ABRIL DE 2024, OR FURTHER PORTARIA THAT SUPERSEDES IT, TERMINATES THE LIMITATIONS REQUIRED BY PARAGRAPH (B)(1) OF THIS AD. AFTER MODIFICATION TO A "RADIO ALTIMETER TOLERANT AIRCRAFT", ACCORDING TO PORTARIA NO. 13.365/SAR, DE 14 DE DEZEMBRO DE 2023, REMOVE THE AFM REVISION REQUIRED BY PARAGRAPH (B)(1) OF THIS AD.)						
AD 2024-07-10 Airframe AD - N/A FAA #90	LANDING GEAR - FILTER PLATE CONNECTOR Notes (AVG MAN HRS: 4) (UPDATE NOTE: AD 2024-07-10 NOT APPLICABLE DUE TO P/N 7040-15 BEING INSTALLED. NO FURTHER ACTIONS REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, CERTIFICATED IN ANY CATEGORY, WITH SERIAL NUMBERS 5301 THROUGH 5665 INCLUSIVE, 5701 THROUGH 5990 INCLUSIVE, AND 6050 AND SUBSEQUENT.)		09-SEP-2024 H: 8541.00 L: 3920				
AD 2024-07-10 AMD Par. (h) Airframe AD - N/A FAA #1161	LANDING GEAR - FILTER PLATE CONNECTOR - REPLACEMENT Notes (UPDATE NOTE: AD 2024-07-10 NOT APPLICABLE DUE TO P/N 7040-15 BEING INSTALLED. NO FURTHER ACTIONS REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR AIRPLANES IDENTIFIED IN PARAGRAPH (G)(1) OF THIS AD: DO THE ACTIONS SPECIFIED IN PARAGRAPHS (H)(1) AND (2) OF THIS AD. (1) WITHIN 24 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD: REPLACE THE ECM, P/N 601-86100-27, IDENTIFIED IN PARAGRAPH (G)(1) OF THIS AD, IN ACCORDANCE WITH SECTION 2.C. PART B OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE INFORMATION LISTED IN FIGURE 1 TO THE INTRODUCTORY TEXT OF PARAGRAPH (G) OF THIS AD. (2) PRIOR TO RETURN TO SERVICE, COMPLETE THE OPERATIONAL TEST OF THE NWS SYSTEM IN ACCORDANCE WITH SEC		09-SEP-2024 H: 8541.00 L: 3920				



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-07-10 AMD Par. (g) Airframe AD - N/A FAA #1232	LANDING GEAR - FILTER PLATE CONNECTOR - VERIFICATION OF AIRPLANE TECHNICAL RECORDS	09-SEP-2024 H: 8541.00 L: 3920					
	Notes (UPDATE NOTE: AD 2024-07-10 NOT APPLICABLE DUE TO P/N 7040-15 BEING INSTALLED. NO FURTHER ACTIONS REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 24 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD: INSPECT THE SERIAL NUMBER OF THE ECM, PART NUMBER (P/N) 601-86100-27, IN ACCORDANCE WITH SECTION 2.B. PART A OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE INFORMATION LISTED IN FIGURE (1) TO THE INTRODUCTORY TEXT OF PARAGRAPH (G) OF THIS AD TO DETERMINE IF THE SERIAL NUMBER OF THE ECM, P/N 601-86100-27, IS LISTED IN TABLE 1 OF SECTION 1.A. OF THE APPLICABLE SERVICE INFORMATION LISTED IN FIGURE (1) TO THE INTRODUCTORY TEXT OF PARAGRAPH (G) OF THIS AD. A REVIEW OF MAINTENANC						
AD 2024-13-01 Airframe AD - Open FAA #144	FUEL - DAMAGED WIRE INSULATION						
	Notes (ISSUING AUTHORITY: FAA)						
AD 2024-19-15 Airframe AD - N/A FAA #3631	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES (THIS AD REPLACES AD 2023-13-11)	24-OCT-2024 H: 8557.60 L: 3931					
	Notes (UPDATE NOTE: RESEARCHED AD 2024-19-15 SAFRAN AEROSYSTEMS (FORMERLY AVOX SYSTEMS INC.; SCOTT AVIATION): AMENDMENT 39-22857; DOCKET NO. FAA-2024-0759; PROJECT IDENTIFIER AD-2023-01040-T. OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES (THIS AD REPLACES AD 2023-13-11). EFFECTIVE DATE NOVEMBER 26, 2024. FOUND AD TO BE NOT APPLICABLE DUE TO AFFECTED EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA).RESEARCHED AD 2024-19-15 SAFRAN AEROSYSTEMS (FORMERLY AVOX SYSTEMS INC.; SCOTT AVIATION): AMENDMENT 39-22857; DOCKET NO. FAA-2024-0759; PROJECT IDENTIFIER AD-2023-01040-T. OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES (THIS AD REPLACES						
AD 2024-19-15 AMD Par. (l) Airframe AD - N/A FAA #1215	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - NEW IDENTIFICATION OF ADDITIONAL AFFECTED CYLINDER AND VALVE ASSEMBLIES	24-OCT-2024 H: 8557.60 L: 3931					
	Notes (UPDATE NOTE: RESEARCHED AD 2024-19-15 PAR. (L) SAFRAN AEROSYSTEMS (FORMERLY AVOX SYSTEMS INC.; SCOTT AVIATION): AMENDMENT 39-22857; DOCKET NO. FAA-2024-0759; PROJECT IDENTIFIER AD-2023-01040-T. OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - NEW IDENTIFICATION OF ADDITIONAL AFFECTED CYLINDER AND VALVE ASSEMBLIES. EFFECTIVE DATE NOVEMBER 26, 2024. FOUND AD TO BE NOT APPLICABLE DUE TO AFFECTED EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: WITHIN 60 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF THE SERIAL NUMBERS OF THE VALVE,						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-19-15 AMD Par. (m) Airframe AD - N/A FAA #3482	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - NEW INSPECTION OF THE GAP, PARTS MARKING ACTIONS, AND REPLACEMENT FOR ADDITIONAL PARTS - INSPECTION OF THE GAP Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF, DURING ANY INSPECTION OR RECORDS REVIEW REQUIRED BY PARAGRAPH (L) OF THIS AD, ANY OXYGEN VALVE ASSEMBLY, VALVE OR CYLINDER OF AN OXYGEN CYLINDER AND VALVE ASSEMBLY, OR OXYGEN CYLINDER AND VALVE ASSEMBLY HAVING AN AFFECTED SERIAL NUMBER IS FOUND: BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY, IN ACCORDANCE WITH PARAGRAPH 3.C. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (L)(1) THROUGH (3) OF THIS AD.)						
AD 2024-19-15 AMD Par. (m)(1) Airframe AD - N/A FAA #881	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - NEW INSPECTION OF THE GAP, PARTS MARKING ACTIONS, AND REPLACEMENT FOR ADDITIONAL PARTS - PARTS MARKING ACTIONS Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF THE GAP IS FOUND TO BE ACCEPTABLE, AS DEFINED IN THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (L) (1) THROUGH (3) OF THIS AD, BEFORE FURTHER FLIGHT, DO THE PARTS MARKING ACTIONS IN ACCORDANCE WITH PARAGRAPH 3.D.(1) OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (L)(1) THROUGH (3) OF THIS AD.)						
AD 2024-19-15 AMD Par. (m)(2) Airframe AD - N/A FAA #2071	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - NEW INSPECTION OF THE GAP, PARTS MARKING ACTIONS, AND REPLACEMENT FOR ADDITIONAL PARTS - REPLACEMENT Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF THE GAP IS FOUND TO BE UNACCEPTABLE, AS DEFINED IN THE MATERIAL IDENTIFIED IN PARAGRAPHS (L)(1) THROUGH (3) OF THIS AD, BEFORE FURTHER FLIGHT, REMOVE THE AFFECTED ASSEMBLY, IN ACCORDANCE WITH PARAGRAPHS 3.D.(2) OR 3.D.(3), AS APPLICABLE, OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (L)(1) THROUGH (3) OF THIS AD; AND REPLACE WITH A SERVICEABLE ASSEMBLY.)						
AD 2024-19-15 AMD Par. (h) Airframe AD - N/A FAA #3687	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - RETAINED IDENTIFICATION OF AFFECTED CYLINDER AND VALVE ASSEMBLIES, WITH UPDATED LANGUAGE Notes (UPDATE NOTE: RESEARCHED AD 2024-19-15 PAR. (H) SAFRAN AEROSYSTEMS (FORMERLY AVOX SYSTEMS INC.; SCOTT AVIATION): AMENDMENT 39-22857; DOCKET NO. FAA-2024-0759; PROJECT IDENTIFIER AD-2023-01040-T. OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - RETAINED IDENTIFICATION OF AFFECTED CYLINDER AND VALVE ASSEMBLIES, WITH UPDATED LANGUAGE. EFFECTIVE DATE NOVEMBER 26, 2024. FOUND AD TO BE NOT APPLICABLE DUE TO AFFECTED EQUIPMENT NOT INSTALLED ON AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: THIS PARAGRAPH RESTATES THE REQUIREMENTS OF PARAGRAPH (H) OF AD 2023-13-11, WITH UPDATED LANGUAGE. WITHIN 60 DAYS AFTER SEPTEMBER 5, 2023 (THE EFFECTIVE DATE OF A			24-OCT-2024 H: 8557.60 L: 3931			



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-19-15 AMD Par. (i) Airframe AD - N/A FAA #2576	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - RETAINED INSPECTION OF THE GAP, PARTS MARKING ACTIONS, AND REPLACEMENT, WITH UPDATED LANGUAGE - INSPECTION OF THE GAP Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: THIS PARAGRAPH RESTATES THE REQUIREMENTS OF PARAGRAPH (I) OF AD 2023-13-11, WITH UPDATED LANGUAGE. IF, DURING ANY INSPECTION OR RECORDS REVIEW REQUIRED BY PARAGRAPH (H) OF THIS AD, ANY OXYGEN VALVE ASSEMBLY, VALVE OR CYLINDER OF AN OXYGEN CYLINDER AND VALVE ASSEMBLY, OR OXYGEN CYLINDER AND VALVE ASSEMBLY HAVING AN AFFECTED SERIAL NUMBER IS FOUND: BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY, IN ACCORDANCE WITH PARAGRAPH 3.C. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (3) OF THIS AD.)						
AD 2024-19-15 AMD Par. (i)(1) Airframe AD - N/A FAA #2192	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - RETAINED INSPECTION OF THE GAP, PARTS MARKING ACTIONS, AND REPLACEMENT, WITH UPDATED LANGUAGE - PARTS MARKING ACTIONS Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF THE GAP IS FOUND TO BE ACCEPTABLE, AS DEFINED IN THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (3) OF THIS AD, BEFORE FURTHER FLIGHT, DO THE PARTS MARKING ACTIONS IN ACCORDANCE WITH PARAGRAPH 3.D.(1) OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (3) OF THIS AD.)						
AD 2024-19-15 AMD Par. (i)(2) Airframe AD - N/A FAA #2601	OXYGEN - OXYGEN LEAKAGE FROM CYLINDER AND VALVE ASSEMBLIES - RETAINED INSPECTION OF THE GAP, PARTS MARKING ACTIONS, AND REPLACEMENT, WITH UPDATED LANGUAGE - REPLACEMENT Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: IF THE GAP IS FOUND TO BE UNACCEPTABLE, AS DEFINED IN THE MATERIAL IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (3) OF THIS AD, BEFORE FURTHER FLIGHT, REMOVE THE AFFECTED ASSEMBLY, IN ACCORDANCE WITH PARAGRAPHS 3.D.(2) OR 3.D.(3), AS APPLICABLE, OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE MATERIAL IDENTIFIED IN PARAGRAPHS (H)(1) THROUGH (3) OF THIS AD; AND REPLACE WITH A SERVICEABLE ASSEMBLY.)						
AD 2024-26-02 Airframe AD - N/A FAA #2513	CABIN EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY - BUCKLE HANDLE (THIS AD REPLACES AD 2021-07-13) Notes (UPDATE NOTE: AD 2024-26-02 (EFFECTIVE 07/MAR/2025) CABIN EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY - BUCKLE HANDLE (THIS AD REPLACES AD 2021-07-13). N/A AFFECTED EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO ALL AIRPLANES AND HELICOPTERS, CERTIFICATED IN ANY CATEGORY, WITH A RESTRAINT SYSTEM WITH A PACIFIC SCIENTIFIC COMPANY PLASTIC ROTARY BUCKLE ASSEMBLY (BUCKLE) PART NUMBER (P/N) 1111430 OR P/N 1111475 (ALL DASH NUMBERS) INSTALLED HAVING A DATE OF MANUFACTURE ON OR BEFORE MAY 31, 2007, OR AN UNKNOWN DATE OF MANUFACTURE, EXCEPT NOT THOSE BUCKLES REPAIRED WITH THE INSTALLATION OF AN AIRWO					19-SEP-2025 H: 8650.80 L: 3987	



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2024-26-02 AMD Par. (g)(1) Airframe AD - N/A FAA #3096	CABIN EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY - BUCKLE HANDLE - INSPECT FOR CRACK	19-SEP-2025 H: 8650.80 L: 3987					
Notes (UPDATE NOTE: AIRWORTHINESS DIRECTIVE 2024-26-02 PAR. (G)(1) (EFFECTIVE 07/MAR/2025) CABIN EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY - BUCKLE HANDLE - INSPECT FOR CRACK. N/A AFFECTED EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO ALL AIRPLANES AND HELICOPTERS, CERTIFICATED IN ANY CATEGORY, WITH A RESTRAINT SYSTEM WITH A PACIFIC SCIENTIFIC COMPANY PLASTIC ROTARY BUCKLE ASSEMBLY (BUCKLE) PART NUMBER (P/N) 1111430 OR P/N 1111475 (ALL DASH NUMBERS) INSTALLED HAVING A DATE OF MANUFACTURE ON OR BEFORE MAY 31, 2007, OR AN UNKNOWN DATE OF MANUFACTURE, EXCEPT NOT THOSE BUCKLES REPAIRED WITH THE INST							
AD 2024-26-02 AMD Par. (g)(2) Airframe AD - N/A FAA #980	CABIN EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY - BUCKLE HANDLE - MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE	19-SEP-2025 H: 8650.80 L: 3987					
Notes (UPDATE NOTE: AIRWORTHINESS DIRECTIVE 2024-26-02 PAR. (G)(2) (EFFECTIVE 07/MAR/2025). CABIN EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY - BUCKLE HANDLE - MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE. N/A AFFECTED EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO ALL AIRPLANES AND HELICOPTERS, CERTIFICATED IN ANY CATEGORY, WITH A RESTRAINT SYSTEM WITH A PACIFIC SCIENTIFIC COMPANY PLASTIC ROTARY BUCKLE ASSEMBLY (BUCKLE) PART NUMBER (P/N) 1111430 OR P/N 1111475 (ALL DASH NUMBERS) INSTALLED HAVING A DATE OF MANUFACTURE ON OR BEFORE MAY 31, 2007, OR AN UNKNOWN DATE OF MANUFACTURE, EXCEPT NOT THO							
AD 2025-0088 Airframe AD - Open EASA #1535	NAVIGATION - SATELLITE BASED AUGMENTATION SYSTEMS / GLOBAL POSITIONING SYSTEM RECEIVER - REPLACEMENT		M: 24			30-APR-2027	M: 10 D: 29
Notes (ISSUING AUTHORITY: EASA) (NOTE: APPLICABILITY: ROCKWELL COLLINS GPS-4000S, GLU-2100, GLUS-2100 AND GLUS-2100A RECEIVERS, HAVING A PART NUMBER (P/N) AS LISTED IN APPENDIX 1 OF THIS AD, ALL SERIAL NUMBERS. AFFECTED PART: ANY ROCKWELL COLLINS (COLLINS) SATELLITE BASED AUGMENTATION SYSTEMS (SBAS) RECEIVER GPS-4000S, GLU-2100, GLUS-2100 AND GLUS-2100A, HAVING HARDWARE AND OPERATIONAL PROGRAM SOFTWARE (OPS) P/N AS IDENTIFIED IN APPENDIX 1 OF THIS AD. COMPLIANCE: FOR AFFECTED AEROPLANES HAVING AIRWORTHINESS APPROVAL FOR LPV-200 OPERATIONS: WITHIN 2 YEARS AFTER THE EFFECTIVE DATE OF THIS AD, OR BEFORE NEXT FLIGHT AFTER HAVING OBTAINED THE AIRWORTHINESS APPROVAL FOR LPV-200 OPERATIONS, WHICHEVER OCC							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2025-07-01 Airframe AD - N/A FAA #2566	AIR DATA COMPUTER - AC32 DIGITAL AIR DATA COMPUTERS - REPLACEMENT Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO THOMMEN AIRCRAFT EQUIPMENT AG (THOMMEN) AC32 DIGITAL AIR DATA COMPUTERS (ADCS) HAVING AN AFFECTED PART AS DEFINED IN PARAGRAPH (F)(1) OF THIS AD. (2) THIS APPLIANCE IS INSTALLED ON, BUT NOT LIMITED TO, THE FOLLOWING AIRCRAFT MODELS SPECIFIED IN TABLE 1 TO PARAGRAPH (C)(2) OF THIS AD, CERTIFICATED IN ANY CATEGORY. (3) THIS APPLIANCE IS APPROVED FOR INSTALLATION AND COULD BE INSTALLED ON VARIOUS AIRCRAFT MODIFIED BY SUPPLEMENTAL TYPE CERTIFICATE (STC) NO. SR09595RC OR ST01523WI. AFFECTED PART: THOMMEN AC32 DIGITAL ADCS, PART NUMBERS (P/N) AC32.10.21.10.XX, AC32.10.21.11.XX, AC32.11.21.10.XX, AND AC32.11.21.11.XX (WHERE XX RE	06-MAR-2026 H: 8670.40 L: 3995					
AD 2025-07-09 Airframe AD - Complied With FAA #736	OXYGEN - PORTABLE OXYGEN BOTTLE INSTALLATION OF UPPER BRACKET LATCH ASSEMBLY (THIS AD SUPERSEDES FAA AD 2020-19-13) Notes (AVG MAN HRS: 1) (UPDATE NOTE: AD REQUIREMENTS PREVIOUSLY COMPLIED WITH UNDER SB 604-35-006 R1 ON 5 JUL 2024 BY STANDARD AERO ON WO: 377320.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO BOMBARDIER, INC., AIRPLANES, IDENTIFIED IN PARAGRAPHS (C)(1) THROUGH (3), CERTIFICATED IN ANY CATEGORY, EQUIPPED WITH SCOTT (AVOX/ZODIAC) 5500 OR 5600 SERIES 11 CUBIC FOOT PORTABLE OXYGEN BOTTLE(S) WITH UPPER BRACKET PART NUMBER (P/N) 36758-02, P/N 36758-12 OR P/N H3-2091-1 INSTALLED AT THE NECK OF THE BOTTLE(S). (1) MODEL CL-600-1A11 (600) AIRPLANES, SERIAL NUMBERS (S/NS) 1004 THROUGH 1085 INCLUSIVE. (2) MODEL CL-600-2A12 (601) AIRPLANES, SERIAL NUMBERS 3001 THROUGH 3066 INCLUSIVE. (3)	03-NOV-2025 H: 8670.40 L: 3995					
AD 2025-07-09 AMD Par. (j) Airframe AD - Complied With FAA #1507	OXYGEN - PORTABLE OXYGEN BOTTLE INSTALLATION OF UPPER BRACKET LATCH ASSEMBLY - NEW CHECK REQUIREMENT FOR ADDED AIRPLANES Notes (UPDATE NOTE: AD REQUIREMENTS PREVIOUSLY COMPLIED WITH UNDER SB 604-35-006 R1 ON 5 JUL 2024 BY STANDARD AERO ON WO: 377320.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR AIRPLANE S/NS 6158, 6161, 6176, AND 6181: WITHIN 60 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, CHECK EACH PORTABLE OXYGEN BOTTLE INSTALLATION TO DETERMINE THE MANUFACTURER AND PART NUMBER AND ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE PROCEDURES SPECIFIED IN PARAGRAPH (L)(1) OF THIS AD.)	03-NOV-2025 H: 8670.40 L: 3995					
AD 2025-07-09 AMD Par. (h) Airframe AD - Complied With FAA #383	OXYGEN - PORTABLE OXYGEN BOTTLE INSTALLATION OF UPPER BRACKET LATCH ASSEMBLY - RETAINED BRACKET MODIFICATION, WITH SPECIFIED COMPLIANCE TIME Notes (UPDATE NOTE: AD REQUIREMENTS PREVIOUSLY COMPLIED WITH UNDER SB 604-35-006 R1 ON 5 JUL 2024 BY STANDARD AERO ON WO: 377320.) (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: THIS PARAGRAPH RESTATES THE REQUIREMENTS OF PARAGRAPH (H) OF AD 2020-19-13, WITH A SPECIFIED COMPLIANCE TIME. IF, DURING THE INSPECTION SPECIFIED IN PARAGRAPH (G) OF THIS AD, ANY PORTABLE OXYGEN BOTTLE IS FOUND TO BE MANUFACTURED BY SCOTT (AVOX/ZODIAC) AND IS A 5500 OR 5600 SERIES 11 CUBIC FOOT BOTTLE, WITH UPPER BRACKET P/N 36758-02, 36758-12, OR H3-2091-1 INSTALLED AT THE NECK OF THE BOTTLE: WITHIN 60 MONTHS AFTER NOVEMBER 3, 2020 (THE EFFECTIVE DATE OF AD 2020-19-13), MODIFY THE PORTABLE OXYGEN BOTTLE BRACKETS IN ACCORDANC	03-NOV-2025 H: 8670.40 L: 3995					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2025-07-09 AMD Par. (i) Airframe AD - Complied With FAA #3675	OXYGEN - PORTABLE OXYGEN BOTTLE INSTALLATION OF UPPER BRACKET LATCH ASSEMBLY - RETAINED CHECK FOR AIRPLANES NOT LISTED IN THE SERVICE INFORMATION, WITH REVISED FIGURE REFERENCE AND REVISED SERVICE INFORMATION	03-NOV-2025 H: 8670.40 L: 3995					
	Notes (UPDATE NOTE: AD REQUIREMENTS PREVIOUSLY COMPLIED WITH UNDER SB 604-35-006 R1 ON 5 JUL 2024 BY STANDARD AERO ON WO: 377320.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: FOR AIRPLANES WITH A SERIAL NUMBER THAT IS NOT LISTED IN SECTION 1.A. OF THE APPLICABLE BOMBARDIER SERVICE INFORMATION SPECIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD: FOR THE MODEL CL-600-1A11, THE APPLICABLE BOMBARDIER SERVICE BULLETIN IS 600-0772, REVISION 01, DATED JUNE 28, 2023. FOR THE MODEL CL-600-2A12, THE APPLICABLE BOMBARDIER SERVICE BULLETIN IS 601-0646, REVISION 01, DATED JUNE 28, 2023. FOR THE MODEL CL-600-2B16, THE APPLICABLE BOMBARDIER SERVICE BULLETINS ARE 601-0646, REVISION 01, DATED JUNE 28, 2023; 604-3						
AD 2025-07-09 AMD Par. (g) Airframe AD - Complied With FAA #1693	OXYGEN - PORTABLE OXYGEN BOTTLE INSTALLATION OF UPPER BRACKET LATCH ASSEMBLY - RETAINED CHECK FOR AIRPLANES, WITH REVISED FIGURE REFERENCE AND REVISED SERVICE INFORMATION	03-NOV-2025 H: 8670.40 L: 3995					
	Notes (UPDATE NOTE: AD REQUIREMENTS PREVIOUSLY COMPLIED WITH UNDER SB 604-35-006 R1 ON 5 JUL 2024 BY STANDARD AERO ON WO: 377320.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: FOR AIRPLANES WITH A SERIAL NUMBER LISTED IN SECTION 1.A. OF THE APPLICABLE BOMBARDIER SERVICE INFORMATION SPECIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD, EXCEPT AIRPLANE S/NS 6158, 6161, 6176, AND 6181: FOR THE MODEL CL-600-1A11, THE APPLICABLE BOMBARDIER SERVICE BULLETIN IS 600-0772, REVISION 01, DATED JUNE 28, 2023. FOR THE MODEL CL-600-2A12, THE APPLICABLE BOMBARDIER SERVICE BULLETIN IS 601-0646, REVISION 01, DATED JUNE 28, 2023. FOR THE MODEL CL-600-2B16, THE APPLICABLE BOMBARDIER SERVICE BULLETINS ARE 601-0646, RE						
AD 2025-12-02 Airframe AD - N/A FAA #2166	EQUIPMENT/FURNISHINGS - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS	19-SEP-2025 H: 8650.80 L: 3987					
	Notes (UPDATE NOTE: AIRWORTHINESS DIRECTIVE 2025-12-02 (EFFECTIVE JUNE 30, 2025). EQUIPMENT/FURNISHINGS - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS. N/A AFFECTED EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA)						
AD 2025-12-02 AMD Par. (g)(1) Airframe AD - N/A FAA #2526	EQUIPMENT/FURNISHINGS - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - INSPECTION	19-SEP-2025 H: 8650.80 L: 3987					
	Notes (UPDATE NOTE: AIRWORTHINESS DIRECTIVE 2025-12-02 PAR. (G)(1). (EFFECTIVE JUNE 30, 2025). EQUIPMENT/FURNISHINGS - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - INSPECTION. N/A AFFECTED EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS, IDENTIFIED BY SERIES PART NUMBER IN FIGURE 1 TO PARAGRAPH (C)(1) OF THIS AD. (2) THESE PILOT AND CO-PILOT SEATS ARE KNOWN TO BE INSTALLED ON, BUT NOT LIMITED TO, ATR-GIE AVIONS DE TRANSPORT RÉGIONAL MODEL ATR42 AND ATR72 AIRPLANES. COMPLIANCE: WITHIN 3 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, INSPECT						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2025-12-02 AMD Par. (g)(2)(3) Airframe AD - N/A FAA #3203	EQUIPMENT/FURNISHINGS - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - OPERATIONAL TESTS	19-SEP-2025 H: 8650.80 L: 3987					
Notes (UPDATE NOTE: AIRWORTHINESS DIRECTIVE 2025-12-02 PAR. (G)(2)(3). (EFFECTIVE JUNE 30, 2025). EQUIPMENT/FURNISHINGS - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - OPERATIONAL TESTS. N/A AFFECTED EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: (1) THIS AD APPLIES TO IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS, IDENTIFIED BY SERIES PART NUMBER IN FIGURE 1 TO PARAGRAPH (C)(1) OF THIS AD. (2) THESE PILOT AND CO-PILOT SEATS ARE KNOWN TO BE INSTALLED ON, BUT NOT LIMITED TO, ATR-GIE AVIONS DE TRANSPORT RÉGIONAL MODEL ATR42 AND ATR72 AIRPLANES. COMPLIANCE: (2) IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (C)(2), THE PILOT AND CO-PILOT SEATS ARE KNOWN TO BE INSTALLED ON, BUT NOT LIMITED TO, ATR-GIE AVIONS DE TRANSPORT RÉGIONAL MODEL ATR42 AND ATR72 AIRPLANES.							
AD 2025-16-09 Airframe AD - N/A FAA #2598	EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY	26-FEB-2026 H: 8670.40 L: 3995					
Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ALL AIRPLANES, CERTIFICATED IN ANY CATEGORY, WITH A RESTRAINT SYSTEM WITH A PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY (BUCKLE) PART NUMBER (P/N) 1111475 (ALL DASH NUMBERS) OR P/N 1111548-01 INSTALLED HAVING A DATE OF MANUFACTURE (DOM) BETWEEN JANUARY 2012 AND APRIL 2013 INCLUSIVE, OR AN UNKNOWN DOM. THESE BUCKLES MAY BE INSTALLED ON, BUT NOT LIMITED TO, THE BOEING COMPANY MODEL AIRPLANES. NOTE 1 TO PARAGRAPH (C): THE BUCKLE MAY BE INCLUDED AS A COMPONENT OF A DIFFERENT PART-NUMBERED RESTRAINT SYSTEM ASSEMBLY. NOTE 2 TO PARAGRAPH (C): THESE BUCKLES MAY ALSO BE INSTALLED ON HELICOPTERS; HOWEVER, THE FAA DETERMINED THAT							
AD 2025-16-09 AMD Par. (g)(1)(2) Airframe AD - N/A FAA #2214	EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY - INSPECTION AND CORRECTIVE ACTION(S)	26-FEB-2026 H: 8670.40 L: 3995					
Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: FOR AIRPLANES WITH BUCKLE P/N 1111475 (ALL DASH NUMBERS) AND/OR AIRPLANES WITH BUCKLE P/N 1111548-01. COMPLIANCE: WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPHS B.(1) AND (2), OF PARKER MEGGITT SERVICE BULLETIN SB 1111475- 25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111475-25-001-2023 REV 002), AND/OR ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH B.(1), OF PARKER MEGGITT SB 1111548-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111548-25-001-2023 REV 002).)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2025-16-09 AMD Par. (g)(3) Airframe AD - N/A FAA #1767	EQUIPMENT/FURNISHINGS - PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLY - REMOVING MALE SIDE OF LAP BELT AND PLACARDING SEAT INOPERATIVE (OPTION FOR A CREWMEMBER SEAT OR PASSENGER SEAT ONLY) Notes (ISSUING AUTHORITY: FAA) (NOTE: COMPLIANCE: FOR A CREWMEMBER SEAT OR PASSENGER SEAT WITH A RESTRAINT SYSTEM WITH A BUCKLE IDENTIFIED IN PARAGRAPH (C) OF THIS AD INSTALLED, AS AN OPTION FOR THE ACTIONS REQUIRED BY PARAGRAPH (G)(1) OR (2) OF THIS AD, AS APPLICABLE, WITHIN 12 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD: (I) REMOVE THE MALE SIDE FROM THE LAP OF THE RESTRAINT SYSTEM ASSEMBLY. (II) FABRICATE A PLACARD USING AT LEAST 1/8 INCH LETTERS WITH THE WORDS "USE OF THIS SEAT IS PROHIBITED" ON IT AND INSTALL THE PLACARD ON THE SEAT WITHIN THE CREWMEMBER OR PASSENGER'S CLEAR VIEW. THE SEAT IS THEN INOPERATIVE UNTIL THE ACTIONS REQUIRED BY PARAGRAPH (G)(1) OR (2) OF THIS AD, AS APPLICABLE, ARE	26-FEB-2026 H: 8670.40 L: 3995					
AD 2025-17-12 Airframe AD - Open FAA #688	TIME LIMITS/MAINTENANCE CHECKS - REVISION TO THE MAINTENANCE OR INSPECTION PROGRAM - INCORPORATION OF NEW OR MORE RESTRICTIVE AIRWORTHINESS LIMITATIONS Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO THE BOMBARDIER, INC., AIRPLANES IDENTIFIED IN PARAGRAPHS (C)(1) AND (2) OF THIS AD, CERTIFICATED IN ANY CATEGORY. (1) ALL MODEL CL-600-1A11 (600), CL-600-2A12 (601), AND CL-600-2B16 (601-3A AND 601-3R VARIANTS) AIRPLANES. (2) MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, SERIAL NUMBERS 6050 THROUGH 6192 INCLUSIVE.)						
AD 2025-17-12 AMD Par. (h)(1)(2) Airframe AD - Complied With FAA #1664	TIME LIMITS/MAINTENANCE CHECKS - REVISION TO THE MAINTENANCE OR INSPECTION PROGRAM - INCORPORATION OF NEW OR MORE RESTRICTIVE AIRWORTHINESS LIMITATIONS - COMPLIANCE TIME EXCEPTION FOR A CERTAIN TASK Notes Task 27-42-01-110 initially C/W 23-MAR-2017	01-FEB-2026 H: 8670.40 L: 3995					
AD 2025-17-12 AMD Par. (g)(1)(2) Airframe AD - Open FAA #8	TIME LIMITS/MAINTENANCE CHECKS - REVISION TO THE MAINTENANCE OR INSPECTION PROGRAM - INCORPORATION OF NEW OR MORE RESTRICTIVE AIRWORTHINESS LIMITATIONS - MAINTENANCE OR INSPECTION PROGRAM REVISION Notes (ISSUING AUTHORITY: FAA)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2025-22-04 Airframe AD - Open FAA #2987	FLIGHT CONTROLS - FLAP SYSTEM ON-BOARD RECORDER (FSOB) EFFECTS ON FLAP CONTROL UNIT - DISCONNECTION AND INSTALLATION PROHIBITION OF THE FSOBR Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ALL BOMBARDIER, INC., MODEL CL-600-2B16 (604 VARIANT) AIRPLANES, CERTIFICATED IN ANY CATEGORY. COMPLIANCE: FOR AIRPLANES THAT HAVE INCORPORATED BOMBARDIER SERVICE BULLETIN 604-27-035, BOMBARDIER SERVICE BULLETIN 605-27-006, OR BOMBARDIER SERVICE BULLETIN 650-27-001 AS OF THE EFFECTIVE DATE OF THIS AD: WITHIN 1,000 FLIGHT HOURS OR 14 MONTHS, WHICHEVER OCCURS FIRST, AFTER THE EFFECTIVE DATE OF THIS AD, DISCONNECT THE FSOBR IN ACCORDANCE WITH SECTION 2.B OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SERVICE BULLETIN LISTED IN TABLE 1 TO PARAGRAPH (G) OF THIS AD.)		M: 14 H: 1000.00			23-FEB-2027 H: 9671.70	M: 8 D: 22 H: 976.60
AD 2025-24-11 Airframe AD - N/A FAA #1549	AUXILIARY POWER UNIT - REVISING MAINTENANCE/INSPECTION PROGRAM - FUNCTIONAL TEST OF APU MUFFLER DRAIN Notes (ISSUING AUTHORITY: FAA) (NOTE: APPLICABILITY: THIS AD APPLIES TO ALL BOMBARDIER, INC., MODEL CL-600-2A12 (601) AND CL-600-2B16 (601-3A, 601-3R, AND 604 VARIANTS) AIRPLANES, CERTIFICATED IN ANY CATEGORY. NOTE: CHALLENGER 605 AND CHALLENGER 650 IS ADDED AS IT WAS INDICATED IN THE COMPLIANCE. COMPLIANCE: WITHIN 90 DAYS AFTER THE EFFECTIVE DATE OF THIS AD, REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE, TO INCORPORATE THE INFORMATION SPECIFIED IN THE APPLICABLE TASKS IDENTIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD. THE INITIAL COMPLIANCE TIME FOR DOING THE TASKS IS AT THE TIME SPECIFIED IN THE APPLICABLE TASKS IDENTIFIED IN FIGURE 1 TO PARAGRAPH (G) OF THIS AD, OR WITHI	26-FEB-2026 H: 8670.40 L: 3995					
AD 2025-26-06 Airframe AD - N/A FAA #3728	OXYGEN - PORTABLE BREATHING EQUIPMENT (PBE) - INCORRECT USAGE OF PBES (THIS AD REPLACES AD 2025-25-02) Reference Number 47209785 Notes No PBE installed.	01-FEB-2026 H: 8670.40 L: 3995					
AD 2026-03-09 AMD Par. (g) EASA Par. (1.1)(1.2) Airframe AD - N/A FAA #3729	OXYGEN - REPLACEMENT OF AEROSPACE AND DEFENSE OXYGEN SYSTEMS SAS PORTABLE BREATHING EQUIPMENT (PBE) - REPLACEMENT (IAW EASA AD 2025-0297R1)	16-MAR-2026 H: 8670.40 L: 3995					
AD 2026-03-09 AMD Par. (g) EASA Par. (1.3) Airframe AD - N/A FAA #3730	OXYGEN - REPLACEMENT OF AEROSPACE AND DEFENSE OXYGEN SYSTEMS SAS PORTABLE BREATHING EQUIPMENT (PBE) - REPLACEMENT FOR AFFECTED PBE NOT AFFECTED BY PARAGRAPH (1.1) AND (1.2) (IAW EASA AD 2025-0297R1)	16-MAR-2026 H: 8670.40 L: 3995					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 2026-03-09 AMD Par. (g) EASA Par. (4) Airframe AD - N/A FAA #3732	OXYGEN - REPLACEMENT OF AEROSPACE AND DEFENSE OXYGEN SYSTEMS SAS PORTABLE BREATHING EQUIPMENT (PBE) - REPLACEMENT OF AFFECTED PBE - LIFE LIMIT (CABIN) (IAW EASA AD 2025-0297R1)	16-MAR-2026 H: 8670.40 L: 3995					
AD 2026-03-09 AMD Par. (g) EASA Par. (4) Airframe AD - N/A FAA #3731	OXYGEN - REPLACEMENT OF AEROSPACE AND DEFENSE OXYGEN SYSTEMS SAS PORTABLE BREATHING EQUIPMENT (PBE) - REPLACEMENT OF AFFECTED PBE - LIFE LIMIT (COCKPIT) (IAW EASA AD 2025-0297R1)	16-MAR-2026 H: 8670.40 L: 3995					
AD 2026-03-09 Airframe AD - N/A FAA #3727	THIS AD WAS PROMPTED BY REPORTS OF OCCURRENCES OF PBE NOT DELIVERING OXYGEN ONCE DONNED. FOLLOWING INVESTIGATION, A MANUFACTURING ISSUE HAS BEEN IDENTIFIED, AFFECTING CERTAIN PBE. THE FAA IS ISSUING THIS AD TO ADDRESS AFFECTED PBE. THE UNSAFE CONDITION...	16-MAR-2026 H: 8670.40 L: 3995					
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE DETERMINE ANY FURTHER APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS.							
AD 2026-07-01 AMD 39-23296 Airframe AD - Open FAA #3737	2026-07-01 Paragraph (g)(1) through (5). THIS AD WAS PROMPTED BY A REPORT OF UNCOMMANDED NOSE WHEEL STEERING UPON LANDING WITH TOUCHDOWN ON THE RUNWAY CENTERLINE. THE FAA IS ISSUING THIS AD TO ADDRESS UNCOMMANDED NOSEWHEEL STEERING DUE TO LOOSE NOSEWHEEL STEERING RUDDER PEDAL POTENTIOMETER...					08-MAY-2029 H: 10086.90	M: 35 D: 7 H: 1391.80
Notes INDICATED NEXT DUE DATE IS AD EFFECTIVE DATE. PLEASE DETERMINE ANY FURTHER APPLICABILITY, PRIOR COMPLIANCE, AND/OR SCHEDULING REQUIREMENTS.							
AD 2026-07-01 PAR (h) AMD 39-23296 Airframe AD - Open FAA #3734	THIS AD WAS PROMPTED BY A REPORT OF UNCOMMANDED NOSE WHEEL STEERING UPON LANDING WITH TOUCHDOWN ON THE RUNWAY CENTERLINE. THE FAA IS ISSUING THIS AD TO ADDRESS UNCOMMANDED NOSEWHEEL STEERING DUE TO LOOSE NOSEWHEEL STEERING RUDDER PEDAL POTENTIOMETER...	08-MAY-2026 H: 8686.90 L: 3999	D: 60			07-JUL-2026	M: 1 D: 6
Notes (h) Maintenance/Inspection Program Revision Within 60 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information in the applicable temporary revision identified in paragraphs (h)(1) through (6) of this AD.							
AD 74-08-09 R3 Airframe AD - Complied With FAA #576	EQUIPMENT/FURNISHINGS - IMPROPER DISPOSAL OF SMOKING MATERIALS IN LAVATORY WASTE RECEPTACLES	25-APR-2022 H: 7477.20 L: 3329					
Notes (UPDATE NOTE: WORK PERFORMED BY JET EAST CRS VYQR491Y ON WO DALM-21906) (ISSUING AUTHORITY: FAA)							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 74-08-09 R3 AMD Paragraph (k) Airframe AD - Recurring FAA #124	EQUIPMENT/FURNISHINGS - IMPROPER DISPOSAL OF SMOKING MATERIALS IN LAVATORY WASTE RECEPTACLES - INSPECT ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ENCLOSURE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, AND LATCHING FOR THE CONTAINMENT OF POSSIBLE TRASH FIRES.	10-JUL-2024 H: 8462.00 L: 3865	H: 1000.00			H: 9462.00	H: 766.90
	Notes (UPDATE NOTE: COMPLIED WITH BY DIRECT MX, JOSE SALVADORE FLORES A&P 2747413, ON WO# LAS240138 DATED 7/10/2024.) (ISSUING AUTHORITY: FAA)						
AD 74-08-09 R3 AMD Paragraph (i) Airframe AD - Complied With FAA #2452	EQUIPMENT/FURNISHINGS - IMPROPER DISPOSAL OF SMOKING MATERIALS IN LAVATORY WASTE RECEPTACLES - INSTALL A SELF-CONTAINED, REMOVABLE ASHTRAY ON OR NEAR THE ENTRY SIDE OF EACH LAVATORY DOOR. ONE ASHTRAY MAY SERVE MORE THAN ONE LAVATORY DOOR IF THE ASHTRAY CAN BE SEEN READILY FROM THE CABIN SIDE OF EACH LAVATORY DOOR SERVED.	15-JUN-2016 H: 5753.40 L: 2496					
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION PER AD) (ISSUING AUTHORITY: FAA).COMPLIED WITH INSPECTION PER AD						
AD 74-08-09 R3 AMD Paragraph (g) Airframe AD - Complied With FAA #2769	ISPOSAL OF SMOKING MATERIALS IN LAVATORY WASTE RECEPTACLES - (1) INSTALL A PLACARD ON EACH SIDE OF EACH LAVATORY DOOR OVER THE DOOR KNOB, OR ON EACH SIDE OF EACH LAVATORY DOOR, OR ADJACENT TO EACH SIDE OF EACH LAVATORY DOOR. (2) INSTALL A PLACARD ON OR NEAR EACH LAVATORY PAPER OR LINEN WASTE DISPOSAL RECEPTACLE DOOR, CONTAINING THE LEGIBLE WORDS OR SYMBOLOGY INDICATING "NO CIGARETTE DISPOSAL."	15-JUN-2016 H: 5753.40 L: 2496					
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION PER AD) (ISSUING AUTHORITY: FAA).COMPLIED WITH INSPECTION PER AD						
AD 74-08-09 R3 AMD Paragraph (j) Airframe AD - Complied With FAA #2425	ORY DOORS MAY BE OPERATED WITH UP TO 50 PERCENT OF THE LAVATORY DOOR ASHTRAYS MISSING OR INOPERATIVE, PROVIDED 50 PERCENT OF THE MISSING OR INOPERATIVE ASHTRAYS ARE REPLACED WITHIN 3 DAYS AND ALL REMAINING MISSING OR INOPERATIVE ASHTRAYS ARE REPLACED WITHIN 10 DAYS. AN AIRPLANE WITH ONLY 1 LAVATORY DOOR MAY BE OPERATED FOR A PERIOD OF 10 DAYS WITH THE LAVATORY DOOR ASHTRAY MISSING OR INOPERATIVE	15-JUN-2016 H: 5753.40 L: 2496					
	Notes (UPDATE NOTE: COMPLIED WITH INSPECTION PER AD) (ISSUING AUTHORITY: FAA) (NOTE: NOTE 1 TO PARAGRAPH (J) OF THIS AD: THIS AD PERMITS A LAVATORY DOOR ASHTRAY TO BE MISSING, ALTHOUGH THE FAA-APPROVED MASTER MINIMUM EQUIPMENT LIST (MMEL) MAY NOT ALLOW SUCH PROVISION. IN ANY CASE, THE PROVISIONS OF THIS AD PREVAIL.)COMPLIED WITH INSPECTION PER AD						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 74-08-09 R3 AMD Paragraph (h) Airframe AD - Complied With FAA #3139	QUIRES THAT, NO LATER THAN A TIME IMMEDIATELY AFTER THE "NO SMOKING" SIGN IS EXTINGUISHED FOLLOWING TAKEOFF, AN ANNOUNCEMENT BE MADE BY A CREWMEMBER TO INFORM ALL AIRCRAFT OCCUPANTS THAT SMOKING IS PROHIBITED IN THE AIRCRAFT LAVATORIES; EXCEPT THAT, IF THE AIRCRAFT IS NOT EQUIPPED WITH A "NO SMOKING" SIGN, THE REQUIRED PROCEDURE MUST PROVIDE THAT THE ANNOUNCEMENT BE MADE PRIOR TO EACH TAKEOFF. Notes (UPDATE NOTE: COMPLIED WITH INSPECTION PER AD) (ISSUING AUTHORITY: FAA).COMPLIED WITH INSPECTION PER AD	15-JUN-2016 H: 5753.40 L: 2496					
AD 97-24-02 Airframe AD - Complied With FAA #1965	UNDERFLOOR PRESSURE BULKHEAD OF FUSELAGE Notes (UPDATE NOTE: COMPLIED WITH AD 97-24-02-R1 SB 604-53-06 ON 03-AUG-2005) (ISSUING AUTHORITY: FAA).COMPLIED WITH AD 97-24-02-R1 SB 604-53-06 ON 03-AUG-2005	03-AUG-2005					
AD 97-24-02 R1 AMD Para (b) Airframe AD - Complied With FAA #3628	DETAILED INSPECTION TO DETECT CRACKS AT FS 409.00 OF THE BULKHEAD WEB (P/N 600-32014-105/-137) Notes (UPDATE NOTE: CW SB 604-53-006) (ISSUING AUTHORITY: FAA).CW SB 604-53-006	03-AUG-2005 H: 2522.30 L: 983					
AD 97-24-02 R1 Airframe AD - Complied With FAA #470	PRESSURE BULKHEAD Notes (UPDATE NOTE: COMPLIED WITH SB 604-53-006) (ISSUING AUTHORITY: FAA).CW SB 604-53-006	03-AUG-2005 H: 2522.30 L: 983					
AD 99-09-52 Airframe AD - Complied With FAA #2025	FUEL MANIFOLD AND IDG WIRE Notes (UPDATE NOTE: COMPLIED WITH PARAGRAPHS (C1) (D1)) (ISSUING AUTHORITY: FAA).COMPLIED WITH PARAGRAPHS (C1) (D1)	12-APR-1999 H: 289.00 L: 117					



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 99-09-52 AMD Par. (d) Airframe AD - Complied With FAA #421	PERFORM A ONE-TIME VISUAL INSPECTION OF BOTH THE LEFT AND RIGHT ENGINE NACELLES OF THE AREA SURROUNDING THE 10TH STAGE BLEED AIR CHECK VALVE AND THE TOP AND BOTTOM PIGTAILS OF THE FUEL MANIFOLD TO VERIFY CLEARANCES AND DETECT CHAFING (MANDATORY)	12-APR-1999 H: 289.00 L: 117					
	Notes (UPDATE NOTE: COMPLIED WITH PARAGRAPHS (C1) (D1)) (ISSUING AUTHORITY: FAA).COMPLIED WITH PARAGRAPHS (C1) (D1)						
AD 99-09-52 AMD Par. (c) Airframe AD - Complied With FAA #903	PERFORM A ONE-TIME VISUAL INSPECTION OF THE IDG CABLE HARNESS IN THE RIGHT ENGINE NACELLE TO VERIFY CLEARANCES (MANDATORY)	12-APR-1999 H: 289.00 L: 117					
	Notes (UPDATE NOTE: COMPLIED WITH PARAGRAPHS (C1) (D1)) (ISSUING AUTHORITY: FAA).COMPLIED WITH PARAGRAPHS (C1) (D1)						
AD 99-23-26 Engine 1 AD - Complied With FAA #153	MAIN FUEL CONTROL (MFC)		03-AUG-2005				
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10						
AD 99-23-26 Engine 2 AD - Complied With FAA #419	MAIN FUEL CONTROL (MFC)		03-AUG-2005				
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10						
AD 99-23-26 AMD Para (c) Engine 1 AD - Complied With FAA #401	PREVENT UNCOMMANDED ENG ACCEL INST MFC W/ OSPEED PROTECTION (MANDATORY)	03-MAY-2004					
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).INSTALLED ON ENGINE BLD UP FROM FACTORY MFC P/N 6078T55P10						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD 99-23-26 AMD Para (c) Engine 2 AD - Complied With FAA #837	PREVENT UNCOMMANDED ENG ACCEL INST MFC W/ OSPEED PROTECTION (MANDATORY)	03-MAY-2004					
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P1010						
AD 99-23-26 AMD Para (a)(1) Engine 2 AD - Complied With FAA #805	PREVENT UNCOMMANDED ENG ACCEL REPLACE BUNA-N O-RINGS (MANDATORY)	03-MAY-2004					
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ON ENGINE BLD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10						
AD 99-23-26 R1 Engine 1 AD - Complied With FAA #225	MAIN FUEL CONTROL (MFC)	03-AUG-2005					
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10						
AD 99-23-26 R1 Engine 2 AD - Complied With FAA #61	MAIN FUEL CONTROL (MFC)	03-AUG-2005					
	Notes (UPDATE NOTE: ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10) (ISSUING AUTHORITY: FAA).ENGINE BUILD UP ORIGINAL FROM FACTORY MFC P/N INSTALLED 6078T55P10						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2023-01 Airframe AD - Complied With TRANSPORT CANADA #3243	FLIGHT CONTROLS - GROUND SPOILERS - DEPLOYMENT IN AIR Notes (UPDATE NOTE: COMPLIED WITH AD 2023-26-08 EFFECTIVE DATE MARCH 20, 2024, AMENDMENT 39-22651 PARAGRAPH (G)(1) THROUGH (3) BY VERIFYING AFM REVISION INCORPORATING INFORMATION SPECIFIED IN PARAGRAPHS (G)(2)(I) AND (II) OF THE AD. CURRENT AFM REVISION IS REV 131 DATED 5 SEPT 23 AND INCORPORATES THE DATA AS SPECIFIED IN PARAGRAPH (G)(1) THROUGH (3) OF THE AD. THIS IS A TERMINATING ACTION.) (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-2B16 (604 VARIANT) AEROPLANES, SERIAL NUMBERS 5301 THROUGH 5665, 5701 THROUGH 5988 AND 6050 THROUGH 6174. COMPLIANCE: WITHIN 60 DAYS FROM THE EFFECTIVE DATE OF THIS AD, UNLESS ALREADY ACCOMPLISHED.)	20-MAY-2024 H: 8412.90 L: 3840					
AD CF-2023-05 Airframe AD - Open TRANSPORT CANADA #3499	PNEUMATIC - NON-CONFORMING BLEED AIR LEAK DETECTION SYSTEM SENSING ELEMENTS Notes (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-2B16 AEROPLANES, SERIAL NUMBERS 5580 TO 5665, 5701 TO 5988 AND 6050 AND SUBSEQUENT. AS OF THE EFFECTIVE DATE OF THIS AD, AN AFFECTED PART IS NOT ELIGIBLE FOR INSTALLATION AS A REPLACEMENT PART ON GROUP 1 AND GROUP 2 AEROPLANES.)						
AD CF-2023-05 AMD Part I Airframe AD - Open TRANSPORT CANADA #3723	PNEUMATIC - NON-CONFORMING BLEED AIR LEAK DETECTION SYSTEM SENSING ELEMENTS - TESTING AND REPLACEMENT Notes (ISSUING AUTHORITY: TC)						
AD CF-2023-06 Airframe AD - Open TRANSPORT CANADA #3453	OXYGEN SYSTEM - PASSENGER OXYGEN MASK LANYARD IMPROPER SLEEVE LOOP CRIMPING AND/OR ENDS NOT SEALED Notes (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-2B16 AEROPLANES WITH SERIAL NUMBERS. NOTE: PART III - INSTALLATION PROHIBITION OF AFFECTED PARTS: AS OF THE EFFECTIVE DATE OF THIS AD, IT IS PROHIBITED TO INSTALL A PASSENGER OXYGEN MASK LANYARD ASSEMBLY PROVIDED WITH KIT P/N CDKC29-006-501 OR P/N CDKC29-006-503 CONTAINING A LOT NUMBER FROM TABLE 1 IN SECTION 2.B. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE SB.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2023-06 AMD Part I Airframe AD - Open TRANSPORT CANADA #2741	OXYGEN SYSTEM - PASSENGER OXYGEN MASK LANYARD IMPROPER SLEEVE LOOP CRIMPING AND/OR ENDS NOT SEALED - INSPECTION OF THE PASSENGER OXYGEN MASK ASSEMBLIES Notes (ISSUING AUTHORITY: TC)						
AD CF-2023-06 AMD Part II Airframe AD - Open TRANSPORT CANADA #2814	OXYGEN SYSTEM - PASSENGER OXYGEN MASK LANYARD IMPROPER SLEEVE LOOP CRIMPING AND/OR ENDS NOT SEALED - REPLACEMENT OF THE PASSENGER OXYGEN MASK LANYARD (IF THE PASSENGER OXYGEN MASK LANYARD(S)IS(ARE)NOT CRIMPED AND SEALED) Notes (ISSUING AUTHORITY: TC)						
AD CF-2023-07 Airframe AD - Complied With TRANSPORT CANADA #1351	FLIGHT CONTROLS - UNCOMMANDED FLAP EXTENSION Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: TC)			31-MAY-2025 H: 8649.70 L: 3986			
AD CF-2023-07 AMD Part I Airframe AD - Complied With TRANSPORT CANADA #3459	FLIGHT CONTROLS - UNCOMMANDED FLAP EXTENSION - INITIAL OPERATIONAL TEST OF THE INBOARD AND OUTBOARD FLAPS Notes (AVG MAN HRS: 1) (UPDATE NOTE: COMPLIED WITH BOMBARDIER AD CF-2023-07 EFFECTIVE 24 FEB 2023. COMPLIED WITH BY OPERATIONAL TEST OF THE INBOARD AND OUTBOARD FLAP IAW BOMBARDIER CL 604 S/B 604-27-040 2.B. PER AD CF-2023-07. NEXT DUE AT 8399.5. NO DEFECTS NOTED AT THIS TIME.) (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 100 HOURS AIR TIME OR 15 MONTHS, WHICHEVER OCCURS FIRST, FROM THE EFFECTIVE DATE OF THIS AD, PERFORM THE INITIAL OPERATIONAL TEST OF THE INBOARD AND OUTBOARD FLAPS IN ACCORDANCE WITH SECTION 2.B. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE BOMBARDIER SERVICE BULLETIN (SB) IDENTIFIED IN TABLE 1 BELOW.).COMPLIED WITH BOMBARDIER AD CF-2023-07 EFFECTIVE 24 FEB 2023. CO			04-APR-2023 H: 7999.50 L: 3609			
AD CF-2023-07 AMD Part II Airframe AD - Complied With TRANSPORT CANADA #3069	FLIGHT CONTROLS - UNCOMMANDED FLAP EXTENSION - REPEAT OPERATIONAL TEST OF THE INBOARD AND OUTBOARD FLAPS Notes (UPDATE NOTE: WORK COMPLIED WITH BY DUNCAN AVIATION CRS# JGVR194F DATED MAY 31, 2025) (ISSUING AUTHORITY: TC)			31-MAY-2025 H: 8649.70 L: 3986			

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2023-14 Airframe AD - Open TRANSPORT CANADA #2357	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE						
	Notes (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-2B16 AEROPLANES, ALL SERIAL NUMBERS.)						
AD CF-2023-14 AMD Part II Airframe AD - Open TRANSPORT CANADA #2931	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE - INSPECTION						
	Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 24 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, INSPECT THE SERIAL NUMBER OF THE ECM, P/N 601-86100-27, IN ACCORDANCE WITH SECTION 2.B. PART A OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SB LISTED IN TABLE A OF THIS AD.)						
AD CF-2023-14 AMD Part III Airframe AD - Open TRANSPORT CANADA #1416	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE - REPLACEMENT						
	Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 24 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, REMOVE AND REPLACE THE ECM, P/N 601-86100-27, IDENTIFIED IN PART I OR PART II OF THIS AD, IN ACCORDANCE WITH SECTION 2.C. PART B OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SB LISTED IN TABLE A OF THIS AD.)						
AD CF-2023-14 AMD Part I Airframe AD - Open TRANSPORT CANADA #1219	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE - VERIFICATION OF THE AEROPLANE TECHNICAL RECORDS						
	Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 24 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, VERIFY THE AEROPLANE TECHNICAL RECORDS TO DETERMINE IF THE SERIAL NUMBER OF THE ECM, P/N 601-86100-27, IS LISTED IN TABLE 1 OF SECTION 1.A. OF THE APPLICABLE SERVICE BULLETIN (SB) LISTED IN TABLE A OF THIS AD.)						
AD CF-2023-14R1 Airframe AD - Open TRANSPORT CANADA #1841	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE						
	Notes (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-2B16 AEROPLANES WITH SERIAL NUMBERS 5301 THROUGH 5665, 5701 THROUGH 5990, 6050 AND SUBSEQUENT.)						



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2023-14R1 AMD Part II Airframe AD - Open TRANSPORT CANADA #1370	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE - INSPECTION, APPLICABLE TO AEROPLANES WITH SERIAL NUMBERS 5301 THROUGH 5665, 5701 THROUGH 5990 AND 6050 THROUGH 6171						
Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 24 MONTHS FROM THE EFFECTIVE DATE OF CF-2023-14 (14 MARCH 2023), INSPECT THE SERIAL NUMBER OF THE ECM, P/N 601-86100-27, IN ACCORDANCE WITH SECTION 2.B. PART A OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SB LISTED IN TABLE A OF THIS AD.)							
AD CF-2023-14R1 AMD Part III Airframe AD - Open TRANSPORT CANADA #2379	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE - REPLACEMENT, APPLICABLE TO AEROPLANES WITH SERIAL NUMBERS 5301 THROUGH 5665, 5701 THROUGH 5990 AND 6050 THROUGH 6171						
Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 24 MONTHS FROM THE EFFECTIVE DATE OF CF-2023-14 (14 MARCH 2023), REMOVE AND REPLACE THE ECM, P/N 601-86100-27, IDENTIFIED IN PART I OR PART II OF THIS AD, IN ACCORDANCE WITH SECTION 2.C. PART B OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE SB LISTED IN TABLE A OF THIS AD.)							
AD CF-2023-14R1 AMD Part I Airframe AD - Open TRANSPORT CANADA #3695	LANDING GEAR - NOSE WHEEL STEERING SYSTEM - ELECTRONIC CONTROL MODULE FILTER PLATE CONNECTOR FAILURE - VERIFICATION OF THE AEROPLANE TECHNICAL RECORDS, APPLICABLE TO AEROPLANES WITH SERIAL NUMBERS 5301 THROUGH 5665, 5701 THROUGH 5990 AND 6050 THROUGH 1671						
Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 24 MONTHS FROM THE EFFECTIVE DATE OF CF-2023-14 (14 MARCH 2023), VERIFY THE AEROPLANE TECHNICAL RECORDS TO DETERMINE IF THE SERIAL NUMBER OF THE ECM, P/N 601-86100-27, IS LISTED IN TABLE 1 OF SECTION 1.A. OF THE APPLICABLE SERVICE BULLETIN (SB) LISTED IN TABLE A OF THIS AD.)							
AD CF-2023-21 Airframe AD - N/A TRANSPORT CANADA #2878	OXYGEN - PORTABLE PROTECTIVE BREATHING EQUIPMENT (PBE) - MISSING PBE IN THE FORWARD AREA OF THE AEROPLANE					31-JAN-2024 H: 8254.00 L: 3749	
Notes (AVG MAN HRS: 3) (UPDATE NOTE: AD CF-2023-21 OXYGEN - PORTABLE PROTECTIVE BREATHING EQUIPMENT (PBE) - MISSING PBE IN THE FORWARD AREA OF THE AEROPLANE. THIS AD IS NOT APPLICABLE DUE TO PORTABLE O2 SYSTEM PREVIOUSLY INSTALLED. NO FURTHER ACTION REQUIRED.) (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-2B16 AEROPLANES WITH SERIAL NUMBERS. COMPLIANCE: WITHIN 12 MONTHS FROM THE EFFECTIVE DATE OF THIS AD, UNLESS ALREADY ACCOMPLISHED.)AD CF-2023-21 OXYGEN - PORTABLE PROTECTIVE BREATHING EQUIPMENT (PBE) - MISSING PBE IN THE FORWARD AREA OF THE AEROPLAN. THIS AD IS NOT APPLICABLE DUE TO PORTABLE O2 SYSTEM PREVIOUSLY INSTALLED. NO FURTHER ACTION REQUIRED.							



Maintenance Items

N530BD

ATA / Type / Group	Description	Compliance	Intervals	Tolerance	TSN/TSO	Next Due	Remaining
AD CF-2024-12 Airframe AD - Open TRANSPORT CANADA #2323	LANDING GEAR - UNCOMMANDED STEERING DUE TO NOSEWHEEL STEERING POTENTIOMETER UNIVERSAL COUPLING SETSCREW FAILURE Notes (ISSUING AUTHORITY: TC) (NOTE: APPLICABILITY: BOMBARDIER INC. MODEL CL-600-1A11, CL-600-2A12 AND CL-600-2B16 AEROPLANES, ALL SERIAL NUMBERS.)						
AD CF-2024-12 AMD Part II Par. A. C. Airframe AD - Open TRANSPORT CANADA #3174	LANDING GEAR - UNCOMMANDED STEERING DUE TO NOSEWHEEL STEERING POTENTIOMETER UNIVERSAL COUPLING SETSCREW FAILURE - INTRODUCTION OF TLMC TASK - INCORPORATE THE NEW TLMC TASK FOR THE REMOVAL AND REPLACEMENT OF THE COUPLING SETSCREWS Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 60 DAYS FROM THE EFFECTIVE DATE OF THIS AD, INCORPORATE THE NEW TLMC TASK FOR THE REMOVAL AND REPLACEMENT OF THE COUPLING SETSCREWS IN THE TLMC MANUAL, AS IDENTIFIED IN TABLE 2 BELOW. THEREAFTER, REPEAT THE REMOVAL AND REPLACEMENT OF THE COUPLING SETSCREWS, IN ACCORDANCE WITH THE TLMC TASK INTRODUCED IN THE AFFECTED TLMC MANUAL AS DETAILED IN TABLE 2 BELOW.)						
AD CF-2024-12 AMD Part I Airframe AD - Open TRANSPORT CANADA #1052	LANDING GEAR - UNCOMMANDED STEERING DUE TO NOSEWHEEL STEERING POTENTIOMETER UNIVERSAL COUPLING SETSCREW FAILURE - REPLACEMENT OF NOSEWHEEL STEERING POTENTIOMETER UNIVERSAL COUPLING SETSCREWS Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 36 MONTHS OR 1400 HOURS AIR TIME, WHICHEVER OCCURS FIRST, FROM THE EFFECTIVE DATE OF THIS AD, REPLACE THE NOSEWHEEL STEERING POTENTIOMETER UNIVERSAL COUPLING SETSCREWS IN ACCORDANCE WITH SECTION 2.B. AND 2.C. OF THE ACCOMPLISHMENT INSTRUCTIONS OF THE APPLICABLE BOMBARDIER SERVICE BULLETIN (SB) IDENTIFIED IN TABLE 1 BELOW, OR LATER REVISIONS APPROVED BY THE CHIEF, CONTINUING AIRWORTHINESS, TRANSPORT CANADA.)						
AD CF-2024-31 Airframe AD - Open TRANSPORT CANADA #3268	FLIGHT CONTROLS - FLAP SYSTEM ON-BOARD RECORDER (FSOBR) EFFECTS ON FLAP CONTROL UNIT Notes (ISSUING AUTHORITY: TC) (NOTE: COMPLIANCE: WITHIN 1000 HOURS AIR TIME OR 14 MONTHS, WHICHEVER OCCURS FIRST, FROM THE EFFECTIVE DATE OF THIS AD, UNLESS ALREADY ACCOMPLISHED.)						